Available from

GPO Sales Program
Division of Technical Information and Document Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Printed copy price: \$9.00

and

National Technical Information Service Springfield, Virginia 22161

.

Title List of Documents Made Publicly Available

April 1-30, 1980

Division of Technical Information and Document Control Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	2
Domestic Licensing of Production and Utilization Facilties - Docket 50	8
Domestic Licensing of Special Nuclear Material - Docket 70	334
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions - Docket 71	349
Nondocketed Items	357
10CFR — Commission Meeting Records	357
ACRS — Advisory Committee on Reactor Safeguards	357
COMMISSION — NRC Commissioners	361
CONTRACT — NRC Contracts and Modifications	364
FOIA — Freedom of Information Act Requests and Releases	367
GEN TECH IS — Generic Technical Issues	375
I&E — Inspection and Enforcement	375
MISC — Public Document Room Miscellaneous	376
NUREG — NUREG Reports and Related Correspondence	378
ORG — Correspondence with Other Organizations	381
PR — Proposed Rule	382
PRM — Petition for Rulemaking	387
PROJ — Projects - Predocket Licensing	388
PT21 — Noncompliance Reports and Related Correspondence	388
QA999 — Quality Assurance Inspections	389
REGGD — Regulatory Guides	392
RES — Research and Technical Assistance Reports	393
REVIEW GRP — NRC Research Review Groups	395
SECY — Position Papers Before the Commission	395
STATE PROG — State Programs	396
TOPREP — Vendor Reports and Related Correspondence	398
WASTE MGT — Nuclear Waste Management	400
XPORTLIC — Export and Import Licenses	402
Personal Author Index	409
Corporate Source Index	443
Report Number Index	475
Cross Reference of Enclosures to Principal Documents	477
Appendix A – Definitions of Docket 50 Categories	495
Appendix B - Definitions of Nondocketed Categories	503

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:


1

P. Operating license stage documents & correspondence



7904170015 Forwards info on TMI:JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- I NRC/PDR Document category (see Appendix A)
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records

ACRS — Advisory Committee on Reactor Safeguards

COMMISSION — NRC Commissioners

CONTRACT — NRC Contracts and Modifications

FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG - Correspondence with other organizations

PR — Proposed Rule
PRM — Petition for Rulemaking
PROJ — Projects-Predocket Licensing
PT21 — Noncompliance Reports and Related Correspondence
QA999 — Quality Assurance Inspections
REGGD — Regulatory Guides
RES — Research and Technical Assistance Reports
REVIEW GRP — NRC Research Review Groups
RM — Rulemakings
SECY — Position Papers Before the Commission
STATE PROG — State Programs
TOPREP — Vendor Reports and Related Correspondence

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

WASTE MGT — Nuclear Waste Management XPORTLIC — Export and Import Licenses

1 NUREG – NUREG Reports and Related Correspondence

2 3

7901060007 NUREG/CR-0161

"Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.

FIN A-2093. 78/11/30. 26pp. Available at NTIS.

(7) (5) (8) (9) (10) (6)

- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on the next page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8380	Rocky Mountain Energy Co.	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8452	Bear Creek Uranium Co.	6
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8502	Irigaray Mine, Wyoming Mining Corp.	6
40-0215	S.F. Appliance, Ltd.	2	40-8584	Union 76 Minerals Exploration Co.	7
40-0261	Kerr-McGee Chemical Co.	3	40-8602	United Nuclear Corp.	7
40-0299	Union Carbide Corp.	3	40-8647	Kerr-McGee Corp.	7
40-0672	Nuclear Metals, Inc.	3	40-8675	Energy Fuels Nuclear, Inc	7
40-1162	Western Nuclear, Inc.	3	40-8681	Energy Fuels Nuclear, Inc.	7
40-1193	Babcock & Wilcox Co.	3	40-8698	Plateau Resources, Ltd.	8
40-1341	Edgemont Uranium Mine, TVA, and Mines	3	40-8721	Rocky Mountain Energy Co.	8
10.0061	Development, Inc.		40-8722	Brush-Wellman, Inc.	8
40-2061	West Chicago Facility, Kerr-McGee Corp.	4	40-8727	Kerr-McGee Nuclear Corp.	8
40-2259	Pathfinder Mines Corp.	4	40-8728	Teton Exploration Drilling Co., Inc.	8
40-2286	Westinghouse Electric Co.	4	40-8745	Ogle Petroleum	8
40-3453	Atlas Minerals	4	40-8760	Edlow International Corp.	8
40-4492	Federal American Partners (Mining)	5	40-8768	Kerr-McGee Nuclear Corp.	8
40-6329	Catholic Univ. of America	5	50-2	Univ. of Michigan Research Reactor	8
40-6622	Pathfinder Mines Corp.	5	50-2	•	9
40-6659	Petrotomics Co., Getty Oil Co.	5		Indian Point Station, Unit 1	11
40-7127	Univ. of Toledo	5	50-10	Dresden Nuclear Power Station, Unit 1	
40-7982	Honeywell, Inc	5	50-13	Babcock & Wilcox Co. Critical Facility	14
40-8027	Kerr-McGee Corp.	6	50-18	Vallecitos Boiling Water Reactor	14
40-8064	Exxon Minerals Co. USA, Exxon	6	50-29	Yankee-Rowe Nuclear Power Station	14
	Corp.		50-30	Plum Brook Research Reactor Facility	15
40-8102	Exxon Minerals Co. USA, Exxon Corp	6	50-54	Union Carbide Research Reactor	16
40-8135	3M Co., Minnesota Mining and	6	50-57	State Univ. of New York Research Reactor	16
CC10-01	Manufacturing Co.	v	50-70	General Electric Test Reactor	16
40-8304	Wyoming Mining Corp.	6	50-73	General Electric Nuclear Test Reactor	16

Docket	Name	Page	Docket	Name	Page
50-111	North Carolina State Univ. Research Reactor	16	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	33
50-123	Univ. of Missouri Research Reactor	17	50-245	Millstone Nuclear Power Station, Unit 1	34
50-123	Virginia Polytech Institute Training Reactor	17	50-247	Indian Point Station, Unit 2	37
		17	50-249	Dresden Nuclear Power Station, Unit 3	40
50-128	Texas A&M Univ. Research Reactor		50-250	Turkey Point Plant, Unit 3	42
50-133	Humboldt Bay Power Plant, Unit 3	17	50-251	Turkey Point Plant, Unit 4	46
50-137	Turkey Research Reactor	18	50-254	Quad-Cities Station, Unit 1	49
50-142	UCLA Training Reactor	18	50-255	Palisades Nuclear Plant	51
50-150	Ohio State Univ. Research Reactor	18	50-259	Browns Ferry Nuclear Power Station,	54
50-151	Univ. of Illinois Research Reactor	18		Unit 1	
50-155	Big Rock Point Nuclear Plant	18	50-260	Browns Ferry Nuclear Power Station, Unit 2	56
50-160	Georgia Institute of Technology Research Reactor	21	50-261	H.B. Robinson Plant, Unit 2	59
50-163	General Atomic Co.	21	50-263	Monticello Nuclear Generating Plant	60
50-166	Univ. of Maryland Research Reactor	21	50-264	Dow Chemical Co.	62
50-170	National Naval Medical Center	21	50-265	Quad-Cities Station, Unit 2	62
50-171	Peach Bottom Atomic Power Station, Unit 1	21	50-266	Point Beach Nuclear Plant, Unit 1	64
50-182	Purdue Univ. Research Reactor	22	50-267	Fort St. Vrain Nuclear Generating Station	66
50-183	Vallecitos Experimental Superheat Reactor	22	50-268	Midwest Fuel Recovery Plant	67
50-184	National Bureau of Standards Reactor	22	50-269	Oconee Nuclear Station, Unit 1	67
50-189	University Training Reactor	22	50-270	Oconce Nuclear Station, Unit 2	70
50-103	Rhode Island & Providence Plantations		50-271	Vermont Yankee Nuclear Power Station	72
30-173	AEC	22	50-272	Salem Nuclear Generating Station, Unit 1	74
50-201	West Valley Reprocessing Plant	22	50-275	Diablo Canyon Nuclear Power Plant,	77
50-206	San Onofre Nuclear Station, Unit 1	23	50.276	Unit 1	00
50-213	Haddam Neck Plant	25	50-276	Georgia Tech Research Reactor	80
50-219	Oyster Creek Nuclear Power Plant	27	50-277	Peach Bottom Atomic Power Station, Unit 2	80
50-220	Nine Mile Point Nuclear Station, Unit I	29	50-278	Peach Bottom Atomic Power Station,	82
50-224	Univ. of California Research Reactor	30	£0.000	Unit 3	
50-225	RPI Critical Experiment	30	50-280	Surry Power Station, Unit 1	84
50-228	Aerotest Radiography & Research Reactor	30	50-281	Surry Power Station, Unit 2	86
50-237	Dresden Nuclear Power Station, Unit 2	30	50-282	Prairie Island Nuclear Station, Unit 1	88
50-243	Oregon State Univ, Research Reactor	33	50-285	Fort Calhoun Station, Unit 1	90

Docket	Name	Page	Docket	Name	Page
50-286	Indian Point Station, Unit 3	91	50-329	Midland Plant, Unit 1	174
50-287	Oconee Nuclear Station, Unit 3	95	50-330	Midland Plant, Unit 2	175
50-289	Three Mile Island Nuclear Station, Unit 1	97	50-331	Duane Arnold Energy Center	177
50-293	Pilgrim Nuclear Power Station, Unit 1	108	50-332	Barnwell Reprocessing Plant	179
50-294	Michigan State Univ. Research Reactor	110	50-333	James A. Fitzpatrick Nuclear Power Plant	179
50-295	Zion Nuclear Power Station, Unit 1	110	50-334	Beaver Valley Power Station, Unit 1	181
50-296	Browns Ferry Nuclear Power Station, Unit 3	114	50-335	St. Lucie Plant, Unit 1	184
50-298	Cooper Nuclear Station	116	50-336	Millstone Nuclear Power Station, Unit 2	186
50-301	Point Beach Nuclear Plant, Unit 2	117	50-338	North Anna Power Station, Unit 1	188
50-302	Crystal River Nuclear Plant, Unit 3	119	50-339	North Anna Power Station, Unit 2	190
50-303	Crystal River Nuclear Plant, Unit 4	121	50-341	Enrico Fermi Atomic Power Plant, Unit 2	194
50-304	Zion Nuclear Power Station, Unit 2	121	50-344	Trojan Nuclear Plant	195
50-305	Kewaunee Nuclear Power Plant	124	50-346	Davis-Besse Nuclear Power Station, Unit 1	198
50-306	Prairie Island Nuclear Station, Unit 2	126	50-348	Joseph M. Farley Nuclear Plant, Unit 1	200
50-309	Maine Yankee Atomic Power Plant	128	50-351	Korea Research Reactor	202
50-311	Salem Nuclear Generating Station, Unit 2	130	50-352	Limerick Generating Station, Unit 1	202
50-312	Rancho Seco Nuclear Generating Station	132	50-353	Limerick Generating Station, Unit 2	203
50-313	Arkansas Nuclear One, Unit 1	135	50-354	Hope Creek Nuclear Station, Unit 1	205
50-315	Donald C. Cook Nuclear Power Plant,	138	50-355	Hope Creek Nuclear Station, Unit 2	206
	Unit 1		50-356	Univ. of Illinois LOPRA Research Reactor	207
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	140	50-358	William H. Zimmer Nuclear Station, Unit 1	207
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	142	50-361	San Onofre Nuclear Station, Unit 2	209
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	145	50-362	San Onofre Nuclear Station, Unit 3	211
50-320	Three Mile Island Nuclear Station, Unit 2	147	50-363	Forked River Nuclear Station, Unit 1	212
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	157	50-364	Joseph M. Farley Nuclear Plant, Unit 2	213
50-322	Shoreham Nuclear Power Station	159	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	214
50-323	Diablo Canyon Nuclear Power Plant,	161	50-367	Bailly Generating Station	216
	Unit 2		50-368	Arkansas Nuclear One, Unit 2	218
50-324	Brunswick Steam Electric Plant, Unit 2	163	50-369	William B. McGuire Nuclear Station, Unit 1	220
50-325	Brunswick Steam Electric Plant, Unit 1	165	50-370	William B. McGuire Nuclear Station,	222
50-327	Sequoyah Nuclear Plant, Unit 1	167		Unit 2	_
50-328	Sequoyah Nuclear Plant, Unit 2	171	50-373	LaSalle County Station, Unit 1	223

Docket	Name	Page	Docket	Name	Page
50-374	LaSalle County Station, Unit 2	225	50-434	Surry Power Station, Unit 3	260
50-376	North Coast Nuclear Plant, Puerto Rico	22 6	50-435	Surry Power Station, Unit 4	260
50-382	Waterford Generating Station, Unit 3	226	STN-50-437	Floating Nuclear Plant	260
50-384	Indonesia Research Reactor	227	50-438	Bellefonte Nuclear Plant, Unit 1	260
50-387	Susquehanna Steam Electric Station, Unit 1	227	50-439	Bellefonte Nuclear Plant, Unit 2	262
50-388	Susquehanna Steam Electric Station, Unit 2	231	50-440	Perry Nuclear Power Plant, Unit 1	264
50-389	St. Lucie Plant, Unit 2	234	50-441	Perry Nuclear Power Plant, Unit 2	265
50-390	Watts Bar Nuclear Plant, Unit 1	236	50-443	Seabrook Nuclear Station, Unit 1	266
50-391	Watts Bar Nuclear Plant, Unit 2	238	50-444	Seabrook Nuclear Station, Unit 2	267
50-395	Virgil C. Summer Nuclear Station, Unit 1	239	50-445	Comanche Peak Steam Electric Station,	269
50-397	WPPSS Nuclear Project, Unit 2	241	20 446	Unit 1	
50-400	Shearon Harris Nuclear Power Plant,	243	50-446	Comanche Peak Steam Electric Station, Unit 2	275
50-401	Unit I Shearon Harris Nuclear Power Plant,	244	50-448	Douglas Point Nuclear Station, Unit 1	281
JU-401	Unit 2	244	50-449	Douglas Point Nuclear Station, Unit 2	281
50-402	Shearon Harris Nuclear Power Plant, Unit 3	245	50-452	Greenwood Energy Center, Unit 2	281
50-403	Shearon Harris Nuclear Power Plant,	246	50-453	Greenwood Energy Center, Unit 3	281
20 103	Unit 4	#40	50-454	Byron Station, Unit 1	281
50-404	North Anna Power Station, Unit 3	247	50-455	Byron Station, Unit 2	282
50-405	North Anna Power Station, Unit 4	248	50-456	Braidwood Station, Unit 1	284
50-409	La Crosse Boiling Water Reactor	248	50-457	Braidwood Station, Unit 2	284
50-410	Nine Mile Point Nuclear Station, Unit 2	250	50-458	River Bend Station, Unit 1	285
50-412	Beaver Valley Power Station, Unit 2	251	50-459	River Bend Station, Unit 2	286
50-413	Catawba Nuclear Station, Unit 1	252	50-460	WPPSS Nuclear Project, Unit I	287
50-414	Catawba Nuclear Station, Unit 2	252	50-461	Clinton Power Station, Unit 1	288
50-416	Grand Gulf Nuclear Station, Unit 1	253	50-462	Clinton Power Station, Unit 2	288
50-417	Grand Gulf Nuclear Station, Unit 2	255	50-463	Fulton Generating Station, Unit 1	289
50-423	Millstone Nuclear Power Station, Unit 3	257	50-464	Fulton Generating Station, Unit 2	289
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	258	50-466	Allens Creek Nuclear Station, Unit 1	289
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	259	STN-50-470	CESSAR System 80	290
50-427	Alvin W. Vogtle Nuclear Plant, Unit 4	260	50-471	Pilgrim Nuclear Power Station, Unit 2	290
50-433	Univ. of California at Santa Barbara Research Reactor	260	STN-50-482	Wolf Creek Generating Station	291

Docket	Name	Page	Docket	Name	Page
STN-50-483	Calloway Plant, Unit 1	292	STN-50-523	Skagit Nuclear Power Project, Unit 2	318
STN-50-484	Tyrone Energy Park, Unit 1	293	50-524	Barton, Unit I	319
STN-50-485	Sterling Power Project Nuclear, Unit 1	293	50-525	Barton, Unit 2	319
STN-50-486	Calloway Plant, Unit 2	294	50-526	Barton, Unit 3	319
STN-50-488	Perkins Nuclear Station, Unit 1	295	50-527	Barton, Unit 4	319
STN-50-489	Perkins Nuclear Station, Unit 2	296	STN-50-528	Palo Verde Nuclear Station, Unit 1	319
STN-50-490	Perkins Nuclear Station, Unit 3	296	STN-50-529	Palo Verde Nuclear Station, Unit 2	320
STN-50-491	Cherokee Nuclear Station, Unit 1	297	STN-50-530	Palo Verde Nuclear Station, Unit 3	321
STN-50-492	Cherokee Nuclear Station, Unit 2	297	50-534	Wolsung I, Korea	322
STN-50-493	Cherokee Nuclear Station, Unit 3	298	50-537	Clinch River Breeder Reactor	322
STN-50-495	SWESSAR-PI	298	STN-50-546	Marble Hill Nuclear Station, Unit I	322
50-496	Montague Nuclear Power Station, Unit 1	299	STN-50-547	Marble Hill Nuclear Station, Unit 2	323
5 0-497	Montague Nuclear Power Station, Unit 2	299	50-548	Fort Calhoun Station, Unit 2	325
STN-50-498	South Texas Project, Unit 1	299	50-549	Greene County Nuclear Power Plant	325
STN-50-499	South Texas Project, Unit 2	304	STN-50-550	GESSAR-238-BOP Interface	325
50-500	Davis-Besse Nuclear Power Station, Unit 2	310	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	325
50-501	Davis-Besse Nuclear Power Station, Unit 3	310	STN-50-554	Phipps Bend Nuclear Plant, Unit 2	326
STN-50-502	Haven Nuclear Plant, Unit 1	310	STN-50-556	Black Fox Station, Unit 1	328
STN-50-508	WPPSS Nuclear Project, Unit 3	310	STN-50-557	Black Fox Station, Unit 2	329
STN-50-509	WPPSS Nuclear Project Unit 5	311	50-564	Nuclear Fuels Recovery & Recycle Center	330
50-510	Blue Hills Station, Unit 1	311	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	330
50-511	Blue Hills Station, Unit 2	311	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	331
50-513	WPPSS Nuclear Project, Unit 4	311	STN-50-568	NEP Nuclear, Unit I	333
50-514	Pebble Springs Nuclear Plant, Unit 1	312	STN-50-569	NEP Nuclear, Unit 2	333
50-515	Pebble Springs Nuclear Plant, Unit 2	313	STN-50-574	Bagnac Nuclear Power Project, Philippines	333
STN-50-516	Jamesport Nuclear Station, Unit 1	313	STN-50-580	Erie Nuclear Plant, Unit 1	333
STN-50-517	Jamesport Nuclear Station, Unit 2	314	STN-50-581	Erie Nuclear Plant, Unit 2	333
STN-50-518	Hartsville Nuclear Plant, Unit 1	314	50-582	Sundesert, Unit 1	333
STN-50-519	Hartsville Nuclear Plant, Unit 2	315	50-583	Sundesert, Unit 2	333
STN-50-520	Hartsville Nuclear Plant, Unit 3	316	50-585	TRIGA Mark II	333
STN-50-521	Hartsville Nuclear Plant, Unit 4	317	STN-50-592	Palo Verde Nuclear Station, Unit 4	333
STN-50-522	Skagit Nuclear Power Project, Unit 1	318	STN-50-593	Palo Verde Nuclear Station, Unit 5	334

Docket	Name	Page	Docket	Name	Page
STN-50-596	New Haven Unit 1	334	70-1100	Combusion Engineering, Inc.	342
STN-50-597	New Haven, Unit 2	334	70-1113	General Electric Co.	342
50-599	Carroll Facility I	334	70-1143	Westinghouse Electric Corp.	343
50-600	Carroll Facility II	334	70-1151	Westinghouse Electric Corp.	343
70-0008	Battelle Columbus Laboratories	334	70- 1 19 3	Cimarron Facility, Kerr-McGee Corp	343
70-0025	Rockwell International	334	70-1201	UF-6 Conversion Facility, Babcock &	344
70-0027	Babcock & Wilcox Co	334	70.1222	Wilcox Co	244
70-0033	Texas Instruments, Inc.	335	70-1222	Univ. of Missouri	344
70-0047	National Aeronautics & Space	335	70-1227	Erie Mining Co.	344
70.0000	Administration		70-1251	Albright College, Reading, PA	344
70-0082	Nuclear Metals, Inc.	335	70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	344
70-0098	Univ. of Toledo	335	70-1308	Morris Operations, General Electric Co	345
70-0135	Babcock & Wilcox Co.	335	70-1319	U.S. Nuclear, Inc.	346
70-0143	Nuclear Fuel Services, Inc.	337	70-1426	Transnuclear, Inc.	346
70-0190	Catholic Univ.	338	70-1729	Fuel Recovery & Storage Station, Allied	346
70-0364	Parks Township Site, Babcock & Wilcox Co.	338	13	General Nuclear Service Corp.	Jac
70-0371	United Nuclear Corp.	340	70-1739	Tri-State Motor Transit Co.	346
70-0398	Dept. of Commerce	340	70-2554	New England Medical Center, Boston, MA	346
70-0572	Monsanto Research Corp.		70-2322	Edlow International Co.	346
70-0687	•	340	70-2362	Brockton Hospital, Brockton, MA	346
70-0696	Union Carbide Corp.	340	70-2478	Transnuclear, Inc.	346
	General Services Administration	340	70-2479	Transnuclear, Inc.	347
70-0734	General Atomic Co.	340	70-2623	McGuire Spent Fuel Pool, Duke Power Co.	347
70-0754	Vallecitos Nuclear Center, General Electric Co.	341	70-2786	General Electric Co.	348
70-0820	United Nuclear Corp.	341	70-2805	Nissho-Iwai American Corp	348
70-0824	Babcock & Wilcox Co.	341	70-2845	Transnuclear, Inc.	348
70-0827	The Defiance College, Defiance, OH	341	70-2872	Reuter-Stokes	348
70-0925	Cimmaron Facility, Kerr-McGee Corp.	341	70-2909	Westinghouse Electric Corp.,	348
70-0984	Pacific Northwest Labortory	341		Power Systems	
70-1007	General Electric Co.	342	70-2917	Tennessee Valley Authority	348
70-1068	Univ. of Florida	342	70-2920	Alabama Power Co.	349
70-1089	Commonwealth of Pennsylvania	342	71-0005	Magnaflux Corp.	349

Docket	Name	Page	Docket	Name	Page
71-0009	Isomedix, Inc.	349	71-0380	General Electric Co	351
71-0013	Dept. of the Navy	349	71-0381	E L. Conwell & Co.	351
71-0024	Hittman Nuclear & Development Corp.	349	71-0383	Model: NLI 1/2 LWT Cask, NL Industries,	351
71-0035	Rockwell International	349		Ine	
71-0049	Dept. of the Navy	349	71-4824	Model: HA-10, Babcock & Wilcox Co.	351
71-0096	Pan American World Airways	349	71-5395	Model CC, Westinghouse Electric Corp.	351
71-0097	Nondestructive Testing Service	349	71-5607	Model: GE T-2, General Electric Co.	351
71-0102	Source Production & Equipment Co,	349	71-5796	Model: 181361, Picker Corp	351
	Inc.		71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	351
71-0107	Dept. of the Navy	349	71-5938	Model HNPF, General Atomic Co.	351
71-0116	Dept. of the Navy	350	71-5939	Model: GE-1500, General Electric Co.	351
71-0121	Neutron Products, Inc.	350			
71-0135	Babcock & Wilcox Co.	350	71-5942	Model GE-700, General Electric Co	352
71-0165	Dept. of the Navy	350	71-5971	Model: GE-200, General Electric Co.	352
71-0170	General Electric Co.	350	71-5979	Model: 5979, Alpha-Omega Services, Inc.	352
71-0180	Hartford Steam Boiler Co.	350	71-5998	Model GE-400, General Electric Co.	352
71-0185	FBF, Inc.	350	71-6078	Model: 927 A1 & C1, Combustion Engineering Co.	352
71-0227	Tennessee Valley Authority	350	71-6144	Model: 6144, Nuclear Engineering Co.	352
71-0230	Babcock & Wilcox Co.	350	71-6272	Model: Poly Panther, Teledyne Energy	352
71-0249	Nuclear Fuel Services, Inc.	350		Systems	
71-0250	Transnuclear, Inc.	350	71-6375	Model PB-1, Chem-Nuclear Systems, Inc.	352
71-0252	Dayton X-Ray Co.	350	71-6387	Model: 60, Battelle Memorial Institute	352
71-0273	Dept. of the Navy	350	71-6400	Model: Super Tiger, Westinghouse Electric Corp	352
71-0367	Dept. of the Navy	350	71-6574	Model: HN-200, Hittman Nuclear &	352
71-0370	Amersham Corp.	351		Development Corp.	
71-0372	Boeing Co.	351	71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	352
71-0373	Dept. of the Navy, Naval Explosive Ordnance Disposal Facility	351	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	353
71-0375	Univ. of California	351	71-6717	Model: 6717 B	353
			71-9006	Model: 500 SU, Argonne National	353
71-0377	Indiana & Michigan Electric Co.	351	B 1 000-	Laboratory	
71-0378	Wisconsin Electric Power Co.	351	71-9007	Model: 520, Argonne National Laboratory	353
71-0379	Hittman Nuclear & Development Corp., Hittman Material & Medical	351	71-9009	Model: FL 10-1, General Electric Co.	353
	Components, Inc.		71-9010	Model: NLI-1/2, NL Industries, Inc.	353

Docket	Name	Page	Docket	Name	Page
71-9011	Model: E-MEH-00-00004, Dept. of Transportation	353	71-9080	Model HN-600, Hittman Nuclear & Development Corp.	354
71-9015	Model: TN-8, Transnuclear, Inc.	353	71-9081	Model: CNSI-1600, Chem-Nuclear Systems, Inc.	354
71-9016	Model: TN-9, Transnuclear, Inc.	353	71-9089	Model: NH-100 S, Hutman Nuclear &	354
71-9019	Model: BU-7, General Electric Co.	353	,,,,,,,	Development Corp	
71-9020	Model: SL-10-1, Nuclear Containers, Inc.	353	71-9094	Model: CNSI-14-195-H, Chem-Nuclear Systems, Inc	354
71-9029	Model: 676, Technical Operations, Inc.	354	71-9096	Model, CNSI-21-300, Chem-Nuclear	355
71-9036	Model: C-1, Source Production Equipment Co.	354		Systems, Inc.	
71-9039	Model: 715, Technical Operations, Inc.	354	71-9105	Model Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	355
71-9043	Model: NNPU, Dept. of the Navy	354	71-9111	Model: CN6-80A, Chem-Nuclear Systems, Inc	355
71-9044	Model: GE-1600, General Electric Co.	354			255
71-9045	Model: GE-1000, General Electric Co.	354	71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	355
71-9046	Model: GE-1100, General Electric Co.	354	71-9122	Model. 18-450, Chem-Nuclear Systems, Inc.	355
71-9049	Model: GE-500, General Electric Co	354	71-9130	Model: NP-50-XXL, Nuclear Packaging, Inc.	355
71-9050	Model: GE-900, General Electric Co.	354			
71-9067	Model: BCL-3	354	71-9132	Model. T-3, Nuclear Packaging, Inc.	355
71-9070	Model: N-55, Dept. of Energy	354	71-9135	Model: Century, Gamma Industries	355
71-9072	Model: GAHC-1, General Atomic Co.	354	71-9142	Model: 2526, Monsanto Research Corp.	355
	,		71-9853	Model: ORNL-BNL-NBS, Unirradiated	355
71-9073	Model: OH-142, Nuclear Packaging, Inc	354		Fuel Container, Dept. of Energy	
71-9079	Model: HN-100, Series 2, Hittman Nuclear & Development Corp.	354			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

lame	Docket	Page	Name	Docket	Page
kerotest Radiography & Research Reactor	50-228	30	Browns Ferry Nuclear Power Station, Unit 2	50-260	56
Illens Creek Nuclear Station, Unit 1	50-466	289	Browns Ferry Nuclear Power Station,	50-296	114
rkansas Nuclear One, Unit 1	50-313	135	Unit 3	50.225	165
rkansas Nuclear One, Unit 2	50-368	218	Brunswick Steam Electric Plant, Unit 1	50-325	165
Puane Arnold Energy Center	50-331	177	Brunswick Steam Electric Plant, Unit 2	50-324	163
abcock & Wilcox Co. Critical Facility	50-13	14	Byron Station, Unit 1	50-454	281
agnac Nucleat Power Project, Philippines	STN-50-574	333	Byron Station, Unit 2	50-455	282
ailly Generating Station	50-367	216	Calloway Plant, Unit 1	STN-50-483	292
arnwell Reprocessing Plant	50-332	179	Calloway Plant, Unit 2	STN-50-486	294
arton, Unit 1	50-524	319	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	142
arton, Unit 2	50-525	319	Calvert Cliffs Nuclear Power Plant,	50-318	145
arton, Unit 3	50-526	319	Unit 2	£0 £00	224
arton, Unit 4	50-527	319	Carroll Facility I	50-599	334
caver Valley Power Station, Unit 1	50-334	181	Carroll Facility II	50-600	334
eaver Valley Power Station, Unit 2	50-412	251	Catawba Nuclear Station, Unit 1	50-413	252
ellefonte Nuclear Plant, Unit 1	50-438	260	Catawba Nuclear Station, Unit 2	50-414	252
ellefonte Nuclear Plant, Unit 2	50-439	262	CESSAR System 80	STN-50-470	290
ig Rock Point Nuclear Power Plant	50-155	18	Cherokee Nuclear Station, Unit 1	STN-50-491	297
lack Fox Station, Unit 1	STN-50-556	328	Cherokee Nuclear Station, Unit 2	STN-50-492	297
lack Fox Station, Unit 2	STN-50-557	329	Cherokee Nuclear Station, Unit 3	STN-50-493	298
lue Hills Station, Unit 1	50-510	311	Clinch River Breeder Reaction	50-537	322
lue Hills Station, Unit 2	50-511	311	Clinton Power Station, Unit 1	50-461	288
raidwood Station, Unit 1	50-456	284	Clinton Power Station, Unit 2	50-462	288
raidwood Station, Unit 2	50-457	284	Comanche Peak Steam Electric Station, Unit 1	50-445	269
owns Ferry Nuclear Power Station, Unit 1	50-259	54	Comanche Peak Steam Electric Station, Unit 2	50-446	275

Name	Docket	Page	Name	Docket	Page
Cooper Nuclear Station	50-298	116	Fulton Generating Station, Unit 2	50-464	289
Crystal River Nuclear Plant, Unit 3	50 302	119	General Atomic Co.	50-163	21
Crystal River Nuclear Plant, Unit 4	50-303	121	General Electric Test Reactor	50-70	16
Davis-Besse Nuclear Power Station, Unit 1	50-346	198	General Electric Nuclear Test Reactor	50-73	16
Davis-Besse Nuclear Power Station, Unit 2	50-500	310	Georgia Institute of Technology Research Reactor	50-160	21
Davis-Besse Nuclear Power Station, Unit 3	50-501	310	Georgia Tech Research Reactor GESSAR-238-BOP Interface	50-276 STN-50-550	80 325
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	77	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	33
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	161	Grand Gulf Nuclear Station, Unit 1	50-416	253
Donald C. Cook Nuclear Power Plant,	50-315	138	Grand Gulf Nuclear Station, Unit 2	50-417	255
Unit 1	30-313		Greene County Nuclear Power Plant	50-549	325
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	140	Greenwood Energy Center, Unit 2	50-452	281
Douglas Point Nuclear Station, Unit 1	50-448	281	Greenwood Energy Center, Unit 3	50-453	281
Douglas Point Nuclear Station, Unit 2	50-449	281	Haddam Neck Plant	50-213	25
Dow Chemical Co.	50-264	62	Shearon Harris Nuclear Power Plant, Unit 1	50-400	243
Dresden Nuclear Power Station, Unit 1	50-10	11	Shearon Harris Nuclear Power Plant,	5 0.401	244
Dresden Nuclear Power Station, Unit 2	50-237	30	Unit 2	50-401	244
Dresden Nuclear Power Station, Unit 3	50-249	40	Shearon Harris Nuclear Power Plant,	50-402	245
Erie Nuclear Plant, Unit 1	STN-50-580	333	Unit 3	50 402	246
·			Shearon Harris Nuclear Power Plant, Unit 4	50-403	246
Erie Nuclear Plant, Unit 2	STN-50-581	333	Hartsville Nuclear Plant, Unit 1	STN-50-518	314
Joseph M. Farley Nuclear Plant, Unit 1	50-348	200	Hartsville Nuclear Plant, Unit 2	STN-50-519	315
Joseph M. Farley Nuclear Plant, Unit 2	50-364	213	Hartsville Nuclear Plant, Unit 3	STN-50-520	316
Enrico Fermi Atomic Power Plant, Unit 2	50-341	0-341 194	Hartsville Nuclear Plant, Unit 4	STN-50-521	317
James A. Fitzpatrick Nuclear Power Plant	50-333	179	Edwin I. Hatch Nuclear Plant, Unit 1	50-32!	157
Floating Nuclear Plant	STN-50-437	260	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	214
Forked River Nuclear Station,	50-363	212	Haven Nuclear Plant, Unit 1	STN-50-502	310
Unit 1			Hope Creek Nuclear Station, Unit 1	50-354	205
Fort Calhoun Station, Unit 2	50-548	325	Hope Creek Nuclear Station, Unit 2	50-355	206
Fort St. Vrain Nuclear Generating	50-267	66	Humboldt Bay Power Plant, Unit 3	50-133	17
Station	JU**2\}}		Indian Point Station, Unit 1	50-3	9
Fulton Generating Station, Unit 1	50-463	289	Indian Point Station, Unit 2	50-247	37

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	91	NEP Nuclear, Unit 2	STN-50-569	333
Indonesia Research Reactor	50-384	227	New Haven, Unit 1	50-596	334
Jamesport Nuclear Station, Unit 1	STN-50-516	313	New Haven, Unit 2	50-597	334
Jamesport Nuclear Station, Unit 2	STN-50-517	314	Nine Mile Point Nuclear Station,	50-220	29
Kewaunee Nuclear Power Plant	50-305	124	Unit 1	50 410	260
Korea Research Reactor	50-351	202	Nine Mile Point Nuclear Station, Unit 2	50-410	250
La Crosse Boiling Water Reactor	50-409	248	North Anna Power Station, Unit 1	50-338	188
LaSalle County Station, Unit 1	50-373	223	North Anna Power Station, Unit 2	50-339	190
LaSalle County Station, Unit 2	50-374	225	North Anna Power Station, Unit 3	50-404	247
Limerick Generating Station, Unit 1	50-352	202	North Anna Power Station, Unit 4	50-405	248
Limerick Generating Station, Unit 2	50-353	203	North Carolina State Univ. Research	50-111	16
Maine Yankee Atomic Power Plant	50-309	128	Reactor	£0.27/	226
Marble Hill Nuclear Station, Unit 1	STN-50-546	322	North Coast Nuclear Plant, Puerto Rico	50-376	226
Marble Hill Nuclear Station, Unit 2	STN-50-547	323	Nuclear Fuels Recovery & Recycle Center	50-564	330
William B. McGuire Nuclear Station, Unit 1	50-369	220	Oconee Nuclear Station, Unit 1	50-269	67
William B. McGuire Nuclear Station,	50-370	222	Oconee Nuclear Station, Unit 2	50-270	70
Unit 2			Oconee Nuclear Station, Unit 3	50-287	95
Michigan State Univ Research Reactor	50-294	110	Ohio State Univ. Research Reactor	50-150	18
Midland Plant, Unit 1	50-329	174	Oregon State Univ. Research Reactor	50-243	33
Midland Plant, Unit 2	50-330	175	Oyster Creek Nuclear Power Plant	50-219	27
Midwest Fuel Recovery Plant	50-268	67	Palisades Nuclear Plant	50-255	51
Millstone Nuclear Power Station, Unit 1	50-245	34	Palo Verde Nuclear Station, Unit 1	STN-50-528	319
Millstone Nuclear Power Station,	50-336	186	Palo Verde Nuclear Station, Unit 2	STN-50-529	320
Unit 2	30-330	100	Palo Verde Nuclear Station, Unit 3	STN-50-530	321
Millstone Nuclear Power Station, Unit 3	50-423	257	Palo Verde Nuclear Station, Unit 4	STN-50-592	333
Montague Nuclear Power Station,	50-496	400	Palo Verde Nuclear Station, Unit 5	STN-50-593	334
Unit 1	30-490	299	Peach Bottom Atomic Power Station, Unit I	50-171	21
Montague Nuclear Power Station, Unit 2	59-497	299	Peach Bottom Atomic Power Station, Unit 2	50-277	80
Monticello Nuclear Generating Plant	50-263	60	Peach Bottom Atomic Power Station,	50, 279	82
National Bureau of Standards Reactor	50-184	22	Unit 3	50-278	04
National Naval Medical Center	50-170	21	Pebble Springs Nuclear Plant, Unit 1	50-514	312
NEP Nuclear, Unit 1	STN-50-568	333	Pebble Springs Nuclear Plant, Unit 2	50-515	313

Name	Docket	Page	Name	Docket	Page
Perkins Nuclear Station, Unit 1	STN-50-488	295	Sequoyah Nuclear Plant, Unit 2	50-328	171
Perkins Nuclear Station, Unit 2	STN-50-489	296	Shoreham Nuclear Power Station	50-322	159
Perkins Nuclear Station, Unit 3	STN-50-490	296	Skagit Nuclear Power Project, Unit 1	STN-50-522	318
Perry Nuclear Power Plant, Unit 1	50-440	264	Skagit Nuclear Power Project, Unit 2	STN-50-523	318
Perry Nuclear Power Plant, Unit 2	50-441	265	South Texas Project, Unit 1	STN-50-498	299
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	325	South Texas Project, Unit 2	STN-50-499	304
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	326	State Univ. of New York Research Reactor	50-57	16
Pilgrim Nuclear Power Station, Unit 1	50-293	108	Sterling Power Project, Nuclear,	STN-50-485	293
Pilgrim Nuclear Power Station, Unit 2	50-471	290	Unit 1	G**** 20 702	473
Plum Brook Research Reactor Facility	50-30	15	St. Lucie Plant, Unit 1	50-335	184
Point Beach Nuclear Plant, Unit I	50-266	64	St. Lucie Plant, Unit 2	50-389	234
Point Beach Nuclear Plant, Unit 2	50-301	117	Virgil C. Summer Nuclear Station, Unit I	50-395	239
Prairie Island Nuclear Station, Unit 1	50-282	88	Sundesert, Unit 1	50-582	333
Prairie Island Nuclear Station, Unit 2	50-306	126	Sundesert, Unit 2	50-583	333
Purdue Univ. Research Reactor	50-182	22	Surry Power Station, Unit 1	50-280	84
Quad-Cities Station, Unit 1	50-254	49	Surry Power Station, Unit 2	50-281	86
Quad-Cities Station, Unit 2	50-265	62	Surry Power Station, Unit 3	50-434	260
Rancho Seco Nuclear Generating Station	50-312	132	Surr; Power Station, Unit 4	50-435	260
Rhode Island & Providence Plantations AEC	50-193	22	Susquehanna Steam Electric Station, Unit 1	50-387	227
River Bend Station, Unit 1	50-458	285	Susquehanna Steam Electric Station, Unit 2	50-388	231
River Bend Station, Unit 2	50-459	286	SWESSAR-PI	STN-50-495	298
H. B. Robinson Plant, Unit 2	50-261	59	Texas A&M Univ. Research	50-128	17
RPI Critical Experiment	50-225	30	Reactor		
Salem Nuclear Generating Station, Unit 1	50-272	74	Three Mile Island Nuclear Station, Unit I	50-289	97
Salem Nuclear Generating Station, Unit 2	50-311	130	Three Mile Island Nuclear Station, Unit 2 TRIGA Mark II	50-320 50-585	147 333
San Onofre Nuclear Station, Unit 1	50-206	23	Trojan Nuclear Plant	50-344	195
San Onofre Nuclear Station, Unit 2	50-361	209	Turkey Research Reactor	50-137	18
San Onofre Nuclear Station, Unit 3	50-362	211	Turkey Point Plant, Unit 3	50-250	42
Seabrook Nuclear Station, Unit 1		266	Turkey Point Plant, Unit 4	50-251	46
Seabrook Nuclear Station, Unit 2	50-443		Tyrone Energy Park, Unit 1	STN-50-484	293
	50-444	267		50-142	18
Sequoyah Nuclear Plant, Unit !	50-327	167	UCLA Training Reactor	JU-142	10

Name	Docket	Page	Name	Docket	Page
Union Carbide Research Reactor	50-54	16	Waterford Generating Station, Unit 3	50-382	226
Univ of California at Santa Barbara Research Reactor	50-433	260	Watts Bar Nuclear Plant, Unit 1	50-390	236
Univ. of California Research Reactor	50-224	30	Watts Bar Nuclear Plant, Unit 2	50-391 50-201	238 22
Univ. of Illinois LOPRA Research Reactor	50-356	207	West Valley Reprocessing Plant		291
Univ. of Illinois Research Reactor	50-151	18	Wolf Creek Generating Station	STN-50-482	322
Univ. of Maryland Research Reactor	50-166	21	Wolsung I, Korea	50-534	
Univ. of Michigan Research Reactor	50-2	8	WPPSS Nuclear Project, Unit 1	50-460	287
Univ. of Missouri Research Reactor	50-123	17	WPPSS Nuclear Project, Unit 2	50-397	241
University Training Reactor	50-189	22	WPPSS Nuclear Project, Unit 3	STN-50-508	310
Vallecitos Boiling Water Reactor	50-18	14	WPPSS Nuclear Project, Unit 4	50-513	311
Vallecitos Experimental Superheat Reactor	50-183	22	WPPSS Nuclear Project, Unit 5	STN-50-509	311
Vermont Yankee Nuclear Power Station	50-271	72	Yankee-Rowe Nuclear Power Station	50-29	14
Virginia Polytech Institute Training Reactor	50-124	17	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	330
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	258	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	331
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	259	William H Zimmer Nuclear Station, Unit 1	50-358	207
Alvin W. Vogtle Nuclear Plant, Unit 4	50-427	260	Zion Nuclear Power Station, Unit 1	50-295	110
			Zion Nuclear Power Station, Unit 2	50-304	121

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

- DOCKET 27-039 SHEFFIELD, IL , NUCLEAR ENGINEERING CO
- BOO4010104 Forwards "Preliminary Rept on Hydrogeology of Low Level Radwaste Disposal Site Near Sheffield, IL," Open-File Rept 79-1545
- TOLER,L Q Interior, Dept of 60/03/07 1p
- ---B004010104 "Preliminary Rept on Hydrogeology of Low Level Radwaste Disposal Site Near Sheffield.IL." Open-File Rept 79-1545 FOSTER,J B. ERICKSON,J R. Interior.Dept of, Geological Survey 79-1545 B0/01/31 B7pp
- 8004020132 Requests that site be inspected when thawing occurs Bignificant trench subsidence & erosion was observed in 1979 Surface deterioration admits water & leads to increased leaching of radwaster. Particularly during spring thaw SMITH, R D Low Level Waste Licensing Branch 80/03/13 1p
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Doard notification GOSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET 27-047 BARNWELL, BC , CHEM-NUCLEAR SYSTEMS
- 8004040032 Forwards Waste Packaging Insp Rept 79-06A on 791126-29 No noncompliance noted DAVIS.A Il Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 2pp 2pp
- --B004040035 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements radiation levels removable contamination & external package features POTTER.J P. BROWN:R A Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 App
- H004040392 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch BO/02/13 2pp
- ---B004040399 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompilance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & external packaging features POTTER, J P. BROWN, R A Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 App
- 8004040450 Forwards Waste Packaging Insp Rept 79-04A on 791124-28 No noncompliance noted DAVIS.A B. Region 3. Chicago: Fuel Facility & Materials Safety Branch 80/02/13 2pp
- --8004040453 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels & marking POTTER: J P Region 3, Chicago, Fuel Facility & Materials Bafety Branch BROWN,R A Region 3, Chicago, Office of the Director 80/02/13 4pp
- 8004070131 Forwards wasta packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 2pp

- 8004100518 Forwards Waste Packaging Insp Rept 79-07A on 791219 & notice of violation DAVIS:A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/22 2pp
- --B004100522 Notice of violation from insp on 791219
 * Region 3, Chicago, Office of the Director B 80/02/22 10
- --8004100528 Waste Packaging Insp Rept 79-07A on 791219 Noncompliance noted failure to mark package as radinactive low specific activity POTTER.J P . BRGHN,R A Region 3, Chicago, Fuel Facility & Materials Safety Branch 90/02/22 3pp
- 8004040160 Forwards Waste Packaging Insp Rept 79-07A on 791219 & natice of violation
 DAVIB.A B Region 3. Chicago, Fuel Facility & Materials Bafety
 Branch 80/02/25 App
- --8004040144 Notice of violation from insp on 791219
 * Region 3, Chicago, Office of the Director 8 An/02/25 1o
- ~-8004040171 Waste Packaging Insp Rept 79-07A on 791217 Noncompliance noted cask shipped from facility not marked "Radioactive LSA," as required POTTER, J P. BROWN, R A Region 2, Atlanta, fuel facility & Materials Safety Branch 80/02/23 4pp
- 8004080135 Forwards Water Packaging Insp Rept 80-01 on 800131-0201 No noncompliance noted STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/25 3pp
- --8004080140 Waste Packaging Insp Rept 80-01 on 800131-0201 No noncompliance noted Major areas inspected DDT & NRC requirements including shipping paper DDT placard, radiation levels, removable contamination & labeling PDTYER, J P. PEERY, W W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/21, 4pp
- 8004080145 Forwards Waste Packaging Insp Rept BO-02A on 800206-08 No Noncompliance noted

 STOMR.J.P Region 2. Atlanta, Fuel Facility & Materials Safety
 Branch 80/02/26 5pp
- --B0040B0147 Waste Packaging Insp Rept 80-02A on 800206-08 No noncompliance noted. Major areas inspected DDT & NRC requirements including shipping paper DDT placard, radiation levels.marking & labeling. POTTER.J P. BROWN.R A Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/02/20 4pp
- 8004140165 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted
 SMITH.Q H Region 1. Philadelphia, Fuel Facility & Materials Safety
 Branch 80/02/27 2pp
- --B004160172 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected radiation levels, shipping paper requirements removable contamination & labeling requirements for packages POTTER.J P. BROWN, R.A. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 79/12/12 7pp
- 8004210027 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No oncompliance noted.

 BHITH OH Region 1. Philadelphia, Fuel Facility & Materials Safety
 Branch BO/03/05 1p

- --8004210034 Waste Packaging Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external feature requirements
 POTTER, U.P., PEERY, W.W., WOODRUFF, R.L. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 8004210029 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted SMITH:0 H Region i, Philadelphia. Fuel Facility & Materials Safety Branch 80/03/05 ip
- --800421003\$ Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels, memorable contamination & package external feature requirements FOTTER, J.P., BROWNR A. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/12/12. 7pp
- 8004210074 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH, G H Region i, Philadelphia, Fuel Facility & Materials Bafety Branch B0/03/09 2pp
- --8004210076 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels removable contamination & package external feature requirements FOTTER.J P. PEERY.W W. WOODRUFF.R L. Region I. Philadelphia. Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 8004210079 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH.G H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 299
- ---8004210082 Waste Packaging Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels removable contamination & packaging external feature requirements POTTER.J P. PERRY.M W. HOODRUFF.R L. Ragion i, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/18. 7pp
- 8004210115 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted. SMITH.0 Rt Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- ---8004210120 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements padiation levels removable contamination & package external feature requirements POTTER.JP., BROWN.RA Region 1. Philadelphia. Fuel Facility & Materials Esfety Branch 79/12/12 7pp
- 8004210334 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH, 0 H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --8004210339 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected: shipping paper requirements. DOT placarding requirements. radiation levels, removable contamination & DOT/NRC marking & labeling POTTER, J P., PEERY, W W. NOODRUFF, R L Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 9004210349 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No oncompliance noted 4ITH, 0 H. Region i. Philadelphia, Fuel Facility & Materials Safety anch 80/03/05 2PP
 - 04210345 Waste Pactaging Insp Rept 79-07A on 791212-13 No noncompliance noted. Major areas inspected; shipping paper requirements, DOT placarding, madiation levels, removable contentnation, DOT marking & labeling & external features POTYER, J P., PEERY, W W. WOODRUFF, R L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 6004220379 Forwards Waste Packaging Insp Rept 79-07A No noncompliance noted SMITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 60/03/05 2pp.
- --8004220402 Maste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected review of shipping papers radiation survey of vehicles contamination surveys & radiation level surveys of packages POTTER, J. P., PEERY, W. W. WOODRUFF, R. L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/18 7pp

- 8004280280 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH.O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --8004280288 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Mayor areas inspected shipping paper requirements.DDT placarding requirements.radiation levels & removable contamination HDDRWFF.R L . PEERY.U W . POTTER, I P Region 1, Philadelphia. Office of the Director 80/01/19 7pp
- 8004280277 Forwards IE Insp Rept 50-293/79-23 & Waste Packaging Insp Rept 79-088 on 791227-28, 800104 & 791218, respectively GRIER.B H Region 1, Philadelphia, Office of the Director 80/03/06 2pp
- --8004280310 Waste Packaging Insp Rept 79-088 on 791218 Noncompliance noted radiation layels in excess of specified limits BROWN.R A. POTTER.J P Region 1. Philadelphia. Office of the Director 79/12/21 3pp
- 8004070410 Forwards FR notice of availability of applicant OL application environ assessment & opportunity to request hearing DRAGONETTE, K S Low Level Waste Licensing Branch 80/03/13 ip
- --8004070414 Notice of availability of applicant OL application.environ assessment & opportunity to request hearing DRAGONETTE.K S Low Level Was'te Licensing Branch 80/03/13 3pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 77-07A Requests that rept sent on 800222 be destroyed DAVIS.A B Region 3, Chicago. Fusi Facility & Materials Safety Branch 80/03/21 ip
- --8004040017 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted BAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels; removable contamination & package external features
 POTTER.J P Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/02/22 7pp.
- B004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13. No noncompilance notes DAVIS. A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22. 2pp
- ~~E004i00408 Waste Packaging 79-07A on 8079i2i2-i3 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DDT labeling PDTTER, J P. Region G. Chicego, Fuel Facility & Materials Safety Branch B0/02/22. App
- DOCKET 27-048 RICHLAND, WA , NUCLEAR ENGINEERING CO
- 8004210015 Forwards Waste Packaging Insp Rept 80-06 on 600128-0201 No noncompliance noted. 6HITH O H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/03/31. 2pp
- ~~8004210020 Waste Packaging Insp Rept 80~06 on 800128-0201 No noncompilance noted Major areas inspected proper vehicle placarding, package integrity & package labeling & marking BOOK, H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch. CAIN, C L Region 4. Dallas, Office of the Director 80/02/27 App.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0215 B F. APPLIANCE: LTD

- 8003310412 Discusses IE insp of License STB-259 on 800124 & 28 & forwards notice of violation KEPPLER, J & Region 3, Chicago, Office of the Director 80/03/03, 3pp
- ---B003310416 Notice of violation from insp on 800124 & 28 Noncompliance noted, survey data & info obtained during 1979 not available for review Burveys performed by consultant firm between Aug & Oct 1979 not documented & given to licensee # Region 3. Chicago, Office of the Director B0/03/03 App.

DOCKET 40-0261 KERR MCKEE CHEMICAL CO

- 8004100548 Forwards IE Insp Rept 40-0216/79-01 on 791220-800104 Ne noncompliance noted KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/13 2no
- --8004100551 IE Insp Rept 40-0216/79-01 on 791220-800104 No noncompliance noted Major areas inspected allegations that unsurveyed, steel beam had been remayed from facility & installed in residence during 1976
 PAPERIELLO,C , NOVELIUS,C E , WEIL,C H Region 3, Chicago, Office of the Director 80/02/07 7pp

DOCKET 40-0299 UNION CARBIDE CORP

- BOO4240499 "Geotechnical Investigation of Proposed Evaporation Pond, East Gas Hills, WY for Union Carbide Corp " MURDDCK, L T , NEWTON, S M Dames & Moore 79/09/10 78pp
- 8004090347 Forwards request to State of WY Dept of Environ Guality for increase in reclamation bond for projected costs of below grade tailings disposal area & evaporation pend area WDNG.T Union Carbide Corp 80/03/12 3pp.

DOCKET 40-0672 NUCLEAR METALS: INC

- 8004210029 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 60/03/05 ip
- --B004210035 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, memorable contamination & package external feature requirements POTTER, J.P., BROWN, R.A. Region i, Philadelphia, Fuel Facility & Materials Safety Branch 79/12/12 7pp

DOCKET 40-1162 WESTERN NUCLEAR, INC.

- 8004090064 Forwards 800301 revised renewal application for Source Matis License 8UA-56 W/o encl 8000EN, O Westinghouse Electric Corp 80/03/04 ip
- 8004090250 Discusses investigation to determine if radon checks mentioned in encl EPA 730108 itr were completed Forwards Jul 1972 "Western Nuclear News," 800226 article from Riverton Ranger BOODEN,O Western Nuclear, Inc. (subs of Phelps Dodge Corp.) 80/03/04 4pp
- BOO4090255 Forwards BOO301 revised renewal application for Source Matls License SUA-56 W/p encl BOO2EN.0 Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) BO/03/04 ip
- 8004080606 Submits justification for deviation from operational quidelines re use of pipe-in-pipe sys as discussed w/NRC on 770926 & 27 Lists disadvantages of sys & proposes alternative BOODEN, 0 Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.) 80/03/07 3pp
- BOO4070259 Requests that review time be set aside to prepare safety evaluation for proposed tailings dam raise at U mill by BOO324 Safety evaluation must be completed before license can be renewed Further delays will mean wasted time BCARANO,R.A. Uranium Recovery Licensing Branch 80/03/13 1p
- B004080607 Responds to concerns in B00131.0214.15 & 18 ltrs re renewal of Bplit Rock mill license Reference to 10CFR2 206 in hearing request re renewal not applicable NRC has no direct authority over mining or haulage of ore.

 LINEHAN.J.J Uranium Recovery Licensing Branch 80/03/15 3pp
- BOO4070424 Notifies that transmittal ltrs for distribution of U mill FEB were hand carried to Document Distribution Svcs Branch on BO0221 Total of 192 FEB were mailed on BO0222 FEB Uranium Recovery Licensing Branch. BO/03/17 1p

- B0042200B3 Requests reconsideration of NRC recommendation for continued use of present tailings pond at Jeffrey City, WY Potential contamination of moving underground water endangers human & animal life BUN.8 Affiliation Unknown B0/03/18 ip
- 8004210387 Forwards notice of intent to appeal final EI8 re operation of Split Rock U Mill EA8T.D J Wyoming Outdoor Council 80/03/21 ip
- --8004210388 Notice of intent to appeal final EIS re operation of Split Rock U Mill BOOKE, B L. Wyoming Outdoor Council BOOKE, B L. Affiliation
- B004110135 Summary of 800311 meeting w/vendor in Silver Spring,MD rereview of updated radiation safety program incorporating generic changes since 1976 license revision & environ monitoring program contained in FEB GARCIA.P J Vranium Recovery Licensing Branch 80/03/25 3pp
- 8004280212 Reports review of 780823 & 790719-20 repts & enforcement records No noncompliance found & no license revisions recommended MDDLSEV.R T Uranium Recovery Licensing Branch 80/03/28 ip

DOCKET 40-1193 BABCOCK & WILCOX

- 8004160027 Notifies that Source Matls License SMB-502 is terminated Activities authorized under license were incorporated into Source Matls License SNM-145 PAGE,R Q Uranium Fuel Licensing Branch 80/03/27 ip
- DOCKET 40-1341 EDGEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC.
- 8004080207 Forwards Revision 2 to decommissioning plan environ rept. Revision replaces existing Section 4 4 re geology MILLS.L M Tennessee Valley Authority 80/02/26 ip
- --8004080210 Revision 2 to decommissioning plan environ rept/replacing existing Section 4.4 re geology # Tennessee Valley Authority 80/02/26 9pp
- 8004020169 Requests legal opinion for U mill tailings in locations away from licensed U recovery facility sites Residents of Edgemont, 8D were exposed to high radiation levels NRC role in control of offsite tailings is in question DIRCKS:N J Office of Nuclear Material Safety & Safeguards 80/02/27 2pp
- 800402004B Requests info re acquisition date for License SUA-816, whether license was transferred from Busquehanna Hestern or applied for separately & when license is up for renewel or expiration Discusses requested info re other mills BUCKB, N Black Hills Alliance 80/03/05 ip.
- 800408028B Responds to Subcommittee on Nuclear Regulation 800116 inquiry about NRC activities re health & safety of residents near facility Program to define & remove offsite tailings in progress No agency clearly responsible for remedial actions. AHEARNE, J F Commission 80/03/13 2pp.
- --8004080300 Responds to 800114 inquiry about NRC activities we health & safety of residents near facility Program to define & remove offsite tailings in progress No agency clearly responsible for membial actions

 AHEARNE, J F Commission 80/03/13 2pp
- --8004080305 Responds to 800116 inquiry about NRC activities re health & safety of residents near facility Program to define & remove offsite tailings in progress No agency clearly responsible for remedial actions

 AHEARNE, J F Commission 80/03/13, 2pp
- --8004080314 Requests info on NRC activities re health & safety of residents near facility. Also requests notification of related progress & problems.

 HART, G. SIMPBON, A. K. Senate, Environment & Public Works.

 MCOCIVERN, G. Senate 89/01/16 ip

004070428 Responds to 800206 request for clarification re info requested by NRC concerning potential for groundwater contamination at tallings disposal site Depth to unjointed unweathered low permeability shale should be determined MILLER: H J Uranium Recovery Licensing Branch 80/03/17 4pp

304290070 Advises that J Jacobs will respond to future questions concerning use of Bureau of Land Mgt administered lands near Edgemont, SD for U tailings disposal site Requests lead time to review draft EIS re decommissioning plan * Interior, Dept of, Dureau of Land Management 80/03/17 ip

004280056 Forwards Revision 3 to decommissioning plan environ rept, providing reclamation info & specific discussion of surface water quality impacts
MILLS.L M Tennessee Valley Authority 80/03/25 ip

-8004280060 Facility decommissioning plan environ rept.Revision 3 # Tennessee Valley Authority 60/03/25 126pp

ICKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP

04030303 Responds to FOIA request for info re thorium residuals in West Chicago, IL Forwards documents listed in App A FELTON, J.M. Division of Rules and Records 80/03/27 2pp

8004030330 "Praft Environ Assessment re Kerr-McGee Chemical Corp - West Chicago Characterization of Geohydrology & Subsurface Chemistry " Argonne National Laboratory 77/05/31 190pp

O4080158 Forwards transmittal ltrs to distribution list which accompanied decommissioning & stab(lization plan for West Chicago facility SHELLEY, W J Kerr-McGwe Nuclear Corp 79/08/17 3pp

8004080169 Forwards decommissioning & stabilization plan for West Chicago facility W/o enci RICE,G B Kerr-McQee Corp 79/08/15 App

340G0147 Bubmits response to stabilization plan by Kerr-McGee Corp for decommissioning West Chicago Facility Proposed detention passin must be designed in accordance whiceal water profinences & city soil & erusion control ordinance GSTER, J D West Chicago, IL 79/09/19 2pp

34080181 Confirms 791101 telcon re notification from C Wenk that numerous matls used to build home were obtained from terr-Hidder factory site Requests that measurements be taken other matls located & measured (ANSELL.D Illinois, State of 79/11/02 2pp

AOBOD92 Advises that participation is welcome in 791218 meeting /public in West Chicago High School re stabilization plan or decommissioning facility ATALAND. G R Chicago. City of, IL 79/12/05 2pp

4080177 Requests assistance in selecting remote site for waste torage from defunct Kerr-McOee factory Based on advice from tate of IL Geological Burvey re unsite buriel problems, city * seeking geologically suitable site ENNELS, A.E. Chicago, City of IL 80/01/07 2pp

4040188 Requests apportunity to review EIS for plan to ecommission facility Early input from EPA could reduce slays that might arise at later date VMLOR.D J. Environmental Protortion Agency 80/01/11 ip

4070151 Advises that per 791218 public meeting progosal, interested arties are requested to submit alternatives to proposed 5site burial of defunct factory waste per stabilization lan for decommissioning site NNEY, J. L. Kerr-McGee Corp. 80/01/14 3pp

\$180061 Advises of present facility security program Gloss Guard & wastigations Svc. Inc provides 24-h coverage & regular Italia Inspa conducted of perimeter fences Signs & closures 'e made & identification cards used NNY.T.L. Herr-McQee Corp 80/01/28 ip

040480 Forwards Waste Packaging Insp Rept 75-06A on 791126-28 noncompliance noted VIS.A B. Region 3, Chicago, Fuel Facility & Materials Safety anch 80/02/13 2pp

---8004040453 Waste Packaging Insp Rept 79-06A on 791124-28 No noncompliance noted Major areas inspected shipping paper t DOT placarding requirements; radiation levels & marking requirements
requirements
POTTER, J P Region 3, Chicago, Fuel Facility & Materials Safety
Branch BROWNR A Region 3, Chicago, Office of the Director
80/02/13 4pp

BOO402026B Requests enci Exhibits I-IV be added to Investigative Rept 40-2061/79-01 Exhibits inadvertently omitted from rept KEPPLER.J G Region 3. Chicago. Office of the Director BO/03/04

--8004020273 Ack receipt of 791113 ltr re transfer of matl from site by M Aver Question exists about accuracy of record of transfer HANSELL, D Illinois, State of 79/11/19 ip

--8004020274 Discusses alpha survey of homes in West Chicago, IL re-const matl from Kerr-McOge site All readings were background level BURGIN, R E Region 3, Chicago, Office of the Director 79/12/04

--B004020276 Testimony re use of matl from Kerr-McGee factory site to construct residence in West Chicago IL AVER.A A Mike Auer Construction Co 79/12/20 1p

8004210348 Submits key dates in schedule for response to comments from various agencies re West Chicago stabilization plan Vendor will edit responses on 800409-10, complete draft w/edit change on 800415 & submit revised plan by 800501
DENNY,T L Kerr-McGee Corp 80/03/17 ip

8004220066 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/04

DOCKET 40-2259 PATHFINDER MINES CORP

8004020291 Forwards radiation surveys for beta-gamma radon daughters & contamination levels of solvent extraction circuit
NUGENTLE L' Pathfinder Mines Corp 80/03/03 14pp

DOCKET 40-2286 WESTINGHOUSE ELECTRIC CO

8004160079 Discusses IE insp of License 40-2286/80-01 on 800211 No noncompliance noted Major areas inspected decontamination of drains & radiation readings MCCLINTOCK,R O Region 1. Philadelphia. Office of the Director 80/02/29 2pp

DUCKET 40-3453 ATLAS MINERALS

8004080085 Forwards "Effluent Monitoring Rept, Jul-Dec 1979 " Mill no longer releases liquid effluent to unrestricted areas EDMARDS,D L Atlas Minerals 80/02/28 [p,

--8004080057 "Effluent Manitoring Rept. Jul-Dec 1979 " * Atlas Minerals 80/02/28 iipp

B004220099 Requests amend to License Condition 16 2 responds to questions in NRC 800219 itr re-potential flood erosion at mill tailings dam Amend requires strengthening of riprap near Section E from existing 4-inch thickness to meet specs SWANBY, G T Atlas Minerals 80/03/13 6pp

8004290449 Forwards "River Water Sample Analysis Jul-Dec 1979." not received w/original rept transmitted 800228 EDWARDS.D L Atlas Minerals 80/03/24 Ip

~8004290452 "River Water Bample Analysis Jul-Dec 1974" # Atlas Minerals 80/03/24 200

8004270110 Forwards consultant repts on tailings retention sys const Also forwards list of specs to be used as guideline during insps at Shootering Cangon site BCARANG,R A Uranium Recovery Licensing Branch B0/04/16. 1p

~-8004270115 Summary of 771004 meeting w/United Nuclear Corp.Dames & Moore & US Army Gorps of Engineers in Casper.WY re hydrologic & geotechnical engineering considerations in United Nuclear rept to be submitted late-Oct 1977. KANEL D. Division of Site Safety & Environmental Analysis 77/10/13 Spp

DOCKETED ITEMS

- --B004290119 Forwards input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Applicant should be informed that 9 ft of freeboard will be required in event dam is raised to ultimate elevation of 5, 282 ft HULMAN.L G Hydrology Meteorology Branch 79/01/11 2pp
- --8004270121 Input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Total freeboard of 9 ft should be provided * Hydrology Meteorology Branch 79/01/11 4pp
- --B004290125 Supplements 790111 input to SER re proposed freeboard not being conservative Should be license condition to assure that applicant does not initiate tailings storage until dam is ultimate height Nine-ft freeboard still adequate HULMAN.L G Hydrology Meteorology Branch 79/05/10 2pp

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MININO)

- 8004070238 Comments on environ rept for expansion of U mill Species lists are too lengthy considering lack of impacts Discussion of groundwater connention between Gas Hills area & Platte river sys should be included HALL, J D Interior, Dept of 80/02/25 ip
- 8004070181 Discusses scoping of draft EIS on Federal American Partners U mill, supplementing comments transmitted previous wk Urges NRC to consider belt filtration or other techniques for producing dry tailings, if seepage to groundwater identified DANIELSON, L. J. National Wildlife Federation 80/02/28 2pp
- 8004020053 Submits addl comments on scoping of DES for relicensing of facility NRC should obtain info from biologists w/knowledge of local conditions before drawing conclusions re migration patterns of deer & antelope in area DANIELSON,L J National Wildlife Federation 80/03/07 2pp
- 8004300043 Ack receipt of 800301 & 791113 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 40-4492/ 79-03 8RGUN. 9.D, Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/03/21 1p
- Branch 80/03721 1p
- --8004300053 Responds to NRC 800220 ltr w/add1 info re violations noted in IE Insp Rept 40-4492//9-03 Micrograms per liter should be substituted for millipsentgens in Sub 1 of vendor 791113 ltr WRIGHT,K H Federal American Partners 80/03/01 1p
- --8004300059 Ack receipt of 791113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-4492/79-03 Requests add1 info per 800215 telcon re Item 2 controls BROWN, 0 D. Region 4, Dallas, Fuel Facility & Materials Bafety Branch 80/02/20 1p
- --8004300065 Responds to NRC 791016 ltr re violations noted in IE Insp Rept 40-4492/79-03 Corrective actions signs have been posted, bloassay programs strengthened & repts will be sent by closing date WRIGHT,K H Federal American Partners 79/11/13 3pp
- ---800430006B Forwards IE Insp Rept 40-4492/79-03, on 790627-28 & notice of violation BROHN, G.D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/10/16 2pp
- --8004300075 Notice of violation from insp on 790427-28 * Region 4, Dallas, Office of the Director 79/10/11 ip
- --8004300081 IE Insp Rept 40-4492/79-03 on 790627-28. Noncompliance noted failure to post radiation area signs to implement bicassay program & to submit effluent rept on time BROWN. O D Region 4. Dallas. Fuel Facility & Materials Safety Branch CAIN. C L . HARRISON. H C Region 4. Dallas. Office of the Director 79/10/11 10pp

DOCKET 40-6329 CATHOLIC UNIV OF AMERICA

8004070089 Ack receipt of 800225 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-00638/80-01, 40-6227/80-01 & 70-0190/80-01 MCCLINTOCK: R D Region 1, Philadelphie, Office of the Director 80/03/04 1p.

- --8004070099 Responds to NRC 800204 ltr re violations noted in IE Rept 30-00638/80-01.40-6329/80-01 & 70-0190/80-01 Corrective actions separate eating space provided for dept of biology & technicians reinstructed re mat
- -8004070104 Forwards IE Insp Repts 30-00638/80-01,40-6329/80-01 70-0190/80-01 on 800116 & notice of violation MCCLINTOCK 0 Region 1, Philadelphia, Office of the Direct 80/02/04 2nn
- --8004070107 Notice of violation from insp on 800116 Noncompliance failure to instruct technicians working in lab on procedures for handling radigactive matls Failure to wear protective gloves & having food in restricted area Region 1. Philadelphia, Office of the Director 80/02/04

DOCKET 40-6622 PATHFINDER MINES CORP

8004290444 Forwards in-vivo info for inclusion in data base for U milling facilities HENDERSON, D. M. Pathfinder Mines Corp. 80/03/25 14pp

DOCKET 40-6659 PETROTOMICS CO , GETTY DIL

- 8004070144 Forwards revised repts showing release amounts per stac sampling test at facility from Aug-Oct 1978 & May 1979 PPAFF.8 J Getty Oil Co , Petrotomics Co Div 80/02/20 ip
- --8004070195 Submits list of particulate in form of stack gases reinto unrestricted areas.including U.Ra-226.Th-230 & Rn-222 No radionuclide liquid effluents released to unrestricted areas during six months prior to 800101.

 PFAFF.S J Getty Oil Co., Petrotomics Co. Div. 80/02/20 1p
- --8004070159 Submits list of particulate in form of stack gases reinto unrestricted areas, including U.Ra-226, Th-230 & Rm-222 No radonuclide liquid effluents released to unrestricted areas during six months prior to 790101 PFAFF, S. J. Getty Oil Co., Petrotomics Co. Div. B0/02/22 ip
- --8004070164 Submits list of particulate in form of stack gases reinto unrestricted areas, including U,Ra-226,Th-230 & Rn-222 No radionuclide liquid affluents released to unrestricted areas during six months prior to 790701
 PFAFF,S J Oetty dil Co . Petrotomics Co Div 80/02/22 ig
- --8004070169 Submits list of particulate in form of stack gases re into unrestricted greas including U,Ra-225.Th-230 & Rn-222 No radionuclide liquid affluent released to unrestricted greas during six months prior to 780701 PFAFF,S U Getty Oil Co., Petrotomics Co. Div. 80/02/22, 1p
- BOD4270110 Forwards consultant repts on tailings retention sys con Also forwards list of specs to be used as guideline during insps at Shootering Canyon site BCARAND, R.A. Uranium Recovery Licensing Branch BO/04/16 is

DOCKET 40-7127 TOLEDO, UNIV OF

- 8004020477 Forwards notice of violation from IE insp of Licenses 34-10247-06, 800-815 & 8NM-915 on 800219-20 DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch. 80/03/24 2pp
- --8004020482 Notice of violation from insp on 800219-20. Noncomplian noted food consumed in room & stored in refrigerator w/ radioactive isotopes.no neutron survey meter available for monitoring & no leak test records available for 1978 * Region S. Chicago, Office of the Director 80/03/24 is

DOCKET 40-7982 HONEYWELL, INC

8004220045 Forwards IE Info Notice 80-14, "Bafety Buggestions From Employees" No action required.

KEPPLER, J. G. Region S. Chicago, Office of the Director. 80/04/10

DOCKET 40-8027 KERR-MCGEE CORP

BCO4070356 Requests addl info in response to vendor BO0129 application for 1780 fertilizer test program Matl balance & flow diagram for raffinate treatment sys starting w/raffinate from U purification circuit. is needed NIXON.W.A. Uranium Fuel Licensing Branch BO/03/13 2pp

DOCKET 40-8054 EXXON MINERALS CO USA, EXXON CORP

8004080198 Submits 1979 fourth quarter rept for U solution mine pilot operations Restoration operations at original pilot continue to be primary source of fluids from solution mining activity to tailings pond Sample analysis results 2 plan maps entl TRUSSELL. H H Exzon Minerals Co , USA 80/02/25 16pp

DOCKET 40-8102 EXXON MENERALS CO USA, EXXON CORP

8004070154 Forwards response to 800204 questions re License 6UA-1137 Encl Figures 1-4 placed in Central Files ORTLOFF: 0 D Exxon Minerals Co., USA 80/02/28 10pp

8004280403 Responds to recent NRC request for correspondence re renewal of License 8UA-1139 W/o enci ORTLOFF, G D Exxon Minerals Co , USA 80/03/27 ip

8004270526 Forwards application submitted to State of WY Dept of Environ Quality for amend to allow commercial scale solution mining operation W/o encl. GRTLOFF; & D. Erzon Minerals Co., USA 80/03/27 Ip

DOCKET 40-8135 3M CQ . MINNESOTA MINING & MFO CO

8004040095 Forwards IE Insp Rept 80-01 of Licenses 22-00057-06 & 8TB-1127 No noncompliance noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch B0/02/07 2pp

--8004040102 IE Insp Rept 80-01 of Licenses 22-00057-06 & STB-1127 on 800108-11 No noncompliance noted Major areas inspected licensee action of previously identified enforcement matters, radiation protection procedures, audits & equipment PAPERIELLO.C.J., DICEY, B B. OBERG, C. T. Region 3, Chicago, Office of the Director 80/01/30 12pp

DOCKET 40-8304 WYOMING MINERAL CORP

BOO42BORB3 Amend to BOO205 renewal application for License BUA-1204 Condition 8 is amended by striking Nall, AB, Dewey & Ball Claims Conditions added re restoration of groundwater quality in aquifers & completion of amo

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO

8004070186 Notifies that state engineers permit not necessary for new evaporation reservoir Ltr to be sent to Rocky Mountain Energy Co requesting termination of LESI, which authorized borehole mining project MORROW, D. Wyoming, State of 80/02/25 ip

8004080203 Forwards correspondence w/state of WY.including water sample results notices of violation & responses for NRC files NEUMANN M R Rocky Mountain Energy Co. 80/02/29 25pp

B004250023 Forwards water sample results for B00226 & 0304 samplings Includes values for arsenic, selenium & U for B00204 NEUMANN, M R Rocky Mountain Energy Co. B0/03/11 Spp

DOCKET 40-8452 BEAR CREEK URANIUM CO

8004100249 Forwards Drawing I-2 to be included in App I & revised Drawing 174-01-0-094 to be included in App H, omitted from 800130 tailings mgt plan. Encl Drawings 174-PF-D-75 & 174-PF-D-77 W/revisions supersede those in App H HERBLOFF, L. W Rocky Mountain Energy Co 80/02/26 18pp.

--8004100257 "Lang Creek Drainage After Reclamation Water Surface Profiles." 4 Rocky Mountain Energy Co 80/02/25 1p

- --8004100263 "Lang Creek Dreinage After Reclamation Plan View "
 * Rocky Mountain Energy Co 80/02/28 Ip
- --8004100264 "North Area After Reclamation " Figure I-2 * Rocky Mountain Energy Co 78/08/25 ip
- --8004100272 "Probable Max Flood.Flood Plain at 8-3 Prt "
 s Rocky Mountain Energy Co 80/02/26 1p
- --8004100276 "Cross Sections for Datermination of Probable Max Flood, Flood Plain " * Rocky Mountain Energy Co 80/02/26 ip
- BOO4070249 Recommends issuance of Amend & to Bource Matl License SUA-1310, authorizing mod of submittal dates for grizzly operation sampling & background radioactivity study Submittal date changed from 800201 to 800501 GARCIA,P J, LINEHAN, J J Uranium Recovery Licensing Branch BO/03/17 1p
- 8004070412 Advises of Amend & to License BUA-1310 authorizing changes in submittal dates for grizzly operation sampling data & background radioactivity study SCARAND,R A Uranium Recovery Licensing Branch 80/03/17 2pp

BOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP

8004020160 Summary of 800121 meeting u/vendor in Silver Spring, MD reresponses to NRC questions & clarifications concerning amond application to increase plant flow rate capacity from 800 to 2,000 gpm COOPERSTEIN, R Uranium Recovery Licensing Branch 80/02/08 2pp

B004070235 Responds to 800201 request for copy of vendor response to NRC 791220 itr re 2.000 gpm amend request Copy of vendor response was hand-delivered to N° Dept of Environ Guality on 800205 Addl copy will be sent as soon as possible WICHERS.D.L. Wyoming Mineral Corp. B0/02/14 ip

8004070244 Notifies that WY Mineral Corp. WY Permit 478 allows max flow rate capacity for Irigarag Plant of 1600 gpm in response to 791228 request If vendor wished to increase capacity, itr of request will be submitted WICHERS.D L Wyoming Mineral Corp. 80/02/14 1p.

8004070195 Confirms 800212 tolcon re startup of yellowcake dry-pack/ calciner operation per License SV-1341 NRC given required min of 90 days advance notification on 790719 WICHERS,D L. Wyoming Mineral Corp., 80/02/20 ip

8004040227 Summarizes 800218 meeting re restoration of alternato lixiviant wellfields, shallow zone excursion & future mine plans Map & agenda enci HOHNE,F C Westinghouse Electric Corp , Wyoming Mineral Corp 80/02/22 App

8004040221 Forwards groundwater restoration plan for Alternate Lixiviant Welifield E FORD,W H Westinghouse Electric Corp . Wyoming Mineral Corp 80/02/25 12pp

8004030184 Responds to 800128 ltr re transfer of surface wastes from solution mining operations to mill tailings area View re applicability of 10Cff40 24 is correct
SCARAND,R A Upanium Recovery Licensing Branch 80/02/28 ip

8004020155 Requests meeting w/NRC on 800312 to discuss cleanup of shallow tone excursion, groundwater restoration of first wellfield conversion of plant to alternate limitant & detailed answers to questions of concern FORD,W H Wyoming Mineral Corp 80/03/04 ip

80040B0219 Forwards MY Mineral Corp 800227 ltr forwarding comments re Btate of MY insp repts for facility Soil erosion plan has been developed, Review of well field roadway sys in progress MICHERG D L. Westinghouse Electric Corp . Nyoming Mineral Corp 80/03/04 Spp

8004090070 Forwards 800306 ltr to Btate of WY w/weekly water quality results for shallow monitor & shallow research wells from samples taken 800213,19 & 26 Pietometric contour maps & arsenic & selenium assay valves from 800213 also encl WICHERS,D L. Wastinghouse Electric Corp , Wyoming Mineral Corp 80/03/06 12pp

800409023; Forwards shallow zone cleanup plan, in support of 790629 application to amend License SUA-1341 FORD, W.H. Myoming Mineral Corp. 80/03/07 11pp

- 8004220088 Responds to 800214 meeting request for clarification of Condition 11 of License SUA-1341 Candition 11 interpreted to refer to production flow rates from mining activities & not restoration flow rates from cleanup Wyoming Mineral Corp B0/03/10 1e
- 8004240178 Forwards rept, "Groundwater Restoration Plan for Production Wellfield A," provided in accordance w/NUREG-0481 Requests authorization to implement plan FORD W H Wyoming Mineral Corp 80/03/10 2pp
- --8004240207 "Groundwater Restoration Plan for Production Wellfield A "
 * Wyoming Mineral Corp 80/03/10 12pp
- BOO411016B Bummary of 800207 meeting w/WY Mineral Corp in Bilver Spring.MD re status of ongoing lixiviant excursion into shallow aquifer from current operations & licensee responses to questions re amend application COOPERSTEIN.R Uranium Recovery Licensing Branch 80/03/14 3pp
- 8004070387 Approves implementation of 800225 groundwater re-of alternate lixiviant well field E plan Requests monthly progress 1tr be submitted re developments & possible LINEHAN, J.J. Uranium Recovery Licensing Branch 80/03/18 1p
- 8004220076 Advises of intent to conduct radon emissions study of alternate lixiviant process to obtain estimate of radon emissions associated u/groundwater cleanup activities at Alternate Lixiviant E Wellfield Wyoming Mineral Corp 80/03/19 ip
- 8004290075 Advises that WY Land Quality Div presently considers shallow tone excursion uncontrolled SM-4 in Field F has been above upper control limit for chloride & conductivity for two ORROW,D Myoming, State of 80/03/21 ip
- BOO4210413 Forwards 800325 itr to State of WY including weekly water quality results for shallow monitor & shallow research wells for 800307.11 & 21 Shallow monitor well SM-4 exceeded upper control limits for chloride for two consecutive samples WICHERS.D L Hyoming Mineral Corp 80/03/26 10pp
- DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO
- 8004070262 Submits info re composition of matl underlying tailings cells in response to NRC request Subsurface strata is mostly poorly communed arxisic sandstone w/interbedded layers of harder siltstone Cites reference works documenting info ACOBYA, A P Union 76 Minerals Exploration Co 80/02/26 ip
- DOCKET 40-8602 UNITED NUCLEAR CORP
- 8004280423 Forwards repts & drawings prepared by CO State Univ of U Mill project ROSEBACH, L 79/08/15 ip Uranium Recovery Licensing Branch FIN 8-4434-9
- --8004280425 Summary of 790224 site visit to assess diversion ditch design & total drainage area of U operation Assessment rept BIMMONS.D D . RUH-MING.L. Colorado State Univ 79/03/22 11pp
- --8004280427 "Assessment of Diversion Ditch Design at Morton Ranch U Mill.WY " SIMMONS,D B , RUH-MING,L Colorado State Univ FIN 8-6436-9
- 8004070242 Notifies that foundation excavation for effluent evaporation pond & embankment is nearing completion & that placement of enhankment fill will commence, weather permitting, on or after
- WOLFF.C E United Nuclear Corp 80/02/27 1p
- 8004290036 Requests that IE conduct insp of foundation excavations for tailings embankment & evaporation pond at Morton Ranch mill tailings pand embankment at Shootering Canyon mill Morton Ranch license encl
 SCARAND.R A Uranium Recovery Licensing Branch. 80/04/02 1p
- ---800429004: License for United Nuclear Corp for possession of byproduct matl in form of U waste tailings generated by milling operations authorized Under License SUA-1356 BCARANO.R O Uranium Recovery Licensing Branch 79/05/10 7pp

- --8004290044 Amend to License SUA-1371 Amend 1 authorizes const of embankment for tailings impoundment SCARANO,R A Uranium Recovery Licensing Branch 79/09/28 Spp
- 8004300106 Requests that IE inspect foundation excavations for tailings pond embankment & evaporation pond at Morton Ranch & tailings pond embankment at Shootering Canyon Summary of specs encl
 SCARAND,R A Uranium Recovery Licensing Branch 80/04/02 2pp
- 8004270110 Forwards consultant repts on tailings retention sys const Also forwards list of specs to be used as guideline during insps at Bhootering Canyon site SCARAND,R A Uranium Recovery Licensing Branch 80/04/16 ip
- --8004290115 Summary of 771004 meeting w/United Nuclear Corp.Damps & Moore & US Army Corps of Engineers in Casper.WY rehydrologic & geotechnical engineering considerations in United Nuclear rept to be submitted late-Oct 1977 KANE.J D Division of Site Bafety & Environmental Analysis 77/10/13 3pp
- --8004270117 Forwards input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Applicant should be informed that 9 ft of freeboard will be required in event dam is raised to ultimate elevation of 5,282 ft HULMAN.L G Hydrology Meteorology Branch 79/01/11 2pp
- --8004290121 Input to SER for Morton Ranch U mill Proposed freeboard for ultimate dam not conservative Total freeboard of 9 ft should be provided * Hydrology Meteorology Branch 79/01/11 4pp
- ---B004290125 Supplements 790111 input to SER re proposed freeboard not being conservative Should be license condition to assure that applicant does not initiate tailings storage until dam is ultimate height Nine-ft freeboard still adequate HULMAN.L G Hydrology Meteorology Branch 79/05/10 2pp
- DOCKET 40-8647 KERR-MCGEE CORP
- 8004070361 Responds to 800217 inquiry re current status of mineral development project Vendor is conducting mining operations at several locations within permit area & has applied for milling license Map of proposed ion exchange facility encl MU.O Uranium Recovery Litensing Branch 80/03/13 3pp
- DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC.
- 8004020151 Forwards rept on decommissioning program for Hanksville Ore Buying Station GLASIER, Q E Affiliation Unknown 80/03/03 6pp
- DOCKET 40-8481 ENERGY FUELS NUCLEAR, INC
- 8004020487 Forwards D'Appolonia 800214 rept re methods of calculating reclamation costs for White Mesa tailings disposal area.
 Discusses reclamation & decommissioning costs Requests that NRC review estimates & concur w/required surety GALBIER, 0 E Energy Fuels Nuclear, Inc. 80/02/18 7pp
- 8004280417 Requests that IE conduct const insp of tailings impoundment SCARANO, R A Granium Recovery Licensing Branch 80/03/31 2pp
- --8004280418 Amend 1 to License BUA-1358 authorizing first stage of const of embankments & liner sys of tailings retention sys. BCARANO,R A Uranium Recovery Licensing Branch 79/10/12 4pp
- --8004280420 Bummary of 791109 site visit to inspect const of embankments on Cells 1.2 & 3 & daily records of density & water content tests Energy Fuels Nuclear 791022 memo documenting 791018 site visit encl
 NELBON, J D Colorado Btate Univ 79/11/12 15pp
- 8004300087 Discusses performance of archaeological excavations & analyses. Buggests review of research proposals of prospective consultants to ensure that ancillary studies are conducted. MADSEN.D B. Utah, State of. 80/04/07 Spp
- 8004270110 Forwards consultant repts on tailings retention sys const Also forwards list of specs to be used as guideline during insps at Shootering Canyon site BCARANG.R A Uranium Recovery Licensing Branch 80/04/16 ip

DOCKET 40-8498 PLATEAU RESOURCES, LTD

8004280064 Confirms 800318 telcon re key trench insp Key trench expected to be ready for insp during first half of Apr 1980 Backfilling of downstream shell foundation will begin upon approval of Hoodward-Ciyde Consultants rept NEHMAN.P S Plateau Resources, Ltd 80/03/18 ip

B004290036 Requests that IE conduct insp of foundation excavations for tailings embankment & evaporation pond at Morton Ranch mill tailings pond embankment at Shootering Canyon mill Morton Ranch license encl

SCARANO, R A Uranium Recovery Licensing Branch 60/04/02 1p

--8004290044 Amend to License SUA-1371 Amend (authorizes const of embankment for tailings impoundment BCARAND,R A Uranium Recovery Licensing Branch 79/09/28 Bpp

8004300106 Requests that IE inspect foundation excavations for tailings pand embankment & evaporation pand at Morton Ranch & tailings pond embankment at Shootering Canyon Summary of space and Scarano, R A Uranium Recovery Licensing Branch 80/04/02 2pp

8004290110 Forwards consultant repts on tailings retention sys const Also forwards list of specs to be used as guideline during insps at Shootering Canyon site BCARAND R A Uranium Recovery Licensing Branch 80/04/14 1p

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

8004090209 Submits trip rept including 790724 scoping meeting w/ applicant, state & føderal agents & general public in Cheyenne,MY, re EIS for proposed Nine Mile Lake in-situ U recovery project List of attendess encl ROTHFLEISCH, J Uranium Recovery Licensing Branch 80/03/21 6pp

DOCKET 40-8722 BRUSH-WELLHAM, INC

8004300243 Advises that U recovery operations will begin on 800517 POWERS, M B Brush-Wellman, Inc. 80/03/21, ip

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP.

8004070361 Responds to 800217 inquiry re current status of mineral development project Vendor is conducting mining operations at several locations within permit area t has applied for militing license Map of proposed ion exchange facility encl NU.0 Uranium Recovery Licensing Branch 80/03/13 3pp

8004070376 Forwards proposed NRC matl license for ion exchange facility, supporting NRC environ impact assessment/safety review & source documents used by NRC to prepare assessment Requests commonts by 800319 M/o encls NU, G Uranium Recovery Licensing Branch. 80/03/13 ip

DOCKET 40-8729 TETON EXPLORATION DRILLING CO . INC

4070038 Bummarizes encl 791024 ltr from consulting geologist.

• Warner, re geology & groundwater aspects of Taton sploration Drilling Co U in situ extraction project environ spt W/o encl

• AUFMAN, R & Uranium Recovery Licensing Branch 80/03/05 4pp

04090334 Notifies of invoice to be sent for add1 fee in connection w/review of application for License SUA-1373
MILLER.W C License Fee Management Branch 80/03/25 ip

KET 40-8745 OGLE PETROLEUM

14020064 Documents from State Dapt of Environ Quality including memo e water quality, analysis of comments on in situ mining regulations & revised regulations & dept guidelines for reparation of RAD in situ testing license lANGINI.A J. Wyoming, State of 60/01/29 91pp

4030001 Responds to NRC 800215 request re biological assessment etermining whether proposed Bison Basin project has impact n bald eagle & black-footed ferret. Add1 biological ssessment impossible due to weather conditions ATCHPOLE, Q J. Ogle Petroleum, Inc. 80/03/06 lipp

--B004030003 Comments on environ rept re Ogle Petroleum Inc River Basin project HALLENSTROM R Interior Dept of, Fish & Wildlife Service B002701 Bpp

8004240563 Forwards response to NRC 791126 Question 25 re analytical data pertaining to barren & pregnant lixiviant streams from 25 gpm R&D test CATCHPOLE: G J Ogle Petroleum. Inc 80/03/2: 3pp

DOCKET 40-8740 EDLOW INTERNATIONAL CORP

8004040412 FOIA request for records re Ediow Intl Co.Inc application to store radioactive matls in or near East St Louis.IL JEFFERS.T Affiliation Unknown 80/02/29 ip

8004040419 Responds to FDIA request for records re Edlow intl Co.inc application to store radioactive matls in or near East St Louis, IL Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/03/24 App

--BCO4040446 License SMC-1377, authorizing storage & use of 1,643,400 kgs natural U in form of U hexafiuoride & 962,300 kgs natural U in form of U ore concentrate by Edlow Intl Co BASSIN.N Licensing Management Branch 80/02/14 2pp

DOCKET 40-8768 KERR-MCKEE NUCLEAR CORP

8004240108 Ack receipt of 800325 application for source matl license to conduct in-situ R&D program at U site Application fee is required to process application
WEISS, U D License Fee Management Branch 80/04/02 ip

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR
P Operating license stage documents & correspondence

7904110103 Responds to NRC questions re pilot study on personnel dosimetry Concludes most processors have not elerted effort required to pass HPSC std Proposes three-phase course of constructive action PLATO,P , HUBBIN, G Michigan, Univ of 79/03/08 12pp

7910180103 Forwards interim position on containment purging during normal operation & proposed purge valve interim position comments Recommends that 20-day ltt to licensees request that licensee comply w/encl position in interim oRIMES.B K Assistant Director for Systems Engineering (Pre 791030) 79/09/24 4pp

8004040385 Application to amend License R-28 changing Tech Specs.App A. Section 5 2 re utilization of low enriched U
KERR.W Michigan Univ of 80/04/02 2pp

--8004040389 "Bafety Analysis - Utilization of Low Enrichment U Fuel," submitted in support of application to amend OL * Michigan, Univ of 79/10/31 Sipp.

@ Inspection reports, JE Gulletins & correspondence

8004090319 Forwards IE Insp Rept 50-002/80-01 on 800121-23 No noncompliance noted DAVIS:A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch, 80/02/25 2pp

---8004070327 IE Insp Rept 50-002/80-01 on 800121-23 No noncompliance noted Major areas inspected radwaste programs including qualifications, audits, facilities, training, procedures, & equipment FIBHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch PAUL, R A , MILLER, D E Region 3, Chicago, Office of the Director 80/02/21 7pp

8004240513 Forwards IE Insp Rept 50-002/80-03 on 600304,10 & 17 No nancompliance noted Rept withheld (ref 100FR2 790) HIND.J A Region 3: Chicago, Office of the Director 60/03/28

80043000B9 Forwards IE Insp Rept 50-002/80-04 on B00310-12 No noncompliance noted Rept withheld (ref 10CFR2 770) HIND, J A Region 3, Chicago, Safeguards Branch 80/03/28 1p

- DOCKET 50-3 INDIAN POINT STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- SOO4100100 Comments on proposed rule 10CFR50 10-mile emergency planning xone for plume exposure lacks technical justification NRC adopted position w/o studying validity of underlying bases WEISS.ER Sheldon, Harmon & Weiss 80/02/19 5pp
- Reactor Accidents at Indian Point," (corrected 790620)
 BEYEA, J Princeton Univ 79/06/20 49pp
- BOO4080695 F01A request,on behalf of UCS,for time analysis required to evacuate public from 10-mile area surrounding facilities WEISS,E R Sheldon, Harmon & Weiss 80/03/20 1p
- SOC4080690 Responds to FOIA request for time analysis required to evacuate public from 10-mile area surrounding facilities Forwards rept: "Evacuation Times Estimates for Areas Near Site," W/a encl FELTON, J M Division of Rules and Records 80/03/31 1p
- 9- Adjudicatory correspondence
- SOC4020091 Forwards UCS 800310 comments on director's decision under 10CFR2 206 Decision & confirmatory order do not resolve Critical issues Objects to exclusion of patitioner from meetings & correspondence solving issues
 WEISS, E.R. Shelden, Harmon & Weiss 80/03/10 2pp

- --GOO4020118 Discusses site visit & outstanding info requests Requests responses by 780918 Requests for info encl STELLO.V Division of Operating Reactors 78/08/31 18pp
- BOO-4030168 Response to NRC 800211 order to show cause re revocation of License Unit has been shut down since October 1974 Plant will retire as generating unit per util 800226 decision.but will remain as support & research ctr W/Certificate of Svc ZARAKAS.P. Consolidated Edison Co of New York, 80/03/12 8pp
- 8004070047 Order granting extension until 800414 for Commission to review director's 800211 decision
 HOYLE, J. C Office of the Secretary of the Commission 80/03/31
- BOO 4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOBSICK. L. V. Office of the Executive Director for Operations GAMM.F Federal Emergency Management Agency 80/04/02 34pp
- 3004150073 Order granting extension until 800425 for Commission to a leact whether to review ALAB-436 & ALAB-561
 CPIELK.B J. Office of the Secretary of the Commission. 80/04/04
- 004220754 Forwards petition supporting UCS petition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAVES, R. S Housetonic Safe Energy Alliance. B0/04/13 ip

- --8004220762 Supports UCS petition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAVES,R S Housatonic Safe Energy Alliance 80/02/15 ip
- H General correspondence
- 8004070200 FOIA request for info re facilities & damage due to earthquakes at Indian Point BEBAS.P G Affiliation Unknown 80/02/10 ip
- 8004030016 Advises that Commission should evaluate need for power generated by facility & take close look at safety achieved for public protection GLINSKY, V Commission 80/03/11 ip
- --800403001B Responds to 800225 ltr Forwards NY Times article re lack of need for electricity produced at facility Cites util trade association statement that reserve margin of 2% would exist if all plants in svc grid were shut down LEVINSON, J O Affiliation Unknown 80/03/02 2pp
- --B004030024 Responds to B00208 ltr supporting petition by UCE requesting decommissioning of Unit 1 & suspending operations of Units 2 & 3 Advises that Commission is reviewing comments on matter
 GILINSKY, V Commission B0/02/25 3pp
- --8004030025 Supports UCS 790917 patition requesting decommissioning of Unit 1 & suspension of operations at Units 2 & 3 Cites safety-related reasons for prompt action Cartificate of Svc encl LEVINSON, J O Affiliation Unknown 80/02/08 3pp
- BOD4070194 Responds to FDIA request for info re facilities & damage due to sarthquakes at Indian Point Forwards Documents 1-4 listed in App A Documents 5 & 6 may be purchased by sending check in amount of \$9 50 to NRC in Washington.D C
 FELTON, J M Division of Rules and Records GO/03/19 2pp
- --8004070205 "Semiannual Operating Rept," Jul-Dec 1973 * Consolidated Edison Co of New York 73/12/31 20pp
- --8004070208 "Semiannual Operating Rept." Jan-June 1974 * Consolidated Edison Co. of New York 74/06/30 21pp
- --8004070214 "Semiannual Operating Rept," Jul-Dec 1974
 * Consulidated Edison Co of New York 74/12/31 21pp
- --8004070224 "Annual Operating Rept." 1975 * Consolidated Edison Co of New York 75/12/31 22pp
- --8004070229 "Annual Operating Rept." 1976 * Consolidated Edison Co of New York 76/12/31 27pp
- --8004070233 "Annual Operating Rept," 1977 TMI semiannual & annual operating rept excerpts encl .

 * Consolidated Edison Co of New York 77/12/31 45pp
- 8004290054 Forwards info requested in 800218 ltr re licensing actions Matl could not be forwarded by 800225 as ltr did not arrive at NRC until 800226 W/o ancls DENTON.H R Diffice of Nuclear Reactor Regulation 80/03/25 2pp
- --8004290058 Requests info re changes affecting extension of ULs to BIO101 FLEISHER, Z B Affiliation Unknown BO/02/1B 1p
- 8004180234 Forwards NRC 800325 response to encl 800218 ltr from ZE Fielsher of West Branch Conservation Association, in response to 800226 request W/o encl DRCKS.H J Office of the Executive Director for Operations 80/03/28 lp.
- --8004180237 Requests info re new safety regulations FLEISHER, Z 8 West Branch Conservation Association 80/02/18
- 80041900BB Responds to 80022B ltr re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites. DENTON, HR Dffice of Nuclear Reactor Regulation 80/04/01 2pp
- --8004150094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER, J W Affiliation Unknown 80/02/28 lp

- 8004160173 Responds to 800212 ltr re continued operation of nuclear power plant Addl measures should be implemented that will further reduce probability of severe reactor accidents. Licensee has been in shutdown pending completion of actions DENTON:H R Dffice of Nuclear Reactor Regulation 80/04/01 2pp
- ~~8004160176 Requests that NRC not phase out facility or convert to monnuclear generators Nuclear power is source for power in US No nuke political arguments have no basis in reality LAVERTY, E Affiliation Unknown 80/02/12 2pp
- 9004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DENTON.H R Diffice of Nuclear Seactor Regulation 90/04/01 2pp
- R00421008B Responds to 800125 request re public hearing & determination on UCS petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences

 DENTON.H R Office of Nuclear Reactor Regulation 90/04/01 2pp
- ~-8004210093 Requests scheduling of public hearing & determination of UCS petition re operation of facility prior to reactivation Concerned for health & safety of community SCIANDRA, J New York, NY 80/01/25 1p
- 8004210193 Responds to 800207 ltr re-continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants Interim measures have already been ordered at sites DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- ~-8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant-lowering rates & dependency on foreign oil WU.J Affiliation Unknown 80/02/07 ip
- 8004210208 Responds to 800204 ltr re continued operation of facility Plants reviewed to determine what addl measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences
 DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- ~-8004210223 Urges NRC to decide in favor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shut down
 OAY R R Affiliation Unknown 80/02/04 ip
- BOO4250013 Responds to BOO212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure

 DENTON: H R Office of Nuclear Reactor Regulation BO/04/01 2pp
- --8004250030 Urges that NRC consider UCS petition re closing of facility
 Possibility of earthquake exists w/plant built near fault
 Only 20% of erra energy generated by nuclear power
 Alternatives should be considered
 GOLDHOR, F Affiliation Unknown 80/02/12 1p
- BOO4230185 Advises that NRC held two meetings in NY re continuing operation at facility Commission presently considering form of review Public comments invited Request for another hearing in vicinity of plant will be considered

 DENTON.H R Office of Nuclear Reactor Regulation BO/04/03 ip
- ---8004230190 Requests that NRC hold another public hearing re continuing operation of facility to offer public chance to question plant operators & govt agencies Public should be properly notified through local news media

 CONNOR:R J New York, State of 80/01/08 2pp
- B004280140 Responds to B00117 ltr to DCE re B00117 incident at facilities Flant did not trip during minor earthquake tremar Epicenter of tremar was located approx seven miles from site Tremar was significantly below design capability, EISENHUT, D & Division of Operating Reactors B0/04/08 1p
- P Operating license stage documents & correspondence
- BOO4070094 Forwards agenda & proposed rule for NRC sponsored BO0115 meeting in New York, NY re proposed rule on emergency response RYAN, R O Office of State Programs 79/12/31 12pp

- --BC0407007B Requests opportunity to testify at NRC 800115 meeting in New York, NY re emergency response plans in fifty-mile zone around plant NY City Council has been holding hearings or resolution to phase out plant FRIEDLANDER. M New York, NY 79/12/21 1p
- B004030102 Forwards "Nuclear Data Link Spece," study of digital communication sys to transmit info from plants to Bathasda Operations Ctr EISENHUT.D 0 Division of Operating Reactors 80/03/12 3pp
- ---B004030118 "Nuclear Data Link Specs "
 + Division of Operating Reactors 80/02/21 28pp
- 8004110045 FOIA request, on behalf of UCS, for Sandia Labs study re liquid effluent pathway at facility WEISS,E R Sheldon, Harmon & Waiss 80/03/18 ip
- 8004110039 Responds to FOIA request for Sandia Labs study re liquid effluent pathway at facility Rept is undergoing NRC technical review prior to publication Draft encl FELTON.J M Division of Rules and Records 80/04/02 1p
- --8004110051 Draft study of facility liquid effluent pathway
 * Bandia Laboratories 80/04/02 800pp
- 8004280197 Responds to util 790720 proposed amend to Tech Specs re radiological efficient & environ monitoring sys Forwards comments & marked-up copy of Unit 2 Tech Specs for incorporation into proposed amend SCHWENCER: A Operating Reactors Branch 1 80/04/14 7pp
- --8004280204 Marked-up version of util 790731 App A Tech Specs re radiological effluent & environ monitoring sys * Office of Nuclear Reactor Regulation 80/04/14, 125pp
- G Inspection reports, IE Bulletins & correspondence
- 8004150253 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or rasponse necessary. GRIER, B H Region 1. Philadelphia. Office of the Director, BO/03/31 ip
- 8004070045 Forwards IE Circular 80-05. "Emergency Diesel Osmerator Lubricating Oil Addition & Onsite Supply " No written response raquired ORIER, BH Region 1. Philadelphia. Office of the Diractor 80/04/01 1p
- GOO4110126 Forwards IE Info Notice 80-13, "QE Type SBM Control Switches Defective CAM Followers " No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/04/02 ip
- 8004240297 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180210 Forwards IE Circuler 80-07, "Problems W/HPCI Turbine 011 8ys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director, 80/04/03 ip
- 8004230403 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pips." Action required GRIER, B M. Region 1. Philadelphia, Office of the Director 80/04/04 p
- B004180125 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required GRIER, B H Region i, Philadelphia, Office of the Director, 80/04/07 ip
- R Periodic operating reports & related correspondence
- 8004150597 Forwards "Environ Discharge Monitoring Rept for Mar 1780 "
 MONTI, W. A Consolidated Edison Co of New York 80/04/10 1p.
- --B004150609 "Environ Discharge Monitoring Rept for Mar 1980 "
 * Consolidated Edison Co of New York 80/04/10 15pp
- 8004210269 Forwards "Daily Counts from Intake Screens Har 1980," re fish collections Circulators were shut down for month at Unit 1 CAHILL, H J Consolidated Edison Co of New York 80/04/15 1p

- --B004210276 "Daily Counts from Intake Screens, Mar 1980," re fish collections
 - Consolidated Edison Co of New York 80/04/15 4pp
- U Congressional/Executive Correspondence
- 8004080193 Responds to 791212 ltr re Rockland Mobilization for Survival ltr concerning Dac 1979 public meeting on emergency preparedness Period of public comment lasted until NRC participants had listened to all speakers DIRCKS,N J Office of the Executive Director for Operations 80/03/05 2pp
- --8004080206 Discusses 791218 public meeting on emergency preparedness
 Plans should be arranged to allow ample time for public
 comment Viewpoints of citizens within facility vicinity
 appear to be unimportant to NRC
 STERN.L D Rockland Mobilization for Survival 79/12/05 2pp
- 8004300792 Forwards Congressman Rosenthal B00114 ltr re concerns falling within FR B00222 notice requesting public views on proceeding issues DIRCKE, W J Office of the Executive Director for Operations 80/04/11 ip
- --8004300299 Conveys concerns re safety & health risks posed by plants & lack of adequate evacuation plan Urges NRC to respond to UCS petition ROSENTHAL.B S House of Rep , Foreign Affairs 80/01/14 1p
- DOCKET 50-10 DREGDEN NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004240831 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AD Network may also be used for daily administrative or facsinglie tra
- 8004030172 Forwards Figure 2-1 to correct omission made in 800311 ltr re evacuation time estimates for facility Figure 3-1 in Section 3 should be placed in Section 2 PEDPLES.D L. Commonwealth Edison Co 80/03/26 2pp
- B004150344 Forwards drawings & submits responses to NRC concerns re mods to fire protection design of fire detection sys & water suppression sys Drawings available in Central Files only JANECEK.R F Commonwealth Edison Co
- 8004230367 Forwards revised security plan Revisions.withheld (ref 10CFR2 770), PEOPLES D. L. Commonwealth Editon Co. 80/04/21, iP
- Q Adjudicatory correspondence
- 8004250054 Responds to 800109 request for info re status of 790319 petition for preparation of EIS for chemical decontamination of facility NRC is presently reassessing environ impact of facility decontamination 'ENTON, H R Office of Nuclear Reactor Regulation 80/03/26 2
- --8004250062 Requests info re whether EI8 will be prepared prior to chemical decontamination of facility. There has been no public hearing, EI8 or opportunity for independent scientists to study impact of decontamination Grience article encl DREY, K. Affiliation Unknown 80/01/09 App
- H General correspondence
- 8004070418 Discusses method of disposal of radwaste from facility decontamination, classification of waste & requirements util must comply with before returning facility to syc in response to 80019 itr
 VDLLMER.R H Assistant Director for Systems & Projects 80/03/13
- --8004070421 Opposes pending decontamination of facility due to possibility of migration of radwaste after burial lack of sites for burial & possibility of damage to facility STEDER,P , STEDER,T . Affiliation Unknown 80/01/19. 3pp.
- 8004210282 Responds to 1tr re chemical decontamination of facility Disposal of waste will not cause any new hazards not previously evaluted. Disposal is acceptable Forwards safety yOLLMER,R,H Bystematic Evaluation Program Branch 80/03/15 5pp

- --8004210256 Protests proposed decontamination of facility Requests that EIB be prepared prior to decontamination & that public hearings be held immediately to address safety MOLONE, L. Affiliation Unknown 80/04/08 ip
- 8004210260 Responds to ltr re chemical decontamination of facility Waste processing transportation & disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLL
- --8004210264 Protests proposed decontamination of facility Requests that EIS be prepared prior to decontamination & that public hearings be immediately held re safety PETRIE.L. Affiliation Unknown 80/04/08 Ip
- 8004210272 Responds to 1tr ro chemical decontamination of facility Waste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER.R H Systematic Evaluation Program Branch 80/09/15
- --8004210279 Protests proposed decontamination of facility Requests that EIS be prepared prior to decontamination & that public hearings be held immediately to address safety FERN.B Affiliation Unknown 80/03/15 1p
- 8004210287 Responds to itr re chemical decontamination of facility Waste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER.R H Systematic Evaluation Program Branch 80/03/15 80/03/15 App
- ---8004210270 Protests proposed decontamination of facility Raquests that EIS be prepared prior to decontamination & that public hearings be hold immediately to address safety LITTLE.R Affiliation Unknown 80/03/15 ip
- 8004210275 Responds to 1tr re chamical decontamination of facility Waste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER.R H. Bystematic Evaluation Program Branch. 80/03/15. App
- --8004210297 Protests proposed decontamination of facility Requests that EIS be prepared prior to decontamination & that public hearings be held immediately to address safety RODERS,L W Affiliation Unknown 80/03/15 lp
- 8004210297 Responds to ltr re chemical decontemination of facility Maste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation. VOLLPER:R H Systematic Evaluation Program Branch 80/03/15
- ~-8004210300 Protests proposed decontamination of facility Requests that ELB be prepared prior to decontamination & that public hearings be held immediately to address safety DEGEN.O. Affiliation Unknown 80/03/15 ip
- 8004210302 Responds to ltr re chemical decontemination of facility Haste disposal will not cause any new hazards not previously evaluated Disposal is acceptable Forwards safety evaluation VOLLMER.R. H Systematic Evaluation Program Branch. 80/03/15
- --8004210305 Protests proposed decontamination of facility. Requests that EIS be prepared prior to decontamination & that public hearings be held immediately to address safety. BRIDOSS, O Affiliation Unknown 80/03/15 ip
- BOO421030B Responds to 1tr re chemical decontamination of facility. Waste disposal will not cause any new hazards not previously evaluated. Disposal is acceptable. Forwards safety evaluation & J Checker 1tr. VGLLMER:P H Systematic Evaluation Program Branch 80/03/15 App
- ---8004210310 Protests proposed decontamination of facility Requests that EIB be prepared prior to decontamination & that public hearings be held immediately to address safety CHECKER, J. Affiliation Unknown 80/03/15 ip
- BOOA:50R21 Responds to ltr re chemical decontamination of facility Haste processing, transportation & disposal will not cause any new hazards not previously evaluated Decontamination is acceptable forwards safety evaluation

 DENTON, HR Office of Nuclear Reactor Regulation BO/03/26. Spp.
- --8004150216 Requests that complete public hearing on planned decontamination action be held that E18 be completed & that no radioactive chamical waste be stored in IL MARTIN. 6 Affiliation Unknown 80/01/08 3pp.

- 04250388 Ack receipt of ltr enclosing J Mayes ltr on decontamination Forwards response to J Mayes ltr.providing background of decontamination review & identifying actions for which EIS is required Need for EIS will be considered DENTON-H R Office of Nuclear Reactor Regulation 80/03/26 1p
- -8004250394 Joins IL Safe Energy Alliance petitioners in request that public hearings be held on decontamination of facility JOHNSON: T V Illinois. State of 80/03/26 ip.
- -8004250397 Requests info re-public hearings & EIB concerning facility decontamination "Experiment" could have alarming effects on population & ecosys
 MAYEB, J. Affiliation Unknown 80/01/14 3pp
- 004280362 Responds to 790425 ltr requesting preparation of EIS for decontamination Presently evaluating whether EIS should be
- decontamination Presently evaluating whether EIS should be prepared DENTON:#R Office of Nuclear Reactor Regulation BO/04/14 2pp
- -8004280366 Believes it imparative that EIB be prepared prior to decontamination of facility VONZELLENS B W Northern Illinois Univ 77/06/25 ip
- -8004280369 Responds to 790625 ltr requesting EIS be prepared prior to decontamination of facility Currently reviewing K Drey 790310 petition requesting preparation of EIS EISENHUT, D G Division of Operating Reactors 79/09/25 ip
- -8004280375 Ack receipt of 790319 petition requesting preparation of EIS prior to decontamination of facility Request will be treated per 2 206
 DENTON.H R Office of Nuclear Reactor Regulation 79/04/09 1p
- --B0042B0379 Notice of receipt of K Drey 790319 petition requesting preparation of EIS prior to decontamination Request treated par 2 206
 B0YD:R S Office of Nuclear Reactor Regulation 79/04/19 ip
 - Operating license stage documents & correspondence
- 'B12060303 Notification of 781207 meeting w/SEP Owner's Oroup in Sethesda.MD to discuss plans to address seismic input for use in SEP seismic review LEVIN.H A Systematic Evaluation Programs Branch (Pre 790625) 78/11/24 2pp
- '908210549 Forwards info to present status & completion schedules for work being performed under technical assistance program Info will be updated monthly PANCIERALV Plant Systems Branch (Pre 791030) 79/07/25 22pp
- 3004100302 Advises that responses to 74i123 ltrs re LNR assessment of enhancement of fission gas rolease at higher burnups have been reviewed No immediate licensing action required for aperating reactors par typical fuel bundle & batch burnups ZIEMANN,D L. Operating Reactors Branch 2 80/02/27 3pp
- 3004090335 Forwards NUREO-0569. "Evaluation of Integrity of SEP Reactor Vessels." completing review of SEP Topic V-6.19/0 encl ZIEMANN.D L. Operating Reactors Branch 2 00/03/09 2pp
- 8004020010 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN, D. L. Operating Reactors Branch 2 80/03/06 Spp
- 8004030102 Forwards "Nuclear Data Link Spece," study of digital communication sys to transmit info from plants to Hethesda Operations Cir EISENHUT, D & Division of Operating Reactors 80/03/12 3pp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- 8004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response cit within 20 days

 KEPPLER.J 9 Pegion 3, Chicago, Office of the Director 80/03/20
- 8004090259 Notification of 800328 meeting w/SEP compars group in Bethesda.MD to discuss sensitivity abudies re SEP sitespecific spectra project LEVIN.H A Systematic Evaluation Program Dranch. 80/03/24 ip

- 8004170279 Forwards evaluation of SEP Topic XV-20 re radiological consequences of fuel damaging accidents, inside & outside containment Review complete & evaluation will be basic input to integrated safety assessment for facility ZIE/ANN/D L Operating Reactors Branch 2 80/03/26 App
- BOO4040341 Forwards response to NRC questions ie potential effect of residual solvent which may be trapped beneath stainless steel cladding during layup conditions Corrosion rates are not expected to pose significant problem

 JANECEK.R F Commonwealth Edison Co BO/03/27 7pp
- BOO4230176 Forwards request for info re environ qualification of electrical equipment Data is needed for NRC calculation of containment temp 2 pressure docay time Calculation should be based on current LOCA analysis ZIEMANN.D L Operating Reactors Branch 2 80/03/28 14pp
- 8004070227 Forwards util 800310 ltr to LLL transmitting drawings recontainment purge sur JANECEK R F Commonwealth Edison Co 80/03/31 2pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. OA program Revisions reflect recent organization title changes NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to GA program
 Revisions reflect recent organizational title changes
 * Commonwealth Edison Co CE-1-A RI3 80/04/04 7pp
- BO04180217 Forwards addl info re failure of control rods to insert fully on scram in response to NRC 800110 & 11 ltrs Dreadon i experienced no control rod failures in 1778-77 Failure at other facilities caused by leakage past worn piston seals JANECEK: R F Commonwealth Edison Co 80/04/14 10pp
- 8004220332 Bubmits list of SEP topic references in response to NRC 800214 ltr Includes info re potential hazards, severe weather flooding, tornado missiles, reactor vessel integrity & control room habitability JANECEK, R F Commonwealth Edison Co 80/04/14 5pp
- 8004230072 Submits SEP topic refs.in response to NRC 800214 ltr JANECEK.R F Commonwealth Edison Co 80/04/14 3pp
- 8004290427 Forwards response to NUREG-0578 & "Dosign Criteria & Conceptual Design Description for Technical Support Ctrs for facilities" for review Util emergency plan will be submitted w/Lossalle County sito-specific emergency plan PEOPLES.D L Commonwealth Edison Co 80/04/15 40pp
- --B004250428 "Dosign Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- Q Inspection reports, IE Bulletims & correspondence
- 8004070157 Forwards IE Insp Repts 50-010/79-23.50-237/79-27 & 50-247/79-25 on 791007 & 1128 & notice of violation DAVIS.A B Region 9, Chicago. Fuel Facility & Maturials Safety Branch 60/02/12 2pp
- --8004070162 Notice of violation from insp on 771007 & 1128
 * Region 3, Chicago, Office of the Director 80/01/31 1
- --8004070166 IE Insp Repts 50-010/79-23,50-237/79-27,& 50-249/79-25 on 791007 & 1128 Noncompliance noted radioactive matl shipment reford not utilized for radwaste shipments made 790101-1128 GREGER.L R. FISHER.W L Region 3, Chicago, Office of the Director 80/01/31 7pp
- 8004040195 Forwards IE Insp Repts 50-010/80-01.50-237/80-01 & 50-247/80-05 on 800108-07 No noncompliance noted FIDMELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/14 2pp
- ---8004040199 IE Insp Repts 50-010/80-01.50-237/80-01 & 50-249/80-01 on 800108-09. No noncompliance noted Hojor areas inspected emergency diesel generator mods & mod of electrical equipment re IEEE-279 compliance
 HAYES.D W Region 3. Chicago. Reactor Construction & Engineering Support Branch HUCHES.J J Region 3. Chicago. Office of the Director 80/02/08 Spp
- E004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted DAVIG.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 60/02/22 2pp

- ---8004100408 Waste Packages Insp Rept 79-07A on 791212-13 No noncompliance noted Major area inspected compliance w/DOT & NRC regulations including shipping paper requirements, radiation levels & DOT labeling POTTER, J P. PEERY, W W, WODDRUFF, R L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 App
- B004100426 Forwards IE Insp Repts 50-010/E0-03.50-237/B0-03 & 50-249/B0-03 on B00107-0201 No noncompliance noted HCISHHAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/02/26 2pp
- ---800410D432 IE Insp Repts 50-010/80-03, 50-237/80-03 & 50-249/80-03 on 800107-0201 No noncompliance noted Major areas inspected maint activities, plant operations, physical protection, safety-related sys survaillance insp followup & refueling BARKER, J. L., TONOUE, T. M., SPESSARD, R. L. Region 3, Chicago, Office of the Director 80/02/22 7pp
- 8004100118 Forwards IE Info Notice 80-08. "States Co Sliding Link Cloctrical Terminal Black" No specific action or response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/07
- 8004100000 Advises that IE Bulletin 80-05. "Engineered Safety Feature (CSF) Reset Controls" was sent to listed utils on 800313 CARROLL, D. E. Region 3. Chicago, Office of the Director 80/03/17
- 8004100119 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-23, 50-237/79-27 & 50-249/79-25 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/20 2pp
- ---8004100128 Responds to NRC 800212 ltr re violations noted in IE Insp Repts 50-010/79-23,50-237/79-27 & 50-249/79-23 Corrective actions informed personnel re cost estimate change order requirements PEOPLES, D. Commonwealth Edison Co 80/03/04 3pp
- BO04140117 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal grainule escape PEOPLES, D. E. Commonwealth Edison Co. 80/03/20 5pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on B00222 be destroyed DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch B0/03/21 1p
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted BAVIS.A B Region 3. Chicago. Fuol Facility & Materials Safety Branch 80/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external features POTTER, J.P., PEERY, W.W., WOODRUFF, R.L., Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004300544 Ferwards IC Insp Repts 50-010/80-04,50-237/80-04 & 50-249/80-04 on 800220-22 & 26 & notice of violation DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 60/03/21 2pp
- ---8004300548 Notice of violation from insp on 800220-22 & 26 # Region 3, Chicago, Office of the Director 80/03/11 1:
- --B004300555 IE Insp Repts 50-010/80-04,50-237/80-04 & 50-249/80-04 on 800220-22 & 24 No noncompliance noted, Major areas inspected internal audits, licensee coardination w/offsice support agencies & review of emergency drills EBSIG.T H. OESTMANN, M.J., MATBON, E. Region 3, Chicago, Office of the Director 90/03/11 10pp
- 8004150159 Forwards IE Info Natice 80-12. "Instrument Failure Gauses Opening of PORV & Block Valva " No specific action or response necessary KEPPLER.J O Region 3. Chicago, Office of the Director. 80/03/31.
- 8004080686 Forwards IE Circular 80-05, "Emergancy Diesal Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER,J G Region 3, Chicago, Défice of the Director 80/04/01

- 8004150146 Advises that IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve," was sent to listed utils on 800331 CARROLL.D E Region 3, Chicago, Office of the Director 80/04/01 3pp
- 8004080569 Advises that IE Circular 80~05. "Emergency Diesel Generator Lubricating 0:1 Addition & Onsite Supply" was sent to listed utils on 800401 CARROLL.D E Region 3. Chicago, Office of the Director 80/04/02 300
- 8004150014 Forwards IE Info Notice 80-13, "QE Type BBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- B004180030 Forwards attachments to IE Circular B0-03, "Protection From Toxic Oas Hazards," inadvertently omitted from B00306 transmittal KEPPLER, J O Region 3, Chicago. Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice BO-14, "Safety Suggestions From Employees " No action required KEPPLER.J G Region 3, Chicago, Office of the Director BO/04/02
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER.J 9 Region 3, Chicago, Office of the Director 80/04/00
- BD041803B5 Advises that IE Circular AD-07. "Problems W/HPCI Turbine Oll Sys" was sont to listed utils an B00403 CARROLL,D C Region 3, Chicago, Office of the Director B0/D4/07
- 8004230224 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ABME SA-312.Type 304 Stainless Steel Pipe " Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/07
- 8004230304 Advises that IE Bulletin 77-03A. "Longitudinal Neld Defects in ABME SA-312 Type 304 Stainless Steel Fipe." was sent to listed utils on 800404 for action CARROLL, D E Region 3. Chicago. Office of the Director 80/04/07
- 8004220067 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/04/09
- 8004220161 Advises that IE Bulletin 80-08, "Cxam of Containment Liner Penetration Helds," was sent to listed utils on 800408 CARROLL,D E Region 3, Chicago, Office of the Director 80/04/09 360
- 8004220199 Advises that IC Info Notice 80-14, "Safety Suggestions From Employees" was sent to listed utils on 800404 CARROLL, D.E. Region 3, Chicago, Office of the Director 80/04/09
- 8004280628 Forwards revised Pages 3 & 5 & omitted Page 4 to IE Insp Repts 50-010/80-05, 50-237/80-05, 50-247/80-05, 50-254/80-05 & 50-265/80-08 F10RELI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/09 1p
- --8004280634 Revised Pages 3 & 5 & omitted Page 4 to 1E Inap Repta 50-010/80-05,50-237/80-05,50-249/80-05,50-254/80-05 & 50-265/80-08 * Region 2. Atlanta, Office of the Director 80/04/09 3pp
- R Portodic operating reports & rolated correspondence
- 8004140330 Forwards "Raduaste & Environ Monitoring Annual Rept 1979." STEPHENBON, B 8 Commonwealth Edison Co. 80/03/19 ip
- --B004140340 "Radwaste & Environ Monitoring Annual Rept 1979." KOHL. K A . CHANDRASEKARAN Eperline Instrument Corp B0/03/31 71pp
- 8004190382 Forwards monthly operating repts for Mar 1980 STEPHENSON.B B Commonwealth Edison Co 80/04/10 Is

- --B004180387 Monthly operating repts for Mar 1980 CIESZKIEWICZ.8 Commonwealth Edison Co 80/04/01 23pp
- S Reportable occurrences: LERs & related correspondence
- BOO4080941 Forwards LER 80-001/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/03/25 1p
- --B004080549 LER 80-001/03L-0 on 800303, capacity in Unit i fire pump found to be in need of updating in order to be equal to Unit 2/3 fire pump Commitment made to NRC to increase capacity New fire pump will be installed # Commonwealth Edison Co B0/03/25 ip
- 8004220630 Forwards LER 80-002/01T-0 STEPHENSON, B B Commonwealth Edison Co 80/04/17 1p
- --8004220481 LER 80-002/01T-0 on 800405, while in shutdown made w/fuel removed, contaminated demineralized water was being heated & added to primary sys Tube leaks in heat exchanger were found leaking water into river Caused by unloader tube failure GATES. J Commonwealth Edison Co 80/04/17 4pp
- U Congressional/Executive Correspondence
- 8004140183 Forwards response to 800204 request for comments on IL Safe Energy Alliance statements NRC complies w/NFPA requirements Proposed decontamination under review for special circumstances which may require EIS DIRCKS, W J Office of the Executive Director for Operations 90/03/28 6pp
- --8004140177 Requests info on IL Safe Energy Alliance concerns re proposed decontamination of facility Also requests info on studies re reactor environ impact COLLINB.C House of Rep , Foreign Affairs 80/02/04 ip
- 8004140208 Forwards comments on II. Bafe Energy Alliance statements re proposed decontamination of facility per 800220 request NRC complies w/NEPA requirements Proposed action under review for special circumstances which may require EIS DIRCKB.W J Office of the Executive Director for Operations B0/03/28 6pp
- ~~B004i402i5 Bupports IL Bafe Energy Alliance request for completion of EIB prior to facility decontamination YATE8.5 R House of Rep , Appropriations 80/02/20 ip
- 8004i40i49 Forwards response to 800205 request for comments on itr from ER McCullough of It. Safe Energy Alliance NRC complies u/NEPA requirements Proposed decontamination under review for special circumstances which may require EI8 DIRCKS.W J. Office of the Executive Director for Operations 80/03/31 Spp
- --B004140180 Requests comments on encl 790123 itr from ER McCullough of IL Bafe Energy Alliance Ltr proposes that EIS be required for factility decontamination BIMON.F House of Rep . Education & Labor B0/02/05 App
- BO04140225 Forwards response to B00131 request for comments on ltr from ER McCullough of IL Safe Energy Alliance NRC complies w/NEPA requirements Proposed decontamination under review to 'starmine if EIB is required 'RCKB,W J. Office of the Executive Director for Operations /03/31 App
 -)04140230 Requests comments on encl 900122 ltr from ER McCullough of IL 9afe Energy Alliance re facility decontamination STEVENSON, A. Senate 80/01/31 Spp
- 8004140496 Forwards NRC 800328 response to Congressman 8 Yates re status of NRC decision on need for EIS prior to plant decontamination NRC treatment of IL Energy Alliance concerns is inadequate List of concerns encl BHINEFLUG.M Illinois Safe Energy Alliance, 80/04/07 2pp
- ---8004440459 Responds to 800220 request for comments re IL Safe Energy Alliance statements about proposed chemical decontamination NRC will comply whrequirements of NEPA in determining whether EIS should be prepared DIRCKS.W. J. Office of Nuclear Material Safety & Bafeguards, 80/03/28 499

- P Operating license stage documents & correspondence
- 8004180355 Submits add1 info re 771018 amend request Describes range of allowable nonmoderator to moderator ratio & computer codes used for front-end calculations for analysis of max credible accident CLSEN.A F Babcock & Wilcox Co 80/04/11 4pp
- DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

 1 Financial information
- 8004070317 Forwards Annual Financial Rept 1979 CUMNINGHAM, G E General Electric Co 80/03/28 ip
- --8004070321 Annual Financial Rept 1979 * General Electric Co 80/02/15 25pp
- J Insurance & indomnity information
- BO04010323 Forwards Endorsement 23 to MAELU Policy MF-95 CORREAM A Marsh & McLennan.Inc . M & M Nuclear Consultants.Inc Div 80/03/25 2pp
- R Periodic operating reports & related correspondence
- 8004086286 Forwards "1979 Annual Status Rept 15 " CUNNINGHAM, G.E. General Electric Co. 80/02/29 i
- --8004060289 "1979 Annual Status Rept 15 "
 * General Electric Co 80/02/29 5p
- DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

 F. Security, medical, emergency & fire protection plans
- 8004010446 Forwards Items 3 i 5 & 3 i 12(d) of fire protection review Proposed manually operated sprinkler sys is acceptable, contingent upon submittal of final design drawings Proposed i-h rated protection for diesel generator rooms acceptable HALL,R E Broothaven National Laboratory 80/03/24 7pp
- 8004110145 Forwards NRC position on 780822 & 790410 responses re cable fire barrier qualification testing Several deviations to NRC requirements make justification or commitment to add1 testing necessary within 30 days ZIEMANN.D L. Operating Reactors Dranch 2 80/03/24 3pp
- BOO4140172 Forwards revised safeguards contingency plan pages Encl withheld (ref 100FR2 790) MOODY,D E Yankse Atomic Electric Co 80/04/10 1p
- 8004280534 Forwards conclusions re fire barrier qualification testing Deviations stated in NRC 800324 ltr do not significantly affect test results MODDY.D E Yankee Atomic Electric Co 80/04/22 4pp
- G Adjudicatory correspondence
- 8004070288 Requests that enci info he distributed to appropriate boards & parties Includes info re disc cracking in Hestinghouse turbines & Yankee Rowe turbine failure EISENHUT,D 0 Division of Operating Reactors 80/03/07 2pp
- 8004250264 Requests that encl documents be provided to Board notification svc lists for all cases VAROA B A. Assistant Director for Light Water Reactors 80/03/31
- 8004280336 Forwards NRC confirmatory order BTELLD,V Office of Inspection & Enforcement, Office of the Director 80/04/04 1p
- ~-B004250337 Order confirming util commitment to perform review requested by IE Builetin 79-27 by 800701 Required info specified in Attachment A. BTELLD, V Office of Inspection & Enforcement, Office of the Director B0/04/04 App

H General correspondence

- 800421004B Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10CFR20 3 App 1 to 10CFR50 Environ info available in stated LPDRB BALLARD, R L Environmental Projects Branch 1 80/04/01 2pp
- --8004210060 Requests info or current repts re effects of nuclear power plants on New England marine organisms due to radiation. chemical waste disposal, thermal pollution & other factors ROBERS, B J Affiliation Unknown 80/03/09 ip

I Financial information

- 8004010395 Forwards Annual Financial Rept 1979 SOUCY, A R Yankee Atomic Electric Co 80/03/31 10
- --8004010378 Annual Financial Rept 1979 * Yankee Atomic Electric Co 80/02/15 12pp

P Operating license stage documents & correspondence

- 8004100511 Advises that responses to 761123 itrs re LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors per typical fuel bundle & batch burnups ZIEMANN, D L Operating Reactors Branch 2 80/02/29 2pp
- 8004230064 Advises that review & evaluation will not be completed until 800701 re loss of non-Class IE instrumentation & control power sys bus during operation KAY, J A Yankee Atomic Electric Co 80/02/27 ip
- 8004080159 Forwards NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 W/s encl ZIEMANN.D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020004 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary References or updates to info previously submitted are acceptable ZIEMANN.D L Operating Reactors Branch 2 80/03/06 5pp
- 8004080185 forwards evaluation of SEP Topic XV-20 comparing facility w/current licensing criteria Responses will be made if as-built facility differs from licensing basis
 ZIEMANN:D L Operating Reactors Branch 2 80/03/07 App
- B004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISERHUT. D G Division of Operating Reactors 80/03/12 Spp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- B00417030B Forwards request for add1 info re environ qualification of electrical equipment ZIEMANNO L. Operating Reactors Branch 2 80/03/28 29pp
- 8004110434 Forwards Revision 8 to YOGAP-I-A addressing organization changes to 8A program
 HEIDER, L.H. Yankee Atomic Electric Co. 80/04/04 ip
- --8004i10444 GA program Revision 8 for facility operation VANDENBURGH,D E, HEIDER,L H , MODDY,D E Yankee Atomic Electric Co YOGAP-I-A 80/04/01 20pp.
- 8004250123 Forwards Category A Lessons Learned Task Force review items which require addit licensee action Includes info re heater capacity required & time within which capacity must be available to maintain natural circulation at hot standby ZIEMANN,D L. Operating Reactors Branch 2 80/04/05 4pp
- B004290079 Requests payment of Class III fee for proposed Tech Spec Change 168 NRC-requested change is not exempt from fees because change anhances safe operation of facility.

 MILLER, W D License Fee Management Branch 80/04/08 ip
- 8004110417 Responds w/add1 info re 800402 Category A implementation and audit. Westinghouse study determined min heater requirements w/o offsite power met required heater capacity Temp inputs increased to 8 thermocouples KAYJ A Yankee Atomic Electric Co 80/04/09 13pp

- 8004280600 Advises of revised Step 5 to action plan re anchorage & support of safety-related electrical equipment Manpower losses delay response re investigation until 800630 All mods will be completed prior to startup KAY. J A Yankee Atomic Electric Co 80/04/23 ip
- 9 Inspection reports, IE Bulletins & correspondence
- 8004150310 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090110 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 1p
- BOO4110518 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required GRIER. B H Region 1, Philadelphia. Office of the Director BO/04/02 1p
- 8004240355 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180255 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine Oil 8ys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/03 1p
- B004230516 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME BA-312.Type 304 Stainless Steel Pipe " Action required ORIER, B H Region I. Philadelphia, Office of the Director B0/04/04 ip
- B004180302 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/04/07 ip
- R Pariodic operating reports & related correspondence
- 8004100370 Forwards "Annual Radiological Environ Surveillance Rept for 1979 " KAY, J.A. Yankee Atomic Electric Co. 80/03/31 ip
- ---8004100374 "Annual Radiological Environ Surveillance Rept for 1979 " * Yankee Atomic Electric Co 80/03/28 60pp
- 8004150350 Forwards monthly operating rept for Mar 1980 MODDY, D E Yankee Atomic Electric Co 80/04/11 1p
- --8004150352 Monthly operating rept for Mar 1980 BEER8.F C Yankee Atomic Electric Co 80/04/11 5pp
- S Reportable occurrences, LERs & related correspondenc
- 8004080489 Forwards LER 80-009/03L-0 AUTIO,H A Yankee Atomic Electric Co 80/04/04 1p
- --8004080496 LER 80-009/03t.-O on 800307.during maint outage in Mode 5 while performing safety injection time delay verification procedure. TDC2 setpoint found out of Tech Spec limit Caused by setpoint drift. Relay adjusted to within Tech Spec limit FRENCH.L D Yankee Atomic Electric Co 80/04/04 ip
- DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

 O Advisory Committee on Reactor Safeguards reports & correspondence
- 8004040167 Confirms recommendation re add1 subsurface investigations
 Three large diameter borings down to base & below lowest
 shear at reactor at fence uphill & at fence downhill from
 reactor should provide required info
 PHILBRICK.88 Philibrick, S8 79/12/14 1p

DOCKETED ITEMS

CKET 50-54 UNION CARBIDE RESEARCH REACTOR

Operating license stage documents & correspondence

04150082 Advises that License R-84 will expire on 800530 Renewal requires fitting 30 days before expiration date demonstrating that reactor can operate safely for prolonged period REID, R W. Operating Reactors Branch 4 80703/28 ip

Periodic operating reports & related correspondence

304080548 Forwards "Annual Operating Rept for 1979 " RUZICKA:H G Union Carbide Corp 80/03/31 1p

-8004080551 "Annual Operating Rept 1979," reporting facility mod & major maint = Union Carbide Corp 80/03/31 4pp

004070375 Forwards "Annual Operating Rept for 1979 " RUZICKA: W G Union Carbide Corp 80/03/31 ip

-8004090380 "Annual Operating Rept for 1979 " * Union Carbide Corp 80/03/31 4pp

OCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR
Operating license stage documents & correspondence

1905190094 Forwards draft of revised Tech Specs Te effluent monitor operability Requests same limits as granted to Univ of Michigan allow 24-h out of svc for monitors w/o restrictions on speration ORLOSKY, P.M. New York, State Univ of, Buffalo 78/12/29 3pp

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

9 Adjudicatory correspondence

8004000026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GUSBICKL V Office of the Executive Director for Operations B0/04/02 34pp,

I Financial information

8004070317 Forward: Annual Financial Rept 1979 CUNNINGHAM. G E General Electric Co 80/03/26 ip

---8004070321 Annual Financial Rept 1979 # General Electric Co 80/02/15 25pp.

P Operating license stage documents & correspondence

8004040142 Summary of 800131 meeting w/GE in Bethesda. MD to analysis proposed by vendor to support restart of GETR
NELSON: C. Operating Reactors Branch 4. 80/03/21 2pp

--8004040153 "Probability Amalysis of Surface Rupture Offset Beneath GETR Reactor Bldg REED,J W Jack R Benjamin & Associates, Inc. 80/03/21 10pp

8004020185 Forwards results from measurements taken to determine angle of dip in trenches at site. If surface offset to be considered in structural analyses, recommends using dip angles ranging between 10 to 30 degrees.

DARMITZEL, R W Deneral Electric Co 80/03/31 5pp

8004300092 Forwards Revision 1 to GA program CUNNINGHAM: G E General Electric Co , Nuclear Energy Products Div 80/04/07. 1p.

--8004300056 GA program # Ganeral Electric Co. GAP-1 Rt. 80/03/31 33pp

8004170254 Forwards "Seismicity of Livermore Valley in Relation to GE Vallection Plant," & responses to questions & comments raised at ACRE 791114 GETR Subtramelthee meeting. Info noncontroversial & does not alter GE position.

DARMITZEL/R, W Oeneral Electric Co. 80/04/14 2pp.

~-8004170257 "Selamicity of Livermore Valley in Relation to GE Vallecitos Plant" BOLT B A . HANSEN,R A General Electric Co 80/03/31 35pp

---B004170260 Forwards responses to questions & comments raised at ACRS 791114 GETR Subcommittee meeting DDRMITZEL.R W General Electric Co 80/04/14 33pp

8004280311 Forwards partial response to NRC questions re-structural issues of test reactor GILLILAND.B L General Electric Co 80/04/23 12op

R Periodic operating reports & related correspondence

BOO4080348 Forwards "Annual Operating Rapt 21 for 1979 " CUNNINGHAM, O E General Electric Co BO/03/05 1p

--80040B0359 "Annual Operating Rept 21 for 1979 "
* General Electric Co 80/03/05 5pp

S Reportable occurrences, LERs & related correspondence

8004040030 PNO-V-80-019A ground water samples obtained from well located near underground waste tank farm & below ground fuel tank sump Analysis showed no significant activity above detectable limit HENSLANKKI,F. FISH,R Region 5, Ban Francisco, Office of the Director 80/03/19 ip

8004040413 PNO-V-80-015B, correcting PNO-V-80-015A Tritium mistakonly reported as 3 O E-5, should read 3 O E-3 WENSLANSKI,F, FISH,R Region 5, San Francisco, Office of the Director 80/03/19 1p

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

1 Financial information

8004070317 Forwards Annual Financial Rept 1979 CUNNINGHAM.0 E General Electric Co 80/03/28 1s

--8004070921 Annual Finantial Rept 1979 * General Electric Co 80/02/15 25pp

P Operating license stage documents & correspondence

8004170044 Forwards proposed changes to Tech Specs, per 800320 & 21 teleons, in response to NRC questions re util response to postulated seismic event application to amend Fech Specs CUNNINOHAM, O C Oeneral Electric Co 80/04/03 ip

--8004170046 Application to amend License R-33, changing Tech Speck re postulated seismic event * General Electric Co 80/04/10 ip

--8004170049 Proposed changes to Tech Specs 4 i(c), 5 4 3,8 2 2,8 2 ii & Table I Tech Spec 8 2 5 should be deleted * General Electric Co 80/04/10 2pp

R Periodic operating reports & related correspondence

8004080308 Forwards "Annual Operating Rept 20," for 1979 CUNNINGHAM G E General Electric Co 80/02/29 in

--8004080313 "Annual Operating Rept 20," for 1979 OILLILAND, D.L. General Electric Co. 80/02/29 Spp

DGCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8004220558 Forwards "Environ Radiation Surveillance Rept for Oct 1978-Mar 1979" & "Environ Radiation Surveillance Rept for Apr-Sept 1979 " BRAY, T C North Carolina State Univ 80/03/13 3pp

--8004220560 "Environ Radiation Surveillance Rept for Oct 1978-Mar 1979 " BALL-A C , DEBNAM. J North Carolina State Univ B0/03/19 7pp

--8004220565 "Environ Radiation Surveillance Rept for Apr-Sept 1979"
BALLIA C . DEBNAM. J North Carolina State Univ 80/03/13 7pp

- DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8004230167 Forwards IE Insp Rept 50-123/79-03 on 791105-06 & 1204-05 & notice of deviation KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/03 200
- --8004230175 Notice of violation from insp on 791105-06 & 1204-05
 * Region 3, Chicago, Office of the Director 80/02/19 ip
- --8004230179 Natice of deviation from insp on 771105-04 & 1204-05 * Region 3. Chicago, Office of the Director 80/02/19 1p
- --8004230187 IE Insp Rept 50~123/79-03 on 791105-06 & 1204-05
 Noncompliance noted failure to maintain required personnel exposure records & deviations in surveys, measurements & instruments
 FISHER, W.L. Region 3, Chicago, Fuel Facility & Materials Safety
 Branch DUBRY, N.E. Region 3, Chicago, Office of the Director 80/02/19 i3pp
- 8004290080 Ack receipt of 800324 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-123/79-03
 KEPPLER.J 0 Region 3. Chicago. Office of the Director 80/04/08
- --8004270085 Responds to NRC 800303 ltr re violations nated in IE Insp Rept 50-123/79-03 Corrective actions instituted procedural change delegating routine health physics activities to reactor personnel Wauditing by health physicist PLANUE, T J Missouri, Univ of, Rolla 80/03/24 9pp
- DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

 D Utility Preliminary Safety Analysis Report, amends
- 8003310406 Forwards PSAR PARKINSON, T.F. Virginia Tech 80/03/19 ip
- --8003310411 PSAR for VA Polytechnic Inst & State Univ research training reactor CURINCR, A P , DENTON, M M , ESKIN, L D Virginia Tech 79/11/01 10700
- --8003310415 Chapter 1 of VA Polybechnic Inst & State Univ research & braining reactor PSAR, "Introduction"

 CURTNER, A P., DENTON, M. M., ESKIN, L. D. Virginia Tech. 79/11/01
- --8003310417 Chapter 2 of VA Polytechnic Inst & State Univ research & training reactor PSAR, "Sys Mods"
 CURTNER, A P., DENTON, M. M., ESKIN, L.D. Virginia Tech. 79/11/01
- ~~8003310421 Chapter 3 of VA Polytechnic Inst & State Univ research & training reactor PBAR. "Thermal-Hydraulics Analysis "
 CURTNER, A P., DENTON, M M., ESKIN, L. D. Virginia Tech. 79/11/01
- ---8003310427 Chapter 4 of VA Polytechnic Inst & State Univ research & training reactor PSAR. "Reactivity Transients" CURTNER, A P . DENTON, M M . ESKIN, L D Virginia Tech 79/11/01 9no
- --8003310432 Chapter 5 of VA Polytechnic Inst & State Univ research & training reactor PBAR, "Radiation Bafety"

 CURTNER A P , DENTON, M M , ESKIN, L D Virginia Tech 79/11/01
 1600
- --8003310439 Chapter & of VA Polytechnic Inst & State Univ research & training reactor PBAR, "DBA"

 CURTNER, A P . DENTON, M M . ESKIN, L D Virginia Tech 79/11/01
- F Security, medical, emergency & fire protection plans
- 8004040466 Forwards Sept 1979 draft emergency plan PARKINSON, T. F. Virginia Tech 80/03/19 Ip

- P Operating license stage documents & correspondence
- B004150431 Application for renewal of facility License R-62 for term of 20 yrs CURTNER, A P. PARKINSON, T P. KREBS, A H. Virginia Tech. 79/10/02 2pp
- DUCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR
 P Operating license slage documents & correspondence
- 8003190734 Requests maps indicating low population iones for facilities
 EDSON, K. California, State of 80/01/07 in
- R Periodic operating reports & related correspondence
- 8004240416 Forwards "Annual Operating Rept 1979 " KLEIN, D Texas, Univ of 80/03/31 ip
- --8004240420 "Annual Operating Rept 1979 " KLEIN.D E Texas: Univ of 80/03/31 56pp
- DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3
- 8004240340 Urges ASLB to move on hearings re facility Certificate of Svc encl DUQOING.L Affiliation Unknown 80/01/05 3pp
- 8004;50003 Forwards rept by Woodward-Clyde Consultants re status of geologic & seismic investigations involving facility, in accordance w/ABLD 790419 order Work going forward on laddometric dating & trace olement analysis
- 8004080626 Notice of 800603 prehearing conference at Veterans Memorial Bidg, Euroka, CA Conference will address PGSE request that further proceedings be stayed & held in abeyance until 801001 re amend to CL Technical assistance requested LAZO,R M Atumic Safety and Licensing Board Panel 80/03/24 3pp
- BO04030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OCBSICK, L. V. Office of the Executive Director for Operations BO/04/02 34pp
- 8004290280 Requests hearing re plant proximity to earthquake fault Certificate of Svc encl JAMES M Affiliation Unknown 80/04/08 3pp
- I Financial information
- BOD4100233 Forwards Annual Financial Rept 1979 CRANE.P A Pacific Gas & Electric Co BO/04/03 1p
- --8004100244 Annual Financial Rept 1979 * Pacific Qas & Electric Co 80/02/22 43pp
- P Operating license stage documents & correspondence
- 6004070397 Discusses NRC 761123 request that all LWR licensess assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses undicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D G Division of Operating Reactors. 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp.

Q Inspection reports: 1E Bulletins & correspondence

- | 8004150205 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response Decessory
 - ENGELKEN, R H Region 5. San Francisco, Office of the Director 80/03/31 ip
 - 8004100101 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required EMGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 19
 - 8004i10iii Forwards 1E Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN,R H Region 5, San Francisco, Office of the Director
 - B004220038 Forwards IE Info Notice B0-14, "Safety Suggestions From Englayees" No action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/02 ip
 - 8004180148 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required ENGELKEN R H Region S. San Francisco, Office of the Director 80/04/03 ip
 - 8004230374 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/04 ip
- ** 8004220172 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds " Written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 8004170233 Forwards monthly operating rept for Mar 1980 WEEKB, E D Pacific Oas & Electric Co 80/04/09 ip
- --B004170236 Monthly operating rept for Mar 1980 OETTY,B C Pacific Gas & Electric Co 80/04/09 4pp
- S Reportable occurrences, LERs & related correspondence
- BOO40804B1 Forwards LER 8D-002/03L-0 CRANE.P A Pacific Oas & Electric Co 80/04/01 1p
- ---8004080487 LER 80-002/03L-0 on 800310, while in cold shutdown for refueling & seismic mods, fossil unit trip test was not performed within allowable interval Caused by present status being Unresolved Test will be performed prior to startup BIERBAUM.0 A Pacific Gas & Electric Co 80/04/01 ip
- DOCKET 50-137 TURKEY RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8004100302 Advises that responses to 761123 ltrs re LHR assessment of enhancement of fission gas release at higher aurnups have been reviewed No immediate licensing action required for operating reactors per typical fuel bundle & batch burnups ZIEMANN.D L. Operating Reactors Branch 2 80/02/29 Spp
 - :KET 50-142 UCLA TRAINING REACTOR
 - Operating license stage documents & correspondence
- 800430027B Forwards discussion in response to Committee to Bridge the Gap 791003 petition alleging deficiencies in review procedures used in support of Amend 10 to DL Further NRC input to cover all alleged deficiencies necessary REID, R W Operating Reactors Branch 4 80/04/11. 4pp.

- U Congressional/Executive Correspondence
- BO040B0157 Responds to 791102 ltr re constituent concerns about emissions of radioactive gas from Univ of CA,Los Angeles research reactor Ar-41 emissions result in individual doses below max allowed by NRC goldelines
 DIRCKS.# J Office of the Executive Director for Operations DIRCKS, W J 0
- --8004080164 Requests response to encl GD Strum 791007 ltr re emissions of radioactive gas from Univ of CA, Los Angelos research BEILENSON, A C House of Rep 79/11/02 Spp
- DOCKET 50-150 ONIO STATE UNIV RESEARCH REACTOR
- I Financial information
- 8004080046 Responds to FDIA request for documents re extraordinary nuclear occurrence concept including proposed rulemaking, regulations & rules adopted by AEC Forwards documents listed in App A
 FELTON, J.M. Division of Rules and Records 80/03/18 Spp
- ~-8004080070 Ack receipt of 690625 ltr re Amend 2 to Indemnity Agreement E-8 Amend 2 has been executed Forwards N Carlile 660120 CARSON G B
- O Inspection reports, IE Bullating & correspondence
- 8004100372 Forwards IE Insp Rept 50-150/80-01 on 800204-07 No noncompliance noted noncompliance noted of Annicompliance noted DAVIS.A B Region 3, Chicago, Fuel Factlity & Materials Safety Branch B0/02/29 2pp
- --8004100377 IE Insp Rept 50-150/80-01 on 800204-07 No noncompliance noted Major areas inspected radwaste mgt & radiation noted najor areas inspected revealed my minutes of the protection programs
 PIGHER, W i. Region 3, Chicago, Fuel Facility & Materials Safety
 Branch PAUL, RA A BCHUMACHER, M C Region 3, Chicago, Office of
 the Director 80/02/28 7pp
- DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR
- & Inspection reports, IE Bulletins & correspondence
- 8004110237 Forwards IE Insp Repts 50-151/80-01 & 50-356/80-01 on 800204-06 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/03 2pp
- --80041102/+ ic Insp Repts 50-151/80-01 & 50-356/80-01 on 800204-06 No udditu2/4 it inspireps 30-131/80-01 & 30-336/80-01 on B00204-06 N noncompliance noted Major areas inspected emergency planning including support procedures personnel interviews, review of training & drills & inspire goulpment ESSIG.TH NRC Regional Offices GREER.R J Region 3. Chicago, Office of the Director B0/02/22 4pp
- DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8004100286 Forwards input to 790404 fire protection safety evaluation re need for protection of cabling & valve operators in recirculation pump room
 ZIEMANN,D L. Operating Reactors Granch 2 80/03/11 2pp
- ---8004100287 Fire protection safety avaluation of acceptable supplemental item for protection of cabling in recirculation pump area * Operating Reactors Branch 2 80/03/11 ip
- 8004240540 Forwards sys description & operating instructions for NRC health physics telephone network Bys designed for use during nuclear incident or AD Network may also be used for daily administrative or facsimilie traffic KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/20 200
- 8004280015 Forwards new emergency plan implementing new requirements in wake of TMI accident Answers to emergency plan interrogatories will be sent shortly W/o encl OALLD.J Isham. Lincoln & Beale 80/03/24 ip

- 8004280555 Forwards calculations re establishment of primary emergency planning zone radius of five miles for facility, in response to NRC 800414 request FROST, 8 R Consumers Fower Co 80/04/24 1p
- --8004280557 Calculations re establishment of primary emergency planning fone radius of five miles for facility # Consumers Power Co 80/04/24 9pp
- @ Adjudicatory correspondence
- 8004020278 Stresses importance of compliance w/NRC regulations re svc of documents in proceeding J O'Neill 800206 motion for extension was ruled upon prior to receipt of motion by J Gallo Requests avoidance of similar inequities GALLO,J Isham, Lincoln & Beale 80/02/27 2pp
- 8004140275 Motion to extend deadline for filing in spent fuel pool expansion hearing be extended to 800310 O'NEILL, J. Affiliation Unknown 80/03/04 ip
- 8004080191 Forwards current facility emergency plan Plan is complete except for deletion of App F.bomb threat procedures. & telephone numbers contained in App A Deletions will not adversely affect discovery rights W/ø enel
- 8004030363 Requests extension until 800314 to file contentions re need for power at facility Notification of due date for filing contentions was not received until 800310 LEITHAUSER, J Charlevoix, MI 80/03/10 ip
- 8004140041 Intervenor motion to file late brief re power issue in spent fuel pool expansion hearing NRC counsel J Moore, util counsel J Oallo & Christa-Maria counsel E Weiss do not object to delay Certificate of Svc encl
 O'NEILL. J Affiliation Unknown 80/03/10 lp
- --- 8004140044 Intervenor response to ASLB question re NEPA requirement to consider need for power in proceeding Strong precedent exists for ASLB to examine environ impact & cost-benefit & need for power issues in proposed mode Certificate of Svc O'NEILL, J. Affiliation Unknown, 80/03/10 9pp
- --B004140048 Intervenor motion for relief from burden of supplying 20 copies of all filings to NRC as required by 10CFR2 708(d) Relief is essential so that intervenor can devote energies to substantive issues of proceeding O'NEILL, J. Affiliation Unknown 80/03/10 ip
- --8004140089 Intervenor motion for clarification of legal language All parties in proceeding asked to supply simple extranations of Latin & legal terms appearing in relevant documents O'MEILL. J. Affiliation Unknown 80/03/10 4pp
- 8004100570 Forwards util 800222 ltr to NRC explaining util position recertain plant mods proposed by NRC as part of SEP & post-TMI evaluations Ltr is irrelevant to proposed expansion of spent fuel pool QALLO, J Isham, Lincoln & Bosle 80/03/12. 2pp
- BOO41BO396 Motion to be heard on need for power issue Petitioner brief was retaived by ASLB within max time limits Patitioner has raised issues not dealt w/in other briefs Denial of motion is denial of petitioner right to protect property LEITHAUSER.J A Affiliation Unknown 80/03/12 3pp
- --8004180402 Brief on need for power issue Constitutional requirements of due process require ASLB to consider need for power at facility Proposed licensing amend permitting operation of unsatisfactory facility violates due process LEITHAUSER.J A. Affiliation Unknown. 80/03/10 Spp.
- 8004100293 First set of interrogatories Includes questions re expert witnesses intervenor expects to call & areas of expertise CALLO, J. STEPTOE, P.P. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 80/03/13 Apr
- ---8004100276 Request for production of documents identified in intervenor Christa-Maria response to licensee first set of interrogatories Documents requested by 800414 OALLO, J. STEPTOE, P. P. Consumers Power Co. OALLO, J. Isham, Lincoln & Beale. 80/03/13. 1p
- --8004100298 Notice of change of address for Washington.DC law ofc of Isham.Lincoln & Beale Certificate of Svc encl GALLO.J Consumers Power Co GALLO.J Isham, Lincoln & Beale 80/03/13 Spp

- 8004080180 Forwards first set of interrogatories GALLO, J. Isham, Lincoln & Beale 80/03/14
- ~-B0040B01B6 Licensee first set of interrogatories Includes request for identification of all documents including LERs, which serve as basis for contentions filed Cartificate of Bvc encl QALLO, J Consumers Power Co QALLO, J Isham, Lincoln & Beals B0/03/14 bpp
- 8004100451 Forwards licensed response to Interrogatories 9-32 through 9-37 % 9-39 through 9-41 Documents relied upon in preparing licensee responses have been identified OALLO.U Isham. Lincoln & Beale B0/03/19 2pp
- --8004100455 Answers to intervenor Interrogatories 7-32 through 9-37 & 7-39 through 7-41 Includes info re failed fuel assemblies & sight glass used for observation of surge tank CL Larsen affidavit & Certificate of Svc encl GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale BD/03/19 17pp
- ---8004100462 Forwards request for Tech Spec change to License DPR-6 Provides operability & surveillance requirements for modified fuel dry supping sys presently being installed at facility SEWELL, R B Consumers Power Co 75/12/18 11pp
- --8004100465 "Spent Fuel Pool Thermal Analysis "
 * NUS Corp 79/06/25 19pp
- --8004100469 Forwards evaluation of potential consequences of refusling accident inside containment in response to NRC 770429 request Containment ventilation supply & exhaust velves are of "fail-safe" design & shut automatically w/power loss BIXEL,D A Consumers Power Co 77/06/28, 20PP
- --8004100480 Forwards evaluation of potential consequences of refueling accident inside containment in response to NRC 770117 request During single bundle drop, area monitor response times will range from one second to appros four minutes BIXEL, D A Consumers Power Co 77/03/21 Spp
- 8004210420 Errata to license 800303 brief on need for power issue, NRC published proposed regulations re consideration of alternatives in 800303 FR GALLO, J Isham, Lincoln & Beale 80/03/22 ip
- BOO4210401 Forwards util BOO314 ltr to NRC providing further info re-util response to certain NRC requirements resulting from post-TMI evaluations Info is not relevant to proposed spent fuel pool expension OALLO, U Isham, Lincoln & Beale BO/03/24 2pp
- 8004080991 Memorandum & order re spent fuel expansion proceeding Directs parties to address questions raised in safety assessment encl w/HR Denton 800305 itr.re valve aperation & ioss of feedwater event-which will be part of discovery.

 OROBSMAN, H Atomic Safety and Licensing Board Panel 80/03/27
- 8004090001 Response stating no objection to J D'Neill 800310 motion for relief from twenty-copy requirement for documents filing re spent fuel pool mod proceeding Certificate of Svc encl MOURE, J E Hearing Branch 2 80/03/28, 3pp
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICK. V Office of the Executive Director for Operations, B0/04/02 34pp
- 8004170302 Forwards HR Denton 800305 ltr w/safety assessment & 10CFR2 re Commission regulations, in response to 800331 request, re spent fuel pool mod HODRE, J E Hearing Branch 2 80/04/07 1p
- 8004230075 Order granting relief to intervenor J O'Neill from 20-copy requirement Single copies shall be served on parties & two copies on Commission, re spent fuel pool expansion proceeding ORUSSMAN.H Atomic Safety and Licensing Board Panel 80/04/15. 1p
- 8004230422 Minutes of 800407 conference call participated in by all parties in spent fuel pool proceeding re addl questions contained in ABLB 800327 order Discovery on ABLB questions proper at present time MOORE. J E Hearing Branch 2 80/04/23 4pp.

DOCKETED ITEMS

General correspondence

4140022 Discusses steps being taken & procedures being followed to asure safe operation of facility in response to encl 791101 elegram to President Carter NRC response to JA Diers & Johns request to suspend operations will be forwarded TELLO.V Office of Inspection & Enforcement, Office of the irector 80/01/17 ip

004140026 Forwards Christa-Haria 79;101 telegram & 1tr requesting safety investigation prior to plant operation SEAL,H M President of US & Executive Offices 79/11/07 App

004140031 Opposes restart of facility due to foreign object in reactor vessel inhibiting mobility of control rods Related documentation & draft petition encl CHRISTA-MARIA Christa-María 79/11/01 Bpp

4070129 Responds to 800106 petition requesting that eight issues e resolved prior to startup of facility Forwards safety smessment concluding that there is sufficient safety smurance to allow operation pending final ruling ENTON.H R Office of Nuclear Reactor Regulation 80/03/05 3pp

004070132 Bafety assessment re safety issues raised by J Bier & BJ Johns 791104 & 800106 ltrs Bufficient safety assurance exists to allow operation pending final ruling * Office of Nuclear Reactor Regulation 80/03/05 7pp

004070137 Requests action under 10CFR2 206 to require util to resolve listed safety issues prior to startup School sys should have workable evacuation plan & all diffuser pieces should be accounted for BIER, J., JOHNS, S. J. Affiliation Unknown 80/01/06 2pp

4230383 Forwards util 8003iB news release indicating changes in roject, engineering & const organization Hill submit evisions to GA program by 800430 to incorporate rganizational changes OFFMAN, D P Consumers Power Co 80/04/18 7gp

Operating license stage documents & correspondence

4:00312 Advises that responses to 76:123 ltrs re LWR assessment of nhancement of fission gas release at higher burnups have sen reviewed No immediate licensing action required for perating reactors, per typical fuel bundle & batch burnups. IEMANN, D L Operating Reactors Branch 2 80/02/29 3pp

4180025 "Bafety Evaluation Rept.Inservice Testing Program " EMRINGER.J.H., ROCKHOLD,H.C. EG & G. Inc. FIN A-6258 8004150025 80/02/29, 37pp

4020450 Requests necessary action to refund licensee amend fees mend fees waived for certain types of fire protection mends

mends ILLER.W O License Fee Hanagement Branch 80/03/05 ip

4070220 Advises that Ofc of Controller has authorized refund of hrme Class II fees submitted with 800131 & 0201 pplications License amend fees for certain Tech Spec hanges re fire protection waived ILLER.H O License Fee Management Branch 80/03/05 ip.

4090346 Forwards NUREC-0369. "Evaluation of Integrity of SEP eactor Vessels." completing review of SEP Topic V-6.

L. Operating Reactors Branch 2. 80/03/05 200

~ anch 2 80/03/05 6pp

- 8004100159 Notification of 800326 neeting u/util in Bethesda.MD re SEP Topic VI-8, control toon habitability O'CONNDR.P W Operating Reactors Branch 2 80/03/18 2pp
- 8004080201 Requests forwarding of Class III foe for util 600107 application proposing Tech Specs changes re containment sphere leakage testing DIGGS.R M License Fee Management Branch 80/03/20 Ip
- 8004100076 Requests that uncontrolled set of PAIDs be placed on controlled distribution list for any future revisions. Revisions should be forwarded to attention of Region 3 incident response ctr.

 KEPPLER: J O Region 3. Chicago, Office of the Director. 80/03/20
- 8004210125 Forwards Amend 32 to License DPR-6.safety evaluation & notice of issuance 5 availability ZIEMANN.D L Operating Reactors Branch 2 80/03/27 2pp
- --8004210127 Amend 32 to License DPR-6. Increasing min size shift fire brigade from three to five ZIEMANN.D L. Operating Reactors Branch 2 80/03/27 5pp
- --8004210127 Safety evaluation supporting Amend 32 to License DPR-6 * Office of Nuclear Reactor Regulation 80/03/27 2pp
- --8004210132 Notice of issuance t availability of Amend 32 to License DPR-6 ZIEMANN, D L. Operating Reactors Branch 2 80/03/27 2pp
- 8004210170 Forwards request for info re containment environ conditions & sys required for accident mitigation for review of environ qualification of Class IE electrical equipment NRC will estimate time for containment temp to return to near normal ZIEMANN, D.L. Operating Reactors Branch 2 80/03/28 15pp
- 8004040327 Forwards 40-day response required by NRC 800101 ltr re anchorage & support of safety-related electrical equipment Issue will be resolved by end of next refueling outage scheduled to start on 801024 HOFFMAN.D P Consumers Power Co 80/03/31 8pp
- 8004040309 Discusses 800320 meeting w/NRC re proposed overall risk assessment Compensatory measures being taken include more training for fifth operating shift & mods considered for emergency condenser initiation logic Guestions mod deferral DEHITT.R B Consumers Power Co 80/04/02 3pp
- --B004040311 "Technical Approach to Probabilistic Risk Assessment "
 * Consumers Power Co 80/04/02 10pp
- 8004it0308 Forwards info re RELAP input for LOCA analysis at units KUEMIN.J L. Consumers Power Co. 80/04/02 6ipp
- 8004140307 Responds to NRC B00314 request for additional clarification of action item taken as result of TMI short-term Lessons
 Learned Shift supervisor can leave control room for brief periods of time if in best interest of facility safety
 HUFFMAN, D P Consumers Power Co 80/04/10 ip
- B004240372 Responds to NRC B00107 ltr re GA requirements for diesel generator fuel oil GA program will include diesel fuel oil by B00531 Discusses diesel fuel oil testing requirements outlined in Tech Specs 4 7 11 1 1(c)
 HOFFMAN, D P Consumers Power Co B0/04/21 1p
- O Inspection reports, IE Bulletins & correspondence
- BO04080588 Forwards IE Insp Rept 50-155/80-02 on 800204-08 No moncompilance noted HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004080574 IE Insp Rept 50-155/80-02 on 800204-08 No noncompliance noted Major areas inspected plant operations, site organization & administration BAKER.K R, WRIGHT.O C Region 3, Chicago, Office of the Director 80/02/21 3pp
- 8004100132 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J O Region 3, Chicago. Office of the Director 80/03/07

- 8004150169 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3, Chicago. Office of the Director 80/03/31
- 8004080704 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/04/01
- 8004150037 Forwards IE Info Notice 80-13, "GE Type 58M Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004180040 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/02
- 8004220123 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220365 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004110034 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07
- B004230196 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/04/07
- 8004220149 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/09
- 8004220575 Forwards "Final Rusponse to IE Builetin 79-14," Revision 1 HOFFMAN, D P Consumers Power Co 80/04/17 1p
- --80042205Bi "Final Response to IE Bulletin 79-14," Revision i * Consumers Power Co 80/04/02 7pp
- 8004290324 Forwards response to IE Bulletin 80-02, "inadequate QA for Nuclear Supplied Equipment " Plant Feedwater spargers & thermal sleeves were not mfg by Marvin Engineering Co HUSTON.R W Consumers Power Co 80/04/25 2pp
- R Periodic operating reports & related correspondence
- 8004020285 Forwards "Environ Monitoring Rept 1979 " HUSTON,R W Consumers Power Co 80/03/28 ip
- --8004020289 "Environ Monitoring Rept 1979" * Consumers Power Co 80/03/28 7pp
- S Reportable occurrences: LERs & related correspondence
- 8004080470 Forwards LER 80~005/03L~0 HOFFMAN, D P Consumers Power Co 80/04/02 ip
- --8004080475 LER 80-005/03L-0 on 80030i, following several intermittent automatic test circuit alarms, sensor channel D of reactor depressurizing sys removed from svc Caused by satpoint drift on transmitter LT-3183 Transmitter vented & returned to svc * Consumers Power Co 80/04/02 ip
- U Congressional/Executive Correspondence
- 8004080284 Forwards draft ltrs to Congress re NRC response to J Bier & B Johns petitions being treated under 10CFR2 206 SMITH.H Operating Reactors Branch 2 80/03/06 App

- DOCKET 50-160 GEORGIA INST OF TECH REGEARCH REACTOR

 O Inspection reports, IE Bullstins & correspondence
- 8004210204 Forwards IE Mgt Meeting Rept 80-140/80-02 on 800324 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 2nn
- --B004210206 IE Mgt Mesting Rept 50-160/B0-02 on 800326 Areas discussed findings of 800219-22 inspireview of previous enforcement history 5 current enforcement status
 LEWIS,R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch JULIAN,C Region 2. Atlanta, Office of the Director 80/04/04 2pp
- S Reportable occurrences, LERs & related correspondence
- 8004280486 Notifies that 30-day LER for 800305 svent will be forwarded on 800411 due to continuing problem w/coolent flow anomoly KIRKLAND,R S Georgia Institute of Technology 80/04/04 ip
- 8004280477 RO 80-1 on 791009, during ECCS tank TD-2 monthly flow rate verification, flow rate observed to be 8 gpm Caused by loose lock nuts which fix handle-to-ball operating shaft Surveillance program will be strengthened KIRKLAND, R S Georgia Institute of Technology 80/04/11 2pp
- 8004280512 RO 80-02 on 800305, low flow scram of flow recorder fRA-D1 resulted in reactor trip & subsequent shutdown Caused by broken Teflon gasket pieces restricting flow Gasket repaired & sys refilled KIRKLAND.R 8 Georgia Institute of Technology 80/04/14 2pp
- DOCKET 50-169 GENERAL ATOMIC COMPANY

 G Inspection reports, IE Bulletins & correspondence
- 8004040460 Forwards IE Insp Repts 50-163/80-01 & 50-189/80-01 on 800213-15 No noncompliance noted Encls withheld (ref 100FR2 790) NORDERHAUGLE Region 5. San Francisco, Gafeguards Branch 80/03/12 1g
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR
 H General correspondence
- 7908020467 Informs NRC of administrative personnel changes DELCHER.R Maryland, Univ of 79/07/20 ip
- 8004020050 Advises of 10 appointees to membership on reactor safety committee for 1980-1981.

 CADMAN.T W Maryland, Univ of 80/02/27 ip
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

 P Operating license stage documents & correspondence
- 8004170206 Notifies that facility License R-84 will expire on 801108 Renewal of license requires application demonstrating that reactor can continue to be updated safely & that components can withstand prolonged use RID.R.W Operating Reactors Branch 4 80/04/03 ip
- DOCKET 50-171 PEACH BOTTOM ATCHIC POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004010329 Forwards Items 3 1 5(2) & 3 i.7 of fire protection review Licensee submittal re fire barrier penetration seals only partly satisfactory Licensee proposal re fire doors acceptable HALL.R E Brookhaven National Laboratory 80/03/26. 4pp
- I Financial information
- 8004180267 Forwards Annual Financial Rept 1979 BRADLEY, E J Philadelphia Electric Co 80/04/08 ip

- P Operating license stage documents & correspondence
- 8004220549 Responds to NRC 800228 request for info re mgt & technical resources
 COUNEY, M J Philadelphia Electric Co 80/04/11 9pp
- G. Inspection reports. IE Bulletins & correspondence
- BD04100261 Responds to IE Bulletin BO-03 No cells replaced in engineered safety feature filtration sys, however charcoal adsorber cells, will have to be removed to replaced rivits indicated in Item 1
 DALTROFF, B.L. Philadelphia Electric Co. 80/03/18 3pp
- DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR
- Q Inspection reports: IE Bulletins & correspondence
- 8004100380 Forwards IE Insp Rept 50-182/80-01 on 800123-24 No noncompliance noted DAVIB.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/27 2pp.
- --8004100383 IE Insp Rept 50-182/80-01 on 800123-24 No noncompliance noted Major areas inspected radwaste mgt & radiation protection program FISHER.W L. Region 3. Chicago. Fuel Facility & Materials Safety Branch PECK,C C. HUETER,L J. Region 3. Chicago. Office of the Director. 80/02/15 8pp
- DOCKET SO-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR
- I Financial information
- BO04070317 Forwards Annual Financial Rept 1979 CUNNINGHAM, G. E. General Electric Co. 80/03/28 ip
- --8004070321 Annual Financial Rept 1979 * Qeneral Electric Co 80/02/15 25pp
- R Periodic operating reports & related correspondence
- BOO4080217 Forwards "Annual Operating Rept 12,1779 "
 CUNNINGHAM, G E. General Electric Co 80/02/29 1
- --8004080220 "Annual Operating Rept 12,1979 "
 OILLILAND, D.L. General Electric Co. 80/02/29, 3pp
- DUCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
- G Inspection reports. IE Builetins & correspondence
- 8004040191 Notification of contract execution. Hod 2 to "Licensing Assistance/Tailings Mot Program Technical Evaluation Erxon Highland U Hill." Contractor Ofc of Sponsored Reseach. CO State Univ EDOEMORTH.P J Technical Assistance Contracts Branch FIN 8-6446-9 80/02/29 10
- 8004070194 Requests that IE Insp Rept 50-184/80-01 be withheld (ref 10CFR2 790) Info contained in rept reveals amount, type & location of inventory of SMM CARTER, R S Commerce, Dept of, National Bureau of Standards 80/02/15 1p
- 8004100003 Ack receipt of 800215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-184/79-05.
 SMITH, O H. Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 ip
- -8004100007 Responds to NRC 800122 ltr re violations noted in IE Insp. Rept 30-184/79-05 Corrective actions attention drawn to existing requirements & periodic surveys of outside areas implemented CARTER.R 8 Commerce.Dept of National Bureau of Standards 80/02/15 [p
- --8004100007 Forwards IE Insp Rept 50-184/79-05 on 770828-31,0901,04.05 & 1023-26 & notice of violation SMITH.O.H Region 1. Philadelphia, Fuel Facility & Materials Bafaty Branch 80/01/22 2pp

- --8004100011 Notice of violation from insp on 790828-31,0901.04,05 & 1023-26 * Region I, Philadelphia, Fuel Facility & Materials Safety Branch, 80/01/22 Ip
- --8004100014 IE Insp Rept 50-184/79-05 on 790828-31.0901.04.05 & 1023-26 Noncompliance noted required cadiation surveys not performed PLUMLEE.K E Region 1. Philadelphia. Office of the Director CROCKER.H W Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/01/22 97pp
- B004090191 Ack receipt of 800215 request to withhold IE Insp Rept 50-184/80-01 Encl insp rept withheld (ref 10CFR2 790) MARTIN.U 9 Region 1, Philadelphia, Safeguards Branch 80/03/10
- --8004070200 Forwards IE Insp Rept 50-184/80-01 on B00115-16 No noncompliance noted MARTIN.W O Region 1. Philadelphia, Safeguards Branch B0/03/05 1p
- --8004090211 IE Insp Rept 50-184/80-01 on 800115-14 No noncompliance noted Major areas inspected facility organization & operation, measurement & control, shipping & receiving, storage & internal control Details withheld (ref 10CFR2 790) SHAUD, E 7, SUMMERS, R J. MARTIN, W G Region 1, Philadelphia, 8afeguards Branch 80/02/01 1p
- DOCKET 50-189 UNIV TRAINING REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 80040460 Forwards IE Insp Repts 50-163/80-01 & 50-189/80-01 on 800213-15 No noncompliance moted Entls withheld (ref 10CFR2 790) NORDERHAUO, L. R. Region 5, San Francisco, Safeguards Branch 80/03/12 16
- DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC
- I Financial information
- 8004080046 Responds to FOIA request for documents re extraordinary nuclear occurrence concept including proposed rulemaking, regulations & rules adopted by AEC Forwards documents listed in App A
 FELTON.J M Division of Rules and Records. 80/03/18 5pp
- --80040B0103 Forwards executed Amends 2 & 3 to indemnity agreement RI Atty General will comply w/NRC request for legal opinion concerning RI inability to effect waiver of immunity W/o encl DIMEGLID: A F Atomic Energy Commission 69/07/11 1p
- DOCKET 50-201 WEST VALLEY REPROCESSING PLANT
- G Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification QUEBICKL V Office of the Executive Director for Operations 80/04/02 34pp
- P Operating license stage documents & correspondence
- 8004140142 Summary of 800213 meeting w/NF8, DOE, EPA & NY State Energy R&D Authority in Silver Spring, MD re technical data for futute decontamination & decommissioning of facility Index of facility design data for liquid waste treatment encl HAUGHNEY, C. J. Advanced Fuel & Spent Fuel Licensing Branch 80/03/11 18pp
- 8004180096 "Standy Power Usage." Revision 1 PIERCE.A C . SMOKOWSKI.R T.. BURN.P Nuclear Fuel Services. Inc (subs of Oetty Oil Co) TOP 31-6 80/03/11 6pp
- 8004240560 Notification of 800416 meeting w/vendor in Silver Spring.MD to discuss progress of efforts to process available technical info needed to provide basis for future decontamination & decommissioning of facility, HAUGHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch 80/04/04 2pp

Q Inspection reports, IE Builetins & correspondence

- 8004090205 Ack receipt of 800226 ltr further explaining steps taken to correct violations noted in IE Insp Rept 50-201/79-03 Ltr will be withheld tref 100FR2 7901 MARTIN.W G Region 1. Philadelphia, Safeguards Branch 80/03/13
- --8004090210 Ack receipt of 791005 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-201/79-25 Addl info needed re reply to Item I MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/12/13 200
- --8004090215 Forwards IE Insp Rept 50-201/79-03 & 790612-14 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN,W C Region I, Philadelphia, Safeguards Branch 79/09/21 200
- --8004070221 IE Insp Rept 50-201/79-03 on 790612-14 Noncompliance noted TV camera could not meet performance requirements & failure to record details of alarm responses Details withheld (ref 10CFR2 790)

 DEVLIN.J W. Region 1, Philadelphia, Bafaguards Branch
 LADUN.R H, MCKEOWN.L M. Region 1, Philadelphia, Office of the Director 79/09/11 1p
- 8004100214 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-201/80-01 8MITH,0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/18 lp
- --8004100219 Responds to NRC 800207 ltr re violatins noted in IE Insp Rept 50-201/80-01 Corrective actions posted appropriate notification signs & replaced certification for compliance DUCKHORTH, J P Nuclear Fuel Services, Inc (subs of Getty Gil Go) 80/03/03 3pp
- --9004100223 Forwards IE Insp Rept 50-201/80-01 on 800108-11 & notice of violation SHITH 9 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/02/07 2pp
- --8004100225 Notice of violation from insp on 800108-11 * Region 1, Philadelphia, Office of the Director 80/02/07 2pp
- --8004100234 IE Insp Rept 50-201/80-01 on 800108-11 Noncompliance noted failure to post hardstand signs & to verify conformance of purchased filters to specs
 GROCKER.H W Region 1, Philadelphia, Fuel Facility & Materials
 Bafety Branch ROTH.J Region 1, Philadelphia, Office of the Director 80/02/07 14pp
- R Periodic operating reports & related correspondence
- B004190062 Forwards "Fifty-fifth Quarterly Environ Monitoring Rept, for Oct-Dec 1979"

 DUCKNORTH, J P Nuclear Fuel Bervices, Inc (subs of Getty Dil Co)
- --8004150071 "Fifty-Fifth Quarterly Environ Monitoring Rept, for Oct-Dec 1979 " * Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) 80/01/22,
- 8004230053 Forwards "Environ Monitoring Rept 27,Jul-Dec 1979 DUCKWORTH.J.P Nuclear Fuel Bervices, Inc. (subs. of Datty Oil Co.). 80/02/29 1p
- --8004230060 "Environ Monitoring Rept 27, Jul-Dec 1979."

 * Nuclear Fuel Services, Inc (subs. of Getty Oil Co.) 80/02/29, 26pp
- 8004030315 Notification of 800416 meeting w/NFB in Silver Spring,MD to discuss progress of NFB efforts to provide basis for future decomtamination & decommissioning of facility. HAUDHNEY,C J Advanced Fuel & Spent Fuel Licensing Branch 80/03/11, 3pp
- DOCKET 50-204 SAN DNOFRE NUCLEAR STATION: UNIT 1
- F Security, medical, emergency & fire protection plans
- B00411014B Forwards addl comment for util to Address during review of safeguards contingency plan submitted on 790323 Requests response by 800421 Encl withheld (ref 100FR2 790)

 ZIEMANN, D L Operating Reactors Branch 2 80/03/24 2pp

- 8004080515 Forwards review summary of fire protection covering Itams 3 1 6.foam suppression sys.3 1 7.gas suppression sys & 3 2 3.turbine bldg structure Itams 3 i 1.3 1 2.3 1 5 are partially complebed & summary will be provided accordingly HALL.R E Brookhaven National Laboratory 80/03/31 16pp
- 8004080395 Notifies that combined response to NRC 791211 & 800324 ltrs re safeguards contingency plan will be sent by 800421 HAYNES.J G Southern California Edison Co 80/04/01 1p
- 8004230320 Forwards revision to BNL 800331 ltr re Items 3 1.1(5),3 1 2 (b),3 1 5(d),3,1 4,3 1 7(a),3 1 7(b),3 1 19(b) & 3 2 3 for fire protection review MALL,R E. Brookhaven National Laboratory 80/04/16 16pp
- 8004300363 Notifies NRC that util requires addl time to revise safeguards contingency plan as described in NRC 800324 ltr Rayised safeguards plan will be forwarded by 800512 BAGKIN, K.P. Southern California Edison Co. 80/04/21 lp
- G Adjudicatory correspondence
- 8004280019 Forwards NRC confirmatory order BTBLLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 ip
- --B0042B0031 Order confirming util commitment to perform review requested , by IE Bulletin 79-27 by B00515 Required info specified in Attachment A STELLO, V Office of Inspection & Enforcement. Office of the Director B0/04/04 App
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8004040409 Discusses LER 79-017 event on 791107 involving fire & loss of 480-volt Bus 1 caused by rodents in switchgear housing Event constituted common mode failure not previously postulated Add1 info required for adequate assessment LIPINGKI, W C Argonne National Laboratory BO/01/15 3pp
- P Operating license stage documents & correspondence
- 8004170297 Forwards request for add1 info re environ qualification of electrical equipment ZIEMANN.D L. Operating Reactors Branch 2 80/03/28 14pp.
- 8004090242 Advises that responses to 761123 ltrs re LHR assessment of enhancement of fission gas release at higher burnups has been reviewed No immediate licensing action required for operating reactors, per revised typical fuel bundle codes ZIEMANN.D.L. Operating Reactors Branch 2 80/02/29 3pp.
- 8004030188 Netification of 800320 meeting w/util in Betheada.MD to discuss seismic reassessment program O'CONNOR.P W Operating Reactors Branch 2 80/03/05 2pp
- 8004080699 Forwards NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 M/o encl. ZIEMANN.D.L. Operating Reactors Branch 2 80/03/05 2pp.
- 8004020013 Forwards review schedule for environ qualification of Class IE electrical equipment per 80022/ meeting.Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable.

 ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 5pp.
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT; D. 9 Division of Operating Reactors, 80/03/12 Spp.
- --8004030ii8 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21. 28pp.
- 8004090142 Forwards request for add1 info per 800310-11 site visit to review implementation of Category A Lessons Learned Tesk Force requirements Response required by 800318 ZIEMANN.D.L. Operating Reactors Branch 2 80/03/13. 5pp
- 8004020327 Responds to NRC 800117 request for review of draft evaluation of REP Topic XV-20, "Radiological Consequences of Fuel Damaging Accidents, (Inside & Outside Containment), " Review Confirms facts as correct HAYNES, J Q Southern California Edison Co, 80/03/28 1p

- 8004030140 Forwards application for Amend 87 to License DPR-13 consisting of Proposed Change 87 to Tech Specs 3 5, "Instrumentation & Control," & 4 1, "Operational Safety Itens "Westinghouse evaluation withheld (ref 10CFR2 790) DIETCH,R Southern California Edison Co 60/03/31 2pp
- --8004030141 Amend 89 to License DPR-13-modifying existing Tech Specs 3 S & 4 1 to require limiting conditions for operation based on control rod misalignment & to specify surveillance requirements Certificate of Svc enc1

 DIETCH.R Southern California Edison Co 80/03/11 7pp
- --8004030145 Proposed Change 89 to Tech Space 3 5. "Instrumentation t Control." & 4 i. "Operational Safety Items " * Southern California Edison Co 60/03/31 lipp
- 8004300889 Provides addition on automatic initiation of auxiliary feadwater sys flow concerning implementation of Item 2 1 7a requirements of NUREC-0578 Requests detail of safety-grade sys design Certain commitments required within 15 days EIBENHUT.D O Division of Operating Reactors 80/04/03 3pp
- 8004080491 Forwards application for Amend 90 to License DPR-13 & Proposed Changes 91 & 92 describing offsite power sources & incorporating changes necessary for implementation of fire protection mods Fee encl
 DIETCH.R Southern California Edison Co 80/04/04 2pp
- --8004080498 Application for Amend 90 to License DPR-13, describing affaite power sources & incorporating changes necessary for implementation of fire protection mods
 DIETCH.R Southern California Edison Co 80/04/04 7pp
- --8004080504 Description of Proposed Changes 91 & 92 to Tech Specs Comparison of seismic design criteria for high voltage switchyard & summary of util remarks at 791025 meeting re offsite power sources entl # Southern California Edison Co. 80/04/04 26pp
- 8004090326 Forwards response to 800214 request for refs to docketed info re series SEP topics
 HAYNES, J. G. Bouthern California Edison Co. 80/04/04 3pp
- 8004240503 Discusses licensed actions to 800310 failure of saltwater cooling sys Auxiliary salt water cooling pump will not be considered in determining operability of sys Requests review of all emergency procedures & revision prior to operation ENOELKEN.R H Region 5, San Francisco, Office of the Director 80/04/04 3pp
- 8004180449 Advises that info re electrical distribution sys adequacy, requested by NRC 790808 ltr.will be submitted by 80050).
 Instead of 800301 date indicated in 791224 response HAYNES, J 9 Southern California Edison Co 80/04/11 1p
- 8004220303 Forwards response to upon items identified at 791114 meeting re-soismic backfit project & site specific carthquake program Results of program for svaluating earthquake anticipated in Jul 1980 BASKIN.K P Southern California Edison Co 80/04/11 36pp
- B004220634 Confirms B00410 telcons w/regulatory gersonnel re implementation of several Category A TMI Lessons Learned Task Force requirements described in B00325 ltr BABKIN, K P Bouthern California Edison Co 80/04/11 2pp
- 8004220570 Notifies that difficulties w/proposed memorandum of agreement re transmission project have been resolved to satisfaction of CA Ofc of Historic Preservation NRC should forward agreement to advisory council for action MELLON, K California, State of BO/04/15 1p
- 8004230494 Provides preliminary info re impact of auxiliary feedwater sys automation on main steam line break safety analysis, in response to NRC 791221 request Revised scaping studies will be completed by 800516
 BASKIN.K P Bouthern California Edison Co 80/04/18 2pp
- BOO4220446 Notifies that evaluation of potential magnitude & effects of postulated water hammers will include development of forcing functions for classic textbook-type water hammers Evaluation will be completed by 800/30

 HAYNES, J Q Southern California Edison Co 80/04/22 19
- 8004240374 Forwards "Analysis of Capsule F.Reactor Vessel Radiation Burveillance Program." & Tech Specs 3 1 3 for combined heatup, cooldown & pressure limitations Proposed change to Tech Specs will be submitted by 801231 BABXIN.X P Southern California Edison Co. 80/04/24 2pp

- --8004240395 Yech Spec 3 1 3 for combined heatup, cooldown & pressure limitations, Figures 3 1 3a-3 1 3d & Table 3 1 3 1 for reactor vessel toughness data (unirnadiatad) * Bouthern California Edison Co 80/04/24 8pp
- ---8004240397 "Analysis of Capsule F.Reactor Vessel Radiation Surveillance Program " YANICHKO.8 E , ANDERSON.S L , KAISER, W T Westinghouse Electric Corp , Nuclear Energy Systems WCAP-9520 79/05/31 67pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004110532 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-204/80-01 NORDERHAUD.L R Region 5. San Francisco. Safeguards Branch 80/03/14 lp
- 8004150214 Forwards IE info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/31 ip
- B004100107 Forwards IE Circular B0-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 8D/04/01 1p
- 8004110114 Forwards IE Info Natice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02 10
- 8004220048 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/02 ip
- 8004170268 Forwards IE Insp Rept 50-206/80-07 on 800318-21 No nancompliance noted Encl withhold (ref 100FR2 770) NORDERHAUÖL R Region 5. San Francisco. Safeguards Branch 80/04/03 2pp
- 8004180135 Forwards IE Circular 80~07, "Problems H/HPCI Turbine Oil Sys " No written response required ENGELKEN,R H Region S, San Francisco. Office of the Director 80/04/03 1p
- 8004230364 Forwards IE Bullatin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required ENGELXEN.R H Region 3, San Francisco. Office of the Director 80/04/04 ip
- 8004220175 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Welds " Written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director BO/04/07 ip
- 8004300465 Forwards IE Insp Rept 50-206/80~08 No noncompliance nuted Rept withheld (ref 10CFR2 790) NGRDERMAUGL R Region 5. San Francisco, Safeguards Branch 80/04/11 200
- R Periodic operating reports & related correspondence
- 8004070338 Forwards info re occupational exposure & environ surveillance programs for 1979
 OTTOSON.H L. Southern California Edison Co. 80/03/31 3pp
- --80040/0342 "Annual Operating Rept for 1979 Environ Monitoring & Radiation Exposure Ropts " + Southern California Edison Co 80/03/31 41pp
- ~-8004070345 "1979 Annual Operating Rept.Vol 1,Oceanographic Data Rept " # Brown & Caldwell 80/03/31 400pp.
- ---8004070348 "1777 Annual Operating Rept.Vol 2.Biological Data Rept Intertidal Infauma.Gubtidal Infaumal.Kelp. Ichthyopianatkon " * Marine Biological Consultants, Inc. * 80/03/31 300pp
- ---B004070352 "1979 Annual Operating Rept.Vol 3.Biological Data Rept Plankton.Hard Benthos Rocky Intertidal " * Lockhood Center for Marine Rosearch 80/03/31 500pp

- --8004070357 "1979 Annual Operating Rept.Vol 4.Biological Data Rept Nekton " * Brown & Caldwell 80/03/31 250pp
- 8004150345 Forwards monthly operating rept for Mar 1780 CURRAN, J M Southern California Edison Co 80/04/09 1p
- ---8004150347 Monthly operating rept for Mar 1980 WATTSDN.P Sauthern California Edison Co 80/04/07 5pp
- S Reportable occurrences, LERs & related correspondence
- 8004080539 RO on B00310, north saltwater cooling pump auto started upon indication of low discharge pressure from south pump North pump power operated relief valve could not be opened Cause under review Auxiliary pump used CURRAN, J M Southern California Edison Co 80/03/11 2pp
- 8004080477 Forwards LER 80-009/04L-0 OTTOSUN, H L Southern California Edison Co 80/04/02 2pp
- ---BOQ4080483 LER BO-009/04L-0 on BOO331.during first quarter of 1980. benthic data could only be taken from six of eleven ETS benthic stations Caused by severe storm conditions interrupting data collection QTTOSON.H L Southern California Edison Co BO/04/02 ip
- 8004210270 Forwards LER 80-011/43Z-0 OTTOSON, H L Southern California Edison Co 80/04/08 2pp
- --B004210273 LER 80-011/432-0 on 800310, while purging pressurizer relief tank to remove oxygen tank, disc ruptured Caused by overfilling w/primery makeup water Ruptured disc replaced * Southorn California Edison Co 80/04/08 ip
- 8004180490 Forwards LER 80-008/03L-0 DITOSON, H L Southern California Edison Co 80/04/09 2pp
- --B0041B0454 LER 80-008/03L-0 on 80031B during maint of saltwater cooling pump, pips support 9-416-4 & concrete anchors found corroded Caused by vibration & corrosion induced by saltwater environ. Support redestigned & built CURRAN, J M Southern California Edison Co 80/04/04 1p
- 8004210254 Forwards LER 80-010/03L-0 OTTOSON,H L Southern California Edison Co 80/04/09 2pp
- --8004210257 i.ER 80-010/03L-0 on 800318 during full power operation high temp indication observed on south charging pump thrust bearing Caused by loose coupling hub on pump shaft Damaged inboard bearing shoes & coupling hub septated CURRAN, J M Southern California Edison Co 80/04/09 ip
- 8004230335 RO hydrostatic test of steam generator tubes revealed nine leaking tubus (ause unstailed Tubes will be plugged at later time during current outage CURRAN, J M Sputhern California Edison Co 80/04/14 1p
- 8004250416 Forwards LER 80-012/03L-0 OTTOSON, H L Southern California Edison Co 80/04/21 2pp
- --8004250420 LFR 80-012/03L-0 on 800324, during normal operations, Number 2 diesel generator fuel oil transfer pumps 0-75A & 0-75B tripped on current overload Caused by failure of sump pumps in transfer pump vault due to high water levol in vault CURRAN. J M Southern California Edison Co 80/04/20 ip
- DOCKET 50-213 HADDAM NECK PLANT
- F Security, medical, emorgency & fire protection plans
- 8004020408 Forwards "Feasibility Rept on Evacuation of Area Around Facility " CNUNSILN O Northeast Utilities 80/03/31 2pp
- --B004020418 "Feasibility Rept on Evacuation of Area Around Facility " One oversize drawing encl RODOGRB,L M, PELL.B M Biorch Engineers MOLLOY.E J Northeast Utilities Service Co 60/03/31 58pp
- ---8004020418 "Feasibility Rept on Evacuation of Area Around Facility "
 One oversize drawing encl
 RODGERS,L M Affiliation Unknown 80/03/31 58pp

- --8004020424 "Feasibility Rept on Evacuation of Area Around Facility "
 One oversize drawing enc!
 RDD9CRS,L M. PELL,B M. Storch Engineers 80/03/31 77pp
- 8004230299 Proposes to provide automatic total fluoding Halon 1301 fire suppression sys for entire switchgear room (Fire Zone S-8) Forwards Drawing D-127989, sheets 1.2. & 3 CDUNSILN 6 Connecticut Yankee Atomic Power Co 80/04/14 3pp
- --8004230309 "Automatic Halon Fire Extinguishing Sys for Switchgear Room " Sheet 1 of 3 * Fire Equipment, Inc 127989 80/03/10 1p
- ~-8004230313 "Automatic Halon Fire Extinguishing Bys for Switchgear Room " Sheet 2 of 3 * Fire Equipment Inc 127987 80/03/05 1p
- --8004230316 "Automatic Halon Fire Extinguishing Sys for Switchgar Room" Sheet 3 of 3 # Fire Equipment, Inc. 127989 80/03/10 1p
- H General correspondence
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 100FR20 & App 1 to 100FR90 Environ info available in stated LPDRS BALLAND, R L Environmental Projects Branch 1 80/04/01 2pp
- I Financial information
- 8004080292 Forwards SEC Form 10-K listing util financial statements for 1978 & 1979 BIBHOP,R W Connecticut Yankee Atomic Power Co 80/04/02 36pp
- J Insurance & indemnity information
- 8004150379 Forwards Endorsement 58 to MAELU Policy MF-39 IFFLAND, R R Northeast Utilities 80/04/10 2pp
- P Operating license stage documents & correspondence
- BO04040066 Requests that application for route approval for round trip shipment of irradiated fuel assemblies between facility & Columbus, Oli, be approved by B00317 so that assemblies can be shipped to BMI before B00502 shutdown COUNSIL. N Q Connecticut Yankoe Atomic Power Co B0/02/22 App
- 6004030365 Forwards NRC safety evaluation supporting precautions taken to minimize steam generator water hammer ZIEMANN,D L. Operating Reactors Branch 2 60/02/26 2pp
- --9004030366 Bafety evaluation supporting precautions taken to minimize steam generator water hammer, EG&O 791228 ltr to DOE encl # Division of Operating Reactors 80/02/26 10pp
- 8004100309 Advises that rusponses to 761123 ltrs ru LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors, per typical fuel bundle & batch burnups ZIEMANN.D L. Operating Reactors Branch 2 GO/02/29 3pp
- 8004090358 Forwards NUREG-0569, "Evaluation of Integrity of USP Reactor Vessels," completing review of SEP Topic V-6 W/o encl ZIEMANN.D L Operating Reactors Branch 2 80/03/05 2pp
- BOD4020007 Forwards review schedule for environ qualification of Class
 IE electrical equipment per 800P21 meeting Resubmittal of
 info is unnecessary Refs or updates to info previously
 submitted are acceptable
 ZIEMANN, D L Operating Reactors Branch 2 80/09/06 Spp
- 8004030102 Forwards "Nuclear Data Link Egecs," study of digital communication sys to transmit info from plants to Nethesda Derations Ctr EISENUULD O Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclest Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004030293 Responds to NRC 800214 ltrs re request for list of refs for five SEP topict Forwards topics by number title & listing of refs for ECCS actuation sys. automatic ECCS realignment & testing of reactor trip sys CQUNSIL, W Q , FCE, W F Northeast Utilities 80/03/21 3pp

- 8004100161 Notification of 800326 meeting w/util in BethesdarMD removement of heavy loads near fuel & changes to move spent fuel cask.
 CARUSO, R. Aperating Reactors Branch 2 80/03/24 2pp
- 8004210411 Submits add1 info re armed escorts for 800222 requested route approval through embargoed areas of CT Guards will be off-duty CT State Police officers Util will provide special training Te security & radiological considerations COUNSIL.W C . FEE.W F Connecticut Yankee Atomic Power Co 80/03/24
- 8004020349 Submits info re safety evaluation for postulated fuel handling accident in new & spent fuel storage bldg, in response to NRC 791220 request COUNSIL.W 9 Mains Yankee Atomic Power Co 80/03/25 4pp
- 8004110928 Provides add1 info re implementation requirements set forth in Item 2 i 7a of NUREO-0978 Requests response by 800601 indicating commitment to install safety-grade sys by 810101 EISENHUT, D O Division of Operating Reactors 80/03/27. 2pp
- 8004070265 Submits info re direct indication of PORV & safety valve positions Recent discussions w/vendor revealed difficulty w/800401 completion date Revised date of completion is CBUNSIL.W G Wortheast Utilities 80/03/28 2op
- 8004210227 Forwards request for info re containment environ conditions & sys required for accident mitigation for review of environ qualifications of Class IE electrical equipment NRC will estimate time for containment temp to return near normal ZIEMANN, D.L. Operating Reactors Branch 2 80/03/28 14pp
- 8004070274 Discusses current intentions to submit design for providing sampling capacity for primary coolant & containment air by 800427 Utils are currently engaged in finalizing design details Blight delay is required to optimize design COUNSIL.W G. Connecticut Yankee Atomic Power Co 80/04/01 2pc
- 8004150297 Confirms 800403 telcon re Hestinghouse low pressure turbine disc integrity Util & Westinghouse concur that safety concern does not exist Turbine overspeed will be limited to 20% atd speed until arguments are documented GOUNBIL.N G., FEE.N F Connecticut Yankee Atomic Power Co 80/04/03 19
- 8004180345 Forwards info re saismic re-evaluation requested by NRC during 790516 meeting Previous seismological determination of DSE unaffected Connecticut Yankes Atomic Power Co 80/04/07 2ap
- --8004180348 "NRC Info Request on Geology & Seismology "
 * Western Geophysical 80/03/31 18pp
- 8004170012 Discusses problems w/implementation of Lessons Learned Task Force recommendation to automatic initiation of auxiliary feedwaters sys Requests NRC concurrence w/plan for implementing requirement during 1980 refueling outage CDUNBIL.W G Connecticut Yankee Atomic Power Co CDUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11
- 8004180224 Forwards info clarifying & supporting conclusion that Category A Lessons Learned Task Force requirements have been implemented Oversite drawing encl COUNBIL:N O Connecticut Yankee Atomic Power Co. 80/04/11 81pp
- 8004270442 Forwards add1 info in support of 780321 proposed changes to Tech Specs Revisions delete prohibition of spent fuel cask movement over spent fuel pool & substitute add1 restrictions Requests expeditious action G
- 004280465 Responds to final questions in review of changes to Tech Spect re spent fuel cask movement Five separate shipments planned re testing & evaluation effort Return shipments not yet scheduled Requests seven movements to allow for changes GOUNSIL: H G. Connecticut Yankee Atomic Power Co BO/04/23 2pp
- @ Inspection reports. IE Bulletins & correspondence
- BO04090131 Forwards IE Insp Repts 50-213/79-20, 50-245/79-26 & 50-336/79-28 on 791127-30 & 1203-07 No noncompliance noted. BRUNNER:E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/02/08. 2pp.

- --8004090138 IE insp Repts 50-213/79-20.50-245/79-26 & 50-336/79-28 on 791127-30 % 1203-07 No nuncompliance noted Major areas inspected QA program implementation re QA/QC administration, design changes & mods & document control program BAUNACK,W H Region 1, Philadelphia, Reactor Operations Nuclear Support Branch NAPUDA.6 Region 1, Philadelphia, Office of the Director 80/02/07 15pp
- B0040B0448 Forwards IE Insp Rept 50-213/80-02 on 800122-25 No noncompliance noted BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/19 ≳pp
- --8004080450 IE Insp Rept 90-213/80-02 on 800122-25 No noncompliance noted Major areas inspected details re establishment of onsite efc for full-time resident inspector KEIMIG.R R Region 1. Philadelphia. Reactor Operations Nuclear Support Branch MCGSCAR.J J. BMITH.T H Region 1. Philadelphia. Office of the Director 80/02/15 7pp
- 8004110012 Submits response to IE Bulletin 79-27 re loss of non-Class 104110012 Submits response to IE Bulletin 77-27 me loss of I IE instrumentation & control power supply bus during operation Facility has two semivital buses w/two feeds via auto transfer & backed by two emergency generators COUNSIL.W G , FEE.W F Connecticut Yankee Atomic Power Co 80/03/03 2pp
- 8004030261 Submits response to IE Bulletin BO-04, re analysis of PWR main steam line break w/continued feedwater addition Efforts are in progress to finalize details of control grade automatic initiation of auxiliary feedwater scheme COUNSIL. W O Northeast Utilities 80/03/05 1p
- 8004070425 Ack receipt of 791227 & 800104 ltrs informing NRC of corrective & preventive actions & check in payment of 791206 notice of proposed imposition of civil genalties Acting supervisor did not meet min qualifications
 STELLG. V Office of Inspection & Enforcement, Office of the Director 80/03/20 2pp
- 8004250132 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-Inch Tray, Adsorber Colls" No replacements necessary due to damage to or corresion of engineered safety feature filters COUNSIL. N Θ , FEE. N F Connecticut Yankee Atomic Power Co B0/03/24 5pp
- ---8004250143 Special Haint Procedure SPL 10 7-5, "Containment Air Recirculation Fans Installation of Addl Charcoal Air Filters" Connecticut Yankee Atomic Power Co 79/02/07 10pg
- 8004030211 Advises that reactor coolant pump & vessel cladding exams scheduled for 1980 refueling outage are impractical Proposes alternative inservice insplexam method for Category B-B welds on regenerative heat exchanger Requests NRC review COUNSIL.W 0 Connecticut Yankee Atomic Power Co 80/03/25 Spp
- 8004250051 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/80-01 Util ltr to be withheld (ref 10CFR2 770)

 MARTIN.W 9 Region 1. Philadolphia, Safeguards Branch 80/03/28
- --8004250054 Forwards IE Insp Rept 50-213/80-01 on 800108-11 MARTIN,W G Region 1, Philadelphia, Bafeguards Branch 80/02/21
- --8004250059 IE Insp Rept 50-213/80-01 on 800108-11 Noncompliance noted door found unlocked & unattended in vital area Failure to maintain surveillance of protected area barriers & exterior vital area door Details withheld (ref 100FR2 790) LADUN.R H . MADDEN.W Region 1. Philadelphia, Office of the Director DEVLIN.J W Region 1. Philadelphia, Bafeguards Branch 80/02/11 ip
- 8004150262 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region i, Philadelphia. Office of the Director 80/03/31 lp
- 8004090047 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER:B K Region 1. Philadelphia. Office of the Director 80/04/01 lp
- 8004110128 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p

- 8004240278 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No aution required GRIER, B H Region i, Philadelphia, Office of the Director 80/04/02 ip
- 8004180226 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys "No written response required GRIER.B H Region i, Philadelphia. Office of the Director 60/04/03 ip
- 8004230401 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 Ip
- 8004180131 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 6004020372 Forwards "Personnel Exposure & Monitoring Rept for 1979 " ORAVES,R H Connecticut Yankes Atomic Power Co 80/03/14 1p
- 8004040331 Forwards "Annual Environ Operating Rept, 1979," Part A nonradiological CDUNSIL.W Q Connecticut Yankee Atomic Power Co 80/03/30 1p
- --8004040338 "Annual Environ Operating Rept. 1979 " Part A nonradiological * Connecticut Yankae Atomic Power Co 80/03/31 48pp
- 8004150487 Forwards "Radiological Environ Monitoring Program Annual Environ Operating Rept.Part 8,1979," prepared by Northeast Utils Svc Co CDUNSIL.W 0 Connecticut Yankee Atomic Power Co 80/03/31 1p
- ~-8004190493 "Radiological Environ Monitoring Program Annual Environ Operating Rept.Part B. 1977 " * Northeast Utilities Service Co 60/03/31 100pp
- 8004240437 Forwards "Annual Rept of Changes, Tests & Experiments 1979 "
 GRAVES, R H Connecticut Yankee Atomic Power Co 80/04/01 ip
- --8004240437 "Annual Rept of Changes, Tests & Experiments 1979 "
 GRAVES, R H Connecticut Yankee Atomic Power Co 80/04/01 44pp
- 8004290264 "Annual Operating Rept of Facility Changes, Tests & Experiments, 1979 "
 ORAVES, R H Connecticut Yankee Atomic Power Co 80/04/01 47pp
- 8004210251 Forwards monthly operating rept for Mar 1980 ORAVEB.R H Connecticut Yankee Atomic Power Co 80/0 80/04/10 ip
- --8004210253 Monthly operating rept for Mar 1980 * Connecticut Yenkee Atomic Power Co 80/04/10 Bpp
- S Reportable occurrences, LERs & related correspondence
- B004090027 PND-I-80-041 on 800313, radiological surveys of site grounds uncovered three small patches of contaminated soil outside controlled area Approx three tablespoons soil removed Burvey continuing to determine if other areas contaminated BCRABIAN, J. KNAPP, P., GMITH, G. Region I, Philadelphia, Office of the Director 60/03/14 1p
- 8004010362 Forwards LER 80-006/03L-0.

 ORAVES:R H Connecticut Yankee Atomic Fower Co. 80/03/20 1p
- --8004010369 LER 80-006/03L-0 on 800306. during routine monthly fan damper test, broken linkage coupling was found on CAR2 fan bypass damper.causing fan to be inoperable, Linkage coupling was replaced w/steel coupling of greater strength ORAVES.R H Connecticut Yankee Atomic Power Co 80/03/20 Ip

- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT
- 6 Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDSSICK, L V Office of the Executive Director for Operations B0/04/02 34pp
- 8004240532 Forwards NRC confirmatory order STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 1p
- --8004240537 Order confirming util commitment to perform review requested by IE Bullstin 79-27 by 800425, Required info is specified in Attachment A STELLO, V Office of Inspection & Enforcement, Office of the Director 60/04/04 opp
- H General correspondence
- 8004030123 Responds to 790816, itr re plans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restart of TMI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety FOSTER.K Affiliation Unknown 79/08/16 2pp
- l Financial information
- 8004100352 Forwards JCP&L & General Public Utils Corp Annual Financial Repts 1979 ROSS, D.A. Jersey Cantral Power & Light Co. 80/04/01 ip
- --8004100355 Annual Financial Rept 1979 * Jersey Central Power & Light Co 80/03/24 24pp
- --B004100356 Annu41 Financial Rept 1979
 * General Public Utilities GPU Service Corp 80/04/01 44pp
- P Operating license stage documents & correspondence
- 8004100317 Advises that responses to 761123 ltrs re LHR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors, per typical fuel bundle & batch hungs.

 ZIEMANN.D L Operating Reactors Branch 2 80/02/29 3pp
- B004100320 Notification of B00305 meeting w/util in Bethesda.MD recore spray sparger cracks & repairs NOHICKLS J Operating Reactors Branch 2 B0/03/03 200
- 8004uzuvur rerwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 Spp
- BOO4040086 Notifies that NRC inedvertently omitted approved change to .Tech Spec 3 4.8 L.rs automatic depressurization sys.during issuance of Amend 45 to Provisional CL DPR-16 Forwards corrected Page 3 4-19 ZIEMANN.D L Operating Reactors Branch 2 80/03/07 Spp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Sethesda Operations Ctr CISENHUT, D 9 Division of Operating Reactors. B0/03/12 5pp
- --8004030110 "Nuclear Data Link Specs " * Division of Operating Reactors. 80/02/21 28pp
- 8004230234 Forwards NRC 800128 & 0211 ltrs to GE re proposed control rod drive sys mods & optimizing pump flow to reactor vessel. Mods should not be performed until complete guidance is issued in NUREG-0619 or w/o NRC approval ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 2pp

- 3004090329 Forwards "Fish Kill Associated W/800105 Outage at Facility "ROSB:DA Jersey Central Power & Light Co 80/03/26 Ip
- --8004090330 "Fish Kill Associated W/800105 Outage at Facility "
 ROCHE.M D Jersey Central Power & Light Co 80/03/31 50pp
- 8004170253 Notification of 800401 meeting w/util in Bethesda.MD to discuss core spray sparger cracks & repairs MORWICKI,8 J Operating Reactors Branch 2 80/03/28 2pp
- 8004170285 Forwards request for addl info re environ qualification of electrical equipment
 ZIEMANN,D L Operating Reactors Branch 2 80/03/28 14pp
- BO04020319 Forwards Tech Spec Change Request 83.modifiping App A. Section 4 3 to provide for augmented inservice insp of corespray sys spargers Class III fee encl FINFROCK: I R Jersey Central Power & Light Co 80/03/31 lp
- ---8004020320 Tech Spec Change Request 83 modifying App ArSection 4 3 to provide for augmented inservice insp of core spray sys spargers
 - Jersey Central Power & Light Co 80/03/31 66pp
- BOO4160276 Forwards component list for SEP Topic III-12 re safety sysessential to mittigate postulated accidents as requested by NRC at 800310-13 meeting TIPTON, T.E. Jersey Central Power & Light Co. BO/04/11 12pp
- 8004220509 Forwards Revision 4 to Amend 71 to application for QL Responds to several items in NRC 790814 request for add1 info re operational GA plan Remaining items will be addressed in Revision 4 to GA plan FINFROCK-I R Jersey Central Power & Light Co 80/04/17 ip
- --B004220511 Revision 4 to Amend 71 to application for DL Revision 4 incorporates organizational changes FINFROCK, I.R. Jersey Central Power & Light Co. 80/04/17 7pp
- --8004220514 Operational GA plan Revision 3 FINFROCK, I R Jersey Central Power & Light Co 79/11/09 190pp
- 8004230341 Forwards QE "Reload Fuel Application " Fee encl ROBS.D A Jersey Central Power & Light Co 80/04/21
- -8004230343 "Reload Fuel Application "
 OALER R R , ENGEL R E General Electric Co NEDO-24195
 79/08/31 200pp
- 8004280513 Requests extension until 800831 for completion of matl status rept & physical inventories Inventories taken immediately would not be representative of post-outage conditions R 088, D. A. Jersey Central Power & Light Co 80/04/25 1p
- G Inspection reports: lE Bulletins & correspondence
- 8004070417 Forwards IE losp Rept 50-219/80-01 on 800104-05.08-11 & 14 No noncompliance noted
 BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear
 Bupport Branch 80/02/14. 2pp
- --8004090422 IE Insp Rept 50-219/80-01 on 800104-04.08-11 \$ 14 No JUNEAU VALUE (E INSP. REPT 50-217/80-01 on BOOID4-03.08-11 & 14 No noncompliance noted Major areas inspected refueling preparation, refueling activities & independent inspectfor KEIMIG R R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. BRIQOGAL E Region 1. Philadelphia. Office of the Director. 60/02/13 App
- 3004080421 Advises that response to IE Bulletin 79-27 re loss of non-class IE instrumentation will not be complete within 90 days Requests extension until 800425 ROBS.D A Jarsey Central Power & Light Co 80/02/22 is
- 8004180329 Forwards IE loss Rept 50-219/80-02 on 800115-18 No noncompliance noted CARLSON.R.T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/26. 2pp
- ---8004180334 IE Insp Rept 50-219/80-02 on 800115-18 No noncompliance noted Major areas inspected: five mods & event rept followups.

 ENNETER, S. D. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. #1NKEL, A. E. Region i, Philadelphia, Office of the Director 80/02/25, 4pp

- 8004210326 Forwards IE Insp Rept 50-219/79-20 on 791127-30 No noncompliance noted MARTIN,W G Region 1. Philadelphia, Safeguards Branch 60/02/27
- -8004210330 IE Insp Rept 50-219/79-20 on 791127-30 No noncompliance noted Major areas inspected security plansprogram audit, physical barriers in protected & vital areas lighting & access control Details withheld (ref 10CFR2 790) DEVLIN, J W Region 1, Philadelphia, Bafeguards Branch MADDEN, k Region 1, Philadelphia, Office of the Director 80/02/20 1p HANDEN, IJ
- 8004210439 Forwards IE Insp Rept 50-219/80-05 on 800129-0201 No noncompliance noted
 BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear
 Support Branch 80/02/27 2pp
- --8004210450 IE Imap Rept 50-219/80-05 on 800129-0201 No noncompliance noted Major areas inspected refueling activites, independent insp effort.IE builetin followup, inofc LER roview & periodic REINIG,R R , BRIGGS,T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/26 App
- 8004090238 Ack receipt of 800222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/79-24 BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/03/04 1p
- --8004070246 Responds to NRC 800128 itr violations noted in IE Insp Rept 50-219/79-24 Corrective actions crates were painted w/fire retardant paint & administrative controls established ROSS, D.A. Jersey Central Power & Light Co. 80/02/22 2pg
- --8004090249 Forwards IE Insp Rept 50-219/79-24 on 791211-14 & 18 & notice of violation BRUNNER,E J Region 1. Philadelphia, Reactor Operations Muclear Support Branch 80/01/28 2pp
- --8004090254 Notice of violation from insp on 791211-14 & 18 * Region 1, Philadelphia, Office of the Director 80/01/25 ip
- ~~8004090262 IE Insp Rept 50~219/79~24 on 791211~14 & 18 Noncompliance noted, improper storage of flammable matl KEIMIO:R R Region i, Philadelphia: Reactor Operations Nuclear Support Branch KOLTAY, P. BR1908;L Region i, Philadelphia. Office of the Director 80/01/25 6pp
- 8004100424 Responds to IE Bulletin 80-03 Charcoal adsorber cells presently utilized are acceptable & provide no indication of structural deficiencies which would affect filter ormance p.D.A. Jarsey Central Power & Light Co 80/03/13 2pp
- 8004090420 Advises that IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVC8) Holdup Tanks," was incorrectly sent for action No response required GRIER, B H Region i, Philadelphia, Office of the Director 80/03/17 ip
- 8004150269 Forwards IE Info Notice 80-12, "Instrument Failure Causes Deming of PORV & Block Valve " No specific action or response necessary ORICE, B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- 8004090057 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/01 ip
- BO04110137 Forwards IE Info Notice 80-13, "OE Type SBM Control Bwitches Defective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004110422 Provides NRC w/immediate corrective actions in radiation grotection dept in response to IE Insp Repts 80-3 & 80-11 Corrective actions involve personnel, procedures, training & work activities Jersey Central Power & Light Co. 80/04/02 2pp
- 8004240311 Forwards IR Info Notice 80-14, "Safety Suggestions From Employees" No action required ORIER, B H Region 1, Philadelphia, Office of the Director. 80/04/02 ip

.

DOCKETED ITEMS

- 8004180166 Forwards 1E Circular 80-07, "Problems W/MPCI Turbine Oil Sys "No written response required GRIER, B H Region 1, Philadelphia, Office of the Director
- 8004230478 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312.Tupe 304 Stainless Steel Pipe " Action required GRIER,B H Region 1. Philadelphia. Office of the Director BO/04/04 ip
- B0041B0149 Forwards IE Bulletin B0-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER, B H Region 1. Philadelphia, Office of the Director B0/04/07 ip
- R Periodic operating reports & related correspondence
- 8004020383 Forwards "1979 Annual Environ Operating Rept for ETS, App 8 " FINFROCK, I R Jarsey Cantral Power & Light Co 80/03/28 2pp
- --8004020386 "1979 Annual Environ Operating Rept for ETS, App B " * Jersey Central Power & Light Co 80/03/31 183pp
- 8004240425 Forwards monthly operating rept for Mar 1980 ROSS,D A Jersey Central Power & Light Co 80/04/16 80/04/16
- --8004240432 Monthly operating rept for Mar 1780 MCCLAIN.C M Jersey Central Power & Light Co 80/04/09
- 8 Reportable occurrences, LERs & related correspondence
- 8004010480 Forwards LER 80-014/01T-0 ROSS,D A Jersey Central Power & Light Co 80/03/24 ip
- -8004010485 LER 80-014/01T-O on 800302. emergency diewel generator 1 ,failed to synchronize & tripped when generator 2 was lagged for mod Caused by component failure Fuse [7. found loose in holder Fuseholder repaired RDS8,D A Jersey Central Power & Light Co 80/03/24 3pp
- 8004010503 Forwards LER 80-013/01T-0 ROBS,D A Jersey Central Power & Light Co 80/03/24 ip
- -8004010509 LER 80-013/01T-0 on 800309, fire suppression removed from svc to replace cracked valve contrary to Tech Specs Fire truck pumper used as water supply backup Cause of valve body crack under investigation ROSS.D A Jersey Central Power & Light Co 80/03/24 Sp
- 8004040284 Forwards LER 80-012/03L-0 ROSS,D A Jarsey Central Power & Light Co 80/03/27 1p
- --8004040288 LER 80-012/03L-0 on 800228, discovered that weekly purpovered LEK co-distributed on bookers discovered that weeking surveillance tests for main station & diesel generation batteries not performed during seventh wk Caused by error in personnel Evaluation will be made to determine improvements ROSS:D A Jersey Central Power & Light Co 80/03/27 Spp
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1 Security, medical, emergency & fire protection plans
- 8004230216 Forwards criteria not adequately covered by 791228 emergency plan for revision per NUREO-0654, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparedness in Support of Nuclear Power Plants "
 ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 17pp
- 8004230221 Forwards criteria not adequately covered by 800125 emergency plan for revision per NUREG-0654, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparedness in Support of Nuclear Power Plants "IPPOLITO,T A Operating Reactors Branch 3 80/03/27, 17pp
- 8004070269 Forwards into re 791211 security plan change Encl withheld (ref 100FR2 790) BARTLETT, J Niagara Mohawk Power Corp 80/03/31 1p
- 8004180345 Forwards "Functional Spec for Facility Fire Protection Mods. Fire Detection & Control." BARTLETT, J Niagara Mohawk Power Corp 80/04/14 1p
- -8004180349 "Functional Spec for Facility Fire Protection Mode.Fire Dataction & Control " SWEET, K J Niagara Mohawk Power Corp 80/03/27 50pp

- H General correspondence
- 8004280440 Notifies that position of Vice President for Electric Production abolished & future NRC correspondence should be sent to DP Dise,Vice President for Engineering Security matters should be addressed to JJ Sunse; BARTLETT, J Niagara Mohawk Power Corp 80/04/22 ip
- 8004270363 Informs of changes in mgt to provide for more efficient operation Effective 800301.TE Lempges elected Vice Presidents.Nuclear Generation Correspondence is security matters should be sent to Sunser & Lempges BARTLETT.J G Niagara Mohawk Power Corp 80/04/22 ip
- P Operating license stage documents & correspondence
- 8004070402 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 9pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr Division of Operating Reactors 80/03/12 5pp EIBENHUT, D Q
- --8004030118 "Nuclear Data Link Specs" * Division of Operating Reactors 80/02/21 28pp
- B004010330 Forwards info re primary copiant pressule isolation capability as per 800223 request Info demonstrates that continued operation of facility does not present undue safety hazard to public DISE.D P Niagara Mohawk Power Corp 80/03/19 14pp
- 8004100032 Forwards "Evaluation of License Compliance W/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned " All Category A requirements have been satisfactorily met Mods will be verified by IE IPPOLITO.T A Operating Reactors Branch 3 80/03/21 15pp
- 8004180253 Forwards Amend 36 to License DPR-43, safety evaluation & notice of issuance & availability IPPOLITO, T A Decrating Reactors Branch 3 80/03/20 2pp
- -8004180258 Amend 36 to License DPR-63, changing Tech Specs to modify power-to-flow curve & allowing addl operational flexibility during plant load changes PPOLITO, TA Operating Reactors Branch 3 80/03/28 8pp
- --8004180277 Safety evaluation supporting Amend 36 to License DPR-63 * Operating Reactors Branch 3 80/03/28 3pp
- --8004180278 Notice of issuance & availability of Amends 36 to License DPR-63 IPPOLITD.T A Operating Reactors Branch 3 80/03/28 2pp
- 8004250034 Forwards 800128 & 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line nottles Mods should not be performed prior to issuance of NUREG-0617.scheduled for Apr 1980 IPPOLITO, T A Operating Reactors Branch 3 80/04/07 2pp
- 8004210407 Submits info clarifying util NUREG-0578 commitment re containment water level indication Util will install new differential pressure transmitters on torus using existing instrument taps BARTLETT, J Niagara Mohawk Power Corp 80/04/11 ip
- 8004220464 Forwards application for amend to License DPR-63 & proposed Tech Spec changes to App A
 THDMAS,E B LeBosuf, Lamb, Leiby & HacRae 80/04/21 ip
- --8004220501 Application for amend to License DPR-43, requesting that Bections 2 (1.3 (7.3 6 4.6 O & bases of Tech Specs set forth in App A be revised BARTLETT, J Niagara Mohawk Power Corp 80/04/18 2pp
- ---8004220504 Proposed Tech Spec App A changes to Sections 2 1 1.3 1 7. 3 6 4.6 0 % bases * Niagara Mohawk Power Corp 80/04/18 33pp

```
Inspection reports. (E Bulletins & correspondence
```

- 004100162 Forwards IE Insp Rept 50-220/79-26 on 791210.il & 13 No noncompliance noted SMITH, 0 H Region I. Philadelphia. Fuel Facility & Materials Safety Branch 80/02/19 2pp
- -8004100173 IE Inep Rept 50~220/79-26 on 79:210.11 & 13 No noncompliance noted Major areas inspected licenses response to IE Bulletin 79-19, documents, procedures, training, audits, facility tours & records
 KNNFP.P J Region 1. Philadelphia, Fuel Facility & Materials
 Bafety Branch THOMAS.L H Region 1. Philadelphia, Office of the Director 80/02/15 4pp
- 1004080415 Advises that per 791207 ltr re IE Bulletin 79-14.ho mods are necessary to condensate demineralizer recycle loop DISE.D P Niagara Mohawk Power Corp 80/02/22 1p
- 3004090239 Forwards response to IE Bulletin 79-27 re loss of non-class IE instrumentation & control power sys buses during operation No mode nocessary after review BARLETT, J Niagara Mohawk Power Corp 80/02/29 8pp
- B004110055 Forwards response to IE Bulletin 79-018, re environ qualification of Class IE equipment Util is investigating equipment qualification of outstanding items Results will be reported in second response on B00417 W/o encl
 LEMPGES.T E Niagara (Johawk Power Corp B0/03/05 2pp
- 6004100401 Responds to IE Bulletin 79-018 Response to 1E Bulletin 79-01 dtd 790712 indicated interim repts on equipment environ qualification would be provided every 60 days Repts will be discontinued & replaced by IE Bulletin 79-018 responses LEMPGEB.T E Niagera Mohawk Power Corp 80/03/07 ip
- 8004090407 Advises that IE Bulletin BO~05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 ip
- 8004010373 Responds to IE Bulletin 80-03, "Loss of Charcoal from 8td Type il. Tuo-Inch. Tray Adsorber Cells " No aquipment abnormalities evident which would affect performance of reactor or control room emergency ventilation sys LEMPGES, T E Niagara Mohawk Power Corp 80/03/19 ip
- 8004010392 Discusses corrective action re IC Insp Rept 50-220/80-01 No apparent reason found for missing chain locking device on liquid poison sys valve 41-12 Valve was checked off as locked & closed during 790522 sys valve lineup check LEMPGES.T E Niagara Mohawk Power Corp 80/03/19, 1p
- 8004080642 Clarifies 800319 response to IE Insp Rept 50-220/80-01 All locks which secure valves in position described by operating procedure valve check-off list will have cores changed to unique key series by end of 1981

 LEMPGES, T E Niagara Mohawk Power Corp 80/03/28 ip
- 8004150282 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER.B H. Region 1, Philadolphia. Office of the Director 80/03/31 1p
- 9004090080 Forwards IE Circular 80-05, "Emergency Biesel Generator ubricating Oil Addition & Onsite Bupply " No written appose required IEE, B H Region 1, Philadelphia. Office of the Director /04/01 1p
 - 110158 Forwards IE info Notice 80-13, "QE Type SBM Control Switches fective CAM Followers " No written response required Aler. B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004240324 Forwards IR Info Notice 80-14. "Safety Suggestions From Employees" No action required. GRIER, B. N. Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004180262 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/04/03, 1p

- 8004230386 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required GRIER. B H Region 1. Philadelphia. Office of the Director 80/04/04 1p
- 8004180209 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director. 80/04/07 1p
- R Periodic operating reports & related correspondence
- 8004040404 Forwards "1979 Aquatic Ecology Studies " LEMPGES,T C. Niagara Mohawk Power Corp. 80/03/28 ip
- --8004040409 "1979 Aquatic Ecology Studies " * Teras Instruments, Inc 80/03/31 100pp
- 8004140406 Forwards monthly operating rept for Mar 1980 LEMPGES, T. E. Niagara Mohawk Power Corp. 80/04/03 3pp
- --8004140411 Monthly operating rept for Mar 1980 RDMAN, T W Niagara Mohawk Power Corp 80/04/02 3pp
- DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

 G Adjudicatory correspondence
- BOO4230340 Requests NRC intentions for planning hearings re-petition to auspend all activities of TRIGA reactor Urges immediate resolution of issues between NRG & Berkeley, CA NEWPORT, E-G Berkeley, CA 80/04/17 ip
- DOCKET 50-225 RPI CRITICAL EXPERIMENT
- G Inspection reports, IE Bulletins & correspondence
- 8004300317 Ack receipt of 800328 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-225/80-01 SMITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/07, 1p
- ---8004300320 Responds to NRC 800310 ltr re violations noted in IE Insp Rept 50-225/80-01 Corrective actions personnel monitoring procedure revised & TLD records now computerized RYAN.R M Rensselaer Polytechnic Inst 80/03/28 ip
- --B004300322 Forwards IE Insp Rept 30-225/80-01 on 800(15-17 & notice of violation SMITH.OF Region 1. Philadelphia. Fuel Facility & Materials Safety Branch B0/03/10 2pp
- --8004300324 Notice of violation from insp on 800115-17 * Region 1, Philadelphia, Offica of the Director, 80/03/06 ip
- --8004300328 IE Insp Rept 50-225/80-01 on 800115-17 Noncompliance noted failure to maintain personnel dosimetry records TERC, N M, BORRES, R J. Region i. Philadelphia, Fuel Fecility & Materials Safety Branch 80/03/04 9pp
- DOCKET SO-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8004170005 Application for transfer of License R-98 from Acrotest Operations, Inc to Acrotest Operations Acquisitions, Inc Bupporting documentation encl ELKUS.R J Aerotest Operations 80/04/11 11pp
- DOCKET 80-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone network Bys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimille tra

- 8004030172 Forwards Figure 2-1 to correct omission made in 800311 ltr re gvacuation time estimates for facility Figure 3-1 in Section 3 should be placed in Section 2 PEOPLES.D L. Commonwealth Eduson Co. 80/03/26 2pp
- 8004110399 Confirms & documents 800326 teleon re facility turbine bldg mezzanine area fire protection capabilities fire provention & protection features are adequate & provide high degree of plant safety JANECEK, R F Co Commonwealth Edison Co 80/04/08 2pp
- 8004220299 Informs that Unit 3 refueling outage bagan 4 wks early & will end approx one month earlier than scheduled, due to failure in recirculation sys jet pump Completion of some fire protection mods will not be possible prior to startup PEOPLES.D L. Commonwealth Edison Co. 80/04/10 ip
- 8004230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790) PEOPLES, D L Co Commonwealth Edison Co 80/04/21 1P
- @ Adjudicatory correspondence
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSIGN, L V Office of the Executive Director for Operations 80/04/02 34pp
- P Operating license stage documents & correspondence
- 8004080276 Forwards corrected Pages 88 & 93 for Licenses DPR-17 Amend 44 & DPR-25 Amend 39 & corrected Pages 3 6/4 6-2 & 3 6/4 6-9 for licenses DPR-27 Amend 53 & DPR-30 Amend 50 in response to 791002 itr IPPOLITO, T A Operating Reactors Branch 3 80/02/20 2pp
- --B004080310 Corrected License Pages 88 & 93 for Amends 44 & 39 to Licenses DPR-19 & DPR-25, respectively & corrected License Pages 3 6/4 6-2 & 3 6/4 6-9 for Amends 53 & 50 to Licenses DPR-29 & DPR-30, respectively * Operating Reactors Branch 3 60/02/20 8pp
- 8004030027 Submits info requested in 800201 ltr re seepage from plant cooling lake No dike stability or integrity concerns have been identified No effect on health & safety of public Increased surveillance will provide info to evaluate change PEOPLES:D L Commonwealth Edison Co 80/02/29 2pp
- 8004070335 Forwards NUREG-0569. "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 W/o encl ZIEMANN,D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020010 Forwards review schedule for environ qualification of Class IC electrical equipment per 800221 moeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN.D L Operating Reactors Branch 2 80/03/06 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENNUT, D G Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Seactors 80/02/21 28pp
- BO04010357 Forwards LPCI hanger details from ring header to pumps 2A-1502 Matrix indicating hanger number, type, manufacturer, rated load & design encl
 JANECEK,R.F. Gommonwealth Edison Co 80/03/17 6pp
- 8004100102 Requests controlled set of P&IDs for each plant Bubmittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER, J O. Region 3. Chicago. Office of the Director 60/03/20
- 8004230226 Forwards NRC 800128 & 0211 ltre to GE re proposed control rod drive sys mods & optimizing pump flow to reactor vassel Mods should not be performed until complete guidance is issued in NUREO-0619 or w/o NRC approval ZIEMANN,D L Operating Reactors Branch 2 80/03/24 2pp
- BOO4080235 Submits status rept for open site suitability review items per BOO304 commitment QE has extracted info re reactor vessel supports from original design files Info will be forwarded to NRC Mar 1980 Issue should be resolved JANECEK.R F Commonwealth Edison Co 80/03/27 6pp.

- 8004070245 Forwards OE info re imposed loads on reactor pressure vessel Novile reaction loads tabulated on Drawing 885D910, Revision 6 intended to include all loads that piping can impose on reactor pressure vessel JANACEK,R F Commonwealth Edison Co 80/03/28 4pp
- B004230178 Forwards request for info re environ qualification of electrical equipment Data is needed for NRC calculation of containment temp & pressure decay time Calculation should be based on current LOCA analysis ZIEMANN.D L Operating Reactors Dranch 2 80/03/28 14pp
- B004110458 Responds to NRC 800101 itr requesting info re anchorage of safety-related electrical equipment Submits action plan & info required by Question 1

 JANACEK.R F Commonwealth Edison Co 80/04/01 App
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02
- --800415032B Revised pages constituting Revision 13 to GA program
 Revisions reflect recent organizational title changes
 * Commonwealth Edison Co CE-1-A R13 80/04/04 7pp
- 800414039B Advises that replacement of spring safety valves w/safety relief valves will not be necessary due to reclassification of pressuriation transient frequency & addl measures for prevention of premature valve actuation

 JANENCEK.R F Commonwealth Edison Co 80/04/08 2pp
- 8004180217 Forwards addl info re failure of control rods to insert fully on scram in response to NRC 800110 & 11 ltrs Dresdem 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worn piston seals JANECEK.R F Commonwealth Edison Co 80/04/14 10pp
- 8004220348 Responds to NRC 800214 ltr re SEP topic references Lists references for ECC8 actuation sys.engineering safety feature switch over from injection to recirculation mode & testing of reactor trip sys

 JANECEK.R F Commonwealth Edison Co 80/04/14 3pp
- 8004250427 Forwards response to NUREG-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lasalle County site-specific emergency plan PEOPLES,D L Commonwealth Edison Co 80/04/15 6Opp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- G Inspection reports, IE Bulletins & correspondence
- 8004070197 Forwards IE Insp Repts 50-010/79-23,50-237/79-27 & 50-249/79-29 on 791009 & 1128 & notice of violation DAVIB.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/12 2pp
- --8004070142 # Region
- --8004070166 IE Insp Repts 90-010/79-23,50-237/79-27,% 50-249/79-25 on 791007 & 1128 Noncompliance noted radioactive mat1 shipment record not utilized for raduaste shipments made 790101-1128 GREGERL R. FISHER, W.L. Region 3, Chicago, Office of the Director 80/01/31. 7pp
- 8004040195 Forwards IE Insp Repts 50-010/80-01.50-297/80-01 & 50-249/80-01 on 800108-09 No noncompliance noted FIORELLI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --8004040199 IE Insp Repts 50-010/80-01,50-237/80-01 & 50-249/80-01 on 800108-09 No noncompliance noted Major areas inspected amergency diesel generator mods & mod of electrical equipment re IEEE-279 compliance HAYES,D W Region 3. Chicago, Reactor Construction & Engineering Support Branch HUGHES,J Region 3. Chicago, Office of the Director 80/02/08 5pp
- 8004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted

 DAVIG.A B Region 3, Chicago, Fuel Facility & Materials Bafety

 Branch B0/02/22 2pp

- --8004100408 Waste Packages Insp Rept 79-07A on 791212-13 No moncompliance noted Major area inspected compliance w/DOT & NRC regulations including shipping paper requirements. radiation levels & DOT labeling POTTER,J P. PEERY,W W. WOODRUFF,R L. Region G. Chicago, Fuel Facility & Materials Safety Branch. 80/02/22 App
- 8004100426 Forwards IE Insp Repts 50-010/80-03.50-237/80-03 & 50-249/80-03 on 900107-0201 No noncompliance noted HEIGHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004100432 IE Insp Repts 50-010/80-03.50-237/80-03 & 50-249/80-03 on 800107-0201.No noncompliance noted Major areas inspected maint activities.plant operations.physical protection, safety-related sys surveillance insp followup & rafueling BARMER, J L , TONQUE.T M , SPESSARD, R L Region 3. Chicago, Office of the Director 80/02/22 7pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region G, Chicago, Office of the Director 80/03/07
- 8004100119 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in JE lnsp Repts 50-010/79-23, 50-237/79-27 & 50-249/79-25 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/20 2pp
- --8004100128 Responds to NRC 800212 ltr re violations noted in IE Insp Repts 50-010/79-23.50-237/79-27 & 50-249/79-25 Corrective actions informed personnel re cost estimate change order requirements PEOPLES.D L. Commonwealth Edison Co. 80/03/04 3pp
- BOO4140119 Forwards response to IE Bullotin BO-OG. "Loss of Charcoal from Std Type II.Two-lack Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES.D L. Commonwealth Edison Co. 80/03/20 5pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS,A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted DAVIB.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No moncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels, removable contamination & package axternal features POTTER, J.P. PEERY, W. W. WOODRUFF, R.L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004300544 Forwards IE Insp Repts 50-010/80-04.50-237/80-04 & 50-249/80-04 on 800220-22 & 26 & notice of violation DAVIS,A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 2pp
- ---8004300548 Natice of violation from imap on 800220-22 t 26 * Region 3. Chicago. Office of the Director 80/03/11 ip
- --8004300555 IE Insp Repts 50-010/80-04.50-237/80-04 & 50-249/80-04 on 800220-22 % 26 No moncompliance noted Major areas inspected internal audits, licensee coordination w/offsite support agencies & review of emergency drills EBSTO.T H. DESTMANN.M J. MATSON.E Region 3, Chicago, Office of the Director 80/03/11 10pp.
 - 150159 Forwards IE Info Notice BO-12, "Instrument Failure Causes ening of PORV & Block Valve " No specific action or esponse necessary KEPPLER. J G Region 3. Chicago. Office of the Director 80/03/31
- 8004080686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Qil Addition & Onsite Supply " No written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/04/01

- B004150014 Forwards IE Info Notice 80-13, "GE Type BBM Control Switches Difective CAN Followers" No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/04/02 ip
- BO0418003D Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hezards," inadvertently omitted from 800306 transmittal KEPPLER. J G Region 3. Chicago, Office of the Director 80/04/02 in
- 8004220093 Forwards IE Info Natice 80-14, "Safety Buggestions From Employees" No action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02 ip
- B004220324 Forwards IE Circular B0-07, "Problems W/HPC1 Turbine Oil Sys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director B0/04/03 ip
- BOO4110025 Forwards IE Bulletin BO-07, "BWR Jet Pump Assembly Failure " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/07 ip
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312.Type 304 Stainless Steel Pipe " Action required KEPPLER. J. G. Region 3. Chicago. Office of the Director 80/04/07 to
- 8004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/09 1p
- 8004280628 Forwards revised Pages 3 % 5 % omitted Page 4 to 1E insp. Repts 80-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 % 50-265/80-08 FiGRELLI, G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/09 ip
- --8004280434 Revised Pages 3 & 5 & omitted Page 4 to IE Insp Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-294/80-05 & 50-265/80-08 * Region 2. Atlanta, Office of the Director, 80/04/09 3pp
- R Periodic operating reports & related correspondence
- 8004140330 Forwards "Radwaste & Environ Monitoring Annual Rept 1979 " STEPHENSON.B B Commonwealth Edison Co 80/03/19 ip
- ----B004140340 "Radwaste & Environ Monitoring Annual Rept 1979 "
 KOHL, K A , CHANDRASEKARAN Eberline Instrument Corp 80/03/31
 91pp
- 80041503B2 Forwards monthly operating repts for Mar 1980. STEPHENSON: B B Commonwealth Edison Co 80/04/10 ip
- --8004150387 Monthly operating repts for Mar 1980 Cleszkiewicz,8 Commonwealth Edison Co 80/04/01 23pp
- S Reportable occurrences, LERs & related correspondence
- 8004140423 Forwards updated LER 80-006/03X-1 STEPHENBON, B B Commanwealth Edison Co BO/03/21 in
- ---8004140429 Updated LER 80-006/03X-01 on 800119 during normal operation. two successive samples of waste sample tank A showed radioactivity in excess of Tech Specs Caused by effluent release Tank A reprocessed BADER, 8 Commonwealth Edison Co 80/03/24 ip
- B004150503 Forwards LER 80-011/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/04/03 ip
- --8004150513 LER 80-011/03L-0 on 800318,while performing isolation condenser condensate line hi flow calibr, DPIS 1349A tripped at 32 2 inches Caused by instrument setpoint drift, Switch read justed to trip at 28 5 inches MAGROW, R Commonwealth Edison Co 80/04/03, 1p.

DOCKET 50-243 DREGON STATE UNIV RESEARCH REACTOR

- Q Inspection reports, IE Bulletins & correspondence

8004110543 Forwards IE Insp Rept 50-243/80-01,on 800128-30 No noncompliance noted BOOK,H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/03/04 2pp

- ---8004110550 IE Insp Rept 50-243/80-01 on 800128-30 No noncompliance noted Major areas inspected radiation protection including control procedures, training, area posting radiation monitoring & personnel dosimetry

 BOOK, H E Region 5, San Francisco, Fuel Facility & Materials
 Safety Branch CURTIS, J R Region 5, San Francisco, Office of the Director 80/03/04 6pp
- B004210187 Forwards IE Insp Rept 50~243/80~02 on 800224~27 No noncompliance noted CREMS.J L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/03/07 Zpp
- ---8004210196 IE Insp Rept 50-243/80-02 on 800226-27 No noncompliance noted Major areas inspected organization, logs & records, review & audit-requalification training, refueling, surveillance & experiments
 STERNBERG, D. M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch CARLSON, J.P.; MORRILL, P.J. Region 5. San Francisco, Office of the Director 80/03/06 5pp

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
F Security, medical, emergency & fire protection plans

- 8004100448 Comments on proposed rule 10CFR50 plant should be kept open while emergency plan is upgraded for Monroe County SMITH.E J New York, State of 80/02/13 ip
- 8004170372 Notification of 800415 meeting w/util in Ontario.NY to 'discuss plant emergency planning review SHEA.J J Operating Reactors Branch 2 80/03/26 2pp
- 8004110195 Forwards add1 revisions to security plan, Chapter 9 (contingency plan) Encl withheld (ref 10CFR2 790) WHITE, L D Rochester Gas & Clectric Corp 80/04/03 ip

Q Adjudicatory correspondence

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 90981CK,L V Office of the Executive Director for Operations 80/04/02 34pp
- I Financial information

8004150502 Annual Financial Rept 1979 * Rochester Gas & Electric Corp 80/03/14 35pp

- P Operating license stage documents & correspondence
- 8004240222 Responds to 800208 itr re shipment of mixed oxide fuel rods Route & law enforcement contact info provided by Tri-State Motor Transit Co meets 10CFR73 requirements Data re contacts & shipment route encl Data withheld (ref 10CFR2 770) MCCORKLE, 0 W Physical Security Licensing Branch 80/02/13 1p
- 8004100316 Advises that responses to 761123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors.per typical fuel bundle & batch burnups ZIEMANN.D.L. Operating Reactors Branch 2 80/02/29 3pp
- 8004100859 Forwards NUREG-0569. "Evaluation of Integrity of SEP Reactor Vessels." completing review of SEP Topic V-6 W/o encl. ZIEMANN.D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020014 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary References or updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 5pp

- 8004220110 Expresses concern re NRC failure to approve util request to use four mixed oxide fuel assemblies as reactor fuel NRC approved receipt of assemblies on 800213 Requests prompt approval due to 800329 annual refueling shutdown DRAKE.F E Rochester Gas & Electric Corp 80/03/06 3pp
- BO04220780 Forwards request for add1 info for continued review of SEP Topic XV-16. "Radiological Consequences of Small Lines Carrying Primary Coolant Dutside Containment "
 ZIEMANN.D L. Operating Reactors Branch 2 80/03/11 Jpp
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D 0 Division of Operating Reactors BO/03/12 5pp
- --8004030ii8 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/2i 28pp
- 8004180094 Forwards evaluation of SEP Topic VIII-4, "Electrical Penetrations of Reactor Containment" ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 17pp
- BOO4010355 Submits deferred response to NRC 791022 ltr re long-term recommendation X 4 3 3-2 for auxiliary feedwater sys Water source capabilities will provide required flow by gravity feed to pump suction
 WHITE, L D Rochester Gas & Electric Corp 80/03/28 4pp
- 8004240003 Supplements 800306 itr re accelerated review schedule of environ qualification of electrical equipment Forwards schedule for & discussion of submittals & data necessary for NRC calculation of containment temp ZIEMANN.D L Operating Reactors Branch 2 80/03/28 14pp
- 8004100461 Forwards responses to 800325 Lessons Learned audit questions
 MILKENS.P C Nochester Oss & Electric Corp 80/04/03 400pp
- 8004210036 Advises that 800213 proposed mods to spent fuel pool cooling sys require Class III fer category Requests prompt payment Any overpayments or addit charges will be determined at final review D1005.R M License Fee Management Branch 80/04/04 1p
- 8004170261 Notification of 800408 meeting w/util in Bethasda.MD to discuss seismic structural analysis for plant WAMBACH.T V Operating Reactors Branch 2 80/04/06 2pp
- 8004150434 Forwards add1 info requested by NRC 800328 ltr re environ qualification of electrical equipment Info provided virtually identical to util 770810 ltr Requests that analysis make use of previously supplied info WHITE, L D Rochester Gas & Clectric Corp 80/04/10 19pp
- 8004150329 Forwards application for amend to License DPR-18, containing Tech Spec change request Certificate of Svc encl MCGRANERY, J. P. LeBoeuf, Lamb, Leiby & MacRae 80/04/11 4pp
- --8004190331 Application for amend to License DPR-18 to changing Tech Specs 6 2-1 & 6 2-2 re organization WHITEL D Rochester Oas & Electric Corp 80/04/11 2pp
- ---8004i50332 Tech Specs changes to Figures & i-1 & 6 2-2 for mgt organization Safety evaluation encl
 * Rochester Gas & Electric Corp 80/04/11 ip
- ---8004150334 Mgt organization chart, Figure 6 2-1 * Rochester Gas & Electric Corp 80/04/ii 1
- --8004;50335 Facility organization chart. Figure 6 2-2
 * Rochester Qas & Electric Corp 80/04/11 1p
- 8004190457 Submits info in response to NRC 770527 draft evaluation of SEP Topic III-2 Bronsite meteorological measurements program Forwards "Upper Air Meteorological Study."

 WHITE, L D Rochester Gas & Electric Corp 80/04/11 3pp
- --8004150462 "Upper Air Meteorological Study "
 * York Research Corp 74/06/07 164pp
- B00423037i Forwards Class III fee for review & approval of spent fuel pool cooling sys W/o encl WHITE.L D Rochester Gas & Electric Corp 80/04/17 ip

- B004230387 Forwards info to NRC consultant for seismic review team for seismic review of electrical equipment, in response to PJ Gallagher B00116 ltr Info includes sketches of battery racks & other diagrams W/o encl WHITE, L D Rochester Gas & Electric Corp 80/04/17 lp
- 8004290378 Forwards "Environ Qualification of Electrical Equipment," Revision 2, in response to NRC 800306 & 28 requests WHITE,L D Rochester Gas & Electric Corp 80/04/25 ip
- --B0042703Bi "Environ Qualification of Electrical Equipment," Revision 2 * Rochester Gas & Electric Corp 80/04/25 75pp
- O Inspection reports. IE Bulletins & correspondence
- 8004210059 Forwards IE Insp Rept 50-244/80-01 on 800115-17 No monicompliance noted 1. Philadelphia, Reactor Operations Nuclear BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/25 2pp Support Branch
- --B004210071 IE Insp Rept 50-244/80-01 on 800115-17 No noncompliance noted Najor areas inspected tours of plant areas & plant plant status compliance w/Tech Specs.licensee action on insp findings & review of licensee action on IE circulars MISTER.H B Region 1. Philadelphia, Reactor Operations Nuclear Support Branch MARKOWSKI.R S , RAYMOND.H J Region 1. Philadelphia, Office of the Director 80/02/21 10pp
- 8004090445 Submits response to IE Bulletin 79-27 re loss of non-Class IE instrumentation & control power sys bus during operation
 Detailed descriptions of IA, ID, IC, & ID instrument buses
 given No mods required
 HHITE, L D Rochester Gas & Electric Corp BO/02/26 13pp
- 8004230003 Forwards response to 1E Builetin 80-03 Insp of charcoal filters completed Minor deficiencies found in two filter sys WHITE,L D. Rochester Gas & Electric Corp 80/03/21 2pp
- 8004300223 Ack receipt of 800304 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 50-244/79-18 SHITH.0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/03/26 ip
- ---8004300227 Responds to NRC 800207 ltr re violations noted in IE Insp Rept 50-244/79-18 Corrective actions isotopic analysis required of mati being shipped Higt stressed importance of timely response to audit findings A
- --8004300232 Forwards IE Imap Rept 50-244/79-18 on 791203-06 & notice of violation SMITH.O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/07 2pp.
- --8004300235 Notice of violation from insp on 791203-06 Portion withheld (ref 10CFN2 770) * Region 1. Philadelphia, Office of the Director 80/02/01 3pp
- --8004300244 IE Insp Rept 50-244/79-18 on 791203-06 Noncompliance noted 004300244 It insp Rept 50-244/79-IB on 791203-06 Noncampliance not failure to respond to audit findings, to camply w/requirement of security plan, Paragraph i3 % to have written procedures for 10CFR71.App E Portion withheld (ref 10CFR2.790) CROCKER, H , YUHAG.G P, MARKONSKI.R S Region 1. Philadelphia, Office of the Director BO/02/01 17pp
- 8004150303 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or presponse necessary GRIER, B. H. Region 1, Philadelphia, Office of the Director
- 8004090106 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required
 ORIER.B H Region 1. Philadelphia. Office of the Director
 80/04/01 ip
- 8004110513 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No written response required ORIER, B. H Region 1, Philadelphia, Offics of the Director 80/04/02 ip
- 8004240347 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees" No action required ORIER, BH Region 1. Philadelphia, Office of the Director BO/04/02 1p

- Sys " No written response required GREER. H Region 1, Philadelphia, Office of the Director 80/04/03 ip 8004180248 Forwards IE Circular 80-07, "Problems W/HPC! Turbine Oil
- B004230435 Forwards IE Bulletin 79~03A, "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required ORIER, B H Region 1. Philadelphia, Office of the Director B0/04/04 | 1p
- 8004180287 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/07 1p
- B004300407 Forwards results of add1 wolds inspected during 1980 outage in accordance w/IE Bulletin 79-19.Revision 1 Beven welds inspected w/one indicating 1/32 inch cut Weld repaired WHITC.L D Rochester Gas & Electric Corp 80/04/25 2pp
- R Periodic operating reports & related correspondence
- 8004150380 Forwards monthly operating rept for Mar 1980 SNOW, B A Rochester Cas & Electric Corp 80/04/09
- --8004150384 Monthly operating rept for Mar 1980 MCNAMARA:A E Rochester Gas & Electric Corp 80/04/10 Spp
- S Reportable occurrences, LERs & related correspondence
- 8004180458 Forwards LER BO-002/03L-0 WHITE.L D Rochestor Gas & Electric Corp BO/04/14 1p
- --8004180471 LER 80-002/03L-0 on 800331, during review of special instructions, discovered that time from previous boron concentration sample exceeded 75 days Caused by inadequate guidance for bimonthly sampling schedule Schedule changed FILKINS.D Rochester Oas & Electric Corp 80/04/14 ip
- 8004230372 RO 80~003.eddy current exams conducted to detect potential tube defects Based on results.pulling initiated to remove tube w/abnormal absolute signal NGON.J C Rochester Oas & Electric Corg 80/04/14 2pp
- U Congressional/Executive Correspondence
- B004070127 Discusses recent util proposal to use four mixed oxide fuel assemblies containing approx 47 kg Pu Requests views on whether approval would adversely affect UB nonproliferation policy AHEARNE.JF Commission 80/03/04 1p
- DOCKET SO-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1 F Becurity, medical, emergency & firs protection plans
- 8004030268 Notifies that NRC review of util Feb 1980 revises 104030666 NOCETTEE ENGL PROTESS OF THE STATE OF THE STATE
- 8004080444 Advises of completed NRC review of 790411,0518 & 1009 submittals re Item 3 2 2, fire hose station evaluation Items acceptable as described Operating Reactors Branch 2 80/03/13, 2pp
- B00402040B Forwards "Feasibility Rept on Evacuation of Area Around Facility "
 COUNSIL, M. G Northeast Utilities 80/03/31 2pp
- ---800402041B "Feasibility Rept on Evacuation of Area Around Facility "
 One oversize drawing encl
 RODGERS.L M , PELL.B M Storch Engineers, MOLLOY.E J Northeast
 Utilities Service Co 80/03/31 58pp
- H General correspondence
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants, Radiation effluent lavels determined by 10CFR20 & App 1 to 10CFR50 Environ info available in stated LPDRB. BALLARD, R L Environmental Projects Branch 1 80/04/01 2pp

- I Financial information
- 8004080557 Responds to NRC 800305 ltr re adequacies of cash flows to meet possible retrospective premium payments & forwards 1979 annual repts for CT Light & Power Co, Hartford Electric Light Co & Western MA Electric Co O'CONNDR.L A Northeast Utilities 80/04/01 ip
- ---8004080564 Annual Financial Rept 1979
 ** Connecticut Light & Power Co 80/03/14 24pp
- ---80040805B1 Annual Financial Rept 1979
 * Hartford Electric Light Co 80/03/14 24pp
- --8004080590 Annual Financial Rept 1979 * Western Massachusetts Electric Co 80/03/14 21pp
- BOO4150320 Forwards Annual Financial Repts 1979 BISHOP,R W Northeast Utilities BO/04/02 i
- --8004150322 Annual Financial Rept 1979 * Connecticut Light & Power Co 80/03/14 50pp
- --8004150325 Annual Financial Rept 1979 * Hartford Electric Light Co 80/03/14 60pp
- --8004150409 Annual Financial Rept 1979 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/14 10pp
- 8004150412 Annual Financial Rept 1979
 * Western Massachusetts Electric Co 80/03/14 60pp
- J Insurance & indemnity information
- 8004140254 Forwards Endorsements 57 & 58 MAELU Policy MF-52 IFFLAND,R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 3pp
- P Operating license stage documents & correspondence
- BOO4100311 Advises that responses to 761123 ltrs re LWR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors.per typical fuel bundlo & batch burnups ZIEMANN,D L. Operating Reactors Branch 2 80/02/29 3pp
- 8004080669 Confirms 800313 corporate mgt meeting in King of Prussia.PA to discuss 791219 water hammer event Proposed agenda encl QRIER.B H Region 1. Philadelphia. Office of the Director 80/03/05. 2pp
- 8004100568 Forwards NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 W/o encl ZIEMANN, D. L. Operating Reactors Branch 2 80/03/05 2pp
- BOO4020015 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is Unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 5pp
- 8004090147 Forwards request for add1 info per continuing review of SEP Topic III-6 Requests response within 30 days of receiving Ltr ZIENANN D L. Operating Reactors Branch 2 80/03/11 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D & Division of Operating Reactors. 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21. 28pp
- B004030293 Responds to NRC 800214 ltrs re request for list of refs for five SEP topics Forwards topics by number, title & listing of refs for ECCS actuation systautomatic ECCS realignment & testing of reactor trip sys CQUNSIL, W Q , FEE, W F Northeast Utilities 80/03/21 3pp

- B004240497 Forwards NRC 80012B & 0211 ltrs to GE re proposed control rod drive sys mods & optimizing pump flow to reactor vessel Mods should not be performed until complete guidance is issued in NUREG-0619 or w/o NRC approval ZIEMANN.D L. Operating Reactors Branch 2 80/03/24 2pp
- 8004020331 Forwards aperture cards for drawings requested in NRC 791128
 1tr requesting info for review of 82P Topic VI-7 C i AC
 power for control valves is depicted in previously submitted
 Drawings 25202-30008 & 25202-30003 M/o encl
 COUNGIL,N G Northeast Nuclear Energy Co (subs of Northeast
 Utilities) 80/03/24 2pp
- 8004030215 Advises that GE Rept NEDD-24583, Revision 1, "Plant Unique Analysis Application Guide," was transmitted to NRC via LJ Soban 791227 ltr to DC Eisenhut Rept provides info re structural evaluation of Mark I containment program COUNBIL.M O Northeast Utilities 80/03/26 ip
- 8004100171 Notification of 800328 meeting w/util in Bethesda.MD repotential cracks in turbine robors
 CARUSD.R Operating Reactors Granch 2 80/03/24 2pp
- 8004040306 Submits info re control rods failing to fully insert after scram & summary of other control rod drive malfunctions for 1978-1979, per NRC 800111 request COUNSIL N G Northeast Utilities 80/03/28 2pp
- B004070265 Submits info re direct insication of PORV & safety valve positions Recent discussions w/vendor revealed difficulty w/B00401 completion date Revised date of completion is 810401 COUNSIL.W O Northeast Utilities B0/03/28 2p
- 8004170303 Forwards request for add1 info re environ qualification of plectrical equipment
 ZIEMANN, D L Operating Reactors Branch 2 80/03/28 14pp
- G004070274 Discusses current intentions to submit design for providing sampling capacity for primary coolant & containment air by G00429 Utils are currently engaged in finalizing design details Glight delay is required to optimize design C0UNGIL. W G Connecticut Yankee Atomic Power Co
- 8004110457 Application to amend QL by incorporating encl proposed Tech Spec change Change would add three new curves extending max average planer linear heat generation rate limits & would delate curve for "MS" type fuel Fee encl COUNSIL. & O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/02 3pp
- --8004110463 Proposed Tech Spec change adding three new curves which extend max everage planar linear heat generation rate limits & deleting max average planar linear heat generation rate vs planar average exposure curve for "MS" type fuel # Northeast Nuclear Energy Co (subs of Northeast Utilities) BD/04/30 Spn.
- 8004240373 Submits add1 info requested for NRC review of proposed Tech Bpec change Existing Tech Spec for continuous leak rate monitoring via nitrogen maker-up cannot be performed w/existing equipment or other instrumentation COUNBIL. W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/16 4pp
- 8004250362 Forwards add1 info to support upgrading of isolation condenser COUNBLLW O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/16 22pp
- 8004290651 Forwards drawings & info requested by NRC 800311 ltr re EEP.Topic III-6 concerning seismic re-evaluation Drawings & info available in Central Files only Info requested by NRC 800331 & 0416 ltrs will be provided later COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/21 400pp
- G Inspection reports, IE Bulletins & correspondence
- BO04090131 Forwards IE Insp Repts 50-213/79-20, 30-245/79-26 & 50-336/79-29 on 791127-30 & 1203-07 No noncompliance noted BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/08 2p
- --8004090138 IE Insp Repts 30-213/79-20,50-245/79-26 & 50-336/79-28 on 791127-30 & 1203-07. No noncompliance noted Major areas inspected QA program implementation re QA/QC administration, design changes & mods & document control program BAUNACK, W H Region 1, Philadelphia, Reactor Operations Nuclear Support Branch NAPUDA, Q Region 1, Philadelphia, Office of the Director 80/02/07 15pp

- 8004070213 Ack receipt of 800206 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/79-25 & 50-336/79-27 CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/28 1p
- --8004070218 Responds to NRC 800111 ltr re violations noted in [E Insp Repts 80-245/79-25 & 50-336/79-27 Corrective actions open trash can replaced w/covered trash can & no smoking signs posted at entryways to main control boards COUNSIL.W G . FEE.W F Northeast Utilities 80/02/06 2pp
- --8004070223 Forwards IE Into Repts 50-245/79-25 & 50-336/79-27 on 791105-09 & notice of violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/11 2pp
- ~-8004070226 Notice of violation from insp on 791105-09 * Region 1. Philadelphia. Office of the Director 80/01/08 ip
- --8004070231 IE Insp Repts 50-245/79-25 & 50-336/79-27 on 771105-09 Noncompliance noted failure to follow housekeeping procedurg KOLTAY.PS Region 1, Philadelphia, Office of the Director EBNETER.S D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch BO/O1/OB Spp
- 8004140129 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Sufficient alternate indications & controls plus manual operation are available w/o most COUNSIL.44 G Northeast Utilities 80/02/29 4pp
- 8004180138 Forwards IE Insp Repts S0-245/79-29 & 50-336/79-30 on 77:1201-31 No noncompliance nated
 BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear
 Support Branch 80/03/03 2pp
- --8004180147 IE Insp Repts 50-245/79-29 & 50-336/79-30 on 791201-31 No noncompliance noted Major areas inspected control rooms & accessible portions of Unit I containment, reactor, turbine, radwate, gas turbine generator & intake bldgs KEIMIG.R R Region I, Philadelphia, Reactor Operations Nuclear Support Branch ZIMMERHAN.R P, SHEDLOSKY, J T Region I, Philadelphia, Office of the Director 80/02/29 10pp
- 8004210343 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted BKITH O H Region 1. Philadelphia. Fuel Facility & Matorials Safety Branch 80/03/05 2PP
- --B004210345 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper requirements.DOT placarding radiation levels removable contamination, BOT marking & labeling & external features POTTER, J.P., PEERY, W. W. WOUDRUFF, R. L. Region 2, Atlanta Facility & Materials Safety Branch 80/01/18 7pp L Region 2, Atlanta, Fuel 60/01/18 7pp
- 8004090404 Advises that IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control 8ys (CVC8) Holdup Tanks," was incorrectly sent for action No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 1p
- 8004270057 Responds to IE Bulletin BO-OG. "Loss of Charcoal from Std Type II.Twg-Inch,Tray Adsorber Cells " Visual insp showed that screen on Type II.cells was tightly affixed & no evidence of deformation or charcoal loss was observed COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/24 2pp
- 8004150279 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090074 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region i, Philadelphia. Office of the Director 80/04/01. 1p.
- 8004110156 Forwards IE Info Notice 80-13. "QE Type 88M Control Switches Defective CAM Followers " No written response required. CRIER, B H Region 1, Philadelphia. Office of the Director 80/04/02 ip

- 8004240319 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees "No action required

 ORIER, B H Region 1, Philadelphia, Office of the Director

 60/04/02 1p
- 8004180231 Forwards IE Circular 80-07, "Problems W/KPCI Turbine 0il Sys' No written response required
 GRIER.B H Region 1, Philadelphia. Office of the Director
 80/04/03 1p
- 8004110054 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/04 | 1p
- 8004230433 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME GA-312, Type 304 Stainless Steel Pipe" Action required GRIER, D H. Region I, Philadelphia, Office of the Director 80/04/04 ip
- 8004180201 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Writton response required GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/04/07 1p
- 6004140375 Requests relief from requirements of ASME Code Section XI.
 requiring examination of Category B-L-2 reactor
 recirculation pump casings during each insp interval Relief
 would postpone examination until major maint on pump
 CDUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast
 Utilities) 60/04/09 2pp
- R Periodic operating reports & related correspondence
- 8004040205 Forwards annual environ operating rept, "Monitoring Marins Environ of Long Island Sound " Requests rept be incorporated into proceedings for Unit 3 COUNSIL.W G Northeast Utilities 80/03/30 ip
- --8004040206 "Monitoring Marine Environ of Long Island Sound," annual Northeast Utilities B0/03/31 400gp
- 8004150327 "Annual Environ Operating Rept,1979 "
 * Northeast Utilities Service Co 80/03/31 100pp
- 8004180383 Forwards menthly operating rept for Mar 1980 OPEKA, J. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/04/14 1p
- --8004180388 Monthly operating rapt for Mar 1980 HARRAN.Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/03 7pp
- 8004210246 Forwards monthly operating rept for Mar 1980 OPEKA, J F Northeast Utilities 80/04/14 ip
- --8004210249 Monthly operating rept for Mar 1980 HARRAN.0 Northeast Utilities 80/04/03
- B Reportable occurrences, LERs & related correspondence
- 8004090118 PND-I-80-043 on 800318, one truck full of chlorine rail tank car derailed at broken switch on licensee property. Car presently located outside protected area, but is upright, intact, & stable Formulating plans to replace car on rail KEIMIG.R R , BRUNNER, E J Region 1, Philadelphia, Office of the Director 80/03/18 2pp
- 8004180437 Forwards updated LER 80-005/03X-GPEKA, J F Northeast Utilities 80/04/1
- ---8004180440 Updated LER 80-005/03X-1 on B00220,core spray subsys declared inoperable Caused by water hammer due to seat leakage of core spray injection & check valves Pipe supports repaired & keep-fill sys modified.Valves to be reworked BIGIARELLI,N J Northeast Utilities 80/04/10 1p.
- 8004290299 Forwards LER 80-006/03L-0 GPEKA, J. F Northwest Utilities 80/04/21. 1p
- ---9004270303 LER 80-006/03L-0 on 800407,during normal operation,pressure indicating switch that senses drywell pressure for automatic pressure relief sys logic initiation.found isolated Caused by personnel error Suitch returned to svc
 BIOIARELLI,M J Northeast Utilities 80/04/21 2pp

- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8004020110 Advises of FES issuance re selection of preferred alternative closed-cycle cooling sys.NUREG-0574.Dec 1979 Future discussions re simplification of proceeding. appropriate LEWIS.8 H Hearing Branch 2 80/03/19
- --8004020126 Summary of meeting w/PAGNY re DES, selection of preferred closed cycle cooling sys & related issues NRC will draft stipulation for parties' comments GECKLER, R P Environmental Projects Branch 1 79/09/14 3pp
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8004180281 Addresses questions in 800214 memo on R Pollard allegations re facility SER Issue of containment isolation valves was previously addressed R Pollard input & final SER are substantially same SER excerpt encl DENTON.H R Office of Nuclear Reactor Regulation 80/04/03 9pp
- --8004180284 Responds to 770110 ltr re possibility of tornado damage & re-evaluation of containment isolation features of auxiliary steam lines Auxiliary steam supply & condensate return lines yatisfy Criterion 57 of general design criteria BCHWENGER.A Operating Reactors Branch 1 78/09/27 7pp
- --8004180294 Submits questions about R Pollard allegation at 800205 commission meeting re SER inaccuracies & plants not meeting current regulations on containment isolation & environ qualification Transcript except encl
 BRADFORD.P A Commission 80/02/14 9pp
- B004220462 Discusses B00926 ltr re request to have UCB identify inaccuracies in plant SER in support of NRC review Requests info re purpose of request & findings of review Buggests procedure to identify SER discrepancies for Units 1 & 2 WEISS, E R Sheldon, Harmon & Weiss 80/04/17 2pp
- Becurity, medical, emergency & fire protection plans
- 8004100100 Comments on proposed rule 10CFR90 10-mile emergency planning some for plume exposure lacks technical justification NRC adopted position w/o studying validity of underlying bases WEIBB.E R Sheldon, Harmon & Weiss 80/02/19 5pp
- ---B004100127 Statument before NY City Louncil, "Impact on NY City of Reactor Accidents at Indian Point," (corrected 790620)
 DEYEA, J Princeton Univ /9/06/20 49pp
- 8004080695 FOIA request on behalf of UCS for time analysis required to evacuate public from 10-mile area surrounding facilities WEISBLE R Sheldon, Harmon & Weiss 80/03/20 1p
- B004080690 Responds to FOIA request for time analysis required to evacuate public from 10-mile area surrounding facilities forwards rept. "Evacuation Times Estimates for Areas Near FELTON, J M. Division of Rules and Records 80/09/31.
- 8004220589 Forwards design details on control & turbine bldg fire walls & fires detectors for reactor coolant pumps Design details for reactor coolant pump oil collection sys will be provided by 800307 CAHILL, W J Consolidated Edison Co of New York 80/04/14 2pp
- O Adjudicatory correspondence
- 8004020091 Forwards UCS 800310 comments on director's decision under 10CFR2.206 Decision & confirmatory order do not resolve critical issues Objects to exclusion of petitioner from meetings & correspondence solving issues HEISS,E R Sheldon, Harmon & Weiss 80/03/10 2pp
- --B004020099 Comments on director's decision under 10CFR2 20A Decision & confirmatory order do not resolve crucial issues re site suitability & do not establish necessity schedule or stds of mods Urges disqualification of JM Hendrie W/documentation WEISB.E R Union of Concerned Scientists WEISB.E R Sheldon, Harmon & Weiss 80/03/10 43pp
- --8004020105 Memorandum to counsel for parties disclosing previous involvement w/facility as member of ACRE & as Deputy Director for Technical Review Hill consider objections to participation if received prior to 771104 W/documentation HENDRIE, J M Commission 77/10/20 11pp

- --8004020109 Responds to 730717 ltr re siting criteria Facility site does not meet NRC regulations & criteria HENDRIE.J M Commission 73/09/10 3pp
- 8004070047 Order granting extension until 800414 for Commission to review director's 800211 decision HDYLE,J C Office of the Secretary of the Commission 80/03/31
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & FEMA re pr improvement in radiological emergency planning & preparedness, distributed as Board notification QDSSICK.L. V Office or the Executive Director for Operations 80/04/02 34pp
- 8004150073 Order granting extension until 800425 for Commission to elect whether to review ALAB-436 & ALAB-561 CHILK.5 J Office of the Secretary of the Commission 80/04/04
- 8004240510 Forwards NRC confirmatory order
 STELLD.V Office of Inspection & Enforcement, Office of the
 Director 80/04/04 1p
- ~-8004240517 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800407 Required info specified in Attachment A STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/04 δρρ
- 8004220754 Forwards petition supporting UCS petition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAVES R 8 Housatonic Safe Energy Alliance 80/04/13
- --8004220762 Supports UCS potition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAVES,R S Housatonic Safe Energy Alliance 80/02/15 1p
- 8004220030 Order granting extension until 800430, for Commission to review Director's 800211 decision HOYLE.J C Office of the Secretary of the Commission 80/04/14
- H General correspondence
- BOO4070200 FOIA request for info re facilities & damage due to earthquakes at Indian Point BEBAS:P Q Affiliation Unknown BO/02/10 1p
- 8004030016 Advises that Commission should evaluate need for power generated by facility & take close look at safety achieved for public pratection OILINSKY, Commission 80/03/11 ip
- --8004030018 Responds to 800225 ltr Forwards NY Times article re lack of need for electricity produced at facility Cites util trade association statement that reserve margin of 2% would exist if all plants in eve grid were shut down LEVINSON.J D Affiliation Unknown 80/03/02 2pp
- ---B004030024 Responds to B00208 ltr supporting petition by UCB requesting decommissioning of Unit 1 & suspending operations of Units 2 & 3 Advises that Commission is reviewing comments on GILINSKY, V Commission 80/02/25 3pp
- --8004030025 Supports UCB 790917 petition requesting decammissioning of Unit i & suspension of operations at Units 2 & 3 Cites safety-related reasons for prompt action Cortificate of Svc LEVINSON, J O Affiliation Unknown 80/02/08 3pp
- 800 4070174 Responds to FOIA request for info re facilities & damage due to earthquakes at Indian Point Forwards Documents 1-4 listed in App A Documents 5 & 6 may be purchased by sending check in amount of \$7 50 to NRC in Washington, D C. FELTON, J M Division of Rules and Records 80/03/17 2pp
- --9004070205 "Bemiannual Operating Rept," Jul-Dec 1973 * Consolidated Edison Co of New York 73/12/31 73/12/31 2000
- --800407020B "Semiannual Operating Rept." Jan-June 1974 * Consolidated Edison Co. of New York 74/06/30 21pp
- ---BOO4070214 "Semiannual Operating Rept," Jul-Dec 1974
 * Consolidated Edison Co of New York 74/12/31 Zipp

- -8004070224 "Annual Operating Rept," 1975 * Consolidated Edison Co. of New York 75/12/31 2200
- --8004070229 "Annual Operating Rept." 1976
 * Consolidated Edison Co. of New York 76/12/31 27pp
- --8004070233 "Annual Operating Rept," 1977 THI semiannual & annual operating rept excerpts enci * Consolidated Edison Co of New York 77/12/31 45pp
- 8004290054 Forwards info requested in 800218 ltr re licensing actions Matl could not be forwarded by 800225 as ltr did not arrive at NRC until 800226 H/o encls DENTON, H R OFFice of Nuclear Reactor Regulation 80/03/25 2pp
- --8004270058 Requests info re changes affecting extension of ULs to FLEISHER, 2 8 Affiliation Unknown 80/02/18 1p
- 8004180234 Forwards NRC 800325 response to encl 800218 ltr from ZE Fleisher of West Branch Conservation Association in response to 800226 request W/o encl DIRCKS, W J Office of the Executive Diroctor for Operations 80/03/28 ip
- --8004180237 Requests info re new safety regulations FLEISHER, Z S West Branch Conservation Association 80/02/18
- 8004210336 Advises that 791106 ltr to President Carter re emergency plans has been referred to NRC Since Summer 1979, NRC has been actively pursuing program to upgrade emergency preparedness Forwards NRC/FEMA documentation W/o encl DENTON.H R DP#ice of Nuclear Reactor Regulation 80/0 BO/03/31 3on
- 8004150085 Responds to 800228 itr re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites

 DENTON.H R Office of Nuclear Reactor Regulation. 80/04/01 2pp
- ---8004150094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER.J W Affil(ation Untrown 80/02/28 lp
- 8004160173 Responds to 800212 ltr re continued operation of nuclear power plant Addi measures should be implemented that will further reduce probability of severe reactor accidents Licensee has been in solutious pending completion of actions DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pg
- --B004160176 Requests that NRC not phase out facility or convert to non-nuclear generators Nuclear power is source for power in US No nute political arguments have no bests in reality LAVERTY. E Affiliation Unknown B0/02/12 2pp
- 8004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DENTON.H R Office of Nuclear Reactor Regulation 80/04/01. 2pp
- 800421003B Responds to 800125 request me public hearing & determination on UCB petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences
 DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 208
- --8004210093 Requests scheduling of public hearing & determination of UCB petition re-operation of facility prior to reactivation Concerned for health & safety of community SCIANDRA. J New York, NY, 80/01/25 19
- 8004210193 Responds to 800207 ltr re-continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants interim measures have already been ordered at sites DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant, lowering rates & dependency on foreign oil.

 MU.J Affiliation Unknown 80/02/07, ip

- 8004210208 Responds to 800204 1tm re continued operation of facility Plants reviewed to determine what add1 measures or design changes can & should be implemented to further reduce obability of reactor accident or consequences NTCN, H R Office of Nuclear Reactor Regulation
- --B004210223 Urges NRC to decide in favor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shut down
 OAY R Affiliation Unknown B0/02/04 ip
- 8004250013 Responds to 800212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure

 DENTON
- --8004250030 Urgas that NRC consider UCS petition re closing of facility Possibility of earthquake exists w/plant built near fault Only 20% of area energy generated by nuclear power Alternatives should be considered Affiliation Unknown 80/02/12 ip
- 8004250018 Responds to 800219 ltr re operation of facility NRC considering special measures to reduce probability of severe reactor accident or to lessen consequences Confirmatory orders issued as interim measure DENTON.H R Office of Nuclear Reactor Regulation, 80/04/01 2pp.
- --8004250033 Urges NRC to approve UCB petition re shutdown of facility because of proximity to New York City & impossibility of evacuation of so many people MDS.L L , MQS.M Affiliation Unknown 80/02/15 ip
- 8004230185 Advises that NRC held two meetings in NY re continuing operation at facility Commission presently considering form of review Public comments invited Request for another hearing in vicinity of plant will be considered DENTON.H R Office of Nuclear Reactor Regulation 80/04/03 80/04/03 1n
- --8004230190 Requests that NRC hold another public hearing re continuing operation of facility to offer public chance to question plant operators & govt agencies Public should be properly notified through local news media CONNOR.R J New York, State of 80/01/08 2pp.
- 8004280140 Responds to 800117 ltr to DDE re 800117 incident at facilities Plant did not trip during minor earthquake tremor Epicenter of tremor was located approx seven miles from sits Tremor was significantly below design capability EISENHUT.D 0 Division of Operating Reactors 80/04/08 ip.
- P Operating license stage documents & correspondence
- B004070094 Forwards agenda & proposed rule for NRC sponsored B00115 meeting in New York, NY re proposed rule on emergency response RYAN,R G Office of State Programs 79/12/31 12pp.
- --8004070098 Requests opportunity to testify at NRC 800115 meeting in New York, NY re emorgency response plans in fifty-mile zone around plant NY City Council has been holding hearings on resolution to phase out plant FRIEDLANDER, M New York, NY 79/12/21 ip.
- 8004180387 Forwards modified near-site study in response to NRC 791205 request for 40-day crash effort PEOPLEG.D L. Commonwealth Edison Co DAVIS, J.F. Power Authority of the State of New York CAHILL, W. J. Consolidated Edison Co of New York 80/02/25 ip
- --B004180373 "Near-Site Study " Viewgraphs encl.

 * Commonwealth Edison Co * Consolidated Edison Co

 * Power Authority of the State of New York. 80/02/ of New York !5 95pp 80/02/25
- 8004020289 Forwards status rept on implementation of Lessons Learned Task Force short-term requirements Basis for judging acceptability of implementation of sach item is requirement of NURGE-0578 4 HR Denton 791030 for to operating plants TELFORD, J T Division of Safeguards 80/02/29 Spp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D 0 Division of Operating Reactors. 80/03/12 5pp
- --800403011B "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp

- 8004140221 Summary of 800221 meeting w/representatives of all SEP plants, utils & Franklin Research Ctr re accelerated program for evaluating qualification of safety-related electrical equipment WILSON, R Plant Systems Branch 80/03/14 3pp
- 8004:10045 FOIA request, on behalf of UCS, for Sandia Labs study re liquid effluent pathway at facility WEI85 E R Sheldon, Harmon & Weiss 80/03/18 1p
- 8004240163 Forwards add1 info & clarification re guide for evaluating environ qualification of Class IE electrical equipment in operating reactors & for identification of appropriate safety equipment of SEP reactors & SCHWENCER. A Operating Reactors Branch 1 80/03/20 15pp
- --B004240175 Forwards add1 info & clarification re guidelines for evaluating environ qualification of Class IE electrical equipment in operating reactors & for identification of appropriate safety equipment of SEP reactors

 SCHWENCER: A Operating Reactors Branch 1 80/03/20 15pp
- B004080410 Forwards answers to generic questions re turbine disc integrity in operating Westinghouse nuclear low pressure turbines in response to NRC B00223 ltr CAHILL N J Consolidated Edison Co of New York 80/03/28 10pp
- 8004100169 Notification of 800403 meeting w/util in Bethesda.MD re environ qualification of electrical equipment CLSHAN.L N Operating Reactors Branch 1 80/03/31 2pp
- 8004080417 Forwards additinfoire overpressure protection systimstalled at facility, in response to NRC 800227 ltr
 CAHILL, W. J. Consolidated Edison Co. of New York 80/04/02 4pp
- BOO411003B Responds to FOIA request for Sandia Labs study re liquid affiluent pathway at facility Rept is undergoing NRC technical review prior to publication Draft entl FELTON.J M Division of Rules and Records 80/04/02 ip
- --8004110051 Draft study of facility liquid effluent pathway
 # Bandia Laboratories 80/04/02 800pp
- 8004220117 Forwards request for info needed to continue NRC review of util 800311 ltr re control room habitability SCHWENCER, A Operating Reactors Branch 1 80/04/04 4pp
- 8004290198 Forwards initial request for add1 info re upgraded program & procedural GA controls resulting from analysis of TMI-2 accident Response requested within 45 days after receipt of 1tr SCHWENGER, A Operating Reactors Branch 1 80/04/08 7pp
- BOO4240480 Forwards addl info rp review of unresolved safety issues, trip rept of Lessons Learned implementation team. & task action plan in view of high population density surrounding plants.

 DENTON, H.R. Office of Nuclear Reactor Regulation 80/04/09 33pp
- --8004240486 Bummary of Westinghouse Lessons Learned team 800124-25 site visit re status of Category A implementation, Attendance & status lists encl
 TELFORD.J T Safeguards Standards Branch 80/02/20 5pp
- --8004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON, H R. Office of Nuclear Reactor Regulation 80/02/21 80pp
- --B004240518 Discusses Event 5 probabilities Guggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements TAYLOR,M A Division of Reactor Safety Research G0/01/15 17pp
- 8004250232 Forwards status of unresolved safety issues at Indian Point 1 & 2, trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON.H R Office of Nuclear Reactor Regulation 80/04/09 34pp
- 8004240458 Formalizes plans re series of technology exchange meetings re facilities' accident mitigation features activity Five meetings suggested, Recommended meeting schedule & agenda items encl SCHMENCER, A Operating Reactors Branch 1 80/04/10 15pp

- 8004150433 Forwards summary of actions taken to comply w/NRC 800211 confirmatory order Detailed confirmatory documentation available at plant for review O'TOOLE, J D Consolidated Edison Co of New York 80/04/11 8pp
- 8004220627 Forwards response to NRC 800305 request for addl info re auxiliary feedwater sys reliability improvements CAHILL.H J Consolidated Edison Co of New York 80/04/14 7pp
- 9004240410 Ack receipt of NRC 900107 ltr re diusel generator fuel oil GA requirements Advises that fuel oil for standby diesel generators included in GA program CAMILL-W J Consolidated Edison Co of New York 80/04/14 ip
- 8004280199 Responds to util 790720 proposed amend to Tech Specs re radiological effluent & environ monitoring sys Forwards comments & marked-up copy of Unit 2 Tech Specs for incorporation into proposed amend SCHWENCER.A Operating Reactors Branch 1 80/04/14 7pp
- --8004280204 Marked-up version of util 790731 App A Tech Specs re radiological effluent & environ monitoring sys * Office of Nuclear Reactor Regulation 80/04/14 125pp
- 8004300307 Forwards drawings & info re mods that provide addl assurance of safety & reliability of automatic transfer circuits & resolve concerns of UCS allagation Drawings available in Central Filos only CAHILL, W J Consolidated Edison Co of New York 80/04/23 Spp
- 8004300429 Advises that all necessary procedural revisions & operator retraining re replacement of certain Fosboro 600 transmitturs will be completed on or before 800701 GAHILL N J Commonwealth Edison Co 80/04/23 2pp
- 8004300416 Forwards application for amend to License DPR-26, modifying Tech Specs to reduce min required RCS flow & revising limit for total nuclear peaking factor Certificate of Svc ancl CAHILL, W J Commonwealth Edison Co 80/04/25 3pp
- --8004300419 Application for amond of License DPR-24, modifying Tech Spers 2 1,3 10 ½ 3 3 to change min required RCB flow & to revise limit for botal nuclear peaking factor CAMILL.W J Commonwealth Edison Co 80/04/25 2pp
- ---8004300423 Tech Specs 2 1,3 10 & 3 3 for safety limits & limiting safety sys settings & control rad & power distribution limits Safety evaluation encl

 * Commonwealth Edison Co 80/04/29 66pp
- 8004300411 Forwards update to util 791016 ltr re degraded grid voltage & adequacy of station electric distribution sys voltages Computer studies, as modified by 800228 discussions w/NRC, encl CAHILL, N J Consolidated Edison Co of New York 80/04/28 19pp

- 8004090045 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written rasponse required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/01 ip
- 8004110126 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/02 tp
- 8004240297 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, D.H. Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180210 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required
 GRIER.B H Region 1. Philadelphia. Office of the Director
 80/04/03 1p
- 8004230403 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required CRIER.B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004180125 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds "Written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/04/07 19
- R Periodic operating reports & related correspondence
- 8004150599 Forwards "Environ Discharge Monitoring Rept for Mar 1980 " MONTLW A Consolidated Edison Co of New York 80/04/10 ip
- --8004150609 "Environ Discharge Monitoring Rept for Mar 1780" * Consolidated Edison Co of New York 80/04/10 15pp
- 8004210255 Forwards monthly operating rept for Mar 1980 CAHILL,W J Consolidated Edison Co of New York 80/04/14 ip
- --8004210258 Monthly operating rept for Mar 1980 EICH.E Consolidated Edison Co of New York 80/04/04 7pp
- 8004210269 Forwards "Baily Counts from Intake Screens, Mar 1980." re fish collections Circulators were shut down for month at Unit 1 CAHILL, W.J. Consolidated Edison Co. of New York 80/04/15 ip
- --8004210276 "Daily Counts from Intake Screens, Mar 1980," re fish
- Consolidated Edison Co of New York 80/04/15 App
- S Reportable occurrences: LERs & related correspondence
- 6004210440 PNO-77-172 on 770976 Units 2 & 3 tripped from 100 & 91% power, respectively Caused by spurious signals in reactor protection sys resulting from electrical disturbances in Buchanan substation State of NY informed KLINGER O , NOLAN.F , SNIEZEK.J Region i, Philadelphia, Office the Director 77/09/27 ip Region i, Philadelphia, Office of
- U. Congressional/Executive Correspondence
- 8004080193 Responds to 791212 ltr re Rockland Mobilization for Survival ltr concerning Dec 1979 public meeting on emergency preparedness Period of public comment lasted until NRC participants had listened to all speakers BIRCKS, N J Office of the Executive Director for Operations, 80/03/05. 2pp
 - 8004080206 Discusses 791218 public meeting on smargency preparedness
 Plans should be arranged to allow ample time for public
 comment Viewpoints of citizens within facility vicinity
 appear to be unimportant to NRC
 STERN,L D Roctland Mobilization for Survival 79/12/05 2pp
- G004300292 Forwards Congressman Rosenthal B00114 ltr ra concerns falling within FR B00222 notice requesting public views on proceeding issues
 DIRGXS.W.J Dffice of the Executive Director for Operations Office of the Executive Director for Operations 80/04/11

- --8004300299 Conveys concerns re safety & health risks posed by plants & lack of adequate evacuation plan Urges NRC to respond to UCS petition ROSENTHAL, B 8 House of Rep , Foreign Affairs 80/01/14 ip
- DOCKET 50-249 DREEDEN NUCLEAR POWER STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimile traffic KEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/20
- 8004030172 Forwards Figure 2-1 to correct omission made in 800311 ltr re evacuation time estimates for facility Figure 3-1 in Section 3 should be placed in Section 2 PEOP-LEG.D L. Commonwealth Edison Co. 80/03/26 2pp
- 8004220299 Informs that Unit 3 refueling outage began 6 wks early \$ will end approx one month earlier than scheduled, due to failure in recirculation sys jet pump Completion of some fire protection mods will not be possible prior to startup PEOPLES,D L. Commonwealth Edison Co. 60/04/10 ip
- 8004230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790)
 PEOPLES, D L Commonwealth Edison Co 80/04/21 1P
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- P Operating license stage documents & correspondence
- 8004080296 Forwards corrected Pages 68 & 93 for Licenses DPR-19 Amend 44 & DPR-29 Amend 39 & corrected Pages 3 6/4 6-2 & 3 6/4 6-9 for licenses DPR-29 Amend 53 & DPR-30 Amend 50. in response to 791002 ltr
 IPPOLITO, T A Operating Reactors Branch 3 80/02/20 2pp
- --8004080310 Corrected Liconse Pages 88 & 93 for Amends 44 & 39 to Licenses DPR-19 & DPR-25, respectively & corrected License Pages 3 6/4 6-2 & 3 6/4 6-9 for Amends 53 & 50 to Licenses DPR-29 & DPR-30, respectively * Operating Reactors Branch 3 80/02/20 8pp
- 8004030027 Submits info requested in 800201 ltr re seepage from plant cooling lake. No dike stability or integrity concerns have been identified No effect on health & safety of public increased surveillance will provide info to evaluate change PEOPLES. D L Commonwealth Edison Co 80/02/29 2pp
- 8004070381 Discusses NRC 761123 request that all LNR licensess assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp.
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENNUT.D O Division of Operating Reactors 80/03/12. Spp.
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors, 80/02/21 28pp.
- BOO4iOOiO2 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER.J 9 Region 3. Chicago. Office of the Director. BO/03/20
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title NAUGHTON: W.F. Commonwealth Edison Co. 80/04/02, 1p.
- --8004180328 Revised pages constituting Revision 13 to GA program. Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1-A R13 80/04/04 7sp.

- 8004290104 Forwards request for info re turbine disc cracking to be supplied on schedule that will allow review prior to startup from current refueling outage Assessment of potential for turbine missile damage should be provided IPPOLITO,T A Operating Reactors Branch 3 60/04/07 4pp
- B004300599 Notification of R00416 meeting w/util in Bethesda.MD to discuss jet pump beam cracking HANNON, J N Operating Reactors Branch 3 80/04/07 ip
- 8004140395 Advises that replacement of spring safety valves w/safety relief valves will not be necessary due to reclassification of pressurtiation transient frequency & add1 measures for prevention of premature valve actuation

 JANENCEK, R F Commonwealth Edison Co 80/04/08 2pp
- 8004180217 Forwards add1 info re failure of control rods to insert fully on scram in response to NRC 800110 & 11 ltrs Dresden 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worn piston seals JANECEK.R F Commonwealth Edison Co 80/04/14 10pp
- 8004180372 Forwards responses to questions raised in NRC 800407 ltr Responses include justification for startup & operation w/ultrasonic indications of water cutting in turbine disk Evaluating applicability of any turbine missile analyses PEOPLES, D. L. Commonwealth Edison Co. 80/04/15 9pp
- 8004250427 Forwards response to NURCO-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lesalle County site-specific emergency plan PEOPLES,D L Commonwealth Edison Co 80/04/15 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bachtel Corp) 79/12/26 32pp
- 8004290353 Outlines add1 surveillance to be implemented per 800416 , meeting re recent jet pump failure Daily comparisons will be made of jet pump flow to respective recirculation pump speed & compared to expected values
 PEOPLES.D L Commonwealth Edison Co 80/04/21 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004070197 Forwards IE Insp Repts 50-010/79-23, 50-297/79-27 & S0-249/79-25 on 791009 & 1128 & notice of violation DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 60/02/12 2pp
- --8004070162 Notice of violation from insp on 791009 & 1128 * Region 3, Chicago, Office of the Director 80701/31 1
- --8004070166 IE Insp Repts 50-010/79-23,50-237/79-27,& 50-249/79-25 on 791009 & 1128 Noncompliance noted radioactive matl shipment record not utilized for radwaste shipments made 790101-1128 OREGER.L R. FIBHER.W.L. Region 3, Chicago, Office of the Director 80/01/31 7pp
- 8004040195 Forwards IE Insp Repts 50-010/80-01,50-237/80-01 & 50-249/80-01 on 800108-09 No noncompliance noted FIGRELLI,G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/02/16 2pp
- --8004040197 IE Insp Repts 50-010/80-01,50-237/80-01 & 50-249/80-01 on 800108-09. No noncompliance noted Major areas inspected.

 emergency diesel generator mods & mod of electrical aquipment to IEEE-279 compliance HAVES,D W Region 3, Chicago, Reactor Construction & Engineering Support Brench HU9HES,J Region 3, Chicago, Office of the Director. 80/02/08 5pp
- 8004100140 Forwards Haste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted. DAVIB.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- ~~B00410040B Waste Packages Insp Rept 79-07A on 791212-13 No noncompliance noted Major area inspected compliance w/DOT & NRC regulations including shipping paper requirements, radiation levels & DOT labeling POTYER, J P. PEERY, W W. HOORNUFF, R L. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/02/22 App
- 8004100426 Forwards IE Insp Repts 50-010/80-03,50-237/80-03 & 30-249/80-03 on 800107-0201 No noncompliance noted HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/26 2pp

- --8004100432 IE Insp Repts 50-010/80-03,50-237/80-03 & 50-249/80-03 on 800107-0201 No noncompliance noted Major areas inspected maint activities, plant operations, physical protection, safety-related sys surveillance insp followup & refueling BARKER, J L , TUNOUE, T M , SPESSARD, R L Region 3, Chicago, Office of the Director 80/02/22 7pp
- B004100119 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KCPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- 8004100117 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-23, 50-237/79-27 & 50-249/79-25 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Br
- --B004100128 Responds to NRC 800212 ltr re violations noted in IE Insp Repts 50-010/79-23.50-237/79-27 & 50-249/79-25 Corrective actions informed personnel re cost estimate change order requirements PEOPLES, D.L. Commonwealth Edison Co. 80/03/04 3pp
- 8004140119 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape
 PEOPLES.D L Commonwealth Edison Co 80/03/20 5pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/03/21 1p
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external features POTTER, J P. PEERY, W W, WOODRUFF, R L. Region G, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004300544 Forwards IE Insp Repts 50-010/80-04,50-237/80-04 & 50-249/80-04 on 800220-22 & 26 & notice of violation DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/21 2pp
- ---8004300548 Notice of violation from insp on 800220-32 & 26 * Region 3. Chicago, Office of the Director 80/03/11 1
- --B004300555 IE Inep Repts 50-010/80-04.50-237/80-04 & 50-249/80-04 on 800220-22 & 26 No noncompliance noted Najor areas inspected internal audits, licensee coordination w/offsite support agencies & review of emergency drills ESSIO, Y H, DESTMANN.H J, MATSON.E Region 3, Chicago, Office of the Director 80/03/11 10pp
- 8004150159 Forwards IE Info Notice BO-12, 'Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/31 ip
- BOD4080686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J Q Region 3. Chicago. Office of the Director BO/04/01
- 8004150014 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J.G Region 3, Chicago, Office of the Director 80/04/02.
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Yoxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J. G Region 3. Chicago, Office of the Director 80/04/02
- 8004220093 forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/02 in

- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004110025 Forwards IE Bulletin 80-07. "BWR Jet Pump Assembly Failure " Written response required KEFFLER.J Q Region 3. Chicago, Office of the Director 80/04/07
- 8004230224 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASHE SA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/04/07
- 8004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/09
- 8004280428 Forwards revised Pages 3 & 5 & cmitted Page 4 to IE Insp Repts 50-010/80-09,50-237/80-05,50-249/80-09,50-254/80-05 & 50-245/80-08 FIORELLI G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/09 Ip
- --8004280634 Revised Pages 3 & 5 & omitted Page 4 to IE Insp Repts 50-010/Rep-05.50-237/80-05.50-249780-05.50-254/80-05 & 50-265/80-08
 - Region 2, Atlanta, Office of the Director 80/04/09 3pp
- R Periodic operating reports & related correspondence
- 8004140330 Forwards "Radwaste & Environ Monitoring Annual Rept 1979 " STEPHENSON, B B Commonwealth Edison Co 80/03/19 ip
- --8004140340 "Radwaste & Environ Monitoring Annual Rept 1979 " KOHL, K. A., CHANDRASEKARAN Eberline Instrument Corp 80/0 Fipp 80/03/31
- 8004150382 Forwards monthly operating rapts for Mar 1980 STEPHENSON, B B Commonwealth Edison Co 80/04/10 f
- --8004150387 Monthly operating repts for Mar 1980 ClE62KlEWICZ.8 Commonwealth Edison Co 80/ 80/04/01 23nn
- S Reportable occurrences. LERs & related correspondence
- 8004030110 PNO-III-80-051 on 800314.ultraspnic testing performed on 20 get pump holddown beam assemblies at Unit 3 Pumps 2, 5, 7, 11 & 20 beam indications ranged from greater than 6 mile to approx 20 mile Pump w/largest indication removed CHRISSDTIMOS, N. BARKER, J. L., BRESSARD, R. L. Region 3, Chicago, Office of the Director 80/03/17 ipp
- 8004020309 Forwards LER 80-009/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/03/25 ip
- -8004020310 LER 80-009/03L-0 on 800306, during refueling outage, while performing LPCI logic tests, injection valve MD 3-1501-22A failed to open Caused by loose wire on terminal block in MCC-38-7 due to stripped brass acrew ZIRHAS,K R Commonwealth Edison Co 80/03/25 ip.
- 8004020363 Forwards LER 80-008/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/03/25 ip
- ---B004020367 LER B0-00B/03L-0 on B00307, during refueling outage while performing temp switch calibr surveillance, three temp switches failed to trip per specs Caused by drift; excessive gap between actuator & switch plunger or dirty contacts.

 * Commonwealth Edison Co 80/03/25 2pp
- BOO4020332 Forwards LER 80-010/03L-0 BTEPHENSON, B B Commonwealth Edison Co 80/03/26 ip
- --8004020337 LER 80-010/031-0 on 800301, during shutdown, while performing EBLC relief valve setting test, relief valves RN 1105A & B actuated above Tech Specs at 1.525 psig & 1.520 psig, respectively, Caused by setpoint drift MAGROW, R. A. Commonwealth Edison Co. 80/03/26 ip.
- 8004080456 Forwards updated LER 79-030/03X-i 8TEPHENBON, B B Commenwealth Edison Co 80/03/26 ip

- ---8004080463 Updated LER 80-030/03K-; on 791110, during scram testing in refuel mode, substantial loss of position indication noted for control rod draveline H--9 Caused by improperly seated socket, suggesting faulty electrical pin-socket alignment # Commonwealth Edison Co 80/03/26 ip
- 8004080552 Forwards LER 80-011/03L-0 BTEPHENSON D B Commonwealth Edison Co 80/03/28 tp
- --8004080561 LER 80-051/03L-0 on 800305, while conducting steam line area temp switch calibr surveillance, temp switch TS 3-261-178 tripped above Tech 8pecs Caused by dirt deposits on switch actuation plunger Switch cleaned, adjusted & tested 8PERROFF, R Commonwealth Edison Co 80/03/28 ip,
- 8004210286 Forwards LER 80-012/03L-0 Commonwealth Eduson Co. 80/04/09 1p STEPHENSON, D. R.
- --8004210288 LER 80-012/03L-0 on 800313 during refueling fuel pool area radiation monitor (ARM) channels A & B & reactor bldg vent ARM channel A tripped above Tech Spec Caused by setpoints drift BADRAN, B Commonwealth Edison Co 80/04/09 ip
- 8004220693 Forwards LER 80-015/01T-0 STEPHENSON B B Commonwealth Edison Co 80/04/10 ip
- --8004220700 LER 80-015/01T-0 on 800402 during refueling reactor water cleanup mechanical snubber found fully retracted Caused by water hammer Remaining cleanup welds in weld penetrant tested Affected pipe section to be replaced before startup SPERROFF, R Commonwealth Edison Co. 80/04/14 SPP
- 8004290422 Forwards LER 80-013/03L-0 BTEPHENSON, B B Commonwealth Edison Co 80/04/22 in
- --8004270429 LER 80-013/03i-0 on 800328 during performance of LLRT on B feedwater outboard check valve 3-220-628 measured leakage recorded in excess of limit Caused by worn seat/disc assembly pins Assembly replaced & valve retested DUNBAR.J F Commonwealth Edison Co 80/04/22 ip.
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8004030271 Notifies that NRC review of util safeguards contingency plan complete Forwards comments indicating need for addl info Comments withheld (ref 10CFR2 790)
 SCHMENCER:A Operating Reactors Branch 1 80/03/10 2pp
- BO04070179 Summary of 800227 meeting w/otil re emergency planning, OROTENHUIS,M Operating Reactors Branch 1 80/03/19 3pp
- ---8004070183 Notification of 800227 & 28 meeting w/FEHA & util in Homestead.FL re emergency planning Proposed agenda & press release enci ROE.J W Emergency Preparadness Tast Force 80/02/07. 400.
- BO04090275 Summary of BO0227 meeting w/util to discuss B00215 draft update of emergency plan for facilities Plan should be updated to comply w/NUREG-04554 by B00531 CROTENHUIB,M Operating Reactors Branch 1 B0/03/19, 3pp
- --8094070277 Forwards proposed agenda & press release for 800227 meeting w/util to review emergency planning RDE.J W Emergency Preparedness Task Force, 80/02/07 4pp
- 8004270077 Forwards fire protection review of util design details,NRC positions re fire protection program & status table re resolution of incomplete items Response within 20 days requested

 SCHWENCER, A Operating Reactors Branch 1, 80/04/03 App
- --8004290081 "Staff Positions on Fire Protection Program." Status of resolution of incomplete items encl * Commission BO/04/03 14pp
- BOO4190519 Informs that response to NRC 800310 ltr re safeguards contingency plan will be sent by 800618. Extension required due to complexity of matter & delays in coordinating response w/outside agency personnel.

 UHRIGAR E Florida Power & Light Co 80/04/11 ip

G Adjudicatory correspondence

- 8004070051 Order granting withdrawal of RA Marshall as counsel for intervenor in amends to OL proceeding re steam generator repair
 - * Atomic Safety and Licensing Board Panel 80/03/06 1p
- E004080239 Mation to amend contentions re proposed amend to DL to permit steam generator repairs Questions safety of storage & other unreviewed safety matters Certificate of Svc & prof qualifications encl HARNAGE, H H. CHONIN, N. Oncavage, Mark HARNAGE, H H. Harnage, H H. B0/03/11 28pp
- BOO4240086 Motion to amend Contention 1 to include Contention 18 Util application for DL amend involves matl alteration of facility Alteration requires CP prior to issuance of amend CP requires preparation of EIS Certificate of Svc encl CNCAVAGE, M A Oncavage, Mark HARNAGE, H H Harnage, H H CHONIN, N Chonin, N 80/03/11 20pp
- 8004170330 Forwards util 800318 ltr re steam generator repair, in response to NRC 791119 ltr to intervenor Cortificate of Svc encl COLL.N A Steel, Hector & Davis 80/03/21 4pp
- 8004240484 Response to intervenor motion to amend contentions Intervenor proposos to amend Contention is solely related to preparation of EIS, rather than add independent contention Contention i rendered moot W/Certificate of Svc REIS, HF Florida Power & Light Co REIS, HF Lowenstein, Newman. Reis, Azelrad & Toll 80/03/26 12pp
- 8004080656 Response in opposition to intervener 800311 motion sesking amend of admitted contentions EIS re steam generator repair amend is being prepared Factors re nontimely fillings are not addressed in motion Certificate of Svc encl GOLDBERO, S C Hearing Branch 2 80/04/01 3pp
- B004110529 Forwards Mar 1980 "Steam Generator Repair Rept." Revision 7 & util B00328 transmittal ltr to DG Eisenhut re proposed amend to OLs to germit steam generator repairs by pipe cut approach Certificate of Svc encl REIB.H F. Lowenstein, Newman, Reis, Axelrad & Toll B0/04/01 3pp
- --8004110533 Forwards Mar 1980 "Steam Generator Repair Rept," Ravision 7 Major changes cover lower assembly removal, dose calculations, steam generator disposal & return to svc testing Affidavit encl UHRIG,R E Florida Power & Light Co 80/03/28 3pp
- --8004110536 "Steam Generator Repair Rept," Revision 7 # Florida Power & Light Co 80/03/31 111pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004080550 Requests temporary suspension of 800301 petition for leave to intervene, pending informal resolution of safety issues re time extensions between steam generator insps Provides list of terms & questions for NRC review GNCAVAGE, M. P. Oncavage, Mark 80/04/02 5pp
- 8004210128 Order dissmissing intervenor M Oncavage 800311 motion to amend contentions as moot.NRC will issue EEB, re proposed steam generator repair, in compliance w/Commission 800304 order & as fulfilment of relief sought by intervenor. BOMERS, E. 8 Atomic Sefety and Licensing Board Panel 80/04/09 4pp.

H General correspondence

- 8004070423 Requests info re public meeting originally scheduled for 800108.Reiterates 790820 request to make statement re radioactive leaks Requests placement on meiling list 80HERA.L Affiliation Unknown. 80/03/17 ip
- I Financial information
- BOC4150404 Forwards Annual Financial Rept 1979
 URRIG.R E Florida Fower & Light Co 80/04/08 ip
- --8004150411 Annual Financial Rept 1979 * Florida Power & Light Co. 80/02/08 72pp

J Insurance & indemnity information

- B004080281 Forwards Endorsement 43 to MAELU Policy MF-55 FIELDER.J Marsh & McLennan.Inc , M & M Nuclear Consultants.Inc Div 80/03/31 3pp
- 8004280449 Forwards Endorsement 52 to NELIA Policy NF-185 FIELDER.) Marsh & McLennan.Inc , M & M Nuclear Consultants,Inc Div 80/04/21 1p
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Spets," study of digital communication sys to transmit info from plants to Bethesda Dperations Ctr EISENHUT,D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- BOO4090166 Forwards Amends 53 \$ 45 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability SCHWENGER, A Operating Reactors Granch 1 80/03/12 2pp
- --8004090169 Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively, increasing min low-low generator water level reactor trip point from 5% to 15% of narrow range instrument scale SCHMENCER.A Operating Reactors Branch 1 80/03/12 App
- --8004090170 Bafety evaluation supporting Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation 80/03/12 2pp
- ---8004090174 Notice of issuance & availability of Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively SCHWENCER, A Operating Reactors Branch 1 80/03/12 2pp
- 8004040179 Forwards Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively safety evaluation & notice of issuance & availability
 BCHWENCER, A Operating Reactors Branch 2 80/03/13 2pp
- ---8004040183 Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively, incorporating results of revised ECCS analysis for steam generator tube plugging level of 22% ECHMENCER, A Operating Reactors Branch 2 80/03/13 9pp
- ---8004040187 Safety evaluation supporting Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively * Office of Nuclear Reactor Regulation 80/03/13 6pp
- ---8004040170 Notice of issuance & availability of Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively SCHWENCER.A Operating Reactors Branch i 80/03/13 2pp
- 8004110093 Bummary of 800304 meetings w/util & Westingbouse in Bethesda.MD re steam generator insp & plugging program GROTENHUIS.M Operating Reactors Branch 1 80/03/13 17pp
- 8004140120 Summary of 800304 meeting w/util % Westinghouse re steam generator insp & plugging program Util presented scheduling considerations & technical basis for operation until 800501 GROTENHUIG.M Operating Reactors Branch 1 80/03/13 20pp
- 8004240251 Forwards Amends 53 & 47 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availabilty SCHMENGER, A Operating Reactors Branch 1 80/03/14 2pp
- --8004240263 Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively, incorporating new limiting conditions for operation & murveillance requirements re low temp reactor vessel overpressure protection sys installed in both units SCHWENGER, A Operating Reactors Branch 1 80/03/14 14pp
- --8004240276 Bafety evaluation supporting Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation 80/03/14 14pp
- --8004240283 Notice of issuance & availability of Amends 55 & 47 to Licenses DPR-31 & DPR-41, respectively 8CHWENCER, A Operating Reactors Branch 1 80/03/14 2pp

- 8004100268 Forwards Amends 36 & 48 to Licenses DPR-31 & DPR-41 respectively safety evaluation & notice of issuance & availability SCHMENCER.A Operating Reactors Branch 1 80/03/21 2pp
- --8004100275 Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively, revising reactor coolant pressure-temp limits to account for neutron irradiation induced increases in reactor vessel mit ductility temp
 SCHWENCER.A Operating Reactors Dranch 1 80/03/21 9pp
- ---8004100281 Safety evaluation supporting Amends 55 & 48 to Licenses DPR-31 & DPR-41 respectively * Office of Nuclear Reactor Regulation 80/03/21 3pp
- ~-8004100284 Notice of issuance & availability of Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively SCHWENCER.A Operating Reactors Branch I 80/03/21 2pp
- 8004010210 Forwards "Steam Generator Repair Rept," Revision 7 re lower assembly removal dose calculations, steam generator disposal & return to svc testing UHRIG.R E Fiorida Power & Light Co 80/03/28 Jpp
- --8004010214 "Steam Generator Repair Rept," Revision 7 * Florida Power & Light Co 80/03/31 150pp
- 8004030289 Responds to NRC 800320 ltr re implementation of short-term Lessons Learned requirements Bupplemental info re direct indication of valve position, subcooling meter, containment isolation & plant shielding review encl UHR10.R E Florida Power & Light Co 80/03/28 11pp
- 8004080452 Provides response to NUREO-0578, short-term requirements re subcooled margin, plant shielding review & technical support ctr data display Detailed info on ability of digital data processing sys to supply subcooling data encl UHRIO, R E Florida Power & Light Co 80/04/04 6pp
- 8004280062 Forwards evaluation of licensee compliance w/Category A of NRC recommendations resulting from TMI-2 Lessons Learned Util has satisfied all Category A requirements Attendee list for NRC 800117-18 site visit encl SCHWENCER, A Operating Reactors Branch 1 80/04/07 15pp
- 8004280177 Approves one-month extension of 1979-80 licensed operator requalification program COLLING.P F Operator Licensing Branch 80/04/08 1p
- 80042B0247 Responds to NRC 800410 itr requesting that info re use of NUKEM 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified caulk requested from Ameron Info will not be available by 800530 Submittal expected 800730 UHRIQ.R E Florida Power & Light Co 80/04/22 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8004090344 Forwards 1E Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/06
- 8004040003 Responds to NRC itr re violations noted in IE Insp Repts 50-250/79-37 & 50-251/79-37 Corrective actions testing will be incorporated into security plan w/security supervisor taking responsibility UHRIG:R E Florida Power & Light Co 80/02/19 ip
- 8004100195 Forwards IE Insp Repts 50-250/80-02 & 50-251/80-02 on 800118-21 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004100202 IE Insp Repts 50-250/80-02 & 50-251/80-02 on 800118-21 No noncompliance noted Major areas inspected.engineered safeguards & energency power sys integrated testing UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch BRODKS, E H Region 2. Atlanta, Office of the Director 80/02/19 Jpp
- 8004230009 Forwards IE Insp Repts 50-250/80-05 & 90-251/80-05 on 800205-07. No noncompliance noted . BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/22 2pp.

- --8004230024 IE Insp Repts 50-250/80-05 & 50-251/80-05 on 800205-07 No 10423024 It Insp Repts 50-250/80-05 & 20-251/80-05 on 800205-07 MC noncompliance noted Major areas inspected pipe support baseplates & safety-related piping sys per IE Bulletins 79-02 & 79-14, respectively WERDT, AR Region 2, Atlanta, Reactor Construction & Engineering Support Branch ANO, W.P. Region 2, Atlanta, Office of the Director 80/02/20 App
- 8004230026 IE Insp Repts 50-250/80-05 & 50-251/80-05 on 800205-07 No nancompliance noted Major areas inspected pipe support baseplates & safety-related piping sys per IE Bulletins 79-02 & 79-14, respectively HEROT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/20 App
- 8004020279 Summary of telcon w/Westinghouse & Fi. Power & Light returbine rotor insp Insp revealed one crack in law pressure rotors Data is in part proprietary & will be transmitted separately Insp still in progress GROTENHUIS.N Operating Reactors Branch 1 80/03/12. 3pp
- 8004280115 Forwards IE Insp Repts 50-250/80-06 & 50-251/80-06 on 800204-07 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/03/12 2pp
- --8004280125 IE Insp Repts 50-250/80-06 & 50-251/80-06 on 800204-07 No noncompliance noted Mayor areas inspected areas of small break loss of coolant procedures & training MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch JUHNSDN.A H., WEDSTER,E H Region 2, Atlanta, Office of the Director 80/03/12 7pp
- 8004040328 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE lnsp Ropts 50-250/79-39 & 50-251/79-39 BTOHR.J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/03/13 ip
- ---8004040347 Responds to NRC 800128 ltr re violations noted in IE Insp Repts 50-250/79-39 & 50-251/79-39 Corrective actions new procedures & revisions implementing subsections will be reviewed & approved prior to issuance for use UHRIG.R E Florida Power & Light Co 80/02/19 2pp
- --8004040351 Forwards IE Insp Repts 50-250/79-39 & 50-251/79-39 on 791219-21 & notice of violation STORK, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 60/01/28 2pp
- --8004040360 Notice of violation from insp on 791219-21 * Region 2. Atlanta, Office of the Director 80/0
- --8004040365 IE Insp Repts 50-280/79-39 & 50-251/79-39 on 791219-21 Noncompliance noted deficiency in approval of procedures re implementation of ETS CUNNINGHAM:A L. Region 2. Atlanta. Office of the Director JENNINS,O R. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/01/25 App
- 8004100187 Bummary of 780304 meeting w/vtil & Westinghouse in Bethesda, MD rs steam generator insp & plugging program GROTENHUIS,M Operating Reactors Branch 1 80/03/13 17pp
- 8004080010 Ack receipt of 800307 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-280/79-40 & 50-281/79-40 STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/03/19 ip
- ---8004080015 Responds to NRC 800201 ltr re violations noted in IE Insp Repts 50-250/79-40 & 50-251/79-40 Corrective actions.marking procedures for steam generator heads have been changed to require monitoring UHRIO.R E Florida Power & Light Co 80/03/07 App
- --8004080023 Advises that response to 800201 ltr requesting corrective actions to violations noted in 1E Insp Repts 50-250/79-40 & 50-251/79-40 will be complete by 800307 UHRIG,R E Florida Power & Light Co. 80/02/27 ip
- --B004080027 Forwards IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 & notice of violation SYOHR,J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/01 2pp
- --8004080030 Notice of violation from insp on 791217-20
 * Region 2, Atlanta, Office of the Director 80/02/01 ip

- --8004080038 IE Inso Repts 50-250/79-40 & 50-251/79-40 on 791217-20 00408003B IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 Noncompliance noted failure to follow procedures re marking defective steam generator tubes & failure to have adequate procedures for marking defective tubes 0.0180N.AF; WRAY, J.R. Region 2, Atlanta, Office of the Director 80/02/01 7pp
- 8004240030 Forwards response to IE Bulletin 80-03, "Luss of Charcoal from 8td Type II. Two-Inch.Tray Adsorber Cells " Adsorber cells used in affected sys do not employ screen rivets Possibility of charcoal loss as described does not exist UHRIG.R E Florida Power & Light Co 80/03/26 2pp
- 8004150517 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response nacessary Region 2, Atlanta, Office of the Director 80/03/31
- 8004080619 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04 Region 2. Atlanta: Office of the Director 80/04/01
- 8004150081 Forwards IE Info Natice 80-13, "GE Type 98M Control Buitches Defective CAM Followers " No specific action or response O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02
- 8004240260 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240371 Ack receipt of 800321 ltr informing NRC of steps taken to correct violation noted in IE Insp Rapts 50-280/80-03 & 50-251/80-03 LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 1p
- --8004240378 Responds to NRC 800225 ltr re violation noted in IE Insp Repts 50-250/80-03 & 50-251/80-03 Corrective actions fire protection QA program will be implemented by 800731 UHRIO,R E Florida Power & Light Co 80/03/21 2pp
- --B004240383 Forwards IE Insp Repts 50-290/80-03 & 50-251/80-03 on B00107-11 & notice of deviation LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/02/25 2pp
- --8004240387 Notice of deviation from inep on 800107-1 * Region 2. Atlanta, Office of the Director 80/4 80/02/20 1p
- --8004240370 IE Insp Repts 50-250/80-03 & 50-251/80-03 on 800107-11. Noncompliance noted failure to implement fire protection GA program. MARTIN,R D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch ELROD,B A. Region 2. Atlanta, Office of the Director 80/02/20. App
- 8004180321 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Gil Sys." No written response required O'REILLY, J.F. Region 2: Atlanta, Office of the Director 80/04/03
- 8004230165 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 80/04/04
- 8004180417 Forwards IE Bulistin 80-09. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/07
- 8004300583 Updates 800304 response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Info re Item 7 a will be forwarded by 800401 Info re Item 7 b will be forwarded by 800701 UHRIQ.R.E Fiorida Fower & Light Co 80/04/08 ip
- R Periodic operating reports & related correspondence
- 8004240368 Forwards monthly operating repts for Mar 1978 SCHMIDT, A D. Florida Power & Light Co 78/04/07 1p

- --8004240374 Monthly operating repts for Mar 1978 CHILSON, V T Florida Power & Light Co 78/0 78/04/06
- 8004240448 Forwards monthly operating rapts for Apr 1978 8CHMIDT, A D Florida Power & Light Co 78/05/06 ip
- --B004240452 Monthly operating repts for Apr 1978 CHILSON, V T Florida Power & Light Co 78/05/06
- 6004240350 Forwards monthly operating repts for May 1978 SCHMIDT, A D Florida Power & Light Co 78/06/03 1p
- --8004240356 Monthly operating repts for May 1978 CHIL80N.V T Florida Power & Light Co 78/06/03 13pa
- 8004240470 Forwards monthly operating repts for June 1978 8CHMIDT,A D Florida Power & Light Co 78/07/01 ip
- --8004240474 Monthly operating repts for June 1978 CHILSON.V T Florida Power & Light Co : 78/07 14рр 18/07/01
- 8004240455 Forwards monthly operating repts for Jul 1978 8CMMIDT, A D Florida Power & Light Co 78/08/10 1p
- --8004240459 Monthly operating repts for Jul 1978, CHILBON, V T Florida Power & Light Co 78/08/10
- 8004240357 Forwards monthly operating repts for Aug 1978 BCHMIDT, A D Florida Power & Light Co 78/09/04 ip
- --8004240363 Monthly operating repts for Aug 1978 CHILBON,V T Florida Power & Light Co 78/09/04 13pa
- 8004240443 Forwards monthly operating repts for Sept 1978 SCHMIDT,A D Florida Power & Light Co 78/10/07 ip
- --8004240444 Monthly operating repts for Sept 1976 CHILBON, V T Florida Power & Light Co 78/10/07 1300
- 8004240443 Forwards monthly operating repts for Dct 1978 SCHMIDT, A D Florida Power & Light Co 78/11/04 1p
- --8004240464 Monthly operating repts for Oct 1978 CHILSON, V T Florida Power & Light Co 78/11/04
- 8004240436 Ferwards monthly operating repts for Nov 1978 BCHMIDT, A D Florida Power & Light Co 78/12/06 ip
- --8004240440 Monthly operating repts for Nov 1978 CHILBON, V T Florida Power & Light Co 78/12/06 1400
- 8004240418 Forwards monthly operating ropts for Dec 8CHMIDT, A D Florida Power & Light Co 79/01/06
- --8004240422 Monthly operating repts for Dec 1978 CHILSON, V T Florida Power & Light Co 79/01/06

1500

1200

1300

79/08/04

- 8004230330 Forwards monthly operating repts for May 1979 SCHMIDT A D Florida Power & Light Co 79/06/09 1p
- --8004230332 Monthly operating repts for May 1979 CHILSON, V T. Florida Power & Light Co 79/06/09
- 8004230494 Forwards monthly operating repts for June 1979 SCHMIDT, A D Florida Power & Light Co 79/07/07 1p
- --B004230490 Monthly operating repts for June 1979 CHILSON, V T Florida Power & Light Co 79/07/07
- BOO4230321 Forwards monthly operating repts for Jul 1979 BCHMIDT A D Florida Power & Light Co 79/08/04 1p
- --8004230326 Monthly operating repts for Jul 1979 CHILBON, V T Florida Power & Light Co 79/0
- 8004180524 Forwards monthly operating repts for Jan 1980 8CHMIDT.A D Florida Power & Light Co 80/02/09 1p
- ---B004180528 Monthly operating repts for Jan 1980 CHILBON.V T Florida Power & Light Co 80/02/09 ggE

- 8004180529 Forwards monthly operating repts for Feb 1980 SCHMIDT, A D Florida Power & Light Co 80/03/08 1p
- ~-8004180530 Monthly operating repts for Feb 1980 CHILBON, V.T. Florida Power & Light Co., 80/03/08 3pp
- 8004040380 Forwards "Semiannual Groundwater Monitoring Program Summary Rept" & "Annual Nonradiological Environ Monitoring Rapt, 1979 " UHRIGAR E Floride Power & Light Co 80/03/31 to
- ---6004090387 "Semiannual Groundwater Monitoring Program Summary Rept."
 for period ending Jul 1979 Twenty-one oversize drawings &
 graphs encl
 # Names & Monne 29/07/31 #4000
 - Bames & Moore 79/07/31 14000
- --B004040397 "Annual Nonradiological Environ Monitoring Rept/1979 "
 * Florida Power & Light Co 79/12/31 600ap
- BOO4180373 Forwards monthly operating repts for Mar 1780 SCHMIDT.A D Florida Power & Light Co 80/04/05 tp
- --8004180374 Monthly operating repts for Mar 1980 CHILGON, V T Fiorida Power & Light Co 80/04/05 9pp.
- 8 Reportable occurrences, LERs & releted correspondence
- 8004030249 Forwards LER 80-004/03L-0 SCHMIDT, A D Florida Power & Light Co 80/03/26 ip
- --9004030256 LER 80-004/03L-0 on B00225, operator detected radiator tube leak on emergency diesel generator A Probably caused by foreign object being forced into radiator by cooling fans Leak repaired w/epoxy patch & new radiator cores ordered BCKOPPMANN, M A Florida Power & Light Co 80/03/26 2pp
- BOO40B0601 Forwards LER 80-005/03L-0 SCHMIDT: A D Florida Power & Light Co 80/03/31 1p
- --8004080408 LER 80-005/03L-0 on 800229, during review of Maint Procedure 15537 2, fire hose station found not fully operable Caused by misunderstanding of what constitutes operability & failure of administrative controls Procedure will be revised SCHOPPMANN.M A Florida Power & Light Co 80/03/31 2pp
- B004240309 Forwards LER 80-006/03L-0 SCHMIDT.A D Florida Power & Light Co 80/04/15 ip.
- --8004240317 LER 80-006/C3L-O on 800316.during review of HP 19537 2.four post indicator valves in fire protection water sys found not inspected within time interval limit Caused by misunderstanding of responsibility SCHOPPMANN.M A Florida Power & Light Co 80/04/15 2pp
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- F. Security, medical, emergency & fire protection plans
- 8004030271 Notifies that NRC review of util safeguards contingency plan complete Forwards comments indicating need for additinfo Comments withheld (ref 10CFRZ 790) SCHWENCER.A Operating Reactors Branch 1 80/03/10 2pp
 - 04070179 Summary of 800227 meeting w/util re emergency planning 380YENHUIS.M Operating Reactors Branch 1 80/09/19. 30s
- -8004070189 Notification of 800227 & 28 meeting w/FEMA & util in flomestead, FL re emergency planning, Proposed agenda & press release encl ROE. J W Emergency Preparedness Task Force 80/02/07 4pp Emergency Preparedness Task Force 80/02/07 4pp
- 8004090275 Bunmary of 800227 meeting w/util to discuss 800215 draft update of emergency plan for facilities Plan should be updated to comply w/NUREG-0654 by 80083: GROTENHUIS.M Operating Reactors Branch i 80/03/19 3pp
- ~~8004090277 Forwards proposed agenda & press release for 800227 meeting w/util to review emergency planning.

 RDE: J W Emergency Preparedness Task Force 80/02/07 App
- 8004270077 Forwards fire protection review of util design details, NRC positions re-fire protection program & status table re-resolution of incomplate items Response within 20 days requested SCHHENCER: A Operating Reactors Branch 1. 80/04/03 6pp

- ---8004290081 "Staff Positions on Fire Protection Program " Status of resolution of incomplete items and the Commission 80/04/03 14pp
- B004;50319 Informs that response to NRC B00310 ltr re safeguards contingency plan will be sent by B00618 Extension required due to complexity of matter & delays in coordinating response w/outside agency personnel UHRIG.R E Florida Power & Light Co B0/04/11 ip
- O Adjudicatory correspondence
- 8004070031 Order granting withdrawal of RA Harshall as counsel for intervenor in amends to OL proceeding re-steam generator Atomic Safetu and Licensing Board Panel 90/03/06 ip
- 8004080239 Motion to amend contentions re proposed amend to OL to permit steam generator repairs Questions safety of storage & other unreviewed safety matters Certificate of Evc & prof qualifications encl HARNAGE. H H. CHONIN, N Concevage, Mark HARNAGE, H H Harnage, H H 80/03/11 28pp
- 8004240086 Motion to amend Contention 1 to include Contention 18 Util application for QL amend involves mat! alteration of facility Alteration requires CP prior to issuance of amend CP requires preparation of EIS Cortificate of Svc encl ONCAVACE.M A Oncavage.Mark HARNAGE.H H Harnage.H H CHONIN.N Chomin.N 60/03/11 28pp
- 8004170330 Forwards util 800318 ltr re steam generator repair in response to NRC 791119 ltr to intervenor Certificate of Byc encl CDLL, N A Steel, Hector & Davis 80/03/21 4pp
- 8004240404 Response to intervenor motion to amend contentions intervenor proposes to amend Contention 1, solely related to preparation of EIS, rather than add independent contention Contention 1 rendered most W/Gertificate of Syc REIS, H F Florida Power & Light Co REIS, H F Lowenstein, Newman, Reis, Azelrad & Toll 80/03/26 12pp
- B004080656 Response in opposition to intervenor B00311 motion seeking amend of admitted contentions EIB re steam generator repair amend, is being prepared Factors re nontimely filings are not addressed in motion Certificate of Buc encl COLDBERG, B C Hearing Branch 2 80/04/01 3pp
- B004i10529 Forwards Mar 1980 "Steam Generator Repair Rept." Revision 7 & util 800328 transmittal ltr to D0 Eisenhut re proposed amend to OLs to permit steam generator repairs by pipe cut approach Certificate of Suc encl
- --8004110533 Forwards Har 1980 "Steam Generator Repair Rept," Revision 7 Major changes cover lower assembly removal, dose calculations, steam generator disposal & return to svc testing Affidavit encl UHRIO,R E Florida Po Florida Power & Light Co 80/09/28 3pp.
- --8004110536 "Steam Generator Repair Rept." Revision 7 # Floride Power & Light Co 80/03/31, 111pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSBICKI. V Office of the Executive Director for Operations, 80/04/02 34pp
- 80040B0350 Requests temporary suspension of 800301 petition for leave to intervens, pensing informal resolution of safety issues retime extensions between steam generator insps. Provides list of terms & questions for NRC review.

 ONGAVAGE, M. P. Oncavago, Mark 80/04/02 5pp
- 8004210128 Order dissmissing intervenor M Oncavage 800311 motion to amend contentions, as most NRC will issue EIB, re proposed steam generator repair, in compliance w/Commission 800304 order & as fulfilment of relief sought by intervenor BDMERB, E 8 Atomic Bafety and Licensing Board Panel. 80/04/09
- H. Osneral correspondence
- 8004070423 Requests info re public meeting originally scheduled for BOOLOB Resterates 770820 request to make statement re radioactive leaks Requests placement on mailing list BCHERALL Affiliation Unknown BO/03/17 ip.

I Financial information

- 8004150406 Forwards Annual Financial Rept 1979
 UHRIG.R E Florida Power & Light Co 80/04/08 ip
- --8004i504ii Annual Financial Rept 1979 * Florida Power & Light Co 80/02/08 72pp
- J Insurance & indemnity information
- 8004080281 Forwards Endorsement 43 to MAELU Policy MF-55 FIELDER, J. Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/03/31 3pp
- 8004280449 Forwards Endorsement 52 to NELIA Policy NF-185 FIELDER J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/04/21 1p
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 3pp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004090166 Forwards Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability SCHWENCER, A Operating Reactors Branch 1 80/03/12 2pp
- --3004070169 Amends 53 & 45 to Licenses DPR-31 & DPR-41.respectively, increasing min low-low generator water level reactor trip point from 5% to 15% of narrow range instrument scale 'SCHWENCER.A Operating Reactors Dranch 1 80/03/12 opp
- ---8004090170 Safety evaluation supporting Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation 80/03/12 2pp
- --9004090174 Notice of issuance & availability of Amends 53 & 45 to Licenses DPR-31 & DPR-41, respectively GCHWENCER, A Operating Reactors Branch 1 80/03/12 2pp
- 8004040179 Forwards Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively, safety evaluation & notice of issuance & availability SCHWENCER, A Operating Reactors Branch 2 80/03/13 2pp
- ---8004040183 Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively. incorporating results of revised ECCS analysis for steam generator tube plugging level of 22% BCHWENGER.A Depending Reactors Branch 2 80/03/13 9pp
- --8004040187 Safety evaluation supporting Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively * Office of Nuclear Reactor Regulation 80/03/13 App
- --8004040190 Notice of issuance & availability of Amends 54 & 46 to Licenses DPR-31 & DPR-41 respectively BCHWENCER:A Operating Reactors Branch 1 80/03/13 2pp
- BOO4110093 Summary of 800304 meetings w/util & Westinghouse in Bethesda.MD re steam generator insp & plugging program ORDTENHUIS.M Operating Reactors Branch 1 80/03/13. 17pp
- BOO4240251 Forwards Amends 55 & 47 to Licenses DPR-31 & DPR-41. respectively safety evaluation & notice of issuance & availability SCHWENGER.A Operating Reactors Branch 1 80/03/14 2pp
- --8004240263 Amends 55 & 47 to Licenses DPR-91 & DPR-41, respectively, incorporating new limiting conditions for operation & surveillance requirements re low temp reactor vessel overpressure protection sys installed in both units SCHWENGER.A Operating Reactors Branch 1 80/03/14 14pp
- --8004240276 Bafsty evaluation supporting Amends 55 % 47 to Licenses DPR-31 % DPR-41: respectively * Office of Nuclear Reactor Regulation 80/03/14, 14pp

- --8004240283 Notice of issuance & availabilty of Amends 55 & 47 to Licenses DPR-01 & DPR-41.respectively SCHWENCER.A Operating Reactors Branch 1 80/03/14 2pp
- 8004100268 Forwards Amenda 56 & 48 to Licenses DPR-31 & DPR-41 respectively, safety evaluation & notice of issuance & availability SCHWENCER. A Operating Reactors Branch 1 80/03/21 2pp
- --8004100275 Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively, revising reactor coolant pressure-temp limits to account for neutron irradiation induced increases in reactor vessel nil ductility temp
 SCHWENCER.A Operating Reactors Branch 1 80/03/21 9pp
- ---8004100281 Safety evaluation supporting Amends 56 & 48 to Licenses
 DPR-31 & DPR-41 respectively
 * Office of Nuclear Reactor Regulation 80/03/21 3pp
- --8004100284 Notice of issuance & availability of Amends 56 & 48 to Licenses DPR-31 & DPR-41 respectively SCHWENCER.A Deprating Reactors Branch 1 60/03/21 2pp
- B004100498 Forwards Amend 49 to License DPR-41, safety evaluation & notice of issuance & availability
 SCHWENCER, A Operating Reactors Branch 1 80/03/21 3pp
- --8004100467 Amend 49 to License DPR-41, revising Tech Specs to permit continued operation for one month more than authorized by Amend 44

 SCHMENCER, A Operating Reactors Branch 1 80/03/21 Spp
- --8004100473 Safety evaluation supporting Amend 49 to License DPR-41 * Office of Nuclear Reactor Regulation 80/03/21 3pp
- ---BOD4100475 Notice of issuance & availability of Amend 49 to License DPR-41 SCHWENCER.A Operating Reactors Branch 1 80/03/21 2pp
- 8004010210 Forwards "Steam Generator Repair Rept," Revision 7 re lower assembly removal dose calculations, steam generator disposal & return to svc testing
 UNRIG:R E Florida Power & Light Co 80/03/28 3pp
- --8004010214 "Steam Generator Repair Rept." Revision 7 * Florida Power & Light Co 80/03/31 150pp
- B004030287 Responds to NRC B00320 ltr re implementation of short-term Lessons Learned requirements Supplemental info re direct indication of valve position, subcooling meter, containment isolation & plant shielding review encl

 UHRIO.R E Florida Power & Light Co 80/03/28 11pp
- 8004080492 Provides response to NUREG-0578, short-term requirements re subcooled margin plant shielding review & technical support ctr data display Detailed info on ability of digital data processing sys to supply subcooling data encl UHRIO.R E Florida Power & Light Co 80/04/04 App
- BO04280042 Forwards evaluation of licensee compliance w/Category A of NRC recommendations resulting from TMI-2 Lessons Learned Util has satisfied all Category A requirements Attendee list for NRC B00117-18 site visit encl
- 8004280177 Approves one-month extension of 1979-80 licensed operator requalification program

 COLLINS,P F Operator Licensing Branch 80/04/08 ip
- 8004280247 Responds to NRC 800410 ltr requesting that info re use of NUKEM 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified caulk requested from Ameron Info will not be available by 800530 Gubmittal expected 800730 UHRIG.R E Florida Power & Light Co 80/04/22 ip
- G Inspection reports, IE Bulletins & correspondence
- 9004070344 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Calls " Action required D'REILLY, J P Region 2, Atlanta, Office of the Director 90/02/06 2pp
- 8004040003 Responds to NRC ltr re violations noted in IE Insp Repts 50-250/79-37 & 50-251/79-37 Corrective actions testing will be incorporated into security plan w/security supervisor taking responsibility UHRIO:R E Florida Power & Light Co 80/02/19 1p

- B004100195 Forwards IE Insp Repts 50-250/B0-02 & 50-251/B0-02 on B0011B-21 No honcompliance noted LEWIS/R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/02/20 2pp
- --8004100202 IE insp Repts S0-250/80-02 & 50-251/80-02 on 800118-21 No noncompliance noted Major areas inspected engineered safeguards & emergency power sys integrated testing UPRIGHT, C M. Region 2. Atlanta, Reactor Operations Nuclear Support Branch BROOKS, E H. Region 2. Atlanta, Office of the Director 80/02/15 3pp
- 8004230009 Forwards IE Insp Repts 50-250/80-05 & 50-251/80-05 on 800205-07 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/22 2pp
- --8004230026 IE Insp Repts 30~250/80~05 & 50~251/80~05 on B00205~07 No noncompliance noted Major areas inspected pipe support baseplates & safety-related piping sys per IE Bulletins 79~02 & 79~14, respectively HERDT. A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ANO.W P Region 2. Atlanta, Office of the Director B0/02/20 4pp
- 8004280115 Forwards IE Insp Repts 50-250/80-06 % 50-251/80-06 on 800204-07 No noncompliance noted LEHIS:R C Region 2: Atlanta, Reactor Operations Nuclear Support Branch 80/03/12 2pp
- --8004280125 IE Insp Repts SD-250/80-06 & 50-251/80-06 on 800204-07 No noncompliance noted Major areas inspected areas of small break loss of coulant procedures & training MARTIM.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch JOHNSON.A H, WEBSTER.E H Region 2. Atlanta, Office of the Birector 80/03/12 7ps
- 8004040328 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-39 & 50-251/79-39 STOHR.J P Region 2. Ablanta, Fuel Facility & Materials Safety Branch 80/03/13 is
- Branch 80/03/13 1p
- --8004040347 Responds to NRC 800128 ltr re violations noted in IE Insp Repts 50-250/79-39 & 90-281/79-39 Corrective actions new procedures & revisions implementing subsections will be reviewed & approved prior to issuance for use UHRIG.R E Florida Power & Light Co 80/02/19 2pp
- --8004040351 Forwards IE Intp Repts 50-250/79-39 & 50-251/79-39 on 791219-21 & notice of violation STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/28 2pp
- --800404036D Notice of violation from insp on 771217-21 * Region 2. Atlanta, Office of the Director 80/01/25 ip
- --8004040365 IE Insp Repts 50-250/79-39 & 50-251/79-39 on 791219-21
 Noncompliance noted deficiency in approval of procedurat re
 implementation of ETS
 GUNNINGHAM.A L. Region 2, Atlanta, Office of the Director
 JENKINS,O R. Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch 80/01/25 4pp
- 8004100187 Summary of 760304 meeting w/util & Westinghouse in Bathesda, MD re steam generator insp & plugging program GROTENHUIS,M Operating Reactors Branch 1 80/03/13 17pp
- B004080010 Act receipt of 800307 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-40 & 50-251/79-40
 BTOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/19 19
- -8004080015 Responds to NRC 600201 itr re violations noted in IE Insp.
 Repts 50-250/79-40 & 50-251/79-40 Corrective actions marking
 procedures for steam generator heads have been changed to
 require monitoring
 UHRIG.R E Florida Power & Light Co 80/03/07 4pp
- --8004080023 Advises that response to 800201 ltr requesting corrective actions to violations noted in IE Imap Repts 50-250/79-40 & 50-251/79-40 will be complete by 800307 UHRIG-R E Florida Power & Light Co 80/02/27 ip
- ~-8004080027 Forwards IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 & notice of violation STOHR.J.P Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/02/01 2pp

- --8004080030 Notice of violation from insp on 791217-20
 * Region 2. Atlanta, Office of the Director 80/02/01 ip
- --8004080038 IE Insp Repts 50-250/79-40 & 50-251/79-40 on 791217-20 Noncompliance noted failure to follow procedures re marking defective steam generator tubes & failure to have adequate procedures for marking defective tubes OIBSON.A F. WRAY.J R. Region 2. Atlanta. Office of the Director 80/02/01 7pp
- 8004240030 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch. Tray Adsorber Cells "Adsorber cells used in affected sys do not employ screen rivets Possibility of charcoal luss as described does not exist UHRIG.R E Florida Power & Light Co 80/03/26 2pp
- 8004190517 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/3: 2nn
- 8004080619 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required D'REILLY. J.P. Region 2, Atlanta, Office of the Director 80/04/01 201
- 8004150081 Forwards IE Info Notice 80-13. "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required D'REILLY. J P Region 2. Atlanta. Office of the Director 80/04/02
- 8004240260 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 200
- 8004240371 Ack receipt of 800321 ltr informing NRC of steps taken to correct violation noted in IE lasp Repts 50-250/80-03 & 50-251/80-03 LEMBS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 lp
- --8004240378 Responds to NRC 800225 ltr re violation noted in IE Insp Rapts 50-250/80-03 & 50-251/80-03 Corrective actions fire protection GA program will be implemented by 800731 UHRIO,R E Florida Power & Light Co 80/03/21 2pp
- --8004240383 Forwards IE Insp Repts 50-250/80-03 & 50-251/80-03 on 800107-11 & natice of deviation LEMIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/23 2pp
- --8004240387 Notice of deviation from insp on 800107-11 * Region 2. Atlanta, Office of the Director. 80/02/20 ip
- --8004240390 IE Insp Repts 50-280/80-03 & 50-251/80-03 on 800107-11 Noncompliance noted failure to implement fire protection GA program MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch ELROD.8 A Region 2, Atlanta, Office of the Director 80/02/20 dpp
- 8004180321 Forwards IE Circular 80-07, "Problems H/HPCI Turbine Dil Sys " No written response required O'REILLY, J & Region 2, Atlanta, Office of the Birector. 80/04/03, 2an.
- 8004230145 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 8A-312,Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180417 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 200.
- 8004300583 Updates 800304 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Info re Item 7. a will be forwarded by 800601, Info re Item 7. b will be forwarded by 800701
 UHRIQ.R.E. Florida Power & Light Co 80/04/08 ip

- R Pariodic operating reports & related correspondence
- 8004240366 Falwards monthly operating lepts for Mar 1978 SCHMIDT, A.D. Florida Power & Light Co. 78/04/07 ip
- --8004240374 Monthly operating repts for Mar 1978 CHILBON, V T Florida Power & Light Co 78/04/06
- 8004240448 Forwards monthly operating repts for Apr 1978 SCHMIDT, A D Florida Power & Light Co 78/05/06 ip
- --B004240452 Monthly operating repts for Apr 1978 CHILSON, V T Fiorida Power & Light Co 78/05/04
- 8004240350 Forwards monthly operating repts for May 1978 SCHMIDT, A D Florida Power & Light Co 78/06/03 tp
- --8004240354 Monthly operating repts for May 1978 CHILSON, V T Florida Power & Light Co 78/04/03 13pp
- 8004240470 Forwards monthly operating repts for June 1978 8CHMIDT, A D Florida Power & Light Co 78/07/01 ip
- --BO04240474 Monthly operating repts for June 1978 CHILSON, V T Florida Power & Light Co 78/07/01
- 8004240455 Forwards monthly operating repts for Jul 1978 SCHMIDT, A D Florida Power & Light Co 78/08/10 ip
- --8004240459 Monthly operating repts for Jul 1978 CHILBON,V T Florida Power & Light Co 78/08/10
- 8004240359 Forwards monthly operating repts for Aug 1978 8CHMIDT A D Florida Power & Light Co 78/09/04 ip
- --8004240363 Monthly operating repts for Aug 1978 CHILSON,V T Florida Power & Light Co 78/09/04 1300
- BOO4240443 Forwards monthly operating ropts for Sept 1978 BCHMIDT, A D Florida Power & Light Cd 78/10/97 1p
- --8004240444 Monthly operating repts for Sept 1978
 CHILBON, V T Florida Power & Light Co 78/10/07
- 8004240466 Monthly operating rapts for Oct 1978 CHILBON, V T Florida Power & Light Co 78/11/04
- BOO4240436 Forwards monthly operating repts for Nov 1978 BCHMIDT, A.D. Florida Power & Light Co. 78/12/06 ip
- --8004240440 Monthly operating repts for Nov 1978 CHILBON, V T Florida Power & Light Co 78/1 78/12/06
- BOO4240418 Forwards monthly operating rapts for Dec 1970 SCHMIDT, A D Florida Power & Light Co 79/01/06 ip
- --8004240422 Monthly operating lepts for Dec 1978 CHILSON, V T Florida Power & Light Co 79/01/06
- BOO4230330 Forwards monthly operating repts for May 1979 SCHMIDT.A D Florida Power & Light Co 79/06/09 1p
- --8004230332 Monthly operating repts for May 1979 CHILBON, V T Florida Power & Light Co 79/06/09
- 8004230484 Ferwards monthly operating repts for June 1979 SCHMIDT, A D Florida Power & Light Co 79/07/07 ip
- --8004230490 Monthly operating repts for June 1979 CHILBON,V T Florida Power & Light Co 79/07/07 lipp
- 8004290321 Forwards monthly operating repts for Jul 1979. 8CHMIDT, A D Florida Power & Light Co 79/08/04 1p.
- --8004230326 Monthly operating repts for Jul 1979 CHILSON, V T Florida Power & Light Co 79/08/04
- 8004240463 Forwards monthly operating rapts for Oct 1978 SCHMIDT, A D Florida Power & Light Co 78/11/04 1p

- 8004180524 Forwards monthly operating repts for Jan 1980 SCHMIDTAN D Florida Power & Light Co 80/02/09 ip
- --8004180528 Monthly operating repts for Jan 1980 CHILSON, V T Florida Power & Light Co 80/02/09 3pp
- 8004180529 Forwards monthly operating tepts for Feb 1980 SCHMIDT, A.D. Florida Power & Light Co. 80/03/08 ip
- ---8004180830 Monthly operating repts for Feb 1980 CHILSON,V 7 Florida Power & Light Co 80/03/08
- B0040403B0 Forwards "Semiannual Groundwater Monitoring Program Summary Rept" & "Annual Nonradiological Environ Monitoring Rept, 1979 "
 - UHRIG.R E Florida Power & Light Co 80/03/31 1p
- ---8004040387 "Semiannual Groundwater Monitoring Program Summary Rept," for period ending Jul 1979 Twenty-one oversite drawings & graphs encl # Dames & Moore 79/07/31 140pg
 - Dames & Moore 79/07/31 140pp
- --8004040397 "Annual Nonradiological Environ Monitoring Rept.1979 "
 * Florida Power & Light Co 79/12/31 600pp
- BOO4180373 Forwards monthly operating repts for Mar 1980 SCHMIDT, A D Florida Power & Light Co 80/04/05 ip
- --80041803/4 Monthly operating repts for Mar 1980 CHILSON, V T Florida Power & Light Co 80/04/05
- S Reportable occurrences, LERs & related correspondence
- 8004020377 Forwards LER 80-003/03L-0 8CHMIDT, A.D. Florida Power & Light Co. 80/03/17 ip
- --8004020391 LER 80-003/03L-0 on 800215, while testing 40 steam generator feedwater control valve rapid change in steam generator level resulted in lifting RV-1410 which did not fully reseat Caused by binding between gear & nut Valve tested BCROPPMAN.M A Florida Power & Light CO 80/03/17 ip

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

- F Socurity, modical, emorgency & fire protection plans
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone network Bys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimilie traffic KEPPLER, J Q Region 3. Chicago. Office of the Director 80/03/20
- 80040702/2 Forwards input to facility fire protection review for fire detection sys, water suppression sys & foam suppression sys Info completes items for which adequate licenses input
 - HALL, R E Brookhaven National Laboratory 80/03/31 5pp
- BOD4070273 Forwards Pages C-26 & C-27 of Revision 5 to security plans, amitted from BOO324 submittal Encl withheld (ref 10CFR2 770)
 PEOPLES, D L. Commonwealth Edison Co BO/04/02 1p
- BOO4230524 Forwards revisions to 800331 ltr re fire protection revisus Item 3 1 lefire detection sys. Item 3 1 5, water suppression sys. & Item 3 1 6 foam suppression sys HALLE Brookhaven National Laboratory 80/04/16 Spp
- B004230367 Forwards revised security plan Revisions withheld (ref 100FR 790) PEOPLES,D L. Commonwealth Edison Co. 80/04/21 IP
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification.

 ODSBICK,L V Office of the Executive Director for Operations 80/04/02 34pp

P Operating License stage documents & correspondence

- 8004080296 Forwards corrected Pages 88 & 93 for Licenses DPR-19 Amend 44 & DPR-25 Amend 39 & corrected Pages 3 6/4 6-2 & 3 6/4 6-9 for licenses DPR-29 Amend 53 & DPR-30 Amend 50, in response to 791002 ltr
 1PPOLITO.T A Deprating Reactors Branch 3 80/02/20 2pp
- ---B0040B0310 Corrected License Pages 88 & 93 for Amends 44 & 39 to Licenses DPR-19 & DPR-25, respectively & corrected License Pages 3 6/4 6-2 & 3 6/4 6-9 for Amends 53 & 50 to Licenses DPR-29 & DPR-30, respectively + Operating Reactors Branch 3 B0/02/20 8pp
- 8004070381 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MW-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bothesda Operations Ctr EisENHUT, D O Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- 8004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/20
- 8004190316 Forwards revised pages constituting Revision 13 to CE-1-A, GA program Revisions reflect recent organization title changes
 NAVOHTON, W F Commonwealth Edison Co 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-I-A R13 80/04/04 7pp
- 8004180217 Forwards add1 info re failure of control rods to insert fully on scram in response to NRC 800160 & 11 ltrs Bresden 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worm piston seals JANECEK, R F Commonwealth Edison Co 80/04/14 10pp
- 8004250427 Forwards response to NUREO-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Factlities" for review Util emergency plan will be submitted w/Lasalle County site-specific emergency plan PEOPLES,D L Commonwealth Edison Co 80/04/15 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " # Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- G Inspection reports. IE Bulletins & correspondence
- 8004040029 Forwards IE Insp Repts 50-254/79-30 & 50-265/79-28 on 791211-14. No noncompliance noted DAVIB, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/12 2pp
- ---B004040034 IE Insp Repts 50-254/79-30 & 50-265/79-28 on 791211-14 No noncompliance noted Major areas inspected licensess data, repts & experience in meeting design objective gaseous release rate for radioiotine & radiactive matl. HUETER, J. Region 3, Chicago, Office of the Director FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/06 Spp.
- 8004100140 Forwards Haste Packaging Insp Rept 79-07A on 791212-13.No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/02/22 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No nuncompliance noted Major areas inspected compliance w/BDT & NRC regulations including shipping paper requirements, radiation levels & BDT labeling POTER, J P. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/02/22 App

- 8004100516 Forwards Waste Packaging Insp Rept 79-07A on 791219 & notice of violation DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004100522 Notice of violation from insp on 791217

 * Region 3, Chicago, Office of the Director B0/02/22 ip
- --B004100528 Waste Packaging Insp Rept 79-07A on 791219 Noncompliance noted failure to mark package as radioactive low specific activity POTTER.JP, BROWN,R A Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/02/22 3pp
- 6004100192 Forwards IE Insp Repts 50-254/80-03 & 50-265/80-05 on BOO115-16 & O211 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch BO/02/28 2pp
- --8004100207 IE Insp Repts 50-254/80-03 & 50-265/80-05 on 800115-16 & 0211 No noncompliance noted Major areas inspected torus support 9A/GC program, procedures, work activities & feedwater sys welds

 DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch WARD, K D Region 3, Chicago, Office of the Director 80/02/25 9pp
- 8004080617 Forwards IE Insp Repts 50-294/80-01 & 50-265/80-02 on 800102-0201 No noncompliance noted HEISHMAN.R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/29 2pp
- --8004080625 IE Insp Repts 50-284/80-01 & 50-265/80-02 on 800102-0201 No noncompliance noted Major areas inspected maint plant operations, physical protection & followups SPESSABLR L. CHRISBOTINOS.N Region 3. Chicago, Office of the Director 80/02/25 7pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07
- 8004140117 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch Tray Adsorber Cells" Visual examination determined that contact between casing & screen is edequate to prevent charcoal granule escape PEOPLES, D. L. Commonwealth Edison Co. 80/03/20 5pp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 1p
- --8004040019 Forwards corrected Haste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted. DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Bafety Branch 60/02/22 2pp
- ---B004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels removable contamination & package external features FOTTER, J P Region G, Chicago, Fuel Facility & Materials Bafsty Branch 80/02/22 7pp
- 8004080494 Forwards final technical evaluation rept re feedwater nozzle cracking Insp program for feedwater nozzles & control rod driveline return line nozzle acceptable CASRAON,8 P. Franklin Institute/Franklin Research Center. NRC-03-79-118 80/03/28 6pp
- 8004150159 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary.

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31 ip.
- 8004080686 Forwards IE Circular 80-05, "Emergency Diesel Cemerator Lubricating Dil Addition & Onsite Supply " No written response required KEPPLER.J 9 Region 3. Chicago. Office of the Director 80/04/01.
- 8004190014 Farwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Fallowers" No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02.

- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/03
- 8004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J G Region 3, Chicago Office of the Director 80/04/09
- B004110025 Forwards IE Bullotin 80-07, "BWR Jet Pump Assembly Failure " Written response required KEPPLER,J G Region 3, Chicago, Office of the Director 80/04/07
- 8004230224 Forwards IE Bulletin 79-03A: "Longitudinal Weld Defects in ABME SA-312.Type 304 Bisinless Steel Pipe " Action required KEPPLER.J G Region 3: Chicago, Office of the Director 80/04/07
- 8004280628 Forwards revised Pages 3 & 5 & omitted Page 4 to IE Insp. Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08 FIGRELL, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/09 ip
- --8004280634 Revised Pages 3 & 5 & omitted Page 4 to IE Insp Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08
 - Region 2, Atlanta, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004150004 Forwards "Radioactive Waste & Environ Monitoring Annual Rept.1979 " Rept constitutes Part 3 of facility operating rept KALIVIANAKIS:N Commonwealth Edison Co 80/03/06 ip
- --8004150007 "Radioactive Wasts & Environ Monitoring Annual Rept.1979 "
 * Eberline Instrument Corp 80/03/31 91pp
- 8004220333 Forwards listing of changes, tests & experiments performed in KALIVIANAKIS,N Commonwealth Edison Co 80/04/14 5pp
- 8 Reportable occurrences: LERs & related correspondence
- B004020422 Forwards LER 80-006/03L-0 KALIVIANAKIS, N. Commonwealth Edison Co 80/03/14 1p
- --8004020427 LER 80-006/03L-0 on 800222; while doing routine panel checks, reactor core isolation cooling supply valves MO 1-1301-16 & 17 were found in closed position Caused by procedural inadequacy & personnel performance Procedures revised VAHRENWALD, J Commonwealth Edison Co 80/03/14, 1p
- BOO4020350 Forwards LER 80-005/03L-0 KALIVIANAKIS.N Commonwealth Edison Co BO/03/20 1p
- --8004020357 LER 80-005/03L-0 on 800224, while performing MISV closure timing, valva AD 1-203-1B failed to close when control switch was operated Caused by blockage of exhaust restrictor on pilot valve Exhaust restrictor cleaned 80DEN, R Commonwealth Edison Co 80/03/20 2pp
- 8004190463 Forwards LER 80-007/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 80/03/25 1p
- --8004150467 LER 80-007/03L-0 on 800308, while performing control room insp & panel check. B main steam line radiation monitor found reading low Caused by logarithmic radiation monitor chassis electronically drifting out of callpr Chassis recalibr HYKOFF, D Commonwealth Edison Co 80/03/25 2pp
- 8004150457 Forwards LER 80-008/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 80/03/27 ip

-8004150468 LER BO-008/03L-O on 800308, after performing proventive maint, 1/2 diesel generator would not start from control room Caused by poor electrical contact between fuse & clip fouse clip adjusted LEECH.K Commonwealth Edison Co 80/03/27 2pp

DOCKET 50-255 PALIBADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

- 8004080426 Advises that designs for fire protection, sprinklers, cable penetration seals & cable firestops described in util 800222 ltr are acceptable for protection intended in NRC safety ZIEMANN,D L Operating Reactors Branch 2 80/03/11 2pp
- 8004110022 Forwards suppl to 780701 fire protection safety evaluation in response to 780915 & 29 ltrs providing addl info Items 3 2 f & 3 2 5 are resolved ZIEMANN,D L. Operating Reactors Branch 2 80/03/19 2pp
- --8004110026 Suppl 1 to fine protection safety evaluation, resolving [tems 3 2 1 & 3 2 9 # Office of Nuclear Reactor Regulation 80/03/19 1p
- 8004240540 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimile traffic KEPPLER.J Q Region 3. Chicago, Office of the Director 80/03/20
- 8004280614 Forwards drawings indicating fire protection mods to Item 3 1 5. "Fire Barriers" FROST.8 R Consumers Power Co 80/04/24 3pp
- --8004280624 "Curtain-Type Fire Doors Heating & Ventilation Sys, Fire Areas 1.2,3 & 4.,Mod 10 " Sheet 1 of 1 * Nuclear Bervices Corp 79/11/29 ip
- --8004280617 "Heating & Ventilation Auxiliary & Containment Plan at Elevation 607 Ft 6 inches & 611 Ft " * Bechtel Corp 79/11/29 ip
- --8004280421 "Heating & Ventilation Auxiliary & Containment Bldg Plan Elevation, 625 Ft " * Bechtel Corp 5935 79/11/29 1p
- ---8004280625 "Heating & Ventilation Auxiliary & Containment Plan at Elevation 639 Ft & 649 Ft " # Bechtel Corp 79/07/03 ip
- --8004280627 "Mod 8, Fire Doors 81, 115, 184, 185 Fire Area Numbers 1, 2, 5, 9 " Sheet 1 of 1 * Nuclear Services Corp 79/01/03 ip

Q Adjudicatory correspondence

- 8004100310 Forwards Revision 4 of "Stram Generator Repair Rept," which is being served on parties to proceeding W/o encl
 01889.M E Isham, Lincoln & Beale 80/03/03 ip
- BOO4090442 Responds to 800221 ltr enclosing CPC first round of interrogatories & request for production of documents Answers will be accompodated informally to extent of relevancy to civil penalty issues, w/o waiving objections MURRAY, J P Rulemaking & Enforcement Division 80/03/06
- 8004080062 Response to CPC 800221 first set of interrogatories & request for production of documents re civil penalty Itams 12,13,14 & 17 will be supplemented by 800411 Forwards objections & responsive answers Certificate of Syc encl BURNS,8 A Rulemaking & Enforcement Division 80/03/31 2pp
- --8004080067 Response in opposition to certain of CPC B00221 first set of interrogatories & request for documents re civil penalty Employees home addresses & personal handwritten notes are not discoverable per case law re invasion of privacy BURNS:8 Q Rulemaking & Enforcement Division 80/03/31 iipp
- --B0040B0074 Response to CPC B00221 first set of interrogatories & request for production of documents re civil penalty Includes facts supporting IE notice of violation & name of persons who have knowledge of stated facts W/affidavit MGSELEY.N C Division of Reactor Operations Inspections 80/03/31 27pp

- 8004080006 Discovery rept for Mar 1980 re civil penalty proceeding Responded to CPCC first round of interlogatories Received GPC 800319 request per FDIA, repeating requests for documents under CPC 80021 discovery filling Certificate of Svc encl BURNS, S G Rulemaking & Enforcement Division 80/04/01 3pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOBSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004170255 Supplemental responses to CPC 800221 first set of interrogatories & request for documents re civil penalty proceeding Regulations do not require performance of research or compilation of data not readily known BURNS,8 G Rulemaking & Enforcement Division 60/04/14 3pp
- ---8004170258 Supplemental answers to CPC first interrogatories & request for documents re civil penalty proceeding Includes statements re identified noncompliances & actions taken after discovery of violation BURNS.S G Rulemaking & Enforcement Division 80/04/14 35pp
- ---8004170262 Recommends civil penalty be assessed against CPC due to Violation discovered in Sept 1979 re manual isolation valves in locked open condition Bases penalty on prior violations re containment integrity W/affidavit & Certificate of Svc KEPPLER.J G Region 3. Chicago. Office of the Director 79/10/
- 8004210232 Interrogatories & request for documents directed to CPC recivil penalty proceeding Requests description of investigations re 791911 discovery of two locked-open manual containment isolation valves Certificate of Svc enc! LIBERMAN.J. BURNS.8 0 Rulemaking & Enforcement Division 80/04/18 8pp

H General correspondence

- 8004230383 Forwards util 800318 news release indicating changes in project angineering & const organization Will submit revisions to GA program by 800430 to incorporate organizational changes HOFFMAN.D P Consumers Power Co 80/04/18 7pp
- P Operating license stage documents & correspondence
- 8004180135 Discusses fission gas release rate from LWR fuel pellets Data re C-E & Exxon PWR fuel bundles demonstrated no adverse effect on ECCS evaluations nor did internal fuel rod pressure exceed sys pressure ZIEMANN.D L Operating Reactors Branch 2 80/02/27 2pp
- B004020450 Requests necessary action to refund licensee amend fees Amend fees waived for certain types of fire protection amends

MILLER, W O License Fee Management Branch 80/03/05

- 8004070220 Advises that Ofc of Controller has authorized refund of three Class II fees submitted with 800131 & 0201 applications License amend fees for certain Tech Spec changes re fire protection waived MILLER, W D License Fee Management Branch 80/03/05 ip
- 8004090346 Forwards NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 W/o encl w/g enc. ZIEMANN,D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020001 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resobmittal of info is unnecessary Refs on updates to info previously submitted are acceptable ZIEMANN.D L. Operating Reactors Branch 2 80/03/06 6pp
- 8004080402 Forwards Amend 55 to License DPR~20, safety evaluation & notice of issuance & availability
 ZIEMANN, D. L. Operating Reactors Branch 2, 80/03/06 2pp
- --8004080405 Amend 55,to License DPR-20, revising Tech Specs contained in App A, changing Tech Specs to conform w/aperating limits of 100FR50, App O, "Fracture Toughness Requirements" ZIEMANN, D L Operating Reactors Branch 2 80/03/04 13pp
- --8004080408 Safety evaluation supporting Amend 55 to License DPR-20 & Office of Nuclear Reactor Regulation 80/03/06 3pp

- --- BCO4080412 Notice of issuance & availability of Amend 55 to License WAMBACH, T V Operating Reactors Branch 2 80/03/06 2pp
- B004030102 Forwards "Nutlear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIEENHUIT, D 9 Division of Operating Reactors 80/03/12 Spp
- ---8004030118 "Nuclear Data Link Specs "

 ** Division of Oberating Reactors 80/02/21 28pp
- 8004100159 Notification of 800326 meeting w/util in Bethesda,MD re BEP Topic VI-B.control room habitability O'CONNOR,P W Operating Reactors Branch 2 80/03/18 2pp
- 8004100154 Requests that future revisions to P&IDs be forwarded to Region 3 incident response ctr Also requests removal of WL Azelson from distribution list Region 3, Chicago, Office of the Director 80/03/20 KEPPLER, J Q
- 8004010289 Submits ref list for SEP Topics VI-7 A 3.VI-7 B.VI-10 A.VII-1 A & VII-2.in response to NRC 800214 request HOFFNANN,D P Consumers Power Co 80/03/26 3pp
- 8004100166 Notification of 800331 meeting w/util in Bethesda.MD re automatic initation of auxiliary feeduater SILVER.R D Operating Reactors Branch 2 80/03/26 2pp
- 8004020166 Responds to NRC 800327 request for add1 info re factlity pressurizor pressure transmitters Rosemont Model 1151 transmitters are being used When plant is taken to cold shubdown, higher selsmic quality Model 1153 will be used HUSTON, R W Consumers Power Co 80/03/28 ip
- 8004210190 Ferwards request for info re containment environ conditions System required for accident mitigation for review of environ qualification of Class IE electrical equipment NRC will estimate time for containment temp to return to near normal ZIEMANN,D t. Operating Reactors Branch 2 80/03/28 15pp
- 8004070320 Forwards "Environ Assessment, Steam Generator Replacement" addressing effects of proposed new barge slip HOFFMAN,D P Consumers Power Co B0/03/31 2pp
- --8004070322 "Environ Assessment Steam Generator Replacement "
 * Consumers Power Co 79/12/31 50pp
- 8004070305 Forwards sys design description re proposed containment hydrogen monitoring sys as committed to under NUREO-0578 HOFFMAN,D P Consumers Power Go 80/04/01 21pp
- 6004080232 Notifies that 800401 C-E owners group rept is applicable to facil; ty & constitutes util response to short-term analysis & emergency procedure guideline requirements of Section 2: 19(c) of NUREO-0578

 HOFFMAN, D P Consumers Power Co 80/04/01 1p
- 8004090389 Forwards "Beismic Consultation for Bafety-Related Electrical Equipment, Interim Rept 1, Equipment Checklist, " providing results of investigation of positive anchorage for certain electrical equipment HOFFMAN, D P Consumers Power Co 80/04/02 ip
- ---B004090394 "Geismic Consultation for Bafety-Related Electrical Equipment Interim Rept 1. Equipment Checklist " 4 John A Blume & Associates: Engineers (subs. URB Corp.) 60/03/20 35pp
- 8004110300 Forwards info re RELAP input for LOCA analysis at Units KUEMIN, J. L. Consumers Power Co. 80/04/02 61pp
- 8004300055 Provides add1 info on automatic initiation of auxiliary feedwater sys flow concerning implementation of Item 2 1 7a requirements of NUREO-0578 Requests detail of safety-grade sys design Certain commitments required within 15 days EISENHUT, D 0 Division of Operating Reactors 80/04/03 3pp
- 8004150215 Advises that facility has not experienced turbine overspeed trip to date per 800321 commitment re cracking in low gressure turbine discs HDFFMAN.D P Consumers Power Co 80/04/10 ip

- 8004150398 Responds to NRC 791109 order modifying license Controlled review to upgrade plant drawings, checklists & procedures associated w/engineered safeguards sys initiated Revisions resulting from review will be completed prior to startup DEWITT, R B Consumers Power Co 80/04/10 3pp
- 8004i50474 Requests amend change to License DPR-20 to allow plant personnel to conduct feedwater line water hammer test Forwards Special Tost Procedure T-30, "Feedwater Line Water Hammer Test "
 DFWITTS R Consumers Power Co. 80/04/11 200
- --8004150479 "Feedwater Line Nater Hammer Test "
 * Consumers Power Co 80/04/11 15pp
- BO04150627 Notifies that current main steam line break analysis requested in NRC 791221 itr cannot be completed until containment spray problem identified in LER 80-002, is resolved MOFFMAN, D P Consumers Power Co 80/04/11 ip
- 8004210150 Submits add1 info requested by NRC re amend to DL to conduct feedline water hammer test MOFFMAN, D P Consumers Power Co 80/04/16 3pp
- BOO4240450 Responds to NRC 800107 request to review aspects of GA program re diesel fuel for facility Diesel fuel oil is included in GA program Sample of main storage tank diesel fuel is tested every three months.per ASTM-D270-65 HOFFMAN.D P Consumers Power Co 80/04/21 ip
- 8004250425 Forwards add1 info in response to NRC 800331 recommendations ro automatic initiation of auxiliary feedwater sys Believes that auxiliary feedwater flow of 300 gpm adequate to recover from loss of main feedwater, HUSTON,R W Consumers Power Co 80/04/22 5pp
- 8004250426 Submits add1 info ro auxiliary feedwater sys in response to NMC 800403 request Short-term Lessons Learned Task Force requirements will be implemented w/o prior NRC approval Sys will be upgraded to sefety-grade sys by 810101 HOFFMAN.D P Consumers Power Co 80/04/23 2pp
- BOO4280519 Forwards request for exemptions to ARME BV & PC Code.Section XI re inservice pump testing Request will remain in effect after code update & is in addition to 780613 submittel HOFFMAN.D P Consumers Power Co 80/04/25 3pp
- G Inspection reports, IE Bulletins & correspondence
- B004040032 Forwards Waste Packaging Insp Rept 79-06A on 791126-28. No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/02/13 2pp
- --8004040035 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & BOT placarding requirements, radiation levels, removable contamination & external package features POTTER, J P. BROWN, R A. Region G. Chicago, Fuel Facility & Materials Safety Branch 80/02/13 App
- 8004100132 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block "No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- 8004090379 Ack receipt of 800208 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/79-20 KEPPLER, J O. Region 3, Chicago, Office of the Director 80/03/20 2pp.
- --B0040903B3 Responds to NRC E00102 ltr re violations noted in IE Insp Rept 50-255/79-20 Corrective actions submitted revised LER 79-044,marked test gauge w/serial number & resolved all discrepancies in valve stroke times HOFFMAN.DP Consumers Power Co B0/02/QB 7pp
- 8004030325 Ack receipt of 800305 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept Util ltr withheld (ref 10GFR2 790) HINDLY A Region 3, Chicago, Safeguards Branch 80/03/21 1p
- 8004150169 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J Q. Region 3, Chicago, Office of the Director 80/03/31 1p

- 8004080704 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dii Addition & Onsite Supply " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01 Ip
- 8004150037 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J Q Region 3, Chicago, Office of the Director 60/04/02
- 8004180040 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J.O. Ragion 3. Chicago, Office of the Director 80/04/02
- 8004220123 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220365 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys "No writted respon≤e required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 io
- 8004280402 Notifies that response to Item 2 of IE Bulletin 79-27 "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation" will be submitted upon completion of emergency procedures review HOFFMAN.D P Consumers Power Co 80/04/03 1p
- B004230196 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/07
- 8004140334 Responds to NRC 800306 ltr re violation noted in IE Insp Rept 50-285/80-02 Corrective actions containment pressure instrument lines will be modified prior to startup HDFFMAN D P Consumers Power Co 80/04/08 4pp
- 8004220149 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/04/09
- BOO41804B7 Responds to NRC telcon request for addl info re "stubbed-in" joints at facility Mods requiring addition of pipe saddles on some joints made so that FBAR or interim acceptance criteria for allowable stress limits in piping are met HOFFMAN,D P Consumers Power Co BO/04/14 1p
- 8004220588 Submits addl info re IE Bulletin 79-27. "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation." per 800417 & IB teleon requests Estimates 320 man-hours will be expended on bulletin to complete action HOFFMAN.D P Consumers Power Co 80/04/18 2pp
- 8004250313 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe "Bulletin is not applicable to plant safety-related sys HUSTON.R W Consumers Power Co 80/04/22 2pp
- R Periodic operating reports & related correspondence
- 8004030217 Forwards "1979 Radiological Environ Monitoring Rept " HOFFMAN, D.P. Carolina Power & Light Co 80/03/31 1p
- ---8004030220 "1979 Radiological Environ Monitoring Rept "
 * Consumers Power Co 80/03/31 9pp
- BOD4040371 Forwards "1977 Environ Monitoring Rept " Analysis of rept data demonstrates no detectable increase in radioactivity levels of snyiron media attributable to facility effluents HOFFMAN.D P Consumers Power Co 80/03/31 Ip
- ---8004040374 "1979 Environ Monitoring Rept "
 * Consumers Power Co 80/03/31 9pp
- 8004080436 Forwards monthly operating rept for Mar 1980 ADAMS:WE Consumers Power Co 80/04/01 ip
- --8004080438 Monthly operating rept for Mar 1980 BODTKE:P J Consumers Power Co 80/04/01 4pp

- S Reportable occurrences, LERs & related correspondence
- 8004180520 PNO-III-78-197 factlity was shut down on 781128 to correct excessive control rod drive mechanism seal leakage Cause may be metallurgy problem associated w/seal matl Most seals installed during refueling outage have been replaced KLINGER, G. NOLAN, F. Region 3. Chicago, Office of the Director 78/11/30 1p
- B004100396 Forwards LER B0-002/03L-0 H0FFMAN, D P Consumers Power Co 80/04/03 1p
- --8004100399 LER 80-002/OSL-0 on 791023, during routine testing of hydraulic snubbers, snubber 8-6, located on main steam line, failed to meet test acceptance criteria Caused by loose accumulator oil fill fitting Snubber replaced * Consumers Power Co 60/04/O3 1p
- 6004100403 Forwards LER 80-003/01T-0 HOFFMAN, D P Consumers Power Co 60/04/03 1p
- --9004100404 LER 80-003/01T-0 on 800304 during evaluation of 8EP Topic VI-3 discovered total activation time for containment spray sys in excess of FSAR instintion times Caused by personnel error during initial accident analyses * Consumers Power Co 80/04/03 2pp
- 8004100413 Forwards updated LER 79-044/01X-1 HOFFMAN.D P Consumers Power Co 80/04/03 ip
- --8004100415 Updated LER 79-044/01X-1 on 790729, after surveillance test AO-0, valves 3363 ES & 3364 EB left in closed position, resulting in sodium hydroxide addition sys not being returned to svc Caused by inadequate procedure requirements * Consumers Power Co 80/04/03 ip
- 8004150012 Forwards NPBES noncompliance notification HOFFMAN. D.P. Consumers Power Co. 80/04/09 1p
- --8004150019 NPDES noncompliance notification on 800310 diesel fuel spill detected in diesel generator room Caused by fuel tank high level shutoff switch failing to stop transfer pump while filling fuel tank Crew assigned to clean up turbine sump FORBES,R L Consumers Power Co 80/03/26 3pp.
- 8004150530 Forwards LER 80-004/01T-0 HDFFMAN, D P Consumers Power Co 80/04/10 ip
- --8004150537 LER 80~004/01T-0 on 800327 during review of Tach Spec surveillance procedures discovered procedure MO-19 requiring isolation of both containment spray headers during test violated Cause not stated Procedure rewritten * Consumers Power Co 80/04/10 1P
- 8004150544 Forwards LER 80-005/01T-0 HOFFMAN-D P Consumers Power Co. 80/04/10 1p
- --8004150556 LER 80-005/017-0 on 800327, during review of Tech Spec surveillance procedures, discovered that procedures GO-2 & MD-23 require stroking SIRW tank autlet valves Amend to DL or clarification of Tech Spec requirements will be sought * Consumers Power Co 80/04/10 1P
- 8004250350 Forwards LER 80-007/01T-0 FROST, S R Consumers Power Co 80/04/21 is
- ~-8004250358 LER 80-007/01T-0 on 800407, during maint on control room ventilation sys, discovered leakage defects through shaft of fan V-36. Fresh eir damper D-i woold not close Caused by inadequate pre-operational testing of ventilation sys * Consumers Power Co 80/04/21 ip
- 8004250354 Forwards LER 80-006/03L-0 MOFFMAN, D. P. Consumers Pawer Co 80/04/21. 1p
- --8004250359 LER 80~006/03L-0 on 791110, during routing surveillance of containment purge valves, redundant T-ring air supplies for 12-inch & 48-inch valves leaked beyond accepted criteria Cause not stated Leaks were primarily at fittings & packing * Consumers Power Co. 80/04/21.

- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency % fire protection plans
- 8004190185 Forwards comments on 790301 safeguards contingency plan & 790901 Revision 1 Requests revisions & add1 info Encl withheld (ref 10CFR2 790) | IPPDLITO, Y A Operating Reactors Branch 3 | 80/03/27 | 2pp
- O Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSSICK, U Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 8004300404 Requests that public hearing & EI8 be required for proposed low level waste compaction & incineration facility at site JURENKO,R C Affiliation Unknown 80/04/22 1p
- P Operating license stage documents & correspondence
- 8004020178 Forwards request for add1 info on proposed. Tech Spec changes re control & wiring diagrams LAINAS: 0 Plant Systems Branch 80/02/11 3pp
- 8004070384 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 Spp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bathesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- GO04040127 Forwards Corrected Pages 159 & 160 to Amend 59 & Pages 157 & 158 to Amend 35 For Licenses DPR-33 & DPR-52 IPPOLITO T A Operating Reactors Branch 3 BO/03/14 4pp.
- 8004110519 Forwards Amends 40.55 & 32 to Licenses DPR-33.DPR-52 & DPR-68 respectively, safety evaluation & notice of issuance & availability PPDLITO.T A Operating Reactors Branch 3 80/03/17 2pp
- --8004110525 Amends 60.55 & 32 to Licenses DPR-33.DPR-52 & DPR-68, respectively, authorizing temporary storage of low level radwaste in existing covered pavilion, outside security fence but inside site exclusion area IPPOLITO, T A Operating Reactors Branch 3 80/03/17 App
- --8004110525 Amends 40, 55 & 32 to Licenses DPR-33, DPR-52 & DPR-46, respectively, authorizing temporary storage of low level radwaste in existing covered pavilion outside security fence but inside site exclusion area IPPOLITO. T A Operating Reactors Branch 3 80/03/17 App
- --8004110527 Bafety evaluation supporting Amends 60.55 & 32 to Licenses DPR-33,DPR-52 & DPR-6B, respectively * Office of Nuclear Reactor Regulation, 80/03/17 7pp
- --8004110531 Notice of issuance & availability of Amends 60,55 & 32 to Licenses DPR-33.DPR-52 & DPR-68, respectively IPPOLITO, T A Operating Reactors Branch 3. 80/03/17. 3pp
- 8004150423 Advises that add1 time will be needed to develop coordinated response to NRC request of 800215 Response will be submitted by 800501 MILLS:L M Tennessee Valley Authority. 80/04/07 1p
- 8004150557 Forwards add1 info re containment purge & venting sys.in response to NRC 800226 ltr. Key lock switches are provided on control switches to allow overriding primary containment isolation signal
 MILLB.L M Tennessee Valley Authority 80/04/07 3pp

- 8004290020 Forwards 600128 & 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line nozzles Guidelines for mods will be discussed in NUREG-0619, to be issued in "For Comment" form in Apr 1980 JPPOLITOIT A Operating Reactors Branch 3 80/04/07 2pp
- 8004230283 Forwards request for add1 info re degraded grid voltage Also requests revised schedule for submission of design of long-term mods re adequacies of station electric distribution sys voltages IPPOLITUIT A Operating Reactors Branch 3 80/04/08 3pp
- 8004230506 Forwards info re control drive malfonctions during CY78 & 79,in response to NRC 800110 request
 MILLS.L M Tennessae Valley Authority 80/04/11 Rpp
- 8004220340 Application to amend Licenses DPR-33, DPR-52 & DPR-69 changing Teck Specs to allow conduct of short containment integrated leak rate test Fee encl
 MILLS, L M Tønnessee Valley Authority 80/04/15 2pp
- --8004220349 Proposed Tech Spec revisions, allowing conduct of short containment integrated leak rate test * Tennessee Valley Authority 80/04/15 13pp
- ---BOO4220358 "Nuclear Containment Testing for TVA Nuclear Power Plants,"
 presented at ANS 79111[-16 winter meeting
 CLARK,K H , WHITE,T J Tennessee Valley Authority 79/11/16
- BOO4220523 Responds to NRC 800212 request for info needed to compare RETRAN code results w/simulator results & EQ&O 800317 request for info re LOCA calculational models Singer Co could more adequately address NRC request MILLS.L M Tennessee Valley Authority 60/04/15 2pp
- --8004220331 Requests assistance in comparing RETRAN & simulator results for BWR plant transients/incidents re loss of feedwater & loss of load BML should be provided w/related info EO&O 800317 request for info encl
 FABIC.8 Analysis Development Branch 80/02/12 App
- 8004220533 Advises that Section 316 documents re NNPDES Permit ALO022080 are being sent to JW Warr,H Zeller & LB Tebp.in accordance w/util 800331 ltr EL-ABHRY,M T Tennessee Valley Authority 80/04/17 2pp
- O Inspection reports, IE Bulletine & correspondence
- 8004040174 Ack receipt of 800124 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-42. 50-260/79-42 & 50-276/79-42 BRYANT.J.C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/04 Epp
- --8004040181 Responds to NRC 800102 ltr re violations noted in IE Insp. Repts 80-259/79-42,50-260/79-42 & 50-296/79-42 Corrective actions, review of all previous insp data records was made to verify notification to DES en
- --8004040185 Forwards IE Insp Repts 50-289/79-42,50-260/79-42 & 50-296/79-42 on 791126-27 & notice of violation MURPHY,C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/02 2pp
- --8004040189 Notice of violation from insp on 791126-27
 * Region 2, Atlanta, Office of the Director 79/12/14, 1p.
- --B004040194 IE Insp Repts 50-259/79-42.50-240/79-42 & 50-296/79-42 on 791126-27 Noncompliance noted failure to report discrepancies to DES engineer HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENOS.L. Region 2. Atlanta, Office of the Director 79/12/14 4pp
- 8004070352 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06, 250.
- 8004090245 Forwards IE Insp Repts 50-259/80-03:50-260/80-03 & 50-276/80-07 on 800127-31. No noncompliance noted LEWIS.R.C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/02/19 2pp

- --8004090252 IE Insp Repts 50-259/80-03,50-240/80-03 t 50-296/80-09 on 800129-31 No noncompliance noted Major areas inspected refueling activities KELLOGO.P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 3pp
- 8004110503 Forwards IE Insp Repts 50-259/80-07.50-240/80-07 & 50-294/80-07 on B00205-07 No noncompliance noted BRYANT.U C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004110514 IE Insp Repts 50-259/80-07,50-260/80-07 & 50-296/80-07 on 800205-07 No noncompliance noted Major areas inspected video observation of core spray sys sparger & review of proposed actions for LER HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch VANDORN.P K Region 2. Atlanta, Office of the Director 80/02/25 3pp
- 8004280194 Forwards IE Insp Repts 50-259/80-05,50-260/80-05 & 50-296/80-05 on B00206-08 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/07 2pp
- --8004280202 IE Insp Repts 50-259/80-05.50-260/80-05 & 50-276/80-05 on 800205-08 No noncompliance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Bullotin 79-14)
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENGS, L Region 2. Atlanta, Office of the Director 80/03/04 4pp
- 8004020242 Ack receipt of 800204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-38, 50-260/79-38 & 50-296/79-38 LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/11 ip
- --8004020249 Responds to NRC 800110 ltr re violations noted in IE Insp Repts 50-259/79-38, 50-260/79-38 & 50-296/79-38 Corrective actions local leak rate test performed on normal hatch cover & control rod drive added to CILRT results MILLS.L M Tennessee Valley Authority 80/02/04 3pp
- --8004020252 Forwards IE Insp Repts 50-259/79-38,50-240/79-38 & 50-296/79-38 on 791119-23 & notice of violation LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/10 2pp
- --8004020258 Notice of violation from insp on 791119-23
 * Region 2, Atlanta, Office of the Director 80/01/08 ip
- --8004020263 IE Insp Repts 50-259/79-38.50-260/79-38 & 50-296/79-38 on 791:19-23 Noncompliance noted use of temporary control rod driveline hatch cover during integrated leak rate test UPRIGHT,C M Region Z: Atlanta, Reactor Operations Nuclear Support Branch 80/01/08 6pp
- --8004020263 IE Insp Repts 50-259/79-38:50-260/79-38 & 50-296/79-38 on 791119-23 Noncompliance noted use of temporary control rod driveline hatch cover during integrated leak rate test UPRIGHT.C M Region 2, Atlanta. Reactor Operations Nuclear Support Branch BROOKS.E H, WHITENER, H L. Region 2, Atlants, Office of the Director 80/01/08 App
- 8004100364 Responds to IE Bulletin 79-23 Conducted sustained full-load operational test on Emergency Diesel Generator 3A Test demonstrated ability of diesel generators to function properly over 24-h period at specified loads MILLS,L M Tennessee Valley Authority 80/03/21, ip
- 8004210178 Forwards response to IE Bulletin 80-03, "Loss of Charcost from 8td Type II. Two-Inch.Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessae Vailey Authority 80/03/21 4pp
- 8004280001 Supplements 800212 response to IE Bulletin 79-18 Forwards info re procedural controls necessary until completion of sys mods for upgrading public address & evacuation alarm sys as required by bulletin MILLS.L M Tennessee Valley Authority 80/03/25 2pp
- 8004150527 Forwards IE Info Notice 80~12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31

- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required C'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80~13, "QE Type SBM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees " No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3hs
- 8004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0il Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004110021 Forwards IE Bulletin 80~07, "BWR Jet Pump Assembly Failure " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards 1E Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312.Type 304 Stainless Steel Pipe" Action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04 in
- 8004180445 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required Q'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
- 8004280170 Forwards monthly progress rept for Mar 1980 in response to IE Bulletin 79-14. "Seismic Analysis for As-Busht Safety-Related Piping Sys " Includes insp of drawings, pipe supports & floor & wall penetrations MILLS.L K Tennessee Valley Authority 80/04/07 20pp
- 8004270170 Forwards IE Insp Repts 50-259/80-12,50-240/80-10 & 50-296/80-11 on 800311-14 No noncompliance noted KENNA-W B Region 2: Atlanta, Safeguards Branch 80/04/09 2pp
- --8004290177 lE Insp Repts 50-259/80-12, 50-260/80-10 & 50-296/80-11 on BOO311-14 No noncompliance noted Major areas inspected review of security plan.organization.access controls & barriers Details withheld (ref 100FR2 790) OILLESPIE.F Region 2, Atlanta. Bafeguards Branch TillHAN,A Region 2. Atlanta. Office of the Director 80/04/07 10
- B004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp
 MILLS.L.M. Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004240411 Forwards monthly operating repts for Mar 1780 ABERCROMBLE, IL Tennessee Valley Authority 80/04/10 is
- --8004240415 Monthly operating repts for Har 1980 TH0H.T Tennessee Valley Authority 80/04/02 32pp
- S Reportable occurrences, LERs & related correspondence
- 8004180518 PNO-11-78-147 on 780818, one of six air compressors suffered massive failure resulting in rapid loss of control air pressure to all three units Caused by large hole in cylinder head of failed compressor Compressor was isolated XLINOER, 9 . NOLAN, F . SNIEZEK, J Region 2, Atlanta, Office of the Director 78/08/18 ip
- 8004010451 Forwards LER 80-020/03L-0 CALHOUN, J R Tennessee Valley Authority 80/03/28 1p
- --8004010458 LER BO-020/03L-0. on 800301 during normal operation, w/high winds & freezing rain. Trinity offsite 161-kV power source was lost intermittently Caused by ice loading & high winds requiring operation of line protective relay # Tennessee Valley Authority 80/03/28 2pp
- 8004010487 Forwards LER 80-021/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/03/28 ip

- --8004010491 LER 80-021/03L-0 on 800301 during severe ice storm, wind speed instrumentation on meteorology tower failed to indicate true wind speed Caused by ice formation on instrument No action planned

 * Tennessee Valley Authority 80/03/28 2pp
- 8004150573 Forwards LER 80-023/03L-0 CALHOUN,J R Tennessee Vailey Authority 80/04/08 ip
- --8004150585 LER 80-023/03L-0 on 800312 during refueling outage, relay 23A-XA2 found wared incorrectly eliminating HPCI reactor high water level trip Cause undetermined * Tennessee Valley Authority 80704/08 2pp
- 8004150525 Forwards LER 80-024/03L-0 CALHOUM J R Tennesses Valley Authority 80/04/10 ip
- --9004150536 LER 80-024/03L-0 on 900312 during refueling outage w/Units 2 % 3 under normal operation nut came off bracket holding insulated communications ground wire above Athens 161-K line.causing fault resulting in trip of breakers * Tennessee Valley Authority 90/04/10 2pp
- 8004150523 Forwards LER 80-025/03L-0 CALHOUN,JR Tennessee Valley Authority 80/04/11 ip
- --8004150535 LER 80-025/03L-0 on 800313, primary containment isolation testing revealed failure of RHR injection valve 74-67 to close upon isolation signal Caused by limit switch on FCV-74-48 not making good contact Contact cleaned & adjusted Tennessee Valley Authority 80/04/11 2pp
- 8004220486 Forward's supplemental LER 80-001/01T-1 CALHOUN, J R Tennessee Valley Authority 80/04/18 ip
- --8004220699 Supplemental LER 80-001/01T-1 on 800107, during performance of STER 7902 per IE Bulletin 79-23 diesel generator 3A lost speed control Caused by deteriorated electomer spider coupling Spider coupling Peplaced
 * Tennessee Valley Authority 80/04/18 2pp
- 8004220742 Forwards LER 80-027/03L-0 CALHOUN:J R Tennessee Valley Authority 80/04/18 ip
- --8004220750 LER 80-027/03L-0 on 800322, while performing 81 4 2, 8-14, RHR66 pump D3 timer found 3-8 less than min requirement Cause unknown Timer adjusted & verified within Tech 8pec tolerance

 * Tennessee Valley Authority 80/04/18 2pp
- 8004250376 Forwards updated LER 80-011/01T-1 CALHOUNUUR Tennessee Valley Authority 80/04/18 ip
- --8004250408 Updated LER 60-011/017-1 on 800214 analysis indicated potential loss of secondary containment should primary containment purging be conducted during hot standby concurrent w/LDCA. No cause stated Purging will be limited tennessee Valley Authority 80/04/18 2pp
- B0042B0593 Forwards LER B0-026/03L-0 CALHOUN,J R Tennessee Vailey Authority B0/04/18 1p
- ---B004280598 LER 80-026/03L-0 on 800322; HPCI stop valve would not open completely Caused by worn mechanical overspeed trip piston, Hydraulic sys adjusted & stop valve tested * Tennessee Valley Authority 80/04/18 2pp
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8004150185 Forwards comments on 790301 safeguards contingency plan & 790901 Revision i Raquests revisions & add1 info.Encl withheld (ref 100FR2 790) IPPOLITO.T A Operating Reactors Branch 3 80/03/27 2pg
- Q Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparadness distributed as Board notification GDSBICKL V Office of the Executive Director for Operations. 80/04/02 34pp

H Ganeral correspondence

- 8004300404 Requests that public hearing & EIS be required for proposed law level waste compaction & incineration facility at site JURENKO:R C Affiliation Unknown 80/04/22 ip
- P Operating license stage documents & correspondence
- 8004020178 Forwards request for addl info on proposed Tech Spec changes re control & willing diagrams LAINAS.O Plant Systems Branch 80/02/11 3pp
- GOO40703B4 Discusses NRC 761123 request that all LWR licenses assess higher fission gas release for fuel burnups above 20.000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- 8D04030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004040127 Forwards Corrected Pages 159 & 160 to Amend 59 & Pages 157 & 158 to Amend 35 for Licenses DPR-33 & DPR-52 IPPCLITO.T A Operating Reactors Branch 3 80/03/14 4pp
- BO04110519 Forwards Amends 40,55 & 32 to Licenses DPR-33,DPR-52 & DPR-68.respectively, safety evaluation & notice of issuance & availability IPPCLITO,T A Operating Reactors Branch 3 80/03/17 2pp
- ---8004110525 Amends 60.55 % 32 to Licenses DPR-33.DPR-52 & DPR-48, respectively, authorizing temporary storage of low level radwaste in existing covered pavilion, outside security fence but inside site exclusion area IPPOLITO, T A Operating Reactors Branch 3 80/03/17 6pp
- --8004i10527 Safety evaluation supporting Amends 60.55 & 32 to Licenses DPR-33,DPR-52 & DPR-68, respectively * Office of Nuclear Reactor Regulation 80/03/17 7pp
- --8004110831 Notice of issuance & availability of Amends 60,58 & 32 to Licenses DPR-33,DPR-82 & DPR-68, respectively IPPDLITO,T A Operating Reactors Branch 3 80/03/17 3pp
- BOO4150423 Advises that addl time will be needed to develop coordinated vasponse to NRC request of 600215 Response will be submitted by 800501 MILLSIL M Tennessee Valley Authority 80/04/07 1p
- 8004150857 Forwards additinfore containment purge & venting sys, in response to NRC 800226 ltr Key lock switches are provided on control switches to allow overriding primary containment isolation signal MILLGL M Tennessee Valley Authority 80/04/07 3pp
- 8004270028 Forwards 800128 & 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of crocking in return line notices Guidelines for mods will be discussed in NUREO-0619, to be issued in "For Comment" form in Apr 1980 IPPOLITO.T. A Operating Reactors Branch 3 80/04/07 2pp
- 8004230283 Forwards request for add1 info re degraded grid voltage Also requests revised schedule for submission of design of long-term mods re adequacies of station electric distribution sys voltages IPPQLITO.T A Operating Reactors Branch 3 80/04/08 3pp
- 8004230506 Forwards info re control drive malfunctions during CY70 & 79.in response to NRC 800110 request MILLB.L M Tennesses Vailey Authority 80/04/11, 2pp
- 8004220340 Application to amend Licenses DPR-33, DPR-92 & DPR-68 changing Tech Specs to allow conduct of short containment integrated leak rate test Fee encl.
 MILLS, L.M. Tennesses Valley Authority 80/04/15 2pp
- --8004220349 Proposed Tech Spec revisions, allowing conduct of short containment integrated look rate test * Tennessee Valley Authority 80/04/15, 13pp

- --8004220358 "Nuclear Containment Testing for TVA Nuclear Power Plants," presented at ANS 791111-16 winter meeting CLARK.K H, WHITE,T J Tennessee Valley Authority 79/11/16 46op
- BOO4220523 Responds to NRC BO0212 request for info needed to compare RETRAN code results w/simulator results & E0&C 800317 request for info re LOCA calculational models Singer Co could more adequately address NRC request MILLS,L M Tennessee Valley Authority 80/04/15 2pp
- --8004220531 Requests assistance in comparing RETRAN & simulator results for BWR plant transionts/incidents re loss of feedwater & loss of load BNL should be provided w/related info EO&Q 800317 request for info encl FABIC.B Analysis Development Branch 80/02/12 4pp
- Q Inspection reports: IE Bulletins & correspondence
- 8004040174 Ack receipt of 800124 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-42, 50-260/79-42 & 50-296/79-42 & 50-296/79-42 & BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8004040181 Responds to NRC 800102 ltr re violations noted in IE Insp Repts 50-259/77-42.30-260/79-42 & 50-296/79-42 Corrective actions review of all previous insp data records was made to verify notification to DES engineer MILLS:L M Tonnessee Valley Authority 80/01/24 3pp
- --8004040189 Forwards IE lnsp Repts 50-259/79-42,50-260/79-42 & 50-296/79-42 on 791126-27 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/02 2pp
- --8004040189 Notice of violation from insp on 791126-27 * Region 2, Atlanta, Office of the Director 79/12/14 1p
- --B004040196 lE Insp Repts 50-289/79-42.50-260/79-42 & 50-296/79-42 on 791126-27 Noncompliance noted failure to report discrepancies to DES engineer HERDT. A Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch MCDENOS. L. Region 2. Atlanta, Office of the Director 79/12/14 4pp
- 8004070352 Forwards IE Bulletin BO-O3, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06 2pp
- B004090245 Forwards IE Insp Repts 50-259/B0-03.50-260/B0-03 & 50-276/80-09 on B00127-31 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/19 2pp
- --8004090252 IE Insp Repts 50-259/80-03:50-260/80-03 & 50-296/80-09 on 800129-31 No noncompliance noted Major areas inspected refueling activities KELLOGO, P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 3pp
- 8004110503 Forwards IE Insp Repts 50-259/80-07.50-260/80-07 & 50-276/80-07 on 800205-07 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004110514 IE Insp Repts 50-259/80-07.50-240/80-07 & 50-294/80-07 on 800205-07 No noncompliance noted Major areas inspected video observation of core spray sys sparger & review of proposed actions for LER HERDT. A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch VANDOURN.P K Region 2. Atlanta. Office of the Director 80/02/25 3pp
- 8004280194 Forwards IE Insp Repts 50-299/80-05,50-260/80-05 & 50-294/80-05 on 800206-08 No noncompliance noted BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80703/07 2pp
- --8004280202 IE Insp Repts 30-259/80-05.50-260/80-05 & 50-296/80-05 on 800204-08 No noncompliance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14)
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENOS, L. Region 2. Atlanta. Office of the Director 80/03/04 4pp

- 8004020242 Ack receipt of 800204 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-259/79-38, 50-260/79-38 & 50-296/79-38 LEUIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support
- G Region 2, Atlanta, Reactor Operations Nuclear Support BO/03/11 1p
- ---B004020249 Responds to NRC B00110 ltr re violations noted in IE Insp Repts 50-259/79-38.30-260/79-38 & 50-296/79-38 Corrective actions local leak rate test personned on normal hatch cover & control rod drive added to CIRT results HILLS,L H Tennessee Valley Authority B0/02/04 3pp
- --8004020252 Forwards IE Insp Repts 50-259/79-36.50-260/79-38 & 50-296/79-38 on 791119-23 & notice of violation LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 60/01/10 2pp
- --8004020258 Notice of violation from insp on 771119-23 + Region 2, Atlanta, Office of the Director 80/0 80/01/08 1p
- -8004020263 IE Insp Repts 50-259/79-38,50-260/79-38 & 50-296/79-38 on 79119-23 Noncompliance noted use of temporary control rod draveline hatch cover during integrated leak rate test UPRIGHT.C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch BROOKS.E H. WHITENER, HL Region 2, Atlanta, Office of the Director 80/01/08 App
- BOO4100364 Responds to IE Bulletin 79-23 Conducted sustained full-load operational test on Emergency Dissel Generator 3A Test demonstrated ability of dissel generators to function properly over 24-h period at specified loads HILLS.L M Tennessee Valley Authority 80/03/21 1p
- 800421017B Forwards response to IE Bullstin 80-03, "Loss of Charcoal from 8td Type II. Two~inch. Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 App
- 800A280001 Supplements 800212 response to 1E Bulletin 79-18 Forwards info re procedural controls necessary until completion of ays mods for upgrading public address & evacuation alarm sys as reguired by bulletin MILLS/L M Tennessee Valley Authority 80/03/25 2pp
- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Gauses Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Cenerator Lubricating Oil Addition & Onsite Supply " No written response required O'RELLLY.J P Region 2. Atlanta, Office of the Director 80/04/ Region 2. Atlanta, Office of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required D'REILLY.J P Region 2: Atlanta. Office of the Director 80/04/02
- BQ04180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Bil Bys " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/03
- 8004110021 Forwards IE Bulletin 80-07, "BMR Jet Pump Assembly Failure." Written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/04.
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Hald Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 80/04/04 B0/04/04
- B004180445 Forwards IE Bulletin 80-08, "Eram of Containment Liner Penetration Melds," Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/04/07

- 8004280170 Forwards monthly progress rapt for Har 1980 in response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys "Includes insp of drawings, pipe supports & floor & wall penetrations
 MILLS
- 8004290170 Forwards IE Insp Repts 50-259/80-12.50-260/80-10 & S0-276/80-11 on 800311-14 No noncompliance noted KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/04/09 2pp
- --R004290177 IE Inso Repts 50-259/80-12.50-260/80-10 & 50-296/80-11 pn 004290177 IE Insp Repts 30-259/80-12.50-250/80-10 & 50-296/80-1
 BDO311-14 No noncompliance noted Major areas inspected
 review of security plan.organization.access controls &
 barriers Details withheld (ref 10CFR2 790)
 GILLEBIRF, Region 2. Atlanta, Eafeguards Branch TILLMAN, A
 Region 2. Atlanta, Office of the Director BD/04/07 Ip
- 8004270379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice MILLS, L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004240411 Forwards monthly operating repts for Mar 1980 ABERCROMBLE, H. L. Tennessee Valley Authority 80/04/10
- --8004240415 Monthly operating repts for Mar 1980 THOM.T Tennessee Valley Authority 80/04/02 32pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004180518 PNO-II-78-147 on 780818, one of six air compressors suffered massive failure resulting in rapid loss of control air pressure to all three units Caused by large hole in cylinder head of failed compressor Compressor was isolated KLINGER, 0 Region 2, Atlanta, Office of the Director 78/08/18
- 8004010460 Forwards LER 80~013/03L-0 CALHOUN, J R Tennesses Valley Authority 80/03/28 in
- --8004010466 LER 80-013/03L-O on B00301 during preparations for startup after outage for maint offsits 161-kV power source intermittently lost power Caused by winter storm Icing & wind effects under investigation # Tennessee Valley Authority 80/03/28 ip
- 8004070288 Forwards LER 80-014/031-0 GALHOUN, J R Tennessee Valley Authority 80/03/31, ip
- --8004070289 LER 80-014/03L-0 on 800216, intent of special instruction 4 2 13-44 not met because RHR pump C in operation in torus cooling mode when special instruction performed Caused by procedural inadequecy for experienced plant configuration * Tennessee Valley Authority 80/03/31. 2pp
- B004150515 Forwards LER B0-015/03L-0 CALHOUN, J R Tennessee Valley Authority, 80/04/07, 1p.
- --8004150522 LER 80-015/03L-0 on 800309 during startup rod block monitor A was bypassed for more than 24-hrs in 30-day period Caused by need for calibr & maint Channel recalibr tested & returned to eve Tennessee Valley Authority 80/04/07 2pp
- 8004140433 Forwards LER 80~017/03L-0. CALHOUN,J.R. Tennessee Valley Authority 80/04/08, ip
- ~~8004i40436 LER 80-017/03L-0 on 8003iO, while performing surveillance instruction 4 5.E 1.HPCI turbine tripped Caused by failed rupture disc in turbine exhaust line Rupture disc replaced * Tennessee Valley Authority 80/04/08 2pp.
- 8004190451 Forwards LER 80-016/03L-0 GALHOUN, J R Tennessee Valley Authority 80/04/08 1p
- ~~8004180457 LER 80~016/03L~0: on 800310, after startup, discovered roof valve failure after being closed during short outage to allow repair on instrument panel Caused by blocked sensing line & slow leak Valve mechanically cleared

 * Tennesses Valley Authority 80/04/08 2PP
- 8004220669 Forwards LER 80-018/03L-0, CALHOUN, J.R. Tennessee Valley Authority 80/04/18 ip.

- ~~8004220680 LER 80-018/03L-0 on 800321, during normal operation, 2A reactor recirculation mator generator set tripped Caused by generator stator temp high relay actuation
 * Tennessee Valley Authority 80/04/18 2pp
- DOCKET 90-241 H B ROBINSON PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004070313 Forwards response to NRC 800207 questions re fire protection Add1 responses will be submitted no later than 800601 Mods necessary to provide adequate fire protection will be completed by 801031 UTLEY.E E Carolina Power & Light Co 80/04/01 4pp
- O Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL, V Office of the Executive Director for Operations 80/04/02 34pp
- I Financial information
- BOD4010405 Forwards Annual Financial Report 1979 Also forwards info recash flow projection to guarantee retrospective premium liability to nuclear liability insurance carriers GRAHAM.W E Carolina Power & Light Co 60/03/27 4pp
- --8004010409 Annual Financial Rept 1979
 * Carolina Power & Light Co 80/03/01 36pp
- J Insurance & indemnity information
- BOO4180344 Forwards Endorsement 63 to NELIA Policy NF-180 GRAHAM.W E Carolina Power & Light Co 80/04/11 2pp
- BD04240379 Forwards Endorsement 51 to MAELU Policy MF-49 GRAHAM, W E Carolina Power & Light Co B0/04/17 2pp
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 3pp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004280148 Forwards Amend 46 to License DPR-23 & notice of issuance & availability
 8CHHROGER A Operating Reactors Branch 1 80/03/13 3pp
- --8004280151 Amend 46 to License DPR-23, revising Tech Spacs to reflect corporate & plant organizational changes
 SCHWENGER.A Operating Reactors Branch 1 80/03/13 14pp
- ---B004280194 Notice of issuance & availability of Amend 44 to License DPR-23. BCHKENCER,A Operating Reactors Branch 1 B0/03/13 2pp
- 8004010324 Informs of addition of onsite diesel generator for auxiliary shutdown sys, to be installed & operational by 801031 Forwards Figures 1-15 to be substituted for Figures 1-14 of 800201 submittal UTLEY, E Carolina Power & Light Co. 80/03/21 14pp
- 8004020076 Forwards request for add1 info re electricial & instrumentation aspects of containment purging Advises that 791207 commitment meets NRC interim position re purge & vent valve operation pending resolution of isolation operability SCHWENGER.A. Operating Reactors Branch 1. 80/03/21 4pp
- BOO4020307 Supplements 800223 ltr re-preliminary results of Zircaloy guide tube wear measurement Subsequent analysis assures no safety concern re-assembly integrity & control rod scram capability
 OWBLEY.OF Exxon Nuclear Co / Inc (subs of Exxon Corp).
 BO/03/29 io

- 8004040273 Forwards suppl to 741218 application for amend to License DPR-23 Revision consists of rewarding of proposed changes to Items B through EDF Paragraph 2 & description of health physics program UTLEY, E Carolina Power & Light Co 80/03/31 1p
- --8004040297 Suppl to 741218 application to amend License DPR-23 Revision consists of rewording of proposed changes to Items B through E of Paragraph 2 % description of health physics program * Carolina Power & Light Co 80/03/31 4pp
- 8004080648 Forwards suppl to 791231 response to Lessons Learned Task Force short-term requirements Describes pressurizer level & mods to control switches UTLEV,E E Carolina Power & Light Co 80/03/31 50pp
- 8004250029 Forwards list of addl info needed to complete review of auxiliary feedwater sys.containing NRC positions on certain recommendations Requests response within 30 days from itr receipt Revised version of endurance test requirements encl SCHWENCER, A Operating Reactors Branch 1 80/03/31 11pp
- 8004140413 Submits addl info re implementation of Task Force shortterm Lessons Learned requirements Discusses replacement of switch for radiation monitors R-11 & R-12 circuits & mod to power operated relief valve position indication UTLEY.E E Carolina Power & Light Co 80/04/04 3pp
- 8004300443 Confirms 791231 plans, reviewed w/ NRC, re interim implementation of shift technical advisor program SROs will be substituted for shift technical advisors undergoing planned training UTLEV.E E Carolina Power & Light Co 80/04/25 ip
- G Inspection reports. IE Bulletins & correspondence
- 8004070134 Forwards 45-day response to IE Bulletin 79-01 W/o encl FURR.B J Carolina Power & Light Co 80/03/10 1p
- 8004280099 Forwards IE Insp Rept 50-261/80-05 on 800220-21 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/14 2pp
- --B0042B0109 IE Insp Rept 50-261/B0-09 on B00220-21 No noncompliance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Builetin 79-14) HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch MODENOS, L Region 2. Atlanta. Office of the Director 80/09/13 App
- 8004100343 Responds to IE Bulletin 80-03 No charcoal colls of ref type are used at facility FURR.B J Carolina Power & Light Co 80/03/21 6pp
- 8004;50497 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31
- 8004080598 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating DII Addition & Onsite Supply" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01
- 8004140462 Ack receipt of 600314 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 80-261/80-01 BTOHR.JP Region 2. Atlanta, Fuel Facility & Materials Safety Branch 60/04/01 Ip
- --8004140468 Responds to NRC 800225 itr re violation noted in IE Insp Rept 50-261/80-01 Corrective actions written procedures re gamma rays are being developed STARKEY'R B Carolina Power & Light Co 80/03/14 2pp
- --8004140473 Forwards IE Insp Rept 50-261/80-01 on 800204-07 & notice of violation STOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/02/25 2pp
- --BOO4140477 Notice of violation from insp on BOO204-07 * Region 2, Atlanta, Office of the Director BO/02/22 ip

- --80041404B0 IE Insp Rept 50-261/80-01 on 800204-07 Noncompliance noted failure to have & foilou uritten approved procedures for radiochemical measurements
 JENKINS. G R Region 2. Atlanta, Fuel Facility & Materials Safety
 Branch MONTGOMERY. D M Region 2. Atlanta, Office of the
 Director 80/02/22 Spp
- B004i500A7 Forwards IE Info Notice 80-13. "GE Type SBM Control Suitches Defective CAM Followers ' No specific action or response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240245 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required D'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/04/02
- E3004180378 Forwards IE Circular 80-07, "Problems W/MPCI Turbine Dil Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 200
- GO04230117 Forwards IE Bulletin 79-03A 'Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/04 ip
- E004180340 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Hritten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 2pp
- E3004250251 Ack receipt of 800320 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-261/80-03 STOHR. J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/04/09 to
- ---8004250261 Responds to ARC 800227 ltr re violations noted in IE Insp Rept 50-261/80-03 Corrective actions acid & battery removed Shipping container reinspected & resealed for shipment Labeled containers of radioactive mat1 STARKEY, R B Carolina Power & Light Co 80/03/20 3pp
- ---8004250275 Forwards IE Insp Rept 50-261/80-03 on 800204-06 & notice of violation STORR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/27 2pp
- --8004250282 Notice of violation from insp on 800204-06 * Region 2, Atlanta, Office of the Director 80/02/26 ip
- ---B004250291 IE Insp Rept 50-261/80-03 on B00204-06 Noncompliance noted failure to properly label containers of radioactive matl & to follow procedures
 OIBSDN.A F Region 2. Atlanta, Fuel Facility & Materials Gafety
 Branch PUCKETI, J M , WRAY, J R Region 2. Atlanta, Office of the
 Director B0/02/26 opp
- R Periodic operating reports & related correspondence
- 81-004040305 Forwards "Annual Environ Surveillance Rept, 1979 " STARKEY. R B Carolina Power & Light Co 80/03/31 ip
- SOO4150374 Forwards monthly operating rept for Har 1980 STARKEY,R B Carolina Power & Light Co 80/04/09 1
 - 3004150376 Monthly operating rapt for Mar 1980 WATFORD,M L Carolina Power & Light Co 80/04/01 3pp
 - Reportable occurrences. LERs & related correspondence
- EDO4080361 PNG-II-80-044 on 800314, reactor shut down for regain of primary-to-secondary steam generator leak During outage, 480-volt power transfer switch operated, causing loss of power to half of ECCS valves Cause under investigation HARDIN, A. K. KELLG90, P. J. Region 2, Atlanta, Office of the Director 80/03/17 1p
- BOQ4030171 RO on 800324, determined that potential generic problem could exist in Hestinghouse relay Model NBFD-315 Three relays have exhibited coil failures due to shorting of lead-in wires Hestinghouse is investigating problem STARKEY, R B Carolina Power & Light Co 80/03/24 1p

- 8004100340 Forwards LER 80-006/01T-0 BTARKEY, R B Carolina Power & Light Co 80/04/04 ip
- --8004100345 LER 80-006/017-0 on 800324, w/plant at cold shutdown for steam generator maint, three relay coils in B train found failed & one coil found contacting ground in B battery bus Caused by shorting of outer layer of coil windings STARKEY, R B Carolina Power & Light Co 80/04/04 2pp
- 8004180418 Forwards LER 80-004/03L-0 STARKEY, R B Carolina Power & Light Co 80/04/14 1p
- --8004180425 LER 80-004/03L-0 on 800316.u/facility shut down u/primary sys at 350 psig & 250F in RHR recirculation mode.loss of power to all MCC-5 & 10 loads occurred Caused by overcurrent trip of MCC-9 main power transfer switch Settings reset STARKEY.R B Carolina Power & Light Co 60/04/14 4PP
- 8004230520 Forwards LER 80-005/03L-0 STARKEY,R B Carolina Power & Light Co 80/04/19 ip
- --8004230525 LER 80-005/03L-0 on 800320 during cold shutdown while performing PT 42 0, valve CCW-626.RCP thermal barrier outlet containment isolation valve failed to close Caused by loose locknut Nut tightend & staked STARKEY.R B Carolina Power & Light Co 80/04/19 2pp
- 8004240342 Forwards LER 80-007/03L-0 STARKEY, R B Carolina Power & Light Co 80/04/21 ip.
- --8004240366 LER 80-007/03L-0 on 800326, data from previous instrument calibr identified that first stage pressurs transmitters PT-446 & PT-447 on turbine were found out of calibr nonconservatively Caused by instruments drifting high STARKEY, R B Carolina Power & Light Co 80/04/21 2pp
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

 F. Security, medical, emergency & fire protection plans
- 8004070223 Submits results of drywell safe shutdown analysis required by NRC 790829 fire protection safety evaluation No add1 fire protection provisions needed During normal operation drywell inerted w/nitrogen/reducing oxygen & combustion possibility MAYER, L Q Northern States Power Co 80/03/31, 2pp
- 8004080508 Submits design info for installation of sprinklar curtain to cool hot gases entering cable tray area in water treatment & engineered safety feature motor control ctrarea.ss discussed in fire protection safety evaluation MAYER: L O Northern States Power Co 80/04/01 3pp
- 8004080368 Forwards design info re mod to cable spreading room, standby gas treatment sys room, switchgear areas, intake structures & motor generator set room, as required by NRC 790829 fire protection SER MAYER, L.O. Northern States Power Co. 80/04/02 1p
- BOO40BO479 Forwards security plan.Revision 9 pages Encl withheld (ref 10CFR2 790) MAYER.L.D. Northern States Power Co. BO/04/03 1p
- 8004180357 Forwards "Evacuation Time Estimates" in response to NRC 791129 ltr MAYER, L. O. Northern States Power Co. 80/04/10 ip
- ---B004180360 "Evacuation Time Estimates "
 * Northern States Power Co. B0/04/30 18pp.
- 8004230387 Forwards input for fire protection review. Items 3 1.8(5 & 6) & 3 2 2(1), fire barriers/penatration seals & Item 3 1 12(2), yard loop Recommends approval of licensee submittals recriteria & test procedures & proposed mods HALL, R E Brookhaven National Laboratory 80/04/14 3pp.
- O Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK, V Office of the Executive Director for Operations

- P. Operating license stage documents & correspondence
- 0004070777 Discusses NRC 75112 | request that All LVR licensees assess higher fission gas release for fuel burnups above 20.000 MM day per metric ton Responses indicate that no immediate licensing action is required.

 1PPOLITHEA A Special Manacters Branch J. 00/09/10. 3pp
- U004030102 forwards "Nuclear Data Link Operation of digital communication sys to transmit info from plants to Bethesda Operations (tr (THENNOTED O Division of Operating Reactors DD/03/12 Spp.
 - 00040 l0110 "Nuclear Data Link Upers"
 # Division of Operating Reactors (82/02/21 20pp
- 0004070.178 forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics into docton incident or abnormal occurrence at facility Region % Chicago, Office of the Director 00/03/19 KLPPLLR, J. Q. Opp
- 8004100100 Requests controlled set of PADs for each plant Dubmittal should be forwarded to attention of Region (finished) to sponse cts within 20 days (EPPLIE.) O Beginn t. Chirago. Office of the Director (80203740)
- BOOM1000'F/ Incompands "Isolination of Licensee (empliance M/Category A Items of NHC Recommendations Resolting IIII & Leanus Learned " All Category A requirements satisfactorily met Node will be verified by II IPPOLITHEY A Operating Resitors Branch 1 10/01/21 Lipp.
- 10004040319 Advises that most of reactor protection systampply protective circuiting will be performed when qualified equipment is available from QI MAYER.(, () Northern Blates Power (o. 199701736 ip
- EUCAOHO400 Notifies that piping supports between automatic pressurs tells valve accomplator (beth valves & valve operators will be upgraded to correct between Class 1 criteria prior to startup following correct refueling outage [LIADHR: 1 B. Northern fitates Power (b. 1070,1740) tp
- 10040B0.F.G Notifies of revised schedule for installing containment penetrations for recombines a frigural Feb 1900 schedule not met due to problems developed w/containment (solution valves Addl design & febrication work required MAYIBLE O. Morthern States Flower Co. 180204701 tp
- BODE-200021 Forwards HBH-21 & 0211 Itrs to GI is proposed control rod drive sys mode related to elimination of cracking in return line northes Consectines for mode will be discussed to MMHO 0A19, to be issued in "for Comment form in Apr 1980 IPPO ITO. T.A. Specialing Resistors Street for I 09/04/07 2pp
- il Inspection reports, li Bulletina & correspondence
- 8004040405 forwards II Insp Rept 50 25'000 03 on 800114 No noncompliance noted Fighttiig Hegion J. Chicago, Beartor Construction & Engineering Copport Branch - 80702/16 - Jpp Uupport Branch
 - 8004040410 th thep Rept 50 JAI/IIO Of an 400114 An nuncompliance noted Hajor areas inspected actions so II Butistin 79 14-general discussion of ABC requirements procedure review A review of stress calculations DANILLEON, I T. Region 3, (hitago, liftice of the Director 160702/11 Dpg
- 8804100143 Forwards II. Info Notice 80 OH, 'Ntates Co Stading Link Clastrical Yerminal Block " He specific artion or response required REPPLEATION Region T. Chicago: Office of the Director - 00/03/07
- 00040B0A37 Forwards If Insp Rept BO 2APAN BION 000204 OB & notice of violation Notice of violation withheld less 100182 7901 HIND-U A. Region D. Chicago: Baseguards Branch 0070J/18 2pp
- ---B0040D0640 IF Insp Rept 30 261/80-01 on H00204-6H Nondompliance noted inadequary in area of physical barriers Details withheld (ref 100782 790) HIND. J.A. Region D. Chicago, Safeguards Branch. USTICK, CHRISTOPPER, O. Region J. Chicago, Sefece of the Director 80/03/05. Rep.

- 8004150184 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31
- 0004080719 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating 811 Addition & Onsite Supply " No written beriuper negotred
 - KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/01
- U004190092 Forwards IC Info Notice 80-13. "GE Type SBM Contro) Switches Defective CAM Collowers " No specific action or response tenutred
- KEPPLER, J G Region 3, Chicago, Office of the Director 80704702
- 8004180055 Forwards attachments to IE Circular 80-03, "Protection From Toxic Qas Haiards," inadvertently emitted from 800306
 - transmittal KCPPLER,J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220148 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/04/02
- 80042203/8 Forwards IC Circular 80-07, "Problems W/HPCI Turbine Oil 1042037H Furwards 12 office of the Director 80/04/03 Hys "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 800411004/ Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Hritten response required KLPPLER, J O Region 3: Chicago, Office of the Director 80/04/07
- HD04230277 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME BA-312.Type 304 Stainless Steel Pipe " Action required KCPPLCR.J Q Region 3. Chicago, Office of the Director 80/04/07
- 6004220047 Forwards II Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLFR.J G Region 3. Chicago. Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004150401 Forwards monthly operating rept for Mar 1980 MAYLR.L O Northern States Power Co 80/04/10 ip
- 8004150405 Monthly operating rept for Mar 1980
 HYRASO, A L. Northern States Power Co. 80/04/04 4pp
- B Reportable occurrences, LERs & related correspondence
- 8004220247 PND-77-033 on 770223, during reactor startup period of less than 5-s was obtained before reactor tripped on lowest level intermediate range Caused by combination of temp & high senon concentration OCWER, O C . ROY, O W THO Director 77/02/25 2pp THOMPSON, D. Region 3. Chicago, Office of the
- GOO4010472 Forwards LER 8D-015/01T-0 MAYER, L D Northern States Power Co 80/03/27 ip
- ---8004010455 LER 80-015/01T-0 on 800317 during refueling outage & insprequired by IE Bulletin 79-01B, unqualified splices found in power cables for inboard MBIV sciencid valves Cause not stated Eplices replaced w/qualified matls HAMMER.M F Northern States Power Co 80/03/27 ip
- 8004130543 Forwards LERs 80~002/01T-0,80~003/01T-0,80~004/01T-0, 80~005/01T-0,80~008/01T-0,80~009/01T-0,80~010/01T-0, 80 012/01T-0 & 80~014/01T-0 HAYER.L 0 Northern States Power Co 80/04/08 1p
- --B004150555 LER 80-002/017-0 on B00225, during refueling outage, local leak rate for A0-2-B6A outboard MSIV exceeded Tech Spec acceptance criteria Caused by poppet not seating properly Poppet machined & stem replaced OVERLID.T H Northern States Power Co B0/04/08 19

- --BC04150554 LER 80-003/017-0 on 800225, during refueling outage, local leak rate for A0-2-050 outboard MSIV, exceeded Tech Spec acceptance criteria Caused by lapping of main seat so that popped did not seat propertly Popped rachined OVERLID T W Northern States Power Co 80/04/09 lp
- --8004150571 LER 80-004/01T-0 on 800223, during local leak rate testing.

 HPCI-9 turbing eshaust line check valve found leaking in
 escess of Toch Spec acceptance criteria Caused by leakage
 past body-to-seat ring threaded joint
 SHURTS.S J Northern States Power Co 80/04/08 1p
- ---B004150599 LER 80-008/01T-O on B00303.during local leak rate testing, A0-2876 torus vent isolation valve found leaking in excess of Tech Spec acceptance criteria Cause undetermined Valve disabse-bled, inspected, cleaned & reassembled SHURTS, S J Northern States Power Co 80/04/08 Ip
- --8004150598 LER 80-009/01T-0 on 800306.during refueling outage, local leak rate for RCIC-9 turbine exhaust check valve, exceeded Fach Spec acceptance criteria Probably caused by downstream check valve jacked shut for test Valves lapped & retested SHURTS.S J Northern States Power Co 80/04/08 ip
- --B004150610 LER B0-010/01T-0 on B00324, during local leak rate testing, CV-7956 torus instrument air isolation valve found leaking in excess of Tech Spec acceptance criteria Apparently caused by dirt on seat Valve cleaned & reassembled IVERSON.O N Horthern States Power Co 80/04/08 ip
- ---B004150617 LER 80-012/01T-0 on 800307, during local leak rate testing.
 AD-2561A drywell equipment drain sump isolation valve found leaking in excess of Tech Specs Caused by packing leak Packing tightened
 HINDSCHILL.J E Northern States Power Co 80/04/08 ip
- --8004150623 LER 80-014/01T-O on 800314, during refueling outage, local lask rate for A0-2-80A inboard MSIV exceeded Yech Bpec acceptance criteria Caused by poppet not seating properly New poppet & stem installed OVERLID.T W Northern States Power Co 80/04/08 ip
- B004140370 Responds to NRC B00110 ltr requesting update of control rod drive sys malfunctions through 1979 Two drives stopped at position 02 during 1978 & 1979 Caused by stop piston seal leakage Drives removed & rebuilt during feel outages MAYER.L O Northern States Power Co 80/04/09 2pp
- 8004140431 Forwards LER 60-016/01T-0 MAYER.L 0 Northern States Power Co 80/04/10 1p
- --8004140437 LER 80-016/017-0 on 800327.during refueling, supports for SRV pheumatic supply sys would not meet seismic Class I requirements Caused by inadequate design & installation of sys Sys was upgraded to satisfy requirements

 OVERLID.T H Northern States Power Co 80/04/10 ip
- E004180468 Forwards LER 80-017/01T-0 MAYER,L 0 Northern States Power Co 80/04/11 19
- --8004180472 LER 80-017/01T-O on 800328, Bechtel Power Corp notified util that control rod driveline hydraulic piping frame supports would not meet OBE stress limits Caused by EDS computer code error Supports modified DAY.8 D Northern States Power Co 80/04/11 ip
- DDCKET 50-264 DOW CHEMICAL CO
- P Operating license stage documents & correspondence
- B004220533 Advises that Section 316 documents re NNPDES Permit AL0022080 are being sent to JW Warr.H Zeller & LB Tebo, in accordance w/util 800331 ltr EL-ASHRY.M T Tennessee Valley Authority 80/04/17 2pp

- DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- B004240531 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimilie traffic KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/20 200
- 8004070272 Forwards input to facility fire protection review for fire detection systwater suppression sys & foam suppression sys Info completes items for which adequate licensee input exists
 HALL, R E Brookhaven National Laboratory 80/03/31 5pp
- 8004070273 Forwards Pages C-24 & C-27 of Revision 5 to security plans, omitted from 800324 submittal Encl withheld (ref 10CFR2 770)
 PEOPLES D L Commonwealth Eduson Co 80/04/02 ip
- 8004230524 Forwards revisions to 800331 ltr re fire protection review, Item 3 1 1.fire detection sys. Item 3 1 5.water suppression sys. & Item 3 1 6.foam suppression sys. & Item 3 1 6.foam suppression sys. MALL, R E Brookhaven National Laboratory. 80/04/16 5pp
- BOO4230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790) PEDPLES, D L Commonwealth Edison Co 80/04/21 1P
- P Operating license stage documents & correspondence
- 8004080276 Forwards corrected Pages 88 % 93 for Licenses DPR-19 Amend 44 % DPR-25 Amend 39 % corrected Pages 3 6/4 6-2 % 3 6/4 6-9 for Licenses DPR-29 Amend 53 % DPR-30 Amend 50 in response to 791002 ltr IPPDLITO, T A Operating Reactors Branch 3 80/02/20 2pp
- --8004080310 Corrected License Pages 88 & 93 for Amends 44 & 37 to Licenses DPR-19 & DPR-25, respectively & corrected License Pages 3 6/4 6-2 & 3 6/4 6-9 for Amends 53 & 80 to Licenses DPR-29 & DPR-30, respectively * Operating Reactors Branch 3 80/02/20 8pp
- 80040703B1 Discussos NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MH-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO T A Operating Reactors Branch 3 80/03/10 3pp
- BOO4030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT, D O Division of Operating Reactors BO/03/12 Spp
- ---9004030118 "Nuclear Data Link Specs "
 # Division of Operating Reactors 80/02/21 28pp
- 8004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days

 KEPPLER. J G Region 3. Chicago. Office of the Director 80/03/20 lp
- 8004100313 Natification of 800325 meeting w/util & OE to discuss damonstration bundles BEVAN R Operating Reactors Branch 3 80/03/21 2pp
- 8004150316 Forwards revised pages constituting Revision IG to CE-1-A, GA program Revisions reflect recent organization title changes
 NAUGHTON.W F Commonwealth Edison Co 80/04/02 ip
- ---800419032B Revised pages constituting Revision 13 to QA program Revisions reflect recent organizational title changes.

 * Commonwealth Edison Co CE-1-A RI3 80/04/04 7pp.
- 8004180217 Forwards addl info re failure of control rods to insert fully on scram in response to NRC 800110 & 11 ltrs. Dresden 1 experienced no control rod failures in 1978-79 Failure at other facilities caused by leakage past worn piston smals. JANECEK.R F Commonwealth Edison Co 80/04/14. 10pp

- 8004250427 Forwards response to NUREG-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lasalle County site-specific emergency plan PEOPLES, D L Commonwealth Edison Co 80/04/15 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004240412 Advises of review & plans re reload core Forwards Table 1 providing summary of key parameters W/approval of Amend 51 to DPR-30, util concludes that addl Tech Spec changes not required Reload core design will be verified by std tests PEOPLES, D L Commonwealth Edison Co 80/04/17 4pp
- G Inspection reports, IE Bulletins & correspondence
- 8004040029 Forwards IE Insp Repts 50-254/79-30 & 50-265/79-28 on 791211-14 No noncompliance noted DAVIS, A B Region 3, Chicago, Fuol Facility & Materials Safety Branch 60/02/12 2pp
- --B004040034 IE Insp Repts 50-254/79-30 & 50-265/79-28 on 791211-14 No noncompliance noted Major areas inspected licensees data, repts & experience in meeting design objective gaseous release rate for radiolodine & radiactive mat!
 HUETER, U J Region 3, Chicago, Office of the Director FIBHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/06 Spp
- 8004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted DAVIS.A D Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DOT labeling POTTER, J P Region 3, Chicago, Fuel Facility & Materials Safety Branch 80702/22 6pp
- 8004100192 Forwards IE Insp Repts 50-254/80-03 & 50-265/80-05 on 800115-16 & 0211 No noncompliance noted FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8004100207 IE Insp Repts 50-254/80-03 & 50-265/80-05 on 800115-16 & 0211 No noncompliance noted Major areas inspected torus support GA/GC program, procedures, work activities & feedwater sys welds
 DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch WARD, K D Region 3, Chicago, Office of the Director 60/02/25 9pp
- 8004080617 Forwards IE Insp Repts 50-254/80-01 & 50-265/80-02 on 800102-0201 No noncompliance noted. HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/27 2pp
- --8004080625 IE Insp Repts 50-254/80-01 & 50-265/80-02 on 800102-0201 No noncompliance noted Major areas inspected maint plant operations, physical protection & followups BPESBARD, R L . CHRISBOTIMOS N Region 3, Chicago, Office of the Director 80/02/25 7oo
- 8004280020 Forwards IE Insp Rept 50-265/80-07 on 800130-31 No noncompliance noted FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/03/06 2pp
- --8004280025 IE Insp Rept 50-265/80-07 on 800130-31 No noncompliance noted Major areas inspected IE Bulletin 80-02, inadequate QA for nuclear supplied equipment & examination of GE replacement feedwater spargers DANIELSON.D H Region 9. Chicago, Reactor Construction & Engineering Support Branch KEY, W. J Region 3. Chicago, Office of the Director 80/02/27 3pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/03/07 in
- 8004140119 Forwards response to IE Bulletin BO-OS, "Loss of Charcoal from Std Type II.Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES, D L. Commonwealth Edison Co 80/03/20. Spp.

- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.A Il Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/03/21 tp
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A, on 791212-13 No noncompliance noted DAVIS.A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- ~-8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels, removable contamination & package external features POTTER, J P Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- 8004150159 Forwards IE Info Notice BO-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary XEPPLER.J G Region 3. Chicago, Office of the Director BO/03/3t
- 8004080696 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Bupply " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01
- 8004150014 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220324 Forwards IC Circular 80-07, "Problems W/HPCI Turbine 0:1 Bys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- B004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/04/09
- 8004110025 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure "Written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/07
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 8A-312.Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07 to
- 8004280628 Forwards revised Pages 3 & 5 % omitted Page 4 to IE Insp Repts 30-010/80-05,50-237/80-05,50-249/80-05,50-254/80-05 & 50-245/80-08 FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/09 ip
- --8004280634 Revised Pages 3 & 5 & omitted Page 4 to 1E Insp Repts 50-010/80-05, 50-237/80-05, 50-249/80-05, 50-254/80-05 & 50-265/80-08 * Region 2. Atlanta, Office of the Director 80/04/09 3pp
- R Periodic operating reports & related correspondence
- B004150004 Forwards "Radioactive Waste & Environ Monitoring.Annual Rept.1979 " Rept constitutes Part 3 of facility operating rept KALIVIANAKIS,N Commonwealth Edison Co 80/03/04 1p
- --B004150007 "Radioactive Waste & Environ Monitoring Annual Rept,1979, "
 * Eberline Instrument Corp 80/03/31 91pp

- 220333 Forwards listing of changes tests & experiments performed in LIVIANAKIB, R Commonwealth Edison Co 80/04/14 5pp
- eportable occurrences. LERs & related correspondence
- 080573 Updated PNO-III-80-045B licensee ultrasonic examination of re spray piping in A & B loops located in drywell mpleted Piping will be replaced w/low carbon stepl pipe RRESOTIMOS.N. SPESSARD.R L Region 3. Chicago, Office of the rector BO/03/14 2pp
- 020435 Forwards supplemental LER 79-009/03L-1 LIVIANAK15.N Commonwealth Edason Co E0/03 LIVIANAKIS, N
- 104020443 Supplemental LER 79-009/03L-0 on 790429, while measuring MSIV limit switchtrip position.13 of 16 switches were set at greater than 10% of MSIV closure Caused by failure to field calibre vant limit switch trip point Switches adjusted VAHRENWALD, J Commonwealth Edison Co 80/03/17 2pp
- iO30110 PND-1]I-80-051 on 800314.ultrasonic testing performed on) jet pump holddown beam assemblies at Unit 3 Pumps 5.9.11 5 20 beam indications ranged from greater than 6 ls to approx 20 mils Pump w/largest indication removed RISSOTIMOS.N., SARKER, J.L., SPEESARD, R.L. Region 3, Chicago, fice of the Director 80/03/17 ipp
- 020392 Forwards LER 80-006/01T-0 LIVIANAKIS.N Commonwealth Edison Co 80/03/22 ip
- 104020399 LER 80-006/017-0 on 800308.while performing reactor vessel pressure test, several crack indications were discovered in pipe to elbow welds Cause not determined Affected pipe sections will be replaced w/carbon steel piping CLARK, D Commonwealth Edison Co 80/03/22 7pp
- 020430 Forwards LER 80-005/03L-0
 *LIVIANAMIS.N Commonwealth Edison Co 80/03/24 in
- 104020445 LER E0-005/03L-0 on 800303 while performing LPCI & containment cooling modes of RHR9 logic test.5-s delay timer 10A-H2A for 102B RHR pump failed to actuate relay K21A Relay failes to energize Caused by microsuritch drift HAFERA,T Communwealth Edison Co. 80/03/24 2pp
- 150492 Forwards LER 80-008/03L-0 LIVIANAKAB.N Commonwealth Edison Co 80/03/26 1p
- 304150498 LER 80-008/03L-0 on 800305, while performing LPCI & containment cooling modes, two 5-8 delay timers for starting 1002D RNR pump failed to actuate timer contacts Caused by microswitch arm being out of alignment HOELLER, J Commonwealth Edison Co. 80/03/26 2PP
- 1220613 Forwards LER 80-007/03L-0
 LIVIANAKAS,N Commonwealth Edison Co 80/04/09 In
- 204220623 LER 80-007/03L-0 on 800316. while ultrasonically inspecting Jet pump fixture beam assemblies one through 20, midth-wise crack indication discovered along upper surface of pump 16 near bolt Gaused by intergranular stress corrosion MURRAY. R. Commonwealth Edison Co BO/04/09 3pp
- 1270380 Forwards LER 80-009/03L-0 LIVIANAKIB,N Commonwealth Edison Co 80/04/21 1g
- 104290407 LER BO-009/03L-O on B00322, while performing PCI simulated automatic closure initiation test, procedure GDS 1600-13, transient in-core probe 2. falled to respond to Group 2 isolation signal Caused by dirty contacts on relay K21 REED, M Commonwealth Edison Co BO/04/21 ip
- KET 50-266 POINT BEACH NUCLEAR PLANT, UNIT I Becurity, medical, emergency & fire protection plans
- 4080224 Forwards operating instructions & characteristics of NRC salth physics telephone network Purpose of network is ransmission of health physics info during incident or
- rnormal occurrence

 PPLER, J G Region 3, Chicago, Office of the Director

- 8004010336 Forwards five protection review Items 3 1 17,3 1 25,3 2 2 & 3 2 6 Licensee proposed mods to hydrogen sys & reactor coolant pump oil collection sys are only partly acceptable NRC should request drawings re mods proposed in Item 3 2 2 HALL.R E Brookhaven National Laboratory 80/03/26 5pp
- B004020410 Forwards estimates of evacuation times for area surrounding plant, per NRC 791129 ltr request FAY, C W Wisconsin Electric Power Co 80/03/26 7pp
- 8004290428 Responds to 800305 ltr re status of NRC review of plant firs protection program List re status of resolution of incomplete items encl BURSTEIN.S Wisconsin Electric Power Co 80/04/21 2pp
- G Adjudicatory correspondence
- 8004010389 Protests licensees failure to serve filings re steam generator tube degradation Roiterates request for relief as stated in 800226 ltr & requests NRC to direct licensee to States in overe it? a requesta the confict of the serve documents
 FALK.K M Wisconsin's Environmental Decade 80/03/27 2pp
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness; distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004230010 Forwards Ofc of Nuclear Reactor Regulation 800404 order requiring that testing be performed within 90 effective full power days Health & safety will not be endangered by continued operation 8CHWENCER, A Operat Operating Reactors Branch 1 BO/04/04 2pp
- ---8004230014 Mod of 791130 order deleting & replacing Condition 1 of Section IV Testing must be performed within 90 effective full power days Health & safety will not be endangered by order remaining in effect Safety evaluation end CASE/E G Office of Nuclear Reactor Regulation 80/04/04 5pp
- --8004230017 Safety evaluation re steam generator tube degradation due to deep crevice corrosion Continued safe operation may be permitted within confirmatory order terms * Office of Nuclear Reactor Regulation 80/04/04 17pp
- I Financial information
- 8004290418 Forwards Annual Financial Rept 1979 & certified financial GORTSCH. J H Wisconsin Electric Power Co 80/04/22 19pp
- --8004290425 Annual Financial Rept 1979 MCNEER,C Wisconsin Electric Power Co 80/03/14 33pp
- P Operating license stage documents & correspondence
- 8004040123 Notifies that description of QA program is App H to final description & SAR FAY.C W Wisconsin Electric Power Co 80/02/25 2pp
- 8004140087 Finds actions taken to repair inspect & test cracking found in feedwater sus piping adequate until recommendations of owners group & NRC Pipe Crack Study Group have been evaluated Safety analysis ancl. 8CHWENCER.A Operating Reactors Branch 1 80/02/25 App
- 9004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENMUT.D 0 Division of Operating Reactors 80/03/12 Spp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004300276 Forwards Amends 42 & 47 to Licenses DFR-24 & DFR-27, respectively, safety evaluation & notice of issuance & availability SCHWENCER: A Operating Reactors Branch i 80/03/19 2pp
- --8004300280 Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively, modifying Tech Spec qualification requirements for radiation protection manager SCHHENCER.A Operating Reactors Branch 1 80/03/19 7pp

- --8004300285 Bafety evaluation supporting Amends 42 \$ 47 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation 80/03/19 2pp
- --80043002B7 Notice of issuance & availability of Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively SCHWENCER, A Operating Reactors Branch 1 80/03/17 2pp
- 8004100172 Requests controlled set of P&IDs Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days KEPPLER.J Q Region 3. Chicago. Office of the Director 80/03/20
- B004020326 Discusses Event 5 valve configurations at facilities in response to NRC 800223 request Valves will be verified properly closed by combination of periodic testing & observation Sketch showing valve configurations encl FAY, C W Wisconsin Electric Power Co 80/03/21 3pp
- 8004010319 Responds to 800107 ltr re GA requirements for diesel generator fuel oil Adequate controls to assure quality of fuel oil are being implemented FAY.C W Wisconsin Electric Power Co 80/03/24 2pp
- B004240096 Provides info to clarify further NRC position re containment isolation (Section 2 1 4 of NUREG-0578) All plants required to have double isolation barriers w/o need for operator action Plant does not meet position on two penetrations SCHWENGER, A Operating Reactors Branch 1 80/04/03 Spp
- 8004280273 Forwards Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability SCHMENGER, A Departing Reactors Branch 1 80/04/03 2pp
- -8004280299 Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively, making minor changes to Tech Specs & approving revised organizational structure SCHHENCER; A Operating Reactors Branch 1 80/04/03 Sipp
- --8004280301 Bafety evaluation supporting Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation 80/04/03 2pp
- --8004280304 Notice of issuance & availability of Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively 8CHMENCER, A Operating Reactors Branch 1 80/04/03 2pp
- 8004300497 Confirms schedule arranged by NC Choules re 800408 meeting at site to discuss regulatory performance of facility KEPPLER.J O Region 3. Chicago, Office of the Director 80/04/07 ip.
- BO04220475 Notifies of changes to undervoltage relaying for protection against degraded grid voltage on 4160 volt safeguard busses Action responds to NRC request to uggrade circuitry upon review of facility 790824 & 1012 & B00117 ltrs
 FAY.C.W Wisconsin Electric Power Co B0/04/17 2pp

G Inspection reports, IE Bulletins & correspondence

- 8004ii0230 Forwards IE Insp Repts 50-266/80-02 & 50-301/80-01 on 800122-24 No noncompilance noted HEISHMAN.R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/05 2pp
- --8004110245 IE Insp Repts 50-266/80-02 & 50-301/80-01 on 800122-24 No noncompliance noted Major areas inspected plant operations organization & administration, GA review audits & records WARNICK, R.F. NRC Regional Offices HAQUE, R.L. SMITH, J.D. Region 3, Chicago. Office of the Director 80/03/04 5pp
- BOO4070206 Bubmits status rept of stress analysis & pipe support review as of BO0227, in response to IE Bulletin 79-14 Analysis has been completed for 52 drawings & pipe supports evaluated for 26 pipe lines.

 FAY: C W Wisconsin Electric Power Co 80/03/07 6pp.
- 8004100149 Forwards IE Info Notice 80-08, "Btates Co Bliding Link Electrical Terminal Block " No specific action or response required.

 KEPPLER.J Q Region 3, Chicago, Office of the Director 80/03/07.

- 8004090353 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment Master list enci compiling all sys required to function under postulated LOCA or high energy line break accident FAY.C W Wisconsin Electric Power Co 80/03/12 12pp
- B004240449 Ack receipt of NRC B00310 ltr transmitting IE Info Notice B0-10 re Crystal River Unit 3 incident Notice will be reviewed by util nuclear projects ofc personnel & by plant supervisory personnel Rosults will determine further action FAY.C W Wisconsin Electric Power Co B0/03/24 1p
- 8004240419 Responds to IE Bulletin 80-03, "Loss of Charcoal from 5td Type II.Two-Inch.Tray Adsorber Cells" Lists number.sys & manufacturer Containment purge sys cell had loose strip securing screen to frame Next insp scheduled for Apr FAY.C M Wisconsin Electric Power Co 80/03/26 2pp
- 8004010223 Submits results of steam generator inspirequested in 791130 order Requests written concurrence that tests are acceptable so that unit may be returned to syc List of tubes plugged & description of QA program encl
 BURSTEIN.S Misconsin Electric Power Co 80/03/28 8pp
- 8004190194 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31
- 8004080727 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/01
- 8004i50059 Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEFPLER, J G Region 3. Chicago. Office of the Director 80/04/02
- 8004180065 Forwards attachments to IE Circular 80-03, "Protection From Taxic Gas Hazards," inadvertently emitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220198 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220392 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required KEPPLER, J O Region 3, Chicago, Dffice of the Director 80/04/03 1p
- 8004230288 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07
- 8004220083 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/04/09 1p
- S Reportable occurrences, LERs & related correspondence
- 8004020333 Forwards LER 80-002/017-0 FAY, C W Wisconsin Electric Power Co 80/03/25 Ip
- --8004020344 LER 80-002/01T-0 on 800311.during shutdown 800 psi secondary-to-primary hydrostatic leak test of B steam generator revealed tube R23C44 leaking, tube RBC37 wet & plug end R23C50 wet Tube holes will be weld plugged FAY,C W Wisconsin Electric Power Co 80/03/25 5pp
- BOO4290307 Forwards LER 80-003/03T-0 FAY, C W Wisconsin Electric Power Co B0/04/16, ip
- --8004290310 LER 80-003/03T-0 on 800318; during post-mod testing of containment spray sys, relay 1CSB would not latch. Caused by latching mechanism misalignment Latch adjusted & proper operation verifited on 800318 Similar relay bench tested FAY.C W Wisconsin Electric Power Co 80/04/16 % Rpp

4290298 Forwards updated LER 80-002/017-1 AY,CH Hisconsin Electric Power Co 80/04/17 1p

004270306 Updated LER BO-OOR/017-01 on 800311 during 800 psi secondary to primary hydrostatic I wak test, tubes 823044 & 88037 & plug end 823030 found leaking Eddy current insp performed Tube holes & loaking explosive plugs were plug welded FAY.C W Wisconsin Electric Power Co 80/04/17 7pp

Congressional/Executive Correspondence

4140374 Responds to M Charlier 800107 ltr requesting facility hutdown until completion of needed repairs Inspectes & tenating limits increased to assure public health & safety ollowing problems w/steam generator tube degradation IRCKS.N J Dffile of the Executive Director for Operations 7/02/21 ip

304140379 Forwards M Charlier B00107 Itr requesting that facility be shot down until needed repairs are completed PROXMIRE. W Senate BO/O1/17 2pg

1140294 Forwards NRC 800104 ltr to J Estes, in response to 791213 iquest If requested Lakeshore Citizens for Safe Energy will included in future meetings are steam generator condition RCKG.H J Office of the Executive Director for Operations 1/03/25 ip

ET 90-26/ FORT ST VRAIN NUCLEAR GENERATING STATION lecurity, modical, energency & fire protection plans

OROGGY Forwards evaluation of emergency planning rone distances per IREO-OSY6 guidelines Requests emergency planning ne & ingestion pathway be established at 5 & 30 miles, apoctively REMBGURO, D Public Gervice Co of Colorado BO/O4/01 27pp

djudicatory correspondence

240512 Forwards NRC confirmatory order ELLD, V Diffice of Inspection & Enforcement, Office of the ractor $-80/04/04-1\rho$

04240514 Drder confirming util commitment to perform review requested by IE Bullatin 79-27 by 800425 Required info specified in Attachment A STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/04 App

inancial information

RECOTTS Forwards Annual Financial Rept 1979
REMBOURD D Public Service Co of Colorado 80/04/14 19

14220778 Annual Financial Rept 1979
Public Service Co of Colorado 80/02/07 43pp

Parating license stage documents & correspondence

170286 Represents that util motification to NRC refuel particles C sicroperoxity was timely. Bases opinion on info ginally presented to util by GA Co & in-reactor formace of fuel to date LER. J K Public Service Co. of Colerado 80/03/04 2pp

10490 Advises that QA grogram implementation differs slightly from codures stated in FBAR I terms are not safety significant onto represent unreviewed safety question QA program rite will be included in updated FSAR Y.H.L. Public Service Co. of Colorado 80/03/24 ip

spection reports. IE builetins & correspondence

40128 Forwards IE Insp Rept 50-267/80-01 on 791231-800131.notice violation & notice of deviation SEN.G.L Region 4, Dallas, Reactor Operations Nuclear Support nch 80/02/19 2pp

4040133 Notice of violation from insp on 791231-800131 Region 4: Dallas, Office of the Director 80/02/15 ip

4040135 Notice of deviation from insp on 791231-800131 Region 4. Dallas, Office of the Director. 80/02/15 ip ~-8004040140 IE Insp Rept 50-267/80-01 on 791231-800131 Noncompliance noted failure to meet diesel fuel tank Tech Spec capacity limits & deficiency re electronic surveillance testing procedures

MESTERMAN, T F . COLLINS, R E . SMITH, R Region 4, Dalles, Office of the Director 60/02/15 9py

8004080600 Forwards IE Insp Rept 50-267/80-04 on 800211-12 No honcompliance noted MADSEN,O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/25 2pp.

~~8004080602 IE Imag Rept 50-267/80-04 on 800211-12 No noncompliance noted Major areas inspected review of licensee performance history & meeting w/licensee mgt
WESTERMAN,T F. DICKERSUN,M W. Region 4, Dallas, Office of the Director MADSEN,G L. Region 4, Dallas, Reactor Operations
Nuclear Support Branch 80/02/25 App

B004240469 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Review & analysis of four instrument buses progressing No violations of basic design criteria found SWART.F E Public Service Co of Colorado BD/02/27 ip

Q004210354 ADvises that util will not be able to keep commitment made per 800227 telcon re partia; response to IE Bulletin 79-01B Communication problems have made info inaccessible Submittal will be made within next 14 days
SHART.F E Public Service Co of Colorado 80/03/04 ip

8004030(30 Forwards Category I inservice insp & testing program submittais re helium circulator & secondary coolant sys FULLER.J K Public Service Co of Colorado 80/03/31 3pp

~-8004030131 Inservice insp & testing program, "Proposed Tech Bpec Gurvaillance Regultements for Primary Coolant Sys Helium Circulators," draft.Revision 2 * Public Service Co of Colorado 80/03/28 5pp

--8004030132 "Burveillance Requirements Review for Primary Coolant Bys Helium Circulators," Revision 1 * Public Bervice Co. of Colorado EE-21-0004 80/03/25 17pp

---8004030133 "Proposed Tech Spec Surveillance Requirements for Secondary Goolant Sys," draft, Revision 2 + Public Service Co of Colorado 80/03/25 9pp

---8004030134 "Surveillance Requirements Review for Secondary Coolant Sys." Revision : * Public Bervice Co of Colorado EE-22-0002 80/03/25 28pp

--8074030136 "ASME Code Equipment & Related Insps & Testing "
Public Service Co of Colorado 80/03/25 9pp

8004150237 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Value" No specific action or response necessary, SEYFRIT, K V Region 4, Dallas, Office of the Director, 80/03/31 in

B004080673 Forwards IE Circular 80-05. "Emergency Dissel Generator Lubricating Oil Addition & Oneite Supply " No written response required SEYFRITK V Region 4. Dallas. Office of the Director 80/04/01 to.

8004110104 Forwards IE Info Notice 80-13, "GE Type 8BM Control Ewitches Defective CAM Followers" No specific action or response required SEYFRITK V Region 4, Dalias, Office of the Director 80/04/02 in

8004180499 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees " No action required. SEYFRIT.K V Region 4. Dallas. Office of the Director. 80/04/02

8004180162 Forwards IE Circular 80-07, "Problems W/HPGI Turbine Oil Sys " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director, 80/04/03 in

8004230350 Forwards IE Builetin 79-03A. "Longitudinal Weld Defects in ABME BA-312. Type 304 Stainless Steel Pipe" Action required SEYFRIT. K. V. Pagion 4. Dallas, Office of the Director. 80/04/04 in

- 8004210163 Ack receipt of 800317 ltr informing NRC of «teps taken to correct violations noted in IE Insp Rept 50-267/80-01 MADSEN.O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/04/07 lp
- --8004210166 Responds to NRC ltr re violations noted in IE Insp Rept 50-267/80-01 Corrective actions graduated gallon scale was installed adjacent to sight glass for quick inventory LEE, UR Public Service Co of Colorado 80/03/17 ip
- 8004290390 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Pawer Sys Bus During Operation "Loss of instrument bus voltage is alarmed in control room Voltmeters are provided for addl verification
 FULLER, J K Public Service Co of Colorado 80/04/25 App
- R Periodic operating reports & related correspondence
- BOO4150333 Forwards monthly operating rept for Jan 1980
 WAREMBOURG.D Public Bervice Co of Colorado BO/04/07 ip
- --8004150336 Monthly operating rept for Jan 1980 QAMM-J W Public Service Co of Colorado 80/04/07 9pp
- 8004150338 Forwards monthly operating rept for Feb 1980 WAREMBOURG, D Public Service Co of Colorado 80/04/07 ip
- 8004210268 Forwards monthly operating rept for Mar 1980 WAREMBOURG, D Public Service Co of Colorado 80/04/14 ip
- --8004210271 Monthly operating rept for Mar 1980 OAHM.J W Public Service Co of Colorado 80/04/02 6pp
- B. Reportable occurrences, LERs & related correspondence
- 8004080422 Forwards LER 80-010/03L-0 WAREMBDURG, D Public Service Co of Colorado 80/04/02 4pp
- --B004080427 LER 80-010/03L-0 on B00303,at 10% thermal power, A emergency diesel generator would not load as required for weekly 50% load test surveillance Caused by diesel generator governor problem which reduced speed control response GAMM, J W Public Service Co of Colorado 80/04/02 1p
- 8004080503 Forwards LER 80-011/03L-0 WAREMBOURG, D Public Service Co of Colorado 80/04/02 9pp
- --8004080512 LER 80-011/03L-0 on 800306-21, reactor dewpoint limiting conditions for operation were exceeded on one occasion & operation in degraded mode accurred on three accasions Gaused by problems w/buffer hellum sys GAMM, JW Public Service Co of Colorado 80/04/02 ip
- BOO4150432 Forwards LER 80-016/03L-0 WAREMBOURG, D Public Service Co of Colorado 80/04/09. Spp
- --8004150438 LER 80-016/03L-0 on 800322, during testing, four of twelve helium circulator seal malfunction pressure differential switch units tripped outside specs Caused by dirt accumulation in electrical switches Readjusted switches # Public Service Co of Colorado 80/04/09 ip
- 8004150542 Forwards LER 80-013/03L-0 WAREMBOURG, D Public Service Co of Colorado 80/04/09 5pp
- --8004150552 LER 80-013/03L-0 on B00310 during 58% thermal power operation, indicated flow for two low level primary coolant dewpoint moisture munitors discovered less than requirements Caused by inaccurate flow elements QAHM.J W Public Service Co of Colorado 80/04/09. 1p
- 8004150582 Forwards LER 79-002/03X-1 WAREMBOURG, D Public Service Co of Colorado 80/04/09 4pg
- --G004180411 Bupplemental LER 79-002/03X-1 on 791207, during repairs to buffer helium purge valve, operation in degraded mode occurred Caused by bypass of buffer helium dryer for repair of valve GAMM, J W Public Service Co. of Colorado 80/04/09, ip
- 8004150626 Forwards LER 80-014/03L-0.
 WAREMBOURG, D. Public Service Co of Colorado 80/04/09 4p

- --8004150634 LER 80-014/03L-0 on B00311.during reactor shutdown, emergence feedwater shubber DFS-228E observed to be missing pin at piston rod eye & rendered inoperable No cause stated for missing pin New pin Fabricated & installed OAHN, J W Public Service Co of Colorado B0/04/09 1p
- 8004210294 Forwards LER 80-017/03L-0 WAREMBOURD, D Public Service Co of Colorado 80/04/09 3pp
- --8004210276 LER 80-017/03L-0 on 800311.w/plant shut down due to loss of main cooling water return line.plant liquid effluent sample required by SR NR 1 i not taken Caused by preempted time due to plant upset Sampling resumed on next shift GAHM.J W Public Service Co of Colorado 80/04/07 ip
- 8004240323 Forwards LER 80-015/03L-0
 WAREMBOURG D Public Service Co of Colorado 80/04/18 400
- --8004240328 LER 80-015/03L-0 on 800320, during operation at approx 60% power, emergency feedwater header supply to loop 2 helium circulation water turbine drives was isolated to repair leaking pressure control valve Gaused by loose 6 block bolt GAHM, J W Public Service Co of Colorado 80/04/18 ip
- DOCKET 50-268 MIDWEST FUEL RECOVERY PLANT
- P Operating license stage documents & correspondence
- 8004190031 Appeals denial of FOIA request for all records re sabotage analyses for spent fuel storage at Morris Operation in Morris, IL GUIGO.C Pollution Environmental Problems 80/02/19 Spp
- 8004010163 Responds to FOIA request for seven documents related to earlier request under FOIA-79-520 Forwards documents listed in App A Safeguards manual NEDD-14502, withheld (ref FOIA Exemption 4)
 FELTON, J M Division of Rules and Records 80/03/18 3pp
- --8004010101 Informs that NRC 720602 ltr containing 720517 issue of proposed license conditions for facility has been reviewed Mods can be made to clarify & strengthen matis mgt components Forwards proposed mods & evaluation of mods VANHOOMISSEN, J General Electric Co 72/07/05 16pp
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8004010255 Forwards list of revisions & additions that should be incorporated in 790803 revised safeguards contingency plan Revised plan incorporating revisions & additions should be submitted within 30 days Info withheld (ref 100FRZ 790) REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004030157 Forwards info in support of standby shutdown facility Encl withheld (ref 10CFR2, 790) PARKER.W O Duko Power Co 80/03/28 2pp.
- BOO4170164 Forwards Revision 4 of security plan Plan withheld (ref 10CFR2 790) PARKER,W Q Duke Power Cq BO/04/09 1p
- 8004220443 Advises that revised pages to safeguards contingency plan will be provided by 800430 in response to NRC 800314 request PARKER: N O Duke Power Co 80/04/11 ip
- Q Adjudicatory correspondence
- BOO4230078 Forwards BOO328 SECY-BO-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements If amend approved effect on NRC case re spent fuel transportation & storage will be provided HUEFLINO.R K Hearing Branch 4 80/04/01 1p
- BOO4180432 Forwards NRC 600403 ltr w/encl commercial newspaper advertisement re resumption of evidentiary hearings NRC wishes to notify public officials of counties in which proposed alternate routes are located KETCHEN,

- -8004180441 Notifies of resumption of evidentiary hearings re amend of License ENM-1773 Proposed action is to transport up to 300 spent fuel assemblies from Oconee nuclear facility to McOure nuclear facility Commercial newspaper notice encl ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/04/03
- 004160197 Forwards BS Baitalny. UN Donohow.CR Marctta & E Lantz prefiled testimonies re amend to License SNK-1773 for Ocones spent fuel transportation & storage at McGuire KETCHEN.E.G. Hearing Branch 4 80/04/11 2pp
- -8004160199 Profiled testimony re 800428 hearing Updates license amend record re spent fuel handling & storage alternatives, status of NRC spent fuel cask review & pin compaction application SPITALNY.8 8 Advanced Fuel & Spent Fuel Licensing Branch 80/04/11 Spp
- -8004160210 Supplemental NRC rept "Spent Fuel Storage of Oconee Spent Fuel at McGuire Nuclear Station - Unit i " * Commission 80/04/11 2pp
- ~8004160219 Prefiled testimony re-doses caused by Oconee spent fuel assembly rupture while stored at McGuire spent fuel pool Converts NRC 800208 affidavits to question & answer format Prof qualifications encl DONOHEN.J N Environmental Evaluation Branch 80/04/11 13pp
- -8004160221 Testimony re ASLB questions at Transcript 4027 & 4432-47 concerning whether fuel stored in McGuire spont fuel pool would remain subcritical if cask falls onto pool Converts NRC 80020B affidavits to question & answer format MAROTTA.C R Office of Nuclear Material Safety & Safeguards 80/04/11 2pp
- -8004160224 "NRC Criticality Analysis of McQuire Spent Fuel Pool Containing Oconee Spent Fuel for Cask-Drop Accident " Prof qualifications encl MARGETA.C R Office of Nuclear Material Safety & Safeguards 80/04/11 10pp
- -8004160227 Testimony re ASLB questions at Transcript 4027 & 4432-47 concerning whether fuel stored in McQuire spent fuel pool would remain subcritical if cast falls onto pool converts NRC 800208 affigavits to question & answer format LANTZ,E Division of Operating Reactors 80/04/11 2pp
- -8004140230 "Supplemental Criticality Analysis for Proposed Transfer of Spent Fuel From Oconee to McGuire " Prof qualifications encl LANTZ, E Division of Operating Reactors 80/04/11 Spp
- -8004160235 Affidavit re occupational doses caused by Oconee spent fuel assembly rupture.at 270 days in age, when stored in McGuire spent fuel pool Completes NRC response to ASLB 791031 order Supporting documentation encl
 DONOHEW.J N Environmental Evaluation Branch 80/04/10 8pp
- -8004160240 Affidavit re occupational doses caused by Oconse spent fuel assembly rupture, at 40 days in age, when stored in McGuire spent fuel pool Completes NRC response to ASLB 791031 order Supporting documentation encl
 DONOMEW.J N Environmental Evaluation Branch 80/04/10 8pp
 - offidavit modifying JN Donohew 800111 affidavit.Table 2.Page 3.Page 11 N Environmental Evaluation Branch 80/04/11 3pp
 - ponse requesting deferral of ASLB consideration of 10405 motion proposing primary route of spent its Urges ASLB to hold motion in absuance pending ction re security issue M/Certificate of Svc Hearing Branch 4 80/04/11 7pp

respondence

pands to 800309 ltr requesting info re environ effects of nuclear power plants Radiation effluent levels y 10CFR20 & App 1 to 10CFR50 Environ info stated LPDRS Environmental Projects Branch 1 80/04/01 2pp

nformation

wards Annual Financial Rept for 1979, annual certified atements, financial forecast for 1980-82 & available sources of funds to satisfy liability

Duke Power Co 80/03/28 App

- --8004020338 Annual Financial Rept 1979
- P Operating license stage documents & correspondence
- B004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl DENTON: HR Office of Nuclear Reactor Regulation 80/03/04 26pp
- B004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENUTION D Division of Operating Reactors B0/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp
- 8004030230 Notification of 800318 meseting w/all operating B&W reactor licensees in Bethesda.MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program " * Duke Power Co 80/03/26 13pp
- BO04010470 Supplements 800324 ltr Confirms conversations w/NRC retesting of loss of non-nuclear instrumentation, integrated control sys power on Unit 1 Test will be completed within 90 days up order, if required PARKER, N D Duke Power Co 80/03/28 1p
- BO04030199 Forwards proposed emend to facility Tech Bpecs Table 4 1-3. Section 6 6 4 4(2)(a) & Table 6 6-1 re monitoring waste disposal programs PARKER.W 0 Duke Power Co 80/03/28 2pp
- --8004030202 Proposed amend to facility Tech Specs Table 4 1-3, Section 6 6 1 4(2)(a) & Table 6 6-1 re waste disposal monitoring programs

 * Duke Power Co 80/03/31 7pp
- BO04210321 Requests followup rept to 791030 ltr re method used to demonstrate conformance w/provisions of 40CFR190 rept required by Tech Spots REID, R W Operating Reactors Branch 4 80/03/28 2pp
- 8004160001 Responds to 791116 Tech Spac change application re operation of Unit 2 at full rated power during Cycle 5 Review has determined that proposed reload requires Class IV amend fee instead of Class III Requests add fee D1008.R M License Fee Management Branch 80/03/31 ip
- BOO40B0595 Forwards info re indications & controls requiring mods to maintain plant at hot shutdown independent of ICS/NNI power supplies PARKER, W O Duke Power Co 80/04/01 2pp
- BOO4080614 Supplements 800102 ltr & confirms discussions w/NRC re reactor vessel head vent required by NUREO-0578 Remotely operable reactor vessel head vent will be installed Design will be similar to that of hot leg vents per 800102 ltr PARKER, W O Duke Power Co 80/04/02 lp.
- B004210328 Summary of S00222 meeting w/B&H comers group in Bethesda.Md re abnormal transient operational guidelines SEIGELB L. Reactor Systems Branch 80/04/02 4pp
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINOS, D M Duke Power Co 80/04/03 11pp.
- BOO4250368 Summary of BOO403 meeting w/utils, B&W. NUS Corp & McGraw-Hill in Bethesda. MD re fraft NUREG-0667. "Transient Response of B&W-Designed Reactors" Standardization Branch 80/04/04 7pp
- BOO4180490 Notification of 800423 meeting w/utils & B&W in Bathesda, MD to discuss implementation of recommendations by B&W Reactor Transfent Response Task Force CAPRA, R. A. Blandardization Branch 80/04/05 2pp.
- B0042B0105 Forwards evaluation of implementation of Lessons Learned Task Force Category A items All items satisfactorily implemented at Unit 1 Three remaining items at Units 2 % 3 will be met prior to restart from Mar 1980 shutdowns REID,R W. Operating Reactors Branch 4 80/04/07, 15pp

- 8004300137 Concurs w/800321 ltr describing safety of fuel pool operation w/o addl cooling capacity due to delay of addl cooler & pump installation Requests procise estimate for procurement & installation by 800601
 REID.R W Operating Reactors Branch 4 80/04/09 3pp
- 8004150465 Forwards supplemental response to NRC 800223 request for info re primary coolant sys pressure isolation valves
 Neither continuous surveillance nor periodic testing is now being performed Check valves display no lack of integrity PARKER.W D Duke Power Co 80/04/11 4pp
- B004220502 Advises that detailed analysis of thermal-mechanical conditions of reactor vessol during recovery from small breaks will be submitted B00715 PARKER.40 O Duke Power CO B0/04/14 ip
- 8004220640 Supplements util 790925,1019 & 1219 ltrs re design & use of containment purge sys Requests NRC concurrence in scape of mods to permit purging during operations above cold shutdown PARKER, W O Duke Power Co 80/04/15 2pp
- 8004180356 Submits add) info to supplement 800324 ltr Describes parameters needed by operator to place plant in safe hot shutdown condition & testing for loss of power PARKER:N 0 Duke Power Co 80/04/18 2pp
- @ Inspection reports, IE Bulletins & correspondence
- BOO4070362 Responds to NRC request made during 800109-11 insp for add1 info re assumptions made for support/restraint calculations performed in compliance w/IE Bulletin 79-02 Add1 & original calculations for Support SR 134 enc1 PARKER.W Q Duke Power Co 80/01/3i 19pp
- 8004040358 Ack receipt of IE lnsp Repts 50-247/80-04.50-270/80-03 & 50-267/80-03 on 600121-25 & 28 & 0201 No proprietary info PARKER, N Q Duke Pawer Ca 80/03/10 1p
- --8004040383 Forwards IE Insp Repts 50-269/80-04.50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted STDHR, J P Region 2. Atlanta, Fue) Facility & Materials Safety Branch 80/02/14 2pp
- --8004040402 IE Insp Repts 50-249/80-04, 50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted Major areas inspected emorgency facilities, equipment & procedures, means for determining release & emergency training UENKING, Q R Region 2, Atlanta, Fuel Facility & Materials Safety Branch PERROTTI, D J Region 2, Atlanta, Office of the Director 800/02/14 | 11pp
- 8004040402 IE Insp Repts 80-269/80-04, 90-270/80-03 & 90-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted Major areas inspected emergency facilities, equipment & procedures, means for determining release & emergency training JENKINB, 0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/14 liep
- 8004080253 Forwards response to IE Bulletin 79-01B re environ qualification of Class IE equipment Completion of Items 1, 2 & 3 documented W/o ancl PARKER, W O Duke Power Co 80/03/13 2pp
- 8004100351 Responds to IE Bulletin 79-13 Results of radiographic examinations of feedwater noizle wolds was provided in 800225 ltr w/o encl rept by H Thielsch documenting metallurgical evaluation PARKER: W O Duke Power Co 80/03/19 1p
- 8004240035 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells " No evidence of filter degradation as described in bulletin was observed at facilities PARKER.W D Duke Power Co 80/03/21 2pp
- B004230202 Ack receipt of B00204 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 50-269/79-41, 50-270/79-39 & 50-2897/79-41
 LEWIS R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/03/26 Ip
- --8004230236 Responds to NRC 800114 ltr re violations noted in IE Insp Repts 50-269/77-41,50-270/79-39 & 50-287/79-41 Corrective actions: technician involved given written warning & independent verification being developed PARKER.W. O Duke Power Co 60/02/04. 2pp

- --8004230249 Forwards IE Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 on 791203-10 % notice of violation LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/14 2pp
- --800423026/ Natice of violation from insp on 791203-10
 * Region 2, Atlanta, Office of the Director 80/01/11 1p
- --8004230277 IE Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 on 791203-10 Noncompliance noted failure to follow maint procedures resulting in noncompliance w/Tech Specs MARTIN.R D. JAPE.F. Region 2. Atlanta. Reactor Operations Nucle Support Branch 80/01/11 App
- 8004210191 Ack receipt of IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 on 800114-24 No proprietary 111fo PARKER, W 0 Duke Power Co 80/03/28 1p
- ~-8004210195 Forwards IE Insp Repts 50-269/80-03.50-270/80-02 \$ 50-28 80-02 on B00114-24 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineerin Support Branch 80/03/04 2pp
- --B004210199 IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 or B00114-24 No noncompliance noted Major areas inspected IE Bulletins 79-13 & 79-17, auxiliary feedwater nozzle thermal sleeve insp & crack repair HERDT, A R Region 2, Atlanta, Reactor Construction & Engineer ing Support Branch ECONOMOS, N Region 2, Atlanta, Office of the Director B0/02/25 7pp
- 8004150511 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'RETILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004220188 Forwards IE Insp Repts 50-269/80-08.50-270/80-06 & 50-287/80-06 on 800225-29 No noncompliance noted KENNA.W B Region 2, Atlanta, Safeguards Branch 80/03/31 2pp
- --8004220204 IE Insp Repts 50-269/80-08.50-270/80-06 & 50-287/80-04 or 800225-29 No noncompliance noted Major areas inspected security plan. security program & physical security Details withheld (ref 10CFR2 790)
 TOBIN.W J Region 2: Atlanta: Safeguards Branch 80/03/25 1p
- 8004080611 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Bupply " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/01
- 8004130070 Forwards IE Info Notice 80-13, "GE Type SBM Control Switche Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Bafety Buggestions From Employees " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02, 2nd
- 8004250330 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-269/80-05, 50-270/80-04 & 50-287/80-04 LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --B004250334 Responds to NRC B00220 ltr re violation noted in IE Insp Repts 50-269/80-05, 50-270/80-04 & 50-287/80-04 Corrective actions areas cited were cleaned & maint practices & procedures changed to include housekeeping practices PARKER, W Q Duke Power Co 80/03/14 2pp
- --8004250340 Forwards IE Insp Repts 50-269/80-05.50-270/80-04 & 50-287/80-04 on B00107-31 & notice of deviation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 60/02/20 2pp
- --9004250346 Notice of deviation from insp on 800107-31
 * Region 2, Atlanta, Office of the Director 80/02/20 ip
- --8004250357 IE Insp Repts 50-269/80-05,50-270/80-04 & 50-287/80-04 or 800107-31 Noncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related equipment MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/20 8pp

- 8004180324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required 6'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004250357 IE Insp Repts 50-269/80-05.50-270/80-04 & 50-287/80-04 on 800107-31 Noncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related equipment MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch JAPE, F Region 2, Atlanta, Office of the Director 80/02/20 Sep.
- BO04230132 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASHE SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY. J.P. Region 2. Atlanta. Office of the Director B0/04/04
- 8004180358 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300205 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations & deviations moted in IE Insp Repts 50-269/79-37, 50-270/79-34 & 50-269/79-37 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 200
- --8004200214 Responds to NRC 800206 ltr re violations & deviations in IE Insp. Repts 50-269/79-37.50-270/79-34 & 80-287/79-37 Corrective actions shift operating personnel instructed on manual transfer intercommunication sys & alarm procedures PARKER.W O Duke Power Co. 80/03/03 4pp
- --9004300230 Forwards IE Insp Repts 50-269/79-37,50-270/79-34 & 50-287/79-37 on 791111,15 & 16 & notices of violation & deviation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/06 2pp
- --8004300237 Notice of violation from insp on 791111,15 t 16 * Region 2. Atlanta. Office of the Director 80/01/18 1p
- --8004300245 Notice of deviation from imap on 791111,15 % 16 * Region 2. Atlanta, Office of the Director 80/01/18 2pp
- -8004300260 IE Insp Repts 50-269/79-37,50-270/79-34 & 50-267/79-37 on 791111,15 & 16 Noncompliance noted inadequate procedures to correct potential malfunctions, excessive RCB cooldown rate & failure to notify of RO within 1-h QUICK,D R. MARTIN.R Region 2. Atlanta, Office of the Director 80/01/18 600
- 1004240296 Forwards add1 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Revised master sys/components list & sys component evaluation work sheets encl Add1 equipment info will be sent by 800701
 THIES: A C. Duke Power Co 80/04/21, 1200pp
- Reportable occurrences: LERs & related correspondence
- 004070327 Forward's LER 80-005/03L-0 PARKER, N. O. Duke Power Co 80/03/28. 3pp
- -8004070330 LER 80-005/03L-0 on 800229, during annual calibr check, reactor protection sys channel B reactor coolant pressure transmitter found out of calibr. Cause undetermined Transmitter recalibr & will be checked at next outage LEWIS.S R. Duke Power Co 80/03/28 ip
- D04080471 Forwards LER 80-006/03L-0 PARKER, W O Duke Power Co 80/04/04 1p
- -8004080476 LER 80-006/03L-0 on 800306.during decay heat removal test, heat removal cooler 10 outlet valve 1LP-4 failed to open manually Caused by limit switch being out of adjustment Switch readjusted LEMIS, S.R. Duke Power Co. 80/04/04 2pp
- 304170203 Forwards LER 80-008/13T-1 PARKER, W Q Duke Power Co 80/04/10 3pp
- -8004170208 LER 80-008/13T-1 on 800327.motor operator on valve 1LP-105 determined unqualified for in-containment use Caused by erroneous provision during transfer to site for installation as part of NSM-507 Valve operator will be replaced.
 WILBON, K.R. Duke Power Co. 80/04/11 ip

- B004220692 Forwards LER 80~007/03L~0
 PARKER, W 0 Duke Power Co 80/04/14 2pp
- --8004220690 LER 80-907/03L-0 on 800315, during installation of cable between cable rooms, void botween two layers of firestop mat1 was discovered Caused by large number of cable trays deflecting layer of mat1 Add1 layer of firestop mat1 added LEMIS.8 R Duke Power Co 80/04/14 1p
- DUCKET 50-270 OCCINE NUCLEAR STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8004010255 Forwards list of revisions & additions that should be incorporated in 790803 revised safeguards contingency plan Revised plan incorporating revisions & additions should be submitted uithin 30 days Info withheld (ref 10CFR2 790) REID,R W Operating Reactors Branch 4 80/03/14 2pp
- 8004030157 Forwards info in support of standby shutdown facility Encl withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/03/28 2pp
- 8004170164 Forwards Revision 4 of security plan Plan withheld (ref 10CFR2 790) PARKER, W D Duke Power Co ED/04/09 Ip
- 8004220443 Advises that revised pages to safeguards contingency plan will be provided by 800430, in response to NRC 800314 request PARKER, W. O. Duke Power Co. 80/04/11 ip
- G Adjudicatory correspondence
- 8004230078 Forwards 800328 BECY-80-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements If amend approved; offset on NRC case re spent fuel transportation & storage will be provided HOEFLING, R K. Hearing Branch 4 80/04/01 ip
- I Financial information
- 8004020334 Forwards Annual Financial Rept for 1979, annual certified financial statements, financial forecast for 1980-82 & statement re available sources of funds to satisfy liability requirements
 THIES, A C Duke Power Co 80/03/28, 4sp
- --- 8004020338 Annual Financial Rept 1979. * Duke Power Co 80/02/11 44pp
- P Operating license stage documents & correspondence
- 8004080641 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valva Isolation & Other Safety Feature Signals. Occuree Nuclear Station," informal rept UDY: A C 60 & 0, Inc FIN A-6256 8004080641 80/02/29 12pp
- BO04040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re B00204 reactor trip at Crystal River Sequence of events & planned corrective actions also encl
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 26pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Dperations Ctr RISENHUT, D & Division of Operating Reactors 80/03/12 Spp.
- --8004030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp.
- 8004030230 Notification of 800318 meesting w/all operating R&W reactor licensees in BethesdarMD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID:R W Operating Reactors Branch 4 80/03/14 2pp
- 8004i70327 "TMI-Plus One Toward a Safer Nuclear Power Program " # Duke Power Co 80/03/26 13pp
- 8004010470 Supplements 800324 itr Confirms conversations w/NRC retesting of loss of non-nuclear instrumentation, integrated control sys power on Unit 1 Test will be completed within 90 days of order, if required PARKER, # D Duke Power Co 80/03/28 tp

- 8004030199 Forwards proposed amend to facility Tech Specs Table 4 1-3. Section 6 6 4 4(2)(a) % Table 6 6-1 re monitoring waste disposal programs
 PARKER, N O Duke Power Co 80/03/28 2pp
- --8004030202 Proposed amend to facility Tech Specs Fable 4 1-3, Section 6 6 1 4(2)(a) % Table 6 6-1 re waste disposal monitoring
- programs
 * Duke Power Co 80/03/31 7pp
- 8004210321 Requests followup rept to 791030 ltr re method used to demonstrate conformance w/provisions of 400FR190 rept required by Tech Specs REID,R W Operating Reactors Oranch 4 80/03/28 2pp
- 8004160001 Responds to 791116 Fech Spec change application re operation of Unit 2 at full rated power during Cycle 5 Review has determined that proposed reload requires Class IV amend fee instead of Class III Requests add | fee DIGOS,R M License Fee Management Branch 80/03/31 ip
- 8004080555 Forwards info re indications & controls requiring mods to maintain plant at hot shutdown independent of ICS/NNI power supplies
 PARKER, W.D. Duke Power Co. 60/04/01 2pp
- BO040B0614 Supplements B00102 ltr & confirms discussions w/NRC re reactor vessel head vent required by NUREO-0578 Remotely operable reactor vessel head vent will be installed Design will be similar to that of hot leg vents per B00102 ltr PARKER.W O Duke Power Co B0/04/02 ip
- 8004210328 Summary of 800222 meeting w/B&W owners group in Dethesda. Md re abnormal transient operational guidelines SEIGEL, B L. Reactor Systems Branch G0/04/02 4pp
- 8004140430 Forwards comparison of draft STB w/snubber functional test sampling plan
 'COLLINGS, D.M. Duke Power Co. 80/04/03 11pp.
- 8004250368 Summary of 800403 meeting w/utils.B&W.NUS Corp & McGraw-Hill in Bathasda.MD re draft NUREO-0467, "Transient Response of B&W-Designed Reactors" GAPRA,R A Standardization Branch 80/04/04 7pp
- BO04180490 Notification of BO0423 meeting w/utils & N&W in Bethesda, MD to discuss implementation of recommendations by D&W Reactor Transient Response Task Force CAPRA, R A Standardization Branch 80/04/05 2pp
- 8004280105 Forwards evaluation of implementation of Lessons Learned Task Force Category A items All items satisfactorily implemented at Unit i Three remaining items at Units 2 & 3 will be met prior to restart from Mar 1980 shutdowns REID.R W Operating Reactors Branch 4 80/04/07 15pp.
- BO04300137 Concurs w/BO0321 ltr describing safety of fuel pool operation w/o addl cooling capacity due to delay of addl cooler & pump installation Requests precise estimate for procurement & installation by BO0601
 REID;R W Operating Reactors Branch 4 80/04/09 3pp
- BOO4150465 Forwards supplemental response to NRC BOO223 request for info re primary coolant sys pressure isolation valves. Neither continuous survoillance nor periodic testing is now being performed Check valves display no lack of integrity PARKER, W O Duke Power Co 60/04/11 App
- 8004220502 Advises that dotailed analysis of thermal-mechanical conditions of reactor vessel during recovery from small breaks will be submitted 800715
 PARKER, M. D. Duke Power Co. 80/04/14 ip
- 8004220640 Supplements util 790925, 1019 & 1219 itrs re design & use of containment purge sys Requests NRC concurrence in scope of mods to parmit purging during operations above cold shutdown
 PARKER, W D Duke Fower Co 60/04/15. 200
- 8004220449 Forwards fee to supplement license fee submitted on 791114 PARKER, W C Duke Power Co 80/04/15 ip
- BOO4180356 Submits add1 info to supplement BO0324 ltr Describes parameters needed by operator to place plant in safe hot shutdown condition & testing for loss of power PARKER, W. O Duke Fower Co 80/04/18 2pp

- Q Inspection reports. IE Bulletins & correspondence
- 8004070362 Responds to NRC request made during 800109-11 insp for addl info re assumptions made for support/restraint calculations performed in compliance w/IE Bulletin 79-02 Addl & original calculations for Support SR 134 encl PARKER.W O Duke Power Co 80/01/31 19pp
- G004040358 Ack receipt of IC Insp Repts 50-269/80-04.50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No proprietary info PARKER, W O Duke Power Co 60/03/10 ip
- --8004040383 Forwards IE Insp Repts 50-269/80-04.50-270/80-03 & 50-287/80-03 on 800121-25 % 28 % 0201 No noncompliance noteu STOHR.J P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/14 2pp Branch
- --8004040402 IE Insp Repts 50-249/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted Major areas inspected emergency facilities/equipment & procedures/means for determining release & emergency training JENKINS,G R Region 2, Atlanta, Fuel Facility & Haterials Safety Branch PERROTTI.D J Region 2, Atlanta, Office of the Director 80/02/14 | 11pp
- 8004080253 Forwards response to IE Bulletin 79~018 re environ qualification of Class IE equipment Completion of Items 1, 2 & 3 documented W/o encl PARKER,W D Duke Power Co 80/03/13 2pp
- 8004240035 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-Inch. Tray Adsorber Cells" No evidence of filter degradation as described in bulletin was observed at facilities Duke Power Co 80/03/21 200
- 8004230202 Ack receipt of 800204 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/79-41, 30-270/79-39 & 50-287/79-41 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/26 ip
- ---8004230234 Responds to NRC 800114 ltr re violations noted in IE Insp Repts 50-249/79-41.50-270/79-39 & 50-287/79-41 Corrective actions technician involved given written warning & independent verification being developed PARKER.W O Duke Pawer Co 80/02/04 2pp
- --8004230249 Forwards IE Insp Repts 50-269/79-41,50-270/79-39 & 50-287/79-41 on 791203-10 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/14 2pp
- 80/01/11 15
- ---B004230277 IE Insp Repts 50-249/79-41,50-270/79-39 & 50-287/79-41 on 791203-10 Noncompliance noted failure to follow maint procedures resulting in noncompliance w/Tech Spacs MARTIN,R D . JAPE,F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/11 dep
- 8004210191 Ack receipt of IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 on 800114-24 No proprietary info PARKER, W O Duke Power Co 80/03/28 ip
- --8004210195 Forwards IE Insp Repts 50-269/80-03.50-270/80-02 & 50-287/80-02 on 800114-24 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004210199 IE Insp Regts 50-249/80-03.50-2/0/80-02 & 50-287/80-02 on 800114-24 No noncompliance noted Major areas inspected IE Builetins 79-13 & 79-17.auxiliary feedwater nozzie thermal Bulleting 79-13 & 79-17 auxiliary resonance notile thermal sleeve insp & crack repair HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2. Atlanta. Office of the Director 80/02/25 7pp
- 8004150511 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 200.
- 8004220188 Forwards IE Insp Repts 50-269/80-08,50-270/80-06 & 50-287/80-06 on 800225-29 No noncompliance noted KENNA,W B Region 2. Atlanta, Safeguards Branch 80/03/31 2pp

- --8004220204 IE Insp Repts 50-249/80-08,50-270/80-04 & 50-287/80-06 on 800225-29 No noncompliance noted Major areas inspected security plan.security program & physical security Details withheld (ref 10CFR2 770)
 TOBIN.W J Region 2, Atlanta, Sateguards Branch 80/03/25 ip
- 8004080611 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 200
- B004150070 Forwards IE Info Notice 80-13, "GE Type SBN Control Switches Defective CAM Followers " No specific action or response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/02 200
- 8004250330 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/80-05, 50-270/80-04 & 50-287/80-04 LENIS, C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --8004250334 Responds to NRC 800220 itr re violation noted in IE Insp Repts 50-249/80-05,50-270/80-04 & 50-287/80-04 Corrective actions areas cited were cleaned & maint practices & procedures changed to knolvde housekeeping practices PARKER, W O Buke Power Co BO/03/14 2pp
- --8004250340 Forwards IE Insp Repts 50-269/80-05,50-270/80-04 & 50-287/80-04 on 800107-31 & notice of deviation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/02/20 2pp
- --8004250346 Notice of deviation from Insp on 800107-31
 * Region 2, Atlanta, Office of the Director 80/02/20 ip
- 8004180326 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 200.
- 8004250357 IE Insp Repts 50-269/80-05,50-270/80-04 & 50-287/80-04 on 800107-31 Moncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related equipment MARTIN,R D Region 2, Atlanta, Reactor Decrations Nuclear Support Branch JAPE,F Region 2, Atlanta, Office of the Director 80/02/20 8pp
- 8004230132 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180358 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300205 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 2m.
 - -8004300214 Responds to NRC BOGROb ltr re violations & deviations in IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 Corrective actions shift operating personnel instructed on manual transfer intercommunication sys & alarm procedures PARKER, W O Duke Power Co. 80/03/03 4pp
 - 8004300230 Forwards IE insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 on 7911fi.15 & 16 & notices of violation & deviation.

 LEWIS,R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/02/06 2pp.
 - 8004000237 Notice of violation from insp on 791111.15 & 16 * Region 2. Atlanta, Office of the Director 80/01/18 ip
 - 8004300245 Notice of deviation from insp on 791111,15 & 14 * Region 2, Atlanta, Office of the Director 80/01/18 2pp

- --8004300260 IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 on 7911ii.15 & 16 Noncompliance noted inadequate procedures to correct patential malfunctions, excessive RCS cooldown rate & failure to notify of RO within 1-h GUICK, D.R.; MARTIN, R. Region 2, Atlanta, Office of the Director BO/01/IB 600
- B004240276 Forwards add1 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Revised master sys/components list & sys component evaluation work sheets encl Add1 equipment info will be sent by B00701
 THIES.A C Duke Power Co B0/04/21 1200pp
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION
- F Security, medical, emergency & fire protection plans
- 8004110465 Confirms provision of self-contained breathing apparatus for ready access by control room personnel, as discussed in fire protection safety evaluation CDNMAY.W F Vermont Yankee Nuclear Power Corp 80/04/07 1p
- 6004140403 Forwards assessment of fire protection review re Item 3 1 (3) portable ventilation equipment Licenses input has not been received Recommends that ventilation equipment be installed HALL.R E Recokhaven National Laboratory 80/04/08 200
- 8004230510 Forwards results of fire protection review, Item 3 1 8, fire barrier penetations Recommends NRC consider design & const of penetration seals as conditionally acceptable Typical H penetration requires addl test data
 HALL,R E Brookhaven National Laboratory 80/04/14 2pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OUSSICK. V Defice of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 80040B0374 Notifies of change in address on "list of copies" to read LH Heiden.Vice President.23 Research Drive.Mestboro.MA & WP Murphy.Plant Superintendent.PD Box 157,Vernon.VT BMITH.R L Vermont Yankee Nuclear Fouer Corp 80/04/01 ip
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10CFR20 & App 1 to 10CFR50 Environ info available in stated LPDR8

 BALLARD
- P Operating license stage documents & correspondence
- B00415003B "Safety Evaluation Rept. Inservice Testing Program"
 FEHRINGER, J M . ROCKHOLD, H C EQ & Q, Inc FIN A-4258 800415003B
 80/02/29 40pp
- 8004070408 Discusses NRC 761123 request that all LMR licensees assess higher fission gas release for fuel burnups above 20.000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBERHUT, D O Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp.
- 80041100B4 Forwards requests for add1 info needed to complete evaluation of electrical/bypass aspects of containment purpe sys IPPOLITO.T A Operating Reactors Branch 3 80/03/12 4pp
- B004110040 Forwards info on B00402 meeting w/util in Bathesda,MD re analysis of accidents & transients & preparation of emergency procedure guidelines RDSS.D F Division of Project Management 80/03/17 App

- 8004070040 Summary of 800129 meeting w/util in Bethesda,MD to App J requirements ROONEY,V L Operating Reactors Branch 3 80/03/21 is
- ---8004070042 Forwards notes of 800129 meeting w/util CARFACNO.8 P Franklin Institute/Franklin Research Center 80/01/31 6pp
- 8004010237 Forwards inadvertently deleted page of "Cycle VII Startup Test Rept " SMITH.R L Vermont Yankee Nuclear Power Corp 80/03/24 1p
- --8004010243 Inadvertently deleted page of "Gycls VII Startup Test Rept "
 * Vermont Yankee Nuclear Power Corp 60/03/24 ip
- 8004010256 Responds to NRC telcon request for addl info & clarification re NOREO-0578. Item 2 i 3a concerning direct position indication of safety & relief valves Position indication sys consists of pressure switches in valve discharge piping CONHAY.W F Vermont Yankee Nuclear Power Corp 80/03/24 2pp.
- 8004080238 Forwards hydrogen monitoring sys description Util has investigated requirements of Recommendation 2.1.9 of NUREG-0578 Present sys meets virtually all monitoring requirements Replacement would be expensive & unnecessary CONWAY.W F Vermont Yankee Nuclear Power Corp. 80/04/01. 7pp
- 8004080470 Forwards nonproprietary version of NRC 791211 presentation rept. "Eight by Eight Fuel Fallure Investigation" SMITH, R L. Vermont Vankee Nuclear Power Corp. 80/04/03 1p
- 8004110170 Responds to NRC 800110 ltr requesting info re failure of control rods to insert fully since Sept 1978 No failures observed On 781101. Control Rod 26-31 failed to latch after scram & settled to Position 02 Rod retested satisfactority CONWAY, W F Vermont Yankee Nuclear Power Corp 80/04/04 ip
- BOO4110434 Forwards Revision 8 to YOGAP-I-A addressing organization changes to 0A program
 HEIDER, L H Yankee Atomic Electric Co 80/04/04 1p
- --8004110444 GA program Revision 8 for facility operation VANDENBURGH,D E, HCIDER,L H , MODDY,D E Yankee Atomic Electric Co YOGAP-1-A 80/04/01 20pp
- 8004210043 Requests that licensee remit addl sum per 100FR170 requirements for Class III fee category ra 800125 Tech Spec amend Fee should be submitted within 15 days after receipt of 1tr.
 MILLER.W O License Fee Management Branch 80/04/04 ip
- 8004250017 Forwards 800128 & 0211 ltrs to QE re proposed control rod drive sys mods related to elimination of cracking in return line notales Quidelines for mods will be discussed in NUREO-0619 to be issued in "For Comment" form in Apr 1980 IPPOLITO T A Operating Reactors Branch 3 80/04/07 2pp
- HO04220307 Requests that Proposed Change 68 to Tech Spacu be withdrawn HEIDER,L H Vermont Yankee Nuclear Power Corp 80/04/15 ip
- BOO4290415 Requests mod to App A of CL reflecting change in organizational structure of util Deletes position of technical svcs supervisor & updates position titles & membership responsibilities of prof techniciens
 HEIDER, L H Vermont Yankes Nuclear Power Corp. BO/04/23 6pp
- 8004280506 Responds to NRC B00417 request Provides add1 info remonitoring to complete NRC review of 800401 response to NUREQ-0578.7MI Lesseons Learned short-term requirements No flooding danger to hydrogen analyzers BMITH.R L. Vermont Yankes Nuclear Power Corp. 80/04/24 4pp.
- Q Inspection reports, IE Bulletins & correspondence
- 8004080423 Advises that per telcon, anchor bolts associated w/two hangers on two 8-inch RHR lines which crossconnect RHR systo spent fewl pool cooling systwill not be inspected or replaced as previously agreed upon for safety reasons MOODY, D. E. Vermont Yankee Nuclear Power Corp. 80/02/28 Ip
- 8004080384 Bubmits schedule for response to IE Bulletin 79-018 re environ qualification of Class IE equipment Certain data for submittal not yet available JOHNSON, W.P. Vermont Yankee Nuclear Power Corp. 80/03/04. 2pp

- 80040B0433 Requests confirmation of NRC understanding that 77-018 missing Item I info will be submitted by 800314 & Items 2 & 3 qualification work sheets submitted by 800314 per util 800304 telecopy ORIER B H Region 1, Philadelphia, Office of the Director 80/03/06 io
- 8004080261 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Util evaluating need for alarm in control room to indicate loss of power & revising instrument power bus procedures SMITH.R L Vermont Yankes Nuclear Power Corp 80/03/10 8pp
- 8004080269 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Revised data re I tem 1 & updated response to Items 2 & 3 attached Missing info will be submitted within 90-day period W/o encl
 JCHNSGN.W P Vermont Yankes Nuclear Power Corp 80/03/14 2pp
- G004090410 Advises that IE Bulletin G0-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required GRIER, B H Region 1, Philadelphia, Office of the Director G0/03/17 ip
- 8004150307 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090107 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 1p
- 8004110515 Forwards IE Info Natice 80-13, "QE Type 88M Control Switches Defective CAM Followers " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 2004240353 Forwards IE Info Notice 80-14, "Eafety Suggestions From Employers" No action required ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004180251 Forwards IE Circutar BO-07, "Problems W/HPCI Turbine Dil Bys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/04/03 1p
- BO04110072 Forwards IE Bulletin BO-O7, "BWR Jet Pump Assembly Failure " Written response required GRIER,B H Region I, Philadelphia, Dffice of the Director BO704/04 ip
- 8004230397 Forwards IE Builetin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required GRIER, B H. Region I, Philadelphia, Office of the Director 80/04/04 ip
- B004180293 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Wolds" Written response required GRIER, B M. Region 1, Philadelphia, Diffice of the Director B0/04/07 1p
- R Periodic operating reports & related correspondence
- 8004150360 Forwards monthly operating rept for Mar 1980 MODDY, D F Vermont Yankee Nuclear Power Corp 80/04/11 1p
- --8004150361 Monthly operating rept for Mar 1980 BEERB.F C Vermont Yankes Nuclear Power Gorp 80/04/11 App
- 9004180368 Notifies that meeting of Environ Technical Advisory Committee will be held 800509 in White River Junction.VT Forwards annual."Ecological Studies of CT River.Vernon/VT, Rept IX.1979 "MARX.D J Vermont Yankee Nuclear Power Corp 80/04/15 ip
- ---8004180371 Annual "Ecological Studies of CT River, Vernon/VT, Rept IX, 1979, "

 * Aquatic, Inc. 80/04/15 203pp
- 8004820301 Forwards "Ecological Monitoring Rept 1979 " SMITH,R L. Vermont Yankas Nyclear Power Corp. 80/04/17 ip

- --8004220304 "Ecological Monitoring Rept 1979"

 * Vermont Yankee Nuclear Power Corp 80/04/17 203pp
- S Reportable occurrences, LERs & related correspondence
- 8004010489 Forwards LER 80-011/01T-0 MURPHY, W P Vermont Yankee Nuclear Power Corp 80/03/26 1p
- ---8004010479 LER 80-011/01T-0 on 900312; investigation of ensite power distribution sys revealed voltage of some 480-volt loads below min allowable w/min grid voltage & worse case loading Caused by incomplete analysis when transformers replaced MURPHY, W P Vermont Yankee Nuclear Power Corp 80/03/26 ip
- BOO4020356 Forwards LER BO-012/01P-0.
 MURPHY,W P Vermont Yankee Nuclear Power Corp BO/03/28 1p
- --8004020362 LER 80-012/01P-0 on 80032B, during seismic analysis, pipe supports RHR-H-83 & RSM-H-168 discovered possibly inadequate to support seismic load Caused by deviations from hanger design details Mods to sys will be performed MURPHY, & P Vermont Yankee Nuclear Power Corp 80/03/20 ip
- B004040329 Forwards LER B0-010/03L-0 MURPHY.N P Vermont Yankee Nuclear Power Corp 80/03/31 1p
- --8004040332 LER 80-010/03L-O on B00307,50-millisecond value used in GE transient analysis for reactor protection sys delay time in violation of Tech Specs Tech Bpec 3 1 A will be revised MURPHY,W P Vermont Yankee Nuclear Power Corp B0/03/31 ip
- 8004150506 Forwards LER 80-012/01T-0 MURPHY.N P Vermont Yankee Nuclear Power Corp 80/04/11 1p
- --8004150514 LER 80-012/017-0 on 800328, during seismic analysis required by IE Bullatin 79-14, discovered that pipe supports RHR-H-83 & RSM-H-168 may be inadequate to support seismic loads Caused by deviations from hanger design details.

 MURPHY, M P Vermont Yankee Nuclear Power Corp 80/04/11 1p
- 8004180410 Forwards LER 80~013/03L~0 MURPHY,W P. Vermont Yankee Nuclear Power Corp 80/04/14 ip
- --6004180413 LER 80-013/03L-0 on 800326, while performing surveitlance test on HPCI, turbine speed would not increase above 800 rpm Caused by failure of flow controller Flow controller was replaced.

 MURPHY, W P Vermont Yankee Nuclear Power Corp 80/04/14. ip
- DUCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8004140039 Notifies that util 800125 proposed emergency plan must be revised Forwards specific criteria for compliance w/NUREG-0654 Proposed plan should be resubmitted SCHWENCER. A Operating Reactors Branch 1. 80/03/28 20pp.
- 9 Adjudicatory correspondence
- 8004040207 Comments on irresponsible way intervenors are being treated Sites case of ruling to allow Salem Unit 1 to operate despite no evidence that licenses could protect endangered shortness sturgeon COLEMAN, E. G., COLEMAN, A. G., Affiliation Unknown 80/03/05 3pp
- 8004080633 Notices of KA Onsdorff withdrawl & RE Makel appearance on behalf of intervenors Colemans in proceeding. ONSDORFF,K A New Jersey, State of 80/03/10 2pp
- B004070005 Forwards intervenor Coleman B00317 motion for extension of time to file testimony & for postponement of B00422 hearing AYRES,S T New Jersey, State of B0/03/19 ip
- ~~8004090008 Motion for 30-day extension to file testimony reconsequences of water loss from spent fuel storage pool Urges postponament of 800422 evidentiary hearing, accordingly Notice of appearance & Certificate of 8vc encl. AYREB.8 T , VAN NESS,8 C New Jersey, State of CDLEMAN Affiliation Unknown 80/03/19 App
- 8004150027 Forwards licensee supplemental brief re motion for directed certification & for stay Pendency of Class 7 issue before Commission noted in Licensee motion for directed certification & for stay Discussed on Pages 7-10 HETTERHAHN, M J Conner, Moore & Corber 80/03/24 2pg

- --9004150030 Supplemental brief re motion for directed certification & for stay Commission 800321 memorandum & order re Black Fox leaves no doubt that ASLAB proposed consideration of Question 5 is contrary to directive of Commission METTERHAHN, M J Public Service Electric & Qas Co of New Jersey WETTERHAHN, M J Conner, Moore & Corber 80/03/24 App
- --8004150043 Memorandum & order varating portion of ALAB 973 captioned "Consideration of Class 9 Accidents" & remanding to ASLAB for further consideration Certificate of Svc encl CHILK B J Office of the Secretary of the Commission 80/03/21
- 8004100253 Memorandum & order denying licensee motion for certification.stay & other relief, re consideration of Class 9 accident environ consequences. In spent fuel pool storage expansion proceeding
 BISHOP.C J Atomic Gafety and Licensing Appeal Panel 80/04/01
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological amergency planning & preparedness, distributed as Board notification QOSBICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004240489 Forwards NRC confirmatory orders STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 ip
- --8004240490 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800701 Required info specified in Attachment A BTELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 6pp
- --8004240495 Order confirming util commitment to perform review requested by IE Bulletin 79-27 Info required is specified in Attachment A STELLOV Office of Inspection & Enforcement, Office of the Director 80/04/04 App.
- BOOA210291 Forwards response to Public Svc Electric & Cas Co of NJ comments re request of Lower Alloways Creek Township for suspension of manatorium of issuance of OL OL should not be issued until conclusion of ASLB hearing VALORE, C J Valore, C 80/04/15, Spp
- 8004300985 Responds to 771018 petitions requesting that Commission issue show cause order to suspend or revoke DL for Balem 1 & CPs for Balem 2 & Hope Creek i & 2. & stay issuance of DL for Balem 2 Request denied W/Director's decision DENTON:H R Office of Nuclear Reactor Regulation 80/04/18 ip.
- --8004300590 Director's decision under 10CFR2 206 on E & A Coleman petition requesting that Commission issue show cause order re facilities OL & CP Issuences Request denied DENTON:H R Office of Nuclear Reactor Regulation 80/04/18 App
- ---B004300598 Notice of issuance & availability of Director's decision under 10CFR2 206 on A & E Coleman patition requesting that Commission issue show cause order re facilities OL & CP issuances DENTON, H R Office of Nuclear Reactor Regulation, 80/04/18 2pp
- --8004300600 "Assessment of Impacts of Facilities on Shortnose Sturgeon, Acipenser Brevirostrum Lesuer " MABNIK.M T , WILSON, J. H Office of Nuclear Reactor Regulation 80/03/31 ip
- 8004220674 Response in opposition to Township of Lower Alloys Creek proposed testimony RE Webb & DB Fankhauser testimonies should not be admitted in entirety, due to total concern w/Class 9 accident Certificate of Bvc encl MODRE. J. E Hearing Branch 2. PATON, W D Hearing Branch 4. 80/04/21 13pp
- 8004270233 Notice of appearance in proceeding Certificate of Svc encl SCINTG.J. Regulations Division. 80/04/25 3pp
- H General correspondence
- 8004030123 Responds to 790816. It replans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents. Plant will not reopen until safety-related issues are resolved Provides info replants in NJ Mo diseases resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp.

- --8004030129 Opposes restart of TMI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety FOSTER.X Affiliation Unknown 79/08/16 2pp

I Financial information

- 8004070225 Confirms extension of date for submittal of annual certified financial statements from 800415 to 800515 Extension requested so that current cash flow projection can be furnished for 1980 SCHNEIDER.F.W. Public Service Electric & Gas Co. of New Jorsey 80/04/01
- P Operating license stage documents & correspondence
- 8004020460 Forwards NRC safety analysis of cracking discovered in feedwater sys Util repair program nondestructive insps & leakage testing are adequate to insure that integrity of feedwater piping will be maintained SCHMENCER, A Operating Reactors Branch 1 80/02/25 6pp
- 8004020433 Summarizes 791210 audit of implementation of small break LOCA guidelines into plant procedures Forwards audit, list of maeting attendees & specific comments ROSS.W J Operating Reactors Branch 1 80/02/29 11pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bathesda Operations Ctr EISENHUT, D 9 Division of Operating Reactors 80/03/12 5pg Division of Operating Reactors 80/09/12 5pp
- --8004030118 "Nuclear Data Link Specs"

 ** Division of Operating Reactors 80/02/21 28pp
- 8004020184 Forwards add1 info re shortnose sturgeon in Delaware River Concludes that continued operation of Unit 1. future operation of Unit 2 & const completion of Hope Creek Units will not jeopardize existence of shortnose sturgeon REGAN.W H Assistant Director for Environmental Projects 80/03/14
- --8004020163 "Assessment of Impacts of Balem & Hope Creek Stations on Shortnose Sturgoon, Acipensor Brevinostrum Losuer " MASNIK, M T , WILSON, J H Office of Nuclear Reactor Regulation 80/03/05 110pp
- 8004150227 Notification of 800408 & 09 meeting w/util in Hancocks Bridge: NJ: re implementation of Lessons Learned Task Force short-term recommendations ROSS: W J Operating Reactors Branch 1 80/03/20 2pp
- 8004080390 Forwards "Reactor Containment Integrated Leak Rate Test: First Retest Aug 1979 " LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey 80/03/31 ip
- -8004080394 "Reactor Containment Integrated Leak Rate Test, First Refest Aug 1979 " * PSE & 9 Research Corp. 79/08/31 200pp
- 8004210032 Forwards evaluation of info re auxiliary feedwater sys Open items must be resolved in acceptable manner prior to completion of safety evaluation Requests notification of further actions that will be taken to meet NRC position SCHMENGER.A Operating Reactors Branch 1 80/04/04 Spp
- 8004170060 Describes plans to staff licensed operator positions on both units, following QL issuance for Unit 2, per 800328 discussion w/NRC MITTLER L. Public Service Electric & Gas Co. of New Jersey 80/04/09, 3pp
- 8004170062 Forwards revised pages to 800102 response to TMI Lessons Learned Task Force short-term requirements, incorporating addl info in response to NRC 800408 request Also forwards revised pages previously submitted for Unit 2 by 800328 ltr LIBRIZZI.F.P. Public Service Electric & Gas Co of New Jersey. 80/04/11, 20pp
- 8004170250 Responds to NRC 800314 biological assessment of impact of continued operation or const of facilities Forwards biological opinion & summary of informal consultation W/NRC re Salam Unit 1 Shorthors sturgeon are not in geopardy LEITZELL.T L. Commerce.Dept of. National Marine Fisheries Bervice LEITZELL, T L 80/04/15 20pp

- 8004250366 Responds to 800107 ltr re QA requirements for diesel feel oil Fuel is supplied from day tanks which are fed from 20,000 gailon storage tanks Lists Tech Spec requirements re surveillance of fuel LIBRIZZI,F P Public Service Electric & Gas, Co of New Jersey 80200421 10 60/04/21 10
- Q Inspection reports, IE Bulletins & correspondence
- 8004080318 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Failure analysis on circuit-by-circuit basis to check bus loads & alarms 40% complete Submittal by 801001 SCHNEIDER,F W Public Service Electric & Gas Co of New Jersey 80/02/24 2pp
- 8004170288 Forwards IE Insp Ropts 50-272/79-32 & 50-311/79-37 on 791118-1215 No noncompliance noted BRUNNER,E J Rogion 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/24 2pp
- --8004170293 IE Insp Repts 50~272/79-32 & 50~311/79-37 on 791118-1215 \(\) noncompliance noted Major areas inspected plant operations, including tours of facility, log & record review, review of licensee events. IE cil culars & bulletins & followup items KEIMIG, R Region 1, Philadelphia, Reactor Derations Nuclear Support Branch JOHNSON, D F , NORHELM, L J Region 1, Philadelphia, Office of the Director 80/02/20 20pp
- 8004220416 Forwards IE insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 & 800109 GRIER, B H Region I. Philadelphia, Office of the Director 80/02/26 2pp
- --8004220429 IE Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 & 800109 Noncompliance noted unauthorized individual approved tagging request w/o knowledge of responsible shift Supervisor KEIMIO, D.F., JOHNBON, D.F. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch NORRHOLM, L.J. Region 1. Philadelphia, Office of the Director 80/02/20 21pp
- 8004100256 Requests extension of response dates re IE Bulletin 77-01 Extension required due to numerous changes & respective scope of work BCHNEIDER,F W Public Bervice Electric & Gas Co of New Jersey 80/02/29
- 8004210074 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance moted BHITH.G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- --8004210076 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements radiation levels removable contamination & package external feature requirements POTTER, J P. PEERY, W W. MODDRUFF, R L. Region i, Philadelphia, Fuel Facility & Materials Safety Dranch 80/01/18 7pp
- 8004100247 Forwards response to IE Bulletin 79-01B "Environ Qualification of Class IE Equipment " Partial response addresses Items 1,2 & 3 Submittal made por 800229 ltr W/o encl BCHNEIDER.F W Public Bervice Eisctric & Gas Co of New Jersey 80/03/07
- 8004300488 Advises that audibility survey requested by IE Bulletin 79-18 has been hampered by recent reactor outage Burvey still in progress Final rept will be forwarded by 800404 8CHNEIDER: FW Public Servace Electric & Oas Co of New Jersey 80/03/18 1p
- 8004240494 Responds to IE Bulletin 80-03 Interim findings of visual insp indicate adsorber cells are adequate w/few exceptions investigation & evaluation are continuing Final rept expected by 800331 SCHNEIDER,F W Public Service Electric & Gas Cg of New Jersey 80/03/19. 3pp
- 8004160004 Forwards notice of violation from IE Insp on 790820-30 & 0930, notice of proposed imposition of civil penaties, enforcement history & order modifying license Notice of violation & enforcement history withheld (ref 10CFR2 790) DEYQUNO,R C Office of Inspection & Enforcement, Office of the Director 80/03/20 2pp

- BC04280207 Forwards second partial response to IE Bulletin 79-01B addressing Items 1.2 & 3 W/o encl SCHNEIDER.F W Public Service Electric & Gas Co of New Jersey B0/03/21 2pp
- BO04210016 Forwards IE Insp Rept 50-272/79-26 on 790828-30 GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/26 2pp
- --B004210024 IE Insp Rept 50-272/79-26 on 790828-30 Moncompliance noted physical barriers. Vital Doors 8 & 9, floor plate openings at i00.84 & 64 ft elevations, physical barrier patrols & access control Details withheld (ref 100FR2 790)
 DEVLIN. J W Region 1. Philadelphia. Safeguards Dranch
 BAILEY. R J Region 1. Philadelphia. Office of the Director 79/12/10 | Ip
- BO04280111 Ack receipt of 800319 itr informing NRC of steps taten to correct violations noted in IE Imap Rept 50-272/80-01 BRUNNER.E J Region 1: Philadelphia, Reactor Operations Nuclear Support Branch 80/03/26 ip
- --6004280124 Responds to NRC 800227 ltr re violations noted in IE Insp Rept 50-272/80-01 Corrective actions personnel error re calibr procedures was corrected & supervisors have been reinstructed SCHNEIDER,F W Public Service Electric & Gas Co of New Jersey 60/03/19 2pp
- ---8004280130 Forwards IE Insp Rept 50-272/80-01 on 800122-25 & notice of violation
 BRUNIER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/29 2pp
- ---B004280135 Natice of violation from insp on 800122-25
 * Region 1, Philadelphia, Office of the Director 80/02/27 19
- --8004280147 IE Insp Rept 50-272/80-01 on 800122-25 Noncompliance noted failure to properly review calibr data BAUNACK. W. Region 1. Philadelphia, Reactor Decrations Nuclear Support Branch BLUMBERG.N J. Region 1. Philadelphia, Office of the Director 80/02/27 12pp
- BOO4150296 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/31. 1p
- BOO4070101 Forwards IE Circular BO-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/04/01 1p
- RO04i10506 Forwards IE Info Notice 90-13. "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/02 ip
- ED04240342 Forwards IE Info Netice 80-14, "Safety Suggestions From Employees" No action required GRIER, B H Ragion 1, Philadelphia, Office of the Director 80/04/02 [p
- BOC4110497 Forwards "Computer Program Verification," using PIPDYN 11 stress analysis for NRC Benchwork Problems 1,2,323A & 803, in response to NRC 790724 request & IE Bulletin 79-07 LIBRIZI.F P. Public Service Electric & Oas Co. of New Jersey. 80/04/03 Ip.
- ---8004110500 "Computer Program Verification"
 NANJAPPA,M Public Service Electric & Gas Co of New Jersey
 LIN:Y 1. Franklin Institute/Franklin Research Center 80/04/03
 2050a

- B0041B0246 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Oil Sus " No written response required ORIER. B H Region I. Philadelphia, Office of the Director B0/04/03 19
- 8004230442 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ASME SA-312.Type 304 Stainlass Stoel Pipe " Action required GRIER. B H Region I, Philadelphia, Office of the Director 80/04/04 ip
- 8004180280 Forwards IE Bulletin 80-08, "Exam of Containment Liner Fenetration Welds" Writton response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/07 1p
- B004160249 Revises 770520 response to item of noncompliance noted in IE Insp Rept 50-272/77-13 re starting reactor coolant pump Operating instruction prohibiting starting while reactor is critical has been deleted BCHNEIDER.F W Public Service Electric & Gas Co of New Jersey B0/04/08 2aa
- 8004140246 Responds to item of noncompliance noted in IE Insp Rept 50-272/80-05 Work order initiated to investigate inoperable boron injection tank heat trace channel & conduct necessary repair action Surveillance procedure will be revised SCHNEIDER,E J Public Service Electric & Gas Co of New Jersey 80/04/10 2pp
- R Periodic operating reports & related correspondence
- 8004010331 Forwards "First Interim Rept,316(b) Studies," for Mar-Nov 1979 LIBRIZZI,F P Public Service Electric & Qas Co of New Jersey 80/03/18 10
- --8004010337 "First Interim Rept, 316(b) Studies," for Mar-Nov 1979 * Public Service Electric & Gas Co of New Jersey 80/02/29 150pp
- 8004150384 Forwards monthly operating rept for Mar 1980 H1DURA.H J Public Service Electric & Gas Co of New Jersey 80/04/10 ip
- --8004150389 Monthly operating rept for Mar 1780 MILLER,L K Public Service Electric & Gas Co of New Jersey 80/04/10 17pp
- 8004290489 Forwards "NPDES Discharge Monitoring Repts for Jan-Har 1980 " MIDURA, H J Public Service Electric & Gas Co of New Jarsey 80/04/21 19
- --8004290497 "NPDES Discharge Monitoring Regts for Jan-Mar 1980 "
 * Public Service Electric & Gas Co of New Jersey 80/04/21.
 54pp
- B Reportable occurrences, LERs & related correspondence
- 8004220226 PND-77-002 on 770103,RCS was leaking Caused by broken vent line in letdown line to chemical vol control sys No personnel overexposures or radioactive releases occurred Licensee plans cleanup operations & repair of broken line DREHER,F, ROY,G W Region 1, Philadelphia, Office of the Director. THOMPSON,D Region 3, Chicago, Office of the Director 77/01/04, 2pp
- B004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 HHITT, K W , NOLAN, F Region 2, Atlanta, Office of the Director 77/08/12 ip
- --8004010348 LER 60-013/03L-0 on 800227, during routine surveillance, temp maintained by heat trace circuit 603 found to be 142 F instead of 145 F Caused by pipe insulation erosion Heat tracing repaired & piping reinsulated HURPHY, M J Public Service Electric & Oas Co of New Jersey 80/03/27 19
- 8004010386 Forwards LER 79-059/03L-0 LIBRIZZI,F P Public Service Electric & Oas Co of New Jersey 80/03/27 3pp

- --B004010370 LER 79-059/03L-0 on 790424 & 0508, during refueling putage, Public Svc Relay Dept was performing relay tests & de-energized vital bus supplying operating RHR pump Caused by inadequate work procedures Low level limit raised KAPPLE,A W Public Service Electric & Oas Co of New Jersey B0/03/27 ip
- 8004040317 Forwards LER 80-014/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/03/31 3pp
- --8004040324 LER 80-014/03L-0 on 800303, ground developed on power supply line to Unit 3.resulting in loss of station power transformer 12 Power supply line replaced & transformer re-energized MURPHY, M J Public Service Electric & Gas Co of New Jersey 80/03/31 ip
- 8004110472 Forwards supplemental LER 79-053/01X-1 LIBRT771.F P Public Service Electric & Gas Co of New Jersey 80/03/31 3pp
- --B004i10494 Supplemental LER 79-053/01X-1 on 790B10, during refueling outage, stress calculations for safety-related pipe support found unacceptable Gaused by uning computer code which calculated piping response by algebraic summation method KAPPLE,A W Public Service Electric & Gas Co of New Jersey B0/03/31 1p
- 8004280225 RD 80-17/01P on B00228, during review of environ qualification documentation for accident mitigation/shutdown equipment, RCS wide pressure transmitters found located below max containment flood level following major LOCA MIDURA, H J Public Service Electric & Gas Co of New Jersey 80/03/31 3pp
- 8004080525 Forwards LER 80-015/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/04/01 1p
- --8004080533 LER 80-015/03L-0 on 800304.during normal operation, auxiliary annunciator typewriter began printing meaningless messages Caused by failed solid state component circuit board in typewriter logic control cabinet Circuit board replaced MURPHY.M J Public Service Electric & Gas Co of New Jersey 80/04/01 Spp
- 8004140320 Forwards LER 80~016/03L~0 LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey 80/04/09 3pp
- --8004140323 LER 80-016/03L-0 on 800319, while taking voltage readings in RMB rack, power supply inadvertently grounded by instrument probe resulting in 115 volts ac breaker trip Caused by personnel error Instrument reset HURPHY. M J Public Service Electric & Gas Co of New Jersey 80/04/09 ip
- 8004140409 Forwards LER 79-081/04L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jarsey 80/04/09 2pp
- --B004140412 LER 79-0B1/04L-0 on 790B23, during normal river trawling survey of DE River. Atlantic loggerhead sea turtle was captured Turtle is listed as threatened & endangered Turtle was released unharmed MURPHY. M J Public Service Electric & Oas Co of New Jersey 80/04/09. ip.
- 8004300495 Ack receipt of 800306 ltr.in response to NRC 8002ii ltr re RO 79-71 Corrective actions will be examined during subsequent insp MDSELEY.N C Division of Reactor Operations Inspections, 80/04/09
- BOO4150553 Forwards LER 80-017/017-0 LIBRIZZI,F P Public Service Electric & Gas Co. of New Jersey 80/04/11 4pp
- --8004150558 LER 80-017/01T-0 on 800328, during review of environ qualification documentation required by IE Bulletin 79-01B, RCS wide range pressure transmitters were found below max flood level Caused by imposition of new requirements MURPHY.M J Public Service Electric & Gas Co of New Jersey 80/04/11 ip

- T Hearing transcripts on non-antitrust matters
- 8004180405 Forwards NRC direct testimeny re ASLB Question 5 & prof qualifications of NRC witness, MF Pasedag Also forwards piofessional qualifications of AS Benjamin, Sandia Labs MCORE, J E Hearing Branch 2 80/04/10 ip
- --8004180416 Direct testimony of WF Pasedag in response to ASLB Question 5 Pp 1-5 WF Pasedag prof qualifications encl PASEDAG, W F Commission 80/04/10 7pp
- V Operator Examinations
- 8004030257 Provides addl info per 800125 request Operator licensed for one unit of two-unit facility must take oral & written examination when applying for license on second unit Applicant must scare win 80% overall to receive license COLLINS.P F Operator Licensing Branch 80/03/20 2pp
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & carrespondence
- 8004040031 Advises of issuance of NUREC-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS:DF Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary foodwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Bubmittal schedule should include NRC approval priof to issuance of OL W/encl ROSS,D F Division of Project Management 80/03/10 53pp
- 8004010436 Forwards add1 info re refueling water storage tank capacity in response to 790720 request FSAR commitments & Tech Spec limit is 350,000 gallons Possibility for 27 error exists in indication of tank level CRANE,P A Pacific Gas & Electric Co 80/03/20 6pp
- B004010437 Forwards Draft 2.Revision 2 of proposed ET8 for facility, in response to NRC request TIDRICK, G A Pacific Gas & Electric Co 80/03/21 1p
- --8004010441 Draft 2.Revision 2 of proposed ETS for facility
 * Pacific Gas & Electric Co 80/03/31 21pp
- 8004080466 Forwards nonproprietary version of response to NRC 790912 Itr re tube wear Application for withholding proprietary info & Westinghouse supporting Itrs encl CRANE.P A Pacific Oas & Electric Co 80/03/25 34pp
- BD040202B3 Advises that work of R Lesley re offshore faults does not impact conclusions contained in Suppl 4 of safety evaluation concerning possible connection between Ban Simeon & Hosgrifault iones

 DEVINE, J F Interior, Dept of, Geological Survey 80/03/31 19
- 8004040281 Forwards response to short-term Lessons Learned Task Force requirements Five oversize drawings encl CRANE, P A Pacific Gas & Electric Co 80/03/31 35pp
- 8004140016 Notification of 800404 meeting w/utils in Bethesda, MD to discuss applicants' progress & status in design review re plant shielding & environ qualification of equipment for spaces/sys used in post-accident operations
 800KLEY, B C Light Water Reactors Branch 1 DROMERICK, A W , LIGITRA, E A Light Water Reactors Branch 3, 80/03/31 7pp
- 8004240248 Responds to 791115 telegram to F Press science advisor to President Kemeny Commission rept on TMI accident is being incorporated into NRC Action Plan Applicants will need to implement recommendations prior to CL issuance ROSS, D F Division of Project Management 80/04/01 5pp
- BO04240820 Discusses potential design deficiencies in hypass override & reset circuits of engineered safety features Cites specific examples, safety significance & criteria to be satisfied Protection sys design conformance response due by B00405 BTOLZ.J F Light Water Reactors Branch 1 B0/04/01 Spp

- BOO4080443 Forwards press clippings purporting to state NRC position re Chumash Indians' access to facility Util is willing to meet & discuss issue Access question derived from possible application of Native American Religious Freedom Act PETERS,R J Pacific Qas & Electric Co 80/04/03 4pp
- B004150435 Forwards draft "Archaeological Resources Mgt Plan " Plan covers area north of plant in area designated SLD-2 PETERS,R J Pacific Gas & Electric Co 80/04/07 2pp
- --8004150441 Draft "Archaeological Resources Mgt Plan "
 Pacific Gas & Electric Co 80/04/30 45gp
- B004150337 Forwards comparison of NUREO-0611 recommendations for auxiliary feedwater sys to design &/or operation of facility sys CRANE.P A Pacific Gas & Electric Co B0/04/08 Bpp
- 8004160253 Responds to NRC request for add1 info re secondary water chemistry control & forwards administrative operating & chemical analysis procedures Procedures include schematic diagrams indicating sampling point locations
 CRANE.P A Pacific Gas & Electric Co 80/04/08 2pp
- --8004160296 Operating Procedure F-5.Revision 1. "Chemical Control Limits"
 - Limits "
 * Pacific Gas & Electric Co 80/02/01 42pp
- --8004160257 Chemical Analysis Procedure A-2.Revision 2, "Secondary Cycle Sampling Schedule" + Pacific Oas & Electric Co 79/12/04 Spp
- ---8004160260 Chemical Analysis Procedure E-6. "Secondary Sys Sampling "
 Pacific Gas & Electric Co 80/01/08 5pp
- ---8004160264 Administrative Procedure C-12, Revision 2, "Resolution & Reporting of Plant Problems"

 * Pacific Gas & Electric Co 78/03/06 12pp
- --8004160267 Administrative Procedure C-201, Revision 1. "General Requirements for Chemical & Radiochemical Control Programs " * Pacific Gas & Electric Co 75/11/24 3pp
- --8004160271 Suppl to Administrative Procedure C-20, "Chemistry Data Review & Record Mgt " Descriptions of secondary water chemistry control program encl * Pacific Oss & Electric Co 75/11/24 12pp
- B004170076 Forwards Ravision 3 to response to NUREO-0578 re short-term Lassons Learned Task Force recommendations CRANE,P A Pacific Gas & Electric Co 80/04/09 29pp
- 3004150343 Forwards Revision 4 to facility response to short-term Lessons Learned Task Force requirements CRANE, P. A. Pacific Gas & Electric Co. 80/04/11 21pp
- 3004220406 Responds to NRC 800228 ltr requesting addl info required to evaluate mpt & technical resources available at PG&E facilities Advises that 800321 telcon w/J Powers of Teknekron relayed requested info CRANE.P A Pacific Oas & Electric Co 80/04/15, 1p
- 3004220692 Reisaues Revision 2 to response to NUREO-0578 Also forwards modified instructions for Revision 2 insertion into manual & eight administrative procedures previously sent to review group Oversize drawings encl
 CRANE.P A Pacific Ons & Electric Co 80/04/18 33pp
- -8004220697 "General Authorities & Responsibilities of Shift Foremen" # Pacific Cas & Electric Co 80/03/27 2pp
- -8004220704 "Plant Staff Organization & Responsibilities for Normal Operations," Revision 2 * Pacific Gas & Electric Co 80/03/27 3pp
- -8004220716 "General Authorities & Responsibilities of Nuclear Plant

7 3pg

hift Tachnical Advisor (Shift

2pp

f Off-duty Personnel."

200

- ---8004220744 "Relieving Watch (Shift Turnover)," Revision 3 * Pacific Gas & Electric Co 80/03/27 2pp
- --8004220751 "Control Room Access "
 * Pacific Gas & Electric Co 80/03/31 2pp
- 8004280373 Forwards Revision 8 to response to NUREO-0578 Changes result from questions by NRC reviewers preparing BER CRANE.P A Pacific Qas & Electric Co 80/04/22 Bpp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004240384 Forwards diaft rapt, "Evacuation Times Assessment Study," in response to NRC 791226 request Rept will be raissued w/ possible minor changes by 800523 LDCKE.R F Pacific Gas & Electric Co 80/04/11 ip
- --B004240387 "Evacuation Times Assessment Study "
 * PRC Systems Services Co 80/04/30 102pp
- O Adjudicatory correspondence
- 8004020133 Request by joint intervenors for Commission early intercession or reconstitution of ABLB.re seismic issues Urges disqualification of JH Buck due to prior involvement Requests oral argument on issue Certificate of Svc encl FLEISCHAKER.D Fleischaker, D B PHILLIPS.J R Center for Law in the Public Interest 80/03/13 23pp
- 8004090038 Request by joint intervenors, to stay 800403 oral argument re seismic issues Adequate time should be given to Commission to evaluate joint intervenors' request for early intercession or reconstitution of ASLAB FLEISCHAKER, D 8 Fleischaker, D 8 PHILLIPS, J R Center for Law in the Public Interest 80/03/13 4pp
- 8004080712 Notifies of appearance on behalf of applicant at oral argument re intervenors exceptions concerning earthquake issues.per ASLAB 800225 order Certificate of Svc enc1 NDRTON.B Bruce Norton 80/03/14 3pp
- 8004030015 Opposes operation of facility CA is not safe place to build power plants due to saismic activity
 SNAPP, C Affiliation Unknown 80/03/15 1p
- 8004090033 Advises of appearance on behalf of Govenor of State of CA, at 800403 hearing Certificate of Svc ancl BROWN, H H Hill Christopher & Phillips 80/03/17 4pp
- 80042200Di Forwards notice of appearance of author,PC Valentine & A Baldwin on behalf of San Luis Obispo Mothers for Peace Intervenor JP Teylor prof qualifications encl JONES,Y I Jones, Brown & Clifford 80/03/17. 13pp
- 8004020086 Response in opposition to joint intervenors 800313 request to stay oral argument re seismic issues Urges denial of joint intervenors 800313 request for Commission early intercession or ASLAB reconstitution H/Certificate of Svc. KETCHENIE 9 Hearing Branch 4 80/03/21, 20pp
- 8004080681 Order re Joint Intervenors' 800313 motions. Commission shall not interceds in seismic proceeding JH Buck should publish decision by 800403 Oral argument denied CHILK.S.J. Office of the Secretary of the Commission 80/03/21 2pp
- 8004020020 Forwards affidavit of mondisclosure & protective order drafts, per ASLAB 800225 first prehearing conference order Advises that parties were unable to agree on certain provisions Encloses list of NRC witnesses re security issue STAEMBURG, MR. Regulations Division 80/03/24 17pp
- 8004070132 Response by joint intervenors in opposition to Commissioner Hendrie decision to hear proceeding. Ex parte communication is sufficient for withdrawal.per case law regardless of bias against or in favor of party Decision should be retracted. FLEISCHAKER. D Fleischaker, D S, PHILLIPS, J. R. Center for Law in the Public Interest 80/03/26 lipp

- --8004090137 Response by joint intervenors in opposition to Commissioner Kennedy decision to hear proceeding Ex parte communication is sufficient for withdrawal.per case law.regardless of bias against or in favor of party Certificate of Svc encl FLEISCHAKER.D Fleischaker.D S PHILLIPS.J R Center for Law in the Public Interest 80/03/26 14pp
- 8004230107 Forwards USOS Circular 795 containing conclusions re adjudicated issues.per ASLAB directive to provide new info if relevant & matl FLETECHAKER.D Fleischaker.D S 80/03/26 51pp
- BOO4080556 Petition by Joint Intervenors for review of JH Buck decision to remain member of ASLAB re seismic appeal Prior involvement in facility seismic concerns may jeopardize ability to maintain total impartiality W/Certificate of Svc FLEISCHAKER, D Fleischakor, D S PHILLIPS, J R Center for Law in the Public Interest 80/03/28 8pp
- 8004210322 Motion by Joint Intervenors to reppen record re seismic issues & environ qualification of safety-related equipment New info invalidates ASLB evaluation of Hosgri seismic fault M/Certificate of Broc & supporting documentation FLEISCHAKER,D Fleischaker, D S PHILLIPS,J Center for Law in the Public Interest FLEISCHAKER,D San Luis Obispo Mothers for Peace 80/03/28 18pp
- --8004210325 Affidavit indicating that facility design accelerations, velocities & displacements are not established as conservative values for M-7 5 design earthquake Bupporting documentation encl
 BRUNE, J N California, Univ of San Diego 80/02/27 43pp
- --B004210327 Affidavit advising of recent investigations indicating that Hosgri & San Simeon rones represent continuous & throughgoing fault sys Chart encl LEBLIE R B California, Univ of, Banta Cruz 80/02/28 7pp
- --8004210393 Affidavít demonstrating that independent review of safety related equipment qualification program should be conducted prior to OL issuance KUBBARD.R B. MHB Technical Associates 80/02/20 13pp
- ~-8004210395 "Preliminary Rept on Strong-Motion Records from Imperial County Svcs Bldg." KOJAHN,C , RAGSDALE,J D Affiliation Unknown 80/02/28, 18pp
- 8004070454 Order denying Jaint Intervenors 800328 petition for review of JH Buck 800324 memorandum stating intention not to disqualify from participation JH Buck prior involvement at CP stage does not require disqualification CHILKER J Office of the Secretary of the Commission 80/04/01 300
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 00851CK, L V Office of the Executive Director for Operations 80/04/02. 34pp
- 8004210100 Memorandum to counsels re Joint Intervenors 791024 motion requesting Commissioner Hendrie's disqualification Intervenors have presented no new info proving bias or appearance of bias Self-disqualification not required HENDRIE, J Commission 80/04/09 2pp
- B0042300B1 Advises that applicant response to joint intervenors 800328 motion to reopen evidentiary hearings is due on 800424 & NRC response on 800505, per 800403 stipulation approved by ABLAB KETCHEN, E 9 Hearing Branch 4 80/04/07 2pp
- 8004240841 Ack receipt of Anson 800328 ltr distributed to all parties for consideration
 BIBHOP, C J Atomic Safety and Licensing Appeal Panel 80/04/09
- --8004240545 Forwards map indicating inner evacuation area Expresses concerns re excape routes during meltdown event ANBON.W B Affiliation Unknown 80/03/25 App
- 8004210168 Order granting extension, until 800415, for Commission to act to review ALAB-583 CHILK'S J. Office of the Secretary of the Commission. 80/04/10

- 8004230098 Order reporting 800402 second prehearing conference re procedures & schedules for receiving security plan evidence Licensee physical security plan is entitled to confidential treatment per encl protective order & affidavit BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/04/11
- --B004230103 Protective order re licensee security plan, restricting San Luis Chispo Mothers for Peace access to protected info per encl affidavit of nondisclosure to be executed by counsel & experts BALZMAN,R S Atomic Safety and Licensing Appeal Panel 80/04/03
- B004220371 Response in opposition to POLE B00414 application for stay of ASLAB B00411 order re disclosure of sanitized version of security plan Applicant failed to show that util will be irreparably harmed from disclosure W/Certificate of Svc DAVIS,L D Hearing Branch 4 80/04/18 12pp
- H General correspondence
- 7706290854 Responds to 770411 ltr on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diablo Canyon EISENWIT, D G Division of Doctating Reactors 77/05/22 200
- BOO4040346 Forwards articles from Los Angeles Times re analysis of util financial problems aggravated by commitment to large coal & nuclear power plants ROE.D Environmental Defense Fund 80/02/27 7pp
- 8004030010 Requests permanent denial of OL ANSHUTZ, T.L. Affiliation Unknown 80/03/08 ip
- 8004030008 Urges licensing of power plants ready or near ready for operation Reliable power reserves at stake in CA TERRELL.O D Affiliation Unknown 80/03/10 1p
- 8004030180 Urges release of hold on licensing plant for operation Area may suffer brownouts & blackouts if plant not licensed within one or iwo months MCRRIS.E W Affiliation Unknown 80/03/10 ip
- 8004020250 Responds to 800207 mailgram to President Carter re validity of rumor concerning 800531 issuance of OL to facility NRC has no knowledge of rumor & no such docision has been made NRC is preparing action plan to complete licensing reviews DENTON, H R Office of Nuclear Reactor Regulation 80/03/17 2pp
- d004i10303 Opposes nuclear power plants due to extreme danger to population resulting from meltdown Winds in area of facility would quickly spread radiation over 35-mile radius NRC should expand evacuation area accordingly ANSON.N 8 Affiliation Unknown 80/03/25 5pp
- I Financial information
- 8004100233 Forwards Annual Financial Rept 1979 CRANE.P A Pacific Gas & Electric Co 80/04/03 ip
- --8004100244 Annual Financial Rept 1979
 * Pacific Gas & Electric Co 80/02/22 43pp
- G Inspection reports. IE Bulletins & correspondence
- 8004070175 Forwards IE Insp Rept 50-275/80-01 on 800101-25 No noncompliance noted CREWS,J L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004070178 IE Insp Rept 50-275/80-01 on 800101-25 No noncompliance noted Hajor areas inspected preoperational testing plant tour, fire protection/prevention operator training & witnessing of testing in progress BTERNBERGID M Region 5 San Francisco. Reactor Operations Nuclear Support Branch YOUND, T Region 5, San Francisco, Office of the Director 80/02/06 3pp
- 8004280016 Forwards IE Insp Repts 50-275/80-02 & 50-323/80-01 on 800211-14 & 20 No noncompliance noted 8PENCER.0 & Region 5. San Francisco: Reactor Construction & Engineering Support Branch 80/03/04 2pp

- ---8004280022 IE Insp Rapts 50-275/60-02 & 50-323/80-01 on 800211-14 & 20
 No noncompliance noted Major areas inspected const & mod
 activities, including licensee actions on previous findings,
 deficiency repts item, IE bulletins & circulars
 HAYNES:R C Region 5, San Francisco, Reactor Construction &
 Engineering Support Branch MORRILL,P J, KIRSCH, DF Region 5,
 San Francisco, Orfice of the Director 80/03/04 7pp
- 8004150205 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary EMGELKEN:R H Region 5, San Francisco, Office of the Director 80/03/31 ip
- BOO4100101 Forwards IE Circular 80-05, "Emergancy Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required EMGELKEN/R M Region 5, San Francisco, Office of the Director 80/04/01 ip
- B004110111 Forwards IE Info Notice B0-13, "GE Type SBH Control Switches Defective CAM Followers " No specific action or response required ENGELKEN.R H Region 5. San Francisco. Office of the Director B0/04/02 1p
- 800422003B Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/04/02 ip
- 8004180148 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/03 ip
- 8004230379 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ASME SA-312-Type 304 Stainless Steel Pipe." Action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/04/04 1p
- 8004220176 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/07 ip
- S Reportable occurrences, LERs & related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of interior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT, K W Region 2, Atlanta, Office of the Director 77/08/12 ip
- 800404013: Preliminary deficiency rept re possible equipment defect Un 800118, licensee reported that plastic castings used to hold auxiliary electrical contacts in safety-related 4-kV circuit breakers contained cracks Vendor will replace CRANE.P A Pacific Gas & Electric Co 80/03/10 2pp

- POCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004010329 Forwards Items 3 1 5(2) & 3 1 7 of fire protection review Licensee submittal re fire barrier penetration seals only partly satisfactory Licensee proposal re fire doors acceptable HALL.R E Brookhaven National Laboratory 80/03/26 4pp
- 8004280252 Forwards comments on 800114 emergency plan, per review against criteria set forth in NUREO-0654 IPPOLITO, T A Operating Reactors Branch 3 80/04/01 14pp
- G Adjudicatory correspondence
- BOO4090192 Explains circumstances involving BOO222 svc of BNWL draft rept re measurements of underground mining radon releases & NRC testimony of RM Wilde re same rept Missing Page & enci BORDENICK.B M Hearing Branch 4 80/03/05 4pp
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK, L. V. Office of the Executive Director for Operations BO/04/02 34pp
- I Financial information
- BOO4130246 Forwards Annual Financial Repts 1979 for Philadelphia Electric Co, Public Svc Electric & Qas Co. Atlantic City Electric Co & Detmarva Power & light Co BRADLEY.E J Philadelphia Electric Co BO/O4/OB 1P
- --8004150250 Annual Financial Rept 1979
 * Philadelphia Electric Co 80/02/25 32pp
- --8004150252 Annual Financial Rept 1979 * Public Service Electric & Gas Cn of New Jersey, 80/02/15 47pp
- --8004150255 Annual Financial Rept 1979 * Atlantic Electric of New Jersey 80/04/09 32pp
- --8004150260 Annual Financial Rept 1979 * Delmarve Power & Light Co 80/02/15 32pp
- 8004150470 Requests that date for filing certified financial statements & cash flow statements be delayed until 800515, due to pending rate proceedings involving Public Svc Electric & Gas Co & Philadelphia Electric Co BRADLEY.E J Philadelphia Electric Co 80/04/10 2pp
- P Operating license stage documents & correspondence
- 8004080194 Discusses NRC 761123 request that all LWR licensess assess higher fission gas release for fuel burnups above 20,000 MW-day per metric ton Responses indicate that no immediate licensing is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D 9 Division of Operating Reactors 80/03/12 Spp.
- --8004030118 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp
- 8004230407 Forwards Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability IPPOLITO.T. A Operating Reactors Branch 3 80/03/26. 2pp
- --8004230414 Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs re-core monitoring, core floading & sysoperability requirements IPPOLITO: TA Operating Reactors Branch 3 80/03/26 28pp
- --B004230419 Safety evaluation supporting Amends 45 & 44 to Licenses DPR-44 & DPR-56 respectively # Office of Nuclear Reactor Regulation 80/03/26 7pp

- ---8004230441 Notice of issuance & availability of Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively IPPOLITO, T A Operating Reactors Branch 3 80/03/26 2pp
- 8004010406 Provides add1 info re proposed installation of analog transmitters & trip units addressed in 790827 amend request Amend is necessary to allow removal of 24 safety-related switches in several facility sys DALTROFF, & L Philadelphia Electric Go 80/03/27 2pp
- 8004080538 Responds to NRC 800110 request for tabulation of instances of control rods failing to insert on scram & summary of other control rod drive malfunctions for 1978 & 1979 Facility experienced 15 scrams w/successful rod insertion GALLAGHER, J H Philadelphia Electric Co 80/03/31 2pp
- BOO4080543 Discusses implementation of ATWS mitigation Alternative 3A Prefers prevention of event rather than mitigation Util will install Alternative 3A in facilities if ACRB subcommittee believes ATWS is not extremely remote event BOYER.V 8 Philadeiphia Electric Co 80/03/31 2pp
- 8004080349 Forwards revisions & additions to info originally submitted 791116 to Bulletins & Orders Task Force re process signals QALLAGMER, J W Philadelphia Electric Co 80/04/02 13pp
- 8004140273 Notifies NRC of intent to modify containment suppression chamber Analysis indicates need for torus mods to mitigate effects of hydrodynamic loads Util will install load mitigation devices during current refueling outage XEMPER, US Philadelphia Electric Co 80/04/03 1p
- 8004240299 Forwards Amends 46 & 65 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability

 1PFOLITO, T A Operating Reactors Branch 3 80/04/03 2pp
- --8004240307 Amends 66 & 65 to Licenses DPR-44 & DPR-56, respectively. revising Tech Specs to permit purging of primary containment through reactor bldg ventilation exhaust IPPGLITG. 7 A Operating Reactors Branch 3 80/04/03 10pp
- --8004240320 Safety evaluation supporting Amends 66 & 65 to Licenses DPR-44 & DPR-96, respectively * Operating Reactors Branch 3 80/04/03 4pp
- --8004240327 Notice of issuance & availability of Amends 66 \$ 65 to Licenses DPR-44 & DPR-56, respectively IPPOLITO, T A Operating Reactors Branch 3 80/04/03 2pp
- 8004250007 Forwards 800128 & 0211 ltrs to 98 re proposed control rod drive sys mods related to elimination of cracking in return line notices Guidelines for mods will be discussed in NUREO-0619, to be issued in "For Comment" form in Apr 1980 IPPOLITO, T A Operating Reactors Branch 3 80/04/07 2pp
- 8004220549 Responds to NRC 800228 request for info re mgt & technical resources. COONEY:M J Philadelphia Electric Co 80/04/11 9pp
- 8004240402 Responds to NRC 800414 ltr re QA of diesel generator fuel ofl QA program mod underway to conform w/Reg Quide I 137 Revision I. "Fuel QII Gys for Standby Diesel Generators " Requires mods of storage tanks & procurement of equipment DALTROFF, S L Philadelphia Electric Co 80/04/14 App
- 8004170246 Forwards application for amend of Licenses DPR-44 & DPR-54 Fee encl BRADLEY.E J Philadelphia Electric Co 80/04/15 ip
- -8004170252 Application for amend of Licenses DPR-44 & DPR-96 changing Tech Specs re station fire hose hydrostatic test pressure & flexibility in min shift crew composition Certificate of Bvc enci. BAUER, E G , BRADLEY, E J Philadelphia Electric Co 80/04/13
- --B0041/0256 Revised pages to Tech Specs re station fire hose hydrostatic test pressure & flexibility in min shift crew composition * Philadelphia Electric Co B0/04/15 10pp
- GOO4270423 Notifies NRC that util has been informed by GE that Unit 1 Reload 4 & Unit 3 Reload 3 safety analyses were performed using 50 millisecond scram circuit delay time Tech Spec specifies delay not to axceed 100 milliseconds COONEY, M J Philadelphia Electric Co BO/04/23 3pp.

- Q Inspection reports: IE Bulletins ₺ correspondence
- 8004100211 Responds to IE Builetin 79-27 re loss of Non-Class IE instrumentation Submits actions requested & responses Design mods pending completion of review DALTROFF.S.L. Philadelphia Electric Co 80/02/29 Spp
- 8004160165 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted BMITH, G H Region I, Philadelphia, Fuel Facility & Materials Saf Branch 80/02/29 2pp
- --8004160172 Waste Parkaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected radiation levels, shipping paper requirements, removable contamination & labeling requirements for packages POTTER, J P. JRONN,R A. Region I, Philadelphia, Fuel Facility & Materials Safety Branch. 79/12/12. 7pp
- 8004140064 Forwards response to IE Bulistin 79-018 re environ qualification of Class IE equipment Master list of engineered safety feature sys 8 environ qualification evidence attached HELB analysis due by 800410 W/o encl DALTROFF, 8 L Philadelphia Clectric Co 80/03/03 3pp
- BOO4210079 Forwards Waste Packaging Inep Rept 79-07A on 791212-13 No noncompliance noted SMITH, G H Region 1. Philadelphia. Fuel Facility & Materials Bafe Branch B0/03/05 2pp
- --B0042100B2 Waste Packaging Rept 79-07A on 791212-13 No noncomplien noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & packaging external feature requirements POTTER, J P. PERRY, W. HODDRUFF, R. L. Region 1, Philadelphia, Fuel Pacility & Materials Safety Branch H0/01/18 7pp
- GOO4090416 Advises that IE Bulletin GO-05, "Vacuum Condition Resultin Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks."
 was incorrectly sent for action No response required ORIER, B H Region I, Philadelphia, Office of the Director BO/03/17 IP
- 8004100261 Responds to IE Buildtin 80-03 No cells replaced in engineered safety feature filtration sys.howover charcoal adsorber cells.will have to be removed to replaced rivits indicated in Item 1 DALTROFF, S.L. Philadelphia Electric Co. 80/03/18 3pp
- 8004140183 Ack receipt of 800228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-29 & 50-278/79-32 BRUNNER/E J Region 1. Philadelphia, Reactor Operations Nuclear
 - Support Branch 80/03/21
- --8004160187 Responds to NRC 890208 ltr re violations noted in IE Inc.
 Repts S0-277/79-29 & 50-278/79-32 Corrective actions review
 of provision allowing entry w/o filling out radiation work
 permit will be made wrevisions to procedures
 DALTROFF, B L Philadelphia Flecter Co. 80/00/29 300

- --B004i60i94 IE Insp Repts 30-277/79-29 & 30-278/79-32 on 79ii01-30 Noncompliance noted failure to adhere to radiation work permit & maintain fire & penetration seal barrier MCCABE.E C Region 1. Philadelphia. Reactor Operations Nuclear Support Branch GREENMAN.E 9 Region 1. Philadelphia. Office of the Director 80/02/04 13pp
- 8004150291 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region (, Philadelphia, Office of the Director 80/03/31 ip
- BOO4250045 Updates BOO22? response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " Lists mods being designed to provide redundant instruments in control room GALLAGHER, J W Philadelphia Electric Co BO/03/31 :11pp

- 8004090095 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region L. Philadelphia, Office of the Director 80/04/01 1p
- 8004110501 Forwards I£ Info Notice 80-13, "OE Type 80M Control Switched Defective CAM Followers " No written response required ORIER.B N Region), Philadelphia, Office of the Director 80/04/02 1p
- 8004240339 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required GRIER, B H Region 1, Philadelphia, Office of the Director 80704702 ip
- 8004180263 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/03 1p
- 8004110066 Forwards IE Bulletin 80-07, "BMR Jet Pump Assembly Failure "Written response required GRIER.B H Region & Philadelphia, Office of the Director 80/04/04 | 1p
- 8004230512 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Action required ORIER.D H Region 1. Philadelphia, Office of the Director 80/04/04 1p
- BO04180252 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ORIER, D H Region 1, Philadelphia, Office of the Director 80/04/07 1p
- 600424039i Forwards second response to IE Bulletin 79-01B re environ qualification of Class IE equipment ALDEN.W M Philadelphia Electric Co B0/04/16 1p
- --8004240392 Provides second response to IE Bulletin 79-018 re environ qualification of Class IE equipment Detailed repts w/sys moster lists & equipment qualification forms encl Repts revise & supersede 800303 submittal re licensed actions DALTROFF, S.L. Philadelphia Electric Co. 80/04/15 1300pp
- R Periodic operating reports & related correspondence
- 8004070270 Forwards "Thermal Manitoring Rept 78 for Dec 1979 " WILLSEY.W B Philadelphia Electric Co 80/03/26 ip
- --8004070271 "Thermal Monitoring Rept 78 for Dec 1979 "
 * Philadelphia Electric Co 80/03/26 27pp
- BOO4170228 Forwards monthly operating repts for Mar 1980 COONEY.M J Philadelphia Electric Co 80/04/10 ip
- --8004170230 Monthly operating repts for Mar 1780 ALDEN:W M Philadelphia Electric Co 80/04/10 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004150560 LER 80-006/03L-0 on 800305, w/both units at full power, one of two offsite power sources tripped due to loss of transformer cooling fans Exect cause unknown Cooling fans restored, blown fuse replaced & transformer tested COONEY, M J Philadelphia Electric Co 80/04/03 1p
- 8004290439 RO 2-80-8/IP on 800417, development of environ spectrums associated w/high energy line breaks indicated guillotine failure of steam supply piping to HPCI turbine Caused by engineering deficiency ULLRICH, W T Philadelphia Electric Co 80/04/I8 2pp
- 8004290443 RO 2-80-8-1P updates info re pressure profile within Unit 3 valve following guillotine failure of HPCI steam supply piping Analysis indicates higher poek pressure than riginally reported Caused by engineering error LRICH.44 T. Philadelphia Electric Co 80/04/28 2gp.

- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8004010329 Forwards Items 3 1 5(2) & 3 1 7 of fire protection review Licensee submittal re fire barrier penetration seals only partly satisfactory Licensee proposal re fire doors acceptable HALL, R E Brookhaven National Laboratory 80/03/26 4pp
- 8004280252 Forwards comments on 800114 emergency plan.per review against criteria set forth in NUREG-0654 IPFOLITO.T A Operating Reactors Branch 3 80/04/01 14pp
- 9 Adjudicatory correspondence
- 8004090192 Explains circumstances involving 800222 evc of BNWL draft rept re measurements of underground mining rador releases & NRC testimony of RM Wilde re same rept Missing Page & encl BDRDENICK, B M Hearing Branch 4 80/03/05 4pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OGSSICKL V Office of the Executive Director for Operations B0/04/02 34pp
- I Financial information
- 8004150246 Forwards Annual Financial Repts 1977 for Philadelphia Electric Co.Public Svc Electric & Gas Co.Atlantic City Electric Co & Delmarva Power & Light Co BRADLEVIE J Philadelphia Electric Co 80/04/08 IP
- --8004190250 Annual Financial Rept 1979 * Philadelphia Electric Co 80/02/25 32pp
- --8004150255 Annual Financial Rept 1979
 * Atlantic Electric of New Jersey 80/04/08 32pp
- --8004150260 Annual Financial Rept 1979
 * Delmarva Power & Light Co 80/02/15 32pp
- 8004150470 Requests that date for filing certified financial statements & cash flow statements be delayed until 800515, due to pending rate proceedings involving Public Svc Electric & Gas Co & Philadelphia Electric Co BRADLEY, E J Philadelphia Electric Co 80/04/10 2pp
- P Operating license stage documents & correspondence
- 8004080194 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing is required for operating reactors IPPOLITO T A Operating Reactors Branch 3 80/03/10 3pp
- B004030102 Forwards "Nutlear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EIBENHUT, D O Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- 8004230409 Forwards Amends 45 & 44 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 3 80/03/26, 2pp
- --8004230414 Amends 65 & 64 to Licenses DPR-44 & DPR-96, respectively, revising Tech Specs re core monitoring, core flooding & sys operability requirements IPPOLITO, T A Operating Reactors Branch 3 80/03/26 28pp
- ---8004230419 Bafety evaluation supporting Amends 65 & 64 to Licenses DPR-44 & DPR-36 respectively * Office of Nuclear Reactor Regulation 60/03/26 7pp
- --8004230441 Notice of issuance & availability of Amends 65 & 64 to Licenses DPR-44 & DPR-56, respectively IPPGLITO,T A Operating Reactors Branch 3 80/03/26 2pp

- 8004010406 Provides addl info re proposed installation of analog transmitters & trip units addressed in 790827 amend request Amend is necessary to allow removal of 24 safety-related suitches in several facility sys

 DALTROFF, S L Philadelphia Electric Co 80/03/27 2pp
- 8004080538 Responds to NRC 800110 request for tabulation of instances of control rods failing to insert on scram & summary of other control rod drive malfunctions for 1978 & 1979 Facility experienced 15 scrams w/successful rod insertion GALLAGHER, J W Philadelphia Electric Co 80/03/31 2pp
- BOOA080543 Discusses implementation of ATWS mitigation Alternative 3A Prefers prevention of event rather than mitigation Util will install Alternative 3A in facilities if ACRS subcommittee believes ATWS is not extremely remote event BOYER, V B Philadelphia Electric Co BO/03/31 2pp
- 8004080349 Forwards revisions & additions to info originally submitted 791116 to Bulletins & Orders Task Force re process signals GALLAGHER, J W Philadelphia Electric Co 80/04/02 13pp
- 8004240299 Forwards Amends 66 & 65 to Licenses DPR-44 & DPR-56, respectively, safety evaluation & notice of issuance & availabity IPPOLITO, TA Operating Reactors Branch 3 80/04/03 2pp
- --8004240307 Amends 66 & 65 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to parmit purging of primary containment through reactor bldg ventilation exhaust IPPOLITO.T A Operating Reactors Branch 3 80/04/03 10pp
- --8004240320 Safety evaluation supporting Amends 66 & 65 to Licenses DPR-44 & DPR-56 respectively * Operating Reactors Branch 3 80/04/03 App
- --8004240329 Notice of issuance & availabilty of Amends 66 & 65 to Licenses DPR-44 & DPR-36, respectively IPPOLITO,T A Operating Reactors Branch 3 80/04/03 2pp
- BOO4250007 Forwards BOO128 & O211 itrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line nozzles Guidelines for mods will be discussed in NUREO-0619 to be issued in "For Comment" form in Apr 1980 IPPOLITO T A Operating Reactors Branch 3 80/04/07 2pp
- 8004240402 Responds to NRC 800414 ltr re QA of diesel generator fuel oil QA program mod underway to conform w/Reg Quide i 137 Revision I, "Fuel Oil Bys for Standby Diesel Consentors" Requires mods of storage tanks & procurement of equipment, DALTROFF, BL. Philadelphia Electric Co 80/04/14 App
- BOO4170246 Forwards application for amend of Licenses DPR-44 & DPR-56 fee encl
 BRADLETYE J Philadelphia Cleatric Co 80/04/15 ip
- --BO04170252 Application for amend of Licenses DPR-44 & DPR-56 changing Tach Space re station fire hose hydrostatic test pressure & flexibility in min shift crew composition Cartificate of Svc encl.

 BAUER, E. G., BRADLEY, E. J. Philadelphia Electric Co. 80/04/15
- E3004290423 Notifies NRC that util has been informed by GE that Unit 1 Reload 4 & Unit 3 Reload 3 safety analyses were performed using 50 millisecond scram circuit delay time Tech Spec specifies delay not to exceed 100 milliseconds COUNEY.M J Philadelphia Electric Co. 80/04/23 3pp
- EMOD4220549 Responds to NRC 80022B request for info re mpt & technical resources
 COUNEY.M J. Philadelphia Electric Co 80/04/11 9pp
- Or Inspection reports, IE Bulletins & correspondence
- EICO4100211 Responds to IE Bullstin 79-27 re loss of Non-Class IE instrumentation. Submits actions requested & responses Design mods pending completion of review. DALTROFF, B L Philadelphia Electric Co 60/02/29 Spp

- 8004140064 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Haster list of engineered safety feature sys & environ qualification evidence attached HELB analysis due by 800410 M/o encl DALTROFF, B L Philadolphia Electric Co 80/03/03 3pp
- BD04210079 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH.0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch B0/03/05 2pp
- --8004210082 Wasto Packaging Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placarding requirements, rediation levels, removable contamination & packaging external feature requirements POTTER, J P. PERRY, W. W. MODRUFF, R L. Region 1, Philadelphia, Fuel Facility & Naterials Safety Branch 80/01/18 7pp
- BD04090416 Advises that IE Bulletin 60~05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVC8) Holdup Tanks." was incorrectly sent for action No response required GRIER.8 H Region 1, Philadelphia, Office of the Director 60/03/17 ip
- 8004100261 Responds to IE Bulletin 80-03 No cells replaced in angineered safety feature filtration sys,however charcoal adsorber cells,will have to be removed to replaced rivits indicated in Item 1 DALTROFF.S L Philadeiphia Electric Co 60/03/18 3pp
- 8004140183 Ack receipt of 800228 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-277779-29 & 50-278779-28 BRUNNER,E J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/21 ip
- --8004160187 Responds to NRC 600208 ltr re violations noted in IE Insp Repts 50-277/79-29 % 50-278/79-32 Corrective actions review of provision allowing entry w/o filling out radiation work permit will be made w/revisions to procedures DALTROFF, S.L. Philadelphia Electric Co. 80/02/28 3pp
- --BOO4160189 Fowards IE Insp Repts 50-277/79-29 & 50-278/79-32 on 791101-30 & notice of violation BHUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch 80/02/08 2pp
- --8004160171 Notice of violation from insp on 791101-30
 * Region 1. Philadelphia. Office of the Director 80/02/06 1p
- --8004160174 IE Insp Repts 50-277/79-29 & 50-278/79-32 on 791101-30 Noncompilance noted failure to adhere to radiation work permit & maintain fire & penetration seal barrier MCCABE,E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch GREENMAN.E G Region 1, Philadelphia, Office of the Director 80/02/06 13pp
- 8004150271 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1. Philadelphia. Office of the Director 80/03/31 1p
- 8004250065 Updates 800229 response to 1E Bulletin 79-27, "Lose of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Lists mods being designed to provide redundant instruments in control room GALLAGHER, J W Philadelphia Electric Co 80/03/31 11pp
- 8004090095 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 ip.
- 8004110801 Forwards IE Info Natice 80-13, "GE Type 88H Control Switches Defective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 lp
- 8004240337 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees " No action required GRIER, B H Region I. Philadelphia, Office of the Director 80/04/02 ip
- 8004180263 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required QRIER.8 H Region I, Philadelphia, Office of the Director 80/04/03 tp

- 8004110066 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/04/04 1p
- 8004230512 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required CRIER.B H. Region 1. Philadelphia, Office of the Director 80704704 p
- B004180252 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Helds " Hritten response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/07 1p
- 8004240391 Forwards second response to IE Bulietin 79-018 re environ qualification of Class IE equipment ALDEN.W M Philadelphia Electric Co 80/04/16 1p
- --8004240392 Provides second response to IE Bulletin 79-018 re environ qualification of Class IE equipment Detailed repts w/sys master lists & equipment qualification forms enci Repts revise & supersed 800303 submittal re licensee actions DALTROFF, S.L. Philadelphia Electric Co. 80/04/15 1300pp
- R Periodic operating reports & related correspondence
- 8004070270 Forwards "Thermal Monitoring Rept 78 for Dec 1979 " WILLSEY.W B Philadelphia Electric Co 80/03/26 ip
- --8004070271 "Thermal Monitoring Rept 78 for Dec 1979 "
 * Philadelphia Electric Co 80/03/26 27pp
- BCO4170228 Forwards monthly operating repts for Mar 1980 COONEY.M J Philadelphia Electric Co 80/04/10 ip
- --8004170230 Monthly operating repts for Mar 1980 ALDEN:W M Philadelphia Electric Co 80/04/10 9pp
- S Reportable occurrences, LERs & related correspondence
- 8004220432 RO 3-80-7/IP on 800221, during routine insp of plant equipment, seismir air supply to five containment ventilation valves valved out of svc Caused by procedural & operation error Investigation continuing Procedural mode considered ULLRICH.H T Philadelphia Electric Co 80/02/22 2pp
- 8004070311 LER 80-003/03L-0 on 800303, while performing surveillance tests, MO-3-10-25A LPCI on A, loop failed to open & RHR pump would not start Gaussd by galled Haluorth 24-inch gate, pressure seal bonnet Valve repaired & leak tested COONEY. M J Philadelphia Electric Co 80/04/02 ip
- 8004150560 LER 80-006/03L-0 on 800305.w/both units at full power, one of two offsite power sources tripped due to loss of transformer cooling fans Exact cause unknown Cooling fans restored, blown fuse replaced & transformer tested COUNEY.H J Philadelphia Electric Co 80/04/03 ip
- 8004290439 RO 2-80-8/IP on 800417, development of environ spectrums associated w/high energy line breaks indicated guillotine failure of steam supply piping to HPCI turbine Caused by engineering deficiency
 ULLRICH.N T Philadelphia Electric Co 80/04/18 2pp
- 8004290443 RO 2-80-8-1P updates info re pressure profile within Unit 3 valve following guillotine failure of HPCI steam supply piping Analysis indicates higher peak pressure than originally reported Caused by engineering error ULLRICH, N T Philadelphia Electric Co 80/04/28 2pp
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- BO04150427 Comments on DEB re steam generator repair Proposed recommended action has no effect on transportation sys, except in event transport of hazardous matl is required. COOPER.S Transportation. Dept of 80/04/08 ip
- F Security, medical, emergency & fire protection plans
- 8004150041 Requests add1 info identified in enclosure, for review of revised contingency plan Requests response within 60 days Encl withheld (ref 10CFR2 790)

 6CHWENCER, A Operating Reactors Branch 1 80/02/29 2pp

- 8004140258 Responds to NRC request at 800326 & 27 meeting for emergency plans revised in accordance w/NUREQ-0654 North Anna emergency plan will be submitted on 800501 Surry plan will be submitted on 800602 BAUN. E A Virginia Electric & Power Co 80/04/08 1p
- BOO4300072 Forwards summary of review by element number for upgraded emergency glam per requirements of NURED-0654 Plan should be reviewed per new elements & revisions provided by BOO616 SCHMENCER. A Operating Reactors Branch (80/04/11 10pp
- 8004220311 Forwards fire protection project status summary for OL Amends 53 & 54 mods SYLVIA:B R Virginia Electric & Power Co 80/04/18 2pp
- H General correspondence
- 8004020400 Forwards resumes of persons holding revised employment positions resulting from 800401 mgt reorganization, to assist in review of proposed Tech Bpec changes Also forwards Job descriptions of positions Info withheld (ref Privacy Act) STALLINGS, C M Virginia Electric & Power Co 80/03/31 1p
- I Financial information
- 8004010269 Forwards Annual Rept 1979 BAUM E A Virginia Electric & Power Co 80/03/27 lp
- --8004010275 Annual Rept 1979
 * Virginia Electric & Power Co 79/12/31 32pp
- J Insurance & indomnity information
- BO04300436 Confirms BO0425 telcon granting extension until BO0915 to file info per guarantee requirements set forth in Alternative 5 of NRC 770615 It re implementation of certain provisions of 1975 amends to Price Anders
- P Deerating license stage documents & correspondence
- BOO4150249 Notification of ACRS Subcommittee on Surry Nuclear Station S00123 meeting in Washington BC to continue review of steam generator replacement program HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 79
- 8004140491 Responds to util 770914 answer to NRC request for info on reactor coolant pump supports info does not resolve concarn re integrity components made of high strength managing steel Requests insp of all maraging components SCHWENCER. A Operating Reactors Branch 1 80/02/28 2pp
- BOD4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D O Division of Operating Reactors BO/03/12 Spp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004080320 Forwards corrected Amend 55 to License DPR-32, safety evaluation & notice of issuance & availability, Date of issuance not affixed to original SCHWENGER, A Operating Reactors Branch 1 80/03/17 2pp
- --8004080325 Corrected Amend 35 to License DPR-32 requiring next steam generator tube imaps be conducted within 6 months of equivalent operation from 791025
 6CHMENCER,A Operating Reactors Branch 1 80/02/05 2pp
- --9004080327 Safety evaluation supporting Amend 55 to License DPR-32 * Office of Nuclear Reactor Regulation 80/02/05 5pp
- --8004080330 Notice of issuance & availability of Amend 95 to License DPR-32 SCHWENCER, A Operating Reactors Branch i 80/02/05. 2pp
- 8004250178 Forwards Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively safety evaluation & notice of issuance & availabity SCHWENGER, A Deerating Reactors Branch 1 80/03/21. App

- --8004250193 Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively changing Tech Specs re condition which required use of temporary containment & ventilation sys for all cutting & grinding operations

 ECHWENCER, A Operating Reactors Branch 1 80/03/21 4pp
- --8004250204 Safety evaluation supporting Amends 58 % 57 to Licenses DPR-32 & DPR-37, respectively * Office of Nuclear Reactor Regulation 60/03/21 2pp
- --8004250212 Notice of issuance & availabilty of Amends 5B & 57 to Licenses DPR-32 & DPR-37 respectively SCHWENCER.A Operating Reactors Branch 1 60/03/21 2pp
- B0040103B4 Forwards corrections to B00115 "Revised Rept on Reanalysis of Bafoty-Related Piping Sys " No impact on previous ltrs indicating that analysis & installation of show cause mods is complete

 BPENCER, W C Virginia Electric & Power Co B0/03/28 ip
- --8004010387 Corrections to "Revised Ropt on Reanalysis of Safety-Related Piping Sys " * Virginia Electric & Power Co 80/01/31 Spp
- 8004030126 Forwards corrected pages to revised. "Reanalysis of Safety-Related Piping Sys"
 SPENCER.W C Virginia Electric & Power Co 80/03/28 1p
- --8004030128 "Reanalysis of Safety-Related Piping Sys," corrected pages * Stone & Webster Engineering Corp 80/03/28 Bpp
- 8004010231 Application for amend to DPR-32 & DPR-37 Encl proposed Tech Spec Change 84 roflects changes to Section 6 O, administrative controls re organization of nuclear operations & maint dept & nuclear technical svcs dept STALLINGS.C M Virginia Electric & Power Co 80/03/31 Jpp
- --8004010236 Proposed Tech Spec Change 84 reflecting changes to Section 6 O.administrative controls re organization of nuclear operations & meint dept & nuclear technical sucs dept * Virginia Electric & Power Co 80/03/31 18pp
- B004030234 Forwards addition of implementation of TMI-2 Lessons Loarned Task Force short-term Category A requirements, based on NRC ensite review SYLVIA, B R Virginia Electric & Power Co 80/04/01 78pp
- 8004210010 Forwards request for add1 info re bupass & reset of engineered safety features for review of containment purging & venting Commitment re performance of containment venting operations meets 791022 position BCHWENCER.A Operating Reactors Granch 1 80/04/02 4pp
- B004140246 Informs NRC that ERL-Marragansett declines to review Mar 1980 DEG Task is outside area of expertise PRAGER, J C Environmental Protection Agency B0/04/08 ip
- 8004220318 Discusses options for disposal of reactor coolant pipe from Unit 1 steam generator replacement Preferred option is onsite storage

 BYLVIA.B R Virginia Electric & Power Co 80/04/18 2pp
- 8904300472 Forwards info re implementation of TMI short-term Category A Lessons Learned Requirements Remaining info will be forwarded at later date, SYLVIA.B.R. Virginia Electric & Power Co. 80/04/28 4pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004170079 Forwards response to IE Bulletin 79-17. Item 1.re cracking in stagnant borated water sys Review identified sys which potentially contain stagnant oxygenated borated water BTALLINGS.C M Virginia Electric & Power Co 79/08/30 22pp
- B004040232 Ack receipt of B00125 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-65 & 50-281/79-85 LEWIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/05 ip
- --8004040242 Responds to NRC 791231 ltr re violations noted in IE Insp Repts 50-280/79-65 & 50-281/79-85 Corrective actions periodic test steps are now signed in ink & reviewed by supervisor Correct review procedures were stressed BTALLINGS.C M Virginia Electric & Power Co 80/01/25 Spp

- --8004040250 Forwards IE Insp Repts 50-280/79-65 % 50-281/79-85 on 791126-30 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/12/31 2pp
- --8004040259 Notice of violation from insp on 791126-30
 * Region 2. Atlanta, Office of the Director 79/12/27 ip
- --B004040289 IE Insp Repts 50-280/79-65 & 50-281/79-89 on 791126-30
 Noncompliance noted failure to follow surveillance test
 procedure & review & retain instrument calibr procedures
 UPRIGHT,C M Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch MODN,B T Region 2. Atlanta, Office of the Director
 79/12/27 7pp
- 8004090358 Forwards IE Bulletin 80-03, "Loss of Charcos) From Std Typo II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/06 200
- B004090366 Forwards IE Insp Repts 50-280/80-02 & 50-281/80-04 on B00129-0201 No noncompliance noted BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/02/21 2pp
- --8004070374 IE Insp Repts 50-280/80-02 & 50-281/80-04 on 800129-0201 No noncompliance noted Major areas inspected previous insp findings.const testing.review of quality records.primary & secondary hydrostatic test & const status
 HUNT.M D Region 2. Atlanta. Reactor Construction & Engineering Support Branch. MILCOX.J D Region 2. Atlanta. Defice of the Director 80/02/20 4pp
- 8004010401 Responds to IE Bulletin 79-17. Revision 1. "Pipe Crecks in Stagnant Borated Water Sys at PWR Plants " No adverse plant conditions re intergranular stress corrosion cracking were detected No mods to plant or operating procedures planned STALLINOS.C M Virginia Electric & Power Co 80/02/27 2pp
- 8004240408 Forwards IE Insp Repts 50-280/80-03 & 50-281/80-05 on 800213-15 No negcompliance noted LEWIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --B004240413 IE Insp Repts 50-280/80-03 & 50-281/80-05 on B00213-15 No noncompliance noted Major area inspected surveillance testing program UPRIGHT,C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch MESSITT-B R Region 2, Atlanta, Office of the Director B0/02/28 App
- 8004080270 Submits interim response to IE Bulletin 79-27. "Loss of Nan-Class IE Instrumentation & Control Power Sys Bus During Operation " Operator can be alerted to loss of power by combination of alarms or indications from equipment STALLINGS.C M Virginia Electric & Power Co 60/03/07 4pp
- BOO4020027 Requests extention until end of May to respond to IE Bulletin 79-14 Two long-term items re sv. water sys outside containment will require addl analysis FEROUSON, J H Virginia Electric & Power Co 80/03/18 2pp
- 8004080356 Submits response to IE Bulletin 79-018 re environ qualification of Class IE equipment Requested Master list will be ready by 800415 Equipment test repts in progress Review of Facility syc conditions ready by 800
- 8004180164 Forwards response to IE Bulletin 80-03 re charcoal adsorber cells North Anna charcoal adsorber cells in use do not have potential for loss of charcoal No evidence of degraded cells has been noted during rockarging at Surry STALLINOS, C M Virginia Electric & Power Co 80/03/21 7pp
- 8004240509 Responds to IE Bulletin 79~17.Revision 1. "Pipe Cracks in Stagnant Borated Water Bys at PWR Plants " No adverse plant conditions re intergranular stress corrosion cracking were detected during required availations STALLINGS.C M Virginia Elactric & Power Co 80/03/27 2pp
- 8004150540 Forwards IE Info Natice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director BO/03/31
- 9004080652 Forwards IE Circular 80-05, "Emergency Dissel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 2pp

- B004150105 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required B'REILLY.J P Region 2. Atlanta, Office of the Director B0/04/02
- 8004240284 Forwards IE info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2ec
- 800411033B Notification of 800415-17 meeting w/wkil in Surry.VA to discuss inservice insp & pump & valve testing NEIOHBORS.D Operating Reactors Branch 1 80/04/03 2pp
- 8004180299 Forwards [E Circular 80-07, "Problems W/HPC[Turbing Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230108 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 8A-312.Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004250036 Responds to 800226 ltr re status of insp on low pressure turbines NRC issued draft EIS re proposed repair Final EIS will be issued soon after required comment period ends on 800505

 DENTON, H R Office of Nuclear Reactor Regulation 80/04/04 2pp
- ---8004250041 Advises that turbine insp originally scheduled for May, is now underway due to vibrations experienced prior to shutdown Completion expected by 800310 Requests that preparation of EIS not interfore u/generator replacement FERGUSON, J H Virginia Electric & Power Co 80/02/26 ip
- 8004i10476 Responds to NRC 800314 ltr re violations noted in IE Insp Repts 50-280/80-0: & 50-281/80-03 Corrective actions personnel instructed to utilize only manufactures recommended replacement parts & proper gaskets SYLVIA:8 R Virginia Electric & Power Co 80/04/07 ip
- 8004180401 Forwards IS Bulletin 80-08, "Exam of Containment Liner Panetration Welds " Written response required O'REILLY, J.P. Region 2, Ablanta, Office of the Director 80/04/07 2pp
- 8004180289 Forwards results of steam generator insp & preventive plugging program Approx 25 1% tubes plugged Existing analysis by Amend 35 to License DFR-32 applicable Approval will be requested to allow addl six months power operation SYLVIA.B R Virginia Electric & Power Co E0/04/15 15pp
- 8004290334 Responds to IE Bulletin 79-13, Revision 2, "Cracking in Feedwater Piping Sys " No nonconformances identified in visual exam of feedwater pipe supports Welds will be inspected during refueling outage Supersedes 800408 ltr SYLVIA.8 8 Virginia Electric & Power Co 80/04/24 2pp
- R Periodic operating reports & related correspondence
- 8004170241 Forwards monthly operating repts for Mar 1980 SYLVIA.R B Virginia Electric & Power Co 80/04/14 1;
- --8004170244 Honthly operating repts for Mar 1980 COSTELLO.O J Virginia Electric & Power Co 80/04/02 42pp
- S Reportable occurrences, LERs & related correspondence
- 8004030266 Forwards LER 80-019/03L-0 STALLINGS.C.H Virginia Electric & Power Co 80/03/28 ip
 - 04030270 LER 80-019/03L-0 on 800304, during evaluation of vols of ontaminated drain tanks for increasing tankage vailability, error was discovered in vols being used Caused y level indication during plant const
 TEWART. H L Virginia Electric & Power Co 60/03/26 2pp
 -)80474 Forwards LERs 80-014/01T-0 & 80-002/01T-0 80N.J W Virginia Electric & Power Co 80/04/02 1p
 - 14080482 LER 80-002/017-0 on 800320, insp of containment following spe A leak rate revealed eight 1/4 inch holders drilled hrough containment liner Caused by improper interpretation f procedure during Design Change 78-48 Repair planned ILSCN.J L Virginia Electric & Power Co 80/04/02 2pp

- ~-8004080486 LER 80-014/017-0 on 800320, informed by Westinghouse that incident of stress corrosion cracking in control rod sypport pins & flexures noted in foreign plant Vendor testing & assessment program in progress Appropriate action planned WILBON, J L Virginia Electric & Power Co 80/04/02 2pp
- 8004250371 RO while conducting PY 25 12. jump 1-FP-P2 in fire protection sys failed to meet acceptance criteria of 250 ft at 2500 gallons per minute Cause not determined Vendor will participate in insp Local fire depts will supply assistance SYLVIA.B R Virginia Electric & Power Co 80/04/22 ip
- 8004280612 Forwards LERs 80-021/03L-0 & 80-022/03L-0 W1L50N,J L Virginia Electric & Power Co 80/04/24 ip
- --8004280616 LER 80-021/03L-0 on 800327, during performance of 1-PT-398-1, snubbar 1-WAPD-HSS-148 discovered w/low fluid level in reservoir Caused by fluid leaking out through reservoir to block tube fitting Bnubber declared inoperable WILSON, J L Virginia Electric & Power Co 80/04/24 2pp
- ---8004280626 LER 80-022/03L-O on 800327, during performance of 1-PT-39B-1, snubbers 1-RC-HS8-116 & 1-RC-HSS-117 discovered installed 90 degrees out of position Caused by corrective work performed per 16 Bulletin 79-14 HILSON, J L Virginia Electric & Power Co 80/04/24 2pp
- DOCKET 50-281 SURRY POWER STATION, UNIT 2
- D NRC Braft/Final Environmental Statements, suppls & correspondence
- BOD4150429 Comments on DES re steam generator repair Proposed recommended action has no effect on transportation systems except in event transport of hazardous matlis required CDOPERS Transportation. Dept of 80/04/08 1p
- F Security, medical, emergency & fire protection plans
- 8004150041 Requests add1 info identified in enclosure, for review of ravised contingency plan Requests response within 60 days Encl withheld (ref 10CFR2 790)
 SCHWENCER.A Operating Reactors Branch 1 80/02/29 2pp
- B004140258 Responds to NRC request at 800326 & 27 maeting for emergency plans revised in accordance w/NUREG-0454 North Anna emergency plan will be submitted on 800501 Surry plan will be submitted on 800402

 BAUM: E A Virginia Electric & Power Co 80/04/08 ip
- B004300072 Forwards summary of review by element number for upgraded bmergency plan per requirements of NUREC-054. Plan should be reviewed per new elements & revisions provided by B00616 SCHMENCER. A dperating Reactors Branch 1 80/04/11. 10pp
- 8004220311 Forwards fire protection project status summary for QL Amends 53 & 54 mods SYLVIA.B R Virginia Electric & Power Co 80/04/18 2pp
- O Adjudicatory correspondence
- 8004070056 Forwards order lifting suspension of facility operation required by 790313 order to show cause DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/26 Zpp.
- --8004070063 Order lifting suspension of facility operation required by 790313 order to show cause, effective immediately All mode to correct piping sys overstress shall be completed prior to startup CABE, E O Office of Nuclear Reactor Regulation 60/03/26 5pp.
- --8004070066 Safety evaluation stating that conditions of 790313 order to show cause have been met

 # Office of Nuclear Reactor Regulation 80/03/21 7pp.
- H General correspondence
- B004020400 Forwards resumes of persons holding revised employment positions resulting from B00401 mgt reorganization to assist in review of proposed Tech Spec changes Also forwards job descriptions of positions Info withheld (ref Privacy Act) STALLINGS.C M Virginia Electric & Power Co. 80/03/31 1p
- 1. Financial information
- BOO4010269 Forwards Annual Rept 1979
 BAUM, E A Virginia Electric & Power Co 80/03/27 ip

- --8004010275 Annual Rept 1979
 * Virginia Electric & Power Co 79/12/31 32pp
- J. Insurance & indemnity information
- 8004300436 Confirms 800425 telcon granting extension until 800515 to file info per guarantee requirements set forth in Alternative 5 of NRC 770615 ltr re implementation of certain provisions of 1975 amends to Price Anderson Act JOHNSON, B D Virginia Electric & Power Co 80/04/25 1p
- P Operating license stage documents & correspondence
- B004150249 Notification of ACRS Subcommittee on Surry Nuclear Station 800123 meeting in Washington.DC to continue review of steam generator replacement program MOYLE, J C ACRS Advisory Committee on Reactor Safeguards 79/12/20 3pp
- B004140481 Responds to util 790914 answer to NRC request for info on reactor coolant pump supports Info does not resolve concern re integrity components made of high strength maraging steel Requests insp of all maraging components

 SCHWENCER, A Operating Reactors Branch 1 80/02/28 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D @ Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004250178 Forwards Amends 58 & 57 to Licenses DPR-32 & DPR-37, raspectively safety evaluation & notice of issuance & availability SCHMENCER. A Operating Reactors Branch 1 80/03/21 2pp
- ---8004250193 Amends 58 & 57 to Licenses DPR-32 & DPR-37, respectively changing Tech Specs re condition which required use of temporary containment & ventilation sys for all cutting & grinding operations.

 BOHWENCER, A Operating Reactors Branch 1 80/03/21 4pp
- --8004250204 Safety evaluation supporting Amends 50 & 97 to Licenses DPR-32 to DPR-37, respectively * Office of Nuclear Reactor Regulation 60/03/21 2pp
- --8004250212 Notice of issuance & availability of Amends 58 & 57 to Licenses DPR-32 & DPR-37 respectively BCHWENCER.A Operating Reactors Branch 1 80/03/21 2pp.
- 8004010231 Application for amend to DPR-32 & DPR-37 Encl proposed Tech Spec Change 84 reflects changes to Section 6 0, administrative controls re organization of nuclear operations & maint dept & nuclear technical svcs dept STALLINGS, C. M. Virginia Electric & Power Co. 80/03/31 Gpp
- --8004010236 Proposed Tach Spec Change 84 reflecting changes to Section 6 0, administrative controls re organization of nuclear operations & maint dept & nuclear technical svcs dept # Virginia Electric & Power Co 80/03/31 15pp
- 8004030234 Forwards add1 info re implementation of TMI-2 Lessons Learned Task Force short-term Category A requirements, based on NRC onsite review, SYLVIA, B. R. Virginia Electric & Power Co. 80/04/01. 78pp.
- 8004210010 Forwards request for additinfoirs bypass & reset of engineered safety features for review of containment purging & venting. Commitment re performance of containment venting operations masets 791022 position, BCHWENCER, A. Operating Reactors Branch 1 80/04/02 4pp.
- 8004140219 Forwards "Rept on Reanalysis of Bafety-Related Piping Sys." Revision i re 800222 request for startup of facility. Incorporates 800321 commitment to complete installation of mods re-order to show cause prior to startup, SPENCER.W C Virginia Electric & Power Co. 80/04/11, ip.
- --8004140224 "Rept on Reanalysis of Safety-Related Piping Sys," Revision

 1

 * Ebasco Services, Inc. (subs. of Enserch Corp.) 80/04/11.

- BOO4220318 Discusses options for disposal of reactor coolant pipe from Unit i steam generator replacement Preferred option is ensite storage BYLVIA.B R Virginia Electric & Power Co 80/04/18 2pp
- BOO4300472 Forwards info re implementation of TMI short-term Category A Lessons Learned Requirements Remaining (nfo will be forwarded at later date SYLVIA.B R Virginia Electric & Power Co 80/04/28 4pp
- G Inspection reports. IE Bulletins & correspondence
- 8004170079 Forwards response to IE Bulletin 79-17. Item i.re cracking in stagnant borated water sys Review identified sys which potentially contain stagnant oxygenated borated water STALLINOS.C M Virginia Electric & Power Co 79/08/30 22pp
- 7907280009 Responds to IE Builetin 79-13, "Cracking in Feedwater Piping Sys " Unit 2 weld insps are approx 25% complete STEMART,W L Virginia Electric & Power Co 79/09/05 ip
- 8004040232 Ack receipt of 800125 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~280/79-65 & 50~281/79-85 LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/05 ip
- --8004040242 Responds to NRC 791231 ltr re violations noted in IE Insp Repts 50-280/79-65 & 50-281/79-85 Corrective actions pariodic test steps are now signed in ink & reviewed by supervisor Correct review procedures were stressed BTALLINOS,C M Virginia Electric & Power Co 80/01/25 3pp
- --8004040250 Forwards IE Insp Repts 50-280/79-65 & 50-281/79-85 on 791126-30 & notice of violation LEWIS,R C Region 2. Atlanta, Reactor Construction & Engineering Support Branch, 79/12/31 2pp
- --8004040257 Notice of violation from insp on 791124-30

 * Region 2, Atlanta, Office of the Director 79/12/27 in
- --80040402B9 IE Insp Repts 50-280/79-65 & 50-281/79-85 on 791126-30 Noncompliance noted failure to follow surveillance test procedure & review & retain instrument calibr procedures UPRIGHT.C M Region 2. Atlanta. Reactor Operations Nuclear Support Branch MODN.B T Region 2. Atlanta. Office of the Director 79/12/27 7pp
- 8004090358 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/06
- 8004090366 Forwards IE Insp Repts 80-280/80-02 & 50-281/80-04 on 800129-0201 No noncompliance noted DRYANT, J_C Region 2. Atlanta, Reactor Construction & Engineering

- 8004080956 Submits response to IE Bulletin 79-0:8 re environ qualification of Class IE equipment Requested Master list will be ready by 800415 Equipment test repts in progress Review of facility svc conditions ready by 800905 STALLINGS.C M Virginia Electric & Power Co 80/03/18
- 8004150164 Forwards response to IE Bulletin 80-03 re charcoal adsorber cells North Anna charcoal adsorber cells in use do not have potential for loss of charcoal No evidence of degraded cells has been noted during recharging at Surry STALLINGS,C M. Virginia Electric & Power Go. 80/03/21 7
- 8004240509 Responds to IE Bulletin 79-17, Revision 1, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants." No adverse glant conditions re intergramular stress corrosion cracking were detected during required evaluations STALLINGS, C.M. Virginia Electric & Power Co. 80/03/27 2pp
- 8004150540 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary Region 2. Atlanta, Office of the Director 80/03/31
- 8004080652 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01

- 8004150105 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02
- 8004240284 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004110338 Notification of 800415-17 meeting w/util in Surry,VA to discuss inservice insp & pump & valve testing NEIOHBORS.D Operating Reactors Branch 1 80/04/03 2pp
- 8004180299 Forwards IE Circular 80-07, "Problems W/HPCI Turbine dil Sys "No written response required.
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230108 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pige" Action required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/04/04 B0704704
- 8004110478 Responds to NRC 800314 ltr re violations noted in IE Insp Repts 50-280/80-01 & 50-281/80-03 Corrective actions personnel instructed to utilize only manufacturer recommended replacement parts & proper gaskets SYLVIA.B R Virginia Electric & Power Co 80/04/07 1p.
- 8004180401 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/07.
- 8004290334 Responds to IE Bulletin 79-13. Revision 2. "Cracking in Feedwater Piping Sys " No nonconformances identified in visual exam of feedwater pipe supports Welds will be inspected during refueling outage Supersedes 800408 ltr SYLVIA.B R Virginia Electric & Power Co 80/04/24 2pp

Periodic operating reports & related correspondence

- 04170241 Forwards monthly operating repts for Mar 1980 BYLVIA.R.B Virginia Electric & Power Co 80/04/14
- --8004170244 Monthly operating repts for Mar 1980. CDSTELLQ.O J Virginia Electric & Power Co 80/04/02 42pp

108

... ginie Electric & Power Co 80/04/02

- --8004080482 LER 80-002/01T-O on 800320, insp of containment following Type A leak rate revealed eight i/4 inch holders drilled through containment liner Caused by improper interpretation of procedure during Design Change 78-48 Repair planned WILSON, J L Virginia Electric & Power Co 80/04/02 2pp
- 8004250371 RD while conducting PT 25 12.pump i-FP-P2 in fire protection sys failed to meet acceptance criteria of 250 ft at 2500 gallons per minute Cause not determined Vendor will participate in insp. Local fire depts will supply assistance SYLVIA.B R Virginia Electric & Power Co 80/04/22 1p
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004080225 Bubmits revised schedule for implementing fire protection moos MAYER.L D Northern States Power Co 80/03/31 2pp
- 8004170056 Forwards "Evacuation Fime Estimates," from areas near nuclear generating plant.in response to NRC 791129 request MAYER, L O Northern States Power Co 80/04/10 ip
- G Adjudicatory correspondence
- 800423008B Request for hearing and petition to intervene re spent fuel pool mod License smend should not be issued until State of MN administrative proceedings are completed re licensee application for certificate of need & environ evaluation BENECHAL.M E. OLSON, J F Minnesota, State of 80/03/31 5pp
- 8004230100 Notice of appearance in proceeding SENECHALIM E , OLSON, J F Minnesota, State of 80/03/31 2pp
- H Ceneral correspondence
- 8004280037 Discusses NRC intervenor funding in response to 800305 ltr. Commission decided not to initiate program to provide funding in 1976 Intervenor funding is being studied again & funds for pilot program have been requested for FY81 CHRISTENBURY, E Mearings Division 80/04/08 ip
- --8004280043 Requests info on availability of govt financial aid for intervenors in facility spent fuel storage license amend proceeding FIELDSETH.H Affiliation Unknown. 80/03/05 ip
- P. Operating license stage documents & correspondence
- 8004110520 Forwards FR notice of proposed issuance of amend to Licenses DPR-42 & DPR-60 re spent fuel storage capacity 8CHMENGER, A. Operating Reactors Branch 1, 80/02/28 2pp
- --8004110524 Notice of proposed issuance of amend to Licenses DPR-42 & DPR-40 re spent fuel storage capacity SCHMENCER.A Operating Reactors Branch 1 80/02/28 4pp
- B004020070 Forwards Amends 41 & 35 to Licenses DPR-42 & DPR-40, respectively & notice of issuance & availability , SCHMENCER.A. Operating Reactors Branch i 80/02/29 4pp
- --8004020073 Amend 41 to License DPR-42 revising App B Tech Specs by changing requirement re blowdown flow over 150 cfs to annual & fish impingement sampling frequency to once every two ECHWENCER, A Operating Reactors Branch 1 80/02/29 2pp
- --8004020075 Amend 35 to License DPR-60 changing App B Tech Specs by revising requested requirement re blowdown flow over 150 cfs to annual 5 fish impingement sampling frequency to once every two wks Tech Spec replacement pages encl.

 SCHWENCER, A Operating Reactors Branch 1 80/02/29 8pp
- --8004020079 Notice of issuance & availability of Amends 41 & 35 to License DPR-42 & DPR-60, respectively. BCHHENGER, A. Operating Reactors Branch 1 80/02/29 2pp.
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethasda Operations Ctr. EISENHUT, D Q. Division of Operating Reactors 80/03/12 5pp.

- --8004030i18 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004070378 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence at facility

 KEPPLER, J G Region 3. Chicago. Office of the Director 80/03/17
- 8004100183 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER, J. G. Region 3. Chicago, Office of the Director BO/03/20
- 8004100486 Summary of 800221 telcon w/util re status of NUREO-0578 implementation Items requiring add1 clarification subcooling meter & backup procedures used to determine subcooling & use of CRTs not having seismic qualifications OROTENHUIS.M Operating Reactors Branch 1 80/03/21 5pp
- 8004140099 Summary of 800321 meeting w/util in Bethesda, MD re fuel pool expansion proposed by util on 800131 Addl info re unresolved questions will be transmitted by util encl list of attendees GROTENHUIB, M Operating Reactors Branch 1 80/03/21 3pp
- 8004210023 Advises that 781122 application to amend Licenses DPR-42 & DPR-60 is pro forma & administrative in nature placing Unit 1 in Class II fee category Refund for Class III overpayment will be processed MILLER.W O License Fee Management Branch 80/04/03 1p
- 8004150339 Forwards add1 info re implementation of short-term Lessons Learned Task Force recommendations MAYER, L O Northern States Power Co 80/04/11 17pp
- 8004180464 Forwards proprietary & nonproprietary versions of "Structural Analysis of RCS for Postulated LUCA," preliminary issue Applications for withholding encl Proprietary version withheld (ref 10CFRZ 790) ANDERSON
- --8004180475 Nonproprietary version of "Structural Analysis of RCS for Postulated LOCA," proliminary issue # Westinghouse Electric Corp , Nuclear Energy Systems 80/02/29
- 8004180341 Forwards Offsite Dose Calculation Manual Revision 1 MAYER, L O Northern States Power Co 80/04/15 1p
- ---8004180342 Offsite Dose Calculation Manual Revision 1

 * Northern States Power Co 80/04/30 150no
- 8004280547 Requests NRC review of proposed implementation of short-term Lessons Learned Task Force recommendations re Item 2 1 6 b. "Plant Shielding Review." Item 2 1 7. "Reactor Vessel Head Vent." & Item 2 2 26. "Onsite Technical Support Ctr" MAYER.L D Northern States Power Co 80/04/25 1p
- O Inspection reports, IE Bulletins & correspondence
- B004100249 Forwards IE Insp Repts 30-282/80-01 & 50-304/80-01 on 800102-31 & notice of violation HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004100283 Natice of violation from inap on 800102-31 * Region 3. Chicago, Office of the Director 80/02/22 2pp
- --8004100270 IE Insp Repts 50-282/80-01 & 50-304/80-01 on 800102-31 Noncompliance noted containment spray additive tank isolated from containment spray sys & failure to follow operating procedure, FEIERABEND.C, D , BOYD, D C Region 3, Chicago, Office of the Director 80/02/22 7pp
- B00407005B Responds to IE Bulletin 79-17, Revision i, "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " Required visual insp completed on Unit 1 in Feb 1980 No corrective actions nacessary.

 OLLBERTS, D E Northern States Power Co 80/03/07 lp
- 8004070210 Responds to IE Bulletin 79-27 outlining conclusions from investigation of instrument buses Design change initiated to replace instrument inverters w/inverters capable of automatic transfer to alternate ac QILBERTS, D E Northern States Power Co 80/03/07 2pp

- 8004100143 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER, J Ø Region 3, Chicago, Office of the Director 80/03/07
- 8004040456 Responds to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Delay until 800314 approved by J Hughes in 800229 telcon Evaluates components & sys qualification for expected operational conditions OILDERTS, D E Northern States Power Co 80/03/13 4pp
- 8004100067 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-282/79-32 & 50-306/79-26
 DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/03/20 lp
- --8004100070 Responds to NRC 800207 ltr re violations noted in IE Insp Repts 50-282/79-32 % 50-306/79-26 Discusses collection of Xe-133 gas samples wiow level gas headers GILBERTS, D E Northern States Power Co 80/02/27 2pp
- 8004140013 Responds to IE Bulletin 80-03 re loss of charcoal from std adsorber cells Visual insp of charcoal filters installed revealed no degradation or sagging Datailed visual insp of each filter performed annually GILBERTS, D.E. Northern States Power Co. 80/03/24 2pp
- 8004150184 Forwards IE Info Notice 80-12, "Instrument Failure Causes Dening of PDRV & Block Valve " No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31
- 8004080719 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J O Region 3. Chicago: Office of the Director 80/04/01
- 8004150052 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- BOO4180055 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800304 transmittal KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- 8004220148 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/02 in
- 800422037B Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/04/03
- 8004230297 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07
- 8004220047 Forwards IE Bulistin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director, 80/04/09
- 80042304B0 Forwards Revision 4 to "ABME Code XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ABME Code Section XI Requirements " MAYER.L D Northern States Power Co 80/04/17 2pp
- --8004230487 Revision 4 to "ABME Code XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements "

 ** Northern States Power Co = 80/04/17 35pp
- R Periodic operating reports & related correspondence
- 8004140339 Forwards monthly operating rept for Mar 1980 MAYER.L O Northern States Power Co 80/04/10 1p

- ~~8004140344 Monthly operating rept for Mar 1980 HUNSTAD, A.A. Northern States Power Co. 80/04/01 Bpp
- S Reportable occurrences, LERs & related correspondence
- 8004080478 Forwards updated LER 79-030/03X-3 MAYER.L D Northern States Power Co 80/04/03 is
- --8004080484 Updated LER 79-030/03X-3 on 791121 during inspirer IE Bulletins 79-14 & 79-02, two snubbers in cooling water sysfound installed incorrectly & five hangers found damaged or in violation of safety requirements Inspiring ongoing HUNSTAD.A A Northern States Power Co 80/04/03 ip
- 8004140435 Forwards LER 80-009/03L-0 MAYER/L 0 Northern States Power Co 80/04/09 ip
- ~-B004140440 LER 80-009/03L~O on 800710, during normal operation, nuclear power range channel 1844 was inoperable for several minutes Caused by latch-up of high voltage power supply due to spike on yellow instrument bus Fuses were removed & reset HUNSTAD, A A Northern States Power Co 80/04/09 ip
- 8004150587 Forwards LER 80-010/03L-0 MAYER.L O , Northern States Power Co 80/04/10 1p
- --8004150603 LER 80-010/03L-0 on 80031; during surveillance test, containment isolation valve 11 opened at 0 57 psi Caused by apparent drift in Barton Model 288A differential pressure switch Setpoint adjusted & valve retested satisfactorily HUNSTAD, A A Northern States Power Co 80/04/10 1p
- 8004230358 Forwards updated LER 80-010/03L-1 MAYER, L. D. Northern States Power Co. 80/04/17 1p
- --8004230359 Updated LER 80-010/03L-1 "cause code" & "component manufacturer" corrected HUNSTAD, A A Northern States Power Co 80/04/17 1P
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1
 P Operating license stage documents & correspondence
- B004030275 Discusses NRC B00307 site visit to review implementation of Category A Lessons Learned requirements Addl licensee action/discussion is necessary by 800314 Request for addlines onci REID.R W Operating Reactors Branch 4 80/03/10 ip
- GD04G30102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethasda Operations Ctr EISENHUT, D O Division of Operating Reactors 80/03/12 Spp

- 8004220561 Responds to NRC 800327 request by providing info regarding implementation of Lessons Learned Task Force item re automatic initiation of auxiliary feedwater sys Control grade sys complying w/requirements has been installed JONES.H C Omeha Public Power District 80/04/08 3pp
- 8004240836 Ack receipt of 800211 ltr by forwarding response to J Weber 800211 questions re power rating REID.R W Operating Reactors Branch 4 80/04/09 Spp
- B004280040 Forwards Amend 47 to License DPR-40, safety evaluation & notice of issuance & availability
 REID,R W Operating Roactors Branch 4 B0/04/11 2pp
- --8004280044 Amend 47 to License DPR-40, changing Tech Specs to be consistent w/Cycle 6 fuel reload analysis & revising coolant sys heatup & cooldown QAMMILL.W P Operating Reactors Branch 4 80/04/11 51pp
- --8004280046 Bafety evaluation supporting Amend 47 to License DPR-40 a Operating Reactors Branch 4 80/04/11 28pp
- ---8004280047 Notice of Issuance & availability of Amend 47 to License DPR-40 REED.R W Operating Reactors Branch 4 80/04/11 2pp
- 4 Inspection reports, IE Bulletins & correspondence
- 8004040252 Forwards IE Insp Rept 50-285/80-01 on 600114-17 No noncompliance noted MADBEN.O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/05 2pp
- --8004040262 IE Insp Rept 50-285/80-01 on 800114-17 No noncompliance noted Major areas inspected plant operations & prerefueling activities KELLEY,O L . WESTERMAN, T F Region 4. Dallas. Office of the Director 80/02/04 App
- 9004080591 Forwards IE Insp Rept 50-285/B0-02 on 800128-0201 No noncompliance noted MADBEN Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/14 2pp
- ~-B004080696 IE Insp Rept 50-285/80-02 on 800128-0201 No noncompliance noted Major areas inspected second periodic containment integrated leak rate test WEBTERMAN, T.F., KELLEY, D.L., HALL, R.E. Region 4, Dailas, Office of the Director 80/02/13 4pp
- 8004290086 Forwards response to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " Based on util review, adequate indication & annunctation available to identify bus failure JONES, N C Omaha Public Power District 80/02/21 App
- 8004140021 Forwards response to Items 1,2,3 % 5 of IE Bullstin 79-01B Chart of svc condition profiles & master list of Class IE components required to function under accident conditions encl
 JONES,W C Omaha Public Power District. 80/03/03. 200pp
- 6004070033 Forwards IK Insp Rept 50-285/80-05 on 600212-15.No noncompliance noted MADSEN/O L Region 4. Dallas. Reactor Operations Nuclear Support Branch. 60/03/19 2pp
- --8004070036 IE Insp Rept 50-285/80-05 on 800212-15 No noncompliance noted Major areas inspected review of security plansphysical barriers, lighting & alarm stations, Details withheld (10CFR2 790) CALDMELL.R A , EVANS, C A Region 4, Dallas, Office of the Director MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/03/19 2pp.
- 8004110489 Forwards IE Insp Rept 50-285/80-04 on 800305-07. No noncompliance noted Details withheld (ref 10CFR2 790), HIND, J.A. Region 3, Chicago, Safeguards Branch 80/03/27, 2pp
- --B00411049B IE Insp Rept 50-285/80-06 on 800305-07. No noncompliance moved Major areas inspected, facility organization & controls, inventory & verification, shipping & receiving, storage & controls Details withheld (ref 1005R2, 790)
 HIND, J. A. Region 3, Chicago, Bafeguards Branch, PATTERSON, J.P., FINLEY, A.G., Region 3, Chicago, Office of the Director, B0/03/25 ip.

- 8004190234 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary
 - Region 4. Dallas. Office of the Director 80/03/31 SEYFRIT, K V
- BOD4080670 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/01
- 8004110102 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response
- SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180496 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180158 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil 8ys " No written response required SEYFRIT,K V Region 4, Ballas, Office of the Director 80/04/03
- 8004230354 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required BEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/04
- R Periodic operating reports & related correspondence
- HDC4190391 Forwards monthly operating rept for Mar 1980 JDNES,W C Dmaha Public Power District 80/04/02
- ---8004150375 Monthly operating rept for Mar 1780 HICKLE, B J Omaha Public Power District 8 80/04/02 17pp
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8004020110 Advises of FES issuance re selection of preferred alternative closed-cycle cooling sys.NURE0-0574, Dec 1979 Future discussions re simplification of proceeding. LEWIS 8 H Hearing Branch 2 80/03/19 1p
- --B004020126 Bummary of mesting w/PASNY re DEB, selection of preferred closed cycle cooling sys & related issues NRC will draft stipulation for parties' comments OECKLER,R P Environmental Projects Branch 1. 79/09/14 Jpp
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8004180281 Addresses questions in 800214 memo on R Pollard allegations re facility SER Issue of containment isolation valves was previously addressed R Pollard Input & final SER are substantially same SER excerpt encl
 DENTON, H R. Office of Nuclear Reactor Regulation. 80/04/03 9pp
- ~-B004iB0286 Responds to 770ii0 ltr re possibility of tornado damage & re-evaluation of containment isolation features of auxiliary steam supply & condensate return lines satisfy Criterion 97 of general design criteria BCHWENCER.A. Operating Reactors Branch 1 78/09/27 7pp
- ---B0041B0294 Submits questions about R Pollard allegation at B00205 commission meeting re BER inaccuracies & plants not meeting current regulations on containment isolation & environ qualification. Transcript excerpt encl.
 BRADFORD, P. A. Commission 80/02/14 9pp BRADFORD, P. A
- B004220462 Discusses B00926 ltr re request to have UCS identify inaccuracies in plant BER in support of NRC review. Requests info re purpose of request & findings of review. Buggests procedure to identify BER discrepancies for Units 1 & 2 WEISS.E R Sheldon. Harmon & Weiss B0/04/17 2pp

- F Security, medical, emergency & fire protection plans
- 8004100100 Comments on proposed rule 10CFR50 10-mile emergency planning ione for plume exposure lacks technical justification NRC adopted position w/o studying validity of underlying bases WEISB.E R Sheldon, Harmon & Weiss 80/02/19 5pp
- ~~8004100127 Statement before NY City Council, "Impact on NY City of Reactor Accidents at Indian Point," (corrected 790620) BEYEA, J Princeton Univ 79/06/20 49pp
- 8004080695 FOIA request, on behalf of UCS, for time analysis required to evacuate public from 10-mile area surrounding facilities WEISS, E.R. Sheldon, Harmon & Weiss 80/03/20 1p
- 8004080690 Responds to FOIA request for time analysis required to revacuate public from 10-mile area surrounding facilities
 Forwards rept. "Evacuation Times Estimates for Areas Near
 Site " W/o encl
 FELTON, J M Division of Rules and Records 80/03/31 1p
- 8004250382 Forwards imput to fire protection review for Items 3 1 8(2). Seprinkler sys. Item 3 2 4, cable spreading nom & Item 3 2 1, separation of instrumentation in containment HALL.R C Brookhavan National Laboratory 80/04/17 3pp
- **G** Adjudicatory correspondence
- 8004020091 Forwards UCS 800310 comments on director's decision under 10CFR2 206 Decision & confirmatory order do not resolve critical issues Objects to exclusion of petitioner from meetings & correspondence solving issues
 WEISSLE R Sheldon, Harmon & Weiss 80/03/10 2pp
- --B004020099 Comments on director's decision under IOCFR2 204 Decision & confirmatory order do not resolve crucial issues re site suitablisty & do not establish necessity schedule or stds of mads Urges disqualification of JM Handrie W/documentation WEISB,E R Union of Concerned Scientists WEISB,E R Sheldon, Harmon & Weiss 80/03/10 43pp
- --8004020109 Responds to /30717 ltr re siting criteria Facility site does not meet NRC regulations & criteria
 HENDRIE, J H Commission 73/09/10 3pp
- 8004070047 Order granting extension until 800414 for Commission to review director's 800211 decision HOYLE,J C Office of the Secretary of the Commission 80/03/31
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSBICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004180073 Order granting extension until 800425 for Commission to elect whether to review ALAB-436 & ALAB-561 CHILK.S J. Office of the Secretary of the Commission 80/04/04
- 8004270002 Forwards NRC confirmatory order STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/04 ip
- --8004270006 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800530 Required info specified in Attachment A STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/04 App
- 8004220784 Forwards potition supporting UCS petition requesting decommissioning of Unit 1 % suspension of operation at Units 2 % 3 GRAVES, R B Housatonic Safe Energy Alliance 80/04/13 ip
- --8004220762 Supports UCS petition requesting decommissioning of Unit 1 & suspension of operation at Units 2 & 3 GRAYES,R 8 Housatonic Safe Energy Alliance 80/02/15 ip
- B004220030 Order granting extension.until B00430, for Commission to review Director's B00211 decision H0YLE.J C Office of the Secretary of the Commission 80/04/14

H General correspondence

- BOO2290456 Comments on ut:1 800201 ltr from 0 Berry re design safety & operating procedures Possible human failure & lack of adequate info about equipment performance (llustrates inherent danger Licensing should not continue FLEISHER.W L Affiliation Unknown 80/02/25 2pp
- BC04030016 Advises that Commission should evaluate need for power generated by facility & take close look at safety achieved for public protection GILINSKY.V Commission B0/03/11 ip
- --8004030018 Responds to 800225 ltr Forwards NY Times article re lack of need for electricity produced at facility Cites util trade association statement that reserve margin of 2% would exist if all plants in svc grid were shut down LEVINSON. J O Affiliation Unknown B0/03/02 2pp
- --8004030024 Responds to 80020B ltr supporting petition by UCS requesting decommissioning of Unit 1 & suspending operations of Units 2 & 3 Advises that Commission is reviewing comments on matter OILINSKY, V Commission 80/02/25 3pp
- ~-8004030025 Supports UCS 790917 petition requesting decommissioning of Unit 1 % suspension of operations at Units 2 % 3 Cites safety-related reasons for prompt action Certificate of Svc encl
 LEVINSON, J O Affiliation Unknown 80/02/08 3pp
- BOO4070174 Responds to FOIA request for info re facilities & damage due to barthquakes at Indian Puint Forwards Documents 1-4 listed in App A Documents 5 & 6 may be purchased by sending check in amount of \$7.50 to NRC in Hashington, D C FELTUN, J M Division of Rules and Records 80/03/19 2pp
- --8004070229 "Annual Operating Rept." 1976 * Consolidated Edison Co of New York 76/12/31 27pp
- --80D4070233 "Annual Operating Rept." 1977 TMI semiannual & annual operating rept excepts encl
 # Consolidated Edison Co of New York 77/12/31 45pp
- BOOA290054 Forwards info requested in 800218 ltr re licensing actions Matl cquld not be forwarded by 800225 as 1tr did not arrive at NRC until 800226 W/o encls DENTON, H R Office of Nuclear Reactor Regulation 80/03/25 App
- --8004190058 Requests info re changes affecting extension of OLs to Bioloi FLEISHER, Z.S. Affiliation Unknown B0/02/19 1p
- 8004180234 Forwards NRC 800325 response to encl 800218 ltr from 2E Fleisher of West Branch Conservation Association in response to 800226 request W/o encl BIRCKB, M J Office of the Executive Director for Operations 80/03/28
- ---EOO4180237 Requests info re new safety regulations FLEISHER, 2 S West Branch Conservation Association 80/02/18
- 8004210336 Advises that 791106 ltr to President Carter re emergency plans has been referred to NRC Since Summer 1979, NRC has been actively pursuing program to upgrade emergency preparedness Forwards NRC/FEMA documentation N/O encl. DENTON-H R Office of Nuclear Reactor Regulation 80/03/31 Spp
- BO041500B5 Responds to B0022B ltm re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in beavily populated areas Interim measures have already been ordered at sites DENTON. H R Office of Nuclear Reactor Regulation B0/04/01 2pp
- --B004150094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER, J W Affiliation Unknown 80/02/28 1p
- BOO4160173 Responds to B00212 ltr re continued operation of nuclear power plant Add1 measures should be implemented that will further reduce probability of severe reactor accidents Licenses has been in shutdown pending completion of actions DENTON, H. R. Office of Nuclear Reactor Regulation 80/04/01 2pp

- 8004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DENTON: H.R. Diffice of Nuclear Reactor Regulation 80/04/01 2pp
- 8004210088 Responds to 800125 request re public hearing & determination on UCS petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences

 DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004210093 Requests scheduling of public hearing & determination of UCB petition re operation of Pacility prior to reactivation Concerned for health & safety of community SCIANDRA, J. New York, NY 80/01/25 ip
- 8004210193 Responds to 800207 ltr re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants Interim measures have already been ordered at sites DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- ---8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant, lowering rates & dependency on foreign oil WU.J Affiliation Unknown 80/02/07 1p
- 8004210208 Responds to 800204 itr re continued operation of facility Plants reviewed to determine what addi measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210223 Urges NRC to decide in favor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shut down

 GAY R Affiliation Unknown 80/02/04 1p
- 8004250013 Responds to 800212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure DENTON.H R Office of Nuclear Reactor Regulation 80/04/01. 2pp
- --8004250030 Urges that NRC consider UCS petition re closing of facility Possibility of earthquake exists w/plant built near fault. Only 20% of area energy generated by fuclear power Alternatives should be considered GDLDHGR.F Affiliation Unknown BO/02/12, 1p
- 8004290019 Responds to 800215 itr re operation of facility NRC considering special measures to reduce probability of severe reactor accident or to lessen consequences Confirmatory orders issued as interim measure
 DENTON, H R Office of Nuclear Reactor Regulation, 80/04/01 2pp
- --8004250033 Urges NRC to approve UCB petition re shutdown of facility because of proximity to New York City & impossibility of evacuation of so many people MOB.L L., MOB.M. Affiliation Unknown 80/02/18 ip.
- 8004230185 Advises that NRC held two meetings in NY re continuing operation at facility. Commission presently considering form of review Public comments invited Request for another hearing in vicinity of plant will be considered.

 DENTON: HR Office of Nuclear Reactor Regulation 80/04/03, ip
- --8004230190 Requests that NRC hold another public hearing re continuing operation of facility to offer public chance to question , plant operators & govt agencies Public should be properly notified through local news media CONNOR, R J New York, State of 80/01/08 2pp
- 8004280287 Responds to 800225 ltr re facility safety Shutdown not ordered due to interim measures imposed by encl confirmatory order M/o encl
 EIBENHUT, D 0. Division of Operating Reactors 80/04/07 1p
- 8004280140 Responds to 800117 ltr to DDE re 800117 incident at facilities Plant did not trip during minor earthquake tremor Epicenter of tremor was located approx seven miles from site. Tremor was significantly below design capability EISENHUT, D G Division of Operating Reactors 80/04/08 1p

- P Operating license stage documents & correspondence
- 8004070094 Forwards agenda & proposed rule for NRC sponsored 800115 meeting in New York.NY re proposed rule on emergency response RYAN.R G Office of State Programs 79/12/31 12pp
- --8004070098 Requests opportunity to testify at NRC 800115 meeting in New York:NY re emergency response plans in fifty-mile ione around plant NY City Council has been holding hearings on resolution to phase out plant FRIEDLANDER:M New York:NY 79/12/21 ip
- 8004030309 Summary of B00123,24 & 30 site visits to facility to identify problems to determine extent of compliance w/ outstanding items Facility meets all short-term Lessons Learned Task Force requirements TELFORD, J T NRC Three Mile Island Task Force B0/02/19 Spp
- 800418038? Forwards modified near-site study in response to NRC 791205 request for 60-day crash effort PEOPLES.D L Commonwealth Edison Co DAVIS, J.F. Power Authority of the State of New York CAHILL.W J Consolidated Edison Co of New York 80/02/25 ip
- -8004180375 "Near-Bite Study " Viewgraphs encl * Commonwealth Edison Co * Consolidated Edison Co of New York * Power Authority of the State of New York 80/02/25 95pp
- B004040260 Forwards response to 791221 ltr addressing NRC requirements for auxiliary feedwater sys at facility NRC review & addl info required for completing review encl Urges reply no later than 30 days from receipt of ltr BCHWENGER.A Operating Reactors Branch 1 B0/03/05 6pp
- NO.4040423 Forwards response to 791219 1tr addressing NRC requirements for auxiliary feedwater sys at facility. NRC review & add1 required info for completing review encl Urges reply no later than 30 days from receipt of itr SCHWENCER. A Operating Reactors Branch 1 80/03/05 7pp
- 8004280223 Forwards SEP schedule & content requirements for environ qualification of electrical equipment Previously submitted info should be incorporated by specific ref Unit exempt from IE Bulletin 79-018

 9CHWENCER, A Operating Reactors Granch 1 80/03/05 4pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D. 0 Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004140221 Summary of 800221 meeting w/representatives of all SEP plants utils & Franklin Research Ctr re accolorated program for evaluating qualification of safety-related electrical equipment WILBON/R Plant Systems Branch 80/03/14 3pp
- B004110045 FOIA request, on behalf of VCB, for Sandia Labs study re liquid effluent pathway at facility WEIBB,& R Sheldon, Harmon & Heiss B0/03/18 ip
- 8004240163 Forwards addl info & clarification re guide for evaluating environ qualification of Class IE electrical equipment in operating reactors & for identification of appropriate safety equipment of SEP reactors SCHWENCER.A Operating Reactors Branch 1 80/03/20 15pp
- B004110001 Forwards corrected attachment to Amend 29 to License DPR-44 forwarded in NRC 800221 ltr Attachment lists page numbers of revised pages to be removed & inserted SCHWENGER.A Operating Reactors Branch 1 B0/03/21 3pp
- 8004140014 Responds to statement during 800225 meeting re many significant discrepancies between inputs to SER & published public version Identification would be helpful so appropriate action can be taken SCHENCER.A Operating Reactors Branch 1 80/03/26 ip
- B004100169 Notification of 800403 meeting w/util in Bethesda.MD re environ qualification of electrical equipment DLSHAN.E N Operating Reactors Branch 1 80/03/31 2pp

- B004080381 Forwards response to L Dishan B00217 verbal request for summary of original evaluations of RCS Includes tables providing seismic loads for RCS piping & supports EARLY.P J Power Authority of the State of New York
- 8004210112 Advises that 780831 amend application re secondary water chemistry monitoring falls in Class II fee category Refund will be forwarded for Class III overpayment MILLER:W O License fee Management Branch 80/04/01 Ip
- 800411003B Responds to FOIA request for Sandia Labs study re liquid effluent pathway at facility Rept is undergoing NRC technical review prior to publication Draft encl FELTON.J M Division of Rules and Records 80/04/02 1p
- --8004110051 Draft study of facility liquid effluent pathway * Sandia Laboratories 80/04/02 800pp
- 8004170061 Submits anfo requested at 800111 meeting w/NRC recontainment bldg basemat X-ray defraction test performed to determine crystalline % noncrystalline calcium compounds & silicon dioxide Results listed EARLY,P J Power Authority of the State of New York 80/0 Power Authority of the State of New York 80/04/08
- 8004250167 Forwards request for info as part of NRC upgrade review of QA program Includes info re requirements & methodology for determining how & to what estent QA program will be applied to specific items & activities

 SCHWENCER.A Operating Reactors Branch 1 80/04/08 7pp
- 8004240480 Forwards addl info re review of unresolved safety issues, trip rept of Lessons Learned implementation team, & task action plan in view of high population density surrounding DENTON, H.R. Office of Nuclear Reactor Repulation 80/04/09 33pp
- --8004240483 Summary of Westinghouse Lessons Learned team 800121-22 site visit to determine status of Category A implementation Attendance & status lists encl TELFORD.JT Safeguards Standards Branch 80/02/18 Spp
- --8004240486 Bummary of Westinghouse Lassons Learned team 800124-25 site visit re status of Category A implementation Attendance & status lists encl TELFORD, J T Safeguerds Standards Branch 80/02/20 Spp
- --80042404B9 Summary of Westinghouse implementation team 800123-24 & 30 site visit re short-term Lessons Learned requirements TELFORD, J T Safeguards Stendards Branch 80/02/15 8pp
- ---8004240472 Forwards evaluation of util actions taken to satisfy Lessons Learned Category A requirements Concludes all requirements satisfied Attendance list for 800121-22 site visit encl SHCWENCER, A Operating Reactors Branch 1 (Pre 791030) 80/02/29
- ---8004240504 Forwards evaluation of util compliance w/Category A Lessons Learned requirements Concludes all requirements satisfied IE followup & attendance lists encl GCHWENCER, A Operating Reactors Branch I (Pre 791030) 80/02/21 14pp
- --8004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON.H R Office of Nuclear Reactor Regulation 80/02/21
- ---8004240518 Discusses Event 5 probabilities Suggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements TAYLOR.K A Division of Reactor Safety Research 80/01/15 17pp
- BOO4290232 Forwards status of unresolved safety issues at Indian Point 1 & 2, trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON, H R Office of Nuclear Reactor Regulation BO/04/09, 34pp
- 8004280054 Forwards status of unresolved safety issues at Indian Point 2 & 3, trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON, HR Office of Nuclear Reactor Regulation 80/04/09 34pp

- 8004280113 Forwards safety evaluation re util 800127 t 0227 LOCA reanalyses All assumptions in analyses are conservative Analyses provide acceptable basis for operation within limitation of Tech Specs
 SCHWENCER, A Operating Reactors Branch 1 80/04/09 2pp
- ~-8004280120 Safety evaluation concluding that assumptions made in util 800127 & 0227 LOCA reanalyses are conservative Analyses provide acceptable basis for operation within limitation of Tech Specs

 * Office of Nuclear Reactor Regulation 80/04/09 2pp
- BOO4R40458 Formalizes plans re series of technology exchange meatings re facilities' accident mitigation features activity Five meetings suggested Recommended meeting schedule & agenda items encl

 8CHWENCER.A. Operating Reactors Branch 1 80/04/10 15pp
- BO04180343 Responds to NRC 800305 Itr re auxiliary feedwater sys Forwards commitment detes &/or responses re level indication & alarm control room & results of endurance test on steam driven auxiliary feed pump

 EARLY.P J Power Authority of the State of New York BO/04/11
 Top
- 83004180350 Forwards responses to 60-day action items of NRC 800211 confirmatory order (interim actions) Steady state generator operating level was chosen on basis of analyses & set point-type studies Level optimized w/Class I transients EARLY.P J Power Authority of the State of Neu York 80/04/11 1000
- G Inspection reports, IF Bulletins & correspondence
- BO04080632 Forwards response to IE Circular 78-08 & IE Bulletin 79-01 re environ qualification of safety-related electrical equipment Basic requirements of FSAR have been met Transmitters environmentally qualified BANE. J P Power Authority of the State of New York 79/06/13 7800.
- 8004220787 Responds to IE Bulletin 79-i7 Examination of stagnant borated water sys detected no visible leaking on normally accessible welds

 BAYNE.J P Power Authority of the State of New York 80/02/04
- BO04090354 Forwards response to 1E Bullotin 79-14 Complete listing of static span table analyzed lines encl Representative sample of bldgs & components investigated for seismic input to design specs
 BCHMIEDER, J.R. Power Authority of the State of New York 80/02/25
- #3004080328 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Review requires addi procedure guidance to be submitted within 60 days Site design differs from bulletin aus PAYME, J P Power Authority of the State of New York 80/02/28 20s
- ©OO4030267 Submits response to IE Bulletin 79-18 re audibility problems encountered on evacuation of personnel from high noise areas Performed survey to determine adequacy of notification sys Results indicated sys needs upgrading DAYNE, J P Power Authority of the State of New York 80/03/03 ip
- BOO4220004 Forwards interim safety evaluation rept of piping reanalysis in response to IE Bulletin 79-07 Total reanalysis package should be submitted by 800411 & supports should be modified by 800420
 BGHWENCER, A Operating Reactors Branch 1 80/03/24 2pp
- ---B004220007 Safety evaluation supporting review of piping reanalysis in response to 1E Bulletin 79-07 * Operating Reactors Branch 1 80/03/24 2pp
- BOO4210056 Ack receipt of 800103 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-286/79-24

 SMITH, O H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/26 ip

- --8004210064 Forwards IE Insp Rept 50-286/79-24 on 791030-31 & notice of violation SMITM G H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/12/11 2pp
- --8004210068 Notice of violation from insp on 791030-31 * Region 1, Philadelphia, Office of the Director 79/12/10 ipp
- ---8004210070 IE Insp Rept S0-286/79-24 on 791030-31 Nuncompliance noted failure to maintain results of surveys re personnel monstoring requirements for individuals entering steam generators
 STOHR, J.P. Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch EERABIAN, J.A. Region 1, Philadelphia, Office of the Director 79/12/10 Spp
- 8004150280 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090092 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 ig
- B004110163 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director B0/04/02 ip
- BG04240333 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004180241 Forwards IE Circular 80~07, "Problems W/HPCI Turbine Oil Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director H0/04/03 ip
- 8004230452 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Stool Pipe " Action required ORIER. B H Region 1. Philadelphia. Office of the Director 80/04/04 ip
- 8004180212 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/04/07 ip
- 8004300041 Responds to IE Builetin 79-14 Forwards 3PT-V14, Revision 3, "As-Built Verification of Beismic Class I & II Pipe Supports,"

 EARLY, P J Pawer Authority of the State of New York 80/04/09
- --8004300044 "As-Built Verification of Seismic Class I & II Pipe Supports " * Power Authority of the State of New York 79/09/29 App
- BOO4150458 Submits final rept of work performed under IE Bulletin 79-07 Safety sys re-evaluated "As-built" varification of piping sys performed per field check plan Plant may continue operation M/o risk to public safety EARLY.P J Pauer Authority of the State of New York 80/04/10
- R Periodic operating reports & related correspondence
- 8004150599 Forwards "Environ Discharge Monitoring Rept for Mar 1980 " MONTI, W A Consulidated Edison Co of New York 80/04/10 1p
- --B004150609 "Environ Discharge Monitoring Rept for Mar 1980 "
 + Consolidated Edison Co of New York 80/04/10 15pp
- 8004180426 Forwards monthly operating rept for Mar 1980 BAYNE, J P Power Authority of the State of New York 80/04/15 ip
- --8004180424 Monthly operating rept for Mar 1980 CONNELL.C Power Authority of the State of New York, 80/04/03 7pp.

- 8004210269 Forwards "Daily Counts from Intake Screens, Mar 1980," re fish collections Circulators were shut down for month at Unit 1
 - CAHILL, U.J. Consolidated Edison Co. of New York 80/04/15 1p
- --- 8004210276 "Daily Counts from Intake Screens, Har 1980," re fish collections
 * Consolidated Edison Co. of New York 80/04/15 App.
- S Reportable occurrences, LERs & related correspondence
- 8004210440 PNO-77-172 on 770926. Units 2 & 3 tripped from 100 & 91% 104210440 PNO-77-172 on 770926, Units 2 & 3 tripped from 100 power, respectively Caused by spurious signals in reactor protection sys resulting from electrical disturbances in Buchanan substation State of NY informed KLINOER, Q Region i, Philadelphia, Office of the Director 77/09/27 1p
- 8004110437 Forwards LER 80-002/03L-0 BAYNE, J P Power Authority of the State of New York 80/04/03 1p
- --8004110442 LER 80-002/03L-O on 800309, at hot shutdown, during routine check of heat trace circuitry, boric acid heat trace circuit 7 was found not continuous Cause not stated Circuit fault GUMBLE.F W Power Authority of the State of New York 80/04/03
- 8004140416 Forwards LER 80-003/03L-0 BAYNE, J P Power Authority of the State of New York 80/04/10 ip
- ---8004140422 LER 80-003/03L-0 on 800311.during hot shutdown body of valve CF-43 was leaking causing piping associated w/boiler feed pumps to become inoperable Caused by pinhole leak in valve body Valve was replaced & returned to svc GUMBLE.F W Power Authority of the State of New York 80/04/10
- 80D4180448 Forwards LER 80-004/03L-0 BAYNE,J P Power Authority of the State of New York 80/04/14 ip
- --8004180461 LCR 80-004/03L-0 on 800315, upon completion of containment sprey pump test operator attempted to open VC isolation valve 8678 w/o success Cause by key failure induced by mechanical fatigue Key & keyway repaired QUMBLE,F W Power Authority of the State of New York 80/04/14
- 8004220741 Forwards LER 80-005/03L-0 BAYNE, J P Power Authority of the State of New York 80/04/17 1p
- ---8004220749 LER 80-005/03L-0 on 800326.while operating at 75% power, signs of outboard pump bearing overheating were indicated from visual observance of auxiliary boiler feed pump Gaused by thrust bearing failure which created shaft scoring, GUMBLE.F W. Power Authority of the State of New York, 80/04/17

U Congressional/Executive Correspondence

- 8004080193 Responds to 791212 1tr re Rockland Mobilization for Survival 1tr concerning Dec 1979 public meeting on emergency preparedness Period of public comment lasted until NRC participants had listened to all speakers DIRCKS.N J Office of the Executive Director for Operations 80/03/05 2pp
- --8004080206 Discusses 791218 public maeting on emergency preparedness
 Plans should be arranged to allow ample time for public
 comment Viewpoints of citizens within facility vicinity
 appear to be unimportant to NRC
 BTERN, L D Rockland Mobilization for Burvival 79/12/09 2pp.
- 8004300272 Forwards Congressman Rosenthal 800114 ltr re concerns falling within FR 800222 notice requesting public views on proceeding issues DIRCKB, y Diffice of the Executive Director for Operations 80/04/11 ip
- ---B004300299 Conveys concerns re safety & health risks posed by plants & leck of adequate evacuation plan Urges NRC to respond to UGS petition
 RDSENTHAL.D B House of Rep , Foreign Affairs. B0/01/14 1p

- DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8004010255 Forwards list of revisions & additions that should be incorporated in 790803 revised safeguards contingency plan Revised plan incorporating revisions & additions should be submitted within 30 days info withheld (ref 10CFR2 790) REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004030197 Forwards info in support of standby shutdown facility Encl withhold (ref 10CFR2 790) PARKER, W D Duke Power Co 80/03/28 2pp
- 8004170164 Forwards Revision 4 of security plan Plan withheld (ref 10CFR2 790) PARKER, N D Duke Duke Power Cn 80/04/09 1p
- 8004220443 Advises that revised pages to safeguards contingency plan will be provided by 800430, in response to NRC 800314 PARKER, N C Duke Power Co 80/04/11 Ip

G Adjudicatory correspondence

- 8004230078 Forwards 800328 SECY-60-166 requesting amend to irradiated NOMENOUSE FORWARDS GOUGED SECTION TO PRODUSTING AMEND to IT reactor fuel in-transit physical protection requirements If amend approved. offect on NRC case re spent fuel transportation & storage will be provided HOEFLING.R K Hoaring Branch 4 80/04/01 ip
- 6004240544 Opposes licensee mution to compel discovery upon intervenor Motion constitutes part of continuing pattern of harrassment by licensee attys Certificate of Svc encl KEPFORD.C Environmental Coalition on Nuclear Power 80/04/03 Зрр

I Financial information

- 8004020334 Forwards Annual Financial Rept for 1979, annual certified financial statements, financial forecast for 1980-82 & statement re available sources of funds to satisfy liability requirements THIES, A C Duke Power Co 80/03/28 608
- --8004020339 Annual Financial Rept 1979 * Duke Power Co 80/02/11 44pp
- P Operating license stage documents & correspondence
- 8004080641 "Electrical, Instrumentation & Control Aspects of Override of Containment Purga Valve Isolation & Other Safety Feature Signals, Oconee Nuclear Station," informal rept UDY, A C EO & G, Inc FIN A-6256 8004080641 80/02/29 12pp
- 8004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl
 DENTON.H R Office of Nuclear Reactor Regulation 80/03/04 26pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT.D & Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- B004030230 Notification of 800318 meesting w/all operating B&W reactor licensees in Bethesda-MD to evaluate implications of Crystal River Unit 3 event \$ response to IE Bulletin 79-27 REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program" * Duke Power Co 80/03/26 13pp
- B004010470 Supplements B00324 ltr Confirms conversations w/NRC retesting of loss of non-nuclear instrumentation integrated control sys power on Unit i Test will be completed within 90 days of order if required PARKER.N O Duke Power Co B0/03/28 ip

- =004030179 Forwards proposed arend to facility Tech Specs Fable 4 1-3, Section 6 6 4 4(2)(a) 2 Table 6 6-1 re conitoring waste disposal programs PARKER,W O Dute Power Co 60/03/28 2pp
- B304210321 Requests followup rept to 791030 ltr re method used to demanstrate conformance wyprovisions of 400FR190 rept required by Tech Specs FEID.R W Operating Reactors Branch 4 80/03/28 2pp
- BOO4160001 Responds to 791116 Tech Bpec change application re operation of Unit 2 at full rated power during Cycle 3 Review has determined that proposed reload requires Class IV amend fee instead of Class III Requests add) fee BIGOS R M License Fee Management Branch 80/03/31 ip
- 8004080555 Forwards info re indications & controls requiring mods to maintain plant at hot shutdown independent of ICS/NNI power PARKER, W O Duke Power Co 80/04/01 2pp
- E0040B0614 Supplements B00102 ltr & confirms discussions w/NRC re reactor vessel head vent required by NUREO-0578 Remotely operable reactor vessel head vent uill be installed Design uill be similar to that of hot leg vents per B00102 ltr PARKER, W D Duie Power Co B0/04/02 lp
- GOO4210328 Summary of BO0222 meeting w/BbW owners group in Bathasda, Md re abnormal transient operational guidelines SEIGEL B L Reactor Systems Branch BO/04/02 4pp
- 8904140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS,D M Dute Power Co 80/04/03 11pp
- 8004250368 Summary of 800403 meeting w/utils. B&W, NUS Corp & McGraw-Hill in Bethesda, MD re draft NUREC-0667, "Transient Response of B&H-Designed Reactors" CAPRA, R A Standardization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 mesting w/utils & B&W in Bethesda. HD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA, R A Standardization Branch 80/04/05 2pp
- 8004280105 Forwards evaluation of implementation of Lessons Learned Tast Force Category A items All items satisfactorily implemented at Unit 1 Three remaining items at Units 2 & 3 will be met prior to restar from Mar 1980 shutdowns REID.R U Operating Reactors Branch 4 80/04/07 15pp
- 8004300137 Concurs w/800321 1tr describing safety of fuel pool 104300137 Concurs ω/800321 ltr describing safety of fuel operation ω/ο add1 cooling capacity due to delay of add1 cooler & pump installation Requests precise estimate for procurement & installation by 800601 REID:R N Operating Reactors Branch 4 80/04/09 3pp
- BOO4150465 Forwards supplemental response to NRC BOO223 request for info re primary coolant sys pressure isolation valves. Neither continuous surveillance nor periodic testing is now being performed Check valves display no lack of integrity PARKER.W O Duke Power Co 80/04/11 4pp
- B004220502 Advises that detailed analysis of thermal-mechanical conditions of reactor vessel during recovery from small breaks will be submitted 800715

 PARKER. H D Duke Power Co 80/04/14 ip
- B004220640 Supplements util 790925,1019 & 1219 ltrs re design & use of containment purge sys Requests NRC concurrence in scope of most to permit purging during operations above cold PARKER, H D Duke Power Co 80/04/15 2pp
- BOO4180356 Bubmits addl info to supplement 800324 ltr Describes parameters needed by operator to place plant in safe hot shutdown condition & testing for loss of power PARKER, H O Dute Power Co BO/04/18 2pp

- G Inspection reports, IE Bulletins & correspondence
- 8004220227 Discusses investigation of scram breaker failures at facility Adjustment mechanisms can potentially fail both ac & dc breakers IE headquarters is pursuing concerns & preparing circular on affected breakers SATTERFIELD,R Electric, Instrumentation & Control Systems Branch
- 8004070362 Responds to NRC request made during 800109-11 insp for addl info re assumptions made for support/restraint calculations performed in compliance w/IE Bulletin 79-02 Addl & original calculations for Support SR 134 encl PARKER.N O Duke Power Co 80/01/31 19pp
- 8004040358 Ack receipt of IE Insp Repts 50-269/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No proprietary info PARKER, W O Duke Power Co 80/03/10 ip
- ---8004040383 Forwards IE Insp Repts 50-269/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance STORR.J P. Region 2. Atlanta, Fuel Facility & Materials Gafety Branch 80/02/14 2pp
- --8004040402 IE Insp Repts 50-269/80-04,50-270/80-03 & 50-287/80-03 on 800121-25 & 28 & 0201 No noncompliance noted, Major areas inspected emergency facilities, equipment & procedures, means for determining release & emergency training JENKINS,6 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch PERROITI.D J Region 2, Atlanta, Office of the Director 80/02/14 11pp
- 8004080283 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Completion of Items 1, 2 & 3 documented H/o encl Duke Power Co 80/03/13 2pp PARKER, W O
- 8004240035 Forwards response to IE Bulletin 80-03. "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells " No evidence of filter degradation as described in bulletin was observed filter usy. facilities RER.W O Duke Power Co 80/03/21 2pp
- 8004230202 Ack receipt of 800204 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50–269/79-41, 50–270/79-39 & 50–287/79-41 LEMIS-R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/26 ip
- --800423023& Responds to NRC 800114 ltr re violations noted in IE Insp Repts 50-269/79-41, 50-270/79-39 & 50-287/79-41 Corrective actions technician involved given written warning & independent verification being developed PARKER. N O Duke Power Co 80/02/04 2pp
- --8004230249 Forwards IE Insp Repts 50-269/79-41,50-270/79-39 & 50-287/79-41 on 791203-10 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch BO/01/14 2pp
- --8004230247 Notice of violation from into an 791203-10. * Region 2, Atlanta, Office of the Director 80/01 80/01/11. 1p
- --8004230277 IE Insp Repts 50-269/79-41.50-270/79-39 & 50-287/79-41 on 791203-10 Noncompliance noted failure to follow maint procedures resulting in noncompliance w/Tech Specs MARTIN,R D , JAPE,F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/11 6pp
- 8004210191 Ack receipt of IE Insp Repts 50-269/80-03, 50-270/80-02 & 50-287/80-02 on 800114-24 No proprietary info PARKER, N O Duke Power Co 80/03/28 ip
- --8004210195 Forwards IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 on 800114-24 No honcompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/04 App
- --80042i0199 IE Insp Repts 50-269/80-03,50-270/80-02 & 50-287/80-02 on 800114-24 No noncompliance noted Major areas inspected IE Bulletins 79-13 & 79-17, auxiliary faedwater nozzle thermal sleeve insp & crack repair HERDT. A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS. N Region 2. Atlanta, Office of the Director 80/02/25 7pp

- 8004190511 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 800422018B Forwards IE Insp Repts 50-249/80-08,50-270/80-06 & 50-297/80-06 on 800225-29 No noncompliance noted KENNA,W B Region 2, Atlanta, Bafeguards Branch 80/03/31 2pp
- --8004220204 IE Insp Repts 50-269/80-08.50-270/80-06 & 50-287/80-06 on 800225-29 No noncompliance noted Major areas inspected security plan, security program & physical security Details withheld (ref 10CFR2 790)
 TOBIN, H J Region 2, Atlanta, Bafeguards Branch 80/03/25 ip
- 80040806ii Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written rasponse required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04. Region 2, Atlanta, Office of the Director 80/04/01
- 8004150070 Forwards IE Info Notice 80~13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required Q'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004250330 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/80-05, 50-270/80-04 t 50-287/80-04 CEMISR C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --8004250334 Responds to NRC 800220 ltr re violation noted in IE Insp Repts 50-269/80-05.50-270/80-04 & 50-287/80-04 Corrective actions areas cited were cleaned & maint practices & procedures changed to include housekeeping practices PARKER.W O Duke Power Co 80/03/14 2pp
- --8004230340 Forwards IE Insp Repts 50-249/80-05,50-270/80-04 & 50-247/80-04 on 800107-31 & notice of deviation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004250346 Notice of deviation from insp on 800107-31.

 * Region 2, Atlanta, Office of the Director 80/00 80/02/20 16
- 8004080432 Forwards steam generating operating history updating info in util 781128 ltr through 1979 refueling outage inservice PARKER, W O Duke Power Co 80/04/03 12pp.
- 8004180326 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Bys "No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/03 2n D
- 8004250357 IE Insp Repts 50-269/80-05,50-270/80-04 & 50-287/80-04 on B00107-31 Noncompliance noted failure to adhere to stated housekeeping practices in areas occupied by safety-related equipment

 HARTIN:R D Region 2, Atlanta, Reactor Operations Nuclear Support

 Branch JAPE.F Region 2, Atlanta, Office of the Director

 80/02/20 Spp
- B004230132 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME BA-312. Type 304 Stainless Steal Pipe" Action required O'REILLY, J. P. Region 2. Atlanta. Office of the Director 80/04/04
- 8004;80358 Forwards JE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P. Region 2, Atlanta. Office of the Director 80/04/07
- 8004300205 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-269/79-37. 50-270/79-34 & 50-287/79-37 UREILLY. J P Region 2. Atlanta, Office of the Director, 80/04/07

- --8004300214 Responds to NRC 800206 ltr re violations & deviations in IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 Corrective actions shift operating personnel instructed on manual transfer intercommunication sys & alarm procedures PARKER.W O Duke Power Co 80/03/03 4pp
- --8004300230 Forwards IE Insp Repts 50-269//9-37,50-270/79-34 & 50-287/79-37 on 791111.15 & 16 & notices of violation & deviation LEMIB: R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/06 2pp
- -8004300237 Notice of violation from insp on 771111,15 & 16 * Region 2, Atlanta, Office of the Director 80/01/18
- --8004300245 Notice of deviation from insp on 791111,15 & 16
 * Region 2. Atlanta, Office of the Director B0/01/18 2pp
- --8004300260 IE Imsp Repts 50-269/79-37,50-270/79-34 & 50-287/79-37 on 79111. 15 & 16 Noncompliance noted inadequate procedures to correct potential malfunctions, excessive RCS cooldown rate & failure to notify of RO within 1-h QUICK, D R , MARTIN, R Region 2, Atlanta, Office of the Director 80/01/18 dpp
- 8004240276 Forwards add1 response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Revised master sys/components list & sys component evaluation work sheets encl Add1 equipment info will be sent by 800701
 THIE8, A C Duke Power Co 80/04/21 1200pp
- S Reportable occurrences, LERs & related correspondence
- 8004160272 RO 287/80-4 rept re breach of fire barrier in cable room should have been submitted by 800327 Anticipates that rept will be submitted no later than 800411 PARKER.W O Duke Power Co 80/03/27 ip
- 8004030223 Forwards LER 80-005/03L-0 PARKER,W G Duke Power Co 80/03 80/03/31 3pp
- ---8004030224 LER 80-005/03L-0 on 800302, borated water storage tank level Channel i failed high when beliows froze Caused by removal of transmitter box cover Transmitter thawed & calibr
 - LEWIS, S.R. Duke Power Co. B0/03/31 1p
- B004160229 Forwards LER 80-004/03L-0 PARKER, W O Duke Power Co B0/04/11 3pp
- --8004160232 LER 80-004/03L-O on 800226 breach in final barrier penetrations discovered in two places Cause for missing matl in one sleeve & hole in plate of other undetermined Hourly firm watch established until firestop matl was installed LEWIS,8 R Duke Power Co 80/04/11 ip
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004100350 Forwards Revision AB to modified amended physical security plan Plan withheld (ref 10CFR2 790)
 HERBEIN, J G Metropolitan Edison Co 80/04/02 1p
- BOO4210263 Notification of 900415 meeting u/util in Behtesda re open items on fire protection per NRC 800207 ltr DIIANNI,D C Operating Reactors Branch 4 80/04/04 ip
- 8004300409 Advises that std market weather alert monitor is sufficient for use in notifying public, regardless of on-off switch HERBEIN, J O Metropolitan Edison Co 80/04/25 ip
- G Adjudicatory correspondence
- 8004100136 First set of interrogatories directed to licensee in restart proceeding re UBDA fixed nuclear facility incident plan Gentificate of Svc enci AAMODT,M M Affiliation Unknown 80/02/16 Spp
- --8004100142 Second set of interrogatories directed to State of PA in restart proceeding re relation between hypothyroidism & radioactive emissions AAMODTA M M Affiliation Unknown 80/02/22 2pp

- -CTD41/3145 Sarind set of interrogatories directed to licensee in restart proceeding re-Contention Θ concerning radiation enission data AAMUST,RIO - Affiliation Unknown - 80/02/22 - La
- -TOPA1v31*3 Thir* set of interrogatories directed to licensee in restart proceeding re-Contention 11 Loconcerning projected & procent capitalizes cost & related data
 AAMSDT.R D Affiliation Unknown 60/02/22 1p
- FIG4100155 Fourth set of interrogatories directed to licensee in restart proceeding re amended Contention 4-concerning data record 4- transmission in control room Supporting documentation & Certificate of Sov entl AAMODY N.G. Affiliation Unknown 80/02/22 Spp
- ECO4033137 Natice of taking of depositions Submits names of add1 licenses employees to be added to list provided in intervenor ECO120 notice of taking of depositions Certificate of Svcs encl HICCF, MP Three Mile Island Alert WIDCFF, MP Widoff, Reager, Seltoint; t Adjer EC/62/22 2pp
- --BO040E0145 Notice of intent to take depositions of individuals listed, all of whom served as staff or consultants to President's Commission on IMI Certificate of Svc & related correspondence encl
 HIDOFF.H P Three Mile Island Alert WIDOFF.H P Hidoff, Reager, Smitquitz & Adier 80/02/22 App
- ~-8004080150 Further amend to 800128 notice of depositions & 800214 amend to notice, adding following dates 800212 & 17 Certificate of Svc enci NUDOFF, M P Three Mile Island Alert HIDOFF, M P Hidoff, Reager, Seltowitz & Adler 80/02/22 3pp
- --8004080167 Seventh set of interrogatories. Includes questions re past b present util personnel.insp & maint log & administrative procedures esplaining use & meaning of job ticket form Centificate of Svcs and!
 HIDDEF.M.P. Three Mile Island Alert HIDDEF.M.P. Hidoff, Reager, Selkouit: & Adler 80/02/22 7pp
- --BOO40B017A Notice of taking of depositions Submits names of NRC personnel to be added to list provided in intervenor BOC20A notice of depositions Certificate of Svc encl WICOFF.H P Three Mile Island Alert WIDOFF.H P Hiddff, Research Hidoff, Reager,
- BO04220350 Certification to Commission re psychological distress issues Urges consideration of issue under NEPA for purgose of mitigating effects of THI-1 licensing activities Intervenors contentions encl JORDAN, H H . LITTLE, L H . SMITH, I H . Atomic Safety and Licensing Board Panel 80/02/22 31pp
- BOO4010064 Third set of interrogatories, re Contention 4 Includes questions re NRC monitoring of data from licensee & NRC role in restricting nath news programming in Harrisburg area during THI-2 accident AAMODT, N C Affiliation Uninown 80/02/23 1p
- --B004010070 Fourth set of interrogatories re Contentions 4 & 5 Includes questions re potential for foodstuff poisoning due to radioactive indine emissions

 AAMODT. H Affiliation Unknown B0/02/25 2pp
- --8004010072 First set of interrogatories re Contention 8 Includes questions re methods of measuring emissions during routine radioactive plant releases AAMODT.N O Affiliation Unknown 80/02/23 1p
- ---8004010076 Third set of interrogatories re Contentions 4 & 5 Includes foodstoffs AAMODT, H Affiliation Unknown 80/02/25 2pg
- --- 8004010082 Fifth set of interrogatories re Contention 4 Includes questions re NRC news release policies & radioactive salesions estimates Certificate of Svc encl AAMODT.N H Affiliation Uninpum 80/02/25 4pp
- AAMODT, N O Affiliation Unknown 80/02/23 2pp

- --8004010087 Fourth set of interrogatories re Contention 2 Includes questions re operator & senior operator basic engineering & physics training in thermal hydraulics
 AAMDDT.M M Affiliation Unknown 80/02/25 8pp
- --8004010093 Sixth set of interrogatories re Contention 2 Includes questions re tests used for licensing operators before & after TMI-2 accident Certificate of Svc encl AMMODT, M M Affiliation Unknown B0/02/25 6pp
- 8004010036 First of set of interrogatories Interrogatories limited to Contention B re emergency planning & preparedness Certificate of Syc encl SHOLLY,8 C Affiliation Unknown 80/02/25 App
- --8004010040 First set of interrogatories & document requests Includes questions re communications links between state agencies & licensee emergency event classification scheme Certificate of Svc encl
 SHOLLY, S C Affiliation Unknown 80/02/25 7pp
- --8004010042 Second set of interrogatories & document requests includes questions ro NRC assessment of adequacy of licensee proposed high radiation containment isolation signal Certificate of SHOLLY, S.C. Affiliation Unknown 80/02/25 15pp
- --8004010044 Fourth set of interrogatories & document requests Includes questions re former employees who served on THI security force & attempted acts of sabotage & theft Cartificate of Svc encl SHOLLY, S C Affiliation Unknown 80/02/25 34pp
- 8004090190 Notice of address change for intervonor Chesapeake Energy Alliance Mail should be sent to representative in Baltimore, MD Certificate of Svc encl POLLARD,R O Chesapeake Energy Alliance 80/02/27 3pp
- 8004020202 Response in opposition to SC Sholly Interrogatories 5.6.18, 22 & 29-34 of third set of interrogatories re Contention 16. Guestions bear on security planning but do not relate to alleged threat posed by Unit 2 Certificate of Svc encl BLAKE.E L. Metropolitan Edison Co. BLAKE.E L. Shaw, Pittman, Potts & Troubridge 80/02/28 7pp
- 8004070076 Motion seaking extension until 800331 to respond to intervenors' interrogatories, due to large voi & last-minute filing, re restart proceeding Certificate of 8vc encl.

 TROWBRIDGE.0 F Metropolitan Edison Co TROWBRIDGE.0 F Shaw, Pittman, Potts & Trowbridge 80/03/03 6pp
- 8004(1054) Notice of intervenor 800307 entry upon premises of TMI-1 for purpose of insp.meesuring & photographing control room storage location for radiation monitoring instruments & hydrogen recombiner Certificate of 8vc encl
 SHOLLY.S C Affiliation Unknown 80/03/03 4pp.
- --8004110546 Intervenor motion to compel licensee response to second set of interrogatories, Licensee filed objections to two intervenor interrogatories on 800225 Intervenor finds objectives w/o merit SHOLLY/S C Affiliation Unknown 80/03/07 10pp
- 8004080375 Advises of late receipt of NRC 800219 notice announcing 800226 meeting between Met Ed. General Public Utils & NRC to discuss restart open issues Urges timely transmittal of info in future WEISS, E. R. Sheldon, Harmon & Weiss, 80/03/04
- 8004110212 Correction to initial objections to second set of interrogatories from intervenor SC Sholly Explanation of objection to interrogatory 14-004 supplied W/Certificate of Svc ZAHLER, R E Metropolitan Edison Co 80/03/04 App
- 8004030320 Suppl to intervenor 800213 omnibus motion, in response to denial of oral argument re restart proceeding. Alleges little justification for funding one class of intervenors over another Budget request & Certificate of Svc encl POLLARD, R G Chesapeake Energy Alliance. 80/03/06 7pp
- B004020018 Response in apposition to certain of intervenor MI Lewis third & fourth sets of interrogatories Questions 23-25, 27-31 & 36-37 irrelevant & do not lead to admissible evidence Remaining questions will be answered W/Certificate of Syc SWARTZ, L Antitrust Division 80/03/07 12pp

- 8004030322 Response in opposition to fourth special prehearing conference order disposing restart Contentions II(C).III(A) (a) & III(A)(b) Urges revision of order due to improper determination of merits Certificate of Svc encl 80HERS.J Anti-Nuclear Group Representing York 80/03/10 4pp
- 8004110155 Forwards licensee response to TMI Alert third set of interrogatories 2AHLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/10 ip
- --8004110162 Response to third set of interrogatories Includes info re radiation releases into atmosphere & into Susquehanna River during first quarter of 1979 Affidavits & Certificate of Svc enci ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/10 16pp
- 8004210235 Forwards licensee supplemental response to TMI Alert second set of interrogatories Responses to Interrogatories 17,21,22 to 35 have been treated as document requests ZAHLER, R C. Shaw, Fittman, Potts & Trowbridge 80/03/10 2pp
- --8004210290 Supplemental response to second set of interrogatories
 Includes info re util mgt audit.TMI-1 operating & emergency
 procedures & names of all health physiciats employed at
 TMI-1 Affidavit & Certificate of Svc encl
 ZAHLER.R E Metropolitan Edison Co ZAHLER.R E Shaw. Pittman,
 Potts & Troubridge 80/03/10 7pp
- 8004040229 Motion for extension until 800324 for depositions noticed on 800128 & until 800331 for depositions noticed on 800222 rerestart proceeding License does not oppose extension Certificate of Svc encl ADLER, T A Three Mile Island Alert ADLER, T A Widoff, Reager, Belkowitz & Adler 80/03/11 3pp
- 80b4080022 Memorandum & order re Chesapeake Energy Alliance 800213 amnibus motion filed in restart proceeding Certification to Commission will not be entertained absent extraordinary circumstances Funding denied Labeling sys granted partially BMITH, I W Atomic Safety and Licensing Board Panel 80/03/11 4pp
- 8004080425 Mution to compel UCS answer to Interrogatory 8-1 of licensee 800118 first set of interrogatories ra facility restart Licensee is ontitled to identification of alleged inadequacy re UCS Contention 8 W/supporting itr & Certificate of 8vc TROMBRIDGE, 0 F Metropolitan Edison Co TROMBRIDGE, 0 F Shaw, Pittman, Potts & Trowbridge 80/03/11 8pp
- B004080720 Objections to intervenor SC Sholly fourth set of interrogatories & document requests Intervenor requests info not within scope of Contentions 15 & id Certificate of Svc encl TROWBRIDGE, 0 F Metropolitan Edison Co TROWBRIDGE, 0 F, Shaw, Pittman, Potts & Trowbridge 80/03/11 12pp
- 8004110027 Objections to Interrogatory 177 of intervenor UCS second set of interrogatories Request for info re licensee hearing preparations is irrelevant to ultimate disposition of issues Certificate of Svc encl
 TROMBRIDGE, OF Metropolitan Edison Co TROMBRIDGE, OF Shaw, Pittman, Potts & Trombridge 80/03/11 5pp
- 8004020044 First set of interrogatories directed to NRC Supplements SC Sholly 800117 interrogatories no restant proceeding Includes questions no quantity of radiation, adequacy of emergency plan & ingestion exposure Certificate of Svc encl SHOLLY, S C Affiliation Unknown 80/03/13 7pp.
- 8004030170 Motion for emergency funding to continue depositions re restart proceeding Funding approved by Comptroller General Jan 1780 opinion Requests immediate certification to Commission Certificate of Svc Encl. ADLER.T A Three Mile Island Alert ADLER.T A Widoff, Reager, Belkowitt & Adler 80/03/13 3pp
- 8004100308 Objects to interrogatories included in intervenor Aamodt Contention 2 interrogatories, fourth set. Info requested is either beyond scope of Contention 2 or irrelevant to Contention 2. Certificate of Svc encl TROMBRIDGE, 0 F Metropolitan Edison Co TROMBRIDGE, 0 F Shaw, Pittman, Potts & Trombridge 80/03/13 8pp
- 8004100433 Objections to intervenor Asmodt Family 800222 second set of interrogatories Interrogatories 1-6 do not relate to Asmodt Contention 8 or any other contention accepted by ASLB ZAHLER, R E Matropolitan Edison Co. ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/13 Rep

- --8004100436 Objections to intervenor Asmodt Family 800222 third set of interrogatories Interrogatories [-7 relate to Asmodt Contention 11 I.rejected by ASLB ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge 80/03/13 ip
- --8004100437 Dbjections to intervenor Aamodt 800225 sixth set of interrogatories Interrogatories 4-10 are unrelated to Aamodt Contention 10 or any other contention accepted by ASLB Certificate of Svc encl
 ZAHLER,R E Metropolytan Edison Co ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/13 6pp
- 8004080064 Forwards Reg Guides 1 134 & 1 145 in further response to document requests partion of intervenor second suppl to interrogatories to NRC staff Copy of MASH 1400 is on order & will be forwarded as soon as received Wo encl SOUDER, J L. Division of Rules and Records 80/03/14 1g
- 8004080678 Notice rescheduling licensee B00318 deposition to 800326 at OF Trowbridge ofc, Washington, DC, re restart proceeding Certificate of Bvc encl WEIBS, E.R. Union of Concerned Scientists WEIBS, E.R. Sheldon, Harmon & Weiss 80/03/14 3pp
- 8004100479 Objections to Chesapeake Energy Alliance first set of interrogatories Intervenor requests are irrelevant to ultimate disposition of issues Certificate of Svc encl TROMBRIDGE.0 F Metropolitan Edison Co TROMBRIDGE.0 F Shaw, Pittman, Potts & Trowbridge 80/03/14 14pp
- B004100563 Amend to notice of deposition Depositions of O Henderson, H Dougherty & T Gerusky, officials of Commonwealth of PA.will be taken on B00324 L Jackson will not be deposed BDHERS, J. Anti-Nuclear Group Representing York 80/03/14 1p
- --8004100545 Intervenor response to first set of interragatories Includes into re intervenor witnesses who will testify as to adequacy of licensee & govt emergency plans
 BOWERS.J Anti-Nuclear Group Representing York 80/03/14 ip
- --8004100567 Followsh interrogatories Includes info re 20-mile evacuation radius discussed by Chairman Hendrie on 790330 Certificate of Svc encl BOWERS.J Anti-Nuclear Group Representing York 80/03/14 2pp
- 8004080179 Forwards licensee responses to MI Lewis 800130 second set of interregatories Affidavits for responses will be forwarded shortly
 - ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/17 1p
- ---B0040B0200 Response to second set of interrogetories Includes info re history of Incident Message Form R-72 entry in radiological data log book ZAHLER:R E Metropolitan Edison Co ZAHLER:R E Shaw, Pittman, Potts & Trawbridge B0/03/17 Spp
- 8004090281 Forwards licenses responses to intervenor 800121 first set of interrogatories Affidavits will be forwarded shortly ZAHLER,R E Shaw, Pittman, Potts & Troubridge 80/03/17 Ip
- --8004070283 Response to first set of interrogatories Includes info re gaseous & liquid effluent filtration devices & measures taken in response to NUREG-0560 reactor central room design criticisms ZAHLER.R E Metropolitan Edison Co 80/03/17 13pp
- 8004090289 Forwards licensee further response to 8C Sholly 800104 first set of interrogatories Affidavits will be forwarded shortly ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/17 1p
- ---8004090275 Further response to first set of interrogatories Includes info re hydrogen control.ECCS flow rate, use of radiation monitoring devices & health physics procedures ZAHLER, R Ε Μετοροlitan Edison Co ZAHLER, R Ε Shaw, Pittman. Potts & Trowbridge 80/03/17 22pp
- 8004100277 Forwards licensee response to Sholly 800206 second set of interrogatories Afficavits for responses will be forwarded shortly ZAMLER.R E Shaw, Pittman, Potts & Trowbridge 80/03/17 ip
- --8004100285 Response to second set of interrogatories Includes info re persons who contributed to licensee emergency plan & emergency plan accident classification sys ZAMLER, R E Hetropolitan Edison Co ZAMLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/17 13pp

- 8004100476 Ack receipt of 800229 request to be informed when TMI refurns to operation ASLB will hold hearings re TMI-1 restart Hearings may commence during Summer 1980, but date of Commission final decision is not known SMITH-I W Atomic Safety and Licensing Board Panel 80/03/17 1
- --B004100478 Requests info as to when TMI will become operational again Author is General Public Utils stockholder SEKULA:P Affiliation Unknown 80/02/29 ip
- B004100537 Commonwealth of PA response to second set of interrogatories includes info re federal state & local emergency response plans Certificate of 80c encl CARTER. K. W. Pennsylvania. State of 80/03/17 33pp
- BO04100549 Response to third set of interrogatories Includes info repersons responsible for internal security, security contracts to incident repts Certificate of Svc & RA Rice affidavit encl
 BLAKE, E.L. Metropolitan Edison Co BLAKE, E.L. Shaw, Pittman, Potts
 & Trowbridge B0/03/17 15pp
- 8004100562 Response to first set of interrogatories Includes info re alleged inadequacy of natural circulation to remove decay heat Certificate of Svc encl HEISS, E.R. Union of Concerned Scientists HEISS, E.R. Sheldon, Harmon & Heiss 80/03/17 28pp
- 8004100566 Objections to Interragatories 1.5 % 6 re intervenor TMI Alert.Inc seventh set of interragatories Bocial security numbers of former employees deemed irrelevant Certificate of Syc encl
 BLAKE, E. L. Metropolitan Edison Co. BLAKE, E. Shaw, Pittman, Potts & Troubridge 80/03/17 5pp
- B004ii0175 Response to first set of interrogatories Includes info re potential for accidents at TMI-1 resulting from TMI-2 accident Centificate of Byc encil POLLARD,R G Chesapeake Energy Alliance B0/03/i7 4pp
- 8004110516 Responds to PA Public Util Commission first set of interrogatories includes info re untresses who will be called to testify by licensee Certificate of Byc & attachment widdl response encl
 TROMBRIDGE.0 F Metropolitan Edison Co TROMBRIDGE.0 F Shaw, Pittman, Potts & Trombridge 80/03/17 27pp
- 80041:0561 Forwards licensee response to TMI Albrt Inc 800128 fifth set of interrogatories Affidavits for responses will be forwarded shortly BLAKE,E L Shaw, Pittman, Potts & Trowbridge 80/03/17 lpp
- --BOC4110557 Responds to fifth set of interrogatories Includes info re independent contractors to perform maint repair & OA functions at TMI Certificate of Svc encl BLAKE.E.L. Metropolitan Edison Co. BLAKE.E.L. Shaw, Pittman, Potts & Trowbridge 80/03/17 18pp
- 8004140074 Forwards Commonwealth of PA responses to intervenor interrogatories & document requests Objects to Interrogatory OS-009 & suggests redrafting Interrogatory OS-002 interpreted very narrowly CARTER, K # Pennsylvania, State of 80/03/17 2pp
- ---8004140077 Response to first set of interrogatories Includes info re communications links between state agencies, control room & emergency planning some Affidavit of MA Railly encl CARTER: K W Pennsylvania, State of 80/03/17 Spp
- --8004140080 Response to Aamodt second set of interrogatories Includes info re connection between incidence of hypothyroidism in PA & TMI-2 accident E8 Boudin, GK Tokuhata & MA Reilly draft affidavity encl CARTER, K W. Pennsylvania, State of 80/03/17 9pp
- --8004440084 Becond response to first set of interrogatories Includes info re persons employed by Commonwealth of PA who were notified by licensee of TMI-2 accident Affidavit of JI Everly & Certificate of Svc encl
 CARTER
- 8004080676 Hemorandum & order rejecting Chasapeake Energy Alliance 800213 late Contentions 14 & 15 NURES/CR-1270 upon which contentions are based, does not deal u/newly discovered info re human factors in control roum design BMITH, I W Atomic Safety and Licensing Board Panel 80/03/18 5p

- 8004080026 Memorandum & order shortening time for answering motions to compel discovery re restart proceeding, to five days after svc of motion Requests for extension will be entertained time to answer motions served prior to order, shortened SHITH, I W Atomic Safety and Licensing Board Panel 80/03/19 3pp
- 8004090189 Motion to compel responses by licensee to fourth set of interrogatories & document requests Licensee 800311 objections attempt to carvo out scope of restart contentions Certificate of Evc enci SHOLLY.8 C Affiliation Unknown 80/03/19 17pp
- 8004210453 Responses to Aamodt first set of interrogatories Includes info re agricultural emergency plans Affidavits & Certificate of Bvc encl CARTER, K.W. Pennsylvania, State of 80/03/19 23pp
- 8004110077 Forwards licensee enswer to SC Sholly Interrogatory 08-006, re restart proceeding.
 ZAHLER E Shew, Pittman, Potts & Trowbridge 80/03/20 ip
- --80041i0081 Response to SC Sholly Interrogatory 08-006 of first set of interrogatories, re restart proceeding Sept 1979 accident classification sys.NUREO-0610, has been adopted by licensee in emergency plan * Metropolitan Edison Co 80/03/20 5pp
- BCO41100B5 Response in opposition to SC Sholly BCO303 motion to compel answers to second set of interrogatories Theoretical assumptions underlying emergency plan impossible to document, due to reliance on thoughts rather than facts ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittmah, Potts & Trowbridge 80/03/20 9pp
- 8004110100 Responds to ASLB 800123 third special prehearing conference order requesting extent to which emergency plan has incorporated NUREO-0374 Class 7 accident considerations Response to Sholly Interrogatory 08-006 provides info ZANLER.R E Hatropolitan Edison Co ZANLER.R E Bhaw, Pittman, Potts & Trowbridge 80/03/20 2pp
- 8004250063 Response in opposition to licensee objections to Aemodt 800229 third set of interrogatories Asserts that appropriate relationship exists between interrogatories & Contention 4 re restart proceeding AAMODT, N O Affiliation Unknown 80/03/20 2pp
- --B0042500Bl Response in apposition to licensee objections to Aamodt second set of interrogatories Challenges licensee assessment of radioactive matl quantities & licensee capability under projected waste mgt mechanisms

 AAMODT.N O Affiliation Unknown B0/03/20 ip
- --8004250475 Response in opposition to licensee objections to Aamndt interrogatories re Contention 4 Questions licensee refusal to disclose tests prior to Apr-May 1780 Requests permission to question employees re training W/Certificate of 8vc AAMODT,M M Affiliation Unknown 80/03/20 5pp
- BO04020104 Suppl to NRC position on need to consider Class 9 events previously submitted in response to ABLB 791218 first special prehearing conference order SINOERAL N Hearing Branch 2 TOURTELLOTTE, J Hearing Branch 4.
- --8004020107 Suppl to NRC 800131 position on need to consider Class 9 events Summarizes & discusses action plans & accident scenarios & measures Plans & recommendations for rulemaking will be placed before Commission W/Certificate of Svc SINGER.L N Hearing Branch 2 TOURTELLOTTE, J Hearing Branch 4 80/03/21 18pp
- B004090399 Advises of TMI Alert lack of financial resources to participate in restart proceeding Urges ABLB to use power & good auspices in order to help provide funding, permitting intervenor continued activity in discovery, W/eyc list.

 ADLER, T. A. Widoff, Reager, Selkowitz & Adler 80/03/21 3pp
- 8004010287 Forwards Commission 800321 memorandum & order vacating part of ASLAB 791207 memorandum & order ALAB-573, re consideration of Class 9 accidents' consequences W/o encl SINGER, L N Hearing Branch 2 80/03/24 3pp.
- B004010315 Response in opposition to MI Lewis 800304 request to compel discovery Urgas issuance of protective order re Interrogatories 14 & 18 Response to Interrogatory 15 re leak reduction will be prepared Certificate of Svc encl. SWARTZ.L.L Antitrust Division 80/03/24 App

- 8004010814 Response in opposition to UCS 800311 motion to compel NRC answer Renews & confirms objections to Interrogatory 210 due to irrelevancy & under protection of Privacy Act NRC will proceed w/Interrogatory 211 Certificate of Svc encl SWARTZ, L L Antitrust Division 80/03/24 6pp
- 8004100010 Motion to compel intervenor Environ Coalition on Nuclear Power to respond to licensee first set of interrogatories Although ASLB granted extension until 800317. Intervenor neither responded nor objected to interrogatories ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge 80/03/24 1p
- --B004100015 Mation to compel intervenor TMI Alert to respond to licensee 800114 first set of interrogatories Although ARLB granted extension until 800317, intervenor neither responded nor objected to interrogatories Cartificate of Svc encl ZAHLER, R E Metropolitan Edison Ca ZAHLER, R E Bhaw, Pittman, Potts & Trowbridge 80/03/24 4pp
- 8004100464 Forwards notarized signed affidavits for "Licensee Response to Interrogatories (Fifth Set) of TMI Alert Inc "
 2AHLER, R E Shaw, Pittman, Potts & Trowbridge 80/03/24 13pp
- 8004230037 Ciarification of intervenor 800306 suppl to amnibus motion Urges ASLB to grant financial assistance due to intervenor lack of resources to contribute effectively to psychological distress issue Centificate of Svc encl PCLLARD, R Q Chesapsaka Energy Alliance 80/03/24 4pp
- 8004080630 Memorandum & order advising licensee that intervenor Aamodt B00321 pleadings should be treated as motions to compel discovery or restart proceeding SMITH.1 W Atomic Bafety and Licensing Board Panel B0/03/25 2pp
- 8004110157 Interrogatories directed to MRC re psychological distress issue.Contention 4 in restart proceeding Requests specification of NRC position.controversial aspect of contention & credibility of licensee PULLARD.R Q Chesapeake Energy Alliance 80/03/26 3pp
- --8004i10i64 Interrogatories directed to licensee re psychological distress contention in restart proceeding Requests adoption of enci 800326 interrogatories directed to NRC POLLARD:R G Chesapeake Energy Alliance 80/03/26 ip
- --8004110164 Interrogatories directed to State of PA re psychological distress contention in restart proceeding Requests adoption of encl 800326 interrogatories directed to NRC Certificate of Svc encl POLLARD.R Q Chesapeaks Energy Alliance 80/03/26 2pp
- 8004080347 Discusses MI Lewis request for documents contained in 800215 further discovery & interrogatories Request for documents authored by RE Webt should be directed to author. CUTCHINJ M Hearing Branch 3 80/03/27 2pp
- 8004100452 Forwards FR notice of proposed rule, "Physical Protection of Plants & Matla:Access Controls to Nuclear Powerplant Vital Areas: "& 8ECY 80-131, "Accident Considerations Under NEPA" BINGER.L N. Hearing Branch 2. 80/03/27 3pp
- 8004i10095 Followon interrogatory directed to State of PA re restart proceeding Requests identification of all repts studies & documentation relied upon in State of PA response to Interrogary 23(b) Centificate of 8vc ent
- 8004090011 Confirms that ASLB has granted extension until 800410 for NRC to respond to SC Sholly, UCS, Chesapsaks Energy Alliance & other intervenors' interrogatories, Majority of answers will be filed on 800331 CUTCHIN. J M Hearing Branch S 80/03/28 3pp
- 8004090403 Memorandum & order inviting parties to move for relief consistent w/Commission 800314 order & ASLB present interpretation of same order Correctness of interpretation may be argued Mottons must be filed within 5 days SMITH, I W Atomic Safety and Licensing Soard Panel, 80/03/28 6pp
- 8004160131 Forwards People Against Nuclear Energy interragatories to licensee Requests that interrogatories be served on those on eve list JORDAN.W B Sheldon, Harmon & Weiss 80/03/28 ip
- --8004i60i38 Interrogatories to licensee Includes questions re intervenor Contentions 1 & 2, documents that licensee expects to introduce into evidence & licensee position on possible psychological distress caused by TMI-2 accident JORDAN, W S , SHELDON, K P Feople Against Nuclear Energy URDAN, W S Sheldon, Harmon & Weiss. 80/03/28 9pp

- 8004230001 Response in apposition to intervenor Aamodt motions to compel Questions do not bear on Contention B Disclosure of tests re Contention 2 delayed W/util 800124 ltr & Certificate of Svc ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Traubridge 80/03/28 i6pp
- 8004230030 Response in opposition to UCS motion to compel licensee to answer Interrogatory 179 Elements of UCS contentions, re licensee position to be provided per motion, should be identified if ASLB grants motion Certificate of Svc encl TROMBRIDGE, GF Metropolitan Edison Co TROMBRIDGE, GF Shaw, Pittman, Potts & Trombridge 80/03/29 8pp
- 8004230097 Forwards affidavits re licensee further response to 9C Sholly first set of interrogatories, response to Sholly Interrogatory 08-006 of first set & response to Sholly second set of interrogatories W/Certificate of Svc ZAHLER, R C Shaw, Pittman, Potts & Trowbridge 80/03/28 11pp
- 8004230127 Forwards RW Keaton affidavit re licensee response to MI Lewis second set of interrogatories ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 80/03/28 2pp
- 8004230131 Forwards RW Keaten & RL Long affidavits re licensee response to intervenor Anti-Nuclear Group Representing York first set of (Interrogatories ZAHLER: R E Shaw, Pittman, Potts & Troubridge 80/03/28 3pp
- 8004080004 Partial response to intervenor BC Sholly second set of interrogatories Addresses Interrogatories 01-005,07-003, 08-010 through 08-016,10-002 & 15-005 through 15-013 Affidavits, prof qualifications & Certificate of Svc encl CUTCHIN, J M Hearing Branch 3 80/03/31 47pp
- 8004080045 Response to Chesapeake Energy Alliance Interrogatory 12-16 re BW analysis of integrated control sys Area of concern re multiple failure is relatively insignificant Affidavit & Certificate of Syc encl SINGER, L N Hearing Branch 2 80/03/31 7pp
- ---8004080051 Response to Intervenor Aamodt first & third through sixth sets of interrogatories Includes info re monitoring programs; operator performance & incidents attributed to human errors Affidavits & Certificate of Svc enci SWANSON,D T Hearing Branch 1 80/03/31 49pp
- 8004080056 Response to UCS first & second sets of interrogatories Includes bibliography of Class 9 accident studies & NRC position on UCS contentions Prof qualifications & affidavits encl SWARTZ, L. L. Hearing Branch | 80/03/31 9900
- 8004100222 Mamorandum & order directing NRC to specify & descibe encl accident sequences of NRC 800331 response to ABLB inquiry re Class 9 accident, in relation to restart proceeding Satisfactory answer should be filed within 15 days from svc LITTLE, L. W., JORDAN, R. H., BMITH, I. W. Atomic Safety and Licensing Board Panel 80/03/31 7pp
- 8004140004 Response to TMI Alert seventh set of interrogatories re restart proceeding includes names & functions of maint & operations personnel OF Trowbridge 800331 forwarding ltr to TA Adler encl BLAKE,E L. Metropolitan Edison Co BLAKE,E L. Shaw, Pittman, Potto & Trowbridge 80/03/31 28pp
- --8004140007 Response to Asmodt family 800222 fourth set of interrogatories re restart proceeding Includes info re primary & backup communication sys in emergency plan OF Troubstidge 800331 forwarding ltr to MM Asmodt encl TROWBRIDGE.OF, ZAMLER.R & Metropolitan Edison Co YROWBRIDGE.OF Shaw, Pittman, Potts & Troubsidge 80/03/31
- --B004140013 Response to Aamodt family 800225 sixth set of interrogatories re restart proceeding Includes info re routine & planned radioactive releases per Tech Specs OF Troubridge 800331 forwarding ltr to MM Aamodt encl TROUBRIDGE, OF, ZAHLERIR E Metropolitan Edison Co TROUBRIDGE, OF, Shaw, Pittman, Potts & Troubridge 80/03/31
- --8004140017 Response to Newberry Township TMI Steering Committee 80021:
 first set of interrogatories re restart proceeding Includes
 info re selection of witnesses & licensee studies re
 emergency plan OF Trowbridge 80033i forwarding ltr encl
 TROWBRIDGE, OF , ZAMLER, R E Matropolitan Edison Co
 TROWBRIDGE, OF Shaw, Pittman, Potts & Trowbridge 80/03/31

- --B004140019 Response to UCS second set of interrogatories re restart protecting includes info re prevention of void formation & reduction of natural circulation loss GF Trowbridge 800331 formarding Itr to ER Weiss enci
 TROWBRIDGE, GF Metropolitan Edison Co TROWBRIDGE, GF Shaw, Pittman, Potts & Trowbridge 80/03/31 Spp
- --8004140023 Response to Anti-Nuclear Group Respresenting York second set of interrogatories he restart proceeding Includes info re offsite emergency operations of a interruption of electrical svc QF Troubridge 800331 forwarding ltr end TROMBRIDGE 6 F. ZAMLER,R E. Metropolitan Edison Co TROMBRIDGE 6 F. SAMLER,R E. Metropolitan Edison Co TROMBRIDGE 6 F. SAMLER,R E. Troubridge 80/03/31 7ap.
- --800414002B Response in opposition to SC Bhally 800321 motion to compai answers to certain of fourth set of interrogatories re restart proceeding Certificate of Svc encl TROMORIDGE, OF Metropolitan Edison Co TROMBRIDGE, OF Shaw, Pittman, Potts & Troubridge 80/03/31 20pp
- --8004140032 Motion to compel Chasapeake Energy Alliance answer to licensee 800118 first set of interrogatories re restart proceeding Intervenor 800317 responses are insufficient & incomplete Certificate of Svc encl TROWBRIDGE, 0 F Metropolitan Edison Co TROWBRIDGE, Q F Shaw Pittman, Potts & Trowbridge 80/03/31 23pp
- --8004140038 Response to HI Lewis third set of interrogatories re restart proceeding includes info re selection of witnesses & background of MI Lewis & B Barley GF Troubridge 800331 forwarding 1th to MI Lewis encl
 TROUBRIDGE GF, ZAHLER RE Metropolitan Edison Co
 TROUBRIDGE GF Show, Pittman, Potts & Troubridge 80/03/31
 Ann
- --B004140045 Response to Aamodt family 800216 first set of interrogatories re restart proceeding Includes info re agricultural emergency plan & other related agricultural issues RE Zahler 800331 forwarding itr to MM Aamodt encl TROMBRIDGE. OF . ZAHLER.R E Metropolitan Edison Co TROMBRIDGE. OF Shaw. Pittman. Potts & Trombridge 80/03/315pp
- --8004140051 Response to MI Lewis fourth set of interrogatories re restart proceeding Includes info re pathway analyses & radwaste gas sys drawings OF Trowbridge B00331 forwarding let to MI Lewis encl TROWDRIDGE, OF T. ZAHLER, R. E. Hetropolitan Edison Co TROWDRIDGE, OF Shaw, Pittman, Potts & Trowbridge B0/03/31
- ---8004140057 Response to AA Aamodt 300225 fourth set of interrogatories re restart proceeding Includes info re training in basic heat transfer, fluid flow & thermodynamics Supporting documentation & GF Troubridge 800331 ltr encl TROWERIDGE, OF Metropolitan Edison Co TROWERIDGE, OF Shaw, Pittman, Potts & Troubridge 80/03/31 3App
- ---B004140062 Response to Chesepeake Energy Alliance first set of interrogatories Includes info re description of present radioactive water storage & methods of decontamination GF Trowbridge B0033i forwarding ltr to RG Pollard encl TROWBRIDGE, G F. Metropolitan Edison Co TROWBRIDGE, G F. Metropolitan Edison Co TROWBRIDGE, G F. Shaw, Pittman, Potts & Trowbridge B0/03/31 30pp.
- --8004140065 Supplemental response to PA Public Util Commission first set of interrogatories re restart proceeding Includes into re decontamination & restoring during operation Affidavits, GF Trowbridge 800331 Forwarding Itr & Certificate of Syc encl TROWBRIDGE, GF Metropolitan Edison Co. TROWBRIDGE, GF Shaw, Co. Trowbridge 80/03/31 19pp.

- 8004080019 Response to intervenor SC Sholly first set of interrogatories includes info re radioactive release as result of containment isolation failure & other related matters Afridavits & prof qualifications encl CUYCHIN.J M Hearing Branch 3 80/04/01 16pp
- .--B0040B0025 Response to intervenor Anti-Nuclear Group Representing York follow-on interrogatories filed as result of NRC answer to Interrogatory 4 Addresses evacuation radius stated by Chairnan Hendrie Affidavit & Certificate of Svc encl SINOER.L N Hearing Branch 2 80/04/01 5pp
- 8004080577 Hemorandum advising that ASLB is in process of selecting map & overlays depicting TMT vicinity, to be presented as exhibit in restart proceeding ASLB member LW Little & NRC employee G LaRoche will select appropriate map features SMITH.IW Atomic Safety and Licensing Board Panel 80/04/01 4pp
- 8004080586 Hemorandum & order compelling UCS to answer licensee 800118 Interrogatory 8-1 re UCS Contention 8 challenging analysis required for ECCS performance Grants 20-day extension after svc of present order for UCS to comply w/ASLB directive SMITH, I W Atomic Safety and Licensing Board Panel 80/04/01 7pp
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004100018 Memorandum & order danying UCS 800324 motion to compel licensee answer to Interrogatory 179 re restart proceeding Interrogatory is broad & premature SMITH, I W Atomic Safety and Licensing Doard Panel 80/04/02 3pp
- 8004100021 Memorandum & order directing NRC to delete confidential info from original record & to provide rest of info in response to UCS Interrogatory 210 re restart proceeding Recommends that NRC & UCS confer re Interrogatory 211 SHITH.I W Atomic Safety and Licensing Board Panel 80/04/02 7pp
- 6004100024 Memorandum & order re SC Sholly 800303 motion to compel licensee answers Response to Interrogatory 08-006 is responsive to Interrogatory 08-019 Enforcement of SC Sholly Interrogatory 08-024 is declined SMITH.I W Atomic Safety and Licensing Board Panel 80/04/02 2pp
- 8004100304 Memorandom & order re Lewis 800304 motion to compel NRC answers to Interrogatories 14.15 & 18 Denies motion re Interrogatory 18 NRC 800324 answer sufficient re Interrogatory 14 Interrogatory 15 is not answerable SMITM, I W Atomic Safety and Licensing Board Panel 80/04/02 2pp
- 8004220011 Response to ASLB 800325 memorandum & order: stating objective of intervenor discovery & deposition program Prospected info will spotlight licensee internal weakness Participation in future depositions uncertain Certificate of Svc encl ADLER: T A Three Mile Island Alert 80/04/02 3pp
- 8004300001 Discusses preparation for 800410 meeting w/USQS re charting of emergency planning maps for TMI-1 restart hearings Forwards lists of relevant items in emergency planning assessment of area LITTLE:LW Atomic Safety and Licensing Board Panel 80/04/02
- ~-8004300005 Confirms 800331 notification of 800410 meeting w/USG8 in Reston,VA re USG8 production of maps for TMI-1 hearings in June or Jul 1780 USG8 land use list encl LARUCHE. © Environmental Specialists Branch 80/04/01 2pp
- 8004100589 Response to ASLB 800325 memorandum & order ASLB does not have authority to order NRC to take depositions on behalf of ASLB & intervenor TMI Alert ASLB proposed action is impractical & intervenor deposition program repetitive SHANSON,D T Hearing Branch 1 SINGER,L N Hearing Branch 2 80/04/03 13pp
- 8004210114 Hemorandum & order re Lewis 800319 motion to compel NRC to answer interrogatories Declines to enforce Interrogatories 23,24,25,27,30 & 37 Interrogatories 27 & 28 will be answered by NRC May submit substituted Interrogatory 31 SMITH, I W Atomic Safety and Licensing Board Panel 80/04/03 App.
- 8004210421 Comments on ASLB B00325 order re adoption of TMI Alert deposition program concerning util mgt & financial compatence Question re whether depositions have been productive should not be addressed by licensee TRCHURITIOE. F Metropolitan Edison Co TRCHURITIOE. F Shaw. Pittman, Potts & Trowbridge 80/04/03. 6pp

- 8004250053 Petition for addition of new contention Hany sys have had to operate unattended at THI-2 for over a yr Same sys must be qualified at TMI-1 to operate unattended for similar period Syc list encl LEWIS, M I Affiliation Unknown 80/04/03 2pp
- 8004150174 Interim memorandum & order directing licensed to answer Interrogatory 16 of Aamodt 800225 fourth set of Interrogatories, re Contention 2 in restart proceeding SMITM.1 W Atomic Safety and Licensing Board Panel 80/04/04 ip
- 8004240176 Memorandum stating practicality of issuing no ruling re Aamodt family request to depose State of PA officers, due to PA offer of continued voluntary responses Informal ASLD 800229 fourth special prehearing order not changed SMITH, I W Atomic Safety and Licensing Board Panel 80/04/08 2pp
- B004210094 Hemorandum & order re Aamodt Family 800320 motions to compel licensee response to discovery requests Licensee not required to answer Contention 8 re radwaste SMITH, I W Atomic Safety and Licensing Board Panel 80/04/09 9pp
- 8004150273 Addl response to SC Shoily second set of interrogatories Answers interrogatories 14-003.14-004.14-009 & 16-004 Includes statements re NUREO-0616 Affidavits, profiqualifications & Certificate of Svc encl CUTCHIN, J M Hearing Branch 3 80/04/11 11pp
- B004150499 Forwards adjudicatory hearing stipulation of settlement document re NPDES Permit 0009920 HERBEIN, J.G. Metropolitan Edison Co. B0/04/11 App
- 8004230115 Memorandum A order directing TMI Alert to respond to licensee 800114 first set of interrogatories within 10 days from svc Answers are essential for licensee litigation of intervener contentions SMITH, I W Atomic Safety and Licensing Board Panel 80/04/11 3pp
- 8004170055 Response in opposition to Lewis 800403 petition for addition of new contention No new allegation advocated due to coverage by UCS Contention 12 Certificate of Svc encl CUTCHIN.J M Hearing Branch 3 80/04/14 4pp
- 8004170058 Motion for extension until 800401 to respond to ASLB 800331 memorandum % order requesting further supplementation re Class 9 accidents involvement in safety evaluation publication will delay answer Certificate of 8vc encl SINDER.L N Hearing Branch 2 80/04/15 5pp
- 8004280356 Ack receipt of 800326 interrogatories Until ASLB rules on whether psychological stress issues will be heard in proceeding NRC is reluctant to initiato review or analysis SWARTZ:L L Hearing Branch 1 80/04/15 ip
- 5004280398 Ack receipt of People Against Nuclear Energy 800331 interrogatories Since ASLB has not ruled on psychological distress issue.NRC is reluctant to initiate review or analysis of issue at this time

 BWARTZ.L L Hearing Branch 1 80/04/15 lp
- B004220291 Reminds of B Pollard commitment during B00411 deposition to inform NRC if discussion in NUREQ-0640, Draft 3, Task IID, satisfies UCB Contention 6
 BWANSON,D T Hearing Branch i B0/04/18 ip
- 8004250373 Requests review & reconsideration of 800407 Director's decision under 100FR2 206 denying 800225 petition Interests of public health demand that cleanup be started at facility QARY.R Affiliation Unknown 80/04/18 2pp
- 8004280249 Advises of intention not to respond to Aamodt 800407 request for further extension of time re State of PA deposition, unless advised to contrary ASLB 800227 memorandum disposes of matter SWANSON,D T Hearing Branch I 80/04/24, 1p.
- H General correspondence
- 8004020227 Responds to 790919 ltr expressing concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const Beyond licensing requirements, commercial operation is corporate decision VOLLMER.R H TMI-2 Operations/Support 80/02/05 2pp
- --8004020234 Expresses concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const. Ltr of 791024 to Met Ed expressing concern re Unit 1 restart encl EDMONSON, L. D. Affiliation Unknown 79/09/19 6pp

- 8004030123 Responds to 790816. For the plans to reopen TMI-1, nuclear plant const in NJ % nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info replants in NJ No diseages resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restait of TMI-1, const of nuclear plants in MJ & nuclear accidents due to health hazards & ;is/s to public safety FOSTER, X Affiliation Unknown 79/08/16 2pp
- 8004180109 Responds to enci itr to President Carter re restart of THI-1 Util lequest to restart TMI-1 is subj of public hearing not expected before early part of 1981 INGRANLF Office of Public Affairs 80/03/05 2pp
- 8004210108 Responds to 800108 itr re boron dilution errors A spent fuel cask drop evaluation Provisions to protect against accidental boron dilution are acceptable Fuel shipment not anticipated for at least one yr after startup REID,R W Operating Reactors Branch 4 80/03/12 1p
- 8004220019 Forwards ST Amant 800219 1tr urging restart of facility Requests NRC findings 5 views STONE.R Senate 80/03/14 2pp
- 8004020112 Responds to 800227 itr re util financial situation NRC does not regulate electrical util rates Licensing board hearing will determine whether Unit I can safely resume operation during Unit 2 cleanup GILINSKY, V Commission 80/03/19 2pp
- --8004020114 Discusses concerns re util financial situation Development of nuclear power should not be blocked GUISENBERRY.G F Affiliation Unknown 80/02/27 2pp
- 8004040002 Responds to General Public Utils stockholder re financial concern for restart of plant site NRC is conducting hearing before Licensing Board to determine whether Unit 1 can restart while cleanup begins at Unit 2 OILINSKY, V Commission 80/03/19 lp
- ---8004040004 Requests restart of unit because dividends are needed & nuclear power is needed until some other source of power is found if util goes bankrupt.NRC is to blame BAKER.R O Affiliation Unknown 80/03/12 ip
- 8004180113 Ack receipt of 800312 ltr concerning financial situation of util NRC does not regulate rates charged by utils Main concern of NRC is regulation of safety of nuclear reactors OILINSKY, V Commission 80/03/19 ip
- --8004180120 Requests assistance of NRC in restoring financial integrity to util Util presently close to bankruptcy because of financial burden of TMI accident LAMSON.J D Affiliation Unknown 80/03/12 2pp
- BOO42103BI Responds to ltr re permanent shutdown of facility, cleanup of waste & payment of expenses concerning accident Dry wastes are packed in steel droms & shipped to burnal sites Util customers do not pay for facility restoration DENTON, H R Office of Nuclear Reactor Pagulation 80/03/19 200
- BOCHAZOLOG RESPONDS to //OGI/ Its to Onto a Every errors being made to protect public health & safety at all nuclear power plants currently operating or planned for operation Restart hearing has not yet begun

 DENTON: HR Office of Nuclear Reactor Regulation 80/03/19 ip
- --B004220171 Requests adherence to regulatory directives
 PHILLIPS,L B , PHILLIPS,V Affiliation Unknown 79/06/17 ip
- 8004240441 Responds to 790815 ltr expressing concern re-pollution of environ by use of EPICOR-II sys Bys will clean water in auxiliary bldg to extent that no further risk will be posed Environ assessment will be issued prior to disposal DENTON, HR Office of Nuclear Reactor Regulation 80/03/19 2pp
- ---B004240447 Expresses concern re plans for disposal of contaminated water at TMI-2 Use of EPICOR-II sys will pollute environ & expose workers to radiation of GLBERTIR S Affiliation Unknown 79/08/15 1p

- all 30' Pespiris to the transport Hendrie re dumping of radius to a parent into forquenants fir methaces of commandation to step and for turnantial permitted except for liquids critaining low or inchestectable radiation levels (PMTC) HOR (Infire in 1) last meactor Regulation 60/03/19 2pp
- in 12770A4 Mespinds to 7% HO ltm to MRG me facility accident in May 1477 NC aaroted meside if inspector program inspectors are presently assigned to approx TO sites Auclear plants are equipped win incroos alarms to automatic shutdown equipment CENTON HOW OFFICE of Norlean Reactor Regulation BO/03/19 Spp.
- PDD4190021 Requests into the racility accident including presente of good integerants at no lear rabilities effectiveness of plant carming sys responsibility for accident 5 actions taken by foreign counstries in post-fill period foreign counstries in post-fill period vyMLSICH (Artilistion Unknown 74/09/10 App.
- r C429CO76 Responds to) Fr re disposal of radioactive water from TMI-2 Release of contenunated water into Susquehanna River is not currently permitted except for liquids containing low or condetectable levels of radioactivity

 CENTOUR R Office of Nuclear Reactor Regulation 80/03/19 2pp
- EJ0427008B3 Opposes releases of radioactive water from TMI-2 into Eurquehanna River NBC is trying to sale nuclear industry w/o regard to interests of public ERGUDE, M. Affiliation Unixoln 80/03/19. lp
- *CO4020117 Hesponds to 800_03 ltr requesting info re application of TMI-2 Lessons Learned Task Force to facility & certain other plants under const NTS should be contacted for SER info ASLB proceedings announced in FP VARCA S A Assistant Director for Light Water Reactors 80/03/22
- 9004250332 Ad ises that response to inquiry re plants under const will be provided in SERs which will include TMT-2 Lessons Learned Task Force findings Forwards Commission order defining TMT-2 review parameters & NAC 1tr to all BNW reactors W/o encis VARDA S.A. Assistant Director for Light Water Reactors 80/03/22 2pp
- 8304210356 Responds to 750904 ltr re release of Kr-831 from facility Util 'Safety Analysis '2 Environ Rept' states that optimum choice for release of Kr-831 is atmospheric dispersion through controlled purging or reactor bldg atmosphere DENION: H R Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004210360 Opposes reopening of facility & release of Kr-85 into atmosphere Requests plans for disposal of waste LECKARD, J. Affiliation Unknown 79/09/04 1p
- BOD4210363 Responds to ltm re holding of public hearings on facilities Commission has ordered that public hearing be conducted to determine whether Unit I should be operated Hill conduct review or technical info on restart beinton H R Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004210373 Expresses conviction that public hearings must be held in communities within 25-mile radius of facility site LYON5:E Affiliation Unknown 79/07/23 2pp
- 8004280342 Responds to 791630 ltr to NRC re TMI NRC has ordered public hearing to determine whether TMI-1 should be restarted Licensee authority to operate Unit 2 was suspended by NRC 790720 order DEMIGN.H R Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004280350 Opposes reopening of TMI due to health hazard posed to area residents Requests info re plans to dispose of radioactive water which flooded reactor Hater may freeze in winter & burst containment walls GAMBINO.M Affiliation Unknown 79/06/30 App
- 8004100047 Forwards Commission 790809 order & notice of hearing for restart of facility in response to 800317 telcon VOLLMER,R H TM1-2 Operations/Support 80/03/25 1p
- BO04110571 Forwards WASH-1400 "Reactor Safety Study, Assessment of Accident Risks in US Commercial Nuclear Power Plants," & listed appendices to rept All documents identified in second suppl to interrogatories to PRC have now been sent SAUDER.J L Division of Rules and Records BO/03/24 2pp
- 8004100574 Responds to 790615 ltr restart up of reactor Both Units 1 & 2 shut down Unit 2 where accident occurred will be shut down for some time NRC hearings to ascertain safety of Unit 1 will be conducted before startup DENTON: HR Office of Nuclear Reactor Regulation 80/03/27 1p

- --8004100578 Requests into no staitup of Unit 1 NRC should be investigating competence of util to have reactor license Presidential Commission rept should be studied Questions NRC concern for safety HOSTETTER.J.J. Affiliation Unknown 79/06/15 [p
- BOOAD90357 Urges NRC to provide educational matis in effort to educate public on nuclear energy Educated public is only way for fair decision re future of nuclear energy, restart of THI-1 & cleanup of THI-2 SNYDER, M G Affiliation Unknown 80/03/31 2pp
- 8004180114 Responds to 800228 itr regarding encl A & D Thompson ltr of concern re delay in sestant Commission /70809 arder identifies items that must be resolved prior to restart Timb needed to resolve items will delay restart until late 1980 pIRKES, M J Office of the Executive Director for Operations 80/03/31 5pp
- 8004220173 Ack receipt of litt re financial situation of Owneral Public Utils NRC does not requiate rates charged by electrical utils NRC is conducting hearing to determine whether THI-1 can be restarted while TMI-2 cleanup proceeds QILINSKY, V Commission 80/04/02 ip
- --8004220181 Urges NRC to expedite rate relief requested by General Public Utils & return TMI-1 to svc Unfair treatment accorded to General Public Utils has encouraged demonstrators LESH.L Affiliation Unknown 80/03/24 2pp
- BOO4290049 Responds to 790823 ltr re nuclear fission & biological effects of radiation FFA.Occupational Safety & Health Administration & NRC are responsible for regulating exposure to radiation or radioactive mat!

 DENTON.H R Office of Nuclear Reactor Regulation 80/04/03 2pp
- 8004100504 Opposition to TMI-1 restart People who live in vicinity of TMI live in constant dread NRC personnel do not have to share danger of living close to plant Chances of nuclear accident greatly underestimated by util & NRC KAUFMANN, D H Affiliation Unknown 80/04/09 3pp
- B004150478 Forwards updated svc copy distribution list for facilities
 Notifies that GK Hovey has replaced RF Wilson as director
 of Unit 2
 ARMILD.R C Metropolitan Edison Co 80/04/10 5pp
- 8004280384 Act receipt of 800308 ltr expressing concern re delay in placing TMI-1 back in svc Based on 770809 shutdown order & current status of proceedings, restart not possible until early 1981
 DENTON, HR Office of Nuclear Reactor Regulation 80/04/14 ip
- --8004280389 Requests immediate restart of unit Delay could cause serious economic dislocations & create political imbalance Draft Ofc of General Counsel reply encl YOUNG, D W Affiliation Unknown BO/03/08 Epp
- | Financial information
- 8004030241 Forwards update to util 800219 ltr re projected 1980 cash flow forecastineflecting recent rate relief Company is able to meet max retrospective premium HERBEIN, J G Metropolitan Edison Co 80/03/31 3pp
- 8004090477 Forwards supplementary financial info in support of TMI-1 restart proceedings
 HAFER: F D General Public Utilities GPU Service Corp 80/04/03 140pp
- --8004090478 Transcript of PA Public Util Commission 800213 hearing in Harrisburg.PA Pp i 7863-2.143 SHANAMAN.S Pennsylvania, State of Ryan. Russell & McConaghy 80/04/03 RUSSELL.8 B , GELTZER.A M 182pp
- ~-8004090479 Transcript of PA Public Util Commission 800227 hearing in Marrisburg,PA Pp 2, 494-2,527A SHANAMAN,S Pennsylvania, State of Ryan, Russell & McConaghy 80/04/03 37pp
- --8004090480 Transcript of PA Public Util Commission 800228 hearing in Harrisburg,PA Pp 2:528-2:682 SHANAHAN.S Pennsqivania: State of Ryan, Russell & McConaghy 80/04/03 156pp
- --800407048: Transcript of PA Public Util Commission 800318 hearing in Harrisburg, PA Pp 3, 217-3, 419 SHANAHAN, S Pennsylvania, State of RUSSELL, S B , SELTZER, A M, Ryan, Russell & McConaghy 80/04/03 204pp

- --8004090482 Annual Financial Rept 1979

 * General Public Utilities GPU Service Corp * Jersey Central
 Power & Light Co * Metropolitan Edison Co 80/04/03 44pp
- --8004090483 "Proposal to Conduct Analysis of Strategic Options for
 - # Arthur Young & Co 80/02/29 125pp
- --B004090484 "TMI-2 Coal Burning Plant Summary of Study of Converting TMI-2 to Fossil-Fueled Plant" + Gilbert/Commonwealth Cas B0/02/25 13pp
- 8004280630 Forwards Met Ed certified Annual Financial Rept 1979 & General Public Utils Corp certified Annual Financial Rept 1979 & certified "Uniform Statistical Rept 1979" HERBEIN.J G Metropolitan Edison Co 80/04/22 1p
- --8004280633 Certified Annual Financial Rept 1979
 * Metropolitan Edison Co 80/03/07 27pp
- ---8004280438 Certified Annual Financial Rept 1979 Certified "Uniform Statistical Rept.1979" encl * General Public Utilities GPU Service Corp 80/04/22 71pp
- P Operating license stage documents & correspondence
- 8004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800204 reactor trip at Crystal River Sequence of events & planned corrective actions also encl DENTON.H R Office of Nuclear Reactor Regulation 80/03/04 26pp
- BOO4080121 Forwards NRC/TMI weekly status rept Liquid effluents from TMI-1 released to Susquehanna River, after processing were within limits specified in Tech Specs No liquid effluents were discharged from TMI-2 COLLING.J T. TMI-2 Operations/Suspensed (2000) TMI-2 Operations/Support 80/03/11 4pp
- BO04030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EIBENNUT.D G Division of Operating Reactors B0/03/12 5pp
- --B004030118 "Nuclear Data Link Specs "
 # Division of Operating Reactors 80/02/21 28pp
- BOD4070[41 Notification of 800321 meeting w/util & NRC consultant, R Mittelstaedt, in Bethesda, MD to discuss TMI-1 restart SILVER, H NRC Three Mile Island Task Force 80/03/13 1p
- 8004030230 Notification of 800318 meeeting w/all operating D&W reactor licensees in Bethesda MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID, R W Operating Reactors Branch 4 80/03/14 2pp
- 8004020067 Confirms 800305 teleon re regulatory requirements for portable radiation survey meter calibr recall sys. Proposed radiation protection plans will specify min frequencies for portable survey meter calibr CQULLING.D M Division of Site Safety & Environmental Analysis 80/03/17 ip
- 8004170274 Forwards suppl to safety evaluation re Amend 46 to License REID,R W Operating Reactors Branch 4 80/03/23 4pp
- --8004170300 Suppl to safety evaluation supporting Amend 46 to License DPR-50, increasing frequency for performing heat balance checks of out-of-core detectors * Uperating Reactors Branch 4 80/03/26 4pp.
- BOO4010412 Advises that Met Ed response to Item 3 of NRC 790914 ltr will be included in revised study on degraded grid, to be submitted on BOO415 HERBEIN.J.Q Metropolitan Edison Co 80/03/28 ip
- 8004070284 Responds to NRC 791030 ltr & 800006 telcon inquiry re IGSCC investigation Forwards item-by-item response to NRC 791030 ltr.describing changes to investigation & repair program MERBEIN-J 0 "Metropolitan Edison Co 80/03/31 4pp
- -8004070285 Revision 2 to "Gas Tungsten Arc Shielded Hetal Arc Welding of Stainless Steel in Borated Water Piping Sys" re ID weld clad procedure * Metropolitan Edison Co 79/12/04 5pp

- 8004070290 Forwards Tech beet Change Request 618 to App A of License HERBEIN, J G Metropolytan Edison Co 80/03/31
- --8004070291 Application to amend App A of License DPR-50 per Tech Spec
- Change Request 61B HERBEIN J G Metropolitan Edison Co 80/03/31 1p
- --8004070306 Tech Spot Change Request 618 to App A of License DPR-50 re mods to high pressure injection sys to ensure min acceptable flow through each leg should one pump fail # Metropolitan Edison Co 80/03/31 4pp
- 8004070318 Advises that capacity of approx 160,000 gallons of Unit 2 water will be maintained by one reactor coclant bleed holdup tank in each unit Tanks will remain empty per NRC . Metropolitan Edison Co 80/03/31 ip
- --8004070323 Application to amend App A of DPR-50 per Tech Spec Change Request 77A HERBEIN, J. G. Metropolitan Edison Co. 80/03/31 1p
- --8004070325 Tech Spec Change Request 77A to App A of DPR-50 re revision of tendon surveillance to reflect Reg Guide 1 35.Revision 3 requirements b to delete ring glidei surveillance program * Metropolitan Edison Co 80/03/3i 10pp
- 8004080960 Responds to NRC 800223 ltr re overpressurization & rupture of low pressure injection sys low pressure piping due to failure of redundant check valves to act as pressure isolation barrier HERBEIN.J G Hetropolitan Edison Co 80/03/31 2pp
- 8004080703 Forwards Yech Spec Change Request 90 to temporarily amend License DPR-50 Certificate of Svc encl HERBEIN, J G Metropolitan Edison Co 60/03/31 1p
- --8004080707 Application to temporarily amend License DPR-50 per Tech Spec Change Request 90 HERBEIN:J G Metropolitan Edison Co 80/03/31 2pp
- --8004080716 Tech Spec Change Request 70 re period for Cycle & refueling Page 4-59 Change would be deleted upon completion of Cycle * Metropolitan Edison Co 80/03/31 2pp
- 8004110471 Notifies NRC that as of 800326, approx 160,000 gallons of shielded storage capacity for TMI-2 water will be maintained by reactor coolant bleed holder tank 1A of Unit 1 & 1A of Unit 2 Util 800328 memo ro TMI-1 bleed tanks encl WIL80N,R F Metropolitan Edison Co 80/03/31 2pp
- 8004110395 Responds to 800307 ltr re reactor bldg spray sys Evaluation determined that by eliminating sodium thiosulfate tank & adjusting sodium hydroxide tank concentration & level, sys can maintain spray ph between 8 5 % 11 0 HERBEIN, J G Metropolitan Edison Co. 80/04/02 in

- 8004150749 Forwall's Amend 15 to Restart Rept " HERBEIN, J.G. Metropolitan Edison Co. 80/04/11 1p
- --B004150351 "Amend to to hestart Rept, providing addl info re plant moss ♦ Metropolitan Edison to 80/04/11 54pp
- 800415044b Forwards nods to encl permits 7 certificates for environ protection in response to NRC 800125 request HERBEIN J G Metropolitan Edison Co 80/04/11 122pp
- 8004220223 Forwards Tech Specs Change Request 92 Certificate of Svc 5 fee encl HERBEIN.J G Metropolitan Edison Co 80/04/11 2pp
- --BC04220224 Terh Specs change Pequest /2 levising Page 3-80 re location of temp detectors in leactor blig HERBEIN J G Metropolitan Edison Co 80/04/11 3pp
- 8004220542 Forwards application to amend License DPR-50.App A, consisting of Tech Spec Change Request 91 Fee encl HERBEIN, J.G. Metropolitan Edison Co. 80/04/11 2pp
- -8004220545 Application to amend License DPR 50.App A.consisting of Tech Spec Change Pequest 91 * Metropolitan Edison Co 80/04/11 ip
- ~~8004220552 Tech Spec Change Pequest 91 replacing Pages 4~11.12.13.13a & 27a re RCS inservice insp to provide interim measures for irradiation of one reactor vessel math surveillance capsule in Crystal River Unit 3 reactor * Metropolitan Edison Co 80/04/ii 6pp
- B0041502B1 Forwards corrected Page 2 1-45, Amend 13, to restart rept. describing short-term mods

 * Metropolitan Edison Co 80/04/14 1p
- --BOO4150287 Corrected Page 2 1-45, Amend 13, to restart rept. describing short-term mods Metropolitan Edison Co 80/04/14 ip.
- H004170104 Forwards Amend 17to Restart Rept," App 7A. Revision 2 to radiation protection plan
 HERBE[N, J G Metropolitam Edison Co 80/04/14 ip
- --B004170106 Amend 17 to 'Restart Rept.' App 7A.Revision 2 to radiation protection plan HERBEIN, J G , POTTS, W E Metropolitan Edison Co 80/04/03 24pp
- 8004210335 Forwards Susquehanna River data in response to NRC 800407 SKINNER.W F Pennsylvania Power % Light Co 80/04/15 ip
- --8004210340 "Demonstration for Brunner [sland Steam Electric Station Units 1-3-Vols 1 5 2 ' * EO & 6. Inc. 77/05/19 200pp
- --8004210344 "Potential Effects of Brunner Island Steam Electric Station on Future Migrations of American Shad in Susquehanna River " # EC / G. Inc 77/08/13 23pp
- --8004210347 "Probabilities of Normal & Worst Case Conditions in Susquehanna River during Critical Periods for Muskellunge Spauning & Smallmouth Bass Egg Survival & Development " * EG & G, Inc 77/09/15 lápp
- ~-8004210349 "Assessment of Thermal Effects from Brunner Island Steam Electric Station Based on Newly Derived Max Weekly Average Temps " * EQ & G. Inc 79/05/3t 33pp
- --8004210395 "Ecological Study of Effects of Brunner Island Steam Electric Station Cooling Water Intakes" JOHNSON.T D Roy F Weston.Inc 77/11/19 78pp
- --8004210358 "Biological Survey of Susquehanna River in Vicinity of York Haven,PA 1978 Terminal Rept ' WURTZ,C B Charles B Wurtz 79/06/29 33pp
- --8004210366 "Ichthyofaunal & Crest Census/Fishing Pressure Surveys in Vicinity of Brunner Island Steam Electric Station "
 DENONCOURT, R F R F Denoncourt 78/05/34 161pp

- 8004220654 Forwards list of outstanding Tech Spec change requests % respective submittal dates Requests review of list % status rept for each item
 HERBEINJ 6 Metropolitan Edison Co 80/04/15 3pp
- 8004250367 Requests withdrawal of Tech Spec Change Request 88 for JUMAZJUJAS/ REQUESTS WICHDIAWAI OF IECH Spec Change Request 80 revision of reactor vessel pressure-temp limits to reflect potential effects of atypical weld wire possibly used in vessel fabrication Existing pressure-temp limits acceptable HERBEIN, U.G. Hetropolitan Edison Co. 80/04/18. 1p
- Q Inspection reports, IF Bulletins & correspondence
- 800421G097 Forwards IE Insp Repts 50-320/79-30 & 50-289/79-24 on ORIGINATION FORWARDS IN THIS REPORT SOCIETY SOCIETY TO SOCIETY FOR THE STREET SOCIETY TO SOCIETY FOR THE SOCIETY SOC
- --8004210102 JE Insp Repts 50-320/79-30 % 50-289/79-24 on 791128-800104 Major areas inspected licensee action on previous insp findings, new & revised recovery procedures, plant operations, plant tours & status meetings MARTIN,T T. PLUMLEE, W. E., YUHAS, O. P. Region 1, Philadelphia, Office of the Director 80/02/26 7pp
- 8004070013 Responds to !E Builetin 77-27 ie loss of non-Class IE instrumentation % control power sys bus during operation Mod to intercommunication sys is being made to ensure prompt action Manual transfer contractors will be provided HERBEIN. J G Metropolitan Edison Co 80/02/27 2pp
- 8004210115 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted moncompriance noted SMITH, G R Region 1, Philadelphia, Fuel Facility & Materials Bofsty Branch 80/03/05 2pp
- --8004210120 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination 5 package oxternal feature requirements

 POTTER, P , BROWN, R A Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/12/12 7pp
- 8004070409 Ack receipt of 800118 A 791211 ltrs informing NRC of steps taken to correct violations noted in IF Insp Rept 50-289/79-18 GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/07 1p
- --8004070416 Responds to NRC 791115 itr re-violations noted in IE Inep Rept 50-289778-18 Corrective actions evaluation of extremity dose to whole body dose ratios in progress Extension until 791231 requested HERBEIN, J 0 11e Netropolitan Edison Co 79/12/11
- ~-8004070420 Ack review of corrective action & advises that corrected termination itrs sent to affected individuals ARNOLD,R C Metropolitan Edison Co 80/01/18 1p
- 8004020054 Forwards response to IE Bulletim /9-01B re environ qualification of Class IE equipment Provides master list of alectrical components Will submit qualification data within 45 days after master list submitted HERBEIN.J 0 Metropolitan Edison Co BO/03/11 33pp
- 8004070219 Responds to IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Burial "Personnel training requirements will be completed by Apr 1980 Requests that Unit 1 radwaste be released for shipment WILSON,R F Metropolitan Edison Co 80/03/31 7pp
- 8004110298 Responds to NRC 800223 ltr requesting status of actions All IE Bulletin 79-19 items essentially complete Personnel training requirements near completion & approval of three radvasts shipments was gained Add status into encl WILBON,R F Metropolitan Edison Co 80/03/31 7pp
- 8004150276 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004070065 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region i. Philadelphia. Office of the Director BO/04/01 ip

- 8004110149 Forwards IE info Notice BO-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required GRIER, II H. Region I. Philadelphia, Office of the Director 80/04/02 lp
- 8004240315 Forwards IE Info Notice BO-14. "Safety Suggestions From Employees" No action required GRIER.B H Region 1. Philadelphia. Office of the Director BD/04/02 1p
- 8004180240 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required CRIER,B H Region I. Philadelphia, Office of the Director 80/04/03 ip
- 8004230448 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004180171 Forwards IE Bulletin 80~08, "Exam of Containment Line: Penetration Welds " Written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/07 1p
- 8004150621 Forwards 790821 & 22 itrs from B&W to B&W owners group as partial response to IE Bulletin 79-050 Includes technical analysis of small breaks & impact assessment of RCP trip on non-LOCA events
 THORPELJ R General Public Utilities GPU Bervice Corp 80/04/09 i3500
- 8004300580 Ack receipt of 800220 itr informing NRC of steps taken to correct violations noted in IF Investigation Rept 50-289/79-10

 * Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/04/10 ip
- --8004300586 Responds to NRC 790906 let re violations noted in IE Investigation Rept 50-289/79-10 Corrective actions reexamination of items not completed during 1979 inservice inspersam has been scheduled for wk of 800218 HERBEIN.J O Metropolitan Edison Co 80/02/20 ip
- B004180473 Discusses inservice insp program submitted 791026 Clarifies position re upgrade of ultrasonic nondestructive examination techniques & procedures Upgrade completed w/o replacing calibr stds
 HERBEIN, J O Metropolitan Edison Co B0/04/11 1p
- R Periodic operating reports & related correspondence
- 8004010444 Bubmits "EPA Preliminary Data Rept 800312.14.17 & 21." prepared by Environ Monitoring Sys Lab SMITH.A E Environmental Protection Agency 80/03/24 ip
- 8004010490 Submits "NRC Air Sample Results for 800305,12 & 19," prepared by Environ Monitoring Sys Lab. EPA 8MITH.A E Environmental Protection Agency 80/03/26 ip
- 8004070222 Submits preliminary air & water sampling data for 800319-26 BMITH.A E Environmental Protection Agenty 80/03/27 ip
- 8004140420 Forwards weekly status rept for uk ending 800328 re offsite emergenty radiological environ monitoring program Surface & drinking water samples had normal tritium & gross beta activities

 OERTZ.8 M Porter-Gertz Consultants, Inc. 80/03/28 22pp
- .
- 8004070335 Forwards "Radiological Environ Monitoring Program Annual Rept,1979," "Hydraulic Survey" & "1979 Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of Facility "
 HERBEIN,J, & Metropolitan Edison Co. 80/03/31 2pp
- --8004070339 "Radiological Environ Monitoring Program Annual Rept for 1979 "
 - * Metropolitan Edison Co 80/04/30 98pp
- --8004070343 "Hydraulic Survey," for Jul 1979 Three oversize drawings
 - enci + Gilbert/Commonwealth Cos, 79/07/31 20pp
- --8004070347 "1979 Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of Facility " PELLEK.R R , FRIDAY.O P , JOHNSON.R R NUS Corp 80/02/29 32pp

- 8004250395 Forwards preliminary data from offsite emergency radiological environ monitoring program consisting of program summary & status for wt of 800328-0403 GERTZ.5 M Porter-Gertz Consultants, Inc. 80/04/0: 14pp
- 8004070332 Submits average daily readings of radiation levels as measured by gamma rate recorder installed at Goldsboro fire hail for 800322-29 BAST. J. Environmental Protection Agency 80/04/07 ip
- 8004230493 Forwards monthly operating rept for Mar 1780 HERBEIN, J G Metropolitan Edison Co 80/04/15 Lp
- --BOO4230495 Monthly operating rept for Mar 1980 M1TCHELL,D G Metropolitan Edison Co 80/04/15 5pp
- 8004230375 Preliminary data lept of air & water sampling CORKERN, W D Environmental Protection Agency 80/04/16 ip
- S Reportable occurrences, LERs & related correspondence
- 800401033B RO BO-06/1P on 800325, during refueling frequency reactor bldg local leak rate tost of valve RB-V7.updated total leakage exceeded Tech Specs Testing is continuing w/approx 1/4 of test program complete TOULE,R J Hetropolitan Edison Co 80/03/26 1p
- 9004040336 Forwards LERs 80-005/99%-0 10 80-011/99%-0 HERBEIN J G Metropolitan Edison Co 80/03/27 1
- --8004040344 LER 80-005/99%-0 on 800321.Rosemount 1152 pressure transmitter in limited cases exhibited output between 4 & 20 ma w/input pressure over or under callbr range Caused by long-term degradation from submergence in water CHAPLIN.S D Metropolitan Edison Co 80/03/27 ip
- --B004040349 LER B0-011/99X-0 on 800321.Rosemount 1152 pressure transmitter in limited cases exhibited output between 4 & 20 ma w/input pressure over or under callbr range Caused by long-term degradation from submergence in water GHAPLIN.S D Metropolitan Edison Co 80/03/27 4pp
- 8004280632 PNS-I-80-004 on 800327, two bomb threats were received both stating that bomb was set for 800328 Search conducted No bombs found MADDEN, W., DEVLIN, J., MARTIN, W. Region 1, Philadelphia, Office of the Director
- 8004230406 Forwards LER 80-006/01T-0 HERBEIN, J. G. Metropolitan Edison Co. 80/04/09 1p
- --8004230411 LER 80-004/01Y-0 on 800325 during periodic reactor bldg local leak rate testing containment isolation Valve RB-V7 had excessive loakage Cause suspected to be seat damage Improved valve placed on order MITCHELL.D O Metropolitan Edison Co 80/04/08 2pp
- U Congressional/Executive Correspondence
- BO040B0137 Responds to B00220 ltr referring to 0 Dogardus concerns re facility restart Hearing could not be expected before June 1980 due to scope of proceeding, magnitude of intervention & late licensee submittal of technical matl DIRCKS:N J Office of the Executive Director for Operations B0/03/07 ip
- --B0040B014i Requests response to encl Q&V Hogardus B00209 ltr supporting plant restart MATHIAS, C M Benate B0/02/20 2pp
- V Operator Examinations
- 8004100420 Discusses reasons for pustponement of re-examination of licensed personnel at facility Startup date has been indefinitely postponed making testing premature Util will probably contest decision COLLING.P F Operator Licensing Branch 80/03/27 2pp

- " > T " , Criticism'r Lewb'r wim Staffer Udit L
- In [5 listinges in [7] tell or ne unberns for emergency readiness and a Publication art. are expected before resumption of latesting feedback for a latest reasure? protect reasure in the section of the latest reasure in the latest reasure i
- T 1429 1424 F transported samegowrith contingency plan Plan withheld (ref 1504/64 750) Ascribed 5 C - Dagtin Edison Co - 80/04/82 - 1p
- Alicatury correspondence
- ACASMAS / Mutiries that liain has been filled by E Brooks ? A Brooks diainst libid in connection of operation of facility extrans and complaint end of ACOSMAN 5 C Boston Editor Co. 80/04/17 App.
- of General currespondence
- to 42(0044 Rescands to 810309 ltr requesting into re environ effects of New England nuclear power plants Radiation effluent levels determined by 1007640 % map 1 to 1007650 Environ info available in stated 10105 BALLAGO & L. Environmental Projects Branch 1 80/04/01 2pp
- M Antitrust rorrespondence
- EU04090471 Response recommending that State of MA Municipals 791013 withdrawal of intervention as most be granted Antitrust tearing no longer necessary per enti 000 800317 Itr & due to settle-ent between municipals & util GOLDBERG U.R. Antitrust Division 80/03/31 2pp
- -- 5004050475 Responds to 791024 itr requesting DOJ advice per Atomic Energy Act Antitrust hearing no longer neressary due to settlement between State of MA numeripels & util Certificate of Sec encl LITYACK. 5 M Justice. Dept of 80/03/17 4pp
- P Operating license stage tocuments & correspondence
- COJ4080113 Surraily of SD3227 neeting u/GE & licensee in Bethesda, MD resiste core spray spaiger cracks associated analysis & plans for resuming power associated enalysis & plans for resuming power associated enalysis & plans for resuming power associated analysis & plans for resuming power associated analysis & plans
- C004070405 Discusses ARC Toll23 request that all LHR licensees assess assess assess assess assess assess assess that all control to the second that all control to the second that all the second the second that all the second that all the second that all the second that all the second t

- 5004030332 Summary of 800313 meeting uzutil.MPR Associates.lnc.GA Power Co. I NUS Corp in Bethesda.MD re util plans to operate facility during Cycle 5 w/visually identifies cracks in core spray sparger

 HANNON.J N Operating Reactors Branch 3 80/03/20 6pp
- B004070304 Submits electrical power sys info re new voltage trip actorints, surveillance testing for timers on shutdown transformer. & installation of undervoltage trip devices for autiliary & shutdown transformer breakers ANDOGNINI.G C Boston Edison Co B0/03/28 5pg
- BO04280167 Forwards video tepe of fuel assemblies in fuel pool provided by vtil on 800321 for NRC review W/o enc! GRIER.B H. Region 1. Philadelphia. Office of the Director
- E0040B039B Responds to NRC B00327 telcon request for info re unscheduled entries of drywell from 750101 to present Submits info for pariag cavering 770B01 to present ANDOONINI.0 C Boston Edison Co B0/04/Q1 2pp

- 8004090470 Forwards proposed changes to App A of Tech Spets & Bupp) to "Supplemental Reload Cicensing Submittal for Reload 4" HOWARD, J E. Boston Edison Co. B0/04/03 Spp
- --8004090472 Proposed changes to Tech Space App A.lovising operating limit may average planer linear heat-peneration rate to ensure LOCA limits will not be exceeded # Boston Edison Co 80/01/03 Bpp
- --8004090476 Cuppl 1 to "Supplemental Reload Licensing Bubmittal for Reload 4" -BRANDOUR J , KISS, E , GRIDLEY, R L General Electric Co NEDD-24224-1 80/03/27 10/pp
- 8004100414 Forwards methods of implementation for Category A items re 791030 discussions of Lessons Learned Task Force short-term requirements Conformance necessary prior to next operating cycle

 AMDGOMINIC C Boston Edison Co 80/04/04 35pp
- BOO41003BA Application for mod of App A Tect. Spece to License DPR -35 consisting of various changes in surveillance requirements between the set of the Booken Booken Co. BO/04/07 ip
- --8004100389 Proposed App A Tech Spec changes re care spray spangar break detection setpoint hydraulic snubbers, electrical power sys surveillance requirements, mods to safety relief valves & containment isolation valve logic # Boston Edison Co 80/04/07 34pp
- 8004140310 Discusses secondary containment leak rate test Tost demonstrated that standby gas treatment sys could maintain 1/4 inch of water vacuum in socondary containment Tust data enci MCGUIRE, P. J. Boston Edison Co. 80/04/07 1p
- --8004140311 "Secondary Containment Leak Rate Test Data "
 * Boston Edison Co 80/03/20 ip
- 8004250037 Forwards 800128 % 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of crecking in return line noises Guidelines for mods will be discussed in NUREO-0617, to de issued in "For Comment" form in Apr 1980
 IPPOLITO, T A Operating Reactors Branch 3 80/04/07 2pp
- 8004280027 Forwards request for info returbine disc cracking to be supplied on schedule that will allow review prior to startup from current refueling outage Assessment of patential for turbine missile damage should be provided 1678CLTCGTA Operating Reactors Branch 3 80/04/07 4pp
- 6004180363 Folwards addl info in response to NRC 791211 itr requesting clarification of adequacy of breakwater to pesign safety function Results of survey b insp of breakwater encl ANDOGNINI.G C Doston Edison Ca 80/04/15 25pp
- 8004220580 Forwards info re control rods failing to fully insert for 1978-79.per 800110 request ANDODNINI.G C Boston Edison Co 80/04/14 App
- 8004230469 Advises of typographical error in NEBD-24224 re Relead 4 licensing Info on Page 2 should be -0 22870 217 Calculations not affected ANDOGNINE, G C Boston Edison Co 80704/17 1p
- G Inspection reports, IE Bulletins & correspondence
- 8004070354 Forwards IE Insp Rept 50-293/80-02 on 8001j7-18 Ne noncompliance noted SMITH, O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/05 2pp
- --8004070358 IE Insp Rept 50-293/80-02 on 800117-18 No nuncompliance noted Major areas inspected radwaste shipment to Barnwell; SC including procedure, thipment record & regulatory requirement reviews CLEMONS, P. CROCKER, H. W. Region 1. Philadelphia, Office of the Director 80/01/31 Jap
- 80040407 Forwards IE Insp Rept 50-293/80-01 on 800108-11 No noncompliance noted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/08 ip

- --B0040404i1 IE Insp Rept 50-293/80-01 on B00108-11 No noncompliance noted Major areas inspected administrative controls for safety-related mainth activaties, technician qualifications & preparation for refueling KEHOE.D., BAUNACK.W. Region I, Philadelphia, Office of the Director MARTIN.T T Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/06 Spp
- 8004090395 Forwards IE Insp Rept 50-293/80-03 on 800122-24 No noncompliance noted CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/12 2pp
- --8004070401 IE Insp Rept 50-273/80-03 on 800122-24 No noncompliance noted Major areas inspected torus mod & inservice insp
 TRIPP.LE Region 1, Philadelphia, Reactor Construction & Engineering Support Branch WALTONG & Region 1, Philadelphia, Office of the Director 80/02/07 App
- 8004160145 Farwards IE Insp Rept 50~293/80-04 on 800128-31 No noncompliance noted BRUNNER,E J NRC Regional Offices 80/02/28 2pp
- --B004i60i53 lE Insp Rept 50-293/80-04 on B0012B-31 No noncompliance noted Major areas inspected inservice insp implementation, snubber program, containment integrated leak rate test procedure & plant tours
 MARTIN.T T Region 1. Philadelphia, Roactor Operations Nuclear Support Branch KEHDE, D. HIGOINS, J Region 1. Philadelphia, Office of the Director 80/02/25 14pp
- BOO4210169 Forwards IE Insp Rept 50-293/79-07 on 791009-10 No noncompliance noted BMITH.Q H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch BO/02/28 2pp
- --8004210173 IE Insp Rept 50-293/79-07 on 791009-10 No noncompliance noted Major areas inspected radiation protection program. including training, surveys, posting & control & facility tours

 KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials
 Bafety Branch GALLINA, C D . THONUS, L H Region 1, Philadelphia, Office of the Director 80/02/27 5pp
- 8004110079 Requests 10-day extension of 45-day response period for Items 1.2 & 3 of IE Bulletin /9-018
 ANDOGNINI.0 C Boston Edison Co 80/03/04 1p
- 8004090469 Forwards If Mgt Meeting Rept 50-293/80-06 on 800207 BRUNNER.E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/06 1p
- --8004090473 IE Mgt Meeting Rept 50-293/80-06 on 800207 Areas discussed astablishment of onsite ofc for two full-time resident inspectors All parties concurred on adminstrative & operational considerations needed to establish ofc MARTIN,T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch MCGAUCHY,R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch (EMDE,D V Region 1, Philadelphia, Office of the Director 80/03/04 2pp
- BOO4280277 Forwards IE Insp Rept 50-293/79-23 & Waste Packaging Insp Rept 79-08B on 791227-28.800104 & 791216.respectively GRIER/B H Region i, Philadelphia. Office of the Director BO/03/06 2pp
- --B004280300 IE Insp Rept 50-273//9-23 nn 791227-28 & 800104 Noncompliance noted failure to comply w/DDT regulations CLEMONS.P , GALLINA.C . CROCKER.H W Region 1. Philadelphia. Office of the Director 80/01/10 Spp
- --8004280310 Waste Packaging Insp Rept 79-088 on 791218 Noncompliance noted radiation levels in excess of specified limits BROWN,R A , POITER, J.P. Region I, Philadelphia, Office of the Director 79/12/21 3pp
- 8004010013 Forwards response to 800215 notice of violation & \$5,000 check for resulting civil penalty imposed Responsible personnel reinstructed on proper methods of radiation surveying, packaging & shielding ANDOGNINI.0 C Boston Edison Co 80/03/10 3pp
- 8004250156 Forwards response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " Environ capability of electrical equipment received adequate consideration during design & const of facility W/o encl ANDOGNINI. Q C Boston Edison Co BO/03/12 5pp

- 8004110008 Ack receipt of 800304 lir requesting extension of IE Builetin 79-018 data submittal date Requests 24-h notification of any deviation from understanding that response to Items 1.2, 7.3 will be submitted by 800317 GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/14 19
- BOO4240552 Advises that IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required GRIER, 8 H Region 1, Philadelphia, Office of the Director BO/03/17 ip
- 8004300602 Forwards IE Insp Rept 50-293/80-07 on 800220-22 No noncompliance noted CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/17 2pp
- --8004300607 [E Insp Rept 50-293/80-07 on 800220-22 No noncompliance noted Major areas inspected activities re torus mod & inservice insp WALTOR & Region 1, Philadelphia, Office of the Director 80/03/13 | 5pp
- 8004160125 Ack receipt of 800229 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 90-293779-21
 BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/03/24 ip
- --8004160133 Responds to NRC 800121 ltr re violation noted in 1E Insp Rept 50-293/79-21 Corrective actions fire protection operating procedures will be revised to implement requirements re Tech Specs 6 B 0.3 12 £ 4 12 ANDOGNINI.G C Boston Edison Co 80/02/29 3pp
- --8004160137 Forwards IE Insp Rept 50-293/79-21 on 791210-14 & notice of violation BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/21 2pp
- --8004160141 Notice of violation from insp on 771210~14

 * Region 1, Philadelphia, Office of the Director 80/01/14 ip
- --B004160146 IE Insp Rept 50-293/79-21 on 791210-14 Noncompitance noted failure to adequately implement fire protection operating procedures BAUNACK, W. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch CHUNG, J. BLUMBERG, N. Region 1. Philadelphia, Office of the Director 80/01/14 14pp
- 8004150242 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- 8004090037 Forwards IE Circular 80-05, 'Emergency Diesel Generator Lubricating Off Addition & Onsite Supply " No written response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/01 ip
- 8004110122 Forwards IE Info Notice 80-13, "9E Type SBM Control Switches Defective CAM Followers" No written response required ORIER, B H Region 1, Philadelphia. Office of the Director 80/04/02 1p
- 8004240270 Forwards 1E Info Notice 80~14, "Gafety Suggestions From Employees" No action required GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/02 1p
- 8004180227 Forwards [E Circular 80-07, "Problems W/HPCI Turbine Cil Sys " No written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/04/03 ip
- 8004110050 Forwards IE Bulletin 80-07, "BMR Jet Pump Assembly Failure " Written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/04/04 ip
- 8004230463 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe " Action required GRIER, B H Region 1, Philadelphia, Office of the Director 60/04/04 1p

- E-U-410VI19 Fire-aris [E Bulletin to UR. Eyem or Containment Liner Penetration Welss - Written response required GRIER B.H. Region 1 Philadelphia, Office of the Director BO/O4/4/2 - 1p
- 12:04233177 Publits response to 1E Bulletin 80-02 Replacement feedwater spargers / treinal siee es ucre purchased through GE-San Unse CA / fabricated by Mar in Engineering during Feb 1980 Mo adverse effects on quality were observed AMOOSMIP G C Boston Filson Co 80/04/17 2pp
- F Periodic operating reports / related correspondence
- 6004080511 Forwards Environ Radiological Monitoring Rept 12. 1979
 ANDOGNINI G C Boston Edison Co 80/04/01 19
- --8004050524 Environ Radiological Monitoring Rept 12, " 1979 50WD0W T L . MGSOLESMO.F J Boston Edison Co BO/04/30 131pp
- EG04230497 Forwards monthly operating rept for Mar 1980 MCGUIRE, P. J. Boston Edison to 60/04/09 1p
- ---BOC4230479 Monthly operating rept for Mar 1980 UHITNEY, G.G. Boston Edison Co. 80/04/03 6pp
- 5 Reportable occurrences &ERs & related correspondence
- 8004250338 Requests 24-h norification of deviation from understanding per 800311 telcon re recent incident that fuel handling operation will not resume until certain conditions are met, including concurrence from IE.

 GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/03/11 ip.
- 8004150576 Forwards revised LER 80-009/04T-1 MCGUIRE, P J Boston Edison Co 80/04/02 1p
- --8004150588 Revised LER 80-009/04T-1 on 800310.util received analysis rept from fankee Atomic Electric Lab indicating reportable Cr-51 concentrations were found in mussel samples from discharge canal Cause not stated HCLOUGHLIN.M T Boston Edison Co 80/03/18 1p
- 6004300552 PNS-I-80-005 on 800404, bomb threat was received Search was conducted No bomb tound MCMEOWILL DEVLIN, J. MARTIN W. Region 1, Philadelphia, Office of the Director 80/01/07 ip
- 8004140337 Forwards LER 80-010/03L-0 MCGUIRE, P. J. Boston Edison Co. 80/04/09 1p
- --8004140342 LER 80-010/03L-O on B00310.hydrant hose house 5 damaged when hit by truck House wrapped around hydrant.preventing access Cause not stated House rebuilt & returned to svc MCLGUGHLIN.M T Boston Edison Co 80/04/09 1p
- 8004170184 Forwards LER 80-011/017-0 HCGUIRE,P J Boston Edison Co 80/04/09 Lp
- --8004170191 LER 80-011/01T-O on 800326, utilizing approved station procedure TP80-37, PNPS jet pumps examined & jet pump beams 1,3 to 15 found to have discontinuities Caused not stated Flawed beams to beam bolt assemblies replaced MCLOUPHLIN.M T Boston Edison Co 80/04/09 1p

- V Operator Examinations
- 8004150158 Approves 750828 revision to requalification program ro simulator retaining Add1 changes may be required after review of other operator training programs COLLINS,PF Operator Licensing Branch 80/03/27 1p
- DOCKET 50-294 HICHIGAN STATE UNIV RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8004010227 Forwards Tech Specs, amended to comply w/new format requirements, for renewal of License R-114 WILKINSON, R., CARRICK, J., TERRY, S.H. Michigan State Univ. B0/03/11
- ~-8004010227 Tech Specs, amended to comply w/new format requirements
 * Michigan State Univ 80/03/11 52pp
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B0041100B9 Forwards request for add1 info re 790323 contingency plan & 791026 Revision 1 Request withheld (ref 10CFR2 790) SCHWENCER, A Operating Reactors Branch 1 B0/02/27 1p
- 8004240531 Forwards sys description b operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimilie traffic KEPPLER, J G Region 3. Chicago. Office of the Director 80/03/20
- 8004010357 Forwards fire protection review Items 3 1 3.3 1 4 % 3 1 5 Review is duplicate of 800307 review W/minor paragraph change in Item 3 1 3 % clarification of Item 3 1 5 HALL,R E Brookhaven National Laboratory 80/03/Ri 4pp
- 6004230125 Forwards evaluation of facility fire protection program & status of incomplete items identified in 780310 & 790413 safety evaluations Position on safe shutdown capability also enc:

 SCHWENCER.A Operating Reactors Branch 1 80/03/24 22pp
- 8004270037 Discusses arrangements for 800411 meeting w/util in Glen Ellym.IL re noncompliance % program weaknesses identified in recent health physics program appraisal insp KEEPLER, J G Ragion 3. Chicago, Office of the Director 80/04/07 ip
- B004300588 Notification of B00417 meeting w/util in Bethesda,MD to discuss meteorological acceptance criteria for emergency preparedness at site REEVES,E Operating Reactors Branch 1 B0/04/08 2pp
- B004220356 Bubmits info in response to NRC question re characteristics of fire suppression sys for grouped cable trays in stairwell between Unit 1 & 2 cable spreading rooms NAUGHTON, W.F. Communical the Edison Co. 80/04/14 2pp
- 8004230318 Forwards add1 info re Item 3 1 3.gas suppression sys.for fire protection review Bys acceptable MALL.R E Brookhaven National Laboratory 80/04/14 2pp
- 8004230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790) PEOPLES D L Commonwealth Edison Co 80/04/21 1P
- G Adjudicatory correspondence
- 8004070139 Forwards 800229 confirmatory order amending facility QLs by incorporating commitments to implement add1 procedural measures & design changes made in util 800222 ltr Actions necessary for continued assurance of public health & safety DENTON, HR Office of Nuclear Reactor Regulation 80/02/29 2pp
- --8004070142 Confirmatory order amending facility OLs by incopprating commitments to implement addl procedural measures & design changes agreed to in util 800222 ltr & discussed in encl. DENTON, H R Office of Nuclear Reactor Regulation 80/02/29

- 8004080078 Forwards FR notice & director's decision under IOCFR2 206 denying request for preparation of EIS re Amends 44 & 41 to facility OLs

 BENTON, H R Office of Nuclear Reactor Regulation 80/03/13 1p
- --8004080083 Director's decision under 10CFR2 206 denying C Quigg 790427 request that Director of Nuclear Reactor Regulations order full EIS for Amends 44 % 41 to OLs Amends will not significantly affect quality of human environ DENTON: H R Office of Nuclear Reactor Regulation 80/03/13 6pp
- --B0040B00BB Notice of issuance of Director's decision under 10CFR2 204 denying C Guigg 790427 request that Director of Nuclear Reactor Regulation order full EIS for Amends 44 % 41 to CLs No basis for issuing EIS exists DENTON, H R Office of Nuclear Reactor Regulation 80/03/13 to
- 8004080568 Order granting extension.until 800409.for Commission to elect whether to review 800319 denial of enforcement action CHILK.S J Office of the Socretary of the Commission 80/03/31
- BD04030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GDSBICKL V Office of the Executive Director for Operations B0/04/02 34pp
- BOO4280590 Requests immediate suspension of license issued by NRC to Comm Ed to rerack & compact spent fuel pool to 2.112 spent fuel assemblies GUIGG.C Pollution Environmental Problems 80/04/17 2pp
- H General correspondence
- 8004210336 Advises that 791106 ltr to President Carter re emergency plans has been referred to NRC Since Summor 1979, NRC has been actively pursuing program to upgrade emergency preparedness Forwards NRC/FEMA documentation W/o encl DENTON, H R Office of Nuclear Reactor Regulation 80/0 B0/03/31 3oo
- 8004i50085 Responds to 800228 ltr re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites

 DENTON, H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004150074 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident BTERNER, J W Affiliation Unknown 80/02/28 ip
- 8004160173 Responds to 800212 ltr re continued operation of nuclear power plant Add1 measures should be implemented that will further reduce probability of severe reactor accidents. Licensee has been in shutdown pending completion of actions DENTON:H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004i60176 Requests that NRC not phase out facility or convert to non-nuclear generators Nuclear power is source for power in US No nuke political arguments have no basis in reality LAVERTY,E Affiliation Unknown B0/02/12 2pp
- 8004170342 Responds to 800206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- 800421008B Responds to 800125 request re-public hearing & determination on UCB petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences
 DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210073 Requests scheduling of public hearing & determination of UCB petition re operation of facility prior to reactivation. Concerned for health & safety of community SCIANDRA. J New York NY 80/01/25 ip.
- 8004210193 Responds to 800207 ltr re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants Interim measures have already been ordered at sites DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant, lowering rates & dependency on foreign oil WU, J Affiliation Unknown 80/02/07 ip •

- 8004210208 Responds to 800204 ltr re continued operation of facility Plants reviewed to determine what addl measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- 8004250013 Responds to 800212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure DENTON, HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004250030 Urges that NRC consider UCS petition re closing of facility Possibility of earthquake crists u/plant built near fault Only 20% of area energy generated by nuclear power Alternatives should be considered GOLDHOR,F Affiliation Unknown 80/02/12 1p
- 8004250018 Responds to 800215 1tr re operation of facility MRC considering what special measures should be taken to reduce probability of severe reactor accident or to lessen consequences Confirmatory orders issued as interim measure DENTON.H R Office of Nuclear Reactor Regulation 80/04/01
- P Operating license stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- B0040B0377 Summary of Westinghouse Lessons Learned team 800121-22 site visit to determine implementation status of Category A Lessons Learned requirements Status of each item & attendance list encl
 TELFORD.J T NRC Three Mile Island Task Force 80/02/15 App
- 8004110569 Forwards Lessons Learned Task Force status re implementation of Catagory A requirements following 800121-22 visit by Wastinghouse Util has signed confirmatory itr specifying that NRC will be notified of noncompliance TELFORD FT TMI-2 Lessons Learned Task Force 50/02/15 App
- 8004020469 Forwards NRC safety analysis of cracking discovered in feedwator sys Util repair program, nondestructive insph & leakage tosting are adequate to insure that integrity of feedwater piping will be maintained SCHMENCER. A Operating Reactors Branch 1 80/02/29 6pp
- BOO4180389 Forwards modified near-site study in response to NRC 791205 request for 60-day crash effort PEOPLES.D L. Componwealth Edison Co. DAVIS.J F. Power Authority of the State of New York CAHILL.M J. Consolidated Edison Co. of New
- 8004020257 Forwards Amends 52 & 49 to Liteuses DPR-39 & DPR-48. NAVOURLY Forwards Amends 32 6 49 to Licensee break & DMR-48 respectively Amends consist of changes to license & appended Tech Specs permitting mod of spent fuel pool increasing storage capacity from 868 to 2.112 fuel assemblies SCHWENCERA Deersting Reactors Branch 1 80/02/28 2pp
- --8004020262 Amend 52 to Liceuse DPR-07.changing license & appended Tech Specs to parmit mod of spent fuel pool to increase storage capacity from 868 to 2.112 fuel assemblies 8CHWENCER, A Operating Reactors Branch 1 80/02/28 3pp
- --8004020266 Amend 47 to License DPR-48, changing license & appended Tech Specs to permit mod of spent fuel pool to increase storage capacity from 868 to 2,112 fuel assemblies Replacement pages of App A Tech Specs encl SCHWENCER, A Operating Reactors Branch 1 80/02/28 6pp
- --8004020270 Notice of issuance of Amends 52 & 49 to Licenses DPR-39 & DPR-48, respectively & negative declaration SCHMENCER. A Operating Reactors Branch 1 80/02/28 3pp
- 8004220192 Requests add1 info re dimension of upper vessel head surrounding control rod penetrations Info needed to complete work being conducted by Los Alamos Labs re vessel strengthening Drawing encl SCHWENCER.A Operating Reactors Branch 1 80/02/28 2pp
- 8004010004 Forwards "Evaluation of Licenses Compliance w/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned " All Category A requirements satisfied BCHWENCER, A Operating Reactors Branch 1 80/02/27 2p 80/02/29 2pp

- ---8004010006 Evaluation of Licensee Compliance U/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned " # Division of Operating Reactors 80/02/28 11pp
- 8004280217 Forwards SEP schedule 5 content requirements for environ JUGGEOUZ) Forwards Str schedule 2 content requirements for qualification of electrical equipment Previously submitted info should be incorporated by specific ref Facilities exempt from IE Bulletin /9-01B SCHWENCER.A Operating Reactors Branch 1 80/03/05 5pp
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital tommunication sys to transmit into from plants to Bethesda Operations Ctr EISENHUT,D G Division of Operating Reactors BO/03/12 Spp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- B0040B0003 Forwards Amends 53 & 50 to Licenses DPR-39 & DPR-48, respectively, safety evaluations & notice of issuance & availability SCHMENCER A Operating Reactors Branch 1 80/03/13 2pp
- ~-8004080005 Amends 53 & 50 to Licenses DPR-39 & DPR-49, respectively, changing, Tech Specs, App. A. to increase allowable LOCA peaking factor from 1 86 to 1 93 based on FCCS reanalysis GAMMILL, W.P. Division of Operating Reactors 80/03/13 7pp
- --8004080008 Safety evaluation supporting Amends 53 & 50 to Licenses DPR-39 & DPR-48 respectively # Office of Nuclear Reactor Regulation 80/03/13 4pp
- --8004080011 "Safety Evaluation of Request for Removal of Conservatism In Westinghouse PAD Computer Code," prepared in response to util request for DL amend * Core Performance Branch 80/03/31 32pp
- --8004080013 Notice of issuance & availability or Amends 53 & 50 to Licenses DPR-39 & DPR-48, respectively SCHWENCER.A Operating Reactors Branch 1 80/03/13 2pp
- 8004140221 Summary of B00221 meeting w/representatives of all SEP plants.utils 5 Franklin Research Ctr re-accelerated program for evaluating qualification of safety-related elactrical equipment HILSON.R Plant Systems Branch 80/03/14 3pp
- 8004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days

 KEPPLER. J G Region 3. Chicago, Office of the Director 80/03/20
- 8004210194 Forwards request for info re containment environ conditions & sys required fo; accident mitigation for review of environ qualification of Class IE electrica) equipment NRC will estimate time for containment temp to return to near normal SCHWENCER A Operating Reactors Branch 1 80/03/20 15pp
- 8004020189 Forwards response to ARC 800227 confirmatory order to perform actions within 30 days Westinghouse representative stationed onsite ventilation intakes re-examined emergency action levels revised by reactor operators training underway NAUOHTON. W.F. Commonwealth Edison Co. 80/03/28 7pp
- 8004080214 Forwards response to immediate action items of NRC 800229 confirmatory order No immediate action required In-plant walk-throughs will be completed prior to next reactor startup Simulator training is in progress NAUGHTON. N F Commonwealth Edison Co 80/03/28 4pp
- 8004290364 "Safety Evaluation of Inservice Testing Program for Pumps & Valves." 780117-790916 FEHRINGER, J M : ROCKHOLD, H C EG & G. Inc FIN A-6258 8004250364 80703731 46pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title NAUGHTON.W F Commonwealth Edison Co 80/04/02 1p
- ~~8004150328 Revised pages constituting Hevision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1~A RIG 80/04/04 7pp

- 8004100338 Responds to NRC 800228 Itr re Drawing 686J374 Apparent increased thickness of upper vessel head surrounding control ind penetrations does not exist Actual thickness uniform & 6-578 inches + 178 inches-0 inches -70 clad NAUGHTON:W F Commonwealth Edison Co 80/04/03 ip
- 8004240480 Forwards addl info to review of unresolved safety issues, trip rept of Lessons Learned implementation team, & task action plan in view of high population density surrounding plants DENTON, H R Office of Nuclear Reactor Regulation 80/04/09 33pp
- --8004240483 Summary of Westinghouse Leasons Learned team 800121-22 site visit to determine status of Category A implementation Attendance & status lists encl TELFORD. J T Safeguards Standards Branch 80/02/15 5pp
- --8004240496 Summary of Westinghouse Lessons Learned team 800124-25 sitg visit re status of Category A implementation Attendance & status lists encl TELFORD J T Safeguards Standards Branch 80/02/20 5pp
- -- 8004240489 Summary of Westinghouse implementation team 800123-24 & 30 site visit re short-term Lessons Loained requirements TELFORD, J T Safeguards Standards Branch 80/02/15 8pp
- --8004240492 Forwards evaluation of util actions taken to satisfy Lessons Learned Category A requirements Concludes all requirements satisfied Attendance list for 800121-22 site visit enc) SHCHENCER,A Operating Reactors Branch 1 (Pre 791030) 80/02/29 27pp
- ---8004240504 Forwards evaluation of util compliance w/Category A Lessons Learned requirements Concludes all requirements satisfied IE followup & attendance lists encl SCHWENCER.A Operating Reactors Branch 1 (Pre 791030) 80/02/21
- ---R004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON.H R Office of Nuclear Reactor Regulation 80/02/21
- --8004240518 Discusses Event 5 probabilities Suggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements TAYLOR:M A Division of Reactor Safety Research 80/01/15 17pp
- 5004250232 Forwards status of unresolved safety issues at Indian Point 1 & 2. trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at facilities, task action plan & facility societal risk info DENTON. H R Office of Nuclear Reactor Regulation 80/04/09 34pp
- 8004240498 Formalizes plans re series of technology exchange meetings re facilities' accident mitigation features activity Five meetings suggested Recommended meeting schedule & agenda items encl
 SCHWENCER.A Operating Reactors Branch 1 80/04/10 15pp
- 8004250427 Forwards response to NUREO-0578 & "Dasign Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lasalle County Site-specific emergency plan PEOPLES.D L. Commonwealth Edison Co. 80/04/15 60pp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities," * Buchtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280509 Forwards revised Page 37 to DL Peoples 800101 ltr concerning commitments re TMI-2 Lessons Learned Task Force short-term PEOPLES, D. L. Commonwealth Edison Co. 80/04/18 2pp
- 8004290502 Application for amend to Licenses DPR-39 & DPR-48, App A Tech Space eliminating refs to part length rods & atmospheric relief valves & revising reactor protection sys permissive testing Table 4 I-1 PECPLES, D L Commonwealth Edison Co 80/04/22 App
- --8004270506 Revised pages to Tech Specs eliminating refs to part length rods & atmospheric relief valves & revising reactor protection sys permissive testing Table 4 1-1 * Commonwealth Edison Co 80/04/22 43pp

- G Inspection reports, IE Bulletins & correspondence
- 8004040316 Forwards IE Insp Repts 50-295/79-22 & 50-304/79-24 on 790910-800204 No noncompliance noted FIORELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004040339 IE Insp Repts 50-295/79-22 \$ 50-304/79-24 on 790910-800204 No noncompliance noted Major areas inspected review of inservice insp program & review of licensee activities re [E Bulletin 79-13 \$ 79-17 DANIELSON.D H. KEY. W.J. Region 3. Chicago, Office of the Director 80/02/14 19pp
- 8004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements radiation levels & DOT labeling POTTER, JP Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/22 6pp
- 9004220157 Forwards IE Insp Repts 50-295/80-01 & 50-304/80-01 on B00103-0206 & notice of violation HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/03/04 2pp
- --8004220165 Notice of violation from insp on 800103-0206 * Region 3. Chicago. Office of the Director 80/03/03 ip
- --8004220175 IC Insp Repts 50-295/80-01 & 50-304/80-01 on 800103-0206 Noncompliance noted facture to follow procedures during shift turnover LITTLE.N 8 . NCHLER.J C Region 3. Chicago. Office of the Director 80/03/03 11pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07 10
- 8004140ii9 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 9td Type II.Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLEG.D L Commonwealth Edison Co 80/03/20 5pp
- B004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS.AB Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/03/21 ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No noncompliance noted DAVIS.A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- ---B004040023 Corrected Maste Packaging Insp Rept 79-07A on 791212-13 Ng noncompliance noted Major areas inspected shapping paper & placarding requirements, radiation levels, removable contamination & package external features POTTER.J P Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/22 7pp
- 8004110555 Bummary of 800118 meeting w/util & Westinghouse in Bethesda, MD re Unit 1 turbine disc insp results repairs made & plans for inspecting Unit 2 low pressure turbine rotor discs List of attendees & supporting mati
- BOO4150159 Ferwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31 10
- 9004090686 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER, J O Region G. Chicago, Office of the Director 80/04/01

- 8004150014 Forwards IE Into Notice 80-13, 'GE Type SBM Control Switches Defective CAM Followers' No specific action of response required KEPPLER, J G. Region 3 Chicago, Office of the Director 90/04/02 tp
- 8004180030 Forwards attachments to IE Circulal 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmitta) KEPPLIK.J G Region 3. Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE into Notice 80-14. "Safety Suggestions From Employees " No action required KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/04/02 in
- 8004220324 Forwards IF Circular 80-07. "Problems W/HPC1 Turbine Dil Sys " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/03
- 8004230224 Forwards JE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/04/07
- 8004220069 Forwards [E Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written tesponse required KEPPLER, J.G. Region 3, Chicago, Office of the Director 60/04/09
- R Periodic operating reports & related correspondence
- BOO4140306 Folwards "Radwaste & Environ Monitoring Annual Rept.1979 " WANDKE,N E Commonwealth Edison Co 80/03/18 1p
- --8004140322 "Radwaste & Environ Monitoring Annual Rept,1979 " KOHL.K A Eberline Instrument Co:p 80/03/18 60pp
- 5 Reportable occurrences, LERs & related correspondence
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT.K W Region 2. Atlanta, Office of the Director 77/08/12
- 8004020311 Forwards LER 80-010/03L-0
 WANDKE, N Commonwealth Edison Co 80/03/17 10
- --8004020313 LER 80-010/03L-0 on 800219 during normal operation component cooling liquid rad monitor IRE-0017 read high alarm intermittently Caused by corroded detector contact pins due to condonsation Pin replaced & more insulation installed DST.F Commonwealth Edison Co 80/03/17 ip
- BDO4020369 Forwards LER 80-011/03L-0 WANDKE,N E Commonwealth Edison Co 60/03/17 1p
- --8004020376 LER 80-011/GJL-O on B00224.while performing daily radiation monitor operability check.PTO App N.Unit 1 passive gas failure radiation monitor. IRTPRIS failed low 2 could not be reset Caused by defective transistor ZN3638
 TRZYNA.G Commonwealth Edison Co 80/03/1/ 1p
- 80042B064; PNO-111-80-063 on 80033; unplanned gaseous radiation release occurred because of operator error in operating valves Preliminary analysis indicates release rates did not exceed Tech Spec limits BOYD, D.C. KCMLER, J.C. Region 3, Chicago, Office of the Director BOY04/01 2pp
- 6004280654 PNO-III-80-063A 800402,1tr from Mayor of Waukegan,IL. demanded actions as result of 800331 unplanned gaseous release Region 3 is continuing investigation & evaluation STRASMAR J. MEISHIMAN,R F. Region 3. Chicago. Office of the Director 80/04/03 2pp
- 8004220586 Forwards LCR 80-012/03L-0 WANDKE,N E Commonwealth Edison Co 80/04/11 tp
- --8004220576 LER 80-012/03L-0 on 800312, during normal power w/18 diesel generator in standby, oc control breaker tripped Caused by use of 5-amp slow blow fuses in annunciator inverter Slow blow fuses replaced w/fast blowing fuses CLARK. S Commonwealth Edison Co 80/04/11 ip

- 8004220660 Forwards LER GC 013 0.L-0 WANDKE N F Commonwealth Edison Co 80/04/14 ip
- --80042a0ha8 LEG Po-613/columb on 800314, while performing periodic ORT-ARO/: nonzert free by the first pldg area nonitor ORT-ARO/: nonzert free by the first pldg area nonitor ORT-ARO/: nonzert free by instrucent f
- 8004290486 Forwards LER 80 014/03L~0 WANDKE,N E Commonwealth Edison to 80/01/18 1p
- --8004290496 LER 80-014/mgl-0 on 800320.during normal operation, blower of containment tent rad monstor IRE-0011 tripped repeatedly Caused by monitor vibration Replaced relays which trip blower on high or low flow OST.F Commonwealth Edison Co. 80/04/18 1P
- 8004270473 Forwards LER 80-015/03L-0 WANDXE,N E Commonwealth Edison Co 80/04/22 1p
- --80042790483 LER 80-015/03L-0 on 800401 during normal operation, additiony bldg exhaust sys particulate Lodine rad monitor ORT-PRI2ASB instrument failed 'alarms activated Caused by natural endofelire of P/N 2000 magnahelic (sendor-duyer)

 AKER.R E Commonwealth Edison Co 80/04/22 IP
- DOCKET 50 296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3 f Security, medical, emergency & fire protection plans
- 8004150185 Forwards comments on 790301 safaguards contingency plan & 790901 Revision 1 Requests resisions b addl info Encl withheld (ref. 10LFR2 790) IPPOLITO,T A Operating Reactors Branch 3 60/03/27 2pp
- H General correspondence
- 8004210208 Responds to 800704 ltr recontinued operation of facility Plants reviewed to determine what addl measures or design changes can h should be implemented to further reduce probability of reactor accident or consequences
 DENTON-H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --B004210223 Urges NRC to decide in Pavor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shot down

 GAY R H Affiliation Unknown B0/02/04 1p
- 8004300404 Requests that public hearing \$ EIS be required for proposed low level wasta compaction \$ inclineration facility at site JUREIMO.R C Affiliation Uninown 80/04/22 ip
- P Operating license stage documents & correspondence
- 8004020178 Forwards request for addl info on proposed. Tech Spec changes re control & wiring diagrams LAINAS.O Plant Systems Branch 80/02/11 3pp
- 8004240505 "Confirmation of Original Qualification Test for Electrical Connectors Used at Facility," suppl BONZON,L L , BUCKALEN,M H , DUGAN,D M Sandia Laboratories NURE9/CR-1191 80/02/29 200pp Available at NTIS
- 8004070384 Discusses NRC 761123 request that all LMR licensees assess higher fission gas release for fuel burnups above 20,000 MH-day per motilic ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 Spp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bothesda Operations Ctr EISENHUT,D G Division of Operating Reactors B0/03/12 5pp
- --8004030118 "Nuclear Data Lin' Specs "
 * Division of Operating Reactors 60/02/21 28pp
- 8004110519 Forwards Amends 60.55 & 32 to Licenses DPR-33 DPR-32 & DPR-68 respectively, salety evaluation & notice of issuance & availability iPPOLITO,T A Operating Reactors Dranch 3 80/03/17 2pp

- -8004110525 Amends 60:55 % D2 to Elicenses DPR-33, DPR-52 & DPR-68, respectively, authorizing temporary storage of low level radwaste in existing covered pavilion, outside security fence but inside site exclusion area 1PPOLITO,T A Operating Reactors Branch 3 80/03/17 App
- --8004110527 Safety evaluation supporting Amends 60.55 & 32 to Licenses
 DPR-33 DPR-52 / DPR-68, respectively

 # Office of Nuclear Reactor Regulation 80/03/17 7pp
- --8004110531 Notice of issuance % availability of Amends 60.95 % 32 to Licenses DPR-33.DPR-52 % DPR-68.respectively IPPOLITO.T A Operating Reactors Branch 3 80/03/17 3pp
- 8004150423 Advises that addl time will be needed to develop coordinated response to MRC request of 800215 Response will be submitted by 800501 MJLLS, L M. Tennessee Valley Authority 80/04/07 ip
- 8004150557 Forwards add1 info to containment purge & venting sys.in response to NRC 800226 ltr Key lock switches are provided on control switches to allow overriding primary containment
 - isolation signal MILLS.L M Tennessee Valley Authority 80/04/07 3pp
- 8004290028 Forwards 800128 & 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line noisles Guidelines for mods will be discussed in NUREO-0619. to be issued in "For Comment" form in Apr 1980 IPPOLITO,T A Operating Reactors Branch 3 80/04/07 2pp
- 8004230287 Forwards request for additinfo re degraded grid voltage Also requests revised schedule for submission of design of long-term mods re adequacies of station electric distribution sys voltages [FPOLITO.T A Operating Reactors Branch 3 80/04/08 3pp
- 8004230506 Forwards info re control drive malfunctions during CY78 & 79 in response to NRC 800110 request MILLS.L.M. Tennassee Valley Authority 80/04/11 2pp
- 8004220340 Application to amend Licenses PPR-33, DPR-52 & DPR-68 changing Tech Specs to allow conduct of short containment integrated leak rate test Fee encl
 MILLS.L.M. Tennessee Vallay Authority 80/04/15 2pp
- --8004220349 Proposed Tech Spec revisions, allowing conduct of short containment integrated leaf rate test
 # Tennessee Valley Authority 80/04/15 13pp
- --8004220359 "Nuclear Containment Testing for TVA Nuclear Power Plants," presented at ANS 791111-16 winter meeting CLARK.K H . WHITE,T J Tennessee Valley Authority 79/11/16 4600
- 8004220523 Responds to NRC 800212 request for info needed to compare RETRAN code results w/simulator results & EQMO 800317 request for info re LOCA calculational models Singer Co could more adequately address NRC request MILLS:L II Tennessee Valley Authority 80/04/15 2pp
- ---8004220531 Requests assistance in comparing RETRAN & simulator results for BUR plant transients/incidents re loss of feedwater & loss of load BNL should be provided w/related info EG&O BOO317 request for info ancl FABIC.6 Analysis Development Branch 80/02/12 4pp
- 8004220533 Advises that Section 316 documents re NNPDES Permit ALO022080 are being sent to JW Warr.H Zeller & LB Tebo.in accordance w/util 800331 itr EL-ASHRY.M T Tennessee Valley Authority 80/04/17 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004040174 Ack receipt or 800124 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-42, 50-260/79-42 t 50-296/79-42 at 150-296/79-42 b So-296/79-42 b
- --8004040181 Responds to NRC 800102 ltr re violations noted in IE Insp Repts 50-259/79-42,50-260/79-42 % 50-276/79-42 Corrective actions review of all previous insp data records was made to verify notification to DES engineer HILLS.L M Tennessee Valley Authority 80/01/24 3pp

- --B004040185 Forwards IE Insp Repts 50-259/79-42.50-260/79-42 & 50-276/79-42 on 791126-27 & notice of violation MURPHY,CE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/02 2pp
- --8004040189 Notice of violation from insp on 791124-27
 * Region 2. Atlanta. Office of the Director 79/12/14 ip
- --8004040194 IE insp Repts 50-259/79-42,50-240/79-42 & 50-294/79-42 on 791124-27 Noncompliance noted failure to report discrepancies to DES engineer
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENOS,L Region 2. Atlanta, Office of the Director 79/12/14 4pp
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required D'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 80/02/06 200
- 8004090245 Forwards IE Insp Repts 50-259/80-03,50-260/80-03 & 30-296/80-09 on 800129-31 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/19 2pp
- --8004090252 IE Insp Repts 50-259/80-03.50-260/80-03 & 50-296/80-09 on 800129-31 No noncompliance noted Major areas inspected refueling activities KELL009.F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 3pp
- 8004110503 Forwards IE Insp Repts 50-259/80-07.50-260/80-07 & 90-296/80-07 on 800205-07 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004110514 IE Insp Repts 50-259/80-07,50-260/80-07 & 50-296/80-07 on 800205-07 No noncompliance noted Hayor areas inspected video observation of core spray sys sparger & review of proposed actions for LER HERDIAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch VANDODRN.P K Region 2, Atlanta, Office of the Director 80/02/25 3pp
- 8004280194 Forwards IE Insp Repts 50~259/80~05.50~240/80~05 & 50~276/80~05 on 800204~08 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/07 2pp
- --8004280202 IE Insp Repts 50-259/80-05, 50-260/80-05 & 50-276/80-05 on 800204-08 No noncompliance noted Major areas inspected areas of seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14)
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENDS, L Region 2. Atlanta, Office of the Director 80/03/04 App
- 8004020242 Ack receipt of 800204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-38, 50-260/79-38 t 50-296/79-38 LEHIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/11 ip
- ---8004020249 Responds to NRC 800110 ltr re violations noted in IE Insp Repts 50-259/79-38,50-260/79-38 & 50-296/79-38 Corrective actions local leak rate test performed on normal hatch cover & control rod drive added to CILRT results MILLS,L M Tennessee Valley Authority 80/02/04 3pp
- --9004020252 Forwards IE Insp Repts 50-259/79-38,50-260/79-38 & 50-276/79-38 on 791119-23 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/10 2pp
- ---8004020258 Notice of violation from insp on 791119-23,
 ** Region 2. Atlanta, Office of the Director 80/01/08 ip
- --8004020263 IE Insp Repts 50-259/79-38,50-260/79-38 & 50-276/79-38 on 791119-23 Noncompliance noted use of temporary control rod drivelins hatch cover during integrated leak rate test UPRIGHT.C.M. Region 2. Atlanta. Reactor Operations Nuclear Support Dranch BROOKS, E H , WHITENER, H L Region 2. Atlanta, Office of the Director 80/01/08 6pp
- 8004100364 Responds to IE Bulletin 79-23 Conducted sustained full-load operational test on Emergency Diesel Cenerator 3A Test demonstrated ability of diesel generators to function properly over 24-h period at specified loads MILLS,L M. Tennessee Valley Authority 80/03/21 ip

- 80042101/8 Forwards response to IE Bulletin 80-03, "Loss of Charcual from Btd Type II.Two-Inch.Tray Adsorber Cells " Encl lists rosults of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- 8004280001 Supplements 800212 response to IE Bulletin 79-18 Forwards info re procedural controls necessary until completion of sys mods for upgrading public address & evacuation alarm sys as required by bulletin
 MILLS,L II Tennessee Vailey Authority 80/03/25 2pp
- 8004190527 Forwards IE info Notice 80~12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY. J P Region 2. Atlanta. Office of the Director 80/03/31 2nd
- 8004080636 Forwards IE Circular 80-05. "Emargency Diesel Generator Lubricating Oil Addition > Onsite Supply ' No written response required U'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/01 2pp
- 8004150097 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 20b
- 8004240274 Forwards IC Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp
- 8004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 200
- 8004110021 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards JE Bulletin 77-03A "Longitudinal Weld Defects in ABME BA-312,Type 304 Stainless Steel Pipe" Action required D'REILLY,J P Region 2, Atlanta, Office of the Director 80/04/04 in
- 8004180445 Forwards IE Bulletin 80-08, "Cram of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/07 3pp
- B0042B0170 Forwards monthly progress rept for Har 1980 in response to IE Bulletin 77-14. "Belsmic Analysis for As-Built Safety-Related Piping Sys" Includes insp of drawings.pipe supports & floor & wall penetrations
 MILLS.L M Tennessee Vailey Authority 80/04/07 20pp
- 8004290170 Forwards IE Insp Repts 50-259/80-12,50-260/80-10 & 50-296/80-11 on 800311-14 No noncompliance noted KENNA:W B Region 2: Atlanta: Safeguards Branch 80/04/09 2pp
- --8004270177 IE Insp Repts 50-259/80-12.50-260/80-10 & 50-296/80-11 on B00311-14 No noncompliance noted Major areas inspected review of security plan.organization.access controls & barriers Details withheld (ref 10CFR2 770) GILLESPIE,F Region 2, Atlanta, Safeguards Branch TILLMAN.A Region 2, Atlanta, Office of the Director 90/04/07 1p
- 8004270377 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLS.L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004240411 Forwards monthly operating repts for Mar 1980 ABERCROMBLE.H L Tennessee Valley Authority 80/04/10 1
- --8004240415 Monthly operating repts for Mar 1980 THOM: T Tennessee Valley Authority 80/04/02 32pp

S Reportable occurrences, LERs 3 related correspondence

- 8004:805:8 PNO-II-70-:47 on 7808:8 one of six air compressors suffered massive failure resulting in rapid loss of control air pressure to all three units Caused by large hole in cylinder head of failed compressor Compressor was isolated XLINGER.G Region 2. Atlanta. Office of the Director 78/08/18 to
- 8004010393 Forwards LER 80-007/03L-0 CALHOUN,J R Tennessee Valle; Authority 80/03/28 Ip
- --8004010402 LER 80-007/03L-0 on 800301, after offsite power was restored to 4-kV bus tie board, short period of time elapsed before reclosure of bus tie boarder feeder breaker Apparent disagreement in time is still being investigated

 * Tennessee Valley Authority 80/03/28 2pp
- 8004180492 Forwards LER 78-008/01/-1 CALHOUN, J R Tennessee Valley Authority 80/04/08 [p
- --8004180456 LER 78-008/01X-1 on 780415 during reactor scram relief valve 1-31 failed to reseat until reactor pressure reached 280 psig Moderator condown late exceeded 100 F allowed by Tech Specs Caused by excessive pilot leakage * Tennessee Valley Authority 80/04/08 ip

DOCKET 50-298 COOPER NUCLEAR STATION

- F. Security, medical, emergency & fire protection plans
- 8004250391 Forwards change to physical security plan, Revision 9 Encl withheld (ref 10CFR2 770) FILANT, J M Rebraska Public Power District 80/03/26 ip
- P Operating license stage documents & correspondence
- 8004070390 Discusses NRC 761123 request that all LWR licenses assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO.T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EISENHUT.D 0 Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs "
 # Division of Operating Reactors 80/02/21 28pp
- 8004300410 Forwards NRC 800128 & G211 ltrs to GE re mods to BHR control rod drive sys NUREC-0419 will provide requirements for facilities where mods to operating reactors have already been performed under code requirements IPPOLITO.7 A Operating Reactors Branch 3 80/04/07 2pp
- 8004230457 Discusses 600317 ltr re request for change in Tech Spec 3 7 E i value for drywe)l suppression chamber differential pressure from 1 47 psid to 1 l psid Requests another change to Tech Spec to value of 1 0 psi
- a Inspection reports. IE Bulletins & correspondence
- 8004230192 Responds to 1F Bulletin BO-01 re operability of automatic depressurization sys valve pneumatic supply Automatic depressurization accumulator sys uses soft-seat design lift check valves mfg by Dragon Valves. Inc
- 8004100093 forwards 1E info Notice 80-02. "BXOR Water Rod Lower End Plug Wear " No specific action or response required SEYFRIT.K V Region 4. Dalias, Office of the Director 80/01/25 ip
- 8004140479 Responds to IE Bullotin 79-02 "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Boits " Torque vertfication of all expansion anchors on supports for 2 5-inch diameter t larger piping completed actisfactorily PILANT, J M. Nebraska Public Power District 80/02/05 4pp
- 8004030246 Forwards IE lnsp Rept 50-298/79-19 on 791203-14 No noncompitance noted MADSEN.6 L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/02/28 2pp

- --800403024/ IE Insp Rept 50-298/79-19 on 791203-14 No noncompitance noted Major areas inspected fow level waste shipments & packaging ZURAKONSKI,P R Region 4. Dallas. Dérice of the Director BOOK.H E Region 4. Dallas. Fuel Facility & Materials Safety Branch 80/01/31 9pp
- 8004250077 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Review identified two instrument panels lacking direct loss of power alarms Direct alarms added PILANT. J M Nebrasia Public Power District 80/02/28 2pp
- 8004210211 Forwards IE Insp Rept 50-298/80-01 on 800129-0201.05-07 & 13-14 ½ notice of violation MADBEN.0 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/03/10 2pp
- --8004210215 Notice of violation from insp on 800129-0201,05-07 & 13-14 * Region 4, Dallas, Office of the Director 80/02/06 ip
- --8004210219 IE Insp Rept 50-298/80-01 on 800129-0201.05-07 % i3-14
 Noncompliance noted failure to adhere to surveillance
 procedure % to wear required protective clothing
 HESTERMAN.T F. YANDELL.L A. SPANQLER.R G. Region 4. Dallas,
 Office of the Director 80/02/06 13pp
- B004280184 Forwards response to IE Bulletin 80-20, "Inadequate QA for Nuclear Supplied Equipment" Rept was omitted from 800318 response
 PILANT, J. N. Nøbraska Public Power District 80/03/17 ip
- --8004280186 "Supply of Improved Interference Fit Feedwater Spargers "
 * Nebiaska Public Power District 79/02/28 30pp
- 8004030349 Forwards IE Insp Rept 50-278/80-02 on 800303-05 No noncompliance noted HIND, J A Region 3, Chicago, Bafeguards Branch 80/03/24 2pp
- ---8004030350 IE Insp Rept 50-298/80-02 on 800303-05 No noncompliance noted Major areas inspected facility organization & operation measurements & control & inventory verification Details withheld (ref 10CFR2 790)
 HIND.J A Region 3. Chicago. Safeguards Branch FINLEY.A G Region 3. Chicago. Office of the Director 80/03/19 ip
- 5004150233 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary SEYRIT, K V Region 4, Dallas, Office of the Director 00/03/31 in
- 6004080668 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/01
- 8004110101 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers" No specific action or response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180494 Forwards IE Info Notice BO-14, "Safety Suggestions From Employees " No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/02 to
- 8004180165 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required SCYFRIT.K V Region 4. Dallas, Office of the Director 80/04/03
- 8004110006 Forwards IE Bulletin 80-07, 'BWR Jet Pump Assembly Failure " Written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/04
- 6004230327 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312.Type 304 Stainless Steel Pipe " Action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/04 in
- 8004290005 Forwards IE Insp Rept 50-278/80-03 on 800317-20 No noncompliance noted MADSEN.G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/04/07 2pp

- --8004270011 IE Insp Rept 50-278/80-03 on 800317-20 No noncompliance noted Major areas inspected security planiphysical barriers, protected & vital areas, access control & alarm station Details withheld (ref 10CFR2 790)
 CALDMELL.R A , EVANS,C A Region 4, Dallas, Office of the Director MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/04/07 2pp
- R Periodic operating reports & related correspondence
- 8004010454 Forwards "Semiannual Operating Rept,Radioactive Effluents, Jul-Dec 1979" PILANT,J M Nebraska Public Power District 80/03/21 2pp
- --B004010457 "Somiannual Operating Rept.Radioactive Effluents, Jul-Dec
 - * Nebraska Public Power District 80/03/21 25pp
- 8004040396 Forwards "Annual Environ Operating Rept.1979," Vol 2 radiological PILANT.J M Nebraska Public Power District 80/03/28 1p
- --8004040406 "Annual Environ Operating Rept 1979," Vol 2 radiological & Teledyne Isotopes 80/03/28 86pp
- 8004090303 Forwards monthly operating rept for Mar 1980 LEBSOR, L. C. Nebraska Public Power District 80/04/03 1p
- --B004090304 Monthly operating rept for Mar 1980
 BALLINGER, P & Nobraska Public Power District 80/04/09 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004040025 PND-IV-80-013 Wastinghouse inspectors found two cracks in rotor disc of low pressure turbine 1 Largest crack is approx 2 9 inches deep & extending over length of keyway Licensee plans to remove cracked disc at next outage CONSTABLE, 0 L. WESTERMAN, T F Region 4, Dallas, Office of the Director 80/03/17 2pp
- 8004280574 Forwards LER 80-007/03L-0 LEGSGR:L C Nebraska Public Power District 80/03/25 2pp
- --B0042B0579 LER B0-007/O3L-0 on B00310 during surveillance testing of standby liquid control pumps standby liquid control pump 18 would pump only 36 5 gpm at 1,215 psig Caused by wear & pitting to seating surface BALLINGER.P L. Nebraska Public Power District 80/03/25 lp
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2
- F Security, medical, emergency & fire protection plans
- 80040B0Z24 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence KEPPLER.J O Region 9. Chicago. Office of the Director 80/03/19
- 8004010336 Forwards fire protection review Items 3 i 17.3 i 25.3 2 2 & 3 2 4 Licensee proposed mods to hydrogen sys & reactor coolant pump oil collection sys are only partly acceptable NRC should request drawings re mods proposed in Item 3 2 2 HAEL, R E Brookhaven National Laboratory 80/03/26 Spp
- 8004020410 Forwards estimates of evacuation times for area surrounding plant, per NRC 791129 ltr request FAY.C W Wisconsin Electric Power Co. 80/03/26 9pp
- BOOA270428 Responds to Educate the status of NRC review of plant fire protection program List re status of resolution of incomplete items encl BURBTEIN.S Wisconsin Electric Power Co BO/04/21 2pp
- G Adjudicatory correspondence
- 8004010389 Protests licensees failure to serve filings re steam generator tubs degradation Reiterates request for relief as stated in 800226 ltr & requests NRC to direct licensee to serve documents
 FALK, K M Wisconsin's Environmental Decade 80/03/27 2pp

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 80041B0122 Ack receipt of 800312 petition requesting that NRC issue order to show cause 0 order enjoining util from returning facility to operation due to steam generator tube degradation Petition will be acted upon within 45 days DENTON. HR Office of Nuclear Reactor Regulation 80/04/02 ip
- ---8004180126 Notice of WI Environ Decade 800312 request that NRC issue order to show cause & order enjoining operation of facility because of steam generator tube degradation Petition will be acted upon within 45 days
 DENTOIN HR 0 Ffice of Nuclear Reactor Regulation 80/04/02 10
- --8004180130 Requests that NRC issue order to show cause & order enjoining operation of facility because of steam generator tube degradation FALK.K M Wisconsin's Environmental Decade 80/03/12 1p
- I Financial information
- 8004290418 Forwards Annual Financial Rept 1979 & certified financial statements GRTSEH.J H Wisconsin Electric Power Co 80/04/22 19pp
- --8004290425 Annual Financial Rept 1979 MCNEER.C Wisconsin Electric Power Co 80/03/14 33pp
- P Operating license stage documents & correspondence
- B004040123 Notifies that description of QA program is App H to final description & SAR FAY, C W Wisconsin Electric Power Co 80/02/25 2pp
- BO04140087 Finds actions taken to repair, inspect & test cracking found in feedwater sys piping adequate until recommendations of owners group & NRC Pipe Crack Study Group have been evaluated Safety analysis encl BCHWENCER. A Operating Reactors Branch 1 80/02/25 4pp
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D G Division of Operating Reactors BO/03/12 5pp
- --8004030i18 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004300276 Forwards Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability SCHMENGER, A. Operating Reactors Branch 1 80/03/19 2pp
- ---8004300280 Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively, modifying Tech Spec qualification requirements for radiation protection manager SCHWERCER, A Operating Reactors Branch 1 80/03/17 7pp
- ---8004300285 Bafety evaluation supporting Amends 42 & 47 to Licenses DPR-24 & DPR-27. respectively * Office of Nuclear Reactor Regulation 80/03/19 2pp
- --8004300287 Notice of issuance & availability of Amends 42 & 47 to Licenses DPR-24 & DPR-27, respectively SCHWENCER.A Operating Reactors Branch 1 80/03/19 2pp
- 8004100172 Requests controlled set of P&IDs Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/20 in
- 8004020326 Discusses Event 5 valve configurations at facilities in response to NRC 800223 request Valves will be verified properly clased by combination of periodic testing & observation Stetch showing valve configurations encl FAY, C W Wisconsin Electric Power Co 80/03/21 3pp
- 8004010319 Responds to 800107 itr re QA requirements for diesel generator fuel oil Adequate controls to assure quality of fuel oil are being implemented FAY.C W Wisconsin Electric Power Co 80/03/24 2pp

- 8004240096 Provides info to clarify further NRC position re containment isolation (Section 2 : 4 of NUREG-0578) All plants required to have double isolation barriers w/o need for operator action Plant does not meet position on two penetrations SCHWENCER.A Operating Reactors Branch 1 80/04/03 3pp
- 8004280293 Forwards Amends 43 8 48 to Licenses DPR-24 & DPR-27-respectively, safety evaluation & notice of issuance & availability SCHMENCER: A Operating Reactors Branch & 80/04/03 2pp
- --8004280299 Amends 43 & 48 to Licenses DPR-24 & DPR-27,respectively, making minor changes to Yach Specs & approving revised organizational structure Operating Reactors Branch ! 80/04/03 31op SCHUENCER. A
- --8004280301 Safety evaluation supporting Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation 80/04/03 2pp
- --8004280304 Notice of issuance & availability of Amends 43 & 48 to Licenses DPR-24 & DPR-27, respectively SCHMENCER, A Operating Reactors Branch 1 80/04/03 2pp
- 8004300499 Confirms schedule arranged by NC Choules re 800408 meeting at site to discuss regulatory performance of facility KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/09
- 8004220278 Forwards "Analysis of Capsule R From Util Facility Reactor Vessel Radiation Surveillance Program " FAY.C W Hisconsin Electric Power Co 80/04/16 4pp
- --8004220284 "Analysis of Capsule R From Util Facility Reactor Vessel Radiation Surveillance Program " MAGAR.T R Westinghouse Electric Corp WCAP-9435 79/12/31
- 8004220475 Notifies of changes to undervoltage relaying for protection against degraded grid voltage on 4160 volt safeguard busses Action pessonds to NRC request to upgrade circuitry upon review of facility 770824 % 1012 & 800117 ltrs
 FAY.C W Hisconsin Electric Power Co 80/04/17 2pp
- O Inspection reports, IE Bulletins & correspondence
- 8004110230 Forwards IE Insp Repts 50-266/80-02 & 50-301/80-01 on 800122-24 No noncompliance noted HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80703/05 2pp
- --8004110245 IE Insp Repts 50-266/80-02 \$ 50-301/80-01 on 800122-24 No noncompliance noted Major areas inspected plant operations organization & administration OA review audits & records MARNICK, R F NRC Regional Offices HAGUE, R L, SMITH, J D Region 3. Chicago, Office of the Director 80/03/04 3pp
- 8004070206 Submits status rept of stress analysis & pipe support review as of 800229: in response to IE Bulletin 79-14 Analysis has been completed for 52 drawings & pipe supports evaluated for 24 pipe lines FAY.C W Wisconsin Electric Pawer Co 80/03/07 App
- 8004100149 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required
 KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/03/07
- 8004030353 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment Master list encl compiling all sys required to function under postulated LOCA or high energy line broak accident FAY, CW Wisconsin Electric Power Co 80/03/12 12pp
- 8004240449 Ack receipt of NRC 800310 ltr transmitting IE Info Notice 80-10 re Crystal River Unit 3 incident Notice will be reviewed by util nuclear projects ofc personnel & by plant supervisory personnel Results will determine further action FAY.C W Wisconsin Electric Power Co 80/03/24 ip.
- 8004240419 Responds to 1E Bulletin BO-03, "Loss of Chercoal from Std Type II, Two-Inch, Tray Adsorber Cells " Lists number, sys & manufacturer Containment purge sys cell had loose strip securing screen to frame Next insp scheduled for Apr FAY.C M Wisconsin Electric Power Co BO/03/26 2pp

- 8004150194 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary Region 3, Chicago, Office of the Director 80/03/31 KERRI FR. J. G.
- 8004080727 forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/0 Region 3, Chicago, Office of the Director 80/04/01
- 8004150059 Forwards IE Info Notice 80~13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response REPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180065 Forwards attachments to IE Circular B0-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 800422015B Forwards IE lnfo Notice 80~14, "Safety Suggestions From Employees " No action required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/02
- 8004220392 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Gil No written response required ER, J G Region 3, Chicago, Office of the Director 80/04/03 KEPPLER, J C
- 8004230288 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainloss Steel Pipe " Action required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/07
- 8004220053 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/09
- S Reportable occurrences, LERs & related correspondence
- 8004270464 Forwards updated LER 80-002/017-1 FAY.C W Wisconsin Electric Power Co 80/04/16 ip
- -8004270449 Updated LER 80-002/01T-1 on 800227.during normal operation, indication of increasing primary-to-secondary leak in A steam generator noted Caused by leaking tube in A steam generator position R18037 FAY.C W Wisconsin Electric Power Co 80/04/16 4PP
- 8004270470 Forwards LER 80-003/017-0 FAY.C W Wisconsin Electric Power Co 80/04/17 ip
- --8004290479 LER 80-803/017-0 on 800408, while testing pressurizer logic channels, pressurizer level channel 427 was momentarily failed low by instrumentation & control technicians Caused by personnel error Event discussed w/personnel FAY.C W Wisconsin Electric Power Co 80/04/17 2pp
- U Congressional/Executive Correspondence
- BO04140374 Responds to M Charlier B00107 ltr requesting facility shutdown until completion of needed repairs Insps. tests & operating limits increased to absure public health & safety following problems w/steam generator tube degradation DIRCKS,N J Office of the Executive Director for Operations B0/03/21 1p
- --8004140379 Forwards M Charlier 800107 ltr requesting that facility be shut down until needed repairs are completed PRDXMIRE, W Senate 80/01/17 2pp
- 8004140294 Forwards NRC 800104 ltr to J Estes, in response to 791213 request If requested, Lakeshore Citizens for Bafe Energy will be included in future meetings re steam generator condition DIRCKS, U J Office of the Executive Director for Operations 80/03/25 1p

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

H General correspondence

- B004250332 Advises that response to inquiry re plants under const will be provided in BERs which will include TMI-2 Lessons Learned Task Force findings Forwards Commission order defining TMI-2 review parameters & NRC itr to all BMN reactors W/s encls VAR9A.S A Assistant Director for Light Water Reactors 80/03/22 20s
- 8004180510 Forwards annotated sequence of 800226 events & simplified olectrical circuitry schematics per 800227 request DENTON, H.R. Office of Nuclear Reactor Regulation 80/04/01 21pp

I Financial information

- BOO4180462 Forwards Annual Financial Repts 1978 & 1979 & Repts of Examinations & Audits
 BRIGHT,R M Florida Power Corp 80/04/15 3pp
- ---8004160469 Annual Financial Rept 1978
 * Seminole Electric Cooperative, Inc. 80/04/15 46pp
- ---8004180474 Annual Financial Rept for yr ending Sept 1979 * Orlando.FL 79/12/07 15pp
- ---8004(60478 Annual Financial Rept 1979 * Orlando,FL 80/02/01 30pp
- --8004180484 Annual Financial Rept 1978 # Florida Power Corp 79/02/06 3ipp
- --8004180491 Annual Financial Rept for yr ending Sept 1978 * Lee*burg.FL 79/01/26 92pp
- --8004180500 Annual Financial Rept for yr ending Sept 1978 * Sebring, FL 78/12/06 147pp
- --8004180503 Annual Financial Rept for yr ending Sapt 1978 Sebring Util Commission financial statements and Tallahasse.FL 79/04/15 129pp
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8004100508 Forwards certified minutes of ACRS Ad Hoc Subcommittee meeting rs TMI-2 accident implications HAJOR,R K ACRS - Advisory Committee on Reactor Safeguards 80/03/04 1p
- --B004100321 Discusses development of general framework for conduct of limited risk assessment of B&W reactor aimed at identifying unique risk-impacting sequences re reactor safety study MURPHY, J A. TAYLOR, M A. Probabilistic Analysis Branch (Pre 791030) 79/10/04 12pp
- P Operating license stage documents & correspondence
- 8004040005 Forwards putline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 26pp
- 8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Decrations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004080002 Summary of 800304 meeting w/util, B&W licensees re facility 800226 nonnuclear instrumentation power supply failura resulting in 43.000 gallons of coolant escaping primary coolant sys into reactor bldg Supporting documentation encl REID.R W Operating Reactors Branch 4 80/03/13 57pp
- 8004030230 Notification of 800318 meseting w/all operating B&W reactor licensees in Bethesda.MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Dranch 4 80/03/14 2pp

- 8004100365 Forwards proposed changes to Tech Specs.App A BRIGHT.R II Florida Power Corp 90/03/24 19
- --8004100367 Proposed changes to Tech Specs.App A re reactivity control sys * Floride Power Corp 80/03/24 12pp
- 8004210328 Summary of 800222 meeting w/B&W owners group in Nethesda. Md re abnormal transient operational guidelines SEIGEL.B L Reactor Systems Branch 80/04/02 4pp
- 8004080374 Forwards "Electrical Distribution Sys Review Summary ' BRIGHT,R M Florida Power Corp 80/04/03 4pp
- --B0040B03B0 "Electrical Distribution Sys Review Summary "
 * Florida Power Corp 80/04/03 ip
- 8004080613 Advises that response to NRC 800229 request for add1 info re containment purge % vent sys will not be completed until 800515 Delay caused by need for plant-specific analysis BRIGHT, R M Florida Power Corp 80704703 2pp
- --B004250008 Amend 29 to License DPR-72, revising Tech Specs re containment structural integrity, to incorporate guidance on selecting number of tendons for insp % detensioning requirements Revisee pages encl REID, R W Operating Reactors Branch 4 80/04/03 7pp
- --8004250012 Safety evaluation supporting Amend 27 to License DPR-72 * Office of Nuclear Reactor Regulation 80/04/03 2pp
- --B004250015 Notice of issuance of Amend 29 to License DPR-72 REID.R W Operating Reactors Branch 4 80/04/03 2pp
- 8004250368 Summary of 800403 meeting w/utils.88W,NUS Corp & McGraw-Hsll in Bethosda.HD re draft NUREG-0667, "Transient Response of B&W-Designed Reactors" CAPRA,R A Blandardization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 meeting w/utils & B&W in Bethesda, MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA.R A Standardization Granch 80/04/05 2pp
- 8004190307 Supplements util H00111 ltr re implementation of TMI-2 Lessons Learned Task Force recommendations In addition to hot leg vents remotely operable reator vessel head vent will be installed at CR-3 MODRC.G C Fiorida Power Corp 80/04/11 2pp
- 8004280351 Forwards BAW-1607.Revision 1, "Cycle 3 Reload Rept," justifying operation of Cycle 3 at rated thermal power of 2544 MN Formal Tech Spec change request will be filed under separate cover BRIGHT.R M Florida Power Carp 80/04/14 3pp
- ---8004280354 "Cycle 3.Reload Rept." Revision 1 * Babcock & Wilcox Co BAW-1607 80/04/14 90pp
- BOO4180239 Responds to NRC BOO215 ltr re NUREG-0578 requirements Forwards reviews of over-low/overpressure protection for tanks & sys containing radioactive fluids & miscellaneous waste storage tank design BRIGHT.R M Florida Power Corp GO/04/15 26pp
- B004240467 Forwards add1 info re implementation of NUREG-0578.TMI short-term Lessons Learned recommendations in response to NRC request
 BAYNARD, P Y Florida Power Corp B0/04/20 4pp
- 8004280567 Application for amend to App A of License DPR-72, consisting of Tech Spec Change Request 51, Revision 1 Certificate of Svc enci BYLONIA, M Florida Power Corp 80/04/23 4pp
- ---B004280568 Fech Spec Change Request 51. Revision 1 (App A) re organizational changes to GA program * Florida Power Corp 80/04/23 ip
- --8004280571 Tech Spec Figure & 2-2, "Facility Organization"

 * Florida Power Corp 80/04/23 1p

- Q Inspection reports, IE Bulletins & correspondence
- 8004090337 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Tun-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2 Atlanta, Orfice of the Director 80/02/06 2pp
- 8004090351 Forwards IE linsp Rept 50-302/60-02 on 800116-18 5 24-25 No noncompliance noted BR/ANT.J C. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/02/21 2pp
- --8004090355 IE insp Rept 50-302/80-02 on 800116-18 & 24-25 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys per IE Builetin 79-14
 HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENOS.L Region 2. Atlanta. Office of the Director 80/02/20 Spp
- 8003240555 Requests notarized statements re util insp of turbine discs for possible crack formation Statements will enable NRC to decide whether OL should be modified suspended or revoked IE Info Notice 79-37 wereats sheet binfo request encl EISENHUT, D G Division of Operating Reactors 80/02/25 5pp
- 8004090133 Forwards 1E Insp Rept 50-302/80-05 on 800205-08 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004070163 IE Insp Rept 50-302/80-05 on 800205-08 No noncompliance noted Major areas inspected plant operations & review of previously identified items

 MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch DYER,J A Region 2, Atlanta, Office of the Director 80/02/25 4pp
- 8004210105 Forwards IE lnsp Rept 50-302/80-06 on 800211-15 No noncompliance noted LEMIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/03/04 2pp
- --8004210(13 lE Insp Rept 50-302/80-06 on 800211-15 No noncompliance noted Major areas inspected licensee action on previous inspector identified items, infractions & unresolved items & review of plant operations
 UPRIGHT,C M Region 2. Atlanta. Reactor Operations Nuclear Support Branch BELISLE.G A Region 2. Atlanta, Office of the Director 80/03/03 App
- 8004040010 Forwards response to 1E Bulletin 60-03. "Loss of Charcoal from Std Type II.2-Inch.Tray Adsorbers " No deficiencies or degradation found CR-3 filter cells siightly different Screens fastened to frame by spot welds w/1-inck spacing BRIOHT.R M Florida Power Corp 80/03/17 2pp
- 8004040437 Ack receipt of 800307 ltr informing NRC of steps taken to correct violations noted in [E Insp Rept 50-302/80-07 LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/18 1p
- --8004040445 Responds to NRC 800215 ltr re violations noted in IE losp Rept 50-302/80-07 Corrective actions stainless steel pipsing capped-plugged or sealed Storing racks have wooden stripping installed to prevent contact of stainless & carbon steel HANCOCK.J A Florida Power Corp 80/03/07 2pp
- --8004040447 Forwards IE insp Rept 50-302/80-07 on 800128-0201 & nutice of violation LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 2pp
- ~-800404049 Notice of violation from insp on 800128~0201 * Region 2, Atlanta, Office of the Director 80/02/14 tg
- ---8004040452 IE insp Rept 50-302/80-07 on 800128-0201 Noncompliance noted several lengths of pipe stored in warehouse were not capped or plugged & open ends unprotected MESSITT.8 R. UPRIONT.C II Region 2. Atlanta, Office of the Director 80/02/14 App
- 8004110562 Ferwards 1E Insp Rept 50-302/80-11 on 800225-28 No noncomplance noted KENNA-W B Region 2. Atlanta, Safeguards Branch 80/03/25 2pp

- --8004110566 IE Insp Regt 50-302/80-11 on 800225-28 No noncompliance noted Major areas inspected vital area access, communications, alarm stations, detection aids & security organization Details withheld (ref 100FR2 790) TOBIN, N J Region 2, Atlanta, Bafeguards Branch BESECKER, K H Region 2, Atlanta, Office of the Director 80/03/25 ip
- 8004210:i) Updates 800229 response to IE Bulletin 79-27 Util will complete review? evaluation of Non-Class IE instrumentation & control sys as required by builetin Rept will be submitted by 800426 RECHT.R H. Florida Power Core. 80/03/26 20p
- 8004150315 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening or PORV & Block Valve " No specific action or response necessary G'AEILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080575 Forwards IE Circular 80-05, "Emergency Diesol Generator Lubricating Oil Addition & Chrite Supply " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01 20p
- B004150080 Forwards IE Info Notice 80-13, "GE Type SBM Control Bwitches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 200
- 8004240259 Forwards IC info Notice 80-14. "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 2pp
- 8004180274 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 200
- 8004230169 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2: Atlanta, Office of the Director BO/04/04
- 8004180317 Forwards IE Bulletin 80-08, "Eiam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300143 Ack receipt of 791107 ltr informing NRC of steps taken to correct violations noted in 1E Insp. Rept 50-302/79-24 LEWIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/11 lp
- --8004300151 Responds to NRC 790924 ltr re violations noted in IE lnsp Ropt 50-302/79-24 Corrective actions insp scheduled for all accessible.posted.high radiation areas once per shift HANCOCK.J A Florida Power Corp 79/11/07 ip
- --8004300158 Ack receipt of 791018 ltr informing NRC of steps taken to correct violations in IE Insp Rept 50-302/79-24 Add1 inforequested re Item A LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/10/26 ip
- --8004300164 Responds to NRC 790924 ltr re violations noted in IE Insp. Rept 50-302/79-24 Corrective actions supervisors instructed not to sign clearances unless clearance log is properly filled out STEWART.W P Flerida Power Corp 79/10/18 2pp
- ~-8004300171 Forwards 1E Insp Rept 50~302/79~24 on 790702-0803 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/09/24 2pp
- --8004300177 Notice of violation from insp on 790702-0803 * Region 2, Atlanta, Office of the Director 79/09/19 ip
- --8004300187 JE Insp Rept 50-302/79-24 on 790702-0803 Noncompliance noted farlure to control high radiation area & failure to properly control equipment clearance MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch GUICK, D. BRADFORD, W Region 2. Atlanta, Office of the Director 79/09/19 13pp

- 8004220526 Responds to IE Bulletin 79-018 Actions required by Items 4 % 5 can be completed by 800630 Responsos required by Items 1,2 % 3 will be submitted by 800421 BRIGHT,R M Florida Power Corp 80/04/17 2pp
- 800430033i Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation" Equipment necessary for cold shutdown available BRIOHT,R M Florida Power Corp 80/04/29 7pp
- R Periodic operating reports & related correspondence
- 8004010469 Forwards "Pust-Operational Ecological Monitoring Program, Annual Rept 1979," Vol 1, Parts 1 & 2 & Vol II MODRE, G C Florida Power Corp 80/03/25 Ip
- --8004010473 "Post-Operational Ecological Monitoring Program, Annual Rept 1979, " Vol I.Part 1 * Florida Power.Corp 80/03/31 300pp
- ~~8004010479 "Post~Derational Ecological Monitoring Program, Annual Rept Vol L.Part 2
 - Fiorida Power Corp 80/03/31 300pp
- --8004010483 "Post-Operational Ecological Monitoring Program, Annual Rept 1979," Vol II * Florida Power Corp 80/03/31 300pp
- 8004010488 Forwards "Annual Environ Operating Rept 1979," Vols 1 5 2 HANCOCK, J A Florida Power Corp 80/03/31 3pp
- --B004010494 "Annual Environ Operating Rept 1979," Vol 1, nonradiological * Florida Power Corp 80/03/31 450pp
- --8004010497 "Annual Environ Operating Rept 1979." Vol 2.radiological * Florida Power & Light Co 60/03/31 95pp
- BOO4210238 Forwards monthly operating rept for Mar 1980 BRIGHT,R M Florida Power Corp 80/04/11 ip
- --8004210240 Monthly operating rept for Mar 1980 CULVER,M W Florida Power Corp 80/04/01
- S Reportable occurrences, LERs & related correspondence
- 8004020318 Forwards LER 80-013/04L-0 HANCOCK, J A Florida Power Corp 80/03/11 4pp
- --8004020323 LER 80-013/04L-0 on 800304,more than two std deviations were discovered between propperational study & operational study in metabolic function of discharge salt marshes Possibly caused by natural or seasonal variations LANCASTER.K F Florida Power Corp BO/03/11 1p
- 8004090313 Forwards LER 80-015/03L-0 HANCOCK, J A Florida Power Corp 80/04/03 lp
- --8004070315 LER 80-015/03L-0 on 800305, while performing engineered safeguards functional test, decay heat suction isolation valve began to close inadvertently No apparent cause for event investigation underway LANCASTER, K. F. Florida Power Corp. 80/03/31 2pp
- 8004290480 Forwards LER 80-016/017-0 HANCOCK,J A Florida Power Corp 80/04/16 ip
- --8004290488 LER 80-016/01T-0 on 800401, inadvertent actuation of fire svc deluge sys resulted in damage to auxiliary bidg ventilation exhaust filter AHFL-2A Caused by personnel error during reset of fire svc panel alarm AHFL-2A media replaced LANCASTER,K F Florida Power Corp 80/04/08 2pp
- DOCKET 50-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4 H General correspondence
- 8004250332 Advises that response to inquiry re plants under const will be provided in 8ERs which will include TMI-2 Lessons Learned Task Force findings Forwards Commission order defining TMI-2 review parameters & NRC itr to all 8&W reactors W/o encls VARGA.8 A Assistant Director for Light Water Reactors 80/03/22

- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8004110089 Forwards request for addi into re 790323 contingency plan & 791026 Revision 1 Request withheld (ref 100FR2 790) SCHWENCER A Operating Reactors Branch 1 80/02/27 1p
- 8004240531 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimile traffic KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/20 Administration KEPPLER, J G
- 8004010357 Forwards fire protection review Itoms 3 1 3,3 1 4 % 3 1 5 Review is duplicate of 800307 leview w/minor paragraph change in Item 3 1 3 & claiification of Item 3 1 5 HALL, R E Brookhaven National Laboratory 80/03/21 4pp
- 8004230125 Forwards evaluation of facility fire protection program & status of incomplete items identified in 780310 & 790413 safety evaluations Position on safe shutdown capability also encl also encl SCHWENCER.A Operating Reactors Branch 1 80/03/24 22pp
- 8004290039 Discusses arrangements for 800411 meeting w/util in Clen Ellyn. IL re noncompliance & program weaknesses identified in recent health physics program appraisal insp KEEPLER. J G Region 3. Chicago. Office of the Director 80/04/07
- 8004300588 Notification of 900417 meeting w/util in Bethesda.MD to discuss meteorological acceptance criteria for emergency preparedness at site REEVES.E Operating Reactors Branch 1 80/04/08 2pp
- 8004220356 Submits info in response to NRC question re characteristics of fire suppression sys for grouped cable trays in stairwell between Unit 1 & 2 cable spreading rooms NAVOHTON.W C Commonwealth Edison Co 80/04/14
- 8004230318 Forwards addl info re Item 3 i 3.gas suppression sys.for fire protection review Sys acceptable HALL.R E Brookhayen National Laboratory 80/04/14 2pp
- 8004230367 Forwards revised security plan Revisions withheld (ref 10CFR2 790) PEOPLES.D L Cor Commonwealth Edison Co 80/04/21 1P
- O Adjudicatory correspondence
- 80040701319 Forwards 800229 confirmatory order amending facility OLs by incorporating commitments to implement add1 procedural measures & design changes made in util 800222 ltr Actions nacessary for continued assurance of public health & safety DENTON, H.R. Office of Nuclear Reactor Regulation 80/02/2 80/02/29 2on
- --8004070142 Confirmatory order amending facility OLs by incoporating commitments to implement add1 procedural measures & design changes agreed to in util 800222 ltr & discussed in encl DEMTON.H R Office of Nuclear Reactor Regulation 80/02/29
- 8004080078 Forwards FR notice & director's decision under 100FR2 206 denying request for preparation of E18 re Amends 44 & 41 to facility OLs
 DENTON:H R Office of Nuclear Reactor Regulation 80/03/13 ip
- ---8004080083 Director's decision under 10CFR2 206 denying C Guigg 790427 request that Director of Nuclear Reactor Regulations order full EIB for Amends 44 % 41 to OLs Amends will not significantly affect quality of human environ DENTON, HR Office of Nuclear Reactor Regulation 80/03/13 6pp
- --B0040000B8 Notice of issuance of Director's decision under 10CFR2 206 denying C Quigg 790427 request that Director of Nuclear Reactor Regulation order full EIS for Amends 44 & 41 to OLs No basis for issuing EIS exists

 DENTON, H R Office of Nuclear Reactor Regulation 80/03/13 ip
- 8004080548 Order granting extension, until 800409, for Commission to elect whether to review 800319 denial of enforcement action CHILK,S J Office of the Secretary of the Commission 80/03/31

- E004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004280590 Requests immediate suspension of license issued by NRC to Comm Ed to remach b compact spent fuel pool to 2.112 spent fuel assemblies QUIGG.C Pollution Environmental Problems 80/04/17 2pp

- 8004210336 Advises that 791106 ltr to President Carter re emorgency plans has been referred to NRC Since Summer 1979.NRC has been actively pursuing program to upglade emorgency preparedness Forwards IRC-FEMA documentation M/o enci DENTON. H R Office of Nuclear Reactor Regulation 80/03/31 Spp
- 8004150085 Responds to 800228 Iti re operation of nuclear power plants in high density areas NRC is investigating special measures to be taken in heavily populated areas Interim measures have already been ordered at sites

 DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004150094 Advises that facilities should be shut down due to proximity to highly populated areas & likelihood of serious accident STERNER, J W Affiliation Unknown 80/02/28 ip
- 8004160173 Responds to 800212 itr re continued operation of nuclear power glant Addl measures should be implemented that will further reduce probability or severe reactor accidents. Cicensee has been in shutdown pending completion of actions DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2p;
- ---B004160176 Requests that NRC not phase out facility or convert to nonnuclear generators Nuclear power is source for power in US No nuke political arguments have no basis in reality LAVERTY,F Affiliation Unknown B0/02/12 2pp
- 8004170342 Responds to G00206 mailgram requesting shutdown of facility Special measures are being considered for plants located in high density areas Interim measures have been ordered at facility.confirming commitment to public health & safety DEMTON.# R Office of Nuclear Reactor Regulation 80/04/01 2pp
- 600421008B Responds to 800125 request re-public hearing & determination on UCS petition NRC considering what special measures should be taken to reduce probability of severe reactor accident or lessen consequences

 DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210093 Requests scheduling of public hearing & determination of UCS petition re operation of facility prior to rectivation Concerned for health & safety of community SCIANDRA. J. New York, NY 80/01/25 19
- 8004210193 Responds to 800207 ltr re continued operations at facility NRC is investigating special measures to be taken in high density population areas surrounding nuclear power plants interim measures have already been ordered at sites DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210201 Supports continued operation of facility Reactors supply 20% of generating capacity for New York City & Westchester County Utils can shut off oil plant.lowering rates & depandency on foreign oil NV.J Affiliation Unknown 80/02/0/ 1p
- 8004210208 Responds to 800204 itr re-continued operation of facility Plants reviewed to determine what add measures or design changes can & should be implemented to further reduce probability of reactor accident or consequences

 DENTON: HR Office of Nuclear Reactor Regulation 80/04/01 2pp
- --8004210223 Urges NRC to decide in favor of continued operation of facility Reactors have long history of safe, clean & economic operation Concerned that fuel adjustment charges will increase if plants are shut down

 GAY R R Affiliation Unknown 80/02/04 19
- 8004250013 Responds to 800212 postcard re operation of facility NRC considering what special measures should be taken to reduce probability of severe reactor accident Confirmatory orders issued as interim measure

 DENTON

- --8004250030 Urges that NRC consider UCS petition re closing of facility Possibility of earthquake exists w/plant built near fault Only 207 of area energy generated by nuclear power Alternatives should be considered GDLDHOR.F Affiliation Unknown 80/02/12 1p
- 800425001B Responds to 800215 ltm re operation of facility NRC considering what special measures should be taken to roduce probability of severe leactor accident or to lessen consequences Confirmationy orders issued as interim measure DENTON.H R Office of Nuclear Reactor Regulation 80/04/01 2
- P Operating license stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS, DF Division of Project Hanagement 80/02/05 7pp
- 80040B0377 Summary of Westinghouse Lessons Learned team B00121-22 site visit to determine implementation status of Category A Lessons Learned requirements Status of each item & attendance list enc!
 TELFORD.J T NRC Three Mile Island Task Force B0/02/15 App
- 8004110569 Forwards Lessons Learned Task Force status re implementation of Category A requirements following 800121-22 visit by Westinghouse Util has signed confirmatory ltr specifying that NRC will be notified of noncompliance TELFORD.FT TMI-2 Lessons Learned Task Force 50/02/15 App
- 8004020463 Forwards NRC safety analysis of cracking discovered in feedwater sys Util repair program, nondestructive imaps & leakage testing are adequate to insure that integrity of feedwater piping will be maintained SCHNENCER. A Operating Reactors Branch i 80/02/25 App
- 8004180387 Forwards modified near-site study in response to NRC 791205 request for 60-day crash effort PEOPLES.D L. Commonwealth Edison Co. 80/02/25 1p
- --8004180375 "Near-Site Study " Viewgraphs enci * Commonwealth Edison Co 80/02/25 75pp
- 8004020237 Forwards Amends 52 & 49 to Licenses DPR-37 & DPR-48, respectively Amends consist of changes to license & appended Tack Specs permitting mod of spent fuel pool increasing storage capacity from 868 to 2.112 fuel assemblies SCHWENCER, A Operating Reactors Branch 1 80/02/28 2pp
- --8004020266 Amend 49 to License DPR-48, changing license & appended Tech Specs to permit mod of spent fuel pool to increase storage capacity from 868 to 2, 112 fuel assemblies Replacement pages of App A Tech Specs encl SCHWENCER, A Operating Reactors Branch 1 80/02/28 6pp
- --8004020270 Notice of issuance of Amends 52 & 49 to Licenses DPR-39 & DPR-48 respectively & negative declaration SCHWENCER. A Operating Reactors Branch 1 80/02/28 3pp
- 8004220192 Requests add1 info re dimension of upper vessel head surrounding control rod penetrations Info needed to complete work being conducted by Los Alamos Labs re vessel strengthening Drawing encl SCHWENCER.A Operating Reactors Branch 1 80/02/28 2pp
- 8004010004 Forwards "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting From TMT-2 Lessons Learned " All Category A requirements satisfied SCHWENCER, A Operating Reactors Branch 1 80/02/29 2pp
- --8004010006 "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned " * Division of Operating Reactors 80/02/28 lipp
- 8004280217 Forwards BEP schedule & content requirements for environ qualification of electrical equipment Previously submitted info should be incorporated by specific ref Facilities exempt from IE Bulletin 79-018

 SCHWENCER.A Operating Reactors Branch 1 80/03/05 Spp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUI, D 9 Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"
 * Division of Operating Reactors 80/02/21 28pp

- 8004090003 Forwards Amends 53 ½ 50 to Liconses DPR-39 ½ DPR-48, respectively, safety evaluations ½ notice of issuance & availability SCHWENCER, A Operating Reactors Branch 1 80/03/13 2pp
- ---8004080005 Amends 53 % 50 to Licenses DPR-39 & DPR-48, respectively, changing, Tech Specs, App A. to increase allowable LOCA peaking factor from 1 86 to 1 93, based on ECCS reanalysis GAMHILL, W.P. Division of Operating Reactors 80/03/13 7pp
- ---8004080008 Safety evaluation supporting Amends 53 % 50 to Licenses DPR-39 % DPR-48.respectively * Office of Nuclear Reactor Regulation 80/03/13 4pp
- --8004080011 "Bafety Evaluation of Request for Removal of Conservatism In Westinghouse PAD Computer Code," prepared in response to util request for OL amend * Core Performance Branch 80/03/31 32pp
- --8004080013 Notice of issuance & availability of Amends 53 & 50 to Licenses DPR-39 & DPR-48, respectively SCHWENCER, A Decrating Reactors Branch 1 80/03/13 2pp
- 8004140221 Summary of 800221 meeting w/representatives of all BEP plants.utils & Franklin Research Ctr re accelerated program for evaluating qualification of safety-related electrical equipment WIEGUN.R Plant Systems Branch 80/03/14 3pp
- 8004100102 Requests controlled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days KEPPLER, J Q Region 3. Chicago, Office of the Director 80/03/20
- 8004210194 Forwards request for info re containment environ conditions & sys required for accident mitigation for review of environ qualification of Class IE electrical equipment NRC will estimate time for containment temp to return to near normal SCHWENCER.A Operating Reactors Branch 1 60/03/20 15pp
- 8004020189 Forwards response to NRC 800229 confirmatory order to perform actions within 30 days Mestinghouse representative stationed onsite ventilation intakes re-examined, emergency action levels revised & reactor operators training underway NAUGHTON, W.F. Commonwealth Edison Co. 80/03/28 9pp
- 80040B0214 Forwards response to immediate action items of NRC 800229 confirmatory order No immediate action required In-plant walk-throughs will be completed prior to next reactor startup Simulator training is in progress
 NAUGHTON.W F Commonwealth Edison Co 80/03/28 4pp
- 8004250364 "Bafety Evaluation of Inservice Testing Program for Pumps & Valves." 780117-790916 FEHRINGER.J M., ROCKHOLD.H C EG & O, Inc FIN A-6298 8004250364 80/03/31 46pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A: AA program Revisions reflect recent organization title changes NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02 1p
- --B004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CC-1-A RIS 80/04/04 7pp
- 8004100338 Responds to NRC 800228 ltr re Drawing 686J374 Apparent increased thickness of upper vessel head surrounding control rod penetrations does not exist Actual thickness uniform & 6-5/8 inches + 1/8 inches-0 inches w/o clad NAUGHTON W F Commonwealth Edison Co 80/04/03 ip
- 8004240480 Forwards add1 info re review of unresolved safety issues, trip rept of Lessons Learned implementation team, & task action plan in view of high population density surrounding plants

 DENTON.H R Office of Nuclear Reactor Regulation 80/04/09 33pp
- --8004240483 Summary of Westinghouse Lessons Learned team 800121-22 site visit to determine status of Category A implementation Attendance & status lists encl TELFORD.J T. Safeguards Standards Branch 80/02/15 5pp
- ---8004240492 Forwards evaluation of util actions taken to satisfy
 Lessons Learned Category A requirements Concludes all
 requirements satisfied Attendance list for 800121-22 site
 visit encl
 BHCWENCER.A Operating Reactors Branch 1 (Pre 791030) 80/02/29

- --8004240507 Forwards action plan developed in recognition of high population densities surrounding sites DENTON, H R Office of Nuclear Reactor Regulation 80/02/2!
- --8004240518 Discusses E.ent 5 probabilities Suggests continuous monitoring & readout capability of check valve position & periodic tests of leak rate measurements TAYLOR.M A Division of Reactor Safety Research 80/01/15 17pp
- 8004250232 Forwards status of unresolved safety issues at Indian Point 1 \$ 2.trip repts from Indian Point & Zion site visits, safety evaluation for Lessons Learned requirements at factlities, task action plan & factlity societal risk info DENTON, H R Office of Nuclear Reactor Regulation 80/04/09 34pp
- 8004240458 Formalizes plans re-series of technology exchange meetings re-facilities' accident mitigation features activity Five meetings suggested Recommended meeting schedule & agenda items encl
 SCHWENCER, A. Operating Reactors Branch 1 80/04/10 15pp
- BO04250427 Forwards response to NUREQ-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Leasalle County site-specific emergency plan PEOPLES.D L Commonwealth Edison Co 80/04/15 4Opp
- --8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280509 Forwards revised Page 37 to DL Peoples 800101 ltr concerning commitments re TMJ-2 Lessons Learned Task Force short-term requirements
 PEOPLES D L Commonwealth Edison Co 80/04/18 2pp
- 8004270502 Application for amend to Licenses DPR-39 & DPR-48.App A Tech Specs eliminating refs to part length rods & atmospheric relief values & revising reactor protection sys permissive testing Table 4 1-1 PEOPLES.D L Commonwealth Edison Co 80/04/22 4pp
- --8004290504 Revised pages to Tech Specs eliminating refs to part length rods & atmospheric relief valves & revising reactor protection sys permissive testing Table 4 1-1 * Commonwealth Edison Co 80/04/22 45pp
- G Inspection reports. IE Bulletins & correspondence
- 8004040316 Forwards IE Insp Repts 50-295/79-22 & 50-304/79-24 on 790910-800204 No noncompliance noted FIORELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004040337 IE Insp Repts 50-295/79-22 & 50-304/79-24 on 790710-800204 No honcompliance noted Major areas inspected review of inservice insp program & review of licensee activities re IE Bulletin 79-13 & 79-17 DANIELBON,D H , KEY,H J Region 3, Chicago, Office of the Director 80/02/14 19pp
- 8004100140 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 Nu noncompliance noted DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004100408 Waste Packaging 79-07A on 80791212-13 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations including shipping paper requirements, radiation levels & DOT labeling POTTER, J P Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 6pp
- 8004220157 Forwards IE Insp Repts 50-295/80-01 & 50-304/80-01 on 800103-0206 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/04 2pp
- --8004220165 Notice of violation from insp on 800103-0206
 * Region 3, Chicago, Office of the Director 80/03/03 ip
- --8004220175 IE Insp Repts 50-295/80-01 & 50-304/80-01 on 800103-0206
 Nancompliance noted failure to follow procedures during shift turnover
 LITTLE,W 8, KOHLER, J E Region 3, Chicago, Office of the Director 80/03/03 ilpp

- 8004100118 Forwards IE Info Notice 80~08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/07
- GOO41100B7 Notifies that facility will be performing inservice inspactivities during refueling outage Insps will include volumetric surface b visual insps of class (b 2 components Insps scheduled for GOO512 will extend through BOO613 WANDKE.N E Commonwealth Edison Co GO/O3/13 ip
- 8004140119 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 6td Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES: D. C. Commonwealth Edison Co. 80/03/20 Spp
- 8004040014 Forwards corrected Waste Packaging Insp Rept 79-07A Requests that rept sent on 800222 be destroyed DAVIS:A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/21 ip
- --8004040019 Forwards corrected Waste Packaging Insp Rept 79-07A.on 791212-13 No honcompliance noted DAVIS, A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/02/22 2pt
- --8004040023 Corrected Waste Packaging Insp Rept 79-07A on 791212-13 No honcompliance noted Major areas inspected shipping paper & placarding requirements, radiation levels, removable contamination & package external features POTTER, J P. Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/22 7pp
- B004(10555 Summary of B001(8 meeting w/otil & Westinghouse in Bethesda, MD re Unit | turbine disc inspiresults, repairs made & plans for inspecting Whit 2 low pressure turbine rotor discs tist of attendees & supporting mat| enc| REEVES, E A Operating Reactors Branch | B0/03/26 14pp
- 8004150159 Forwards If Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/31 to
- 8004080686 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required KEPPLER. J G Region G. Chicago, Office of the Director 80/04/01
- 8004150014 Forwards IE info Notice 80-13, "OE Type 88M Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hajards," inadvertently omitted from 800304 transmittal REPPLER. J G Region 3, Chicago. Office of the Director 80/04/02
- 8004220093 Forwards IC Info Notice 80-14, "Bafety Suggestions From Employees 'No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02

- --8004140322 "Radwaste & Environ Monitoring Annual Rept. 1979 " KOHL, K.A. Ebesline Instrument Corp. 80/03/18 60pp
- S Reportable occurrences, LERs t related correspondence
- BOO4210433 PNO~77-131A on 770/12, during routing testing w/facility in hot shutdown, safety sys circuits were temporarily disabled Caused by inadequate mgt attention & procedural controls Program of Corrective action instituted KLINGER.G . NOLAN,F . SNIEZER.J Region 3. Chicago. Office of the Director 77/07/28 ip
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior mat1 Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT.K & Region 2. Atlanta. Office of the Director 77/08/12 10
- 800402040/ Forwards LER 80-012/03L-0 WANDKE,N E Commonwealth Edison Co 80/03/25 1p
- ~-8004020412 LER 80-012/0JL-0 on 800224, while increasing power to 80%, control rod bank D rod position indicators were slightly greater than 12 steps above bank demand position Caused by instrument drift Recalibr performed
 T'NIEMI,W D Commonwealth Edison Co 80/03/25 lp
- 8004190472 Forwards LER 80-013/031-0 WANDME,N E Commonwealth Edison Co 80/03/28 1p
- --8004150477 LER 80-013/031-0 on 800227, during normal operation, maint personnel found steam generator pressure comparator 2PC-936A-U shifted high by 1 5% Caused by defective unit Defective unit replaced wispare unit JERKINS, R V Commonwealth Edison Co 80/03/28 1p
- 8004280641 PHO-SII-80-063 on 80033).unplanned gaseous radiation release occurred because of operator error in operating valves. Preliminary analysis indicates release rates did not exceed. Tech Spor Limits. BDYD.D C. KUHLER.J E. Region 3. Chicago. Office of the Director 80/04/01 | 2pp
- 9004150918 Forwards LER 80-014/03L-0 WANDKE,N E Commonwealth Edison Co 80/04/02 1p
- --8004150526 LER 80-014/03L-O on 800303 during normal operation maint personnel found steam generator pressure transmitter 2-PI-516 had shifted low by 2% Defective Fisher Porter Model 50EP1041 BCXA replaced & channel returned to syc JENKINS R V Communwealth Edison Co 80/04/02 ip
- BOO4280654 PND-III-BO-063A BOO402.1tr from Mayor of Waukegan,IL, demanded actions as result of 800331 unplanned gaseous release Region 3 is continuing investigation & evaluation STRASMAR J. HEIBHMAN,R F. Region 3. Chicago. Office of the Director 80/04/03 2pp
- 9004220674 Forwards updated LER 80-002/03x-1 WANDXE,N E Commonwealth Edison Co 80/04/14 ip
- --8004220/02 Updated LER 80-002/03X-1 on 800126, during steady state operation, pressure transmitters 2PT-926 for steam generator 28 \$ 2PT-946 for steam generator 2C failed high Caused by cold drafts freezing instrument root lines KURTH, U R Commonwealth Edison Co 80/04/14 2pp
- DOCKET 50-305 KENAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- B004140490 Forwards info on emergency broadcast sys including Dept of Commerce pamphlet entitled.NOAA's Ubiquitous Radio & "Defense Civil Preparedness Agency pamphlet entitled. Emergency Broadcast Bys " SCHWENCER.A Operating Reactors Branch i B0/02/28 24pp
- 8004080187 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence at facility (KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/19

- 8004140086 Confirms 800319 teleon re arrangements for 800423 & 24 meetings in Kewaunee, WI rg licensee emergency preparedness procedure & capability of public agencies Public is invited SCHWENCER, A Operating Reactors Branch 1 80/03/26 2pp
- 8004300502 Informs that certain areas of industrial security manual do not meet requirements of ICCFR73 55 Requests that proposed amends to industrial security manual be submitted for review within 30 days Encl guidance withheld (ref iOCFR2 790) SCHWENCER, A Operating Reactors Branch 1 80/04/03 2pp
- P Operating license stage documents & correspondence
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIBENHUT.D O Division of Operating Reactors BO/03/12 5pp
- --B004030ilB "Nuclear Data Link Specs "
 * Division of Operating Reactors 60/02/21 28pp
- BOO4100186 Requests controlled set of PAIDs Submittal should be forwarded to attention of incident response ctr within 20 days

 KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/20
- 8004010492 Forwards info re qualification of certain equipment, control room indications of bypassed or inoperable safety-related equipment, Page TSA-17 of Tech Specs & listing of current Tech Spec pages, in response to NRC request SCHRUCK, C A Wisconsin Public Service Corp 80/03/27 14pp
- --8004010495 Page TB6-17 of Tech Specs re safety-related equipment & listing of current Tech Spec pages * Wisconsin Public Service Corp 78/01/25 14pp
- 80040B0337 Forwards addl info requested at 800305 meeting w/NRC re implementation of short-term Lessons Learned Task Force requirements Info involves Tech Specs 2 1 3.2 1 & & 2 1 B MATHEWS, E R Wisconsin Public Service Corp 80/04/03 15pp
- 8004170018 Discusses proposed installation of restraints near reactor vessel nozzlos to limit break size of LOCA event & limit asymmetric loads to reactor vessel Restraints will improve safety margin white not prosenting hazard MATHEMS, ER Wisconsin Public Service Corp 80/04/10 3pp
- 8004180464 Forwards proprietary & nonproprietary versions of "Structural Analysis of RCS for Postulated LOCA." preliminary issue Applications for withholding encl Proprietary version withheld (ref 10CFRZ 790) ANDERSON,T M Westinghouse Electric Corp 80/04/11 11pp
- --8004180475 Nonproprietary version of "Structural Analysis of RCS for Postulated LOCA," proliminary issue * Westinghouse Electric Corp , Nuclear Energy Systems 80/02/29 100ce
- 8004180428 Forwards "Reload Safety Evaluation, Cycle VI.Mar 1980 " MATHEWS, E. R. Wisconsin Public Service Corp. 80/04/14 1p
- --8004180433 "Reload Safety Evaluation, Cycle VI, Mar 1980"
 HDLLY, J T Wisconsin Public Service Corp 80/03/27 45pp
- 8004180479 Forwards revised pages of reactor test program Revisions reflect results of conversations w/M Chatterton Program was successful during Cycle V startup MATHEWB,E R Wisconsin Public Service Corp 80/04/14 2pp
- ---8004180483 Revised pages of reactor test program

 * Wisconsin Public Service Corp 79/05/22 3pp
- 8004220756 Responds to NRC 800411 request for add1 info re RCS vent design & radiation qualification of ECCS Will install reactor vessel head vent sys of C-E design Mill define dose criteria for items w/o acceptable dose qualification MATHEMBLE R Wisconsin Public Service Corp 80/04/14 2pp
- 8004210327 Forwards proposed Amend 40a to Tech Specs, Sections 3 15, 4 15 & 6-2 Proposed Amend 40a supersedes proposed Amend 40 & adds appropriate requirements concerning fire protection sys MATHEMB.E R Wisconsin Public Service Corp 80/04/16 2pp

- --8004210331 Proposed Amend 40a to Tech Specs. Sections 3 15,4 15 & 6-2, superseding proposed Amend 40 Adds requirement for five-man fire response team, corrects wording inconsistencies & deletes fire protection mod requirements * Wisconsin Public Service Corp 80/04/14 9pp
- $\boldsymbol{\Theta}$. Inspection reports, IE Bulletins $\boldsymbol{\vartheta}$ correspondence
- 8004100122 Forwards IE Insp Rept 50-305/80-04 on 800204-05 No noncompliance noted FIGRELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/21 2pp
- --B004100130 IE Insp Rept 50-305/80-04 on B00204-05 No noncompliance noted Major areas inspected actions re IE Bulletins 79-14 & 79-04. work procedure review & records DANIELSQN, D H. Region 3. Chicago, Reactor Construction & Engineering Support Branch YIN, I T. Region 3. Chicago, Office of the Director 80/02/21 App
- 8004100153 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/07 in
- 8004100405 Responds to IE Bulletin 79-01B Consistent w/intent of IE Circular /B-08, IE Bulletin 79-01 % 79-01A, review of Class IE instrumentation comparing qualifications w/design specs or FSAR requirements shows addl requirements were met MATHEMB, E.R. Wisconsin Public Service Corp. 80/03/ii 1p
- 8004090428 Forwards IE Insp Rept 50-305/80-05 on 800219-22 No noncompliance noted Details withheld (ref 10CFR2 790) HIND.J A Region 3, Chicago, Safeguards Branch 80/03/18 2pp
- --8004090431 IE Insp Rept 50-305/80-05 on 800219-22 No noncompliance noted Major areas inspected facility organization to operations, previously identified items to nuclear math control Details withheld (ref 100FR2 790) HINDLY A Region 3, Chicago, Safeguards Branch PATTERSON, J P. FINLEY, A G. Region 3, Chicago, Office of the Director 80/03/03
- 8004150196 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31
- BOD4080728 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating 0:1 Addition & Onsite Supply " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director BO/04/01
- 8004150061 Forwards IE Info Notice 80-t3. "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/02
- B004180067 Forwards attachments to IE Circulas B0-03, "Protection From Toxic Qas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- BOO4220140 Forwards IE Info Natice BO-14, "Safety Suggestions From Employees " No action required KEPPLER, J & Region 3, Chicago, Office of the Director BO/04/02
- 8004220375 Forwards IC Cyrcular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/03 ip
- 8004230291 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME 8A-312. Type 304 Stainless Steel Pipe " Action required KEPPLER. J O Region 3, Chicago, Office of the Director 80/04/07
- BOO4220060 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director BO/04/09

- R Periodic operating reports 5 related correspondence
- B604150354 Forwards menthly operating rept to: Mar 1980 MATHEWS, E.R. Wisconsin Public Service Corp. B0/04/09 1
- --8004150355 Boothly operating rept for Mar 1980 RUITER, G. H. Wisconsin Public Service Corp. 80/04/09 Spp
- S Reportable occurrences, LERs ' related correspondence
- 8004080457 Forwards LERs 80-015/03L-0 % 80-016/03L-0 MATHEWS, E.R. Wisconsin Public Service Corp. 80/04/01 1p
- --8004080462 LER 80-015/03L-0 on 800303, while performing SP34-099, valve SI-35IA would not open Caused by setting of 2 1/2 close 1 1/2 open on torque switch Open torque switch raised to 2 1/2 Tested satisfactorily NALEPKA.D S Wisconsin Public Service Colp 80/04/01 1p
- --B0040B0467 LER 80-016/03L-0 on 800305, while testing 18 diesel generator operability for ICPs on 1A diesel generator. 1B generator failed to start Caused by primary air start motors not rotating engine Motors replaced Manufacturers investigating NALEPMA.D S Wisconsin Public Service Corp 80/04/01 ip
- 8004150524 Forwards revised LER 79-028/03X-2 MATHEMS,E R Wisconsin Public Service Corp 80/04/09 ip
- --8004150532 Revised LER 79-028/03/-2 on 791207.during inspithree horizontal piper restraints discovered missing on to-inch syc water header Caused by oversight between seismic analysis // hanger design teams
 SAVER.D W Wisconsin Public Service Corp. 80/04/09 2pp
- 8004150581 Forwards supplemental LER 79-017/03L-0
 MATHEWS, E R Wisconsin Public Service Corp 80/04/09 (p.
- --8004150596 LER 80-017/03L-0 on 800310, during surveillance testing, turbine driven auciliary feedwater pump discharge cross--connect valve AFR 10B would not close from control room When inspected, valve operated properly
 NALEPKA,D S Wisconsin Public Service Corp 80/04/09 ip
- 8004220642 Forwards LER 80-014/04L-0 MATHEWS, E. R. Wisconsin Public Service Corp. 80/04/16 1p
- --8004220648 LER 80-014/04L-0 on 800318, when circulation water inlet temp rose above limit due to circulating water discharge drifting over intake after wind shift, second circulating water pump failed to start Caused by clogged bearing cooler flow line MARCHI,M L. Wisconsin Public Service Corp. 80/04/17 1p
- 8004230504 Forwards LER 80-018/03L-0 MATHEWS E R Wisconsin Public Service Corp 80/04/18 19
- --8004230555 LER 60-018/031-0 on 800320 during normal steady state operation.unfamiliar odor noted in diesel generator room 1B While looking for source. Bus 1-6 potential transformer disconnect cubicle door opened causing loss of voltage NALEPKA: D. Misconsin Public Service Corp. 60/03/19 ip
- 8004290321 Forwards LERs 80-019/03L-0 & 80-020/03L-0 MAYHEWB,E R Wisconsin Public Service Corp 80/04/23 ip
- --8004270327 LER 80-019/031-0 on 800326, during shield bidg ventilation sys surveillance testing, check damper SBV-10A failed to open fully-resulting in Inability to draw vacuum in annulus Caused by controller setpoint drift Setpoint adjusted NAPLEPKA, D S Wisconsin Public Service Corp 80/04/18 1p
- --B004290336 LER 80-020/03L-0 on 800326.control valve 8H 1061A failed to open upon removal of heat detector during charcoal filter heat detector test 9P 08-195 Caused by dirty valve Valve internals cleaned & diaphragn replaced NALEPKA.D S Wisconsin Public Service Corp 80/04/25 ip
- DOCKET 50-304 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fare protection plans
- 8004080225 Submits revised schedule for implementing fire protection mods MAYER, L.O. Northern States Power Co. 80/03/31 2gp

- BOO4170056 Forwards "Evacuation Time Estimates," from areas near nuclear generating plant. in response to NRC 791129 request MAYER, L D Northern States Fouer Co BO/04/10 19
- --8004170059 "Evacuation Time Estimates"

 * Northern States Power Co 80/04/30 18pp
- G Adjudicatory correspondence
- 8004230088 Request for hearing and petition to intervene re spent fuel pool mod License amend should not be issued until State of MN administrative proceedings are completed re licensee application for certificate or need & environ evaluation SENECHAL.M E. DLSON.J F. Minnesota, State of 80/03/31 Spp
- BOO4230100 Notice of appearance in proceeding SEMECHAL, M E , DESON, J F Minnesota, State of 80/03/31 App
- H General correspondence
- 8004280037 Discusses NRC intervenor funding in response to 800305 ltr Commission decided not to initiate program to provide funding in 1976 Intervenor funding is being studied again & funds for pilot program have been requested for FYB1 CHRISTENBURY.E Healings Division 80/04/08 1p
- --8004280043 Requests info on availability of govt financial aid for intervenors in racility spent fuel storage license amend proceeding FIELDSETH.H Affiliation Unknown 80/03/05 lp
- P Operating license stage documents & correspondence
- 8004110520 Forwards FR notice of proposed issuance of amend to Licenses DPR-42 & DPR-60 re spent fuel storage capacity SCHWENCER: A Operating Reactors Branch 1 80/02/28 2pp
- ---BOO4i10524 Notice of proposed issuance of amend to Licenses DPR-42 to DPR-60 re spent fuel storage capacity
 SCHWENCER, A Operating Reactors Branch 1 80/02/28 4pp
- 8004020070 Forwards Amends 41 & 35 to Licenses DPR-42 & DPR-60, respectively & notice of issuance b availability SCHWENCFR.A Operating Reactors Branch 1 80/02/29 4pp
- --8004020075 Amend 35 to License BPR-60 changing App B Tech Specs by revising requested requirement re blowdown flow over 150 cfs to annual & fish impingement sampling frequency to once every two wks Tech Sper replacement pages enci SCHMENCER, A Operating Reactors Branch 1 80/02/29 Spp
- ~-8004020079 Notice of issuance b availability of Amenda 41 \$ 35 to License DPR-42 & DPR-60 respectively SCHWENCER.A Operating Reactors Branch 1 80/02/29 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D G Division of Operating Reactors 80/03/12 5pp
- --8004030110 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp
- 800407037B Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics info during incident or abnormal occurrence at facility
 KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/15
- 8004100183 Requests controlled set of PVIDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/20
- 8004100486 Summary of 800221 telcon w/util re status of NUREG-0578 implementation Items requiring addl clarification subcooling meter b backup procedures used to determine subcooling & use of CRTs not having seismic qualifications GROTENHUIS.M Operating Reactors Branch ! 80/03/21 5pp
- 8004140079 Summary of 800321 meeting w/util in Bethesda, MD re fuel poet expansion proposed by util on 800131 Addl info re unresolved questions will be transmitted by util encl list of attendees GROTENHUIS, M. Operating Reactors Branch 1 80/03/21 3pp

- 8004210023 Advises that 78[122 application to amend Licenses DPR-42 & DPR-60 is pro forma & administrative in nature placing Unit 1 in Class II fee category Refund for Class III overpayment will be processed MILLERAW O License Fee (lanagement Branch 80/04/03 ip
- 8004150339 Forwards addl info se implementation of short-term Lessons Learned Task Force recommendations MAYER.L O Northern States Power Co 80/04/11 17pp
- 8004180464 Forwards proprietary & nonproprietary versions of "Structural Analysis of RCS for Postulated LOCA," preliminary issue Applications for withholding encl Proprietary version withheld (ref 10CFR2 790) ANDERSON, T M Westinghouse Electric Corp 80/04/11 11pp
- --B004180475 Nonproprietary version of "Structural Analysis of RGS for Postulated LUCA." preliminary issue # Westinghouse Electric Corp , Nuclear Energy Systems 80/02/29
- 8004180341 Forwards Offsite Dose Calculation Manual Revision 1 MAYER.L G Northern States Power Co 80/04/15 ip
- --8004180342 Offsite Dose Calculation Manual Revision 1 * Northern States Power Co 80/04/30 150pp
- 8004280547 Requests NRC review of proposed implementation of short-term Lessons Learned Task Force recommendations re Item 2 1 6 t, "Plant Shielding Review," Item 2 1 9, "Reactor Vessel Head Vent." & Item 2 2 26, "Onsite Technical Support Ctr " MAYER, L D Northern States Power Co 80/04/25 ip
- Q Inspection reports, If Bulletins & correspondence
- GOO4010191 Further responds to NRC 790123 itr re violations in IE Insp. Rept 50-306/78-24 Corrective actions Anker Holt snubber delivery scheduled for Apr 1980 & installation will be completed one month after delivery WACHTER,L. J. Northern States Power Co. 79/12/18 ip
- 8004030251 Forwards IE Insp Rept 50-304/80-03 on 800115-18 & notice of violation FIGRELLIO Region 3, Chicago Reactor Construction & Engineering Bupport Branch 80/02/16 2pp
- --8004030252 Notice of violation from insp on 800115-18
 * Region 3. Chicago. Office of the Director 80/02/13 ip
- --8004030255 IE insp Rept 50-306/80-03 on 800115-18 Noncompliance noted failure to follow nondestructive examination procedures KEY,H J., DANIELSON,D H. Region 3, Chicago, Office of the Director 80/02/13 9pp
- 8004100269 Forwards IE Insp Repts 50-282/80-01 & 50-306/80-01 on 800102-31 & notice of violation HEIBHMAN R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004100283 Nutice of violation from insp on 800102-31 * Region 3. Chicago, Office of the Director 80/02/22 2pp
- --8004100290 IE Insp Repts 50-282/80-01 & 50-306/80-01 on 800102-31 Noncompliance noted containment spray additive tank isolated from containment spray sys & failure to follow operating procedure FEIERABEND. C D . BOYD, D C Region 3. Chicago. Office of the Director. 80/02/22 9pp
- 8004070059 Responds to IE Bulletin 79-17. Revision i. "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " Required visual insp completed on Unit 1 in Feb 1780 No corrective actions necessary OILBERTS, D. E. Northern States Power Co. 80/03/07 ip
- 8004070210 Respands to IE Bulletin 79-27 outlining conclusions from investigation of instrument buses Design change initiated to replace instrument inverters w/inverters capable of automatic transfer to alternate ac QILBERTS.D E Northern States Power Co 80/03/07 2pp
- 8004:00143 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block "No specific action or response required KEPPLER.J Q Region 3. Chicago. Office of the Director 80/03/07

- B004040456 Responds to II. Bulletin 79 OIB, 'Environ Qualitication of Class IE Equipment " Delay until 800317 approved by J Hughes in 800259 telcon Evaluates components? sys qualitication for expected operational conditions GLDBERTS, D.E. Northern States Power Co. 80/03/13 4pp
- 8004100067 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IC Insp Rapts 50 282/79-32 \$ 50-306/79-26 DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/20 Ip
- --8004100070 Responds to NRC 800207 ltr .e violations noted in IE Insp Repts 50-282/79-32 % 50-306/79-26 Discusses collection of Xe-133 gas samples w/low level gas headers GILBERTS.D E. Northern States Power Co. 80/02/29 2pp
- 8004140199 Summary of 800212 meeting w/util h Westinghouse at Forest Hills Lab re results of facility steam generator insp Insp & plugging of steam generators was acceptable t supports resumption of power operation Supporting matis encl GRATENHUIS: M Operating Reactors Branch 1 80/03/20 17pp
- --8004140210 STS Pages 3/4 4-1/,3/4 4-18,3/4 4-3 5 3/44 4-4 re steam generator 1859 8 Westinghouse Electric Corp. 79/0//15 4ap
- B004i40013 Responds to IE Bulletin 80-03 ie loss of charcoal from std adsorber colls Visual jusp of charcoal filters installed revealed no degradation or sagging Detailed visual insp of each filter performed annually GILBERTS.D E Northern States Power Co 80/03/24 2pp
- 8004150184 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action of response necessary KEPPLER. J O Region 3, Chicago. Office of the Director 80/03/31
- 8004080719 Forwards 1E Circular 80-05, "Emergency Diosel Generator Lubricating Oil Addition > Onsite Supply " No written response required KEPPLER, J O Region 3, Chicago, Ofrice of the Director 80/04/01
- 8004150052 Forwards IF Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER,J Q Region 3, Chicago, Office of the Director 80/04/02
- 8004180055 Forwards attachments to IC Circular 80-03, "Protection From Toxic Oas Hazards," inadvertently emitted from 800306 transmittal KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/04/02
- 8004220148 Forwards IC Info Notice 80-14. "Safety Suggestions From Employees " No action required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/04/02 to
- BOD4220378 Forwards IE Circular BO-07, "Problems W/HPCI Turbine Dil Sys " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director BO/04/03 in
- 8004230297 Forwards IE Bullesin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/07 ip
- 8004300334 Ack receipt of 800312 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-306/80-03 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/08 2pp
- ---8004300337 Responds to NRC 800216 ltr re violations noted in JE Insp Rept 50-306/80-03 Corrective actions liquid genetrant examinations conducted during fuel outage Helds buffed smooth OTLBERTS.D E Northern States Power Co 80/03/12 2pp
- 8004220047 Forwards IE Builetin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/09 ip

- 8004180296 Forwards inservice insplexem summary for refueling outage Number 4 on 800102-0204 MAYERIL O Northern States Fower Co 80/04/16 ip
- --8004180307 Inservice hisp rept/exam summary for refueling outage Number 4 on 800102-0204 HAUSEN D B , DAHLMAN, L C , MRUNPOB, P J Northern States Power Co 80/04/01 150pp
- 8004230480 Forwards Revision 4 to "ASME Code XI Inservice Insp / Testing Program / Info Requised for NRC Review of Requests for Reliet from ASME Code Section XI Requirements " MAYER, L.O. Northern Stafes Forer Co. 80/04/17 2pp
- --8004230487 Revision 4 to 'ASME Code XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section (I Requirements "

 8 Northern States Power Co 80/04/17 35pp
- A Periodic operating reports ? related correspondence
- 8004140339 Forwards monthly operating rept for har 1980 MAYER, L. O. Northern States Fower Co. 80/04/10 ip
- --8004140344 Monthly operating rept for Mar 1980 HUNSTAD, A.A. Northern States Power Co. 80/04/01 Spp
- S. Reportable occurrences, LERs & related correspondence
- 8004180380 Forwards LER 80-011/031-0 MAYER, L O Northern States Power Co 60/04/11 lp
- --8004180386 LER 80-011/03L-0 on 900312 motor breaker of charging pump 22 would not stay closed Pump stopped Caused by failed TFK breaker Breaker replaced HWHSTAD, A A Northern States Power Co 90/04/11 1p
- DOCKET 50-309 MAINE YANKEF ATOMIC POWER PLANT
- H General correspondence
- 8004240435 Forwards 800229 itr from Sensible ME Power legal counsel S Tupper Counsel takes issue w/NRC stated purpose for meeting to discuss group role in util request to expand spent fuel storage facility Requests comment on Tupper itr COHEN.44 8 Senate 80/03/07 App
- 8004080644 Discusses 800225 teleon w/AF Stevens of ME Voice of Energy re concerns expressed in 800108 ltr Teleon assured that NRC is receptive to info from all parties concerned in action involving energy FAIRTILE.M D. Operating Reactors Branch 4 80/03/11 ip
- ~~8004080653 Expresses concern that NRC may be gaving too much weight to positions of Sensible Mf Power Group does not represent all cititens of ME STEVENS.A F Maine Voice of Energy 80/01/18 ip
- 8004030112 Responds to 800116 ltr re eacility concerns Forwards detailed outline info addressing concerns including info re asymmetric LOCA loads operator training & licensing & Mar radiocative gas release DN:H R Office of Nuclear Reactor Regulation 80/03/17 3pp
- 8004080339 Notifies NRC that util concurs w/C-E owners group request that future correspondence re regulatory matters be directed to individual 1 consees MODDY.D E Maine Yankee Atomic Power Co 80/03/27 2pp
- 8004210048 Responds to 800309 ltr requesting info re environ affects of New England hoclear power plants Radiation effluent levels determined by 10CFR20 & App 1 to 10CFR30 Environ info available in stated LPDPS BALLARD, R t. Environmental Projects Branch (80/04/01 2pp
- l Financial information
- 8004150290 Forwards Form 10-K.util 1979 annual financial rept HOWE.R B Maine Yankee Atomic Power Co 80/04/10 37pp

- P Operating license stage documents & correspondence
- B004280065 Responds to 800128 request for info re testimony before Public Utils Commission & Forwards LER 78-53/01T-0.781206 backup rept & list of decuments on dockets for Oct 1978-Mar 1979 & Mar 1979-May 1979 Request list encl RUSSELL.W T Technical & Administrative Support Branch 80/02/05
- --8004280090 Requests encl chronology of safety injection piping stress analysis to reviews be forwarded to Engineering Branch for review Refs AITS-F14/41H2, document record for dockets for Oct 1978-Mar 1979 to her-May 1979, respectively, encl KEIMIG.R R Region 1. Philadelphia, Office of the Director 79/01/18 95pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethasda Operations Ctr EISENHUT D G Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs" * Division of Operating Reactors 80/02/21 28pp
- 8004080047 Responds to B00229 memo re deletion of NRC water quality requirements from facility DL Commission approval was not sought since action involved implementation of ASLAP decisions Comparison of requirements of EIS & NPDES encl CHAPARIHK Office of the Erecutive Legal Director DENTONIHR Office of Nuclear Reactor Regulation 90/03/21 7pp
- --8004080053 Submits questions re deletion of water quality requirements from facility CL Response should be completed before further deletions are made to other CLs BRADFORD.P A Commission 80/02/29 1a
- 8004i10570 Provides add1 info re implementation of requirements set forth in Item 2 i 7a of NUREG-0578 Commitment to install safety-grade sys prior to 810101 required no later than 15 days after receipt of Itr
 EISENHUT.D 0 Division of Operating Reactors 80/03/27 2pp
- 8004080634 Notifies that info requested in NRC 800312 ltr.re bypass & reset of engineered safety features, will be submitted by 800319 GROCE.R H Maine Yankes Atomic Power Co 80/03/28 2pp
- 8004110434 Forwards Revision 8 to YOGAP-I-A addressing organization changes to GA program HEIDER.L H Yankee Atomic Electric Co 80/04/04 ip
- --B004110444 GA program Revision B for facility operation VANDENBURGH.D C, HEIDER,L H , MGDDY,D E Yankee Atomic Electric Co YOQAP-1-A 60/04/01 20pp
- 8004140308 Notifies that CEN-128, "Response of C-E NBSS to Transients & Accidents" constitutes response to short-term analysis & emergency procedure guideline requirements of NVREO-0578. Section 2 1 9 (C) CROCE,8 H Maine Yankee Atomic Power Cp 80/04/10 1p
- 8004180438 Provides status of response to NRC 800327 request for commitment to installation of auxiliary feedwater sys & safety-grade sys for automatic initiation Development of safety-grade sys underway GROCE, R H Maine Yankee Atomic Power Co 80/04/14 ip
- 8004220522 Forwards revised Section 5 4 1 of "Cycle 5.Core Performance Analysis " VANDENBUROH, D. Maine Yankee Atomic Power Co. 80/04/17 ip
- --8004220530 Revised Section 5 4 1.of "Cycle 5.Core Performance Analysis " * Maine Yankee Atomic Power Co 80/04/17 35pp
- O inspection reports. IF Bulletins & correspondence
- 8004180508 Forwards IC Insp Rept 50-309/80-03 on 800122-25
 No noncompliance noted
 CARLEGUR T Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch 80/02/26 2pp
- --8004180512 IE 1msp Rept 50-309/80-03 on 800122-25 No moncompliance JUMINOSIZ IE INSP Mept 50-30740P-03 on MODIZZ-26 No noncompliance noted Major areas inspected quality related activities associated W/inservice insp program TRIPP: LE Region 2, Atlanta, Reactor Construction & Engineering Support Dranch SANDERS, W F Region 2, Atlanta, Office of the Director 80/02/21 5pp

- 8004230120 Forwards IE Insp Rept 50-309/79-20 on 791217-20 No noncompliance noted MARTIN,W G Region 1, Philadelphia, Safeguards Branch 80/03/03 200
- --8004230128 IE Insp Rept 50-309/79-20 on 791217-20 No noncompliance noted Major areas inspected approved physical security plan, audit organization, barriers, lighting, access controls & alarm stations Details withheld (ref 10CFR2 790)
 DEVLIN.J W Region I, Philadelphia. Safeguards Branch JDNES, E
 Region 1, Philadelphia, Office of the Director 80/02/21 1p
- 8004070458 Forwards addi response to IE Builetin 77-01 re environ qualification of Class IE equipment Master list & electrical component list enc! Qualification work sheets & other missing info will be submitted by 800314 W/o enc!

 JOHNSON, W.P. Maine Yankee Atomic Power Co. 80/03/04 2pp
- 8004100422 Responds to IE Rulletin 79-14 Field verification of valve weights existing pipe geometry, seismic support locations, functions & all details completed Review of field work vs design shows differences at rate of approx 30% MDODY, D E Maine Yankee Atomic Power Co 80/03/04 2pp
- 8004080430 Requests confirmation of NRC understanding that 79-01B missing Item 1 info will be submitted 800314 & Items 2 & 3 qualification work sheets by 800314 per util 800304 telecopy GRIER. B H Region 1, Philadelphia, Office of the Director 80/03/06 ip
- 8004020016 Responds to IE Bulletin 79-19 & NRC 800213 ltr Training groups am required by bulletin presently underway & will be fully implemented by Jul 1980 MODY, D E Maine Yankee Atomic Power Co 80/03/07 ip
- B004100406 Responds to IE Bulletin 79-14 Submits mod to Paragraph 4 of B00304 ltr to NRC.per 800306 telcon All seismic support nonconformance will be restricted prior to restart MODDY,D E Maine Vankee Atomic Power Co 80/03/07 1p
- 8004080263 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Redundancy of info & controls sufficient to achieve cold shutdown in event of single bus failure No mods necessary GROCE,R H Maine Yankoe Atomic Power Co 80/03/10 8pp
- 8004080351 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Revised data re Item 1 & updated work sheets & profiles attached Missing info to be submitted within 90-day response period W/o encl JOHNSON.W P Maine Yankee Atomic Power Co 80/03/14 2pp
- BO04230005 Responds to IE Bulletin BO-03 Investigation completed & charcoal adsorber cells found adequate MODDY,D E Maine Yankee Atomic Power Co BO/03/18 Rpp
- 8004210039 Ack receipt of 800317 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/80-01 ORIER.B H Region 1. Philadelphia, Office of the Director 80/03/24 1p
- --8004210044 Responds to NRC 800225 ltr re violations noted in IE Insp Rept 50-309/80-01 Corrective actions refueling machine operators reminded to wear protective cotton gloves unless special health physics surveys performed MOGDY,D E Maine Yankee Atomic Power Co 80/03/17 2pp
- --8004210045 Forwards IE Insp Rept 50-309/80-01 on 800121-25 & notice of violation BRNNNRR,E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/02/25 2pp
- --8004210049 Notice of violation from insp on 800121-25
 * Region 1, Philadelphia, Office of the Director B0/02/21 1p
- --8004210053 IE Insp Rept 50-309/80-01 on 800121-25 Noncompliance noted failure to comply w/radiation work permit requirements Audible count rate monitor not operating in refueling cavity area MARTIN, T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, SHETLAND, P D, LAZARUS, W J Region 1, Philadelphia, Office of the Director 80/02/21 ip
- 8004i50277 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip

- 8004090069 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER,B H Region 1, Philadelphia. Office of the Director BO/04/01 lp
- 8004110154 Forwards IE Info Notice 80~13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/02 ip
- 8004240318 Forwards IF Info Notice 80-14, "Sarety Suggestions From Employees" No action required ORIER. B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004180174 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0:1 Bys " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/03 1p
- 8004230459 Forwards [E Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Action required GRIER.II H. Region 1, Philadelphia, Office of the Director 80/04/04 | 1p
- 8004180194 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Pemetration Welds "Written response required GRIER, D. H. Region 1, Philadelphia, Office of the Director 80/04/07 Ip
- R Periodic operating reports & related correspondence
- 8004080406 Forwards "Radiological Environ Surveillance Rept,1979 " GROCE,R H Maine Vankee Atomic Power Co 80/03/31 1p
- ---8004080411 "Radiological Environ Surveillance Rept.1979 "
 * Maine Yankee Abomic Power Co 80/03/23 55pp
- 8004140154 Forwards "Discharge Monitoring Rept for Feb 1980" Background info also encl re mixing zone temps recorded during summer of 1979 & status of discharge license renewal GARRITY, J H Maine Yankee Atomic Power Co 80/04/04 3pp
- ---B004140157 "Discharge Monitoring Rept for Feb 1980 "
 * Maine Yankee Atomic Power Co 80/02/12 16pp
- 8004150367 Forwards monthly operating rept for Mar 1980 MDDDY.D E Maine Yankee Atomic Power Co 80/04/11 2p
- --B004150370 Monthly operating rept for Mar 1980 BEERB F C Maine Yankee Atomic Power Co B0/04/11 5pp
- B0042B0562 Forwards "Discharge Monitoring Rept for Mar 1980," submitted to ME Dept of Environ Protection Rept sent to NRC per 800307 commitment Transmittal 1tr encl GARRITY, J H. Maine Yankee Atomic Power Co. 80/04/23 2pp
- --8004280564 "Discharge Monitoring Rept for Mar 1980 " * Maine, State of 80/03/07 App
- S Reportable occurrences, LERs & related correspondence
- 8004180489 Forwards LER 80-007/03L-0 WODD, E C Maine Yankee Atomic Power Co 80/04/10 1p
- --8004180492 LER 80-007/03L-0 on 800319, during routine power escalation following refueling shutdown.RHR valves RH-8 & 10 found open & unlocked Six addl valves found unlocked Caused by personnel error Operators reinstructed on procedures BRINKLER, J E Maine Yankee Atomic Power Co 80/04/10 2pp
- 8004210277 Forwards LER 80-008/03L-0
 WOOD, E C Maine Yankee Atomic Power Co 80/04/14 in
- ---B004210278 LER B0-008/03L-0 on B00321, during special testing of trip matrix polition of reactor protective sys, found one set of relay contacts on one matrix relay would not open reliably upon de-energization Cause not stated BRINKLER, J E Maine Yankee Atomic Power Co B0/04/14 2pp

- U Congressional/Executive Correspondence
- 8004140299 Responds to 800131 inquest Forwards NRC 800317 response to M Dwinell 800116 inquiry is racillty safety DIRCKS.R J. Office of the Elecutive Director for Operations 80703/21 ip
- --8004140303 Forwards response to 809116 ltr to Senator Cohen re facility safety Handware medessary to resolve asymmetric LOCA load issue installed prior to restail Operator training program improved.es illustrated by 1007 success on Oct 1979 test DENTON-H R Office of Nuclear Reactor Regulation 80/03/17 3pp
- --B004140304 Forwards H Numell B00116 inquiry ltr is facility safety SNONE.O J. House of Rep. 80/01/31. 3pp
- GOCKET 50-311 SALEM NUCLEAR GENERATING STATION UNIT 2

 A Application/construction stage documents & correspondence
- 8004040631 Advises or issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment." providing guidance re nethods for Compliance ROSS.D F Division of Project Hanagement
- 8004040017 Submits oddl guidance to NVREG-0588. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re autiliary feedwater sys per Bulletins & Orders Task Force review of IMI-2 accident Info should be provided as amend to application Submittal schedule should include RRC approval prior to issuance of DL W/enci ROSS. DF Division of Project Management 60/03/10 53pp
- 8004040472 Summary of 800727 meeting w/applicant at site re near-term OL requirements LICITRACE A Light Water Reactors Branch 3 80/03/11 3pp
- B004020256 Requests review of protection sys design for potential deficiencies in bypass.override & reset circuits & conformance w/listed critoria Use of nonsafety grade monitor could degrade reliability of isolation sys
- 8004020154 Forwards add1 info re shorthose sturgeon in Delaware River Concludes that continued operation of Unit 1. future operation of Unit 2 & const completion of Hope Creek units will not jeopardize existence of shorthose sturgeon REGAN.W H Assistant Director for Environmental Projects 80/03/14
- ~~8004020163 "Assessment of Impacts of Salem & Hope Creek Stations on Shortnose Storgeon, Acipenser Brevingstrum Leguer" MASNIF,M T , WILEON, J H Office of Nuclear Reactor Regulation 80/03/05 110pp
- 8004070101 Cunfirms points made during 8003]3 teleon w/util to test that simulates loss of all ac power using RCS pump heat to simulate decay heat Preparation of detailed test procedures requested
 PARR.O D Light Water Reactors Branch 3 80/03/17 3pp
- 8004100526 Notification of 800319-21,24 & 25 site visit in Salem County,NU to discuss control room LICITRA,F A Light Water Reactors Branch 3 80/03/18 3pp
- 8004140486 Notification of 800328 meeting w/util in Bethesda.KD to discuss staffing of facility LICITRA.E A Light Water Reactors Branch 3 80/03/27 2pp
- 8004240149 Approves secondary water chemistry control program for steam generator tube integrity Requires addl measures reinstallation of inspiports & plugging of Row I tubes prior to startup
 PARRIO D Light Water Reactors Branch 3 80/03/27 3pp
- BD0401043B Forwards updated info re implementation of TMI Task Porce short-term Lessons Learned requirements Onsite technical support cir operational, w/communications installed as described in 800104 submittal MITTL.R L. Public Service Electric & Gas Co. of New Jarsey 80/03/28 11pp

- 6004010443 Forwards addl info requested to containment purge & pressure-vacuum relief circuitry Containment ventilation isolation circuitry modified to include addl safety injection input signal MITTLER L. Public Service Electric & Gas Co. of New Jersey 80/03/28 8pp
- 8004010449 Advises of new low level alaim on refueling water storage tank Alarms to be installed prior to low power testing MITTL/R L Public Service Electric & Gas Co of New Jeisey 80/03/28 2pp
- B004010453 Notifies of review per NRC request of Tables I-2 & 3, II-1, III-1, IV-1 & VI-1 from NUREC-0611. "Generic Evaluation of Feedwater Transients & Small Break LOCA in Hestinghouse-Designed Operating Plants " Lists corrections for tables MITTL.R L Public Service Electric & Gas Co of New Jersey 80/03/28 2pp
- 8004070250 Requests extension of CPPR-53 until 801101, due to delay in NRC issuance of OLs caused by TNI accident MITTL.R L Public Service Electric & Gas Co of New Jersey 80/03/28 2pp
- 8004040313 Submits supplement to low power test program described in 800208 ltr includes two addl tests re establishment of natural circulation from stagnant conditions & boron mixing & cooldown Test summarios encl MITTLeR I Public Service Electric & Gas Co of New Jarsey 80/03/31 4pp
- BOO4140014 Notification of BOO404 meeting w/utils in Bethesda.MD to discuss applicants' progress & status in design review re plant shielding & environ qualification of equipment for spaces/sys used in post-accident operations BUCKLEY.B C Light Water Reactors Branch 1 DROMERICK, A W , LICITRA.E A Light Water Reactors Branch 3 BO/03/31 7pp
- 8004040282 Notifies that util plans to develop training program re use of installed plant sys to control or mitigate accident involving severe tore damage Licensed operators will be trained prior to full power operation MITTL,R L. Public Service Electric & Gas Co. of New Jersey 80704701. 3pp
- 8004i10305 Informs that mod planned to ECCB to provide automatic sysfor changeover from injection to recirculation shase Modwill provide backup for normal manual changeover operation Design description will be provided prior to implementation MITTL.R I Public Service Electric & Oas Co of New Jersey 80/04/03 ip
- 8004110431 Forwards updated info re implementation of short-term Lessons Learned Task Force requirements Evaluation will be performed of expected Indiation levels prior to initiation of special low power test program MITTL/R L. Public Service Electric & Gas Co. of New Jorsey 80/04/03 4pp
- 8004110469 Notifies that util will establish onsite safety review group, independent of station staffito perform independent reviews of plant operational activities Training program for offsite technical personnel will be instituted by Aug 1980 HITTL, R L Public Service Electric & Oas Co of New Jorsey 80/04/03 2pp
- 8004110474 Forwards "Refueling Water Storage Tank Vortex Test," verifying no vortex formation MITTL, R.L. Public Service Electric & Gas Co. of New Jersey 80/04/03 ip
- ~-8004110475 "Refueling Water Storage Tank Vortex Test "

 * Public Service Electric & Gas Co of New Jersey 80/04/03
 4pa
- 8004110426 Submits info re RWST low level alarm setpoints, in response to 800401 & 02 teleons Setpoints will be set at 150,000 gallons to insure that sufficient vol will be available in RWST to allow changeover from injection to recirculation MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/04/07 Gpp
- 8004170060 Describes plans to staff licensed operator positions on both units, following GL issuance for Unit 2, per 800328 discussion w/NRC MITTLER L. Public Bervice Electric & Oas Co. of New Jersey 80/04/09. 3pp
- 9004280189 Notifies of completion of review of util application for OL Forwards proposed license
 DENTON, H.R. Office of Nuclear Reactor Regulation 90/04/09 18pp

- --8004280162 Draft safety evaluation re CL application

 # Office of Nuclear Reactor Regulation NUREQ-0517 54 80/04/08
 4000p
- 8004170250 Responds to NRC 800314 biological assessment of impact of continued aperation or const of facilities Forwards biological opinion b summary of informal consultation w/NRC re Salem Unit 1 Shortnose sturgeon are not in jeopardy LETTZELL, T & Commerce, Dopt of, National Marine Fisheries Service 80/04/15 2009
- 8004250393 Responds to NRC B00327 request that Row 1 tubes in steam generators be plugged prior to start of operation Util considers mod unnecessary Plugging Row 1 tubes would remove capability for early detection of onset of denting MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/04/15 2pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.hæs been postponed pending GAU clearance under Føderal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004240377 Responds to 800411 telcon requesting info re availability & adequacy of procedural guidance for supervisor of unaffected reactor when companion unit is involved in emergency Procedures to be approved prior to Unit 2 criticality MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/04/14 ip
- 8004240365 Notifies that procedures for corporate mgt & technical support are being prepared for revised emergency plan implementation procedures manual & will be incorporated prior to inital fuel loading MITTL, R L. Public Service Electric & Gas Co. of New Jersey BO/04/15 1p

O Adjudicatory correspondence

- 8004040207 Comments on irresponsible way intervenors are being treated Sites case of ruling to allow Salem Unit 1 to operate despite no evidence that licensee could protect endangered shortnose sturgeon COLEMAN.E 0 . COLEMAN.A C Affiliation Unknown 80/03/05 3pp
- 8004100446 Notice that CJ Valore appears as attorney of record for petitioner SE Donelson, Mayor of Lower Alloways Township, Salem County, KJ VALORE, C, J Lower Alloways Creek, NJ VALORE, C J Valore, C 80/03/25 1p
- 8004100593 Intervenor request for suspension or moratorium on issuance of SL Issuance would permit same enlarged spent fuel pool that is subject of angoing hearing DONELSON, SE Lower Alloways Creek, NJ 80/03/25 4pp
- 8004240485 Forwards NRC confirmatory orders BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/04 1p
- --8004240475 Order confirming util commitment to perform review requested by IE Bulletin 79-27 Info required is specified in Attachment A STELLO. V Office of Inspection & Enforcement, Office of the Director 80/04/04 6pp
- 8004150456 Forwards comments in opposition to Township of Lower Alloways Creek 800325 request for suspension of issuance of OL per 10CFR2 206 Delay not warranted WETTERHAHN.M.J Conner Moore & Corber 80/04/11 1p
- --8004150469 Comments in apposition to Taunship of Lower Allaways Creek 800325 request for suspension of issuance of OL per 100FR2 206. Unges denial due to untimeliness of petition & inadequacy of allegations re noncompliance w/NEPA rules * Public Bervice Electric & Gas Co of New Jersey * Conner. Moore & Corber 80/04/11 Spp
- 8004210291 Forwards response to Public Svc Electric & Gas Co of NJ comments re request of Lower Alloways Creek Township for suspension of monatorium of issuance of OL OL should not be issued until conclusion of ASLB hearing VALORE.C J Valore. C 80/04/15 5pp
- B004280190 Forwards Director's decision under 10CFR2 206 denying 790803 & 31 petitions re issuance of OL Related FR notice encl DENTON, H R Office of Nuclear Reactor Regulation 80/04/16 1p

- --8004280195 Notice of issuance of Director's decision under 100FR2 206 denying intervenors Coleman 790803 & 31 petitions reissuance of OL DENTON H R Office of Nuclear Reactor Regulation 80/04/16 lp
- ~-8004280196 Director's decision under 10CFR2 206 denying intervenors Coleman 790803 & 31 petitions re issuance of OL Operation of facility would result in substantial production cost savings to retepayers DENTON.H R Office of Nuclear Reactor Regulation 80/04/16 40pp
- 8004300585 Responds to 791018 petitions requesting that Commission issue show cause order to suspand or revoke DL for Salem 1 & CPs for Salem 2 & Hope Creek 1 & 2 & stay issuance of DL for Salem 2 Request denied W/Director's decision DENTON:H R Office of Nuclear Reactor Regulation 80/04/18 [p
- ~~8004300590 Director's decision under 10CFR2 206 on E & A Coleman petition requesting that Commission issue show cause older re facilities CL & CP issuances Request denied DENYON.H R Office of Nuclear Reactor Regulation 80/04/18 6pp
- --8004300598 Notice of issuance 3 availability of Director's decision under 10CFR2 206 on A & E Coloman petition requesting that Commission issue show cause order re-facilities OL & CP issuances
 DENTO(I) H R Office of Nuclear Reactor Regulation 80/04/18 2pp
- --8004300600 "Assessment of Impacts of Facilities on Shortnose Sturgeon, Acipenser Brevirostrum Lesuer"
 MASNIK, M T , WILSON, J H Urrice of Nuclear Reactor Regulation
 80/03/31 1p

- B004030123 Responds to 790816. Itr re plans to reopen THI-1.nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from THI DENTON. HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restart of TMI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety
 FOSTER.K. Affiliation Unknown /9/08/16 2pp
- ${\sf P}$ Operating license stage documents ${\sf A}$ correspondence
- 8004230338 Confirms 800417 discussion w/DF Ross re util safety review group commitment to report to general manager of licensing & environ within engineering & const dept Commitment refers only to low power test program & does not preclude mads ECKERT.R M Public Service Electric & Gas Co of New Jersey 80/04/18 1p
- 8004250366 Responds to 800107 Itr re OA requirements for diesel fuel oil Fuel is supplied from day tanks which are fed from 20,000 gallon storage tanks Lists Tech Spoc requirements re surveillance of fuel LIBRIZZI,F P Public Service Electric & Oas Co of New Jersey 80/04/21 | 1p
- G. Inspection reports. IE Bulletins & correspondence
- 8004080318 Submits response to 1E Bulletin 79-27 re loss of instrument control power & effect an ability to achieve cold shutdown Failure analysis on circuit-bey-circuit basis to check bus loads & alarms 40% complete Submittal by 801001
 SCHNEIDER.F W Public Service Electric & Gas Co of New Jersey 80702726. 2pp
- 8004170288 Forwards IE Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 No noncomptiance noted BRUNNER.E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004170293 IE Insp Repts 50-272//9-32 & 50-311/79-37 on 791118-1215 No noncompliance noted Major areas inspected plant operations, including tours of facility.log & record review.review of licensee events.IE circulars & bulletins & followup items KEIMIG.R R Region i. Philadelphia. Reactor Operations Nuclear Support Branch JOHNSON,D F. NORHOLM.J Region i. Philadelphia, Gffice of the Director 60/02/20 20pp
- 8004220416 Forwards 1E Insp Repts 50-272/79-32 & 50-311/79-37 on 791118-1215 & 800109 GRIER, B H Region I. Philadelphia. Office of the Director 80/02/26 | 2pp

- --8004220429 IF Insp. Repts 50-372//9-32 % 50-311/79-37 on 791118-1215 % 800109 Noncompliance nuted unauthorized individual approved tagging request wie knowledge of responsible shift supervisor KEIMIG.D.F. JOHNSON.D.F. Region 1. Philadelphia, Reactor Operations Nuclear Eupport Branch MORRHOLM.L.J. Region 1. Philadelphia, Office of the Director 80/02/20 21pp
- 8004240494 Responds to IE Suiletin ED-03 Interim findings of visual
- 104240494 Responds to 16 Suitetin Bo-od interin Findings or inspiridists adsorber cells are adequate wifew exceptions. Investigation & evaluation are continuing Final rept expected by 800321
 SCHNEIDER F W Public Service Electric & Gas Co. of New J. 80/03/19
 3pp Public Service Electric 5 Gas Co. of New Jersey.
- 8004010447 Forwards response to [£ Bulletin 79-06C, "Nuclear Incident at Thi-Suppi ' Analyses re inadequate core cooling uill be performed MITTL,R L Public Service Electric & Gas Co of New Jersey 80/03/28 1p
- 6004150299 Forwards IE Info Notice 80-12, 'Instrument Failure Causes Opening of PORV > Block Valve " No specific action or response necessary ORIER B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090099 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia. Office of the Director 80/04/01 ip
- 8004110507 Forwards IE Into Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER. B H Region I, Philadelphia, Office of the Director 80/04/02 ip
- 8004240346 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/02 1p
- 8004180196 Forwards IE Circulai 80-07, "Problems W/MPCI Turbine Oil Sys "No written response required Office of the Director 80/04/03 ip
- B004230455 Forwards IF Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/44/04 ip
- 8004180276 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/07 1p

S. Reportable occurrences, LERs & related correspondence

- 8004220084 PNU-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior math Cause unstated All utils w/pumps were notified NRC headquarters notified an 770612 HMITT, K.W. Region 2, Atlanta, Office of the Director 77/08/12
- 8004100611 Ack receipt of final deficiency rept re design defect in auxiliary feedwater storage tank water makeup CARLBONR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/03/12 (p
- --8004100613 Final deficiency sept check valve 2DR-7 failed to meet applicable seismic Class E loading Caused by design defect Add support will be completed by 800228 MARTIN.T J. Public Service Electric & Gas Co. of New Jersey 80/02/15

V Operator Examinations

BO04030257 Provides add1 info per B00125 request Operator licensed for one unit of two-unit facility must take oral t written examination when applying for ficense on second unit Applicant must score min 80% overall to receive license COLLINS.P F Operator Licensing Branch 80/03/20 2pp

- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION F Security, medical, emergency 5 tire protection plans
- 8004150177 Approves 80030/ revised cable tray firestop design for usp inside containment Revision makes minor changes to design approved 791214 Mods will not affect performance of firestop in preventing propagation of rire REID.R U Operating Reactors Branch 4 80/03/13 3pp
- 8004170209 Forwards results of NRC 800310 site visit to review status of emergency planning at facility REID.R N Operating Reactors Branch 4 80/04/02 6pp
- 8004280528 Responds to NRC 800327 request to incorporate vital area analysis results into physical security plan Amend 7 to security plan. submitted 79128 includes analysis results Requests verification of receipt of all five copies MATTIMOE. J J Secremento Municipal Utility District 80/04/21

G Adjudicatory correspondence

- 8004090187 Order granting extension of time until 800319 for NRC to file briefs
 DEANE,R H U S Court of Appeals 9th Circuit FREEMAN,K D
 California, State of 80/02/21 1p
- B004110074 Apologizes for not giving testimony at Sacramento hearings due to prior commitments Mods should incorporate state-of-the-art in safety of design & uperation HAMMER, T. J. Affiliation Unknown B0/03/10 2pp
- BO040B0705 Forwards licenses testimony by RA Dieterich in response to CA Energy Commission Issue 5-2 W/o encl BAXTER.T A Shaw, Pittman, Potts & Trowbridge 80/03/11 1p
- 8004020454 Forwards Commission 800306 order to Met Ed mgt compotence issues which may be relevant to proceeding LEWIS, S.H. Hearing Branch 2 80/03/17 1p
- 8004030329 Forwards ACRS 800311 ltr re Bulletins & Orders Task Force recommendations, which may be relevant to proceeding LEWIS, S R Hearing Branch 2 80/03/20 lp
- ~~8004030333 Comments on Bulletins & Orders Task Force recommendations 45 result of 800306-08 ACRS 239th meeting Action plan review Underway PLESSET M S ACRS - Advisory Committee on Reactor Bafeguards
- BOO4010272 Forwards list of NRC admitted testimony which should be found following Transcript 1163 Requests that list be inserted in record of BOO40B session
 LEWIS,6 H Hearing Branch 2 80/03/24 2pp
- 8004010382 Requests that itr 2 encl newspaper article be included in 800312 hearing record Protests misleading testimony of util englineer Requests Emergency Preparedness Review team rept 198ER.H W Affiltation Unknown 80/03/25 2pp
- 8004080362 Forwards technical documents in response to ASLB request to be informed of 800226 incident analyses & implications NURCO-0667 re 85W apparent designed plant sensitivity will be transmitted when final LEWIS.8 H Hearing Branch 2 80/03/25 2pp
- BOO4080414 Forwards INPO-NASC "Analysis & Evaluation of Crystal River Unit 3 Incident," as followup to 800325 ltr Forwards NUREQ-O454.Vol 1 "Rept of Bulletins & Orders Task Force," for info to ASLB % parties W/o encl LEWIS.5 H Hearing Branch & 80/03/26 ip
- 8004080329 Forwards NUREC-0645, Vol II, to ASLB & parties per Cole & Shon requests W/o encl LEWIS, S H Hearing Branch 2 80/03/27 ip
- 8004230090 Forwards Commission 800321 mamorandum & order reconsideration of Class 9 accidents beyond design basis in Black Fox Station proceeding BAXTER.T A Shaw. Pittman. Potts & Trowbridge 80/03/27 2pp
- 8004080322 Responds to CA Energy Commission 800321 request of B Mann for certain documents Crystal River event documents were provided in 800325 t 26 transmittals Mr Wing studies are in planning stage Task B-24 documents encl W/o encl LEWIS.S H Hearing Branch 2 80/03/28 2pp

- 8004170109 Forwards notice of violation notice of proposed imposition of civil penalties b order modifying license re operation of plant w/portions of ECCS in degraded conditions resulting from personnel errors in implementing operating procedures STELLO, V Office of Inspection b Enforcement. Office of the Director 80/04/01 2pp
- --8004170115 Notice of violation from insp in Feb 1980 of Licence DPR-54 Noncompliance noted two valves in HPI cross-connect line closed & reactor critical w/only one HPI pump operable contrary to Tech Specs

 ** Office of Inspection & Enforcement, Office of the Director 80/04/01 300
- ---8004170121 Notice of proposed imposition of civil penalties Util should pay civil penalties or protest by written answer within 20 days

 * Office of Inspection & Enforcement, Office of the Director 80/04/01 in
- --8004170129 Order modifying Licence DPR-54 to include & implement administrative procedures requiring independent verification of valving line-ups & equipment operability when safety-related equipment is removed or placed into svc STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/01 Spp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification of Stick, L V Office of the Exocutive Director for Operations 80/04/02 34pp
- GOD4110142 Forwards NRC testimony of HL Canter re SMVD competency to operate facility Supplements NRC testimony of AD Johnson & OB Zuetrig on Friends of the Earth Contention III(d) & ASLU Guestion 32
 DLACK.R L Hearing Branch 1 BO/04/02 2pp
- ---8004110151 NRC testimony of HL Canter re SMUD competency to operate facility Supplements NRC testimony of AD Johnson & GB Zwetig on Friends of the Earth Contention III(d) & ASLB Question 32 Prof qualifications encl CANTER.H L Region 5, San Francisco, Office of the Director 80/04/02 10pp
- BOO41404B2 Forwards Apr 1980 "Transient Response of B&W Designed Reactors," Graft NUREO-0667 NRC witnesses will be able to address rept during BOO40B testimony & examination W/o encl RLACK.R L. Hearing Branch 1 BO/04/03 2pp

- 7906290854 Responds to 790411 ltr on reactor sefety, clarifying concerns re Davis-Bosse shutdown & geologic faults near Diable Canyon EIBERHYT, D © Division of Operating Reactors 79/05/22 2pp
- 8004030263 Expresses confidence in util mgt expertise, public constigusmess & sonse of accountability Supports continued operation of plant FLYNN,P Affiliation Unknown 80/02/27 1p
- 8004140122 Responds to 791227 itr by forwarding PA Emergency Mgt Agency booklet, "What You Should Know About Nuclear Incidents" Specific Info may be obtained from Sacramento County Ofc of Emergency Svcs President Carter 791207 statement encl DENTON, H R Office of Nuclear Reactor Regulation B0/03/03 13pp
- 8004040001 Requests nuclear development to provide for agricultural future demands in addition to development of all energy sources if proven not detrimental to environ Sites facility as model nuclear plant Supports continued operation WILCOX.L. Affiliation Unknown 80/03/07 1p
- 8004030012 Demands immediate shutdown of plant, before realities of nuclear accident become reality in CA 8CHASER, H. SCHWEID, S., KLEIN, B. Affiliation Unknown 80/03/15 3pp
- P Operating license stage documents & correspondence
- 7905190134 Forwards revised radiological effluent Tech Specs which include requirements of NUREG-0472
 MATTIMOE, J J Bacramento Municipal Utility District 79/05/15 ip
- --7905190137 Revised radiological effluent Tech Specs including cold & hot shutdown & protection instrumentation logic
 * Sacramento Municipal Utility District 79/05/30 300pp

- 8004040005 Furwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 to 800206 reactor trip at Crystal River Sequence of events 5 planned corrective actions also encl
 DENTON. HR Office of Nuclear Reactor Regulation 80/03/06 26pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit into From plants to Bethesda Operations Ctr EISENHUT.D © Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- 8004030230 Natification of 800318 meseting w/all operating BEW reactor licensees in Bethesda/Mb to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Branch 4 80/03/14 2pp
- 8004080677 Notification of 800327 meeting w/B&W.DDE & util in Bethesda, MD to discuss lead test assemblies using U mill tailings SANDS, S P Reactor Safety Branch B0/03/19 2pp
- 8004020449 Discusses hydraulic snubber surveillance performed during 1980 refueling outage Testing of Grinnel snubbers not needed during followon tests Rebuilding by tosting of failed snubbers fulfilled Tech Specs requirements
 REID.R N Operating Reactors Branch 4 80/03/19 3pp
- 8004100115 Forwards results of NRC-sponsored vital area analysis for util for info & action Requests notification of revisions within 30 days of receipt of ltr Encl withheld (ref 10CFR2 790)
 REID.R W Operating Reactors Branch 4 80/03/27 3pp
- 8004100241 Forwards Amend 29 to License DPR-54, safety evaluation & notice of issuance & availability
 REID,R W Operating Reactors Branch 4 80/03/31 3pp
- --8004100246 Amend 29.to License DPR-54.terminating ECCS exemption to 10CFR50 46 for fuel loading used during Cycle 4 REID.R W Operating Reactors Branch 4 80/03/31 27pp
- --8004100251 Safety evaluation supporting Amend 29 to License DPR-54 * Office of Nuclear Reactor Regulation 80/03/31 13pp
- ---8004100255 Notice of issuance & availability of Amend 29, to License DPR-54 REID,R W Operating Reactors Branch 4 80/03/31 2pp
- 8004210328 Summary of 800222 meeting w/B&W owners group in Bethesda, Md re abnormal transient operational guidelines BE10EL.B.L. Reactor Systems Branch 80/04/02 4pp
- 8004250368 Summary of B00403 meeting w/utils,85W,NUS Corp & McGraw-Hall in Bethesda,MD re draft NUREG-0667, "Transient Response of B&W-Designed Reactors" CAPRA,R A Standardization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 meeting w/utils & B&W in Bethesda,MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA,R A Stendardization Branch 80/04/05 Ppp
- B004180439 Responds to NRC request for info to suppl 791017 response to NRC re-grid voltage degradation Info will be submitted by 800428
 MATTIMOE, J. J. Gacramento Municipal Utility District B0/04/08 1p
- 8004160234 Submits add1 info requested by NURCC-0578 postimplementation review team re Category A & B items MATTIMOS,J J Sacramento Municipal Utility District 80/04/19
- 8004210314 Notifies of fulfillment of conditions stipulated in order for mod of license which required license to adopt & implement administrative procedures for independent verification of valving lineups & equipment operability MATTIMOE, J J Sacramento Municipal Utility District 80/04/14
- 8004220568 Withdraws 800308 commitment concerning Part B. Item 9 of NRC 800226 ltr re proposed mod of auxiliary feedwater sys Operating Procedure A 51 Approval would imply plant could be safely shutdown w/o offsite power or diesel generators MATIMOE. J Sacramento Municipal Utility District 80/04/14 2pp

- 9004220709 Recommends that removal of ref to 3 2 weight percent re U=235 be incorporated into next reload subnittal MATTIKOE, J. J. Sacramento Municipal Utility District 80/04/14 ip
- 8001230498 Revises 600107 response to NUMEG-0578 Category A. Item 2 2 2 b.onsite technical support ctrice interim communications operations described the description of the description
- 800429033B Forwards Revision 1 to inservice testing program Submits program changes & request for relief MATTIMOE.J J. Sacramento Municipal Utilisty District. 80/04/17
- -8004290524 Revision 1 to intervice testing program re ASME code class valve testing requirements * Sacramento Nunicipa) Utility District 80/04/17 lipp
- G inspection reports, IF Bulletins / correspondence
- 8004040054 Forwards 16 Insp Rept 50-312/79-29 on 791213 No Noncompliance noted BOOK, M E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004040055 lE lnsp Rept 50-312/79-29 on 791213 No noncompliance noted Major areas inspected one shipment of low level radwaste for disposal BOOK.H E . PECK.C C Region 5. San Francisco. Fuel Facility & Materials Safety Branch THOMAS.R D Region 5. San Francisco. Materials Safety Branch THOMAS.R D Office of the Director 80/02/21 4рр
- G004280168 Forwards IE Insp Rept 50-312/80-05 on 800130-0201,12-15 & 17-18 No noncompliance noted SPENCER: Q 5 Region 5, San Francisco. Reactor Construction & Engineering Support Branch B0/03/04 2pp
- --8004280180 lE Insp Rept 50-312/80-09 on 800130-0201,12-15 & 17-18 No OURGOURD IE INSPIREDT SUPSIZIONS ON BUOISUNGEDI, 12-15 & 1/-16 No noncompliance noted Major areas inspected licensee activaties performed for inservice inspired for 1980 BODDS.R T Region 3. San Prancisco. Reactor Construction & Engineering Support Branch NARBUT, PP Region 5. San Francisco. Office of the Director 80/03/03 7pp
- 8004210226 Forwards IE Insp Rept 50-312/80-01 on 800117-26 No CREMS.J L Region 5. Ban Francisco, Reactor Operations Nuclear Support Branch 80/03/10 2pp
- ~-8004210229 IE Insp Rept 50~3[2/60~6] on B00117-26 No noncompliance noted Major areas inspected progress in completion of required fire protection mods, major maint & surveillance performed during refueling outage FAULARNECRRY. B Region 5. San Francisco, Reactor Operations Nuclear Support Bianch Z(METZIG, G B Region 5, San Francisco, Office of the Director 800/03/07 4pp
- 8004040126 Att receipt of 800227 ltr informing NRC of steps taken to correct violations noted in 1E Insp Pept 50-312/79-17 SPENCER: G S Region 3. San Francisco, Reactor Construction & Engineering Support Branch 80/03/17 ip
- --8004040139 Responds to NRC 800201 ltr re violations noted in IE Insp Rept 50-312/79-17 Corrective actions revisions in Procedure MT 017 were approved 800202 2 insp data has been reviewed according to revised acceptance criteria HALBRIDGE, W C Bacramento Municipal Utility District 80/02/27
- --8004040146 Forwards IE Insp Rept 50-312/79-17 on 790724-25,0801-02,20, 27, \$ 800110-11 \$ notice of violation SPENCER.G S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/02/01 2pp
- --8004Q40151 Notice of violation from ansp on 790724-25,0801-02,20,27 & Region 5. San Francisco, Office of the Director 80/01/31 ip
- --8004040i61 IE Insp Rept 50-312/79-17 on 770724-25.0801-02.20.27 & 8001i0-ii Noncompliance noted failure to fill in acceptance criteria columns on data sheets for insp of concrete fasteners DDDDS, R 7 Region 5, San Francisco, Reactor Construction & Engineering Support Branch NARBUT, P D . HAIST, D P Region 5, Francisco, Office of the Director 80/01/31 9pp Region 5, San

- 8004210422 Forwards 1E Insp Rept 50-312/80-08 on 800304-05 No Agentials roughly to the control of the control of
- --8004216428 IE Insp Rept 50-312780-08 on 800304-05 No noncompliance Deployed le insp Rept 30-312/2008 on MUDJU4-03 No noncompliance noted Hajor areas inspected activities performed in response to If Bulletin 79 02, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts "DODDS: AT Region 5, San Francisco, Reactor Construction & Engineering Support Blanch NARBUT, P.P. Region 5, San Francisco, Office of the Director 90/03/20 Spp
- 8004210231 Ack receipt or 800312 itr informing NRC of steps taken to correct violations noted in IC limp Rept 50-312/80-02 BODM, H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch 80/03/25 ip
- --8004210237 Responds to NRC 800221 ltr re violations noted in IE Imp Rept 50-312/80-02 Corrective actions Maint Procedure M-112 revised to require two insps, cleanings & completion of checklist of items per week MALBRIDGE, W.C. Sacramento Municipal Utility District 80/03/12
- ~8004210241 Forwards IC Insp Rept 50-312/80-02 on 800121-25 & notice of violation BBODK-HE Region 5, San Francisco, Fuel Fecility & Materials Safety Branch 80/02/21 App
- --8004210243 Notice of violation from insp on 800121-25 * Region 5, San Flancisco, Office of the Director 80/02/20
- ---800421024B IE Insp Rept 50-312/80-02 on 800121-25 Noncompliance noted total chlorine concentration in plant effluent exceeded limit BODK,H E. Rogion 5, San Francisco, Fuel Facility & Materials Safety Branch FISH,R F. Region 5, San Francisco, Office of the Director 80/02/20 12pp
- 8004280214 Forwards IE Insp Rept 50-312/80-04 on 800212-15.28-29 & 0303-07 No noncompliance noted CREMS, J Region 5, 8an Francisco, Reactor Operations Nuclear Support Branch ZWETZIG, 0 B Region 5, San Francisco, Office of the 60/03/59
- ~~E004280226 IE Insp Rept 50-312/80-04 on 800212-15, 28-29 & 0303-07 No noncompliance noted Major areas inspected status of completion of selected fire protection mods, completion of required mods 5 maint during refueling outage FAULKENBERRY, 8 Region 5, San Francisco, Reactor Operations Nuclear Support Branch ZUETIG. 0 B Region 5, Ban Francisco, Office of the Director 800/03/25 Sap
- 8004150218 Forwards IC lnfo Notice 80-12, "Instrument Failure Causes Opening of FORV & Block Valvo " No specific action or response necessary ENGELKER,R H Region 5, San Francisco, Office of the Director GO/03/31 1p
- 8004100108 Forwards 1C Circular 80-05, "Emergency Diasel Generator Lubricating Dil Addition & Ondito Supply " No written response required ENDELMEN.A H Region D. San Francisco, Office of the Director 80/04/01 jp 80/04/01
- 8004110115 Forwards IE Info Notice 80-13, "GE Type 8DM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN,R H Rogion 5, San Francisco, Office of the Director 80/04/02
- 8004220050 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN.R II Region 5, Ban Francisco, Office of the Director 80/04/02 ip
- 8004180195 Forwards IE Circular B0-07. "Problems W/HPCI Turbine Dil Sys " No written response required ENGELKEN,R HE Region S. San Francisco. Office of the Director 80/94/03 ip
- 8004230360 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ABME 8A-312. Type 304 Stainless Steel Pipe" Action required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/04/04 10
- BOO43004R5 Ack receipt of BOO319 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/80-03 CREMSIJ L Region 5. San Francisco, Reactor Operations Nuclear Support Branch BO/04/04 ip

- --8004300433 Responds to NRC ltr re violations noted in IE Insp Rept 50-312/80-03 Corrective actions appropriate individuals have been made cognitant of prompt reporting requirements MATTIKOE. J J Sacramento Municipal Utility District 80/03/19 2pp
- --B004300437 Forwards IE Insp Rept 50-312/80-03 on B00102-31 & notice of violation CREW5,J L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch B0/02/28 2pp
- ---8004300440 Notice of violation from insp on 800102-31

 * Region 5: San Francisco, Office of the Director 80/02/26 1
- --8004300453 IE Insp Rept 50-312/80-03 on 800102-31 Noncompliance noted RO not reported at proper time CANTER,H L. O'BRIEN,J P Region 5, San Francisco, Office of the Director FAULKENBERRY Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/02/26 12pp
- 8004220190 Forwards IE Bulletin BO-OB, "Exam of Containment Liner Penetration Welds " Written response required ENGELKED, R H Region 5. Sam Francisco, Office of the Director BO/04/07 ip
- R Periodic operating reports & related correspondence
- 8004i60266 Forwards monthly operating rept for Mar 1980 RODRIGUEZ,R J Sacramento Municipal Utility District 80/04/03 ip
- --B004i60270 Monthly operating rept for Har 1980 CDLOMBO.R W Sacramento Municipal Utility District B0/03/31 Boo
- B Reportable occurrences, LERs & related correspondence
- BOD4070312 Forwards LER BO-015/017-0 MATTIMUE, J. J. Bacramento Municipal Utility District 80/03/25 200
- --B004070316 LER 80-015/01T-0 on B00312, during visual insp of cycle 3 discharge fuel, approx 4 inches of cladding discovered missing from fuel assembly 1C47 Caused by cladding defect on one pin Insignificant amounts of fuel dispersed COLOMBO, R W Bacramento Municipal Utility District 80/03/25
- BD04140397 Forwards LER 80-016/03L-0 MATTIMOE, J J Sacramento Municipal Utility District 80/04/03
- --8004140405 LER 80-016/03L-0 on 800310, while performing IE Sulletin 79-14 requirements, seismic analysis of supports 18-50052-1A, 18-50052-1A & 18-23626-1 indicated seismic stress would exceed allowable I limit Supports modified COLOMBO, R W Escramento Municipal Utility District 80/04/03 in
- 8004210259 Forwards LER 80-017/03L-0 MATTIMOE, J J Sacramente Municipal Utility District B0/04/10 2pp
- ---8004210262 LER 80-017/03L-0 on 800322, after manually opening SFV-25003 several turns to increase level in pressurizer valve failed to close electrically Caused by excessive wear to shaft clutch & clutch goar Defective parts replaced CDL OMBD.R W Sacramento Municipal Utility District 80/04/10 ip
- 8004270485 Forwards LER 80-018/03L-0 MATTIMOE.J J Sacramento Municipal Utility District 80/04/11 ip
- --9004290491 LER 80-018/03L-0 on 800324, pressurizer gas sample valve. SFY-72502 failed to close Caused by wire separation in valve control circuitry Wire reconnected to terminal lug COLOMBO, R W Sacramento Municipal Utility District 80/04/11
- 8004220731 RO 80-23 on 800414, manager of nuclear operations was informed of receipt of Dresser Industries notification ltr implying that no representation will be provided concerning valve reliability & operation Cause unstated RODRIGUEZ, R J Sacramento Municipal Utility District 80/04/15 is

- 8004290454 Forwards LER 80-021/047-0 MATTIMOE, J. J. Sacramento Municipal Utility District 80/04/21 200
- --B004290465 LER 80-021/01T-0 on 800318, review of previous month plant effluent records indicated that effluent pH exceeded 8.5 for approx 3-h Caused by canal pumping station being out of svc for approx two months COLDMBO.R W Sacramento Municipal Utility District 80/04/21 to
- B004300421 Advises that RO B0-20 in B00417 ltr incorrectly identified NAMCO switches on safety-related valves as functional during accidents Switches utilized only for light indication RO 80-20 will be deloted from LER file MATTIMOE, J.J. Sacramento Municipal Utility District 80/04/23 ip
- T Hearing transcripts on non-antitiust matters
- 8004090257 NRC testimony re ASLB question concerning CA Energy Commission Contention 1-2 on natural circulation if reactor coolant pumps trip as result of math feedwater loss, core can be adequately cooled by natural circulation NDRIAN.P E Analysis Branch 80/03/01 8pp
- 9004100542 Testimony of D Nix,CA Energy Commission,re controlled filtered venting NIX.D California, State of GO/03/11 23pp
- 8004240457 Transcript of 800408 evidentiary hearing in Sacramento.CA Pp 1210-1375 * Atomic Safety and Licensing Board Panel 80/04/08 166pp
- 8004220774 Transcript of 800410 meeting in Sacramento, CA Pp 1569-1793 * Atomic Safety and Licensing Board Panel 80/04/10 224pp
- 8004220407 Transcript of 800411 meeting in Sacraments CA Pp 1794-1984 * Atomic Safety and Licensing Board Panel 80/04/11 190pp
- 8004250237 Transcript of 800414 meeting in Sacramento,CA Pp 1985-2159 * Atomic Safety and Licensing Board Panel 80/04/14 174pp
- 8004250245 Transcript of 800416 hearing in Sacramento, CA Pp 2344-2562 * Atomic Safety and Licensing Board Panel 80/04/16 210pp
- 8004250241 Transcript of 800417 hearing in Sacramento, CA Pp 2963-2796 * Atomic Safety and Licensing Board Panel 80/04/17 234pp
- DOCKET 50-313 ARKANSAS NUCLEAR ORF. UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004010386 Advises that all fire protection mods will be complete by 801001 except Unit 2 Items 3 i4 & 3 i8 Hardware mods for Item 3 i8 scheduled for Har 1981 cold shutdown Smoke detector sys for Item 3 i4 will be installed when complete TRIMBLE, D C Arkansas Power & Light Co 80/03/26 2pp
- 8004220427 Submits info re mod performed on reactor coolant pumps, fire protection Item 3 15 Seventeen photographs encl Drawings available in Central Files only TRIMBLE.D C Arkansas Power & Light Co 80/04/16 2pp
- --8004220431 "Motor Assembly " List of components encl # Allis-Chalmers Corp 70/12/30 7pp
- --8004220434 "9000 Horsepower Reactor Coolant Pump Motor Outline "
 * Allis-Chalmers Corp 70/09/02 19
- --8004220440 "Migh Pressure Dil Lift Sys Picture " Sheet 1 List of components encl * Allis-Chalmers Corp 70/03/12 5pp
- --8004220447 "Circulating Oil Sys Picture " Sheet 1 List of components enc! # Allis-Chalmers Corp 70/03/04 4pp
- ---8004220450 "Backstop Lubrication Sys Picture " Sheet 1 List of components enc! + Allis-Chalmers Corp 70/08/03 4pp
- --8004220453 "Lower Bearing Oil Piping Picture" List of components encl * Allis-Chalmers Corp 69/11/24 3pp

- --8004220454 'Upper Bearing Oil Piping Picture " List of components encl * Allis-Chalmers Corp 69/41/24 200
- --8004220455 "Piping 3 Instrumentation Diagram Control Rod Drives & Miscellaneous Coolant Pump Connections "
 4 Bechtel Corp 6600 79/10/25 1p
- H General correspondence
- 8004170240 Requests that util be required to submit EIS before authority is granted to expand nuclear waste fuel storage pools at site Prior EIS insurficient PETERS.B. Arialiation Unknown 80/04/09 2pp
- I Financial information
- 8004220535 Annual Financial Rept 1979 # Middle South Utilities, Inc. 79/12/31 40pp
- 6004150235 Forwards Abnual Financial Rept 1979
 TRIMBLE: D.C. Arkansas Power / Light Co. 60/04/10 1p
- --B004150239 Annual Financial Rept 1979 * Arkansas Power / Light Co 80/04/10 46pp
- P Operating license stage documents & correspondence
- 8004110508 Summarizes walkdown to identifying seismic Category [piping & safety-related sys attached to or in close proximity to concrete block walls Numbers are preliminary & may be adjusted upon survey completion on 800101

 TRIMBLE,D C Arianses Power & Light Co 80/01/28 ip
- 8004070160 Forwards NRC evaluation of actions taken to satisfy Category A requirements of TMI-2 Lessons Learned All Category A requirements have been met satisfactorily w/exception of Item 2 1 7a for Unit 2 REID.R W Operating Reactors Branch 4 80/03/10 2pp
- --8004070165 "Evaluation of Licensee Compliance W/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned" Operating Reactors Branch 4 80/03/31 14pp
- --8004070170 "Evaluation of Licensee Compliance H/Category A Items of NRC Recommendations Resulting from THI-2 Lessons Learned " + Operating Reactors Branch 4 80/03/31 13pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISEN-UT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/2: 28pp
 - ification of 800318 meeeting w/all operating B&W reactor BethesdarMD to evaluate implications of Crystal event & response to IE Bulletin 79-27 ing Reactors Branch 4 80/03/14 2gp
- non-cool responds to NRC 800225 generic questions re Hestinghouse low pressure turbine rotors Actions necessary to minimize stress corresson cracking will not be known until Hestinghouse identifies causes of cracking TRIMBLE.D.C. Arkansas Power & Light Co. 80/03/24 ip
- 8004ii0559 Provides add1 info re implementation of requirements set forth in Item 2 i 7a of NUREO-0578 Commitment to install safety-grade sys prior to Bioloi required no later than 15 days after receipt of itr EISENHUT.D 0 Division of Operating Reactors 80/03/27 2pp
- 8004030209 Provides descriptions of long-term Lessons Learned changes to plant shielding & modified sampling sys to minimize personnel esposure during worst case accident conditions TRIMBLE, D C Arkansas Power & Light CO 80/03/31 7pp

- 8004070287 Forwards proposed change to Paragraph 15 2 2 constituting Revision 5 to APL-TOP-1A. "GA Manual Nonconforming Matl. Parts or Components "TRIMBLE D C Artansas Power / Light Co 80/03/31 1p
- --B004070403 Proposed change to Paragraph 15 2 2 of "GA Manual, Nonconforming Mati. Parts of Components" * Arkansas Power % Light Co ALP-TOP-1A 80/03/31 2pp
- 8004150304 Forwards brief description of safety evaluation for design changes completed in 1979 which require safety evaluation per 10CFR50 59 Mods include emergency cooling pond change, firehouse station addition b increase of sprinkler coverage TRIMBLE, D.C. Arkansas Power & Light CO. 80/03/31 Spp
- 8004170086 Forwards description of safety evaluation for design changes completed in 1979
 TRIMBLE.D C Arkansas Power & Light Co 80/03/31 6pp
- 8004240506 Requests add1 into re once-through steam generator auxiliary reeduater thermal sleeve/collar weld attachments Cracking reported at weld attachment between collar & thermal sleeve HADSEN, & L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/04/01 2pp
- --80042405[1 Advises that BBW prepared & transmitted to affected utils info re failure discovered at weld attachment between collar & thermal sleeve on auxiliary feedwater nozzles of steam generator NRC should contact utils for info TAYLOR, J & Babcock & Wilcox Co 80/03/17 ip
- 8004210328 Summary of 800222 meeting w/BAW owners group in Bethesda. Hd te abnormal transpent operational guidelines SEIOEL.B L. Reactor Systems Branch 80/04/02 4pp
- 8004070344 Informs that Section 2 & 3, Revision 5 of QA manual re disial generator fuel oil meets Tech Spec requirements per 800107 request. roquest TRIMBLE.D C Attansas Power & Light Co 80/04/03 ip
- 8004220788 Requests Class III fee re 800115 reactor vessel surveillance program Payment should be remitted within 15 days after receipt of ltr License Fee Management Branch 80/04/04 is
- 8004250368 Summary of 800403 meeting w/utils,8&W.NUS Corp & McGraw-Hill in Bethosda.MD re draft NUREG-0667. "Transient Response of BAW-Designed Reactors " CAPRA.R A Standardication Branch 80/04/04 7pp
- ROOA180490 Notification of 800423 meeting w/utils & N&W in Bethesda.MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA.R A Standardization Branch 80/04/05 2pp
- 8004160185 Forwards Class III fee for review of 800115 reactor vessel surveillance program, por NRC 800213 & 0404 ltrs
 TRIMBLE, D.C. Arkansas Power & Light Co. 80/04/11 2pp
- 8004210148 Supplements 800f18 itr re Lessons Learned Task Force implementation of RCS venting Util will install remotely operated reactor vessel head vent provided acceptable vent location can be found TRIMBLE.D C Arkansas Power & Light Co 80/04/11 ip
- 9004290137 Forwards safety evaluation of inservice testing program & relief request WANG:A Plant Systems Branch 80/04/11 ip
- --8004290138 Safety evaluation of inservice testing program Util should be granted relief from ASME Section XI requirements. * Plant Systems Branch 80/04/11 17pp
- 8004220471 Provides clarification re test to show effects of various 104220471 Provides clarification re test to show effects or visingle power failures Subsequent to power supply upgrade, test will be performed to verify non-nuclear instrumentation sys design & power supply design mod TRIMBLE, D.C. Arkansas Power & Light Co. 80/04/16 1p
- 8004290517 Forwards safety sequence diagrams, event trees developed from safety sequence diagrams & auxiliary diagrams on behalf of B&W owners group, in response to NRC 800222 request Diagrams withheld (ref 10CFR2 790)
 TAYLOR, J H Babcock & Wilcox Co 80/04/16 2pp

- 8004240380 Advises that 800416 commitment to perform tests to show various single power failures for NNI-X & NNI-Y cabinets have been changed fer conversations w/G Vissing, test will be performed involving 120 VAC transfer switch power loss RUETER.D A Arkansas Power & Light Co 80/04/18 App
- B004290244 Responds to 800327 ltr concerning Lessons Learned Task Force implementation re automatic initiation of emergency feedwater Specifics of proposed design are still under evaluation NUREG-0667 requirements may need incorporation TRIMBLE.D C Arkansas Power & Light Co 80/04/23 1p
- Q Inspection reports, IE Bulletins & correspondence
- B004090191 Forwards 1E Insp Repts 50-313/80-01 & 50-368/80-01 on B00107-18 & notice of violation MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 60/02/01 2pg
- --8004090153 Notice of violation from insp on 800107-18
 * Region 4, Dallas, Office of the Director 80/02/01 2pp
- --8004070159 IE Insp Repts 50-313/80-01 & 50-368/80-01 on 800107-18
 Noncompliance noted data sheets recorded relay setting only
 & did not contain sufficient info & calibr & testing program
 for protective relaying was deficient in procedures
 SPANDLER.R O , SMITH.R , WESTERMAN, T F Region 4, Dallas, Office
 of the Director 80/02/01 App
- 8004100315 Forwards IE Insp Repts 50-313/80-02 & 50-368/80-02 on 791222-800121 & notice of violation MADSEN.O L. NRC Regional Offices 80/02/08 2pp
- --g004100324 Notice of violation from insp on 791222-800121 * NRC Regional Offices 80/02/06 ip
- --BD04100335 IE Insp Repts 90-313/80-02 & 50-368/80-02 on 791222-800121 Noncompliance noted failure to adhere to requirements of test procedure JCHNSON, W D , CALLAN, L J , WESTERMAN, T F NRC Regional Offices BD/02/04
- 8004250044 Confirms 800131 telcon re status of structural analysis of concrete block walls supporting Beismic Category 1 pipe hangers per IE Bullotin 79-02 Analysis shows five hangers are structurally adequate for inertia forces thanger load TRIMBLE, D C Arkansas Power & Light Co 80/02/12 3pp
- 8004040087 Forwards IC Insp Repts 50-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted MADSEN,0 L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --B004040094 IE Insp Repts 30-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted Major areas inspected current NRC & DOT regulations, current requirements of waste burial firms, instructions & operating procedures & audit program HARRISON, H C Region 4. Dallas, Office of the Director BROWN, O D Region 4. Dallas, Fuel Facility & Materials Safety Branch GO/01/16 4pp
- 8004090143 Ack receipt of 800222 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-313/80-01 & 50-348/80-01.

 HADBEN, O.L. Region 4. Dailas, Reactor Operations Nuclear Support Branch 80/03/05 ip
- --800407014B Responds to NRC ltr re violations noted in IE Insp Repts SQ-313/80-01 & 50-368/80-01 Corrective actions comprehensive program under development for scheduling & performance of relay insp & testing Program will be completed by Nov 1980 TRIMBLE, D C Arkansas Power & Light Co 80/02/22 3pp
- 8004250293 Forwards IE Insp Repts 50-313/80-04 & 50-368/80-04 on 800131 & 0201 No noncompliance noted BROWN.0 D Region 4. Dallas. Fuel Facility & Materials Bafety Branch. 80/03/17 2pp
- ---8004250297 IE Insp Repts 50-313/80-04 & 50-368/80-04 on 800131 & 0201
 No nuncompliance noted Major areas inspected practices of
 licensee health physics personnel & maint contracted
 personnel
 BROWN.0 D Region 4, Dallas, Fuel Facility & Materials Safety
 Branch WESTERMAN.TF, JOHNSON,W D Region 4, Dallas, Office of
 the Director 80/03/13, 8pp

- BOO4010416 Notifies that response to LE Bulletin 79-27 re loss of ac power supply to non-nuclear instrumentation buses, will be provided by BOO401 Delay caused by expansion of review to include Crystal River-3 event RUETER, D.A. Arkansas Power & Light Co. 80/03/27 1p
- 8004150231 Forwards 1E Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/31 1p
- 8004080666 Forwards IC Circular 80-05, 'Emergency Diesel Generator Lubricating Oil Addition & Gheite Supply "No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/01
- B004110097 Forwards JE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/02
- 8004180493 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/02
- BOO4180159 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/03
- 8004230324 Forwards IE Bullotin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pips " Action required SEYFRIT, X V Region 4, Dallas, Office of the Director B0/04/04 tp
- R Periodic operating reports & related correspondence
- 8004010216 Forwards "Intake Impingement Monitoring for Feb 1980 " TRIMBLE D C Artansas Power 5 Light Co 80/03/25 1p
- --B004010217 "Intake Impingement Monitoring for Feb 1980 " * Arkansas Power & Light Co 80/03/22 lipp
- 8004210217 Forwards monthly operating rept for Mar 1980 TRIMBLE.D C Arkansas Power & Light Co 80/04/11 1p
- --8004210220 Monthly operating rept for Mar 1980 BRAMLETT.L S Arkansas Power & Light Co 80/04/11 Spp
- 8004290361 Forwards results of impingement monitoring at facility intake, during Mar 1980 TRIMBLE.D C Arkansas Power & Light Co 80/04/25 1p
- --B004290366 Results of impingement monitoring at facility intake during Mar 1980 * Arkansas Power & Light Co 80/04/22 20pp
- S Reportable occurrences, LERs & related correspondence
- 7811100178 Describes 780916 event at sub, fecil auto transfer of auxiliary loads on both units to startup transformer #2 w/ consequent overload Recommends licensee be advised of nonconformance w/0DC-17 & modify his design ROSA,F Power Systems Branch SATTERFIELD.R Electric, Instrumentation & Control Systems Branch 78/11/01 8pp
- BOO4280487 RO 50-313/80-007 on BOO315, BtW notified util decay heat pumps contain mating wear rings of unequal hardness value Mating wear rings could galt & lock up BbW recommends replacement Decay heat pumps are functioning normally O'HANLON, J P Arkansas Power & Light Co BO/03/17 2pp
- 8004020349 Forwards LER 80-007/01T-0 TRIMBLE, D C Arkansas Power & Light Co 80/03/28 1p
- --BO04020353 LER BO-007/DIT-O on BO0314.B&W advised that mating wear rings on double suction pump could cause pump failure during accident conditions Caused by failure to document design revision on pump design drawlings SHIVELY.C N. Arkansas Power & Light Co BO/03/28 ip
- 8004140328 Forwards LER 80-005/03L-0 TRIMBLE,D C Alabama Power Co 80/04/07 ip

- --8004140333 LEN 80-005/03L-0 on 800336.during scheduled surveillance test of P7-A.CV-2617 alve railed to close remote electrically Caused by valve binding in closed position Valve stem repacked 5 proper operation verified DRAMLETT L S Alabama Power Co 80/04/07 1p
- 8004150630 Forwards LER 60-005/03L-0 TRIMBLE D C Arkansas Power & Light Co 80/04/07 Ip
- --8004150641 LER 80-005/0% -0 on 800306 during scheduled surveil; ance test or P7-A, steen supply valve CV-2617 failed to close remote electrically Caused by Valve binding in closed position Valve stem repacted BRAMLETT. U.S. Arkansas Power 2 Light Co. 80/04/07 1p
- 6004140354 Forwards LER 80-010/03L-0 TRIMBLE D C Alabama Power Co 80/04/08 1p
- --8004140360 LER 60-010/03L-0 on 800307.sys reviews per IE Bulletin 79-14 found hangers imagemable Cause not stated Hangers repaired 5 mods made by revision to DCP 80-D-1207 List of hangers enc!

 SRAMLETT.L S. Alabama Power Co. 60/04/08 2pp
- 8004150541 Forwards LER 80-010/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/04/08 1p
- --8004150549 LER 80-010/03L-0 on 800307, based on sys reviews per IE Bulletin 70-14, attached list of hangers found to be inoperable Affected hangers were modified 3/or repaired within time limit per Tech Specs DRAMLETT.L. S Artansas Power & Light Co 80/04/08 2pp
- 8004230471 Forwards LER 80-006/04L-0 TREMBLE, D.C. Arkansas Power & Light Co. 80/04/16 1p
- --8004230473 LER 80-006/04L-0 on 800318, average gross release rate for Jan-Mar 1980 found to be 4 3% of max permissible concentration, exceeding Tech Specs Major portion caused by reactor bids purge in Jan BRAMLETT, L.S. Arkansas Power & Light Co. 80/04/16 1p
- 0004290374 Forwards LER 80-008/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/04/22 1p
- --8004290385 LER 80-008/03L-0 on 800324.while performing surveylance test; bypass flow was observed to be zero due to faiture of CV-2126 in closed postion Caused by blown control fuse Fuse replaced & valve provid operable SRAMLETT, L.S. Arkansas fower & Light Co. 80/04/22 lp
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & tire protection plans
- 8004300012 Forwards sys description & operation instructions for NRC health physics telephone network Sys designed for use during nuclear incident or AO Network may also be used for daily administrative or facsimilie traffix KEPPLER, J.C. Region 3. Chicago, Office of the Director 80/03/20
- BO04080544 Forwards evacuation time estimates in response to NRC 79;129 info request Time required to evacuate schools & nursing homes under adverse & favorable conditions assumed to be 2-h after notification & 4-h for hospitals DQLAN.JE Indiana & Michigan Electric Co 80/04/01 21pp

- J Insurance & indemnity information
- 8004140324 Forwards Endorsement 35 to MAELU Policy MF-79.Endorsements 42 % 43 to NELIA Policy NF-206.Endorsement 3 to MAELU Binder XB-45.Endorsement 4 to MAELU Binder XB-64.Endorsement 3 to NELIA Binder EB-58 & Endorsement 4 to NELIA Binder EB-64 HUNTER.R S Indiana % Michigan Electric Co 80/04/03 9pp
- P Operating license stage documents & correspondence
- 8004020457 Forwards NRC safety analysis of tracking discovered in feedwater sys Util repair program, nondestructive insps & leakage testing are adoquate to insure that integrity of feedwater piping will be maintained SCHMENCER. A Operating Reactors Branch I 80/02/25 App
- GOO4150130 Forwards request for addi into re review of 791207 request for amend to reflect proposed mods to auxiliary feedwater sys SCHMENCER: A Operating Reactors Branch 1 60/02/27 Jpp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D G Division of Operating Reactors 80/03/12 Spp.
- --8004030118 "Nuclear Data Lin's Specs "
 * Division of Operating Reactors 80/02/21 28pp
- G004210415 Advises that facilities will be using Models CN6-BOA 7-100. CNS1-21-300 // CNS1-14-195-H for shipment of radioactive maths DOLAN, J. & Indiana % Michigan Electric Co. 80/03/17 1p
- 8004240462 Approves review re potential boron dilution incidents at facility.per 770915 Itr about incident involving contents of spray additive tank FSAR analysis represents most limiting case No further action necessary SCHWENCER.A Operating Reactors Branch 1 80/03/19 2pp
- 8004100165 Requests that uncontrolled set of P&IDs be placed on controlled distribution list for any future revisions Revisions should be forwarded to attention of Region 3 incident response ctr KEPPLER. J G Region 3. Chicago, Office of the Director 80/03/20
- 8004010325 Advises that no Event 5 valve configurations exist at fac(lity, in response to NRC B00223 ltr Lists valve configurations used at facility BOLAN.J E Indiana & Michigan Electric Co 80/03/24 3pp
- 8004010420 Requests permission to use divers to cut atuds for replacement of racks in spent fuel pool Dose calculations computed under two separate conditions Mar observed dose would be 0.7 man-roms
 BOLAN.J E Indiana & Michigan Electric Co BO/03/24 2pp
- 8004010486 Advises that upgraded radiation monitoring channels inside containment will be installed during first outage of sufficient duration subsequent to equipment delivery Reset feature does not affect position of control room dampers DDLAN. J E Indiana % Michigan Electric Co 80/03/25 2pp
- 8004240456 Approves use of divers for removal of anchor bolts during spent fuel mods Increase insignificant No change to 791016 safety evaluation necessary SCHMENCER, A Operating Reactors Branch 1 80/03/25 2pp
- 8004030204 Forwards add1 info to util 800310 ltr. Item 2 l.B b re interim method for determining plant releases MALONEY, O P Indiana S Michigan Electric Co 80/03/27 &pp
- B004080534 Forwards responses to NRC 800227 ltr re mods to facility auxiliary feedwater sys & requests for addl info concerning util response to NRC 791030 ltr MALONEY, 0 P Indiana & Michigan Electric Co 80/03/28 4pp
- 8004150507 Forwards ETA Engineering.Inc Mar 1980. "Summary Rept Comparing Thermal Pluma Measurements w/Modeling Predictions" & facility NPDES permit HUNTERIR & Indiana & Michigan Electric Co 80/04/03. 2pp
- ---8004190520 "Summary Rept Comparing Thermal flume Measurements ω/Modeling Predictions " * £1A Engineering, Inc. 80/03/31 53pp

- --8004150531 NPDES Permit MI 0005827.issued to IN & MI Power Co COURCHAINE.R J Michigan, State of 74/12/27 lipp
- 9 Inspection reports, IE Bulletins h correspondence
- 8004040392 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/13 2pp
- --B004040399 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & external packaging features POTTER, J P. BROWN, R A Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 4pp
- 8004040436 Forwards IE Insp Repts 50-315/80~02 & 50-316/80~02 on 791201-800111 & notice of violation HEISHMAN,R F. Region G. Chicago, Reactor Operations Nuclear Support Branch 80/02/16 Spp
- --80040404040 Notice of violation from insp on 791201-800111 * Region 3, Chicago, Office of the Director 80/02/11
- --B004040444 IE Insp Repts 50-315/80-02 & 50-316/80-02 on 791201-800111
 Nancompliance noted standing orders not reviewed by licensed operators as required
 MASSE.R E . B0YD, D C Region 3, Chicago, Office of the Director 80/02/11 6pp
- 8004040285 Forwards IE investigation Rept 50-315/80-03 on 771217 & 800109-10 No honcompliance noted KEPPLER.J D Region 3. Chicago. Office of the Director 80/02/20 200
- --8004040299 IE Investigation Rept 90-315/80-03 on 791217 & 800109-10 No noncompliance noted Major areas investigated allegations concerning improper wolding techniques & security procedures BOYD, D C , NORELIUS, C E , MASSE, R Region 3, Chicago, Office of the Director 80/02/15 Bpp
- 8004070411 Responds to Item 1 of IC Bulletin 79-018. "Environ Gualification of Class IC Equipment " Items 2-5 will be addressed before end of 70-day period Master list attached W/o encl DULAN, J E Indiana & Michigan Electric Co 80/03/07 3pp
- 8004100116 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago Office of the Director 60/03/07
- 8004300611 Forwards response to IE Bulletin 90-03, "Loss of Charcoal from Btd Type II Two-Inch.Tray Adsorber Cells" Rivet spacing problem does not apply at facilities No evidence found of defective cells or casing-screen separations DOLAN.J E Indiana & Michigan Electric Co 80/03/25 3pp
- BO04140484 Advises that Investigation Repts 50-315/79-27 & 50-316/79-27 were forwarded w/incorrect rept numbers Correct numbers are 50-315/79-27 & 50-316/79-25 KEPPLER.J O Region 3. Chicago. Office of the Director BO/03/26 ip
- 8004190162 Advises of error in 800102 IE Insp Repts 50-315/79-27 & 50-316/79-27 Corrected repts are 50-315/79-27 & 50-316/79-27 & 50-316/79-28 KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/26
- 8004180172 Ack receipt of 800312 ltr informing NRC of steps taken to correct violations noted in IE insp HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/03/27 ip
- ---8004180181 Responds to NRC 800216 ltr re violations noted in IE insp Corrective actions method for standing order receipt & review has been changed requiring each reviewer to initial particular sheet HUNTER.R S. Indiana & Michigan Electric Co 80/03/12 2pp
- 8004150153 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific Action or response necessary KEPPLER.J O Region 3. Chicago, Office of the Director 80/03/31

- SOO4080717 Forwards IE Cricular 80-05. 'Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply "No written response required MEPPLER, J.G. Region 3. Chicago, Office of the Director 80/04/01
- 8004150011 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers 'No specific action or response required PEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/02 ip
- 8004180018 Forwards attachments to IC (incular 80-03, "Protection From Toxic Cas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region J. Chicago, Office of the Director 80/04/02
- BOO4220090 Forwards IE Into Notice 80-14. "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3. Chicago. Office of the Director BO/04/02 10
- BOO4220339 Forwards IE Circular BO-O/. 'Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J.G. Region 3. Chicago, Office of the Director BO/O4/O3 15
- 8004230211 Forwards IE Bulletin 79-03A, "Longitudinal Reld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/07 to
- 8004280398 Responds to 800213 IE Bulletin 80-04 "Analysis of PNR Main Steam Break w/Continued Feedwater Addition " FSAR analyses adequately address concerns DDLAN: J E Indiana % Michigan Electric Co 80/04/08 3pp
- 8004220127 Forwards IE Bullotin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- BOO-4110445 Forwards "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1979 " DDLAN. J E Indiana & Michigan Electric Co BO/03/04 Ip
- ---8004110449 "Semiannyal Radioactive Effluent Release Rept.Jul-Dec 1979 "
 * Indiana & Michigan Electric Co 80/03/04 81pp
- 8004080304 Notifies that annual environ operating rept for 1979 is being forwarded under separate cover MALONEY,O P Indiana & Michigan Electric Co 80/04/02 ip
- 8004150369 Forwards monthly operating tept for Mar 1980 SHALLCR.D V Indiana & Michigan Electric Co 80/04/08 ip
- --8004150371 Monthly operating rept for Mar 1980 GILLETT:W T Indiana & Michigan Electric Co 80/04/02 7pp
- S Reportable occurrences, LERs & related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 MHITT.K W Region 2, Atlanta, Office of the Director 77/08/12 in
- BO04070427 PNO-III-80-049 on BO0314, licensee notified inspector that small unexplained radioactive release via auxiliary bldg stack was in progress Caused by leaking relief valve Failed fuel sys isolated BOYN.D C. HELBHMAN.R F Region 3. Chicago. Diffice of the Director 80/03/14 2pp
- BDO4070192 PNG-11I-80-052 on BO0317-portions of plant demineralized water sys found radicactively contaminated Probably caused by tiphoning following use of temporary line to add demineralized water to spent fuel storage pit BOYD.D.C. DUBRY.N.E., HETSHMAN.R.F. Region 3. Chicago. Office of the Director B0/03/17 2pp

1 4

- 8004090030 PND-Iff-80-049% on 200314. Region 3 received notification of unplanned radioactive gas release Caused by relief valve lifting in in-line failed rucl detection sys due to orerbrottling of valve downstream BOYD. D.C., HEISHMAR. R.F. Region 3, Chicago, Ofrice of the Director 80/03/17 Ip
- 8004040059 PrD-iiI-80-052A 800317 investigations revealed contaminated tap to be located outside auriliary bldg Personnel have been instructed that water from that source is not for human consumption * tap has been appropriately tagged 80YD, D.C., BUBRY N.E., HEISHHAN R.F. Region 3, Chicago, Office of the Director 80/03/19 2pp
- 8004140438 Forwards LER 60-004/03L-0 SPALLER, D. V. Indiana & Michigan Electric Co. 80/04/08 ip
- --8004140444 LFR BC-004/03L-O on BC0311, while performing scan sequence, one or two detectors in use for axial power distribution monitoring sys became inoperable Caused by component failure Alternate scan used following detector limit entry

 * Indiana / fischigan Electric Co BO/04/0B 2pp
- --8004230444 LER 80-005/03L-0 on 800321.descovered that Unit 1 extal power distribution manifolding sys 2 P-250 exhall power distribution manifolding sys 1 limits were incorrect Caused by personnel using Unit 2 PG 2 K(z) limits in computer program DELONG.5 D Indiana 2 Michigan Electric Co 80/04/18 2PP
- --800423044/ LER GO-006/O3L-O on B00324.during surveillance test.Unit 1 650-rt elevation airloc) door leakage of 130CFH was found No cause for leak found Retest performed u/satisfactory results DELONG.S D Indiana : Michigan Electric Co B0/04/18 1p
- 8004290417 RO on 800412 during filling of chemical vol & control sysholdup tank w/dimineralized water holdup tank inadvertently pressurized over safety valve setpoint of 12 psig Xe-133 & f-131 released from vent
 SHALLER D V Indiana & Michigan Electric Co 80/04/22 2pp
- DOCKET 50-316 DONALD C LOOP NUCLEAR POWER PLANT. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004300012 Forwards sys description to operation instructions for NRC health physics telephone network Sys designed for use during nuclear finitent or AC Network may also be used for daily administrative or facsimilie traffic AEPPLER.J C Region 3. Chicago Office of the Director 80/03/20 200
- 8004080544 Forwards evacuation time estimates in response to NRC 791129 info request Time required to evacuate schools & nursing homes under adverse \(\tau\) anable conditions assumed to be 2-h after notification \(\tau\) 4-h for hospitals DOLAN. JE Indiana & Michigan Electric Co 80/04/01 2ipp
- BOO4150507 Forwards proposed changes to fire protection Tech Specs to reflect mods made to plant per requirements of 790731 safety evaluation Tech Spec changes were reviewed to approved HUNTER, R.S. Indiana 3 Michigan Electric Co. 80/04/09 lp
- --8004150510 Proposed changes to Fire protection Tech Specs Changes reflect mods made to plant per requirements of 790731 fire protection safety evaluation HUNTER:R © Indiana % Michigan Flectric Co 80/04/09 lipp
- 8004230369 Forwards reliked sateguard contingency plan Plan withheld (ref 1905R2 790) DDLAN, J.E. Indiana & Michigan Power Co. 80/04/21 1p
- J insurance & indemnity information
- 8004140324 Forwards Endorsement 35 to MAELU Policy MF-79.Endorsements 42 & 43 to NELIA Policy NF-204.Endorsement 3 to MAELU Binder XB-45.Endorsement 4 to MAELU Binder XB-45.Endorsement 4 to MELIA Binder EB-64 Endorsement 4 to NELIA Binder EB-64 HUNTER.R S Indiana & Michigan Electric Co 80/04/03 9pp

- P. Operating license stage documents δ correspondence
- 8004020457 Forwards NRC safety analysis of cracking discovered in feedwater sys Util repair program nondestructive insps & loakage testing are adequate to insure that integrity of feedwater piping will be maintained SCHWENCER.A Operating Reactors Branch 1 80/02/25 6pp
- 800415013B Forwards request for add1 info re review of 791207 request for amend to reflect proposed mods to auxiliary feedwater sys SCHWENCER.A Operating Reactors Branch 1 80/02/27 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp
- 8004210415 Advises that facilities will be using Models CN6-80A.7-100, CNSI-21-300 & CNSI-14-195-H for shipment of radioactive matts
 DDLAN, J E Indiana & Michigan Electric Co 80/03/17 in
- B004220012 Summary of B00306 meeting w/Brown Boveri representatives returbine design features Vendor repts encl HIGGINTON: D Operating Reactors Branch 1 (Pre 791030) B0/03/1/
- --8004220017 "1160 MN Turbine for Facility "
 HG95LI:N Brown Bover: Corp (subs Brown Bouveri & Co .Ltd)
 CH-T 060030 E 80/03/17 18pp
- --8004220023 "Welded Rotors for Steam Turbines "

 * Brown Bover: Corp (subs Brown Bouveri & Co.,Ltd.) CH-T C60
 072 E 80/03/17 4pp
- --8004220027 "Rotors for Large Steam Turbines " HONN,A Brown Bover: Corp (subs Brown Bouveri & Co ,Ltd) CH f 060 053 E B0/03/17 14pp
- --8004220034 "Last-Stage Biades of Large Steam Turbines "
 HOHNAA, NOVACEK,P Brown Bovers Corp (subs Brown Bouvers & Co.Ltd.) CH-T 060040 E 80/03/17 12pp
- --8004220037 "Some Aspects of Water Chemistry in LWR Power Stations " BODMER.M Brown Bover: Corp (subs Brown Bouveri & Co ,Ltd) CH-T 030 043 E 80/03/17 Bpp
- 8004240462 Approves review re potential boron dilution incidents at facility.per 770915 ltr about incident involving contents of apray additive tank FSAR analysis represents most limiting case No further action necessary

 SCHMENCER.A Operating Reactors Branch 1 80/03/19 2pp
- 8004100145 Requests that uncontrolled set of P&IDs be placed on controlled distribution list for any future revisions Revisions should be forwarded to attention of Region 3 incident response ctr KEPPLER. J G Region 3. Chicago. Office of the Director 80/03/20 ip
- 8004010325 Advises that no Event 5 valve configurations exist at facility, in response to NRC 800223 ltr Lists valve configurations used at facility DDLAN, J E Indiana & Michigan Electric Co 80/03/24 3pp
- 8004010420 Requests permission to use divers to cut study for replacement of racks in spent fuel pool Dose calculations computed under two separate conditions Max observed dose would be 0.7 man-rams

 DDLAW J.E. Indiana & Michigan Electric Co. 80/03/24 2pp
- 8004010486 Advises that upgraded radiation monitoring channels inside containment will be installed during first outage of sufficient duration subsequent to equipment delivery Reset feature does not affect position of control room dampers DOLAN, J E Indiana & Michigan Electric Co 80/03/25 2pp
- 8004240456 Approves use of divers for removal of anchor bolts during spent fuel mods Increase insignificant No change to 791016 safety evaluation necessary SCHMENGER.A Operating Reactors Branch (80/03/25 2pp

- B004030204 Forwards addl info to util 800310 ltr. Itam 2 1 8 h ra interim method for determining plant releases MALONEY.G P Indiana & Michigan Electric Co 80/03/27 App
- 8004080520 Responds to NRC B00127 ltr requesting fee submittal for review of documents in 791218 ltr Fee already paid Discusses seismic qualification items MALDNEY,G P Indiana 2 Michigan Electric Co 80/03/28 3pp
- 8004080534 Forwards responses to NRC 800227 ltr re mods to facility auxiliary feedwater sys & requests for addl info concerning util response to NRC 791030 ltr MALONEY, G P Indiana & Michigan Electric Co 80/03/28 4pp
- 80040B0367 Forwards add1 info requested by NRC 790109 ltr.re analyses of containment temp response to postulated main steam line breaks
 MALONEY, G P Indiana / Michigan Electric Co B0/04/01 2ipp
- MACOMETIA E THOTANA STITLINGAN ELECTRIC CD 80304301 Sibb
- 8004160016 Returns WCAP-9566 Westinghouse proprietary rept is not necessary for NRC review of util proposed Tech Specs changes to power peaking limits W/o enci SCHWENCER.A Operating Reactors Branch 1 80/04/01 2pp
- 8004170178 Requests submittal of Class III foe per NRC 600127 ltr advising classification of 791218 amend application Response required within 15 days of receipt of ltr MILLER.W D License Fee Management Branch 60/04/01 ip
- B004150509 Forwards ETA Engineering, Inc. Mar. 1980, "Summary Rept. Comparing Thermal Plume Measurements w/Modeling Predictions" & facility NPDEB permit HUNTER.R.B. Indiana & Michigan Electric Co. 80/04/03 2pp
- --8004150520 "Summary Rept Comparing Thermal Plume Measurements u/Modeling Predictions " * ETA Engineering,Inc 80/03/31 53pp
- --BOD4150531 NPDES Permit MI 0005827, issued to IN & MI Pawer Co COURCHAINE, R J Michigan, State of 74/12/27 11pp
- 9 Inspection reports, IE Bulletins & correspondence
- 8604040392 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS,A 8 Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 2pp
- ~~8004040399 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & external packaging features POTTER, J P. BROWN, R A Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 4pp
- 8004040436 Forwards IE Insp Repts 50-315/80-02 & 50-316/80-02 on 791201-800111 & notice of violation HEIBHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80702/16 Spp
- --800404040 Notice of violation from insp on 771201-800111 * Region 3, Chicago, Office of the Director 80/02/11 ip
- --8004040444 IE Insp Repts 50-315/80-02 & 50-316/80-02 on 771201-800111
 Noncompliance noted standing orders not reviewed by licensed operators, as required
 MASBER E , BOYD, D C Region 3, Chicago, Office of the Director BO/02/11 App
- G004070411 Responds to Item 1 of IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Items 2-5 will be addressed before end of 90-day period Master list attached. W/o encl. DOLAN. J E Indiana & Michigan Electric Co 80/03/07 3pp
- 8004100116 Forwards IE Info Notice 80-08, "States Go Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER: J @ Region 3: Chicago, Office of the Director 80/09/07 ip.
- 80043006ii Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II Two-Inch.Tray Adsorber Cells " Rivet spacing problem does not apply at facilities No evidence found of defective cells or casing-screen separations DDLAN.J E. Indiana & Michigan Electric Co 80/03/25 3pp

- 8004140484 Advises that Investigation Rept4 50-315/79-27 % 50-316/79-27 were forwarded wincornect rept numbers Correct numbers are 50-315/79-27 % 50-316/79-25 KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/26 to
- 8004150162 Advises of error in 800102 IE Insp Repts 50-315/79-27 & 50-316/79-27 Corrected repts are 50-315/79-27 % 50-316/79-25 KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/26 in
- 8004180172 Ack receipt or 800312 ltr informing NRC of steps taken to correct violations noted in IE insp HEISHMAN F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/27 1p
- -- GOO4180181 Responds to NRC 800216 itr re violations noted in IE insp Corrective actions method for standing order receipt b review has been changed requiring each leviewer to initial particular sheet HUNTER:RS Indiana / Michigan Electric Co 80/03/12 2pp
- 8004150153 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/31
- 80040B0717 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required KEPPLER.J G Region 3. Chicago. Office or the Director 80/04/01
- 8004150011 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180018 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 to
- 8004220090 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/04/02 in
- 8004220339 Forwards IE Circular 80-07, "Problems W/HFC! Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 in
- 8004230211 Forwards IE Bulletin 79-03A, "Longitudina) Weld Defects in ABME 9A-312,Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07

8004286 Stea ader

- --8004150345 Monthly operating rept for Mar 1980 GILLETT, W.T. Indiana / Michigan Electric Co. 80/04/02 9pp
- 3 Reportable occurrences, LERs ? related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities u/production lot of 40 pumps mfg using sharts made of inferior matl Cause unstated All utils u/pumps were notified NRC headquarters notified on 770812 WHITE, K N Region 2. Atlanta. Office of the Director 77/08/12
- 8004070192 PNO-11[-80-052 on 800317.portions of plant demineralized water sys found radioactively contaminated Probably caused by siphoning following use of temporary line to add demineralized water to spent ruel storage pit 80YO, D C . DURRY, N E . HEISHMAN, R F Region 3, Chicago, Office of the Director 80/03/17 2pp
- B0040400°59 PNO-III-B0 052A 600317 investigations revealed contaminated tap to be located outside auxiliary bldg Personnel have been instructed that water from that source is not for human consumption t tap has been appropriately tagged B0Y0,D C. DUSRY,N E. HEISHMAN R F. Region 3. Chicago. Office of the Director 80/03/19 2pp
- 8004010476 Forwards LER 80-011/03L-0 SHALLER,D V Indiana 2 Michigan Electric Co 80/03/2L 1p
- --800401048L LER 80-011/03L-0 on 800223 during weekly turbine testing, reduction in RCS pressure occurred Pressure dropped below min Tech Spec limit Caused by tripped supply breakers resulting in inoperable heaters Breakers result MURPHY.C E Indiana & Michigan Electric Co 80/03/21 1p
- 8004010493 Forwards LER 80-012/03L-0 SHALLER.D V Indiana & Michigan Electric Co 80/03/25 Ip
- --80040:0500 LER 80-012/031-0 on 800305, while performing surveillance test, steam generator water level low-low trip bistable found to trip at 11 057 narrow range instrument span Cause unstated Bistable recallbr & returned to syc RISCHLING, J L Indiana & Michigan Electric Co 80/03/25 1p
- 8004080510 Forwards LERs 80-013/03L-0 & 80-014/03L-0 SHALLER,D V Indiana & Michigan Electric Co B0/04/02 ip
- --8004080527 LER 80-013/03L-0 on B00307, during normal operation, circuit breaker for R-11 & R-12 sample pump tripped Caused by failure of rubber spider in Lovejoy L-100 coupling Complete coupling replaced b air sampler tested WIZNER, D O Indiana & Michigan Electric Co 80/04/02 1p
- --8004080945 LER 80-014/03L-O on 800216, during surveillance test.
 proximity switch for D main turbine stop valve fell off
 mounting bracket Caused by threads in mounting bracket
 being stripped Hole retapped to larger size
 RISCHLING, J L Indiana & Michigan Electric Ca 80/04/02 ip
- 8004230430 Forwards tER 80-015/03L-0 SHALLER.D V Indiana & Michigan Electric Co 80/04/15 1
- ---8004230432 LER 80-015/03L-O on 800325 during auxiliary feed pump retest auxiliary feed valve FMD-221 for steam generator 2 did not operate Caused by armature lead from limitorque valve operator being pulled out of wire log New 10g crimped BRGMN.M S Indiana 2 Michigan Electric Co 80/04/15 1p
- 8004230351 Forwards LERs 80-016/03L-0 & 80-017/03L-0 SHALLER,D V Indiana / Michigan Electric Co 80/04/18 ip
- --8004230355 LER 80-016/03L-O on 800322. while performing routine panel insp. operator discovered cast RHR pump suction breaker IMO-310 open Cause not determined Operators have been alerted to keep close watch on panel indicators MURPHY.C E. Indiana A Michigan Electric Co. 80/04/18 IP
- --8004230357 LER 80 017/03L-O on B00321, during normal operation, TDAFP trip & throttle valve tripped & could not be reset Caused by defective reset solenoid Coil replacement not effective Trip linkage reset manually New Coil & linkage adjusted RISCHLING, J. L. Indiana & Michigan Electric Co. 80/04/18 2pp
- 8004290417 RO on 800412.during filling of chemical vol & control sysholdup tank inadvertently pressurized over safety valve setpoint of 12 psig Xe-133 & I-131 released from vent SHALLER, D. V. Indiana 3 Michigan Electric Co. 80/04/22 2pp

- BOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, modical, emergency & fire protection plans
- 8004170316 Forwards summary of 800221 meeting w/util re LNG contingency plan.M Hohl trip rept 2 request for addl info necessary to complete review of site emergency plan REID.R W Operating Reactors Branch 4 80/03/31 2pp
- --B004170318 Summary of B00221 meeting w/otil in Bethesda.MD to discuss LPN contingency plan Review will be completed concurrently w/emergency planning review Agenda and CONNER.E L Operating Reactors Branch 4 80/03/31 Spp
- --8004170323 Forwards affices to methene detection using lawors
 Recommends lawer fence idea Sys would act as continuous
 fence under all conditions except heavy fag W/o encl
 WOODMAN, D P GTE Sylvania, Inc (subs of General Telephone &
 Electronics Corp) 79/12/26 ip
- 8004080391 Forwards Revision & to modified amended security plan Plan withheld (ref 10CFR2 /90) EVANS,V R Baltimore Gas & Electric Co 80/04/02 2pp
- 8004230483 Forwards input for fire protection review. Item 3 2 2 reemergency lighting Recommends NRC approval of licensee proposals contained in 791113 itr. Submits recommendations reproposal to change from 15-h units to 8-h units HALL.RE Brookhaven National Laboratory 80/04/14 1p
- H General correspondence
- 8004040300 Objects to radioactive discharges from units Officials irresponsible % not concerned w/public interest People must take immediate, unitied action to gain control over environ & lives RENRO, E. Affiliation Unknown BO/02/15 2pp
- P . Operating license stage documents δ correspondence
- 8004080437 Advises that FR notice of consideration of proposed and to facility spent fuel storage pool has been filed for publication Notice relates to util 800115 request to permit 1.760 in lieu of 1.360 fuel assemblies to be stored REID,R W Operating Reactors Branch 4 80/02/28 2pp
- --8004080440 Notice of consideration of proposed mod to facility spent fuel storage pool REID:R W Operating Reactors Branch 4 80/02/28 App
- 8004040091 Forwards Amends 42 & 29 to Licenses DPR-53 & DPR-69 respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/03/10 3pp
- --B004040094 Amends 42 & 25 to Licenses DPR-53 & DPR-49 respectively, deleting satisfied License Condition 2 C(3), "Steam Generator Water Level Rise Rate," for Unit 2 & deleting satisfied license condition re LNO traffic for both REID,R W Operating Reactors Branch 4 80/03/10 2pp
- --8004040105 Bafety evaluation supporting Amends 42 & 25 to Licenses
 DPR-53 & DPR-69 respectively
 * Office of Nuclear Reactor Regulation 80/03/10 7pp
- --B004040109 Notice of issuance & availability of Amends 42 & 20 to Licenses DPR-53 & DPR-69, respectively REID,R W Operating Reactors Branch 4 80/03/10 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUI.D Q Division of Operating Reactors 80/03/12 5pp
- --9004030118 "Nuclear Data Link Specs "
 # Division of Operating Reactors 80/02/21 28pp
- GOO4100300 Submits add1 info re auto initiation of auxiliary of feedwater sys NRC 791030 ltr stated implementation of Itam 2 i 7a short-term required NRC approval Design must be verified before implementation EISENHUT.D O Division of Operating Reactors 80/03/27 3pp

- 8004010463 Submits additinfore proposed design changes to satisfy requirements for auxiliary feedwater sys Auxiliary feedwater by steam turbine sys will be modified by 830101 Forwards piping & instrumentation blogic diagrams
 LUNDVALL.A E Baltimore Gas b Electric Co 80/03/28 3pp
- ---8004010467 "Piping & Instrumentation Diagram Auxiliary Feedwater Sys " # Bechtel Corp 6750 80/03/18 ip
- --8004010471 "Auxiliary Feedwater Actuation Sys," preliminary drawings * Bechtol Corp 80/03/21 ip
- 8004240244 Ack receipt of 790703 application & 800115 ltr re spont fuel pool mod Results of preliminary review determined that Class IV fee is required for Unit 1 rather than Class III Requests prompt remittance
 DIGOS.R M License Fee Management Branch 80/03/28 1p
- 8004080465 Discusses action taken to correct spurious high power & temp monitor/low pressure trips on Channel A of reactor protection sys Single channel version of reporting identification symbol transmitters ordered LUNDVALL.A E Baitimore Gas & Electric Co 80/03/31 2pp
- 8004230177 Requests addition to complete LOCA review of util 770405 application for partial-loop operation Info required re high & low density fuels including initial clad inside (gap region) & outside exide thickness data REID.R W Operating Reactors Branch 4 80/03/31 2pp
- 8004090359 Forwards addl fee for upgrading, from Class III to Class IV, of 790903 amend request to replace existing spent fuel racks w/high capacity racks
 OLSONOR C Baltimore Oas % Electric Co 80/04/03 2pp
- 8004100227 Furwards response to NRC 800225 request for addl info re facility containment purge sys design Includes info re electrical reset.override & bypass LUNDVALL.A E Baltimore Gas & Electric Co 80/04/07 14pp
- 8004280154 Forwards evaluation concluding that implementation of Lassons Learned Yask Force Category A requirements at facilities is acceptable Evaluation does not address Tech Specs re limiting conditions for operation REID.R W Operating Reactors Branch 4 80/04/07 10pp
- 8004280025 Discusses 791030 ltr to HR Denton Notifications per Tech 8pecs 2 3 A 7 or 2 3 B 8 should include dose assessment illustrating compliance w/40CFR190 REID:R W Operating Reactors Branch 4 80/04/08 2pp
- BOO417023B Forwards response to questions contained in NRC 790827 & 0721 ltrs re proposed spent fuel pool mods Requests that NRC allow storage of 1830 fuel assemblies instead of 1760 assemblies as originally requested LUNDVALL. A E Baltimore Gas & Electric Co BO/04/14 38pp
- 8004220782 Responds to request for addl info re util 790703 license amend request Makeup rate to spent fuel pool from demineralizer tank is 325 gpm Makeup rate from two refueling water tanks is 1.390 gpm
 ASH.R F paltimore Gas & Electric Co 80/04/18 lp
- 8004280435 Disscusses redirecting efforts of Operating Experience Assessments Committee to avoid overlap w/efforts of Plant Operations Bafety Review Committee Described changes meet intent of NUREG-0578 & will be implemented immediately LUNDVALL.A E. Baltimore Gas & Electric Co 80/04/22 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004220441 Responds to IE Bulletin 80-04, "Analysis of Steam Line Break w/Continued Feedwater "Forwards results of analyses assessing ability of containment to withstand effects of break inside containment W/O encl LUNDVALL.A E Baltimore Gas & Electric Co 80/02/12 ip
- 8004070137 Advises that no NAMCO EA180 limit switches are in stock or on order re IE Bullatin 77-28
 LUNDVALL, A E Baltimore Gas & Electric Co 80/02/21 1p
- 6004030311 Responds to IE Bulletin 79-27, "Loss of Non-Class [E Instrumentation & Control Power Sys Bus During Operation " Voltmeters, potential indicators & alatms exist in control room to alert operator to Joss of power to bus LUNDVALL, A E Baltimore Oas & Electric Co B0/02/26 3pp

- 8004080335 Submits response to IF Builetin 79-27 re loss of instrument control power; effect on ability to achieve cold shutdown Mods to cold leg temp loops will allow one panel indicator for each loop temp for single invested loss LUNDVALL.A E Baltimore Gas * Electric Co 80/02/26 3pp
- 8004090243 Forwards 45 day response to IE Bulletin 79-018 W/o encl master list of safety-related electrical equipment, sys component evaluation worksheets h tabulation of syc conditions LUNDVALL, A F Baltimore Gas ' Electric Co 80/03/03 2pp
- 8004280280 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SHITH, 6 H. Region 1. Philadelphia, Fuel Facility 2 Materials Safety Branch 80/03/05 2pp
- --8004280288 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Hajor areas inspected shipping paper requirements, DDT placarding requirements, radiation levels 5 removable contamination WDDDRUFF, R. L., PEERY, W. W., POTTER, 1 P. Region 1, Philadelphia, Office of the Director 80/01/18 7pp
- BOO4100265 Forwards correspondence w/Amphenol Space % Missile Sys & vendor rept re space electrical penetration test data in response to IE Bulletin 79-01 Util considers rept unacceptable due to lack of detail N/o encls
 BHATIA:P Baltimore Gas & Electric Co 80/03/06 lp
- 8004080324 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-24 & 50-318/79-23 GRIER. B H Region 1, Philadelphia, Office of the Director 80/03/08 Ip
- --8004080333 Responds to NRC 800213 ltr re violations noted in IE Insp Repts 50-317/79-24 & 90-318/79-23 Corrective actions design & installation of curbing for Wasting Neutralizing Tank 12 in progress & completion expected by 800229 LUNDVALL.A E Baltimore Oas 5 Electric Co 80/02/27 2pp
- --8004080341 Forwards IE Insp Repts 50-317/79-24 & 50-318/79-23 on 791210-11 & notice of violation ORIER,B H Region 1, Philadelphia, Office of the Director 80/02/13 2pp
- --8004080344 Notice of violation from insp on 771210-11 * Region 1: Philadelphia: Office of the Director 80/02/07 ip
- --8004080352 IE Insp Repts 50-317/79-24 & 50-318/79-23 on 791210-11 Noncompliance noted several sys components including acid, caustic day Lanks, caustic pumps & piping sys were corroded SHANBAKY, M M , KOTTAN, J J Region I, Philadelphia, Office of the Director BORES, R J Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/07 Bpp
- BOO4040271 Describes conformance of inservice insp program to deviation from ASIE Boiler & Pressure Vassel Code. Section XI. 1974-1975 Forwards "Long-Term Inservice Exam Plan for Class I. Class 2 & Class 3 Sys & Components." Vol. 1-3. final plan LUNDVALL.A E Baltimore Gas & Electric Co 80/03/29 18pp

- 8004110124 Forwards IF Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers' No written response required GRIER, B.M. Region 1. Philadelphia. Office of the Director 80/04/02 1p
- 8004240293 Forwards IF into Notice 80 14. "Safety Suggestions From Employees" No action required ORIER,B H. Region 1. Philadelphia. Office of the Director 80/04/02 1p
- 8004180257 Forwards IE Circulai 80-07 'Problems W/HPCI Turbine Oil Sys " No oritten response required GRIER, B M Region 1 Philadelphia, Office of the Director 80/04/03 tp
- B004230394 Forwards IE Bulletin 79-03A, "Longitudinal Wald Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required GRIER, B H. Region 1. Philadelphia, Office of the Director B0/04/04 | Ip
- 8004180117 Forwards IE Bulletin 80-06, "Exam of Containment Liner Penetration Welds " Written response required GRIER. B H Region 1. Philadelphia. Office of the Director 80/04/07 19
- R Periodic operating reports & related correspondence
- B004210192 Forwards "Nontadiological Environ Monitoring Rept. Jan-Dec 1979 " LUNDVALL, A.E. Baltimore Gas & Electric Co. 80/03/14 ip
- ~-80042[0197 "Nonradiological Environ Monitoring Rept.Jan-Dec 1979 "

 ◆ Baltimore Gas & Electric Co → Academy of Natural Sciences of Philadelpnia 80/03/31 400pp
- 8004070275 Forwards, "Radiological Environ Monitoring Program Annual Rept. 1979 " LUNDVALL A E. Baltimore Gas / Electric Co. 80/03/28 1p
- --80040/0274 "Radiological Environ Monitoring Program Annual Reptil979 " BARTALL J . RAFI, A . REICHERI, E C Baltimore Gas & Electric Co 80/03/31 Sopp
- 8004250406 Forwards monthly operating rapts for Mar 1980 Correction to Feb 1980 monthly operating rapt requested MERSON,S D. Baltimore Gas & Flectric Co. 80/04/15 1p
- ~-8004250407 Monthly operating repts to: Mar 1980 MERSON:S D - Saltimore Gas & Electric Co - 80/04/14 - 18pp
- S Reportable occurrences, LERs 3 related correspondence
- 8004010430 Forwards LFR 80-013/03L-0 RUSSELL, L B Baltamore Gas & Electric Co 60/03/25 1p
- --8004010435 LER 80-013/03L-0 on 800225, while performing surveillance test, channel D containment high pressure tilp setpoint was less conservative than value given in Fech Spacs Caused by failed signal isolator 1-F/E-5313D
 HEIBELR P , RIZZO.P G Baltsmore Gas & Electric Cp 80/03/25
- 8004080500 Forwards LER 80-002/04T-0 RUSSELL.L B Raltimore Gas & Electric Co B0/04/03 ip
- --8004050507 LER 80-002/047-0 on 800322.instantaneous hourly average for condenser temp rise observed in excess of Tech Spec limit Caused by operator instrention to temp rise across condenser & environ conditions HEIBEL.R P Baltimore Gas & Electric Co 80/04/03 2pp
- 8004159606 Forwards LER 80-014/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 80/04/10 1p
- --B004150620 LER 80-014/03L-0 on 800380, during surveillance testing, reactor core drain tank & quench tank orggen sample valves failed to shut on safety injection actuation signal Caused by corresson on output relay terminals

 LAGIEWSKI.J S., RIZZO.P G. Baltimore Gas & Electric Co. 80/04/10
- B004170219 Forwards LER B0-020/03L-0 RUSSELL.L B Daltimore Gas & Electric Co B0/04/14 10

- --8004170221 LER 80-020/03L-0 on 800314, while operating at 98% power, fire marshall discovered the barrier penetration between cable spreading room & turbine bldg not sealed w/Flamastic fire retardant matl Caused by inaccessible location WEINCEN. O . BUFFINGTON, D C Baltimore Gas & Electric Co 80/04/14 2pp
- 8004210323 Submits info in confirmation of 800415 conversation u/RE Architis) re generic deficiency & FSAR Section 14 3 concerning boron dilution incident Operating procedures will be changed to require min 2/ shutdown margin DAVIS, 8 ii Baltimore Gas & Electric Co 80/04/16 ip
- --8004220719 LER 80-021/041-0 on 800404, during preventive maint for draining condensate from fuel oil storage tank, operator drained oil instead of water Caused by operator inability to discern difference between oil 1 & water through bullseye DENTON.R & Haltimore Gas & Electric Co 80/04/16 2pp
- 6004220614 Forwards LER 80-015/03L-0
 RUBSELLIL B Baltimore Gas 5 Electric Co 80/04/17 1p
- --8004220621 LER 80-015/03L-0 on 800317, steam generator auxiliary feed pump 11 was taken out of operation Caused by sightglass being broken by operator taking oil sample for analysis Broken glass replaced HUSEBY, D.C., HEIBEL, R.P. Baltimore Gas & Electric Co. 80/04/17
- 8004290372 Forwards LER 80-005/03L-0 RUSSELL, & Baltimore Gas & Electric Co 80/04/25 ip
- --8004290377 LER 80-005/03:-0 on 800325, during normal operation, control room air conditioning Unit 12 tripped Caused by failure of diaphragm on unipressire valve Valve replaced & unit returned to svc
 LAGIENSKI, J S. PENCE, W.B. Baltimore Gas & Electric Co. 80/04/25
- 8004290382 Forwards LER 80-016/03L-0 RUSBELL.L B Baltimore Gas & Electric Co 80/04/25 1p
- --8004290388 LER 80-016/03L-0 on 800325, during surveillance testing.
 Channel A wide range nuclear instrument did not respond in calibr mode Apparently caused by failure of channel preamplifier Power supply replaced w/spare LAGIENSKI, J S , RIZZO, P G Baltimore Gas & Electric Co 80/04/25
- 8004290433 Forwards updated LER 79-052/03X-1 RUSSELL,L B Baltimore Gas & Electric Co 80/04/25 1p
- --800427043B Updated LER 79-052/03x-1 on 79092B, containment gaseous & particulate radioactivity monitoring sys failed due to loss of sampling pump Caused by normal end-of-life failure of graphite particles depositing on bearings
 PENCE, W B Baltimore Gas & Electric Co 80/04/25 ip
- 8004290440 Forwards updated LER 80-011/03X-1 RUSSELL,t B Baltimore Gas & Electric Co 80/04/25 1p
- --8004270447 Updated LER 80-011/03X-1 on 800208, #/RCS at 130 degrees & 250 psia, shutdown cooling suction header relief lifted & failed to reset Caused by personnel error Valve reset DAVIS, S M , HUSEBY, D E Baltimore Cas & Electric Co 80/04/25
- 8004290459 Forwards LER 80-019/03L-0 RUBSELL, L B Baltimore Gas & Electric Co 80/04/25 ip
- --800A290472 LER 80-019/03L-0 on 800327 during normal operation, channel B loss of load trip occurred intermittently Caused by auxiliary master trip relay end-of-life type failure LAGIEMSKI, J S , RIZZO, P G Baltimore Gas & Electric Co 80/04/25 2pp
- 8004290475 Forwards LER 80-022/017-0 RUSSELL, t. B. Baltimore Gas ? Electric Co. 80/04/25 ip
- ---8004290484 LER 80-022/017-0 on 800415 util informed of possible deficiency in FSAR Section 14 3, boron dilution incident, for case when RCB is drained to hot leg w/1% shutdown margin Cause not stated Procedures changed DAVIS, S M Baltimore Gas & Electric Co 80/04/25 2pp

- 8004290490 Forwards LER 80-017/03L-0 RUBSELL, L B Baltimore Gas & Electric Co 80/04/25 1p
- --8004270497 LER 80-017/03L-0 on 800326, results of surveillance test indicated that ECCS exhaust filter train charcoal did not demonstrate removal efficiency of 90% or higher for radioactive methyl lodide Caused by age of filters HEIBEL, R.P. BAUER, R. Baltimore Gas & Electric Co. 80/04/25 ip
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8004170315 Forwards summary of 800221 meeting w/util re LNG contingency plan, M Wohl trip rept & request for addl info necessary to complete review of site emergency plan REID.R W Operating Reactors Branch 4 80/03/31 2pp
- --8004170318 Summary of 800221 meeting w/util in Bethosda.MD to discuss LPN contingency plan Review will be completed concurrently w/emergency planning review Agenda encl CONNER.E L. Operating Reactors Branch 4 80/03/31 5pp
- --8004170323 Forwards articles re methane detection using lasers
 Recommends laser fence (dea 8ys would act as continuous
 fence under all conditions except heavy fog W/o encl
 WOODMAN, D P GTE Sylvania, Inc (subs of General Telephone &
 Electronics Corp) /9/12/26 ip
- 8004080391 Forwards Revision 6 to modified amended security plan Plan withheld (ref 100FR2 790)
 EVAND.V R Baltimore Gas & Electric Co 80/04/02 2pp
- 8004230483 Forwards input for fire protection review. Item 3 2 2 re emergency lighting Recommends NRC approval of licenses proposals contained in 791113 ltr Submits recommendations re proposal to change from 1 5-h units to 8-h units HALL.R E Brookhaven National Laboratory 80/04/14 lp

- 8004040300 Objects to radioactive discharges from units Officials irresponsible & not concerned w/public interest People must take immediate unified action to gain control over environ & lives
 RENNO.E Affiliation Unknown 80/02/15 2pp
- P Operating license stage documents & correspondence
- BOO4080437 Advises that FR notice of consideration of proposed med to facility spent fuel storage pool has been filed for publication Notice relates to util BOO115 request to permit 1,760 in lieu of 1,368 fuel assemblies to be stored REID.R W Operating Reactors Branch 4 BO/02/28 Zpp
- --8004080440 Notice of consideration of proposed mod to facility spent fuel storage pool REID,R W Operating Reactors Branch 4 80/02/28 4pp
- 8004040071 Forwards Amends 42 & 25 to Licenses DPR~53 & DPR-47 respectively safety evaluation & notice of issuance & availability REID:R W Operating Reactors Branch 4 80/03/10 3pp
- --8004040094 Amends 42 \$ 75 to Licenses DPR-53 & DPR-69 respectively, deleting satisfied License Condition 2 C(3), "Steam Generator Water Lovel Rise Rate," for Unit 2 & deleting satisfied license condition re LNG traffic for both REID.R W Operating Reactors Branch 4 80/03/10 2pp
- ---A004040105 Safety evaluation supporting Amends 42 & 25 to Licenses
 DPR-53 & DPR-67 respectively
 * Office of Nuclear Reactor Regulation 80/03/10 7pp
- --8004040107 Notice of issuance & availability of Amends 42 & 25 to Licanses DPR-53 & DPR-69, respectively REID, R W Operating Reactors Branch 4 80/03/10 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr E18EMHUT, D O Division of Operating Reactors 80/03/12 5pp
- ---8004030118 "Nuclear Data Link Spacs "
 * Division of Operating Reactors 80/02/21 28pp

- 8004100300 Submits add1 into relauto initiation of auxiliary of feedwater sys NRC 791000 ltm stated implementation of Item 2 i 7a short-term required NRC approval Design must be verified before implementation RiseRHUT.D G Division of Operating Reactors 80/03/27 3pp
- 8004010463 Submits addl into re proposed design changes to satisfy requirements for auxiliary feedwater sys Auxiliary feedwater & steam turbine sys will be modified by 839101 Forwards piping & instrumentation & logic diagrams
 LUNDVALL,A E Baltimore Gas ' Electric Co 80/03/28 3pp
- --8004010467 "Piping & Instrumentation Diagram Auxiliary Feedwater Sys " * Bechtel Corp 6750 80/03/18 1p
- ---8004010471 "Auxiliary Feedwater Actuation Sys." preliminally drawings * Bechtel Corp 90/03/21 1p
- 8004240244 Ack receipt or 790703 application & 800115 ltr is spent fuel pool mod Results of preliminary review determined that Class IV fee is required for Unit 1 rather than Class III Requests prompt remittance
 DIGOS.R M License Fee Management Branch 80/03/28 1p
- 8004010212 Forwards revision to Svc Data Items G 2.0 3 % O 4 of Attachment 3 to 800318 ltr re Westinghouse low pressure turbine disc insp OLSON.R C Baltimore Gas & Electric Co 80/03/29 2pp
- 8004080465 Discusses action taken to correct spullous high power & temp monitor/low pressure trips on Channel A of reactor protection sys Single channel version of reporting identification symbol transmitters ordered LUNDVALL, A E Baltimore Gas & Electric Co 80/03/31 2pp
- BOO4230177 Requests add1 into to complete LOCA review of util 790405 application for partial-loop operation Info required re high & low density fuels, including initial clad inside (gap region) & outside oxide thickness data REID.R () Operating Reactors Branch 4 80/03/31 2pp
- 8004090359 Forwards addl fee for upgrading, from Class III to Class IV, of 790903 amend request to replace existing spent fuel racks withigh capacity racks OL60N.R C Baltimore Gas & Electric Co 80/04/03 2pp
- 8004100227 Forwards response to NRC 800225 request for addl info re facility containment purge sys design includes info re electrical reset.override & bypass LUNBVALL.A C Baltimore Gas & Electric Co 80/04/07 14pp
- BOO42B0154 Forwards evaluation concluding that implementation of Lessons Leained Task Force Category A requirements at facilities is acceptable Evaluation does not address Tech Specs re limiting conditions for operation REID.R W Operating Reactors Branch 4 80/04/07 10pp
- 8004250025 Discusses 791030 ltm to HR Denton Notifications per Tech Specs 2 3 A 7 or 2 3 B 8 should include dose assessment illustrating compliance w/40CFR190 REID.R W Operating Reactors Branch 4 80/04/08 2pp
- 8004170238 Forwards response to questions contained in NRC 790827 & 0921 ltrs re proposed spent fuel pool mods Requests that NRC allow storage of 1830 fuel assemblies instead of 1760 assemblies as originally requested LUNDVALL.A E Baltimore Gas & Electric Co 80/04/14 38pp
- 8004220782 Responds to request for add1 info re util 770703 license amend request Makeup rate to spent fuel pool from demineraliser tank is 325 gpm Makeup rate from two refueling water tanks is 1.370 gpm
 ASH.R F Baltimore Gas & Electric Co 80/04/16 1p
- 8004280435 Disscusses redirecting efforts of Operating Experience Assessments Committee to avoid overlap w/efforts of Plant Operations Safety Review Committee Described changes meet intent of NUREO-0578 & will be implemented immediately LUNDVALL.A E Baltimore Gas & Electric Co 80/04/22 2pp
- Q Inspection reports: If Bulletins & correspondence
- 8004220441 Responds to IE Bulietin 80-04. "Analysis of Steam Line Break w/Continued Feedwater "Forwards results of analyses assessing ability of containment to withstand effects of break inside containment W/o encl LUNDVALL, A E Baltimore Gas & Electric Co 80/02/12 ip

- 8004070139 Advises that no HAMLO EA180 limit switches are in stock or on order re 16 Bulletin 79~28 LUNDVALL, A E Baltimore Gas? Electric Co 80702/21 tp
- B004030311 Responds to 1E Sulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Voltmeters, potential indicators * alaims exist in control room to alert operator to loss or power to bus LUNDVALL.A E Baltimore Gas / Electric Co 80/02/26 3pp
- 8004080335 Submits response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Mods to cold leg temp loops until allow one panel indicator for each loop temp for single inverter loss LUNDVALL. A E Baltimore Gas / Electric Co 80/02/26 3pp
- 8004090243 Forwards 45-day response to 18 Bulletin 79-018 W/o enc) master list of sarety-related electrical equipmentisys component evaluation worksheets 5 tabulation of svc conditions LUNDVALL, A E Baltimore Gas * Electric Co 60/03/03 2pp
- 8004280280 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No honcompliance noted BMITH.Q H. Region 1. Philadelphia, Fuel Facility & Materials Gafety Branch 80/03/05 2pp
- --8004280288 Waste Packaging Insp Rept 79-07A on 791212-13 No DUMPETURED WASTE PACKAGING INSPIRED TYPOVA ON TYPEIZTIS NO noncompliance noted Major areas inspected shipping paper requirements, DOT placinging requirements, radiation lovels become animation MODROLF, R. L. PERTY, W. W., POTTER, (P. Region 1, Philadelphia, Office of the Director 80/01/18 7pp
- B004100265 Forwards correspondence w/Amphenol Space & Missile Sys & NOTIONAL FORWARDS CORRESPONDENCE WAMPHIELD APACE & FIRST vendor lept respace electrical penetration test data in response to LE Bulletin 79-01 Util considers rept unacceptable due to lack of detail H/o encis BHATIA/P Baltimore Gas & Electric Co 80/03/06 1p
- B0040B0324 Ack receipt of B00227 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-317/79-24 & 50-318/79-23 GRIER.B H Region 1, Philadelphia. Office of the Director ORIER, B H R 60/03/08 1p
- --8004080333 Responds to NRC 800213 ltr re violations noted in IE Insp Repts 50-317/79-24 5 50-318/79-23 Corrective actions design & installation of curbing for Wasting Neutralizing Tank 12 in progress 5 completion expected by 800229 LUNDVALL-A E Baltimore Gas 5 Electric Co 80/02/27 2pp
- --8004080341 Forwards IE Insp Repts 50-317/79-24 & 50-318/79-23 on 791210-11 & notice of violation GRIER, B H. Region 1. Philadelphia, Office of the Director 80/02/13 2pp
- ~~8004080344 Notice of violation from inspin 771210-11 # Region 1, Philadelphia. Office of the Director 80/02/07 ip
- --8004080352 IE insp Repis 50-317//9-24 / 50-318/79-23 on 791210-11
 Noncompliance noted several sys components including acidicaustic day tanks, caustic pumps // piping sys were corruded
 SHANBAKY, M M M. KOTTAN, J J Region 1, Philadelphia, Diffice of the
 Director BORES, R J Region 1, Philadelphia, Fuel Facility &
 Materials Safety Branch 80/02/07 Bpp
- 9247 Forwards IE Info Notice 80-12. "Instrument Failure Causes) of FORV & Block Valve " No specific actson or e necessary H Region 1, Philadelphia. Office of the Director
 - orwards IE Circular 80-05. "Emergency Diesel Generator On Add . Onsite Supply " No written

leighta, Office of the Director

ice 80-13. "GE Type SBM Control Switches written response required in Office of the Director

800424029J Forwards IE Info Notice 80-14 "Safety Suggestions From Configures "No action required ORIER.B H Region 1, Philadelphia, Office of the Director GO/Q4/02 Ip

- 8004180257 Forwards IE Circulat 80-07, 'Problems W/HPCI Turbine Oil Sys " No written response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/03 1p
- 8004230394 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Blainless Steel Pipe" Action required GRIER, B. H. Region I. Philadelphia. Office of the Director 80/04/04 1p
- 8004:80117 Forwards IE Bulletin 80-08. 'Exam of Containment Liner Penetration Helds " Written response required GRIER.B H. Region 1. Philadelphia. Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 8004210192 Forwards "Nonradiological Environ Monitoring Rept, Jan-Dec LUNDVALL, A E Beltimore Gas & Electric Co 80/03/14 1p
- --8004210197 "Nonradiological Environ Monitoring Rept. Jan-Dec 1979 " * Baltimore Gas & Electric Co * Academy of Natural Sciences of Philadelphia 80/03/1 400pp
- 8004070275 Forwards, "Radiological Environ Monitoring Program, Annual Rept.1979 " LUNDVALL, A.E. Baltimore Gas & Electric Co. 80/03/28 ip
- --8004070276 "Radjological Environ Monitoring Program Annual Rept.1979 " BARTAL, J., RAFI.A., REICHERT.E.C. Baltimore Gas & Electric Co BO/03/31 50pp
- G004250406 Forwards monthly operating repts for Har 1980 Correction to Feb 1980 monthly operating rept requested MERSON,S D Baltimore Gas & Electric Co 80/04/15 1p
- --8004250407 Monthly operating repts for Mar 1980 HERSON, S.D. Baltimore Gas & Electric Co. 80/04/14 18pp
- S Reportable occurrences, LERs & related correspondence
- 8004010437 Forwards LER 80-010/03L-0 RUBSELL,L B Baltmore Gas & Electric Co 80/03/24 1p
- --8004010448 LFR 80~010/03L-0 on 800224 during surveillance testing, control element assemblies 31 y 34 dropped into core Caused by fault in timer module Module replaced LAGIEMSKI, J S , BAUER, E R Saltimore Gas & Electric Co 80/03/24
- 8004010342 Forwards LER 80-001/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 80/03/25 1p
- --800401035; LER 80-001/03L-0 on 800225; atthough low pressure safety injection pump 21 was placed out of svc for maint, containment spray pump 21 was disassembled Caused by verbal communication error DAVIS.S M. PENCE.W B Baitimore Gas & Electric Co 80/03/25
- 8004010376 Forwards LER 80-019/02L-0 RUSSELL, B Baltimore Gas & Electric Co 80/03/25 1p
- --8004010383 LER 80 019/02L-0 on 800312, while performing QC insp, cable A2Y0929P was found incorrectly routed, which violated cable separation criteria Caused by personnel not following designed routing of cable Temporary cable installed BAUER.E R Baltimore Gas t Electric Co 80/03/25 ip
- 8004010380 Forwards LER 80-015/03L-0 RUSSELL,L B Baitimore Gas & Electric Co 80/03/25 ip
- --8004010369 LER 80-015/03L-0 on 900227, during maint, control element assembly 44 dropped into core Caused by electrician accidentally grounding prime 15 volt power supply Faulty backup power supply was changed LAGIENSXI, J S , BAUER, E R Baltimore Gas & Electric Co 80/03/25
- 8004010364 Forwards LER 80-016/03L-0 RUBBELL, L 8 Baltimore Gas & Electric Co 80/03/28 ip

DOCKETED ITEMS

- --8004010368 LER 80-016/03L-0 on 800303 emergency diesel generator 21 was placed out of svc after it failed to reach rated speed during start test Caused by diesel generator governor slow response Governor replaced all governors inspected DAVIS, 6 M . HUSEBY, D E Baltimore Gas % Electric Co 80/03/28
- 8004080480 Forwards LER 80-017/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/04/02 1p
- --8004080488 LER 80-013/03L-0 on 800303, channel 7F pressure input signal for steam generator isolation 22 was bypassed Caused by signal isolater 2 E/E-1023C being out of callbr due to nonlinear response HCIUEL, R P , RIZZO, P G Daltimore Gas & Electric Co 80/04/02 2pp
- 8004150483 Forwards LER 80-017/03L-0 RUBSELL, L B Haitimple Gas & Electric Co 80/04/10 1p
- --8004150486 LER 80-017/03L-0 on 800316, saltwater svc water heat exchanger 22 was taken out of svc Caused by need to repair tube leak found & plugged HEIBEL, R P , PENCE, W B Baltimore Gas & Electric Co 80/04/10
- 8004|50624 Forwards LER 80-018/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 80/04/10 1p
- --BOO4150438 LER BD-018/03L-0 on BOO311. during routine into tour, watch stander noticed leak weld on 23 changing pump suction relief valve causing degradation of sys designed to contain radioactive fluid Caused by vibration-induced metal fatigue DAVIB.S M. HUSEBY, D.E. Baitsmore Gas & Electric Co. 80/04/10 ip
- 8004210323 Submits info in confirmation of 800415 conversation w/RE Architzel re generic deficiency & FSAR. Section 14 3 concerning boron dilution incident Operating procedures will be changed to require min 2% subtdown margin DAVIS.8 M Baltimore Oas & Electric Co 80/04/16 1p
- 8004220745 Forwards LER 80-021/03L-0 RUBBELL, L B Baltimore Gas & Electric Co B0/04/18 1p
- ---B004220758 LER 80-021/03L-0 on 800318, during performance of surveillance test 23, saltuator pump did not start upon receipt of safety actuation signal Caused by faulty pin Pin replaced HEIBEL, R P , RIZZO, P G Dallimore Cas & Electric Co 80/04/18 200
- 8004250411 Forwards LER 60-020/03L-0 RUSSELL,L B Baltimoro Gas & Electric Co 60/04/18 1
- --8004250417 LER 80-020/03L-0 on 800320.during surveillance testing.
 channel D high power went into trip condition Malfunction
 stopped before cause could be determined
 LAOIEMBKI,P G Baltimore Oas & Electric Co 80/04/18 ip
- 8004290345 Forwards updated LER 79-001/03X-1 RUSBELL,L B Baltimore Gas & Electric Co 80/04/25 Ip
- --B004270350 Updated LER 77-001/03X-1 on 770104.RCS had unidentified leakage of 1 546 gpm exceeding Tack Spec Caused by cracked weld located on socket weld downstream of second isolation valve Weld repaired HUSEBY, D E , DAVIS, 8 M Baltimore Gas & Electric Co B0/04/25 2pp.
- 8004290410 Forwards updated LER 79-003/01X-2 RUSBELL, L B Baltimore Gas & Electric Co 80/04/25 ip
- --8004270416 Updated LER 79-003/01X-2 on 790120, reactor coolant pump 22A lower seal temp alarm activated & 2 gpm increase in leak rate noted Reactor manually tripped Caused by cracked weld on seal pressure sensing line Seal assembly replaced CARROLL.J D , HUSEBY.D E Baltimore Gas & Electric Co 80/04/25 is.
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

 C Utility Environmental Report (ER), amends & correspondence
- 8004210072 FOIA request on behalf of UCS for documents re venting of Kr-85 gas from facility containment LEAS, J. Union of Concerned Scientists 80/03/13, 2pp

- BOO4210069 Responds to FOIA request for documents to venting of Kr-85 gas from facility containment Documents listed in app are being placed in Washington.DC PDR FELTON.J I. Division of Rules and Records B0/04/09 2pp
- F Security, medical, emergency & rice protection plans
- 8004030162 Forwards index of recommendations appropriate for FEMA responsibilities to emergency preparadness planning around nuclear power plants b federal rule in responding to power emergencies ORIMES, B Emergency Preparedness Task Force 80/03/12 App
- 8004190350 Forwards Revision 6B to modified amended physical security plan Plan withheld (ref 100FR2 790) HERBEIN, J G - Metropolitan Edison Co - 80/94/02 - 1p
- B004300409 Advises that std market weather alert monitor is sufficient for use in notifying publicitegardless of on-off switch HERBEIN, J G Metropolitan Edison Co 80/04/25 1p
- G Adjudicatory correspondence
- /908300622 Opposes reopening of TMJ & nuclear power in general because of risk of genetic damage by high energy subatomic particles
 STOMELY:M F Affiliation Unknown 79/08/23 1p
- 8002040380 Criticites waste removal & decontamination efforts at TMJ Charges URC w/abuse of public opinion & feelings:coverup & insensitivity to problems caused by nuclear power JONES, D. Affiliation Unknown 80/01/25 7pp
- BOO4090192 Explains circumstances involving 800222 svc of BNWL draft rept re measurements of underground mining raden releases 6 NRC testimony of RH Wilde re same rept Missing Page 6 encl
 BORRENICK-B M Hearing Branch 4 80/03/05 App
- BOO4140061 Requests public hearing to evaluate proposed Tech Spets, App A to License DPR-73, NUREG-0432 Will determine whether Tech Specs are sufficient to protect public health & safety for duration of cipanup operations Certificate of Svc encl JOHNSRUD, J H Environmental Coalition on Nuclear Power 80/03/15
- ---9004140067 Emergency request for public hearing prior to alteration of current experimental & operational status of TMI-2 not in accordance w/Tech Spocs, App A Serious Tech Spocs violations have resulted in current degraded reactor core KEPFORD, C R Environmental Coalition on Nuclear Power 79/04/27 Spo
- --8004140075 Supplements 790427 emergency request for public hearing Receipt of petition has not been acknowledged by Director of Nuclear Reactor Regulation Supples submitted due to continuing crisis caused by 790328 accident KEPFORD, C Environmental Coalition on Nuclear Power 79/05/16
- 8004090056 Director's decision under 10CFR2 206 denying R Gary 800227 petition in which installation of cryopenic traps before radioactive gas venting was requested NUREG-0662 of Mar 1980 considered & recommended solution to issue DENTON, H R Office of Nuclear Reactor Regulation 80/03/18 2pp
- 8004110078 Request for hearing & petition for leave to intervene in evidentiary hearings on proposed Tech Specs Tech Specs may be inadequate, resulting in unusually large radiation releases Certificate of Svc encl LOCHSTET. W.A. Affiliation Unknown 80/03/18 4pp
- BOO4140111 Forwards Director's decision under 10CFR2 206, Request for action dtd BOO227, denied Petition dtd BOO225 under consideration DENTON, H R Office of Nuclear Reactor Regulation BO/03/18 ip
- --BOD4140117 Director's decision under 10CFR2 204 denying request that NRC require installation of cryogenic traps before planned venting of radioactive gas from TMI-2 DENTON.H R Office of Nuclear Reactor Regulation 80/03/18 Spp
- 8004110184 Requests hearing to determing whother requirements set forth in proposed Tech Specs are necessary & sufficient to protect public health & safety Tech Specs do not take into account hazards posed by continuing accident at TMI-2 SHOLLY, 8 C Affiliation Unknown 80/03/21 2pp

- #CO4090465 Muti in to upen toward for receipt of USUS 7.5 minute series maps PRC Enhibit 1 previously received as Enhibit 2.
 Transcript 247 Parties have no objection to motion
 Certificate of Sic enul
 LHANDLER L. J. Heating Kraich L. #D7/03/31 App
- 8004220008 Response in opposition to Environ Coalition on Nuclear Power 800315 petition for healing 7 for participation for Tech Spec anend Urges prompt assignment of wSLB 2 early scheduling of prehearing rotherence Certificate of Skc enc! SLBERG JE BERNSTEIN, by Metropolitan Edison Co. SILBERG JE Shaw, Pittnan Potts 7 Trombridge 80/03/31 9pp
- EOD4080574 Order granting NRC unopposed notion to reopen record for receipt of Exhibit 4 Order taken w/o MR Johnson participation BISHOP C J Atomic Sakety and Licensing Appeal Panel 80/04/01
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Soard notification GOSSICK, V Office of the Electrive Director for Operations CAMM, F Federal Emergency Management Agency 80/04/02 34pp
- 8004220102 Response in apposition to NA Lockstet 800318 request for hearing? For intervention re Tech Spec amends Urges prompt assignment of ASLS 5 early schedule of prehearing conference to deternire issue Certificate of Svc enci SILBERG.J E , BERNSTEIN D L Metropolitan Edison Co SILBERG.J E Shaw Pittman. Potts & Trowbridge 80/04/02 15pp
- 8004220405 Response to WA Lockstet request for hearing & petition to intervene Petition fails to neet code requirements re assertion of interest which may be affected by proceeding W/Certificate of Svc BERNSTEIN.D L Metropolitan Edison Co BERNSTEIN.D L Shaw. Pittman. Potts & Trowbridge 80/04/02 15pp
- BOO4070370 Response in support of Environ Coalition on Nuclear Power BOO315 request for hearing re Ofc or Nuclear Reactor Regulation BOO311 order Although deficient petition may be cured by filing required contentions W/Certificate of Svc BORDENICK.B M Hearing Branch 4 BO/04/04 7pp
- 8004090396 Response in support of WA Lochstet 800318 request for hearing & petition to intervene, per Ofc of Nuclear Reactor Regulation 800211 order Although partially deficient, petition may be cured Certificate of Svc encl BORDENICK.B M Hearing Branch 4 80/04/04 App
- 8004210085 Response stating no present apposition to SC Shoily 800321 request for hearing reinterest in Tech Spec amend proceeding Urges prompt assignment of ASLB 2 early scheduling of special prehearing conference SILBERG. JE . BERNSTEIN.D L Metropolitan Edison Co SILBERG. JE . Shaw. Pittman. Potts 8 Troubridge 80/04/07 4pp
- 304230084 Director's decision under 10CFR2 206 denying R Gary 800225 petition in which certain actions re radiation monitoring & energency planning were requested Decision will constitute final action unless Cornission institutes review in 20 days DENTON.H R Office of Nuclear Reactor Regulation 80/04/07 6pp
- 8004300508 Forwards Director's decision denying 800225 request for action re radiation monitoring & emergency planning at site DENTON, HR Office of Nuclear Reactor Regulation 80/04/07 ip
- --B004300519 Advises that two requests for action have been received from R Gary re radiation monitoring & emergency planning at site Both requests have no legal foundation & Director's decision should be issued immediately MURRAY.J P Office of the Executive Legal Director B0/03/10 2pp
- 800415022& Motion for extension until 800430 & 0526 per parties' agreement to submit post-hearing b reply memoranda, respectively, re aircraft crash probability issues Certificate of Svc encl CHANDLER.L J. TREBY.S A Hearing Branch 1 80/04/11 3pp
- 8004150499 Forwards adjudicatory hearing stipulation of settlement document re NPDES Permit 0009920
 HERBEIN, J 9 Metropolitan Edison Co 80/04/11 4pp
- 8004300020 Determination deciding that TMI-2 accident does not constitute extraordinary nuclear occurrence within meaning of Atomic Energy Act & Commission regulations
 AHEARNE.J F Commission B0/04/16 22pp

- 8004250373 Requests review ' reconsideration of 800407 Director's decision under 10CFR2 206 denying 800225 petition Interests of public health demand that cleanup be started at facility CARY.R Affiliation Univioum 80/04/10 2pp
- 8004280222 Order granting extension until 800507 for Commission to elect whether to review Director's 800407 decision denying enforcement action under 100FR2 206 Certificate of Svc encl CHILK.S J Office of the Secretary of the Commission 80/04/23 2pp

- 7908210247 Ark 790412 receipt of water sensor catalog Suggests that industrial butility users would be more appropriate recipients DENTON.HR Office of Nuclear Reactor Regulation 79/06/26 ip
- --7908210283 Forwards ratalog sheets to water lovel sensors Suggests application in teactor installations
 GRUENSFELLDER.K K F Industries.Inc 79/04/12 3pp
- 8004080106 Submits York County Board of Assistance resolution recommending that disaster evacuation plans for nuclear accidents be required to include adequate provisions to meet needs of indigent 5 Annicapped SIPE, L W York, PA /9/12/19 ip
- 8004020227 Responds to 790919 ltr expressing concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const Beyond licensing requirements, commercial operation is corporate decision VOLLMER.R H TMI-2 Operations/Bupport 80/02/05 2pp
- --8004020234 Expresses concern re NRC participation in decision to place reactor in operation & NRC monitoring activities of reactor const Ltr of 791024 to Met Ed expressing concern re Unit 1 restart encl EDMONSON.L D Affiliation Unknown 79/09/19 App
- 8004070200 FOIA request for info re facilities & damage due to earthquakes at Indian Point BEBAS,P G Affiliation Unknown 80/02/10 ip
- B004040300 Objects to radioactive discharges from units Officials irresponsible & not concerned w/public interest People must take immediate, unified action to gain control over environ & lives
 RENNO,E Affiliation Unknown B0/02/15 2pp
- B004040307 Opposes release of radwaste water into Susquehanna River FORREST, Z Affiliation Uninown 80/02/15 1p
- 8004040308 Objects to use of Susquehanna River as dumping site for radioactive matls Urges NRC to find other methods of disposing of waste OPPENHEIM.L Affiliation Unknown 80/02/15 ip
- 8004020286 Ack receipt of 800215 ltr commenting on programmatic EIB re decontamination to disposal of wastes from 790328 accident at site Comments will be considered Statement & name have been added to statement mailing list SELLS,DE Environmental Projects Branch 2 80/02/25 ip
- 8004020217 Responds to 790610 ltr expressing concern for annual insp of pressure relief valve Maint schedule provides for pressurizer relief valve testing approx once yearly during refueling outage

 DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 ip
- --8004020221 Expresses concern for annual inse of pressure relief valve GINTECK,P Affiliation Unknown 79/06/10 ip
- 8004040225 Responds to 790502 ltr requesting info re accident Several groups organized to identify safety concerns Compliance w/recommendations re reactor design analysis & operations will be required of nuclear plants

 DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 ip
- ~~8004040234 Requests info re accident CBNNER.D E Affiliation Unknown 79/05/02 ip
- 8004040247 Responds to 790723 comments on effects of accident Avorage exposure of population within 50 mile radius of TMI was approx 4 mrem Max exposure to any individual was less than 100 mrem which is less than normal annual exposure CENTON, H R Office of Nuclear Reactor Regulation 80/02/28 2pp

- --8004040257 Comments on effects of accident SNYDER, I E Affiliation Unknown 79/07 79/07/23 400
- 8004020456 Responds to 791207 ltr re facility licensing & discusses preparation of action plan for implementing safety objectives
 DENTON:H R Office of Nuclear Reactor Regulation 60/03/03 ip
- ---800402045B Requests re-evaluation of licensing moratorium & suggests individual review of proposed facilities
 MARCHAND,R Marchand Construction,Inc 80/03/03 1p
- 8004020461 Responds to 791203 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DOE 800125 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03
- --8004020465 Forwards JA Lehman 791203 ltr to President Carter discussing moratorium on issuance of CPs & DLs White House 791227 transmittal & EM Loggins (Gulf States Utils Co) 791119 ltr re-moratorium encl RATHKOPF, CL Energy, Dept of 80/01/25 7pp
- 8004030019 Responds to 791207 ltrie facility licensing & discusses preparation of action plan for implementing safety objectives
 DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/03 1p
- --8004030033 Urges lifting of licensing moratorium FISHER, J. R. Affiliation Unknown 79/12/07
- 8004030022 Responds to 791231 ltr re facility licensing & dicusses preparation of action plan for implementing safety objectives DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 ip
- --8004030028 Requests reversal of licensing moratorium & expeditious handling of nuclear energy development IRBY,8 C Affiliation Unknown 79/12/31 ip
- 8004030035 Responds to 791221 ltr re facility licensing & discusses preparation of action plan for implementing safety objectives DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/03 1p
- --8004030038 Urges recognition of nuclear industry initiative since accident & removal of licensing freeze
 JEANES, J W Affiliation Unknown 79/12/21 lp
- 6004030052 Responds to 791128 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Komeny Commission recommendations re YM investigation DOE 800122 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030054 Forwards LF Mogow 771128 ltr to President Carter discussing moratorium on issuance of CPs & QLs White House 771213 transmittal enc! RATHKOPF.C L. Energy Dept of 80/01/22 3pp
- 8004030061 Responds to 791126 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommondations re TMI investigation DDE 800125 memo encl DENTON.H R Office of Nuclear Reactor Regulation 60/03/03
- --8004030065 Forwards GM Henry itr to President Carter discussing moratorium on issuance of CPs & DLs White House 791204 transmittal encl Energy, Dept of 80/01/29 3pp
- 8004030087 Responds to 791206 ltr to President Carter expressing concern over moratorium on issuance of CPs & ULs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation IDE B00122 mena encl DENTON, H R Office of Nuclear Reactor Regulation B0/03/03 80/03/03 2pp
- --8004030093 Forwards RE Putfark 791206 ltr to President Carter discussing moratorium on issuance of CPs & OLs White House 791213 transmittal encl RATHKOPP.C L Energy Dept of 80/01/22 3pp
- BOO4030123 Responds to 790B16. Itr re plans to reopen TMI-i nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from TMI DENTON, H R Office of Nuclear Reactor Regulation BO/03/03 2pp

- --8004030129 Opposes restart of THI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety FOSTER. K Affiliation Unknown 79/08/16 2pp
- 8004040211 Responds to 791118 ltm to President Carter expressing concern over moratorium on issuance of CPs & GLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DGE 800122 memo encl DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- ---8004040237 Forwards P Stark 791118 ltr to President Carter discussing moratorium on issuance of CPs & OLs White House 791213 transmittal & Sam Disego Union news afficies encl RATHKOPF.C L Energy, Dept of 80/01/22 App
- BO04040214 Responds to 791113 Iti to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations or BMI investigation DOE B00125 memo enci DENTON-HR Office of Nuclear Reactor Regulation B0/03/03 2pp
- ---8004040245 Forwards WR Periault 79:113 ltr to President Carter discussing moratorium on issuance of CPs & OLs White House 79:1203 transmittal encl RATHKOPF,C L Energy.Dept of 80/01/25 3pp
- 8004040215 Responds to 791101 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DOE 800122 memo encl DENTON. H R Office of Nuclear Reactor Regulation 80/03/03
- --B004040248 Forwards M Russ 791101 1tr to President Carter discussing moratorium on issuance of CPs & QLs White House /91213 transmittal enc! RATHKOPF, C. Energy, Dept of 80/01/22 4pp
- BOO4040218 Responds to 791129 Its to President Carter expressing concern over moratorium on issuance of CPs & DLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DDE 800125 memo encl DENTON:H R Office of Nuclear Reactor Regulation 80/03/03
- -8004040265 Forwards FM Stasjesky 791129 1tr to Proxident Carter discussing moratorium on issuance of CPs & DLs White House 791227 transmittal encl RATHKOPH.C L Energy. Dept of 80/01/25 4pp
- 8004040219 Responds to 791121 Itr to President Carter expressing concern over moratorium on issuance of CPs & QLs Discusses transition period during implementation of Komeny Commission recommendations re TMI investigation DCF 800122 memo encl DENTON:HR Office of Nuclear Reactor Regulation 80/03/03
- --8004040253 Forwards El Nugent 791121 itr to President Carter discussing moratorium an issuance of CPs & OLs White House 791213 transmittal encil RATHKOPF,C L Energy,Dept of 80/01/22 3pp
- BO04040220 Responds to 791115 ltr to President Carter expressing concern over moratorium on assuance of CPs & DLs Dascusses transition period during amplementation of Kemeny Commission recommendations re TMI investigation DDE 800125 memo encl DENTON:H R Office of Nuclear Reactor Regulation 80/03/03 80/03/03 2pp
- --8004040258 Forwards WR Bledsoe 791115 ltr to President Carter discussing moratorium on issuance of CPs & OLs White House 791204 transmittal & Engineering News Record 791101 article encl RATHKOPF.C L Engigy.Dopt of 80/01/25 App
- 8004040223 Responds to 791121 ltr to President Cartor expressing concern over moratorium on issuance of CPs & DLs Discusses transition period during implementation of Kemeny Commission recommendations to TMI investigation DOE G00125 memo enci DENTON.H R Office of Nuclear Reactor Regulation 80/03/03 80/03/03 2pp
- ---8004040263 Forwards EM Page 791121 ltr to President Carter discussing moratorium on issuance of CPs & OLs White House 791204 transmittal & P Unch & J Udg article 'Personal Transportation Safety Evaluation of Evidence,' encl RATHKOPF.C L Energy.Dept of 80/01/25 App
- 8004220159 Responds to 800115 ltr Forwards Presidential statement on radwaste Two private nuclear energy liability insurance pools paid 13th annual refund of premium reserves to util policyholders NRC committed to public safety DENTON-HR Office of Nuclear Reactor Regulation 80/03/03 App

- --8004220162 Discusses need to resume facility licensing Newspaper article encl RAYMONDLU W Affiliation Unknown 80/01/15 2pp
- 60040300/0 Responds to 791126 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations ie TMI investigation DUE 600122 memo encl DENTON.H R Office of Nuclear Reactor Regulation 60/03/05 2pp
- --80040300/1 Forwards LJ Styslinger 791126 ltr to President Carter discussing moratorium on issuance of CPs & QLs White House 791213 transmittal enci RATHKOPF.C L. Energy.Dapt of 80/01/22 4pp
- 8004040202 Responds to 791128 ltr to President Carter expressing concern over moratorium on issuance of CPs & OLs Discusses transition period during implementation of Kemeny Commission recommendations re TMI investigation DUE 800122 memo encl DENTON: H R Office of Nuclear Reactor Regulation 80/03/05 2p
- --8004040233 Forwards G Esser 791128 lti to President Carter discussing moretorium on issuance of CPs & DLs White House 791213 transmittal % J Cook article "On Failure of Govt" encl RATHKOPF.C L Energy, Dept of BO/01/22 9pp
- 8004040421 Discusses transition period during implementation of Kemeny Commission recommendations of TMI investigation, in response to 791123 ltr to President Carter expressing concern over moratorium on issuance or CP 50L DDE 800122 memo encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/05 2pp
- --8004040431 Forwards JO Weigand 791123 ltr to President Carter re moratorium on issuance of CP & OL White House 791203 meno transmitting ltr encl RATHKOPF.C L Fnargy.Dept of 80/01/22 3pp
- 8004020127 Responds to 800125 ltr commenting on programmatic EIS redecontamination & disposal of raduastes Comments will be considered in preparation of statement
 SELLS.D E Environmental Projects Branch 2 80/03/10 lp
- 8004030265 Responds to 800121 lfr expressing concern re radwaste disposal & emergency response Preparation of programmatic EIS on decontamination & radwaste disposal underway Ltrencl
 SELLS,D E Environmental Projects Branch 2 80/03/10 1p
- 8004090268 Responds to 800207 ltr commenting on programmatic EIS reducantamination & dispose) of radwastes Comments will be considered in preparation of statement SELLS, D.E. Environmental Projects Branch 2 80/03/10 ip
- --BO04090274 Comments on programmatic EIS re decontamination & disposal of radwastes Statement should consider interstate agreements between MD-PA'S IRC to assure cooperation in manitoring across state lines & in Susquehanna River KOMALCZYK.W J Affiliation Unknown BD/02/27 2pp
- 3004090276 Responds to 800218 ltr commenting on programmatic EIS re decontamination / disposa) of radwastes Comments will be considered in preparation of statement BELLS,D E Environmental Projects Branch 2 80/03/10 [p
- --8004090279 Submits comments made at 800215 meeting in Baltimore, MD re programmatic EIS on decontamination / disposal of radwastes Important factors, such as NRC 5 util authority, have not been sufficiently examined KRIEMELMEYER, H. Kriemlmeyer, H. 80/02/18 1p
- 8004110096 Expresses concern over possible effects of release of krypton gas from racility PETRILLO.M Affiliation Unknown 80/03/11 2pp
- 8004030153 Responds to 800306 request for EIS re decentamination & disposal of radwaste resulting from facility incident DES has not been published Scheduled issuance is in June 1980 Cogies will be forwarded SELLS.D E Environmental Projects Branch 2 80/03/12 to
- --8004030156 Requests 2 copies of E18 for alternative waste proposal for radwaste from facility incident MERCURI.J Western Washington State College 60/03/06 ip
- B004220136 Ack receipt of 791106 ltr criticizing nuclear power safety Forwards 791207 press release re Kemeny rept on TH1 Also forwards 791207 fact sheet re Presidential response to Memeny Commission recommendations DENTON; HR Office of Nuclear Reactor Regulation 80/03/03 16pp

- --8004220143 Forwards JC Sinclair 791106 ltm to President Carter for reply Ltm misdirected to DDE RATHKOPF,C L. Energy,Dept of 80/01/22 3pp
- 8004040230 Ack receipt of D Burgess 800215 comments for programmatic EIS on decontamination / disphosal of raduaste from TMI accident Comments considered in preparation of EIS SELLS.D E Environmental Projects Branch 2 80/03/17 ip
- 8004280267 Comments on 'Environ Assessment for Decontamination of Site Contamination Bidg Atmosphere "Public hearing would be in order before final action Expeditious action needed, but not at cost of public health ". safety CRUMLEY, J Affiliation Unknown 80/03/18 ip
- 80042103B1 Responds to ltr re permanent shutdown of facility, cleanup of waste & payment of expenses concerning accident Dry wastes are packed in steel drums % shipped to burial sites Util customers do not pay for facility restoration DENTON, HR Office of Nuclear Reactor Regulation 80/03/19 2pp
- --8004210391 Opposes reopening of Unit 1 Expresses concern re mgt & storage of waste matts > payment of incurred costs
 KELLY.P Affiliation Unknown 79/08/14 ip
- 8004210376 Ack receipt of)trs re facility Public hearing to be conducted to determine whether Facility should be operated Will conduct review of technical info on restait Forwards Commission order W/o encl DENTON: H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- 8004220112 Responds to 791227 ltr to President Carter Forwards Presidentia) statement on Kemeny Commission rept Every effort being made to protoct public health & safety at all nuclear power plants DENTON.H R Office of Nuclear Reactor Regulation 80/03/19 4pp
- --B004220124 Forwards D Funderud 791227 ltr to President Carter for reply Ltr misdirected to DOE RATHKOPF,C L Emergy,Dept of 80/01/25 3pp
- BOO422016B Responds to 790617 ltr re Unit 1 Every effort being made to protect public health to safety at all nuclear power plants currently operating or planned for operation Restart hearing has not yet begun

 DENTON: HR Office of Nuclear Reactor Regulation BO/03/17 ip
- --8004220171 Requests adherence to regulatory directives
 PHILLIPS.L B , PHILLIPS.V Affiliation Unknown 79/06/17 ip
- 8004220182 Responds to encl 770522 ltr to President Carter requesting facility shutdown Every effort being made to protect public health & safety at all nuclear power plants in operation or planned for operation BENTON. HR Defice of Nuclear Reactor Regulation 80/03/19 4pp
- 8004220185 Responds to 791002 ltr to President Carter urging that Americans be informed of useful lessons manifested by Kemeny Commission study Forwards Presidential public statement on Kemeny ropt DENTON-H R Office of Nuclear Reactor Regulation 80/03/19 4pp
- ---8004220191 Forwards FL McMillan 791002 ltr to President Carter for reply Ltr misdirected to DOE RATHKOPF.C L. Energy, Dept of 80/01/22 3pp
- 8004240270 Responds to 790815 ltr to Hendrie re concerns of polluting environ through EPICOR-11 sys Method is limited to decontamination of waste water Processing will not remove all radioactivity
 DENTON.H R Office of Nuclear Reactor Regulation 80/03/19 ip
- --8004240282 Expresses concern re use of EPICOR-II sys to process water when NRC admits use will involve exposing plant workers to radiation & release Xe-133 & 1-131 to environ
 GILBERT.R S Affiliation Unknown 79/08/15 1p
- 8004240441 Responds to 790B15 ltr expressing concern re pollution of environ by use of EPICOR-II sys Sys will clean water in auxiliary bldg to extent that no further risk will be posed Environ assessment will be issued prior to disposal DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 Zpp
- --8004240447 Expresses concern re plans for disposal of contaminated water at TMI-2 Use of EPICOR-II sys will politic environ & expose workers to radiation
 OILBERT,R S Affiliation Unknown 79/08/15 ip

- 8004250111 Responds to 790508 ltr & newspaper column re accident & advises that no Pu was released DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- B0042B0260 Responds to 790B06 ltr suggesting ways to improve security at facilities * advises that compliance w/l0CFR73 55 & ANSI 18 17 protects against sabotage & unsatisfactory personnel, respectively
 DENTON, H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- --8004280268 Urges mandatory internal program be set up to screen potential employees for saboteurs & incompetents GORDON,L. Affiliation Unknown 79/08/06 ip
- 8004280273 Responds to 790902 ltr to President Carter re accident & forwards NUREG-0558. "Population Dose & Health Impact of Accident" & NUREG-0600 "Investigation into 800328 Accident t" & NUMES-1999 2.... W/o encl H R Office of Nuclear Reactor Regulation BO/03/19 3pp DENTON, H R
- BOO4280279 Responds to 790423 ltr to President Carter re health effects of accident 3 advises that NRC investigators concluded offsite collective radioactive dose was minimally risky Summaries of NUREO-0558 5 0600 encl M/o encl
 DENTON.H R Office of Nuclear Reactor Regulation BO/03/19 4pp
- 8004280289 Responds to 790416 itr urging permanent shutdown of facility & advises that public hearing & technical review will take place before restart Licensee's authority to operate Unit 2 suspended by 790720 order DENTON, HR Office of Nuclear Reactor Regulation 80/03/19 3pp
- --B004280303 Urges permanent closing of facility to avoid nuclear destruction NEIDIG.M Affiliation Unknown 79/04/16 1p
- BOO42B0325 Responds to ltr to Commissioner Hendrie re dumping of radioactive water into Susquehanna River Releases of contaminated water are not currently permitted except for liquids containing low or nondetectable radiation levels DENTON, H R Office of Nuclear Reactor Regulation 80/03/17 80/03/19 2pp
- --8004280337 Opposes dumping of radioactive water into Busquehanna River NRC action represents malicious disregard for well-being of humanity Urges proper permanent disposal of radwaste BUSSER, M A Affiliation Unknown 80/03/19 ip
- G004280527 Responds to postcard urging permanent closing of facility & advises that no radiation induced deaths have occurred Notifies of public hearing & technical review planned before restart Forwards 790809 notice of hearing W/o encl DENTON, H R Office of Nuclear Reactor Regulation BD/03/19 3pp
- --8004280532 Urges permanent closing of facility & expresses fear re health effects of accident HEITMULLER, H Affiliation Unknown 79/06/11 ip
- 8004280535 Responds to 790328 request for publications re accident investigation & discussos repts & availability Summaries of NUREO-0600 & 0558 encl W/o encl DENTON.H R Office of Nuclear Reactor Regulation B0/03/19 3pp
- --8004280540 Requests rept on accident investigation when available KIMBLE, K. Affiliation Unknown 79/03/28 2pp
- 8004280542 Responds to 790410 request for info re NRC decision to license facility on 781230 & advises that Met Ed was issued CL several months prior to full generation BOY03/19 2pp DENTON/H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- --8004280545 Protests NRC decision to license facility on 781230 to save util taxes & requests access to subj info ESTRADA.P San Luis Obispo.CA 79/04/10 2pp
- 8004290064 Responds to 790510 ltr to NRC re facility accident In May 1977,NRC adopted resident inspector program Inspectors are presently assigned to approx 30 sites Nuclear plants are equipped w/numerous alarms & automatic shutdown equipment DENTON,H R Office of Nuclear Reactor Regulation 80/03/19 5pp
- -8004270048 Requests info re facility accident, including presence of govt inspectors at nuclear facilities, effectiveness of plant warning systresponsibility for accident & actions taken by foreign countries in post-TMI period YURLSICH.B Affiliation Unknown 79/05/10 2pp

- 8004270076 Responds to Iti te disposal of radioactive water from TMI-2 Release of contaminated water into Susquehanna River is not currently permitted except for liquids containing low or nondetectable levels of radioactivity DENTON.H R Office of Nuclear Reactor Regulation 80/03/19 2pp
- ---8004290083 Opposes releases or radioactive water from THI-2 into Susquehanna River NRC is trying to save nuclear industry w/o regard to interests of public BROUDE, if Affiliation Unhown 80/03/19 ip
- 8004070350 Opposes proposed release of radioactive gases into atmosphere 8 water into Susquehanna River WALTERS, E. Environmental Policy Center 80/03/20 2pp
- 8004210406 Requests that no action be taken before facility status is changed to recovery made MANFRED, K.M. Affiliation Unknown 80/03/20 ip
- 8004140091 Forwards requested copy of NRC comments on Heidelberg Rept June 1977 & Dec 1978 memos on strontium monitoring also encl W/o encls TMI-2 Operations/Support 60/03/21
- BOO4210402 Responds to 79041B postcards opposing resumption of operation of facility Every effort being made to protect public health & safety at all nuclear power plants currently operating or planned for operation DENTDN.K R Office of Nuclean Reactor Regulation 80/03/22
- ---BOO4210403 Protests reopening of facility MASTER,N Affiliation Unknown 79/06/18 1p
- 8004210356 Responds to 790904 lir is release of Kr-851 from facility Util "Safety Analysis & Environ Rept" states that optimum choice for release of Kr-851 is atmospheric dispersion through controlled purging of reactor bldy atmosphere DENTON, HR Office of Nuclear Reactor Regulation 80/03/24 2pp
- --8004210360 Opposes reopening of facility % release of Kr-85 into atmosphere Requests plans for disposal of waste LECNARD, J. Affiliation Unknown 79/09/04 ip
- 8004210363 Responds to it; re holding of public hearings on facilities Commission has ordered that public hearing be conducted to determine whether Unit 1 should be operated Will conduct review of technical info on restart
 DENTONIH R Office of Nuclear Reactor Regulation BO/03/24 2pp
- --8004210373 Expresses conviction that public hearings must be held in communities within 25-mile radius of facility site LYONG, E Affiliation Unknown 79/07/23 2pp
- 800421039B Responds to 800222 Itr inquiring whether ECCS for PWRs have been changed after TMI incident Short-term requirements implemented for PWRs, none of which is "more powerful safety injection sus." injection sys "
 MATTSON, R J Division of Systems Safety 80/03/24
- -8004210399 Inquires whether FCCS for PWRs have been changed following TMI accident, list of changes, reasons & analytica) basis & repts on changes WEBB.R E Affiliation Unknown 80/02/22 ip
- 8004280342 Responds to 791630 ltr to NRC re TMI NRC has ordered public hearing to determine whether TMI-1 should be restarted Licensee authority to operate Unit 2 was suspended by NRC 790720 order DENTON,H R Office of Nuclear Reactor Regulation 80/03/24 2pp
- -8004280350 Opposes reopening of TMI due to health hazard posed to area residents Requests info re plans to dispose of radioactive water which flooded reactor Hater may freeze in winter b burst containment walls

 GAMBIRO
- 8004280357 Responds to encl 790404 ltr to President Carter re facility After chemically inert noble gases entered auxiliary & fuel handling blogs release to atmosphere was inevitable All licenses required to leaf—test sys outside reactor bldg DENTON: HR Office of Nuclear Reactor Regulation 80/03/24 4pp
- B004280550 Responds to 770401 mailgram supporting UCS position for immediate evacuation of residents within 30 mile radius of TMI & shutdown of other B&W PWRs Radioactive releases did not warrant evacuation Doses averaged less than on jet trip DENTON, H R Office of Nuclear Reactor Regulation 80/03/24

- --8004280553 Supports UCS position for immediate evacuation of residents within 30 mile radiu. of TMI 5 shutdown of all BPM PWRs

 ★ Friends United for Safe Energy 79/04/01 2pp
- BO04280565 Responds to 740502 ltr to President Cartei re facility restart & advises that public hearing & technical review will rirst take place licensee is conducting feasibility studies re Unit 2 jecovery DENTOR; H Ofrice of Nuclear Reactor Regulation 80/03/24 App
- B004150407 Forwards comments re NRC draft environ assessment for decontamination of reactor bldg atmosphere Environ assessment lacks perspective required for public to understand significance or proposed action FREDRICKSON.C Affiliation Unknown B0/03/25 4pp
- 8004180442 Forwards NURE9-0991 "Environ Assessment for Use of EPICOR-II at TMI.Unit 2 " VOLUMER.R M TMI-2 Operations/Support 80/03/25 1p
- 8004210319 Forwards NUREG-0591 "Environ Assessment for use of EPICOR-II at THI.Unit 2 ' W/o encl VOLLMER.R H TMT-2 Operations/Support 60/03/25 [p
- 8004210324 Forwards NUREG-0591 "En.ison Assessment for use of EPICOR-II at TMI,Unit 2 ' W/o encl VOLLMER.R H TMI-2 Operations/Support 80/03/25 1p
- 8004210332 Forwards NURE9-059) "Environ Assessment for Use of EPICOR-II at TMI.Vit 2 "W/o enc! VOLLMER.R H TMI-2 Operations/Support 80/03/25 ip
- 8004210333 Forwards NUREC-0591 'Environ Assessment for Use of EPICOR-II at TM1.Unit 2 " W/o encl VDLLMER.R H TM1-2 Operations/Support 80/03/25 ip
- 8004210337 Forwards NUREU-0591 "Environ Assessment for Use of EPICOR-II at TMT.Unit 2 " W/o encl VOLLMER.R H TM1-2 Operations/Support 80/03/25 1p
- B004210338 Forwards NUREG-0591 "Environ Assessment for Use of EPICOR-II at TM1.Unit 2 " W/o encl VOLLMER.R H TM1-2 Operations/Support 80/03/25 1p
- 8004100574 Responds to 770615 lit restart up of reactor Noth Units 1 & 2 shut down Unit 2 where accident occurred will be shut down for some time NRC hearings to ascertain safety of Unit 1 will be conducted before starfup DENTON, H R Office of Nuclear Reactor Regulation 60/03/27 ip
- --B004100578 Requests info re startup of Unit 1 NRC should be investigating competence of util to have reactor license Presidential Commission rept should be studied Questions NRC concern for safety
 HOSTETTER.J J Affiliation Unknown 79/06/15 1p
- 8004100581 Responds to 791212 Its re-computers & safety stds used in nuclear power plants Digital computers used for monitoring operations & core protection calculator sys provides protection functions

 DENTON.H 8 Office of Nuclear Reactor Regulation 80/03/27 ip
- --B0041005B2 Requests info re reliablility of computers that control nuclear plants % safety stds since accident BRADSHAW.M Affiliation Unknown 79/12/12 1p
- BOO4020324 Comments on Els re decontamination & cleanup activities Cost should not be significant factor in selection of cleanup processes or methods
 HOLTAN, A A Affiliation Unknown BO/03/28 2pp
- 8004070340 Requests NRC deny util right to release Krypton gases from damaged reactor People are expected to pity owners re costly cleanup & allow further crippling of environ AHENGER.L Affiliation Uninown 80/03/28 2pp
- 8004100973 Responds to 791214 ltr to President re view on nuclear energy Carter 791207 statement enc! Radiation doses resulting from accident will not cause detectable addl cases of cancer of carter DENTON-H R Office of Nuclear Reactor Regulation 80/03/28 ip
- --8004100575 forwards misdirected Barry 79:214 ltr to President re views on nuclear energy RATHKOPF,C L Energy, Dept of 80/01/25 Spp

- 8004040294 Uiges permanent closure Recommends using util as training site for experimental equipment & decommissioning procedures
 TEETS.T A . TEETS.R A Affiliation Unknown 80/03/29 1p
- 8004040320 Ack receipt of 800118 ltr re statement of policy & notice of intent to prepare programatic EIS EIS not yet received & final decision to dump radioactive gases & liquids set for 800408 Protests release & recommends entombeent BROSS, I D Roswell Park Memorial Institute 80/03/31 3pp
- B004090357 Urges NRC to provide educational matls in effort to educate public on nuclear energy Educated public is only way for fair decision re future of nuclear energy, restart of TMI-1 & cleanup of TMI-2 SNYDER, M O Affiliation Unknown 80/03/31 2pp
- 8004240253 Responds to 800209 ltr to HR Denton Documents published by or funded by NRC are in public domain W/o enti NUREO/CR-1093. "I'MI Telephone Survey" & NUREG/CR-1215. "Social & Economic Effects at THI" ERNST, M L Division of Site Safety & Environmental Analysis 80/03/31 ip
- B004280558 Advises that name of TMI organization has been changed to TMI Program Ofc B Snyder is program manager in Bethesda & JT Collins is deputy program manager at TMI Official correspondence should reflect change COLLINS, J T NRC Three Mile Island Task Force B0/04/01 4pp
- 8004020377 Requests consideration of certain factors in preparing EIB, including public mental & physical health effect of low level radiation on radio & television transmission of radioactive releases on photographic matis

 WHITCOMB, D Affiliation Unknown 80/04/02 6pp
- 8004220173 Ark receipt of ltr re financial situation of General Public Utils NRC does not regulate rates charged by electrical utils NRC is conducting hearing to determine whether TMI-1 can be restarted while TMI-2 cleanup proceeds OILINSKY,V Commission 80/04/02, ip
- --8004220191 Urges NRC to expedite rate relief requested by General Public Utils & return TMI-1 to svc Unfair treatment accorded to General Public Utils has encouraged demonstrators LESH.L Affiliation Unknown 80/03/24 2pp
- 8004190400 Submits suggestions re implementation of EIS Board of citizens, consisting of persons unknown to NRC, doctors, veterinarians & physicists, should participate in preparation of EIS No krypton should be vented into atmosphere KUEHNLE, G Affiliation Unknown 80/04/03 2pp
- 8D04290049 Responds to 790823 ltr re nuclear fission & biological effects of radiation EPA Occupational Safety & Health Administration & NRC are responsible for regulating exposure to radiation or radioactive mat!

 DENTON, H R Office of Nuclear Reactor Regulation 80/04/03 2pp
- 8004180372 Urges funding so that independent specialists can review & comment on all EIB Comments on NUREO-0662 EIB was announced eight months after facility accident Alternative to venting should have been developed in Apr 1979
 HOSSLER, D E Affiliation Unknown 80/04/06 3pp
- 8004230283 Responds to 800317 congressional referral of ltr re util failure to accept loan of cryogenic processing sys from Limerick facility rather than purging to atomosphere Purging chosen for expedience DENTON.H R Office of huclear Reactor Regulation 80/04/07 2pp
- BOO41BO431 Responds to BOO214 ltrs re meteorological monitoring Monitoring program fully operational during TMI-2 incident Activities underway to enhance response capability & review development of deployable instrument package DENTON.R Office of Nuclear Reactor Regulation BO/04/08 3pp
- ---B004180439 Expresses concern for public safety following discharge of radioactivity into atmosphere Company atmospheric sounding techniques which track wind field containing radioactivity could provide info crucial to public safety

 OILMORE.D W Beukers Laboratories. Inc B0/02/14 2pp
- 8004140348 Comments on NUREO-0462 Criticizes selection of ANLS as contractor for TMI EIB, inadequate public participation process, insufficient consultation & absence of mechanism for independent review of purge proposal BURGESB, D Affiliation Unknown 80/04/09 2pp

- 8004170040 Comments on Addendum 2 to NUREG-0662 Supports rapid cleanup of TMI-2, including prompt venting of Kr-85 Criticizes NRC for failure to make decisions quickly & communicate adequately to public HOWARD, A S Affiliation Unknown 80/04/09 1p
- 8004150478 Forwards updated svc copy distribution list for facilities Notifies that OK Hovey has replaced RF Wilson as director of Unit 2
 ARNOLD, R C Metropolitan Edison Co 80/04/10 5pp
- 8004220569 Comments on NRC "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere " Opposes venting due to lack of trust in NRC to ensure that public interest is primary consideration in decisionmaking RICHTER.T Affiliation Unknown 80/04/14 2pp
- 8004220418 Expresses opposition to venting of krypton gas Util has not researched all methods & presented intelligent explanation for each method Reasons for using venting presented only after public produing BEVEL.K A Affiliation Unknown 80/04/15 2pp
- 8004230514 Comments on "Frviron Assessment of TMI Reactor Bldg Atmosphere "Technical explanations of alternatives will make no difference on attitudes of residents near facility Strategy to regain credibility should be foremost issue GUARANTELLI.E Ohio State Univ 80/04/16 2pp
- 8004290188 Responds to FOIA request for rept to inventory of TMI containment radwastes % disposition planned for each inventory Forwards documents listed in App A W/o encls FELTON, J M Division of Rules and Records 80/04/17 1p
- 7908010475 Forwards 790515 1tr re TMI incident BHANK.M J Affiliation Unknown 79/07/20
- ---7908010479 Expresses approciation for HR Denton's assistance during TMI incident Opposes plant reopening SHANK, R B , SHANK, M J Affiliation Unknown 79/05/15 1p
- I Financial information
- 8004030241 Forwards update to util 800219 ltr re projected 1980 cash flow forecast, reflecting recent rate relief Company is able to meet max retrospective premium HERBEIN, J O Metropolitan Eduson Co 80/03/31 3pp
- B004070477 Forwards supplementary financial info in support of TMI-i restart proceedings
 HAFER, F D General Public III-ilities QPU Service Corp 80/04/03
- --8004090478 Transcript of PA Public Util Commission 800213 hearing in Harrisburg,PA Pp 1.743-2,143 SHANAMAN,S Pennsylvania, State of RUSSELL,S B, BELTZER,A M Ryan, Russell & McConaghy 80/04/03
- --8004090479 Transcript of PA Public Util Commission 800227 hearing in Harrisburg,PA Pp 2,494-2,327A SHANAMAN,S Pennsylvania, State of RUSSELL,S D , SELTZER,A M Ryan, Russell & McConaghy 80/04/03 37pp
- ---8004090480 Transcript of PA Public Util Commission 800220 hearing in Harrisburg.PA Pp 2.828-2.682 BHANAMAN.S Peunsylvania. State of RUSSELL,S B . SELTZER.A M Ryan. Russell & McConaghy 80/04/03 154pp
- --8004090481 Transcript of PA Public Util Commission 800318 hearing in Harrisburg.PA Pp 3.217-3.419 SHANAMAN.S Pennsylvania. State of RUSSELL.8 II., SELTZER.A M Ryan. Russell & McConaghy 80/04/03 204pp
- --8004090482 Annual Financial Rept 1979 * General Public Utilities GPU Bervice Corp * Jer Power & Light Co * Metropolitan Edison Co 80/04/03 Jersey Central 1/03 44pp
- ---B004090483 "Proposal to Conduct Analysis of Strategic Options for JCP&L " * Arthur Young & Co 80/02/29 125pp
- ---B004070484 "TMI-2 Coal Burning Plant Summary of Study of Converting TMI-2 to Fossil-Fueled Plant " # Oilbert/Commonwealth Cos 80/02/25 13pp

- 8004280630 Forwards Net Ed certified Annual Financial Rept 1979 & General Public Utils Corp certified Annual Financial Rept 1979 * certified 'Uniform Statistical Rept.1979 * HERBEIN, J G Metropolitan Cison Co
- --8004280633 Certified Annual Financial Rept 1979
 * Metropolitan Edison Co 80/03/07 27pp
- ---8004280638 Certified Annual Financial Rept 1979 Certified "Uniform Statistical Rept.1977' encl * General Public Utilities GPU Service Corp 80/04/22 71pp
- D. Advisory Committee on Reactor Sateguards reports & correspondence
- 8004030260 Forwards certified minutes of 790905 ACRS meeting of Ad Hoc Subcommittee on TMI Accident Implications for attachment to 790927 minutes TAMLP ACRS Advisory Committee on Reactor Safeguards 79/11/13
- --8004030264 Summary of ACRS 790905 Ad Hoc Subcommittee on THI Accident Implications meeting

 * ACRS Advisory Committee on Reactor Safeguards 79/11/07
- 8004100508 Forwards certified minutes of ACRS Ad Hoc Subcommittee meeting is TM1-2 accident implications MA-JORR K. ACRS Advisory Committee on Reactor Safeguards 80/03/04 1p
- --8004100512 Certified summary of ACRS Ad Hoc Subcommittee 791105 meeting in Washington, DC re implications of TMI-2 790328 accident for plant design, policy & criteria # ACRS Advisory Committee on Reactor Safeguards 80/01/08
- ---8004100517 Discusses sensitivity studies of B&W reactor designs to transients 3 accidents DENTON, II R Office of Nucleal Reactor Regulation 79/10/25 2pp
- --8004100521 Discusses development of general framework for conduct of limited ris' assessment of B'W reactor aimed at identifying unique risk-impacting sequences re reactor safety study MURPHY,J A. TAYLOR,M A. Probabilistic Analysis Branch (Pre 791030) 79/10/04 L&pp
- ~B004100530 Forwards response to question laised during ACRS Subcommittee 791003 meeting re THI-2 implications for potential pressurizer pressure boundary failure if pressurizer heaters become uncovered & overheated HATTSON.R J Division of Systems Safety 79/11/05 7pp
- 8004100375 Forwards certified minutes of ACRS Ad Hoc Subcommittee 791003 meeting re TM1-2 accident implications MAJDR.R ACRS Advisory Committee on Reactor Safeguards 80/01/04
- --80041003Bl Certified summary of ACRS Ad Hoc Subcommittee 791003 meeting in Washington, DC re TMI-2 accident implications for plant design # ACRS Advisory Committee on Reactor Safeguards 79/12/07 19pp
- P Operating license stage documents & correspondence
- 8004040231 Advises that util presently reviewing proposed interim solid radwaste staging facility Will forward proposal by 800331 WILSON, R F Metropolitan Edison Co 80/03/03 1p
- SOO4040318 Discusses proposal for removing balance of plant diesel generators as backup sources to circulating water & condensate pumps Schedule for removing diesel generators from svc is early Apr 1980 WILSON,R F Metropolitan Edison Co 80/03/04 App
- 8004040321 Responds to JT Collins 800130 comments re personnel air lock contamination control facility design description Radiation monitor installed in ante roum & monitors particulate, iodine & noble gas activity WILSON,R F Metropolitan Edison Co 80/03/04 2pp
- 8004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned corrective actions also encl DENTON, HR Office of Nuclear Reactor Regulation 80/03/06 26pp

- * The transplant of the state of the stat
- * in46/4/141) Req ests permis in an original three madesste packages of EMICO I I must liner with a limiting of shipment ban Personnel and it is a maniferency of transport received training year mathematical form 77.17 William F. Mathepalitan edition of 20/03/07. 3pp
- OCHAPTO 11 Mak reveipt in ropt at Golernor's commission on TMI Commends
 Golmany, in the ers for tirst class work
 HENDRIF & 1 Commends (1990)
- ± 0.0 (4),/2015 refus. Some time series a Commission on TM1 W/o enclassion in W W Pennsyl et la State of -80/02/26-1p
- FCO41065W Forwards inquiry e alumbian or licensed performance re #300211 [.c.a] e-eigency / di0212 JB minor gaseous leak Addl review will be done for my subsequent monitoring activities Cortain area examined and subj to enforcement actions COLL NO 17 Errivent Treatment Systems Branch 80/03/10 25pp
- BOU4080121 Forwards NRC TMI weekly status mept inquid effluents from TMI-1 meleased to Susquehams River, after processing were within limits specified in Tech Specs No liquid effluents were dischaiged from TMI-2 COLLINS J I TMI-2 Operations/Support BO/03/11 App
- BDO4070061 Peromends authorization or controlled purging of reactor bldg 2 that licenses be directed to propose method for purging over shorter time period than currently proposed 60 days

 DENTON H R Office of Nuclear Reactor Regulation SECY-80-132 BO/03/11 Spp
- 8004020476 Forwards marked-up replacement pages to Braft 3a of action plan, reflecting change in Task J D 3 from Decision Group B to C. clarifying that education requirements portion of Task I A 2 is Group C 5, submitting nissing Task I G 2 MATTSON.R J Division of Systems Garety 80/03/12 37pp
- BOO4030102 Forward: "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Dethesda Operations Ctr ETSENHUT.D G Disision of Operating Reactors 80/03/12 Spp
- --8004030118 Nuclear Data Lint Specs "
 Division of Operating Reactors 80/02/21 28pp
- 8004036272 Forwards Amend In thillicense DPR-73 revising App B Tech Specs re operation of EFICOR-11 filtration & ion exchange descantamination sys to decontaminate intermediate level radwaste in doublinary bldg VDLLMER R H - 1MI-2 Operations/Support 80/03/12 4pp
- --8004030279 Amend 10 to License DPR-73 revising App B Tech Specs re operation of EPICOR-11 filtration 5 ion exchange decontamination sys to decontaminate intermediate level raduaste in auxiliary bldg VOLLMER 8 H IMI-2 Operations/Support 80/03/12 10pp
- --8004030283 Notice of issuance & availability of Amend 10 to License DPR-73 VOLLMER R H TMI-2 Operations/Support 80/03/12 3pp
- 8004080128 Ack receipt of /71219 ltr to Lieutenant Governor Scranton, transmitting York County Board of Assistance resolution respectal provisions in nuclear evacuation plans for indigent & handicapped MRC endories end NUREG-0376 N/o end GRIMES. BK Assistant Director for Engineering & Projects 800/03/12 1p
- 8004090176 FDIA request to records re TMI-2 including OL application, CP application % amends
 ENGELHARDT T W Peterson, Ross & Schloerb & Seidel B0/03/13 ip
- 8004100499 Submits EPA preliminary data rept on air & water sampling for 800305-12 Gamma rate recorder data entl SMITH.A E Environmental Protection Agency 80/03/13 22p
- BOO4010344 Supports use of data from Channel AM-5 for quantification of radings releases Errors involved in averaging data from three monitors greater than from one AM-5 calibr is traceable to NSS krypton 2 ienon stds
 WILSON.RF Metropolitan Edison Go 60/03/21 3pp

- EUU-1100-19a Forwards comment/resolution re proposed Surveillance Procedure 4303-M22, secondary svc closed cooling water pump operability test Requests that procedures be revised to provide more definitive acceptance criteria COLLINS. J.T. Effluent Treatment Systems Branch 80/03/21 5pp
- 8004100385 Responds to RF Wilson 600321 ltr re request to enter reactor bldg prior to purging Entity denied until util provides documentation showing confairment atmosphere will sustain life in event or malfunction or respiratory equipment COLLIFS. J T Division of Site Safety & Environmental Analysis 80/03/25 3pp
- 8004100502 Denies 800321 request re permission to enter reactor hldg prior to purging Util must provide documentation to show that containment atmosphere will sustain life Addl data required re existence or boric contaminants COLLINS.J T Effluent Treatment Systems Branch 80/03/25 5pp
- 8004160034 Forwards 800324 ltr rept from GL Pollack of MI State Univ re alternatives for handling krypton in containment as described in NRC environ assessment GILINBKY.V Commission 60703726 ip
- --8004160037 Discusses alternative methods for removing Kr-85 From atmosphere or reactor bldg Best method is selective absorption process sys Second best method is cryogenic process sys FOLLACK, G.L. Michigan State Univ 80/03/24 App
- 8004170299 Forwards, per 800326 telcon. SECY-80-132 & environ assessment re decontamination of reactor bldg atmosphere W/o encis VOLLMER, R H TMI 2 Operations/Support 60/03/26 1p
- 8004210342 Forwards NUREG-0662. "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere." Addendum 1 & FR notice Public comment period expires 800411 VOLLMER,R II TMI-2 Operations/Support 80/03/26 4pp
- --8004210346 Notice of issuance & availibility of Addendum I to NUREG-0462. "Environ Assessment for Decontamination of TMI-2 Reactor Bidg Atmosphere " Comments due by 800411 VOLLMER.R H TMI-2 Operations/Support 80/03/25 2pp
- --8004210351 "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere," Addendum I * TMI-2 Operations/Support * Office of Nuclear Reactor Regulation NUREG-0662 ADD (BD/03/31 App
- BOO4040304 Notifies that 115 kV interfie has been classified as acceptable backup source for balance of plant equipment; electrical power supply Forwards request for classification of 230 kV power supply as backup source
 WILSON.R F Metropolitan Edison Co 80/03/28 43pp
- 8004250102 Responds to util 800304 request re removal of balance of plant diesel generators Accepts proposal & requests addition complete safety evaluation COLLING.S T NRC Three Mile Island Task Force 80/03/28 App
- 8004020068 "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere " * TMI-2 Operations/Support NUREG-0462 80/03/31 72pp
- 8004040375 Comments on NUREG-0662 re environ assessment of reactor bldq decontamination purging containment bldg best available option Recommends detailed spec of meteorological limitations prior to final purge approval MAGNER, H N Maryland, State of 80/03/31 7pp
- 8004070301 Forwards results of reactor containment bldg air samples analyzed for Sr-89 % 90 WILSON, R F Metropolitan Edison Co BO/03/31 2pp
- 800407031B Advises that capacity of approx 160,000 gallons of Unit 2 water will be maintained by one reactor coolant bleed holdup tank in each unit Tanks will remain empty, per NRC requirements
 WILSON.R F Metropolitan Edison Co 80/03/31 ip
- 8004070171 Responds to FOIA request for records re TMI-2 Forwards NUREG-0568, Revision 1, Suppl 1 & NUREG-0568, Revision 1 W/o encl FELTON, J M Division of Rules and Records 80/03/31 ip
- B004110471 Notifies NRC that as of B00326, approx 160,000 gallons of shielded storage capacity for TMI-2 water will be maintained by reactor coolant bleed holdup tank 1A of Unit 1 & IA of Unit 2 Util B00328 memo re TMI-1 bleed tanks encl WILSON, RF Metropolitan Edison Co B0/03/31 2pp

- 8004280244 Forwards consultant rept to venting Kr-85 from reactor bldg. requested by V Gilinsky W/o encl COLLINS.J T RRC Three Mile Island Task Force 80/04/01 1p
- ---8004280250 Forwards rept on venting Kr-85 from reactor bldg (MI State Univ) OlliNSKY,V Commission 80/03/26 tp
- 8004240472 Forwards G Pollack 800331 rept re suitability of selective absorption process sys for removing Kr-85 from atmosphere of TMI-2 reactor blig Rept based on visit to ORNL selective absorption sys priot plant GILINSKY, V Commission 80/04/03 Ip
- --B004240479 Submits rept re suitability of selective absorption process sys for removing Kr-85 from atmosphere of TMI-2 reactor bldg Rept based on visit to ORML gasoous diffusion plant Absorption process would work well POLLACK.G L Michigan State Univ 80/03/31 App
- 8004160179 Forwards Revision 7 to "Mini Decay Heat Removal Sys Design Criteria Document" HGVEY, G K. Metropolitan Edison Co. 80/04/07 ip
- --B0041601B4 Revision 7 to "Mini Decay Heat Removal Bys Design Criteria " SHILLMAN, G R , DUNFERD, E F Metropolitan Edison Co B0/02/26 1550
- 8004170023 Notifies that recommendations for long-term solid radwaste staging facilities will be delayed until 800531 HOVEY, G.K. Metropolitan Edison Co. 80/04/07 ip
- B00424049B Forwards status rept for wk of B00329-0404 Processed liquid sffluents from TMI-1 released into Susquehanna River were within Tech Spec limits No liquid effluents were discharged from TMI-2 CQLLINB, J T TMI-2 Operations/Support 80/04/07 App
- 8004250271 Forwards tables containing demographic & income data for 50 mile region around TMI Significant differences emerge in 30-40 & 40-50 mile rings
 KALTMAN.M Cost Benefit Analysis Branch 80/04/07 5pp
- 8004300273 Forwards TMI Program Ofc weekly status rapt for 800327-0404 GGLLINB, J T TMI Program Office 80/04/07 5pp
- BOO4150436 Requests NRC further consideration & approval of TMI~2 reactor bldg entry on BOO415 Present data suggests that oxygen deficiency exists in containment atmosphere No data exists to preclude presence of toxic contaminants HOVEY.O K Metropolitan Edison Co BO/04/08 6pp
- 8004160290 Forwards technical evaluation rept, "Submerged Demineralizer Sys," describing ion exchange process for decontamination of water in containment sump & RCS Decontamination required for continued recovery operation HOVEY G K Metropolitan Edison Co 80/04/10 2pp
- --8004160298 Technical evaluation ropt, "Submarged Damineralization Sys "
 * Matropolitan Edison Co 80/04/30 72pp
- BOO4170039 Informs of necessity to locate new time office manual brass alleys in area now occupied by NRC Forwards drawing showing locations NRC could be moved Requests preference indication by BOO417, Drawing available in Central Files only HOVEY. Q K Metropolitan Edison Co BO/04/10 2pp
- 8004150446 Forwards mods to encl permits & certificates for environ protection in response to NRC 800125 request HERBEIN, J G Metropolitan Edison Co 80/04/11 122pp
- BOOA17004B Confirms NRC 800415 meeting w/UCS at Middlatown.PA Anticipates receiving clarification of intent of several questions re relevancy to issue of venting containment ARNOLD,R C Metropolitan Edison Co GO/04/ii 1p
- B004170239 Forwards comments re environ assessment for decontamination of reactor bldg atmosphere MDLHOLT, B Public Interest Law Center of Philadelphia 80/04/14
- 8004300303 Forwards TMI Program Off weekly status rept for 800405-11 COLLING.J T TMI Program Office 80/04/14 5pp
- 8004210335 Forwards Gusquehanna River data in response to NRC 800407 request
 SKINNER,N F Pennsylvania Power & Light Co 80/04/19 ip

- --8004210340 "Demonstration for Brunner Island Steam Electric Station Units 1-3.Vols 1 & 2 " * EC * G. Inc 77/05/19 200pp
- --B004210344 "Potential Erfects of Brunner Island Steam Electric Station on Future Migrations of American Shad in Susquehanna River ' • EG 9 G. Inc. 77/08/13 23pp
- --B004210347 "Probabilities or Normal & Woist Case Conditions in Susquehanna River during Critical Periods for Muskellunge Spawning & Smallmouth Bass Egg Survival & Development " * EG & G. Inc 77/09/15 Lapp
- --8004210349 "Assessment of Thermal Effects from Brunner Island Steam Electric Station Based on Newly Derived Max Weekly Average Temps " * EG & G. Inc 79/05/31 33pp
- --8004210355 "Ecological Study of Effects of Brunner Island Steam Electric Station Cooling Water Intakes" JOHNSON, T.D., PHOENIX, D.R. Roy F. Weston, Inc. 77/11/18 78pp
- --8004210358 "Biological Survey of Susquehanna River in Vicinity of York Haven PA 1978 Terminal Rept " WURTZ, C B Charles B Wurtz 79/06/29 33pp
- --8004210366 "Ichthyofaunal & Creel Census/Fishing Pressure Surveys in Vicinity of Brunner Island Steam Electric Station " DENGNCGURT.R F R F Denoπcourt 78/05/31 161pp
- 8004220677 Supports Dureau of Radiological Health review of NUREO-0662 Venting of Kr-85 in containment bldg to atmosphere under controlled release is prudent & proper course NRC should provide definitive controls VILLFORTH. J C HEW. Dept of, Food & Drug Administration 80/04/16
- 8004240397 Responds to NRC 600328 ltr re hydrogen control sys filter housing negative pressure rating Filter housing not designed to meet ANSI/ABME 509 requirements issued in Dec 1976 Imposition of requirements considered inappropriate HOVEY.O K Metropolitan Edison Co 80/04/16 2pp
- BO042503/B Forwards App Subsection G to comments on EIS for decontamination of TMI-2 reactor bidg atmosphere Section had been omitted from original MOLHOLT, B Public Interest Law Center of Philadelphia BO/04/16 App
- 8004250433 Forwards comments on NUREO-0662, "Environ Assessment for Decontamination of Reactor Bldg Atmosphere & Addenda " Small releases will occur during each airlock & reactor bldg entry Loss restricted access to reactor bldg required HOVEY, O K Metropolitan Edison Co 80/04/18 4pp
- 8004280354 Responds to 800321 t 28 meetings re requirement to protect MDHS Filter housing currently being changed to stainless steel filter will be located in shielded cask in present position on east side of pump HOVEY, G K Metropolitan Edison Co 80/04/21 2pp
- 8004270287 Forwards comments on Addendum 2 to environ assessment for venting of facility containment atmosphere Concludes that reduction of venting time for removal of Kr-85 gas will result in higher overall psychological stress MGLHOLT, B Public Interest Law Center of Philadelphia 80/04/21

- The state of the s
- it I it lis, were " mi 77-2/ on 791002-05 & 09-11 No recitive energy may be a series the end allegations received three allegations received three allegations received three allegations received the end of t
- The state of the s
- 4 * Heautits to IF colletin 77-19. "Packaging of Low Level Patauste for Thansport following Personnel training requirements outlibe unfleted by Mpr 1930 Requests that sit i reduces the release for Shippent HV for Islan Ecison Co. 80/03/31 7pp
- 411 cel Pesnoris to h. 93cE23 ltr requesting status of actions All IF Bulleti ir items exsentially complete Personnel thatring requirements near completion V approval of three maddants shipments was gained Add status info encl within W F. Metropolitan Edison Co. 80,03/31 7pp
- D415TL & Firwards IE Into Notice 80-12 "Instrument Failure Causes Opening of POPV (Dlock Paive No specific action or response necessary SHER BM Region (Philadelphia Office of the Director 80,03,31) ip
- £1204210010 Firlands Waste Packaging Insp Rept 80-06 on 800128-0201 No Tence-plance nated

 SMITH S H Region 1 Philadelphia, Fuel Facility & Materials Safety
 Draich 60/03/si 2pp
- #30 4217020 Waste Packaging Insp Rept 80-06 on 800128-0201 No Total DAG Wester Fackaging insp Rept 80-06 on 800128-0201 No morrongliance rosed Major areas inspected proper vehicle planarding package integrity & package labeling & marking Supart E. Region 5. San Francisco. Fuel Facility & Materials Cafet; Branch C.H.N.C.E. Region 4, Dallas, Office of the Director 10/02/27 opp
- to 104070005 Forwards IE Circular 80-05, 'Emergency Diesel Generator Lubri ating Dil Addition & Onsite Supply " No unitten response raquired Page 8 H Region 1 Philadelphia, Office of the Director 30,04/21 ip
- SEC 3411014/ ForLands IE Info Notice 80-13. "GE Type SBM Control Switches Defective Com Followers," No written response required GRIEF B H. Region 1 Philadelphia. Office of the Director G3/04/02 1p
- © 104240315 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees No action required GMIER.B H Region L Philadelphia, Office of the Director 19
- EST D418CR00 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Gys' No written response required GRIER 8 H. Region I. Philadelphia. Office of the Director B3/04/03 ip
- ### 04233505 Forwards IE Builetin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required GRIER B H Region 1 Philadelphia Office of the Director 1p

- 8004010444 Submits "EPA Preliminary Data Rept 800312,14,17 & 21," prepared by Environ Monitoring Sys Lab SMITH:A E Environmental Protection Agency 80/03/24 1p
- 8004170344 Firwards status rept for wk of 800315-21 COLLINS, J.T. THI-2 Operations/Support 80/03/24 4pp
- 8004010490 Submits "NRC Air Sample Results for 800305,12 & 19," prepared by Environ Monitoring Sys Lab.EPA SMITH.A E Environmental Protection Agency 80/03/26 Ip
- 8004070222 Submits proliminary air & water sampling data for 800319-26 SMITH.A E Environmental Protection Agency 80/03/27 ip
- 8004140420 Forwards weekly status rept for wk ending 800328 re offsite emergency radiological environ monitoring program Burface & dripking water samples had normal tritium & gross bota activities
 GERTI,S M Porter-Gert: Consultants, Inc. 60/03/20 22no
- 8004070335 Forwards "Radiological Environ Monitoring Program Annual Rept.1979," "Hydraviic Survey" / "1979 Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of Facility " HERBEIN, J G Metropolitan Edison Co 80/03/31 2pp
- --8004070339 "Radiological Environ Monitoring Program Annual Rept for * Metropolitan Edison Co 80/04/30 78pp
- --B004070343 "Hydraulic Survey," for Jul 19/9 Three oversize drawings encl • Gilbert/Commonwealth Cos /9/07/31 20pp
- --8004070347 "1979 Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of Facility " PELLEK:R R . FRIDAY.G P . JOHNSON.R R NUS Corp 80/02/29 32pp
- 8004110362 Forwards results of reactor bidg air samples analysed for 800130-0213 for Sr-89 % Sr-90.in accordance w/util 800104 WILSON,R F Metropolitan Edison Co 80/03/31 Rpp
- 8004280230 Forwards TMI weekly status rept for 800322-28 COLLINS.S T NRC Three Mile Island Task Force 80/03.
- ---8004280234 TMI waekly status rept for 800322 28, providing facility status environ 5 effluent informajor activities, futuro evolutions & public affairs info
 * NRC Three Mile Island Task Force 80/03/31 3pp
- 8004140250 Forwards info describing permanent radiological environ monitoring program & program rept for 1779 Continuous air sampling equipment & environ radiation monitors will be used for Kr-85 monitoring W/o encls RESSLER.W C General Public Utilities GPU Service Corp RO/04/01
- 8004250375 Forwards preliminary data from offsite emergency radiological environ monitoring program consisting of program summary & status for wk of 800328-0403 GERTZ,S M Porter-Gerti Consultants, Inc. 80/04/01 14 00/04/01 14pp
- 8004070332 Submits average daily readings of radiation levels as measured by gamma rate recorder installed at Ocidshoro fire hall for 800322-29 Environmental Protection Agency 80/04/07 ip
- 8004180338 Forwards TMI-11-RR-4, "TMI-2 Recovery Quarterly Progress
 Rept for Period Ending 800331 " Describes recovery-related
 progress since accident for Jan-Man 1780
 HOREY, O K Metropolitan Edison Co 80/04/15 1p
- --8004180339 "TMI-2 Recovery Quarterly Progress Rept for Period Ending HOVEY, G K Metropolitan Edison Co TMI-II-RR-6 80/04/30
- B004220415 Forwards air sample data collected in vicinity of TMI from CORKERN W D . EMITH A E Environmental Protection Agency 80/04/16
- 8004230375 Preliminary data rept of air & water sampling CORKERN, W D Environmental Protection Agency 80/04/16 ip

- S Reportable occurrences. LFRs & related correspondence
- 8004070103 PNO-TMI-80-008A on 800310.licensee intends to commence preparations to enter containment personnel airlock 2 Airlock atmosphere radioactivity has been analyzed & will be purged Containment integrity will be maintained CONTE,R J. FASAND.A N. Region 1. Philadelphia. Office of the Director COLLINS.J T. Office of Inspection & Enforcement. Office of the Director 80/03/05 1p
- 8004020072 PND-TMI-80-014 seal rings for outer door to personnel airlock 2 failed leak test conducted following entry of personnel into airlock per PND-TMI-80-013 Seals replaced, door adjusted & seal retested successfully CONTE.R J. FAGAND.A N Region 1. Philadelphia. Office of the Director COLLINS.J T Office of Inspection & Enforcement, Office of the Director BO/03/14 2pp
- 8004020012 RO 80-10/IP on 800314 following use of outer door for first entry into airlock leak test of seals failed to meet acceptable criteria Airlock declared inoperable Door seal replaced & w/addi shims successfully leak tested WILSON, R & Metropolitan Edison Co 80/03/17 1p
- 8004020074 PND-TMI-BO-015 on 800318, employee left site in ambulance experiencing pains near right kidney Individual was not in controlled area at time of event CONTE,R J. FASAND. A N Region 1. Philadelphia, Office of the Director COLLINS. J T Office of Inspection & Enforcement, Office of the Director 80/03/18 ip
- 8004020077 PNG-TMI-80-016 on 800320.licensee plans emergency drill implementing emergency plan Onsite staff will monitor drill w/assistance from Region i CONTE,R J. FASANO,A N. Region 1, Philadelphia, Office of the Director COLLING.J T. Office of Inspection & Enforcement, Office of the Director 80/03/19 1p
- 8004020077 PNO-TMI-BO-017 on 800320, several local air particulate monitors in auxiliary bldg alarmed Makeup sys leak suspected for high reading Preparations underway to locate & isolate leak Press release planned by util HAVERKAMP, D.R., FAGAND, A.N. Region i. Philadelphia, Office of the Director COLLINS, J.T. Office of Inspection & Enforcement, Office of the Director BO/03/20 ip
- 8004040336 Forwards LERs 60-009/99X-0 & 80-011/99X-0 HERBEIN.J G Metropolitan Edison Co 60/03/27 1
- ~~8004040344 LER 80~005/97X~0 on 800321.Rosemount 1152 pressure transmitter in limited cases exhibited output between 4 & 20 ma w/input pressure over or under calibr range Caused by long-term degradation from submergence in water CHAPLIN:S D Metropolitan Edison Co 80/03/27 ip
- --8004040347 LER 80-011/79X-0 on 800321. Rosemount 1192 pressure transmitter in limited cases exhibited output between 4 & 20 ma w/input pressure over or under calibr range Caused by long-term degradation from submergence in water CHAPLIN.S D Metropolitan Edison Co 80/03/27 4pp
- 8004280632 PNS-I-80-004 on 800327, two bomb threats were received both stating that bomb was set for 800328 Search conducted No bombs found MADDEN, W. DEVLIN, J., MARTIN, W. Region i. Philadelphia, Office of the Director
- 8004140372 Forwards LER 80-009/03L-0 WILSON,R F Metropolitan Edison Co B0/04/03 ip
- ---8004140377 LER 80-009/03L-0 on 800305, during recovery mode operation, w/emergency diesel generator A down for maint, emergency diesel generator B was tested for operability Generator would start but could not be loaded Caused by open switch CHAPLIN.6 D Metropolitan Edison Co 80/04/05 3pp
- 8004290377 Forwards LER 80-010/01L-0 HDVEY, G K Metropolitan Edison Co 80/04/12 1p
- --8004250089 LER 80-010/01L-0 on 800314, using outside personnel air lock entry door, door seals were tested Leakage exceeded rate criteria Personnel air lock entry declared inoperable Caused by use of personnel door after one yr of nonuse CHAPLIN.8 D Metropolitan Edison Co 80/04/11 2pp
- 80042905i0 RO-80-14/iP on 800422.boric acid mix tank liquid found to contain higher boron concentration than Tech Spec limit On 800424 boric acid mix tank declared operable following demineralized water addition to bring concentration down HAVEY.O K Metropolitan Edison Co 80/04/24 2pp

- T Hearing transcripts on non-antitrust matters
- 8004300612 Transcript of 791025 telephone interview te participation in 5 knowledge or industry support effort is TMI-2 Pp 1-30 ACKERMAN N Technology for Energy Corp 79/10/25 32pp
- 9004020076 Transcript of 860129 public meeting in Harrisburg.PA to EIS on decontamination & cleanup of raduaste TMI-2 Operations/Support 80/01/29 67pp
- 8004040235 Forwards corrected transcript Page 552/553 for hearing in SMITH. J International Verbatim Reporters, Inc. 80/03/11 2pp
- 8004020140 Transcript of 800312 bijefing le environ assessment for decontamination of TMI-1 bldg atmosphere in Washington DC Pp 1-51
 * Commission 80/03/12 51pp
- 8004080001 Transcript of 800320 meeting in Baltimore.MD re scope or programmatic EIS on decontamination & disposal of radwastes resulting from accident # Commission 80703/20 200pp
- 8004140472 Transcript of 800401 meeting of ACRS Subcommittee on TMI-2 Action Plans in Bethesda, MD Pp 1-285 * ACRS Advisory Committee on Reactor Safeguards 80/04/01 29000
- 8004140474 Transcript of 800402 meeting of ACRS Subcommittee on TMI-2 Action Plans in Rethesda, MD Pp 1-199 * ACRS Advisory Committee on Reactor Safeguards B0/04/02 200an
- 8004150323 Transcript of ACRS Subcommittee on THI Accident Implications 800409 meeting in Washington, DC Pp 1-147 # ACRS -- Advisory Committee on Reactor Safeguards 80/04/09
- U Congressional/Executive Correspondence
- 80040802/5 Ack receipt of 800303 ltr providing comments for programmatic EIS on decontamination & disposal of radwastes resulting from facility 790328 accident Comments will be considered in preparation of statement MULLER, D.R. Division of Site Safety & Environmental Analysis 80/03/19 | 1p
- --8004080280 Comments on programmatic EIS on decontamination & disposal of radwastes resulting from facility 79032A accident Supports statement No actions should be permitted at site until impact on Susquehanna River is determined BAMMAN.R E House of Rep., Merchant Marine & Fisheries 80/03/03
- 8004220657 Comments on NRC approach re contaminated waste disposal from TMI No wastes should be released into Susquehanna River until completion / review of ETS NRC must consult w/state officials re any activities taken prior to ETS review SARBANES, P Senate 80/03/20 2pp
- 8004140270 Discusses NRC Special Inquiry Group review of questions on util conduct re info transfer during 1979 accident No direct evidence found to indicate info withheld intentionally IC will complete investigation AHEARNE, J.F. Commission 80/03/21 3pp
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1 G Adjudicatory correspondence
- 8004270440 Forwards NRC confirmatory orders STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/04 1p
- ---8004290466 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800626 Info required outlined in Attachment A STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/04 Spp
- --8004290477 Order confirming util commitment to perform review requested by IE Bulletin 79-27 by 800626 Info required contained in Attachment A STELLO,V Office of Inspection 7 Enforcement, Office of the Director 80/04/04 Spp Director

- Openstan, list actual to months respectence
- 4. Topo (1), 10.4 h. 11 region that all LBR licensees assess 13 for the first of the formula subove 20 000 (13), get not 1 for Bellin . Indirate that no ammediate like sits of the formula f
- Product of contacts for the transfer of the Between Study of digital communities of the Great Contact of the Great
 - #34u_btid Ni icar Dati E nt opecs

 * Ottasion of Upgrating Featters = LOTO2721 | 20pp
- PTORUGOZZ/ Describes resign or primary coolant sys pressure isolation valves in response to NN B002ZJ ltr ne potential for LGCA forwards systemes or peretrations exhibiting Event 5 valve ionfiguration for ear ninit

 WICTER NA Seongle Power 65 80/03/31 8pp
- M. 34290055 Firwards Buul- / 5 0211 ltms to GE re proposed control rad Strive 5; mais related to elimination or cracking in return line roisles Guideline, sur mods will be discussed in NUREG Ocilito be issued in For connent' form in Apr 1980 IFFOLITO TA Operator; Reactors Granch 3 80/04/07 2pp
- FOURISHINGS Commits into re-control rod operability, in response to ARC FOOLIG Iti Furing cept 1/70 to Dec 1979 no instances occurred or control rods railing to insert fully Only malfunctions were introgen cartridge valve leaks WIDTEP.W m. Georgia Power Co. 80/04/08 lp
- #304250370 Forwards rept re substantial safety hazard in RHR syc water pump motors cooling water supply line Loss of RHR cooling water would result in ecceding safety limit specified in Tech Typers Cooling sys will be separated into two divs MCCRARY D.L. Southern Co Services. Inc. 80/04/15 4pp
- 4 Inspection reports. IF Bulletins 5 correspondence
- 8004090349 Forwards IE Billetin 80-03. "Loss of Charcoal From 5td Type II.Two-Inch Tray Adsorber Cells ' Action required O'REILLY.J P Region 2 Atlanta Office of the Director 80/02/06
- HO04010112 Partially responds to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment" Class IE components listed including environ analysis inadequate qualification data test acrident temp profiles W/o encl
- 9004220215 Forwards IE Repts 50-321/80-08 & 50-366/80-08 on BOO221-22 No noncompliance noted

 BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 60/03/04 2pp
- --8004220221 IE Insp Repts 50-371/80 08 \$ 50-366/80-08 on B00221-22 No noncompliance noted Major areas inspected followup on items of noncompliance re 100FR21 BROWNLEEV L. CONLON 7 E Region 2 Atlanta. Office of the Director 80/03/04 3pp
- COG4095032 Ack receipt of 800310 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-321/80-01 & 50-366/80-01
 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/18 1p

- -8004070035 Responds to IAC 800205 ltr re violations noted in IE Insp Repts 50-391/80-01 % 50-366/80-01 Corrective actions data sheet revised to relorate rire pump fuel level checks & assignment sheet revised to use HHP-2-9503 HIDNER.W A Georgia Power Co 80/03/10 1p
- --8004090035 Forwards IE Irsp Repts 50-321/80-01 & 50-366/80-01 on 800108-11 & notice of violation LEMIS.R C Region 2 Atlanta, Reactor Operations Nuclear Support Branch 80/02/05 dpp
- ---8004090041 Notice of violation from insp on 800108-11 * Region 2. Atlanta. Office of the Director 80/0

- --8004090049 1E Insp Repts 56-321/80-01 / 50-326/80-01 on 800108-11 Moncompliance noted failure to rollow surveillance procedures
 UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch NON, B T Region 2. Atlanta, Office of the Director
 80/02/05 6pp
- 8004110565 Submits response to IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " All filters are in good condition.all screens are stable t housing frames are solid No carbon lost through screens WIDNER.W A Georgia Power Co 80/03/21 3pp
- 8004150198 Responds to IE Bulletin 80-03 re charcoal adsorber colls Insp of all Util 1 ventilation sys indicate that all filters are in good condition Util 2 uses deep bed type carbon rilter beds rather than cells WIDNER,W A Georgia Power Co 80/03/21 3pp
- 8004170298 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation to Control Power Sys Bus During Operation "Review of emergency procedures, required by Item 2. is now scheduled for completion by 800626 WIDNER. N Georgia Power Co 80/03/26 ip
- 8004150521 Forwards IE Info Notice 80-12. "Instrument Failule Causes Opening of PORV & Block Valve 'No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 200
- 8004080624 Forwards IC Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/04 Region 2: Atlanta, Office of the Director 80/04/01
- 8004150045 Ack receipt of 800211 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/79-37 & 50-346/79-41 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/01 1p
- --8004150072 Responds to NRC 800117 ltr re violation noted in IC Inap Rept 50-321779-37 / 50-366779-41 Corrective actions existing radiation work practices / procedures reviewed & modified WIDNER, W A Georgia Power Co 80/02/11 2pp
- --8004150079 Forwards IE Insp Repts 50-321/79-37 % 50-366/79-41 on 1041500/7 Forwards to this nepts 30-321//4-3/ A 30 791110-1207 & notice of violation LEWIS.R C NRC Regional Offices GO/01/17 Ppp
- --8004150084 Notice of violation from insp on 771110-1207 * Region 2, Atlanta, Office of the Director 80/01/
- 8004150096 IE Insp Repts 50-321/79-37 & 50-366/79-41 on 791110-120/ 004150076 IE Insp Repts 50-321/79-37 & 50-366/79-41 on 791110-120/ Moncompliance noted radiation work permits were not approved & posted prior to work contrary to procedures & Tech Specs DANCE.H C NRC Regional Offices ROGERS,R F Region 2, Atlanta, Dffice of the Director BO/01/15 5pp
- B004150126 Act receipt of 800313 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/80-04 & 50-366/80-0 LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/01 1p
- --8004150136 Responds to NRC 800214 ltr re violation noted in IE Insp Repts 90-321/80-04 % 366/80-04 Corrective actions shift foreman 5 operators involved were relieved of duties for special training HIDNER.W A Georgia Power Co 80/03/13 ip
- --8004150142 Forwards IE Insp Repts 50-321/80-04 & 50-346/80-04 on 791212-800104 & notice of violation LEWIS, C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/02/14 2pp
- --8004150147 Notice of violation from insp on 791212-800104 * NRC Regional Offices 80/02/13 1p
- --8004150195 IE Insp Rept 50-321/80-04 & 50-346/80-04 on 791212-800104 Noncompliance noted HPCI sys not proven operable as required by Tech Specs DANCE.H C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch R

```
8004150093 Forwards IE Info Notice 80~13, 'GE Type SBM Control Switches
Defective CAM Followers " No specific action or response
   o'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/04/02
8004240265 Forwards IE Info Notice 80-14, "Safety Suggestions From
                        No action required
P Region 2, Atlanta, Orfice of the Director 80/04/02
   Employees " A
O'REILLY, J P
8004180303 Forwards IC Circular 80-07, "Problems W/HPCI Turbine Oil
              No written response required
LY,JP Region 2, Atlanta, Office of the Director 80/04/03
   Sys " No writ
8004110011 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure "
   Written response required O'REILLY, J.P. Region 2.
                             Region 2, Atlanta, Office of the Director 80/04/04
80042301/3 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/04
8004180436 Forwards IE Bulletin 80-08, "Exam of Containment Liner
Penetration Wolds " Written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
8004230467 Submits info in response to 800121 ltr re IE Bulletin 80-02
Documentation associated w/receipt & installation of
sparger assemblies & mods is on file at plant site
WIDNER.W A Georgia Power Co 80/04/16 4pp
8004280452 Updates 800346 response to 1E Bulletin 79-01B "Environ
Qualification of Class IE Equipment " Enough info re Dechtel
equipment will be available by 800801 to provide meaningful
response Info needed from 0E will be complete by 801226
WIDNER, W A Georgia Power Co 80/04/21 2pp
R Periodic operating reports & related correspondence
8004010321 Forwards "Annual Environ Surveillance Rept for CY79 "
                     Georgia Power Co 80/03/28
--8004010324 "Annual Environ Surveillance Rept for CY79 "
* Georgia Power Co 80/03/28 300pp
8004150388 Forwards monthly operating rept for Mar 1980
MANRY, M Georgia Power Co 80/04/10 ip
  -8004150370 Monthly operating rept for Mar 1980
RODEN,J W. Georgia Power Co. 80/04/10. Sp
8004150377 Forwards monthly operating rept for Mar 1980
MANRY, M Georgia Power Co 80/04/10 1p
---8004150404 Monthly operating rept for Mar 1980
RODEN, J W Georgia Power Co 80/04/10 5p
8 Reportable occurrences, LERs & related correspondence
B004010474 Forwards LER 80-025/03L-0
MANRY, M Georgia Power Co 80/03.
                                                      80/03/25 ip
--8004010477 LER 80-025/03L-O on 800301.during normal operation reactor core isolation cooling pump discharge flow switch found out of spec.Caused by instrument drift Barton Model 289A flow switch recallbr
NIX.R T Georgia Powpr Co 80/03/25 2pp
8004020354 Forwards LER 80-020/03L-0
                     Georgia Power Co 80/03/27 1p
--8004020359 LER 60-020/03L-O on 800308, during normal operation, 180 gallons of radwaste was released to river w/o prior analysis per Tech Specs Caused by technician error Reanalysis showed ETS not exceeded ROGERS, W H Georgia Power Co 80/03/27 2pp
```

8004040416 Forwards LER 80-027/03L-0 MANRY,M Georgia Power Co 80/04

80/04/01 1p

```
--9004040426 LER 80-027/031 -0 on 600310, during review of surveillance schedule, discovered 1 od block monitor functional test // calibr not performed within required interval Caused by personnel oversight Surveillance acceptably performed NIX.R T Georgia Power Co 80/04/01 2pp
8004070281 Forwards LER 80-028/031-0
(IANRY,II Georgia Power Co. 80/04/01 ip
 ~~8004070283 LER 80-028/03L-0 un 800313 * 1/.during full power operation
          secondary containment integrity momentarily violated at 164 rt elevation leavior bild airlock Caused by design deficiency Design change request has been written COGOIN-C L. Georgia Power Co. 80/04/01 2pm
                                           Georgia Power Co
8004220713 Forwards LER 80-029/03L-0
MANRY,M Georgia Power Co 80/04.
                                                                                    80/Q4/15 1p
--B004220721 LER 80-029/03L -O on B00322, during normal surveil) ance, generator IR43-5001C failed to start ∿ reach rated speed within 12-s Caused by bent shutdown solenoid operating rod in engine governor № failed governor booster serve NIX,R T Georgia Power Co 80/04/14 3pp
BOO4220675 Forwards LER BO-031/03L-0
MANRY, M Georgia Power Co 80/04/17 lp
   -8004220484 LER 80-031/03L-0 on 800330, while operating at 99 87 of rated
          MWT, main stack radiation monitor sample pump failed Cause attributed to moisture swelling cathon vanés in pump, locking pump Sampling procedure will be revised ROGERS, W. H. Georgia Power Co. 80/04/17 2pp
8004220689 Forwards LER 80 030/03L-0
MANRY,M Georgia Power Co 80/04/
                                                                                    80/04/17
--8004220710 LER 80-030/03L-0 on 800330, w/mode switch in run position & reactor at 2,432 MWT, discovered analyzer B or primary containment hydrogen ! oxygen analyzer inoperable Caused by personnel error Problem corrected Analyzer returned to svc NIX,R T Georgia Fower Co 80/04/17 2pp
8004280570 Forwards LER 80-032/03L-0
MANRY,M Georgia Power Co 80/04.
                                                                                    G0/04/22 1p
---8004280566 LER 80-032/03L O on 800402 during normal operation primary containment oxygen concentration exceeded Tech Spec limit Caused by air in leakage across seals of torus to drywell delta pumps Pump seals greased & in-leakage stopped * Georgia Power Co 80/04/22 2pp
8004280982 Forwards LER 80-034/03L-0
MANRY, M Georgia Power Co 80/04/22 1p
~~8004280587 LER GO-034/GGL-O on 800403 during steady state power operation on Unit 1 % cold shutdown on Unit 2, fire water level on both water tanks was discovered below Tech Epecs Caused by volve trip at north end of 1B cooling tower NICR T Georgia Power Co 80/04/22 2pp
DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
 A Application/construction stage documents & correspondence
8004040031 Advises of issuance of NUREC-0588, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
BOO4040017 Bubmits addl guidanie to NUREG-0588, "Interim Staff Position
on Environ Qualification of Safety Related Electrical
Equipment "Requests review of equipment qualification
documentation to identify degree of compliance
ROSS.DF Division of Project Management 80/02/21 Opp
8004020466 Notification or 800326 & 27 meeting w/representatives from Mark II guners group in San Jose CA to discuss Mark II Coreace Test Program. 4T c/o tests & foreign tests ELTAWILA.F Containment Systems Branch 80/03/10 12pp
8004030122 Notification of 800326-27 meeting w/Mark II owners group,
NRC consultants & GE in San Jose,CA to discuss Mark II
Creare test program.4T C/O & foreign tests Topics are
proprietary Agenda enc!
ELTAWILA,F Containment Systems Branch 80/03/10 12pp
```

- G004040124 Summary or Fortial" meeting arMark II owners group he status or several long term program has a including Tasks A 17, and 6 task helatify whilization of foreign test data ELTANILA F containment System, Branch 80/03/18 104pp
- 8004040314 Forwards response to TARC 790614 into requests re traffic patterns 4 access to restricted 4 unrestricted areas Employees enter plant training both 4 sv bldg Figures indicating traffir patterns 6 plant diagrams encl MOVARRO JP Long I-land Lighting Co 80/03/31 22pp
- Bu04140439 Request-submitted on pehalt of Util Group for Regulatory applications, that NRC (view RETRAN computer code Code will be used for transient analysis 5 supporting activities required for plant mod or reload licensing VALENTE, J.V. Long Island Lighting Co. 60/04/01 1p
- 8004220620 Forwards responses to NRC Requests 331-31 % 423-1 Plant radiation protection program complies w/Reg Guides 8 8 % 8 10 w/certain sceptions Program does not include speciafic measurement systems to not monitors are unnecessary NGVARROLUP Long Island (lighting Co. 80/04/11 6pp
- 8004300064 Summary of 800326-27 meetings u/Maik II owners group in San Jose, CA te discussion of MRC concerns on data from Creare tests t rorough full-scale feet programs t relationships w/ Mark II designs ELTANILA.F Containment Systems Branch 80/04/14 22pp
- 2004307049 Notification of 1,00508-09 menting w/util in Long Island.NY to evaluate status of renst 5 estimated fuel load date WILSUM J R light Water Reactors Branch 4 80/04/15 6pp
- F Security, medical, emergency trine protection plans
- 8004080077 Advises that submittal date not evacuation time estimates, requested by IRC 791226 ltm.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B k Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004010521 Opposes operation of plant due to inadequate evacuation plan SCHILLER-N Affiliation Unknown 80,02/19 Ip
- 8004040129 Demands site ne er be licensed No plans or evacuation possibilities exist rot east end or Long Island & surveys show util does not need plant XLEIN.P W. Artiliation Uninoun 80/02/23 2pp
- 8004010520 Opposes granting of license to operate plant due to inadequate evacuation plan BRINMMAN,T J. Afriliation Unknown 80/03/15 1p
- 8004030626 Memorandum of upderstanding between NRC & FEMA re-prompt improvement in radiological energency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004230051 Advises that NRC position re-consideration of Class 9 accidents will be submitted to ACLB when evaluation is completed, in response to 800505 order Forwards Commission 8003012 ASLAB 800401 orders, as Interim info

- COU4070122 Protests nucleur power dus to concern of waste disposal TUTHILL E Afriliation Unknown 80/02/29 1p
- u Inspection reports IF Bulletins & correspondence
- 8004100072 Forwards IE In:p Rept 50-322/79-23 on 791210-800113 No noncompliance noted BRUNNER E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 60/02/11 2pp
- --B004100077 IE Insp Rept 50-222/79-23 on 791210-B00113 No noncompliance noted Major areas inspected work activities & preoperational testing, including tours of racility, test uitnessing. QA activities & environ monitoring KISTER.H B Region 1. Philadelphia, Reactor Operations Nuclear Support Branch HIGSINS.J C Region 1. Philadelphia, Office of the Director 80/02/06 7pp
- 8001090004 Responds to IE Sulletin 79-28 te defects in cortain NAMCO Model EA180 series switches Afrected switches procured per IE Buletin 78-04 Returned for rework NOVARRO, J.P. Long Island Lighting Co. 80/02/19. 1p
- 8004210146 Forwards IE Insp Rept 50-322/80-03 on 800128-0201 No noncompliance noted BRUNNER:C J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/02/25 2pp
- -8004210151 IE Insp Rept 50-322/80-03 on 800128-0201 No noncompliance noted Major areas inspected preoperational test program, including implementation, status, procedure review & verification & following on previous items CAPHTON, D.L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch TROSNOSKI, W.M. NICHOLAS, W.H. Region 1, Philadelphia, Office of the Director 80/02/21 lipp
- 8004070)14 Ack receipt of 800221 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/79-16
 BRUNNER.E J. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 60/03/04 2pp
- --8004070117 Responds to NRC 800121 ltr re violations noted in IE Insp Rept 50-322/79-16 Corrective actions replaced caps covers & plugs Space heaters in Panels IHZ1*PNL10 & IHZ1*PNL26 re-energized & battery room cleaned WOFFORD A W Long Island Lighting Co 80/02/21 3PP
- --80040/0120 Forwards IE Insp Rept 50-322//9-16 on 791001-1106 & notice of violation BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/21 2pp
- --8004070121 Notice of violation from insp on 791001-1104
 * Region 1, Philadelphia, Ortice of the Director 79/12/11 2pp
- ~-8004070123 [E Insp Rept 50-322/79-16 on 791001-1106 Noncompliance noted Fa; lure to provide suitably controlled conditions for activities affecting quality KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch HIGGINS, J C Region 1, Philadelphia, Office of the Director 79/12/11 Spp
- 80040904i4 Advises that [E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks." was incorrectly sent for action No response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/17 1p
- 8004150274 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Bloc; Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- E004090063 Forwards IE Circular 80-03, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 tp
- R004110140 Forwards 1E Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required CRIER.B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- 8004240313 Forwards IF Info Notice 80-14. "Safety Suggestions From Employees" No action required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/02 1p

- 8004180179 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 8D/04/03 1p
- 8004110053 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required GRIER, BH Region I, Philadelphia, Office of the Director 80/04/04 ip
- 8004230491 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects (n ASME SA-312.Type 304 Stainless Steel Pipe " Action required GRIER.B H Region 1, Philadelphia, Office of the Director 90/04/04 10
- 8004180161 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Welds " Written response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/04/07 1p
- T Hearing transcripts on non-antitrust matters
- 8004100440 Comments on proposed rule 10CFR50 issue of emergency planning has been prime concern of county as intervenor in CP proceedings for facilities Regulations may not adequately protect public health & safety
 LIKE: 1 Suffolk County, NY 80/02/26 13pp
- DOCKET 50-929 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO--0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDS8.D F Division of Project Management 80/02/05 7pp
- 8004040017 Bubmits addl guidance to NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.DF Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Bubmittal schedule should include NRC approval prior to issuance of OL W/enci ROSS,DF Division of Project Management 80/03/i0 53pp
- 8004010436 Forwards addl info re refueling water storage tank capacity in response to 790720 request FBAR commitments & Tech Spec limit is 350,000 gallons Possibility for 2X error exists in indication of tank level CRANE
- 8004010437 Forwards Draft 2.Revision 2 of proposed ETS for facility, in response to NRC request TIDRICK.O A Pacific Gas & Electric Co 80/03/21 lp.
- --8004010441 Draft 2.Revision 2 of proposed ET8 for facility * Facific Gas & Electric Co 80/03/31 21pp
- 8004080466 Forwards nonpropristary version of response to NRC 790912 ltr re tube wear Application for withholding proprietary info & Westinghouse supporting ltrs encl CRANE,P A Pacific Oas & Electric Co 80/03/25 34pp
- 8004020283 Advises that work of R Lesley re offshore faults does not impact conclusions contained in Suppl 4 of safety evaluation concerning possible connection between San Simeon & Hosgrifault lones
 DEVINEJ F Interior.Dept of, Geological Survey 60/03/31 1p
- 8004040281 Forwards response to short-term Lessons Learned Task Force requirements Five oversize drawlings encl CRANE:P A Pacific Gas & Electric Co 80/03/31 35pp
- 8004140016 Natification of 800404 meeting w/utils in Bathasda, MD to discuss applicants' progress & status in design review re plant shielding & environ qualification of equipment for spaces/sys used in post-accident operations
 BUCKLEY, B C Light Water Reactors Branch i DROMERICK, A W , LICITRA, E A Light Water Reactors Branch 3 80/03/31 7pp

- 8004240248 Responds to 771115 telegram to F Press, science advisor to President Kemeny Commission lept on TMI accident is being incorporated into NRC Action Plan Applicants will need to implement recommendations prior to OL issuance ROSS,D F Division of Project Management 80/04/01 Spp
- 9004240520 Discusses potential design deficiencies in bypass.override A reset circuits of engineered salety features Cites specific examples, safety significance / criteria to be satisfied Protection sys design conformance response due by 800405 STOLZ, J F Light Water Reactors Branch I 80/04/01 5pp
- 8004080443 Forwards press clippings purpoiting to state NRC position in Chumash Indians' access to facility Util is willing to meet & discuss issue Access question derived from possible application of Native American Religious Freedom Act PETERS.R J Pacific Qas & Electric Co 80/04/03 4pp
- 8004150435 Forwards diaft "Archaeological Resources Mgt Plan" Plan covers area north of plant in area designated SLO-2
 PETERS.R J Pacific Gas & Electric Co 80/04/07 2pp
- --8004150441 Draft "Archaeological Resources Mgt Plan "
 * Pacific Gas & Electric Co 80/04/30 45pp
- 8004150337 Forwards comparison of NUREG-0611 recommendations for auxiliary feedwater sys to design //on operation of facility sys CRANE,P A Pacific Gas & Flectric Co 80/04/08 8pp
- 8004160253 Responds to NRC request for add1 info re secondary water chemistry control & forwards administrative operating & chemical analysis procedures Procedures include schematic diagrams indicating sampling point locations CRANE,P A Pacific Gas & Electric Co 80/04/08 2pp
- --8004160256 Operating Procedure F-5.Revision 1. "Chemical Control Limits" * Pacific Gas & Electric Co 80/02/01 42pp
- ---8004160260 Chemical Analysis Procedure E-6. "Secondary Sys Sampling "
 * Pacific Gas & Electric Co 80/01/08 5pp
- ---8004160264 Administrative Procedure C-12.Revision 2, "Resolution & Reporting of Plant Problems" * Pacific Gas & Electric Co 78/03/06 12pp
- ---8004160267 Administrative Procedure C--201.Revision 1, "General Requirements for Chemical & Radiochemical Control Programs " * Pacific Gas & Electric Co 79/11/24 3pp
- --8004160271 Suppl to Administrative Procedure C-20, "Chemistry Data Review & Record Mgt " Descriptions of secondary water chemistry control program encl * Pacific Gas & Electric Co 75/11/24 12pp
- 8004170076 Forwards Revision 3 to response to NUREG-0978 re short term Lesgons Learned Task Force recommendations GRANE,P A Pacific Gas & Electric Co 80/04/09 29pp
- 8004190343 Forwards Revision 4 to facility response to short-term Lessons Learned Task Force requirements CRANE,P A Pacific Oas & Electric Co 80/04/11 21sp
- 8004220406 Responds to NRC 800228 ltr requesting addl info required to evaluate mgt & technical resources available at PG&E facilities Advises that 800321 telcon w/J Powers of Teknekron relayed requested info CRANE,P A Pacific Gas & Flectric Co 80/04/15 ip
- 8004220692 Reissues Revision 2 to response to NUREG-0578 Also forwards modified instructions for Revision 2 insertion into manual & eight administrative procedures previously sent to review group Oversize drowings encl
 GRANE,PA Pacific Gas & Electric Co 80/04/18 33pp
- --8004220697 "General Authorities & Responsibilities of Shift Foreman" # Pacific Gas & Electric Co 80/03/27 2pp
- --8004220704 "Plant Staff Organization & Responsibilities for Normal Operations," Revision 2

 # Pacific Gas & Electric Co BO/03/27 3pp

- --8001220716 Gencial Authorities / Responsibilities of Nuclear Plant Operators, 'Revision 3 orators,' Revision 2 | Pacific Gas ! Electric Co. 80/03/27 | Spp.
- 8004220727 Quality, ation & Training of Shift Technical Advisor (Shift Engineer: "

 # Pactric Gas / Flectric to B0/03/2/ 2pp
- --8004220737 Availability ' Notification of Off-duty Personnel."
- # Pacific was & Electric Co. 80/03,27 2pp
- --8004220744 'Relieving Watch (Shift Turnover)," Revision 3 * Pacific Gas & Electric Co 80/03/27 2pp
- ~=8004220751 'Control Roum Acress ' * Pacitic Gas & Electric Co =80/03/31 | 2pp
- ~~8004220755 "Overtime & Emergency Relief Restrictions "
 Pacific Gas & Electric to 80703/31 2pp
- 8004280373 Forwards Revision 5 to response to NUREG-0578 Changes result from questions by NRC reviewers preparing SER CRANE,P A Pacific Gas % Electric Co 80704722 Bpp
- Γ Securaty, medical, emergency & rire protection plans
- 8004240394 Forwards draft tept. "Evacuation Times Assessment Study," in response to NRC 791226 request Rept will be reissued w/ possible minor changes by 800523 LOCKE.R F Pacific Oas 5 Electric Co 80/04/11 ip
- --- 8004240389 "Evacuation Times Assessment Study "
 A PRC Systems Services Co 80/04/30 102pp
- G Adjudicatory correspondence
- 8004020133 Request by joint intervenors for Commission early intercession of reconstitution or ASLB, re-seismic issues. Urges disqualification of JH Busk due to prior involvement. Requests oral argument on issue Certificate of Svc encl. FLEISCHAMER, D. Fleischaker, D. S. PHILLIPS, J.R. Center for Law in the Public Interest. 80/03/13. 23pp
- 8004090038 Request by joint intervenois to stay 800403 oral argument re seismic issues Adequate time should be given to Commission to evaluate joint intervenors request for early intercession or reconstitution of ASLAD FLEISCHAKER.D S Fleischaker. D S PHILLIPS, J R Center for Law in the Public Interest 80/03/13 4pp
- 8004080712 Notifies of appearance on behalf of applicant at oral argument re intervenors exceptions concerning earthquake issues, per ASLAB 800225 order Centificate of Svc encl NORTON, B. Bruce Norton 80/03/14 3pp
- B004030015 Opposes operation of facility CA is not safe place to build power plants due to seismic activity
 SNAPP.C Affiliation Unknown 80/03/15 ip
- 8004090033 Advises of appearance on behalf of Odvenor of State of CA:at 800403 hearing Curtificate of Svc encl BROWN.H H Hill Christopher & Philips 80/03/17 4pp
- 8004220001 Forwards notice of appearance of author.PC Valentine & A Baldwin on behalf of San Luis Obispo Nothers for Peace Intervenor UP Taylor prof qualifications encl JONES.Y I Jones, Brown & Clifford 80/03/17 (3pp
- B004020086 Response in opposition to joint intervenors B00313 request to stay oral argument is spismic issues Urges denial of joint intervenors B00313 request for Commission early intercession or ABLAB reconstitution WCertificate of Buc KETCHEN,E G Hearing Branch 4 80/03/21 20pp
- 8004080691 Order re Joint Intervenors' 800313 motions Commission shall not intercede in seismic proceeding JH Buck should publish decision by 800403 Oral argument denied CHILKES J Office of the Secretary of the Commission 80/03/21
- 3004020020 Forwards affidavit of nondisclosure & protective order drafts.per ASLAS 800225 first prehearing conference order Advises that parties were unable to agree on certain provisions Encloses list of NRC witnesses re security issue STAENBURGIM R Regulations Division 80/03/24 17pp

- viii0 1090132 Response by Juint Intervenors in opposition to Commissioner Hendrie decision to hear proceeding Exparte communication is sufficient for unthoraual.per case law-regardless of bias against or in rayor or party Decision should be retracted FLEISCHAMER.P Fleischaver. D S PHILLIPS.JR Center for Law in the Public Interest 60/03/20 lipp
- --8004690137 Response by joint intervenois in opposition to Commissioner Kennedy decision to hear proceeding Er parte communication is sufficient for uithdrawal, per case law, regardless of bias against or in favor of party Certificate of Svc encificischaker, D. Fleischaker, D. S. PHILLIPS, J.R. Center for Law in the Public Interest 80/03/26 14pp
- 8304230107 Forwards USGS Circular 795 containing conclusions re adjudicated issues,per ASLAB directive to provide new info if relevant t nati FLEISCHAKER,D Fleischaker, D S 80/03/26 91pp
- 8004080556 Petition by Joint Intervenors for review of JH Buck decision to remain member or ASLAB re-seismic appeal Prior involvement in facility seismic concerns may jeopardize ability to maintain total impartiality W/Certificate of Svc FLEISCHAKER.D Fleischaker.D S PHILLIPS.JR Center for Law in the Public Interest 80/03/28 8pp
- 6004210322 Motion by Joint Intervenors to reopen record to seismic issues & environ qualification of safety-related equipment. New info invalidates ASLB evaluation of Hosgri seismic fault W/Certificate of Svc & supporting documentation FLEISCHAKER, D. F) elschaker, D. S. PHILLIPS, J. Center for Law is the Public Interest FLEISCHAKER, D. San Luis Obispo Mothera for Feace 80/03/28 18pp Center for Law in
- -8004210325 Affidavit indicating that facility design accelerations, velocities & displacements are not established as conservative values for N-7 5 design earthquake Supporting documentation encl BRUNE, J N California, Univ of, San Diego 80/02/29 43pp
- --8004210327 Arfidavit advising of recent investigations indicating that Hosgri & San Simeon iones represent continuous & throughgoing fault sys Chart encl LESLIE.R B California, Univ of, Santa Cruz 60/02/28 7pp
- --8004210393 Affidavit demonstrating that independent review of safety related equipment qualification program should be conducted prior to CL issuance HUBIARD.R B MHB Tochnical Associates 80/02/28 13pp
- --8004210375 "Preliminary Rept on Strong-Notion Records from Imperial County Svcs Bldg " KDJAHN,C , RAGSDALE, J D Afriliation Unknown 80/02/28 18pp
- 8004090454 Order denying Joint Intervenors 800328 patition for review of JH Buck 800324 memorandum stating intention not to disquality from participation JH Buck prior involvement at CP stage does not require disqualification GHILK/S J Office of the Secretary of the Commission 80/04/01
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GDSSICKL V Office of the Executive Director for Operations, 80/04/02 34pp
- 8004210100 Memorandum to counsels re Joint Intervenors 771024 motion requesting Commissioner Hendrie's disqualification Intervenors have presented no new info proving bias or appearance of bias Self-disqualification not required HEMDRIE. J Commission 80/04/09 2pp
- 8004230091 Advises that applicant response to Joint intervenors 800328 motion to reopen evidentlary hearings is due on 800424 & NRC response on 800305, per 800403 stipulation approved by KETCHEN, E 9 Hearing Branch 4 80/04/09 2pp
- 8004240541 Ack receipt of Anson 800325 ltr distributed to all parties for consideration BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/04/09
- --8004240545 Forwards wap indicating inner evacuation area Expresses concerns re escape routes during meltdown event ANSON.W B Affiliation Unknown 80/03/25 App

- 800421016B Order granting extension until 800415, for Commission to act to review ALAB-583 CHILK, S. J. Office of the Secretary of the Commission. 80/04/10
- B00423009B Order reporting B00402 second prehearing conference re procedures & schedules for receiving security plan evidence Licensee physical security plan is entitled to confidential treatment per entl protective order & affidavit BISHOP,C J Atomic Safety and Licensing Appeal Panel B0/04/11
- --8004230103 Protective order (e licensee security plan, restricting San Luis Obispo Mothers for Peace access to protected info per encl affidavit of nondisclasure to be executed by counsel & BALZMAN, R S Atomic Safety and Licensing Appeal Panel 80/04/03
- 8004220371 Response in opposition to PQLE 800414 application for stay of ASLAB 800411 order re disclosure of sanitized version of security plan Applicant failed to show that util will be irreparably harmed from disclosure M/Certificate of Svc DAVIS.L D Hearing Branch 4 80/04/18 12pp

H General correspondence

- 7906290854 Responds to 7904ii ltr on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diable Canyon CISENHUT.D © Division of Operating Reactors 79/05/22 2pp
- 8004040346 Forwards articles from Los Angeles Times re analysis of util financial problems aggravated by commitment to large coal & nuclear power plants Environmental Defense Fund 80/02/27 7pp
- 8004030010 Requests permanent denial of DL ANSHUTZ, T L Affiliation Unknown 80/03/08 1p
- 8004030008 Urges licensing of power plants ready or near ready for operation Reliable power reserves at stake in CA TERRELL,O D Affiliation Unknown 80/03/10 ip
- 8004030180 Urges release of hold on licensing plant for operation Area may suffer brownouts & blackouts if plant not licensed within one or two months MDRRIB.E W Affiliation Unknown 80/03/10 ip
- 8004020250 Responds to 800207 mailgram to President Carter re validity of rumor concerning 800531 issuance of CL to facility NRC has no knowledge of rumor & no such decision has been made NRC is preparing action plan to complete licensing reviews DENTON: H R Office of Nuclear Reactor Regulation 80/03/17 2pp
- 8004110303 Opposes nuclear power plants due to extreme danger to population resulting from meltdown Winds in area of facility would quickly spread radiation over 35-mile radius NRC should expand evacuation area accordingly ANSON, W. B Affiliation Unknown 80/03/25 5pp

I Financial information

- 8004100233 Forwards Annual Financial Rept 1979 GRANE, P.A. Pacific Gas & Electric Co. 80/04/03 ip
- --8004100244 Annual Financial Rept 1979 * Pacific Oas & Electric Co 80/02/22 43pp
- G Inspection reports, IE Bulletins & carrespondence
- B004280016 Forwards IE Insp Repts 50-275/80-02 & 50-323/80-01 on B00211-14 & 20 No noncompliance noted SPENCER.O S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004280022 IE Insp Repts 50-275/80-02 & 50-323/80-01 on 800211-14 & 20 No noncompliance noted Major areas inspected const & mod activities including license actions on previous findings, deficiency repts item. IE bulletins & circulars HAYNEB, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch MORRILL, P J . KIRECH, D F . Region 5, San Francisco, Office of the Director 80/03/04 7pp

- 8004150205 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening or PORV > Block Valve " No specific action or response necessary ENGELKENR H Region 5, San Francisco, Office of the Director 80/03/31 ip
- 6004100101 Forwards 1E Circulai 80-05, "Emeigency Diesel Generator Lubricating Oil Addition / Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 ip
- 8004110111 Forwards IE Into Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02
- 8004220038 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN R H Region 5, San Francisco, Office of the Director 80/04/02
- 8004180148 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine 0:1 Sys " No written response required ENGCLKEN.R H Region 5, San Fiancisco. Office of the Director 80/04/03 ip
- 8004230379 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312,Type 304 Stainless Steel Pipe " Action required ENGELKEN,R H Region 5. San Francisco, Orfice of the Director 80/04/04 ip
- 8004220174 Forwards IE Bulletin 80-0B, "Exam of Containment Liner Penetration Welds" Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/07 ip
- 8 Reportable occurrences, LERs & related correspondence
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made or inferior math Cause unstated All utils w/pumps were notified NRC headquarters notified no 770812 WHITT.K W Region 2. Atlanta: Office of the Director 77/08/12
- T Hearing transcripts on non-antitrust matters
- 8004140451 Transcript of 800403 hearing in San Luis Obispo CA re earthquakes Pp 1-179 * Atomic Safety and Licensing Board Panel B0/04/03 180pp
- U Congressional/Executive Correspondence
- 8004030013 Requests comments on encl HH McD; ll ltr re failure by NRC & other govt agencies to properly handle responsibilities LAGDMARSING,R J House of Rep 80/03/05 4pp

H General correspondence

- 8004300445 Discusses utilizing on interim basis qualified plant personnel as shift technical advisors while regular shift technical advisors are undergoing training Program to be fully implemented by 810101 UTLEY.E E Carolina Power & Light Co 80/04/25 ip
- l Financial information
- B004010405 Forwards Annual Financial Report 1979 Also forwards info re cash flow projection to guarantee retrospective premium liability to nuclear hiability insurance carriers GRAHAMAN E Carolina Power か Light Co B0/03/27 4pp
- ---8004010409 Annual Financial Rept 1979
 * Carolina Power & Light Co 80/03/01 36pp
- P Operating license stage documents & correspondence
- 8004070184 Forwards agenda for 800325 & 26 meeting on emergency preparedness for facility site NRC/FEMA leview team will discuss emergency preparedness status re details of problems identified in sessions wistate & local representatives ORIMES.8 K Emergency Preparedness Task Force 80/03/04 3pp
- --8004070198 Memo of understanding between NRC & FEMA to accomplish prompt improvement in tadiological emergency planning & preparedness
 GOSSICK. (, V Ottice of the Executive Director for Operations CAMM.F Emergency Preparedness Task Force 80/03/04 10pp
- 8004070404 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITG.T A Operating Reactors Branch 3 80/03/10 3pp
- 6004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Dethesda Operations Ctr EIBENHUT.D 0 Division of Operating Reactors 60/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004090294 Notification of 800321 meeting w/util in Bethesda.MD to discuss radiological ETS proposed changes, methodology for calculating dose release & process control program for solidification of waste HARNON, J. N. Operating Reactors Branch 3 80/03/19 ip
- 8004150093 Summary of 800321 meeting w/util in Bethesda.MD re radiological ETB changes release dose calculations & waste solidification program control HANNON, J N Operating Reactors Branch 3 80/03/28 3pp
- B0040B03B3 Responds to NRC B00201 request for add1 info on containment purging Reactor bldg vent radiation monitoring sys contains dual-independent monitors & trip sys which meet design requirements of IEEE Std 279-1971
 UTLEY, E.E. Carolina Power & Light Co. 80/04/01 42pp
- 8004160282 Responds to 800110 request for addl info re failuro of control rods to fully insert Enci table provides list of failures during most recent ruel cycles Records not available for scrams before Jan 1979
 UTLEY, E E Carolina Power & Light Co G0/04/11 2pp
- 8004170015 Requests Tach Specs to begin Cycle 4 operation Forwards proposed Tach Specs & NEBO-24235, "Supplemental Reload Licensing Submittal for Reload 3," Revision (UTLEY, E E Carolina Power & Light Co 80/04/11 2pp
- --8004170019 Proposed sexisions to Tech Specs Sections 1 & 3/4, reflecting changes necessary to begin Cycle 4 operation * Carolina Power 8 Light Co 80/04/!1 1799
- --8004170020 "Supplemental Reload Licensing Submittal for Reload 3,"
 Revision 1
 RASH, J. L. General Electric Co. NEDO-24235 R1 80/03/31 35pp
- 8004250410 Submits info re fire bairier penetration seals & supervision of valve control circuits, in response to 800214 ltr Valve control circuit mod completed & tested for Unit 2 Unit 1 will be completed by 800415 Forwards Tech Spec changes UILEY,E E Carolina Power & Light Co 80/04/22 2pp

- --8004250412 Tech Specs 3 7 8 % 4 7 8 for fire barrier penetration seals * Carolina Power & Light Co 80/04/22 10pp
- BO04280497 Submits summary of min critical power ratio limits error corrected by Amend 49 to License DPR-62 ½ util corrective actions Verification guide for nuclear dynamics parameters data book has been changed UTLEY.E E Carolina Power & Light Co 80/04/23 2pp
- 8004300323 Submits proposal on allocation of radioactive effluents between racilities in response to 800321 request Liquid & gaseous releases will be allocated between facilities on equal basis
 UTLEY, E. E. Carolina Power & Light Co. 80/04/23 2pp
- O Inspection reports. IE Bulletins & correspondence
- 6004040461 Responds to IE Bulletin 79-01B. "Environ Gualification of Class IE Equipment" Delay in 45-day response caused by GE data discrepancies as noted in 800303 teleon w/NRC Addl data to be provided in 90-day response FURR, B J Carolina Power & Light Co 80/03/13 1p
- B004280050 Forwards IE lnsp Repts 50-324/80-06 & 50-325/80-06 on B00124 No noncompliance noted LEMIS.R C Region 2, Atlanta Reactor Operations Nuclear Support Branch B0/03/18 2pp
- --8004260057 IE Insp Repts 50-324/80-06 t 50-325/80-06 on 800124 No noncompliance noted Major areas inspected assessment of effect on plant safety re implementation of near-term items presented in NUREG-0660 KFLL060.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch (EWIS.R C Region 2. Atlanta, Office of the Director MADSEN.G Region 4. Dallas, Office of the Director 80/03/17
- 8004230076 Submits response to IE Bulletin 80-03 Five spare cells were pulled from stock & visually inspected w/n opening plastic shipping & storage bag No charcoal was noted in plastic bag Periodic visual insps & insp of cells are sufficient FURR.B J Carolina Power & Light Co 80/03/21 2pp
- GOD4150497 Forwards IC Info Notice 80-12, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 60/03/31
- 8004080578 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oll Addition & Gusite Supply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- B004i500A7 Forwards IE info Notice 80-13, "OE Type 8BM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240245 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees "No action required Q'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 2pp
- BOO4180378 Forwards IC Circular 80-07. "Problems W/HPCI Turbine Oil Sys " No written response required O'RECLLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03
- BOD4110010 Forwards & Bulletin GO-O7. "BHR Jet Pump Assembly Failure " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/O4/O4
- 8004230117 Forwards 1F Bulletin 79-03A "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe" Action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180340 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07

- 8004290116 Ack receipt of 800226 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-324/80-03 %
- --8004270122 Responds to NRC 800212 ltr re violations noted in IE lnsp Repts 50-324/80-03 % 50-325/80-03 Corrective actions hoses properly disposed of f. surveys conducted to assure correct radioactive math labeling TOLLISON, A.C. Carolina Power & Light Co. 80/02/26 3pp
- --800429012B Forwards IE Insp Repts 50-324/80-03 & 50-325/80-03 on 800123-25 & notice of violation STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/12 2pp
- --8004290135 Natice of violation from insp on 800123-25
 * Region 2, Atlanta, Office of the Director 80/0 80/02/11 1p
- ~~8004290141 IE Insp Repts 50~324/80~03 & 50~325/80~03 on 800123~25 Noncompliance noted failure to label containers of radioactive matl & to evaluate & identify radiation hazards associated w/contaminated fire hose OIBSON, A F. JACKSON, L. L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/11 5pp
- G004210293 Responds to IF lnsp Repts 50-324/80-08 & 50-325/80-08 Repts contain no proprietary info Security Instruction SI-18 has been revised to require roll call printout within five minutes of vital area evacuation TOLLISON.A C Carolina Power & Light Co 80/04/14 2pp
- R Periodic operating reports & related correspondence
- 8004010461 Forwards "Environ Surveillance Rept, Jan-Dec 1979 " TOLLISON A C Carolina Power & Light Co 80/03/28 1p
- --8004010446 "Environ Surveillance Rept.Jan-Dec 1979 " EDWARDS,D H Carolina Power & Light Co 80/03/24
- 8004140445 Forwards monthly operating repts for Mar 1980 TOLLISON A C Carolina Power & Light Co 80/04/04
- --G004140447 Monthly operating repts for Mar 1980 WILLIS:E Carolina Fower & Light Co G0/04/03 12pp
- S Reportable occurrences, LERs & related correspondence
- 8004090111 PND-11-B0-043 on B000315, subcontractor labor force started picketing site On B00315 & 16 majority of const forces did not report to work On B0031B, 77 of 600 individuals failed to report to work Estimated outage may be extended three days HARDIN, A K, KELLOGG, P J Region 2, Atlanta, Office of the Director B0/03/1B ip
- 8004020297 RO-2-80-23 on 800319 during liquid penetrant test of reducing insert for 2D reactor recirculation pump committed to in LER 2-79-109. linear indication found at toe of weld between reducer & nipple Weld filed b
- 8004030176 RO 2-80-23 on 800319. during liquid penetrant test of reducing insert for reactor recirculation pump 2B. linear indication was found at toe of weld between reducer k nipple Other welds satisfactorily liquid penetrant tested TOLLISON.A C Carolina Power & Light Co 80/03/19 ip
- 8004010394 Forwards LER 80-038/03L-0 TOLLISON: A C Carolina Power & Light Co 80/03/27 1p
- -8004010400 LER 80-038/03L-0 on 800229, while terminating wire to contact 3 on relay 52AK, recirculation pump M/O set tripped Caused by de-energizing of relay when connection was made for safety Bpcclaf procedure was revised & test successfully completed TOLLISON, A C Carolina Power & Light Co 80/03/27 2pp
- 8004080458 Forwards LER 80-023/017-0 TOLLISON, A C Carolina Power & Light Co 80/03/28 ip
- --8004080464 LER 80-023/01T-O on 800319, during liquid penetrant test of reducing insert for 2B reactor recirculation pump, linear indication was found at toe of weld between reducer & nipple Cause unknown Analysis planned TOLLISON, A.C. Carolina Power & Light Co. 80/03/28 ip

- 8004080357 Notifies that triaxial time-history accelograph sys alarmed 204080337 Notifies that triaxial time-history accelograph sy & recorded on 800208 Seismic monitoring at Shearon Harris Plant & Univ of SC indicated no seismic activity Recorders initiated by Nonseismic shock! vibration TOLLISONA C Carolina Power! Light Co 80/04/01 2pp
- 8004090332 RD on 800215, discovered approx 50% of fire detectors in Zone 14 of reactor bldg were inoperable Caused by reversal of polarity in electrical leads, probably occurring during recently completed plant mod Repairs planned TOLLISON.A C Carolina Power & Light Co 80/04/02 1p
- 8004070333 Forwards LER 80-034/03L-0 TOLLISON, A C Carolina Power ? Lig Light Co 80/04/04 1o
- --8004070337 LER 80-034/03L^0 on 800307.while performing visual insp of accessible snubbers, snubbers 2041-18522,25W-17585166 & 2E41-285105 found inoperable Caused by pipe clamp slippage, missing locking pin % leaking shaft seal, respectively TOLLISON, A C Carolina Power & Light Co 80/04/04 2PP
- 8004150466 RO on 800404.1/4-inch through-wall horizontal crack was located in heat-affected zone 1/4 inch below weld joining 3/4-inch test connection to half coupling on 6-inch reactor water cleanup header Repair being evaluated by engineering TOLLISON.A C Carolina Power & Light Co 80/04/04 1p
- 8004150504 RO on 800231.during investigation re lack of pressure during local leak rate text on reactor water cleanup isolation valves found thiough-wall horizontal crack on heat-affected zone Repair under evaluation TOLLISON, A C Carolina Pawer & Light Co 80/04/04 ip
- 8004150444 Forwards LER 80-024/03L-0 TOLLISON, A C Carolina Power 3 Light Co 80/04/08 [p
- --800415044B LER 80-024/031-0 on 800311.while decontaminating torus in preparation for mods, coating found blistered under normal water line Caused by demineralized water entrapsed between steel liner & coating Samples to be tested in DBA onviron TOLLISON. A C Carolina Power & Light Co 80/04/08 by
- 8004220572 Forwards LER 80-025/03L-0 TOLLISON.A C Carolina Power & Light Co 80/04/15 ip
- --B004220583 LER 80-025/03L-0 on 800318, while performing refueling interlock check, one rod was withdrawn one notch to check refueling bridge interlocks w/shorting links installed Links should have been removed first TOLLISON, A C Carolina Power & Light Co 80/04/15 2PP
- 8004220732 Forwards LER 80-031/01T-0 TOLLIBON,A C Carolina Power & Light Co 80/04/15 ip
- ---8004220740 LER 80-031/01T-0 on 800404, while investigating why pressure could not be maintained during local leak rate test on RWCU isolation valves FOO: & FOOH-horizontal O 23-inch crack was found in heat-affected jone Cause being examined & Carolina Power & Light Co 80/04/15 1p
- 8004280587 Forwards LER 80-029/03L-0 TOLLISON,A C Carolina Power & Light Co 80/04/21 ip
- --8004280577 LER 80-027/03L on 800323, following reactor scram, HPCI discharge valve E41-F006 would not remain open following low level initiation signal Caused by HPCI turbine stop valve E41-V8 opening too quickly Spring loaded bypass adjusted TOLLISON.A C Carolina Power & Light Co 80/04/21 2pp
- 8004280583 Forwards LER 80-027/03L-0 TOLLISON, A.C. Carolina Power & Light Co. 80/04/22 1p
- ---B004280592 LER 80-027/03L-0 on 800325, while performing periodic test 1 7 IPC leak detection level switch for HCU 24-47 did not actuate Caused by contacts on switch not meeting Switch TOLLISON A C Carolina Power & Light Co 80/04/22 1p
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1 f Security, medical, emergency & fire protection plans
- 8004070176 Summary of 800305 & O6 meeting w/util at facility re adequacy of fire protection provided for redundant safe shutdown cabling separated by greater than five ft horizontal distance. HANNON, J Operating Reactors Branch 3 80/03/06 3pp

- 504030-00 factive action or 300005 24 meeting doubtil PAL & FEMA in Bolavia (to be seen en yearly alan against NUREG-0654 / FEMA-REPHI HAMMAN UN Chemating Realizer Branch 3 80/03/11 2pp
- TouA020472 Distribbes findings or 800205-06 meeting W/NAC be fine protection issues Forward protection actions to be implemented by 801001 to two cases or inadequate cable separation
 UTLETTE Carolina Power ' Light Co 80/04/01 4pp
- H General correspondence
- 6004330445 Discusses utilizing on interim basis qualified plant personnel as shift technical advisors unite regular shift technical advisors are undergoing training Program to be fully implemented by 810101 UTLEY.E.E. Carolina Power 5 Light Co. 80/04/25 ip
- I Financial inforcation
- 8004010405 Forwards Annual Financial Report 1979 Also forwards info re cash flow projection to guarantee setrospective prensum liability to nuclear liability insurance carriers GRAHAM.N E Carolina Power? Light Co 80/03/27 4pp
- --8004010467 Annual Financial Rept 1979 * Caroline Power & Light Co 80/03/01 36pp
- P Operating livense stage documents? correspondence
- 8004070184 Forwards agenda for 800325 & 26 meeting on emergency preparedness for facility site NPC/FEMA review team will discuss emergency preparedness status re details of problems identified in sessions whatate & local representatives GRIMES B K Emergency Preparedness Task Force 80/03/04 3pp
- ~-8004070188 Meno of understanding between NRC & FEMA to accomplish prompt improvement in radiological emergency planning & preparedness GUSSICM.L V Office of the Executive Director for Operations CAMM.F Emergency Preparedness Task Force 80/03/04 10pp
- B004070404 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO T A Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "huclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EIGERBUT D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Lin' Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004090294 Notification of 800321 meeting w/util in Bethesda,MD to discuss radiological ETS proposed changes,methodology for calculating dose release & process control program for solidification of waste MARNON, J.N. Operating Reactors Branch 3 60/03/19 1p
- 8004150053 Summary of 800321 meeting w/util in Bethesda.MD re radiological ETS changes release dose calculations & waste solidification program control HANNON, J.N. Operating Reactors Branch 3 80/03/28 Opp
- S0040B03B3 Responds to NRC B00201 request for add1 info un containment purging Reactor bldg vent radiation monitoring sys contains dual independent monitors & trip sys which meet design requirements of IEEE Bdd 279-1971
 UTLEY/EE Carolina Power & Light Co 90/04/01 42pp
- B004160282 Responds to B00110 request for addl into re failure of control rods to fully insert Enc! table provides list of failures during most recent fuel cycles Records not available for scrams before Jan 1979
 UTLEY.E E Carolina Power & Light Co 80/04/11 2pp
- BD04250410 Submits info is fire barrier penetration seals & supervision of valve control circuits in response to B00214 ltr Valve control circuit mod completed i tested for Unit 2 Unit i will be completed by B00615 Forwards Tech Spec changes UTLEY.E E Carolina Power & Light Co B0/04/22 2pp
- --8004250412 Tech Specs 3 7 8 & 4 7 8 for fire barrier penetration seals # Carolina Power & Light Co 80/04/22 10pp

- 8004300323 Submits proposal on allocation of jadioactive effluents between racilities in response to 800321 request Liquid > gaseous releases will be allocated between facilities on equal basss -Carolina Power & Light Co 80/04/23 2pp HTLEV.E.E
- Q Inspection reports, IF Bulletins * correspondence
- 8004040461 Responds to 16. Builetin 79-01B, "Environ Qualification of Class IE Equipment ' Delay in 45-day response caused by 0£ data discrepancies as noted in 800303 teleon w/NRC Addidata to be provided in 90-day response
 FURR.B J Carolina Power & Light Co 80/03/13 ip
- 8004280150 Forwards IE Insp Rept 50-325//9-42 on 791127-29 No noncompliance noted insp Rept 30-32/7/42 by 77112/-F7 No LEMISR C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/13 2pp
- --8004280157 IF Insp Rept 50-325/79-42 on 791127-29 No noncompliance noted Major areas inspected 791120 Unit I reactor trip KELLOGO J Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch RILEY, B V, OUZTS, J E Region 2. Atlanta, Office of the Director 80/03/13 4pp
- B004280050 Forwards IE Insp Repts 50-324/80-06 \$ 50-325/80-06 on B00124 No noncompliance noted LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch B0/03/18 2pp
- --8004280057 IE Insp Repts 50-324/80-06 / 50-325/80-06 on 800124 No noncompliance noted Major areas inspected assessment of effect on plant safety to implementation of near-term items presented in NUREG-0660 KELLOGO, P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch LEMIS.R C Region 2. Atlanta. Office of the Director MADSEN.G Region 4. Dallas. Office of the Director 800/03/17
- 8004230076 Submits response to IE Builetin 80-03 Five spare colls wore pulled from stock & visually inspected w/o opening plastic shipping & storage bog No charcoal was noted in plastic bag Periodic visual insps & insp of cells are sufficient FURR.B J Carolina Power & Light Co 80/03/21 2pp
- 8004150497 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080598 Forwards IE Circulai 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director BO/04. Region 2. Atlanta, Office of the Director - 80/04/01
- 8004150067 Forwards IE Info Notice 80-13, "QE Type SBM Control Switches Defective CAM Followers " No specific action or response O'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240245 Forwards IE Info Notice 80-14, "Bafety Suggestions From D'ARCILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180378 Forwards IE Circular 80-07, "Problems W/MPCI Turbine Oil No written response required

 LLY, J P Region 2, Atlanta, Office of the Director 80/04/03 D'REILLY, J P
- 8004110010 Forwards IE Builetin 80-07. "BWR Jet Pump Assembly Failure " Written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director HO/04/0/ "BO/Q4/Q4
- 8004180340 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07

- 8004270116 Ack receipt of 800226 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-03 & 50-325/80-03 STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/10 in
- --8004290122 Responds to NRC 800212 ltr re violations noted in 1E Insp Repts 90-324/80-03 & 50-325/80-03 Corrective actions hoses properly disposed of 1 surveys conducted to assure correct radioactive matl laboling TOLLISON, A C Carolina Power & Light Co 80/02/26 3pp
- ~-8004270128 Forwards IE Insp Repts 50-324/80~03 & 50-325/80~03 on B00123-25 & notice of violation STDHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/12 2pp
- --8004270135 Notice of violation from insp on 800123-25 * Region 2, Atlanta, Office of the Director 80/02/11 ip
- --8004290141 IE Insp Repts 50-324/80-03 & 50-325/80-03 on 800123-25 Noncompliance noted failure to label containers of radioactive matl & to evaluate & identify radiation hazards associated w/contaminated fire hose GIBBON, A F. JACKBON, L. E. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/11 5pp
- 8004210293 Responds to IE Insp Repts 50-324/80-08 & 90-325/80-08 Repts contain no proprietary info Security Instruction BI-18 has been revised to require roll call printout within five minutes of vital area evacuation
 TOLLISON, A C Carolina Power & Light Co 80/04/14 2pp
- R Periodic operating reports & related correspondence
- 8004010461 Forwards "Environ Surveillance Rept. Jan-Dec 1979 "
 TOLLISON, A C Carolina Power % Light Co BO/03/28 ip
- --8004010468 "Environ Surveillance Rept. Jan-Dec 1979 "
 EDWARDS.D H Carolina Power & Light Co 80/03/24 50pp
- 8004140445 Forwards monthly operating repts for Mar 1980 TOLLISON, A C Carolina Power & Light Co 80/04/04 ip
- --8004140447 Monthly operating repts for Mar 1980 WILLIB,E Carolina Power & Light Co 80/04/03 12pp
- S Reportable occurrences, LERs & related correspondence
- 8004090111 PNO-II-80-043 on 8000315, subcontractor labor force started picketing site On 800319 & 16 majority of const forces did not report to work On 800318, 97 of 600 individuals failed to report to work Estimated outage may be extended three days HARDIN, A K , KELLOGG, P J Region 2. Atlanta, Office of the Director 80/03/18 ip
- 8004010385 Forwards LER 80-004/03L-0 TOLLISON,A C Carolina Power & light Co 80/03/25 ip
- --g004010370 LER 80-004/03L-0 on 800308, during normal plant operation, oxygen channel of containment atmospheric monitor CAC-AT-1263-2 experienced 1% step change Caused by possible wiring or connection problem Monitor repair 1s underway TOLLISON, A C Caroline Power % Light Co 80/03/25 1p
- 8004080566 Forwards LER 80-015/03L-0 TOLLISON, A C Carolina Power & Light Co 80/03/31 1p
- --8004080575 LER 80-015/03L-0 on 800314, during attempt to close HPCI torus suction valve E41-F041, following operability test. RTOB control switch for valve failed Cause not stated Switch replaced TOLLISON, A C Carolina Power & Light Co 80/03/31 ip
- 8004080357 Notifies that triexial time-history accelograph sys alarmed & recorded on 800208 Seismic monitoring at Shearon Harris Plant & Univ of SC indicated no seismic activity Recorders initiated by nonseismic shock & vibration TOLLISON.A C Carolina Power & Light Co 80/04/01 2pp
- 8004080453 Forwards LER 80-021/03L-0 TOLLISON, A C Carolina Power & Light Co 80/04/03 ip

- --8004080454 (ER 80-02) UTL-0 on 500304, while altempting to start 10 RHR syc water pump, pump would not start due to low suction pressure signal in start logic Caused by shut instrument isolation valve for suction pressure switch 1-5N-PS-1175 TOLLISO 4.A C Catolina Power & Light Co 80/04/03 2pp
- 8004150466 RO on 800404,1/4-inch through-wall norizontal crack was located in heat-affected ione 1/4 inch below weld joining 3/4-inch test connection to helf caupling on 6-inch reactor water cleanup header Repair being availated by engineering TOLLISONA C Carolina Power & Light Co 80/04/04 1p
- BO04150804 RC on B0023), during investigation is lack of pressure during local leak rate test on reactor water cleanup isolation valves, found through-wall horizontal crack on heat-affected ione Repair under evaluation TOLLISON. A C Carolina Power & Light Co 60/04/04 lp
- --8004220608 LER 80-022/03L-0 on 800318, during normal operation, containment atmosphere monitor, CAC-AR-1263, was erratic Caused by deteriorated inlet hose plugging inlet valve Hase replaced (their monitor) will be inspected * Carolina Power & Light Co. 80/04/15 ip
- 8004220676 Forwards LER 60-019/03L-0 TOLL 1807.A C Carolina Power 5 Light Co 80/04/15 ip
- ---8004220687 LER 80-019/03L-0 on 800318.while performing high steamline radiation channel alignment & functional test drawer D12-RM-KA03D.Model 238X6063.was found out of specs Caused by instrument drift Drawer recalibr Carolina Power ? (19ht Co 80/04/15 2pp
- 8004220538 Forwards LER 80-027/03L-0 TOLLISON,A C Carolina Power A Light Co 80/04/16 1p
- --8004220547 LER 80-027/03L-0 on 800319.during normal plant operation, standby gas treatment sys 18 would not reset Caused by tripped control power circuit breaker Bleaker was reset, closed & standby gas treatment sys was successfully run TOELISON, A C Carolina Power & Light Co 80/04/16 1p
- 8004280576 Forwards LER 80~030/03L-0 TOLLISOMA C Carolina Power % Light Co 80/04/21 1p
- --8004280584 LER 80-030/03L-0 on 800324 uperator noticed that containment atmospheric monitor 1-CAC-AT-1259 had low flow alarm & would not remain tunning Caused by shorted air dryer compressor due to high cabinot moisture & bad sample pump TOLLISON, A C Carolina Power & Light Co 80/04/21 1p
- 8004290397 Forwards LER 80-031/031-0 TOLLIBON.A C Carolina Power 7 Light Co 80/04/24 1p
- --8004290401 LER 80-031/03L-0 on 800327 during normal operation, containment atmosphere organ monitor 1-CAC-AT-1263 had step change in 800330.1% step change observed Gaused by shift in instrument callbr daygen monitor will be replaced TOLLISON, A C Carolina Power & Light Co 80/04/24 1p
- BOO4270487 Forwards LER 80-025/03L-0 TCLLISON.A C Carolina Power & Light Co BO/04/24 1p
- --8004270494 LER 80-025/03L-0 on 800405 following reactor shutdown, control red 30-03 had dual full in & full out core display position regardless of actual rod position Caused by short in probe buffer card terminal connections
 TOLLISON, A C Carolina Power & Light Co 80/04/24 lp
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040017 Submits addl guidance to AUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment " Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Davision of Project Management 80/02/21 3pp
- 800429017: Recommends issuance of policy statement explaining relationship between Commission action to permit zero or low power operation & licensing pause Drart statement encl BICKMIT.L. Diffice of the Ceneral Counsel HANRAHAN.E J Office of Policy Evaluations SECY-80-081A 80/02/22 App

- F. Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791526 ltm.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES.B K Energency Preparedriess Task Force 80/03/11 4pp
- 8004180306 Forwards comments on facility safeguards contingency plan Encl withheld (sef 100FRZ 790) RUBEUSTEIN L. S. Light Water Reactors Branch 4 80/04/01 2pp
- 8004110186 Forwards response to 7911.26-27 pre-acceptance safeguards visit Procedures to incorporate persodic testing of alarm inne supervisory & tamper circuits & evaluation of openings to vital areas reviewed Encl withheld (ref (OCFR2 790) MILLS-L M Tennossee Valley Authority 80/04/02 lp
- 8004170225 Forwards draft revisions to emergency operating instructions EOI-0. "Immediate Actions & Diagnostics." EOI-1. "Loss of Reactor Coolant." & EOI-2. "Loss of Secondary Coolant." & EOI-3. "Steam Generator Tube Rupture "
 MILLS.L M Tennessee Valley Authority 60/04/15 lp
- --8004170227 Draft Emergency Operating Instructions EQI-O. "Immediate Actions & Diagnostics"
 WALKER, J.R., RECORD.D. J. Tennessee Valley Authority 80/01/31
 1300
- --8004170229 Draft Emergency Operating Instructions EOI-1, "Loss of Reactor Coolant," Re-ision 10 BENTON,C T , WALKER,J R , RECORD,D J Tennessee Valley Authority 80/03/31 27pp
- --80041/0231 Draft Emergency Operating Instructions EOI-2, "Loss of Secondary Coolant," Revision 7 WALKER J.R., RECORD D.J. Tennessee Valley Authority 80/03/31 17:00
- --8004170234 Draft Emergency Operating Instructions EO[-3, "Steam Generator Tube Rupture." Revision 7 MILSON.6, MALKER, J.R., RECORD, D.J. Tennessee Valley Authority 80/03/31 13pp

G Adjudicatory correspondence

- 8004020483 Speaks strongly against opening plant so close to largely populated area NRC should be financially responsible & liable should accident occur PATTERN,K Affiliation Unknown 80/02/14 1p
- 8002290321 Requests per iOCFR2 206, public hearing in Knoxville, TN prior to granting of license to fuel facility
 SCOTT, A Affiliation Unknown 80/02/PO 1p
- B004020489 Opposes recent licensing of plant Urges NRC to reverse decision 5 resume moratorium of licensing until Kemeny Commission recommendations have been implemented BOREIFO.T Affiliation Unknown 80/02/29 2pp
- 8004080209 Responds to 800220 request for public hearing under 100FR2 20A prior to issuance of fuel load license to facility NRC approved issuance of low power test license on 800229 Forwards 740325 FR notice & license W/o encl SHAPAR.H K. Office of the Evecutive Legal Director 80/03/11 1p

H General correspondence

- 8004070075 Responds to 791205 ltr addressed to President Carter re expediting of enhanced efforts to license all qualified nuclear plants NRC is in process of issuing several neartern OLs Provides info re NRC licensing activities DENTON, HR Office of Euclear Reactor Regulation 80/03/17 26
- --8004070077 Forwards AF Bissell 791205 ltr encouraging early licensing of facility & all qualifies nuclear plants Requests comments Resolution encl SEALM M President of US & Executive Offices 79/12/13 Spp
- J Insurance & indemnity information
- 8004140442 Forwards Endorsements 1-12 to MAELV Policy MF-102 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/04/07 18pp

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004170065 Forwards Amend 64 to FSAP MILLS,L M Tennessee Valley Authority 80/04/11 2pp
- --8004170067 Amend 64 to FSAR
 * Tennessee Valley Authoraty 80/04/11 150pp
- P Operating license stage documents & correspondence
- 8004040031 Advises of Issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS DF Division of Project Management 80/02/05 7pp
- 8004070415 Discusses potential design deficiency in bypass, override & reset circuits of engineered safoty features Requests review of plant protoction sys design to determine degree of conformance u/listed citeria RUBENSTEIN.L 5 Light Water Reactors Branch 4 80/03/19 App
- 8004070393 Forwards Suppl 1 to NUREC-DOLL, safety evaluation re application for facility Ols W/o encl RUBENSTEIN, L S Light Water Reactors Branch 4 80/03/20 2pp
- 8004020093 Forwards list of requests for add) info re process control program, needed to complete review Response requested by 800417 RUBENSTEIN, L.S. Light Water Reactors Branch 4 80/03/24 App
- 8004010408 Responds to NRC 800223 lti Discusses NRC acceptance of response to Guestion & 65 provided in 791031 FSAR, Amend 62 Series check valves periodically tested to ensure closure No
 - revisions planned MLLLS.L M Tennessee Valley Authority B0/03/25 ip
- BOO4110493 Requests analysis of alequacy of equipment qualification program per NUREG-0588 Supplements NRC 791017 request for data te environ qualification of safety-related equipment RUGENSTEIN.L S Light Water Reactors Branch 4 80/03/25 3pp
- B004140016 Natification of B00404 meeting w/utils in Bothusda.MD to discuss applicants' progress & status in design review re plant shielding & environ quelification of equipment for spaces/sys used in post-accident operations BUCKLEY.B C Light Water Reactors Branch i 80/03/31 7pp
- 8004070228 Forwards revisions to revised response to NUREO-0570, Lessons Learned Task Force short-term requirements includes procedures for reducing & quantifying liquid sys leakage Revisions replace corresponding 771021 responses MILLS, L M Tennessee Valley Authority 80/04/02 127pp
- 8004140327 Forwards "Master Plan for Special Low Power Test Program " MILLS.L M Tennessee Valley Authority 80/04/09 1p
- --8004140332 "Master Plan for Special Low Power Test Program " * Tennessec Valley Authority 80/04/09 87pp
- 8004150551 Forwards application for renewal of NPDEG Permit TN0026450 EL-ASHRY, M T Tennessee Valley Authority 80/04/09 2pp
- --8004150559 Application for renewal of NPDES Permit TN0026450 EL-ASHRY T Tennessee Valley Authority 80/04/09 275pp
- 8004150608 Discusses revision to abnormal operating instruction for reactor trip (AG)-1), submitted 771017 Revision clarifies procedure for operator verification of ATMS Util has written separate emergency operating instruction for ATMS (E0I-14) MILLS,L. (1) Tennessee Valley Authority 80/04/11 7pp
- --8004150615 Emergency Operating Instruction EQI-14, "ATWB," Revision 1 MALKER.J R , CANTRELL.C E Tennessee Valley Authority B0/04/i1 7pp
- 8004210202 Responds to NRC 800128 ltr re util participation in QRNL on-time analyses program Complete analyses sys should be installed by 800630 Forwards util procedure CQ-8QNP-8AP. "Startup Test Program" MILLS.L M Tennessee Valley Authority 80/04/11 ip
- ---9004210205 "Startup Test Program "
 * Tennessee Valley Authority 80/02/22 R3pp

- 8004170069 Proposed amend to License DPR-7°, changing Tech Specs 3 1 2 4,4 1 2 4,3 6 5 9 5 4 6 5 9 MILLS, L M Tennessee Valley Authority 80/04/14 ip
- --B004170073 Proposed changes to Tech Specs 3 1 2 4.4 1 2 3 6 5 9 % 4 6 5 9 consisting of correction to parameter test for divider barrier seal & typing correction

 * Tennesse Vallag Authority B0/04/14 6pp
- 8004170134 Forwards procedure to be used to conduct water hammer test on auxiliary feedwater sys at facility MILLS.L. M Tennessee Valley Authority 80/04/15 1p
- --8004170140 "Water Hammer Test on Addition of Auxiliary Feedwater to Steam Generator " * Tennessee Valley Authority B0/04/15 14pp
- 8004170148 Discusses facility low-pressure turbine preservice insp Util has completed visual & volumetric examinations for turbines Single disc indication discovered on Disc 5 of Turbine 1 Disc should operate reliably throughout plant Life MILLS.L M Tennessee Valley Authority 80/04/15 2pp
- 8004280227 Forwards add1 info in response to NRC 800325 ltr re process control program
 MILLS, L M Tennessee Valley Authority 80/04/22 14pp
- --8004280235 "ECOPAC Sys Procedure for Onsite Solification of Low Level Radioactive Waste at Sequoyah Nuclear Plant" & Addl info re process control program * Anefto,Inc 80/01/31 26pp
- 8004270404 Forwards summary of Westinghouse, TVA & NRC 800320 meeting re control rad guide tube support pins Affidavit for withholding & non-proprietary version enci ANDERSON.T M Westinghouse Electric Carp , PWR Systems Div 80/04/23 46pp
- 8004290290 Responds to NRC 800319 ltr rg changes to engineered safety features Design changes initiated to bring util into compliance w/exception of overriding of one type of safety actuation signal by another which is Westinghouse design MILLB,L N Tennessee Valley Authority 80/04/24 7pp
- 8004300341 Forwards drawings & info per NRC request at 800125 meeting re adequacy of piles supporting waste packaging area & condensate demineralizer waste evaporator bldg Drawings avaitable in Central Files only MILLS, L M Tonnessee Valley Authority 80/04/24 37pp
- G Inspection reports, IF Bulletins & correspondence
- 8004090392 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06 2no
- 8004090405 Forwards IE Insp Rept 50-327/80-03 on B00128-30 No noncompliance noted LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/20 2pp
- --8004070413 IE Insp Rept 50-327/80-03 on 800128-30 No noncompliance noted Major areas inspected augmentation of plant personnel for startup test program, independent safety review, onsite & offsite mpt & technical capability
 DANCE:H G Region 2, Atlanta, Reactor Operations Nuclear Support Branch KELL090;P, COTTLE.W Region 2, Atlanta, Office of the Director 80/02/17 10pp
- 8004160066 Forwards IE Insp Repts 50-327/80-04 & 50-328/80-09 on 800208-07 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004160072 IE Insp Repts 50-327/80-04 % 50-328/80-03 on 800205-07 No noncompliance noted Major areas inspected followup on allegation:10CFR50 55 items. IE bulletins & circulars & observation of safety-related activities CANTRELL-F S Region 2. Atlanta, Reactor Construction & Engineering Support Brench GOUQE,M J Region 2. Atlanta, Office of the Director 80/02/27 5pp
- 8004070072 Requests that util provide procedures to be followed for visual & ultrasonic insplexaminations of turbines to assure mutually acceptable insplexaments to assure submitted for NRC to observe examinations
 RUBENSTEIN/L 8 Light Water Reactors Branch 4 80/03/14 2pp

- 8004210178 Forwards response to 1E Bulletin 80-03, "Loss of Charcoal From Std Type 11.Two-inch.Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS, L M Tennessee valley Authority 80/03/21 4pp
- 8004010374 Forwards util visual insp procedure SMI-1-1-1, "Preservice Baseline Insp of Low Piessure Turbine." in response to NRC 800313 request Ultrasonic / visual insp of low piessure turbines is scheduled to be completed by 800331 MILLS.L II Tennessee Valley Authority 80/03/26 1p
- --B004010379 "Preservice Baseline Insp of Low Pressure Turbines " Westinghouse ultrasonic insp program encl ZIEOLER, SIMMONS Tennessee Valley Authority 80/03/11 12pp
- B004190527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of FDRV & Block Valve " No specific action or response necessary O'REILLY, J. F. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circulai 80-05, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required O'REILLY, J.P. Region >. Atlanta, Orfice of the Director BO/04/01 200
- BOD4150077 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/02
- 8004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees "No action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/02 3on
- 8004180275 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 2pp
- 8004230142 Forwards IF Bulletin 79-03A "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainloss Steel Pipe " Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Wolds" Written response required O'REILLY, J.P. Region 7. Atlanta, Orfice of the Director 80/04/07
- 8004170155 Special Maint Instruction SMI-1-1-1. "Preservice Baseline Insp of Low Pressure Turbines" ZIGOLER, SIMMONS Tennessee Valley Authority 80/03/11 13pp
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLS.L M. Tennessee Valley Authority 80/04/23 3pp
- 8004270400 Forwards Revision 7 to preservice baseline insp & inservice insp program, incorporating App E re notification of indications. Unit 2 drawings & revisions to Section 2 MILLS, L M Tennessee Valley Authority 80/04/24 ip
- --B004290406 Preservice baseline insp & inservice insp program.
 Revision 9
 MCLOUD, D O , DANIELS, BELEW Tennessee Valley Authority B0/03/18
- R Periodic operating reports b related correspondence
- 8004180391 Forwards monthly operating rept for Mar 1980 BALLENTINE.J M Tennessee Valley Authority 80/04/11 1;
- --8004180394 Monthly operating rept for Mar 1980
 WALKER,F M Tennesso Valley Authority 80/04/03 9pp

```
5 Reportable occurrence (En. / related correspondence
8004220084 PAU-77-143 Paritic Pump Co supplied facilities u/production
     Tot of 40 pumps mig using shafts made or interior math
Cause unstated All utils wipumps were nutified MRC
headquarters notified on 770812
WHITT, W. W. Region 2. Arlanta Office of the Director 77/08/12
8004280490 Forwards final deficiency reptile improperly installed reactor coolant drain HILLS.L II Tennessee villey Authority 80/03/03 ip
--8004280496 Final deficiency rept re improperly installed teactor
coolant drain line Reanalysis by othly Westinghouse has
changed norrie? support loads Two snubbers replaced
MillS.L M Tennessee Valley Authority 80/03/03 ip
8004030245 RO 50-327/802 on 800306, while in Mode 6, loading fuel for first core load, contents of cask decontamination collector tank discharged via liquid radwaste efficient line to cooling tower blowdown of 6 flow estimate BALLENTINE.M Tennessee Valley Authority 80/03/06 1p
 8004030233 RO 50-327/803 on 800310, sample: flow through radine &
     particulate filters in novillary bldg ventilation sys
gaseous effluent monitor was not maintained for 3-h & 15
minutes Caused by delay in installing auxillary equipment
BALLENTINE: I Tennessee Valley Authority 80/03/ii ip
 8004030222 RO-50-327/804 on 800311.auxiliary bldg yent sys gaseous
     effluent monitor samples flow rate monitor was made inoperable No flow estimates performed for approx 10-h Caused by Failure to initiate conditional safety inject BALLENTINE. J II Tennessee Vailey Authority 80/03/12
                                                                                                                   Fety injection
80/03/12 1
 8004150418 RD on 800315, received notification that incorrect
     valve operator weight was used in seismic analysis for component cooling water valves FCV-70-133.134 & 183 Caused by analysis error Analysis will be rerun w/correct weight BALLENTINE. J M Tenne, see Valley Authority 80/03/15 t
8004150402 Ro on 800314. Westinghouse Itr indicated potential for guide
     tube support pin tracking Possibly caused by insufficient heat treatment temp at control rod guide pins Guide pins will be replaced by pins whigher heat treatment temp BALLENTINE, J. M. Tennessee Valley Authority 60/03/17
8004020366 Forwards LER 80-002/01T-0
CALHOUM J R Tennessee Valley Authority 80/03/19 ip
--80040203/i LER 80-002/01T-O on 800306, contents of task decontamination collector tank discharged via liquid radwaste effluent line to cooling tower bloodown w/o flow detimates being performed Caused by misunderstanding of Tech Specs KINSEY.W H Tennessee Valley Authority 80/03/19 2pp
8004010375 Forwards LER 80-004/017-0
CALHOUN J R Tennessee Valley Authority 60/03/24
--8004010381 LER 80-004/017-0 on 800311 following initial fuel loading, flow estimates for auxiliary bldg vent monitor not performed for 10-h Caused by misunderstanding of Toch Specs Personnel reinstructed re applicable requirements

RECORD. D J Tennessee Valley Authority 80/03/24 2pp
8004010399 Forwards LER 80-003/017-0
CALHOUN, J. R. Tennessee Valley Authority 80/03/24 1p
                                  ER 80-003/017-0 on 800310, following initial fuel loading,
                                  an auxiliary bldg exhaust sampler not maintained aused by misunderstanding of Tech Specs netructed in applicable requirements

1 ley Authority 80/03/24 2pp
```

rency rept re control rod drop events ligation on generic basis Next 13

n 800314, w/essential raw cooling water

uthority 60/03/26 1p

/ Authoraty 80/03/27 1p

A inoperable personnel dition of operation requires iretation of Tech Spacs y Authority 80/03/27 2pp

01T-0

```
8004020440 Forwards NPDES noncompliance notification MILLS,L M Tennossee Valley Authority 80/03/27
   --B004020447 NPDES noncompliance notification on B00305, Discharge 019 from svc bldg sump effluent exceeded max permit limitation Caused by periodic discharge of snall vols of cleanup wastes Sump cleaned ', measures taken to minimize input EL-ASIRY.M T Tennessee Valley Authority 80/03/13 1p
   B004010433 Forwards LFR BU-007/017-0
CALHOUN, J R Tennessee Valley Authority 80/03/28 1p
   --8004010440 LER 80-007/01T-0 on 800315. following initial core loading, found incorrect (nonconservative) valve operator weights used in seismic analysis for component cooling water valves FCV-70-133, 134 9. 183 Caused by incorrect vendor data TERPSTRA. C. L. Tennessee Valley Authority 80/03/28 2pp
   8004010464 Forwards LER 60-012/03L-0
CALHOUR, J.R. Tennessee Valley Authority 80/03/28 ip
        CALHOUN J R
   --8004010475 LFR 60-012/0JL-0 on B00301, during initial core loading. RHR flow secured or throttled above Tech Specs Caused by intentional increase to allow placement of fuel assemblies near loop 4 hot leg RECORD. D J Tennessee Valley Authority 80/03/28 ip
  8004010502 Forwards LER 80-011/01f-0
CALHOUN, J.R. Tennessee Valley Authority 60/03/28 1p
  --8004010506 LER 80-011/017-0 on 800314, support pin insp at foreign plant
levealed stress corrosion cracking in Mestinghouse supplied
pins linsp supported Mestinghouse ltr informing utils of
potential hazard Pins will be replaced
KINSEY,N H Tennessee Valley Authority 80/03/28 2pp
  8004020312 Forwards final deficiency rept re Ruskin fire dampers
MILLS, L. II Tennessee Valley Authority 80/03/28 ip
  --8004020316 final dericiency rept re spring slipping problem on Ruskin
Piro dampers Mod packages will be installed w/connection of
Number 6 screw using washer, stan lockwasher & hex nut
through narrow portion of spring slot
* Tennessee Valley Authority 80/03/28 ip
  8004090418 Forwards LER 80-013/03L-0
CALHOUN, J.R. Tennessee Valley Authority 80/04/01 ip
 --8004090426 LFR 80-013/03L-0 on 800302 failed to analyze samples from
Unit 2 shield bldg exhaust Caused by misunderstanding of
surveillance requirements Lab personnel instructed on
sampling & analysis requirements
KINSEY.W H Tennessee Valley Authority 80/04/01 2pp
 8004080519 Forwards LER 80-008/03L-0
CALHOUN, J R Tennessee Valley Authority 80/04/02 1p
 --8004080526 LER 80-008/03L-0 on 800303 cooling tower blowdown effluent
line flow monitor O-FR-27-1/5 was declared inoperable Flow
monitor consistently indicated higher flowrate than actually
existed Cause unknown Different instrument to be installed
KINSEY.W H Tennessee Valley Authority 80/04/02 2pp
8004080616 Forwards LER 80-009/03L-0
CALHOUN, J R Tennesses Valley Authority 80/04/02 1p
     -8004080422 LER 80-009/03L-0 on 800303, liquid radwaste efficient line
flow monitor 0.fT-7/-42 consistently indicated higher
discharge flow rate than actually observed Cause not
stated Flow monitor modified & returned to svc
KINSEY, W H Tennessee Valley Authority 80/04/02 2pp
 8004090333 Forwards LFR 80-016/03L-0
       CALHOUN, J. R.
                                          Tennessee Valley Authority 80/04/03 ip
--8004090336 LER 80-016/03L-0 on 800307, at completion of fuel loading & w/core alterations still underway. Si-65 was not performed Gaused by misinterpretation of Tech Specs by personnel No corrective actions necessary RECORD. D J Tennessee Valley Authority 80/04/03 2pp
8004090427 Forwards LER 80-010/03L-0
CALHOUN.J R Tennessee Valley Authority
                                                                                                                         80/04/03 1p
```

```
--B004090433 LER 80-010/03L-0 on B00304.gaseous vent flow rate monitors for Units 1 & 2 shield bldgs & auxiliary bldg were declared inoperable Cause not stated Gaseous flow rate monitors to be redesigned KINSEY,W H Tennessee Valley Authority B0/04/03 2pp

B004090453 Forwards LER 80-015/03L-0 CALHDUN,J R Tennessee Valley Authority 80/04/03 1p
```

--B004090457 LER B0-015/03L-0 on B00305, while in Mode 6 w/fuel loading complete, pressure was only being monitored in one steam generator % reactor pressure vessel Caused by misunderstanding of surveillance instruction RECORD D J Tennessee Valley Authority 80/04/03 ip

800415040B RO on 800404, investigation of manufacturer std 1/4-inch U bolt, used on vendor-designed pipe supports for 3/4-inch Class A pipes revealed overstress during seismic event Caused by design error Affected supports will be redesigned BALLENTINE, J M Tennessee Valley Authority 80/04/07 ip

8004180460 Forwards LER 80-021/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/07 ip

--8004180465 LER BD-021/03L-0 on 80030B, while in Mode & flow rates from auxiliary bldg ventilation sys flow rate monitor were not recorded for three shifts Caused by misreading of notation used in surveillance instruction Temporary change issued RECORD, D. J. Tennessee Valley Authority 80/04/07 2pp

8004140428 Forwards LER 80-018/01T-0 GALHDUN, J R Tennessee Valley Authority 80/04/08 ip

--B004140432 LER B0-01B/01T-0 on B00326, while in Mode 6 w/all fuel loaded, exposed cables inside containment between conduit & panetrations not qualified to re-evaluated post-LDCA max dose levels Cables shielded from exposure to new dose level ROBINSON, F Tennessee Valley Authority 80/04/08 2pp

8004150528 Forwards LER 80-005/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/08 1p

--8004150533 LER 80-005/03L-0. on 800311, while performing 81-247 605, reactor solid state protection sys was placed in input inhibit mode, removing high voltage from source range channel N31 Caused by removal of fuses from voltage cut out relay MCGRIFF, J M Tennessee Valley Authority 80/04/08 2pp

80D4150539 Forwards LER 80-019/01T-0 CALHOUN, J.R. Tennessee Valley Authority 80/04/08 ip

--8004150547 LER 80-019/01T-0 on 800326, found possibility of not maintaining control room habitability due to leakage of unfiltered air Possibly caused by isolation dampers Corrective mods planned ROBINSDN.F Tennessee Valley Authority 80/04/09 2pp

8004180397 Forwards LER 80-017/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/04/08 ip

~-B004180407 LER 80-017/03L-0 on 800310, while in Mode 6, turbine bldg sump monitor 0-RM-90-212 alarm kept coming in Monitor was declared inoperable, Caused by malfunctioning flow switch not allowing sufficient flow through monitor RECORD.D J Tennessee Valley Authority 80/04/08 2pp

BOO4150500 Forwards LER 80-022/03L-0 CALHOUN,J R Tennessee Valley Authority 80/04/11 ip

--B004150512 LER 80-022/03L-0 on 800318, w/Unit 1 in Mode 6, nonessential & Train A air header isolated valves 0-FCV-32, -82, -80 & -110 closed, causing 1-FCV-90-108, -115, -109, -116, -114 & -110 to close Cause unknown RECORD, D J Tennessee Valley Authorfty 80/04/11 lp

8004150554 Forwards LER 80-025/03L-0 CALHOUN:J R Tennessee Valley Authority 80/04/11 ip

--B004150565 LER 80-025/03L-O on 800313 w/Unit 1 in Mode 6.0-RM 40-225 condensate demineralizer effiuent line was taken out of svc for maint Caused by weak transistor Transistor replaced & monitor returned to svc RECORD.D V Tennesser Valley Authority B0/04/11 ip

BO04170026 Forwards supplemental info to 790529 final deficiency rept re-pressurizer relief piping support MILLS.L.M. Tennessee Valley Authority BO/04/11 1p. ---8004170031 Suppl to final deficiency tept to pressurizer relief piping support Results of tests to verify adequacy of draw boad welding on pressure tellor valve line show that weld is not sensitized

* Tennessee Valley Authority 80/04/11 Spp

8004220715 Forwards LER 80-026/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/04/16 1p

--8004220722 LER 80-026/0.1 -0 on 800416, during Made 6 operations, ERCW effluent line monitors declared inoperable & maint performed Caused by dirt in flow switch Switch cleaned by monitor returned to scc
RECORD, D J Tennessee Valley Authority 80/04/16 2pp

8004220753 Farwards LER 80-027/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/16 ip

~~8004220757 LER 80-027/03L-0 on 800318, during Mode 6 operations, FCV-26-240, 241, 242, 243, 244 ½ 245 were identified closed Caused by inadequate Phase A recovery plocedure Valves opened Temporary change made to procedure to require reopening RECORD, D J Tennessee Valley Authority 80/04/16 2pp

8004220698 Forwards LER 80-020/017-0 CALMOUN, J. R. Tennessee Vailey Authority 80/04/17 1p

--B004220707 LER 80-020/01T-0 on 800404.investigation revealed that several vendor-designed pipe supports were designed utilizing manufacturer std 0 25-inch U-bolt which overstressed during seismic event Caused by design error LAGERGREN, B Tennessee Vailey Authority 80/04/17 2pp

BOD4290311 Forwards LER 80-028/017-0 CALMOUN, J. R. Tennessee Valley Authority 80/04/24 ip

---8004290316 LER 80-028/01T-0 on 8004i1.main steam header pressure transmitters i-PT-(-28,-9A,-9B,-20A,-20B & -278 found to lack environ qualification to substantiate long-term post-high energy line break operation Replacement ordered HEREFORD.J M Tennessee Valley Authority 80/04/24 2pp

8004290435 Forwards LER 80-014/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/04/25 ip

--8004290446 LER 80-014/03L-O on 800328, while performing check source test, auxiliary bldg vent noble gas monitor had module power problem & failed in svc Caused by Zener diode 1N4740 % transistor FMPB AI3 shorting out HEREFORD, J M Tennessee Valley Authority 80/04/29 ip

8004290515 Forwards LER 80-024/03L-0 CALHOUG J R Temnessee Valley Authority 80/04/25 1p

--8004290519 LER 80-024/03L-O on 800331, flow switches on radiation monitors CRM-90-212 \$ 122 found inoperable Caused by small particulate matter in monitored liquid Design change request initiated Neekly preventive maint program established MCGRIFF.J M Tennessee Valley Authority 80/04/25 1p

U Congressional/Executive Correspondence

BOO40B0254 Responds to BO0115 ltr of concern re licensing delays Unit 1 license issued for fuel loading 5 low power testing on BO0229 Post-TMI efforts to upgrade safety requirements causing licensing delay DIRCKS, W J Office of the Executive Director for Operations BO/03/12 2pg

DOCKET 50-328 BEQUIDYAH NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance se methods for compliance ROSB,D F Division of Project Management 80/02/05 7pp

8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance RDSS,D F Division of Project Management 60/02/21 Spp

- 8004290171 Recommends is suance of policy statement explaining relationship between Commission action to permit zero or low power operation (licensing power Praft statement end) BICKWITLL Office of the General Coupsel HANRAHAN, E. J. Office of Policy Evaluations. SFCY-80-081A 80/02/22 6pp
- 8004070A15 Discusses potential design deficiency in bypassioverride & reset circuits of engineered safety features Requests review of plant protection systeming to determine degree of conformance wylisted cirterial RUBENSTEIN-L S Light Water Reactors Branch 4 80/03/17 App
- 8004070393 Forwards Suppl : to NVREG-0011, safety evaluation reapplication for racility (is N/o encl RUBENSTEIN, L.S. Light Water Reactors Branch 4 80/03/20 2pp
- B004020093 Forwards list or requests to: addl info re process control program, needed to complete review Response requested by B00417 RUBENSTEIN. L S Light Water Reactors Branch 4 80/03/24 App
- 8004110493 Requests analysis or adequacy of equipment qualification program per NUREG-0588 Supplements NRC 791017 request for data is environ qualification or safety-related equipment RUBENSTEINLL S Light Water Reactors Branch 4 80703/25 3pp
- 8004140016 Notification of 800404 meeting woutlis in Bethesda.MD to discuss applicants' progress / status in design leview re plant shielding & environ qualification of Equipment for spaces/sys used in post accident operations.

 800KLEY.B C Light Water Reactors Branch 1 80/03/31 7pp
- 8004070228 Forwards revisions to revised response to NUREG-0578.Lessons Learned Task Force short-term requirements includes procedures for reducing & quankifying liquid sys leakage Revisions replace corresponding 791031 responses MILLS.L M Tennessee Valley Authority 80/04/02 129pp
- 8004180058 Forwards older extending const completion date to 810501 % safety evaluation for CPPR-73 RUGENSTEIN,L S Light Water Reactors Branch 4 80/04/04 2pp
- --8004180056 Dider extending const completion date to 810501 for CPPR-73 ROSS, D.F. Division of Project Management 80/04/04 2pp
- --8004180070 Safety evaluation supporting request for extension of const completion date to 810501 for CPPR-73 RUBENSTEIN.L S. Light Water Reactors Branch 4 80/04/04 3pp
- 8004150551 Forwards application for renewal of NPDES Permit TN0026450 EL-ASHRY.M T Tennessee Valley Authority 80/04/09 2pp
- ~-8004150559 Application for renewal of NPDES Permit TN0026450 EL-ASHRY T Tennessee Valley Authority 80/04/09 275pp
- 8004150608 Discusses revision to abnormal operating instruction for reactor trip (AGI-1), submitted 791017 Revision clarifies procedure for operator verification of ATWS Util has written separate emergency operating instruction for ATWS (EGI-14) MILLS.L (I Tennessee Valley Authority 80/04/11 7pp
- --8004150615 Emergency Operating Instruction EDI-14, "ATWS," Revision 1
 WALKER J R , CANTRELL C E Tennessee Valley Authority 80/04/11
 Zoo
- 8004210202 Responds to NRC 800128 ltr re util particapation in QRNL un-line analyzer program Complete analyzer sys should be installed by 800630 Forwards util procedure CD-SONP-6AP, "Startup Test Program" MILLS.L M Tennessee Valley Authority 80/04/11 1p
- --8004210205 "Startup Test Program "
 * Tennessee Valley Authority 80/02/22 23pp
- 8004280229 Forwards additinfo in response to NRC 800325 ltp re-process control program
 MILLS.L M Tennessee Valley Authority 80/04/22 14pp
- --8004280235 "ECDPAC Sys Procedure for Onsite Solification of Low Level Radioactive Waste at Sequoyab Nuclear Plant" & add1 info re process control program # Amerco.inc 80/01/31 25pp
- 8004290404 Forwards summary of Westinghouse, TVA & NRC 800320 meeting recontrol rod guide tube support pins Affidavit for uithholding & non-proprietary version encl ANDERSON, T M Westinghouse Electric Corp. PWR Systems Div 80/04/23 46pp

- 8004290290 Responds to NRC 800319 ltm re changes to engineered safety features Design changes instituted to bring util into compliance w/exception of overriding of one type of safety actuation signal by another which is Westinghouse design MILLS.L // Tennessee Valley Authority 80/04/24 7pp
- G004300341 Forwards drawings & into per NRC request at 800125 meeting re-adequacy or piles supporting waste packaging area & condensate demineralizer wante evaporator bldg Drawings available in Central Files only MILLS.L M Tennessee Valley Authority 80/04/24 37pp
- F Security, medical, emergency % rire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES.B.K. Emergency Preparedness Task Force 80/03/11 4pp
- BO04:70225 Forwards draft revisions to emergency operating instructions EOI-Ω. "Immediate Actions & Diagnostics." EOI-1. "Loss of Reactor Coolant." EOI-2. "Loss of Secondary Coolant." & EOI-3, "Steam Generator Tube Rupture "
 MILLS.L II Tennessee Valley Authority BO/04/15 1p
- --8004170227 Draft Emergency Operating Instructions EOI-O, "Immediate Actions & Diagnostics" WALKER, J.R., RECORD, D.J. Tennessee Valley Authority 80/01/31 13no
- --8004170229 Draft Emergency Operating Instructions EQI-1. "Loss of Reactor Coglant," Revision 10 BENTON,C T , MALKER,J R , RECORD,D J Tennessee Valley Authority 80/03/31 29pp
- --8004170231 Draft Emergency Operating Instructions E01-2, "Loss of Secondary Coolant," Revision 9 WALKER, J.R., RECORD, D.J. Tennessee Vailey Authority 80/03/31 17pp
- --8004170234 Draft Emergency Operating Instructions EO(-3, "Steam Generator Tube Rupture," Revision 7 WILSON.G., WALKER, J.R., RECORD, D.J. Tennessee Valley Authority 80/03/31 13pp
- G Adjudicatory correspondence
- 8004020483 Speaks strongly against opening plant so close to largely populated area NRC should be financially responsible & liable should accident occur PATTERN.K Affiliation Unknown 80/02/14 ip
- 8002290321 Requests per 10CFR2 206.public hearing in Knoxville.TN prior to granting of license to fuel facility SCOTT.A Affiliation Unknown 80/02/20 1p
- 8004020487 Opposes recent licensing of plant Urges NRC to reverse decision & resume moratorium of licensing until Kemeny Commission recummendations have been implemented BOREIKO, Y. Affiliation Unknown 80/02/29 2pp
- 8004080209 Responds to 800220 request for gublic hearing under 10CFR2 206 prior to issuance of fuel load license to facility NRC approved issuance of low power test license on 800229 Forwards 740325 Fr notice & license W/o encl SHAPAR, H K Office of the Executive Legal Director 80/03/11 ip
- 8004300266 Forwards order & safety evaluation extending const completion date until 810501
 RUBENSTEIN.L S Light Water Reactors Branch 4 80/04/04 2pp
- ~-8004300270 Safety evaluation stating that issuance of order extending const completion date until 810501 is reasonable & should be authorized STAHLE, C.R., RUBENSTEIN, L.B. Light Water Reactors Branch 4 80/04/04 30c
- H Coneral correspondence
- 8004070075 Responds to 791205 itr addressed to President Carter re expediting of enhanced efforts to license all qualified nuclear plants NRC is in process of issuing several nearterm OLS Provides info re NRC licensing activities DENTON, H R Office of Nuclear Reactor Regulation 80/03/17 2pp

- --8004070077 Forwards AK Bissell 791205 ltr encouraging early licensing of facility & all qualified nuclear plants Requests comments Resolution encil
 SEAL, M M President of US & Executive Offices 79/12/13 5pp
- J Insurance & indemnity information
- 8004140442 Forwards Endorsements 1-12 to MAELU Policy MF-102 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/04/07 18pp
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8004170065 Forwards Amend 64 to FSAR MILLS, L M Tennessee Valley Authority 80/04/11 2pp
- ---B004170067 Amend 64 to FBAR * Tennessee Valley Authority B0/04/11 150pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Chercoal From Std Type II.Two-Inch,Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06 2pp
- 8004140066 Forwards IE lnsp Repts 50-327/80-04 & 50-328/80-03 on 800205-07 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004160072 IE Insp Repts 50-327/80-04 & 50-328/80-03 on 800205-07 No noncompliance noted Major areas inspected followup on allegation, IOCFR50 55 items, IE bulletins & circulars & observation of safety-related activities CANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Breanch @OUGE, M J Region 2, Atlanta, Office of the Director 80/02/27 Spp
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC & util in Atlanta. 8A to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by 9A program O'REILLY, J P Region 2, Atlanta. Office of the Director 80/03/12 250
- 8004070072 Requests that util provide procedures to be followed for visual & ultrasonic insp examinations of turbines to assure mutually acceptable insp program Test schedule should be submitted for NRC to observe examinations
 RUBENSTEIN.L & Light Water Reactors Branch 4 80/03/14 2pp
- 800421017B Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II. Two-Inch.Tray Adsorber Cells" Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valiey Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 77-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLB.L M Tennessee Valley Authority 80/03/28 2pp
- 8004i50527 Forwards IC info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta. Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/04/01 2pp.
- BD04150097 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director S0/04/02
- 8004240274 Farwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02

- 8004180275 Forwards If circular 80-07, "Problems W/HPCI Turbine Cil Sys " No written response required O'REILLY, J.P. Region P. Atlanta, Orrice or the Director 80/04/03 200
- 8004230142 Forwards IE Bulletin 79-03A 'Longitudinal Weld Defects in ABME 8A-312,Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/04/04 1p
- 8004|80445 Forwards (E Bulletin 80-08, "Eram of Containment Liner Penetration Welds " Whitten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLE, L. M. Tennessee Valley Authority 60/04/23 3pp
- BD04290400 Forwards Revision 9 to preservice baseline insp & inservice insp program, incorporating App E re notification of indications. Unit 2 drawlings & revisions to Section 2 MILLS, L M Tennessee Valley Authority 80/04/24 ip
- --8004290406 Preservice baseline insp & inservice insp program, Revision 9 MCLQUD,D O , DANIELS, BELEW Tennessee Valley Authority 80/03/18 24pp
- S Reportable occurrences, LERs , related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior mat]
 Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812
 WHITT.K W Region 2, Atlanta, Office of the Director 77/08/12
- B004160284 Second interim deficiency lept re-control rod drop events. Westinghouse continuing investigation on generic basis Next rept will be submitted by 800613.

 HILLS.L II Tennessee Valley Authority 80/03/26 1p
- 8004020312 Forwards final deficiency rept re Ruskin fire dampers MILLE, L M. Tensessee Valley Authority 80/03/28 1p
- ---80040203iá Final deficiency rept re spring slipping problem on Ruskin fire dampers Mod packages will be installed w/connection of Number á screw using washer, star lockwasher t hex nut through nariow portion of spring slot * Tennessee Valley Authority 80/09/28 lp
- 9004280453 Forwards final deficiency lept re main control room habitability
 MILLS L N Tonnessee Valley Authority 80/04/03 1p
- --8004280458 Final deficiency rept re main control room habitability
 During preoperational testing significant leakage of
 unfiltered outside air into main control during isolation
 conditions use discovered Air duct will be modified
 * Tennessee Valley Authority 80/04/03 lp
- 8004180365 Forwards final deficiency rept re incorrect motor operator weights in piping load analysis for component cooling water sys
 MILLS,L M Tennessae Valley Authority 80/04/11 ip
- --B004180347 Final deficiency tept re incorrect motor operator weights used in piping load analyses for 3-inch piping in component cooling water sys Analyses rerun w/new loads applied Support design inadequate Slight mod to support necessary * Tennessee Valley Authority 80/04/11 ip
- 8004270346 Forwards first interim deficiency tept re defective reactor vessel upper internals guide tube support pins MILLEGL M Tennessee Valley Authority 80/04/23 ip
- --B004290353 First interim deficiency rept re generic problem w/defective reactor vessel upper internals guide tube support pins. Caused by heat treatment Westinghouse will investigate to determine if design changes are required * Tennessee Valley Authority 60/04/23 ip
- 8004290329 Forwards first interim deficiency rept re unqualified safety-related cable inside containment MILLS, L M Tennessee Valley Authority 80/04/24 ip

- --B004290335 first interim derictionsy rept re unqualified safety-related cable inside containment Exposed portions of cable cannot be environmentally qualified due to higher radiation dose levels recently calculated Cable uill be shielded

 * Tennessee Valley Authority B0704/24 ip
- 8004270455 Enruards erest interim deficiency rept re inconsistency & repeatability difficulty or upper head injection hydraulic isolation valve accumulator weighing sys
 MILLS.L.M Tennessee Velley Authority 80/04/24 lp
- --8004290461 First interim dericiency mept re inconsistency & repeatability difficulty of upper head injection hydraulic isolation valve accomulator weighing sys Caused by stiffening or connecting hydraulic lines under pressure a Tennessee Valley Authority 80/04/24 lp

U Congressional/Elecutive Correspondence

8004080254 Responds to 800115 lt; of concern relicensing delays Unit 1 license issued for fuel loading & low power testing on 800229 Post-TML efforts to upgrade safety requirements causing licensing delay DERCKS.W. J. Orfice of the Ejecutive Director for Operations 80/03/12 2pp

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Qualification or Safety-Related Electrical Equipment," providing guidance remethods for compliance ROSS DF Division of Project Management 80/02/05 7pp
- 8004040017 Submits addi guidance to NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance RO86:D F Division of Project Management 80/02/21 3pp
- 8004140090 Requests that Naval Surface Weapons Ctr receive copies of correspondence re facility structural engineering matters Weapons Ctr will assist NRC in review of OL applications RUBENSTEIN.L S Light Water Reactors Branch 4 80/02/26 3pp
- 8004(10020 Summary of 800227-28 meeting w/util ½ Bechtet consultants in Midland, MJ re-safety review of geotechnical & interfacing matters
 MODD B Light Water Reactors Branch 4 80/03/31 7pp
- 6004060404 Forwards Revision 2 to 791130 response to NRC 791025 request an BNN sys sensitivity Incorporates addl overcooling sensitivity analyses into Apps A & B HOWELL, S H Consumors Power Co 80/04/01 250pp
- 8004080431 Forwards response to NRC 800307 ltm re design adequacy of B&W sys Reviews will be in areas of instrumentation & controls & can be accommodated within current const schedule Requests restart of review of OL application HBWELL,S H Consumers Power Co 80/04/0: 100pp
- 8004100384 Forwards application for Amend /6 to CPs & DLs & Revision 6 to "Responses to NRC Requests re Plant Fill," referenced by Amend 72 HOWELL.8 H Consumers Power Co 80/04/01 1p
- --8004100387 Application for Amend 75 to application for CPs & OLs Includes revised & new pages for incorporation in "Responses to NRC Requests re Plant Fill." Amend 72 HOWELLISH Consumers Power Ca 80/04/01 ip
- ---8004100390 "Responses to NRC Requests re Plant Fill." Vol 2 HOWELL.S H Consumers Power Co 80/04/01 50pp
- 8004250001 Requests repts, drawings & other info re plant fill settlement & effects Data should be submitted within 20 days after receipt of itr Sample listing encl RUBENSTEIN, L 8 Light Water Reactors Branch 4 B0/04/01 6pp
- 8004220555 Forwards revised request for add1 borings & existing soil data
 MCCALLISTER.P Army.Dept of. Corps of Engineers 80/04/16 4pp

- F Security, medical, emergency & fire protection plans
- GOO4080077 Advises that submittal date for evacuation time estimates, requested by IRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004280460 Requests extension to Oct 1980 for submittal of upgraded emergency plans Almost all vtil emergency plansing resources utilized to upgrade Big Rock Point & Palisades plans Local counties' portion may not be submitted until late 1980 HOWELL, S 14 Consumers Power Co 80/04/21 2pp

G Adjudicatory correspondence

- 8004030626 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification QBSICK, L. V. Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 8004020213 Responds to encl 800201 ltr to President Carter urging acceleration of facility hearings & licensing process Discusses impact of TMI-2 accident on process RUSS.D F Division of Project Management 80/03/20 6pp
- 8004290197 FOIA request for PSAR for placement in QA Dow Memorial Library in Midland MI BARNER, A F Affiliation Unknown 80/03/27 tp
- 8004290195 Responds to FOIA request for PSAR for placement in QA Dow Memorial Library in Midland.MI PSAR microfiche is being sent to LPDR in Midland.MI FELTON.J M Division of Rules and Records 80/04/14 72pp
- 8004230383 Forwards util 800318 news release indicating changes in projectiong ineering 2 const diganization Hill submit revisions to GA program by 800430 to incorporate organizational changes HOFFMAN.D P Consumers Power Co 80/04/18 7pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004070248 Forwards Amend 75 to application for CPs & QLs, containing Revision 27 to FSAR, revised piping & instrumentation diagrams & electrical & instrumentation diagrams HOWELLS H Consumers Power Co 80/03/31 ip
- ---B004090251 Application for Amend 75 to CP & OL applications, containing Revision 27 to FSAR HOHELLS H Consumers Power Co B0/03/31 1p
- --8004090298 Revision 27 to FBAR containing revised piping & instrumentation diagrams & electrical & instrumentation diagrams Decrease drawlings available in Central Files only & Consumers Power Co 80/03/31 300pp
- 8004140391 Forwards Certificate of Svc For Amend 75 to application for OL containing Revision 27 to FSAR BACON J L Consumers Power Co 80/04/09 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8004040471 Forwards (F Insp Repts 50-329/79-30 & 50-330/79-31 on 791201-31 No noncompliance noted FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- ~=8004040475 IE Insp Repts 50~329/79~30 & 50~330/79~31 on 791201~31, No nancompliance noted Major areas inspected site conditions & NRC order modifying CPs promotigated from settlement of diesel generator bldg & associated soil KNDP, R C . COOK, R J Region 3, Chicago, Office of the Director 80/02/08 Spp
- 8004100245 Forwards IE Insp Repts 50-329/80-04 & 50-330/80-04 on 800212-15 No noncompliance noted FIORELLI.O Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/03/03 2pp

2pp

- --8004100252 IE Insp Repts 90-329/80-04 % 50-330/80-04 on 800212-15 No noncompliance noted Major areas inspected containment prestressing sys work procedures, work activities & quality records & status of soils work activities & quality GALLAGHER.E J. Region 3, Chicago. Office of the Director HAYES, D.W. Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/02/27 App
- 8004100127 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/03/07
- 8004100368 Responds to IE Bulletin 89-03 No tray type absorber cells have been purchased HOMELL-8 H Consumers Power Co 80/03/19 ip
- 8004100260 Forwards IE Insp Repts 50-329/80-05 & 50-330/80-05 on 800204-05 & 14 No noncompliance noted FIORELLI, O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004100267 IE Insp Repts 50-329/80-05 & 50-330/80-05 on 800204-05 & 14
 No noncompliance noted Major areas inspected pressure vessel
 anchor bolts records, fabrication info gathered by licensee &
 meeting at Southern Bolt Co re bolts supplied
 VANDEL.T E . ERB.C M , KNOP.R C Region 3, Chicago. Office of the
 Director 80/03/11 7pp
- 8004150167 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/31
- 8004080702 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gii Addition & Onsite Supply " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/01
- 8004150035 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response
- required
 KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/02
 ip
- 8004180041 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvartently omitted from 800306 transmittal KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220126 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J. O Region 3, Chicago, Office of the Director 80/04/02
- 8004220336 Forwards IE Circular 80-07, "Problems W/HPCI Turbing Cil Sys " No written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/04/03
- 8004230217 Forwards IE Bulletin 77-03A, "Longitudinal Wald Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/07 is
- 800422012: Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Walds " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/09 is
- R Periodic operating reports & related correspondence
- 8004070293 Forwards "Quarterly Rept 29, Apr-June 1980," in response to ALAB-106 HOWELL, B H Consumers Power Co 80/03/31 ip
- --8004070294 "Quarterly Rept 27.Apr-June 1980," in response to ALAB-106 # Consumers Pawer Co 80/03/31 34pp.

- S. Reportable occurrences, LERs & related correspondence
- 8004020459 Part 21 rept on 800228.884 made telephone rept re defect concenning potentially overstressed supports on reactor coolant letdown coolers due to inadequate support design Corrective action redesign or support stand TAYLORJ H Babcock & Wilcox Co. 80/03/03 App
- 8004070204 Ack receipt of 800229 interim deficiency rept re component qualification test documentation re-review Review will commence upon receipt of final rept FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/17 ip
- 8004090039 PND-III-80-050 on 800315, two pipe fitters attempting to find gas leak, broke hose coupling containing gas pressure of 40 psi Gas denotated by activation of two-way radio Three men received second & third degree burns over 15% of body KNOP,R C , FIDRELLIO Region 3, Chicago, Office of the Director 80/03/17 ip
- 8004030177 Ack receipt of 800303 interim deficiency rept re reactor vessel broken anchor bolt Review will be completed on receipt at final rept FIDRELLI, 8 Region 3, Chicago. Reactor Construction & Engineering Support Branch 60/03/19 lp
- 8004020085 Ack receipt of 800303 final deficiency rept re discrepant terminal block disconnect links Review will be completed during future insp FICRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/20 ip
- 8004210124 Immediate action itr re deficiencies in implementation of GA requirements concerning site work being performed by Zack Corp KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/21
- 8004010397 Interim deficiency rept re potential overstress condition in letdown cooler supports Noizle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOMELL,5 H Consumers Power Co 80/03/27 ip
- --B004010404 Forwards add) info to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by BbW TAYLOR, J H Babcock & Wilcox Co 80/03/03 App
- 8004150356 Interim deficiency rept re safe shutdown boration capability Conceptual design completed for emergency boration sys, containing sufficient boron to independently maintain shutdown margin & transition HOWELL, 8 H Consumers Power Co 80/04/11 2pp
- BOO41700B3 Interim deficiency rept re safe shutdown boration capability assuming restrictive core condition Delineates AE design criteria for separate sys to increase safety-grade boration capability Add I rept will be submitted by BOO731 HOHELL, S H Consumers Power Co 80/04/11 2pp
- 8004210319 Interim deficiency rept re in-containment coatings w/ adhesion loss between successive layers of coating sys Root cause under evaluation Coating acceptance procedure being developed Decttel rept enci HDWELL, S H Consumers Power Co 80/04/15 3pp
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROBS, D F Division of Project Management 80/02/05 7pp
- B004040017 Submits addl guidance to NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 Spp
- BO04140090 Requests that Naval Surface Weapons Ctr receive copies of correspondence re facility structural engineering matters Weapons Ctr will assist NRC in review of OL applications RUBENBTEIN.L S Light Water Reactors Branch 4. B0/02/26 Jpp

- 8004110020 Summary of 800527-28 maeting w/util ½ Bechtel consultants in Midland:MI re safety review of geotechnical & interfacing matters HODD.D S Light Water Reactors Branch 4 80/03/31 7pp
- 8004080404 Forwards Revision 2 to 791130 response to NRC 791025 request on BAN sys sensitivity incorporates addit overcooling sensitivity analyses into Apps n & B HORELL, 5 H Consumers Power Co 80/04/01 250pp
- BOO4080431 Forwards response to NRC BOO307 itr re design adequacy of BSW sys Reviews will be in areas of instrumentation & controls & can be accommodated within current const schedule Requests restart of review of GL application HOWELL, & H. Consumers Power Co. BO/04/01 100pp
- 8004100384 Forwards application for Amend 76 to CPs & OLs & Revision 6 to "Responses to NRC Requests or Plant Fill." referenced by HONELL, S.H. Consumers Power Co. 80/04/01 1p
- ~~8004100387 Application for Amend 76 to application for CPs & OLs Includes revised h new pages for incorporation in "Responses to NRC Requests re Plant Fill." Amend 72 HUMELL,S H Consumors Power Co BO/04/01 1p
- ~~8004100390 "Responses to NRC Requests re Plant Fill," Vol 2 HOWELL'S H Consumers Power Co E0/04/01 50pp
- 8004250001 Requests repts drawings & other info re plant fill settlement y effects Data should be submitted within 20 days after receipt of its Sample listing encl RUBENSTEINLE Light Water Reactors Branch 4 80/04/01 6pp
- 8004220555 Forwards revised request for add1 borings & existing soil data MCCALLISTER.P Army, Dept of Corps of Engineers 80/04/14 App
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp GRIMES, B K
- 8004280460 Requests extension to Dct 1980 for submittal of upgraded emergency plans Almost all util emergency planning resources utilized to upgrade Big Rock Point & Palisades plans Local counties' portion may not be submitted until late 1980 HOWELL.S H Consumers Power Co 80/04/21 2pp

Q Adjudicatory correspondence

- 6004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & FERA re principles of the preparedness distributed as Board notification GOBSICK, L. V. Office of the Executive Director for Operations GO/04/02 34pp
- General correspondence
- 8004020213 Responds to encl 800201 itr to President Carter orging acceleration of facility hearings & licensing process Discusses impact of TMI-2 accident on process ROSS,D F Division of Project Management 80/03/20 App
- 8004290197 FDIA request for PSAR for placement in GA Daw Memorial Library in Midland.MI BANNER, A P Affiliation Unknown 80/03/27 ip
- 8004290195 Responds to FOIA request for PSAR for placement in GA Dow Memorial Library in Midland, MI PSAR microfiche is being sent to LPDR in Midland, MI t in migrano, mi Division of Rules and Records 80/04/14 72pp
- B0042303B3 Forwards util 60031B news release indicating changes in project, engineering 8 const organization Will submit revisions to GA program by 800430 to incorporate organizational changes
 HDFFMAN, D P Consumers Power Co 80/04/18 7pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004090248 Forwards Amend 75 to application for CPs & OLs.containing Revision 27 to FBAR, revised piping & instrumentation diagrams & electrical & instrumentation diagrams HOWELL.S H Consumers Power Co 80/03/31 ip

- --8004090251 Application for Amend 75 to CP & OL applications, containing Revision 27 to FSAR HOWELL, S H Consumers Power Co 80/03/31 1p
- ---8004090258 Revision 27 to FSAR containing revised piping & instrumentation diagrams % electrical & instrumentation diagrams Oversize drawings available in Central Files only consumers Power to 80/03/31 300pp
- 8004140391 Forwards Certificate of Svc For Amend 75 to application for OL containing Revision 27 to FSAR BACON J L Consumers Power Co 80/04/09 2pp
- G Inspection reports, (E Bulletins & correspondence
- 8004040471 Forwards IE Insp Repts 50-329/79-30 & 50-330/79-31 on 791201-31 No noncompliance noted FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --8004040475 IE Insp Repts 50-329/79-30 & 50-330/79-31 on 791201-31 No honcompliance noted Major areas inspected site conditions & NRC order modifying CPs promulgated from settlement of diasel generator bidg & associated soil KNDP,R C , CDOK,R J Region 3. Chicago. Dffire of the Director 60/02/08 Spp
- 8004100245 Forwards IE Insp Repts 50-329/80-04 & 50-330/80-04 on 800212-15 No noncompliance noted FIGRELLIG Region G. Chicago. Reactor Construction & Engineering Support Branch 80/03/03 2pp
- --8004100252 IE Insp Repts 50-327/80-04 & 50-330/80-04 on 800212-15 No noncompliance noted Major areas inspected containment prestressing sys work procedures, work activities & quality records & status of soils work activities & Alliagher.E J Region 3. Chicago. Office of the Director HAYES, D W. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/27 App
- 8004100129 Forwards IC Info Notice 80-08. "States Co Bliding Link Electrical Terminal Block " No specific action or response KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- 8004100368 Responds to IE Bulletin 80-03 No tray type absorber cells have been purchased HOWELL,S H Consumers Power Co 80/03/19 1p
- 8004100260 Forwards IE Insp Repts 50-329/80-05 & 50-330/80-05 on 800204-05 b 14 No noncompliance noted FIORELLI, 9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004[00267 [E Inso Repts 50-329/80-05 & 50-330/80-05 on 800204-05 & 14 JU410U267 It. Insp Nepts 50-327/80-05 & 50-330/80-05 en 800204-05 & No noncompliance noted Major areas inspected pressure vessel anchor bolts records, fabrication info gathered by licensee & meeting at Southern Bolt Co re bolts supplied VANDEL, T E , ERB, C M , KNOP, R C Region 3, Chicago, Office of the Director 80/03/11 7pp
- 8004150167 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/31
- 8004080702 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/0 Region 3. Chicago, Office of the Director 80/04/01
- 8004150035 Forwards IE Info Notice 80~13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/04/02
- 8004180041 Forwards attachments to TE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently unitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220126 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3. Chicago: Office of the Director 80/04/02

- 8004220336 Forwards IE Circular 80-07, "Ploblems W/HPCI Turbine Oil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 ip
- 8004230219 Forwards IE Bulletin 79-03A: "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required KEPPLER.J G Region 3, Chicago, Dffice of the Director 80/04/07 ip
- 8004220121 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004070293 Forwards "Quarterly Rept 29, Apr-June 1980," in response to ALAD-106 MGNELL: B H Consumers Power Co 80/03/31 ip
- --8004070294 "Quarterly Rept 29. Apr-June 1980." in response to ALAB-106 * Consumers Power Co 80/03/31 34pp
- S Reportable occurrences. LERs & related correspondence
- 8004020459 Part 21 rept on 800228.B&W made telephone rept re defect concerning potentially overstressed supports on reactor coolant letdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR.J H Babcock & Wilcox Co B0/03/03 App
- 8004070204 Ack receipt of 800229 interim deficiency rept re component qualification test documentation re-review Review will commence upon receipt of final rept FIORELI.G Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/03/17 ip
- 8004090039 PNO-III-80-050 on 800315 two pipe fittors attempting to find gas leak broke hose coupling containing gas pressure of 40 psi Gas denotated by activation of two-way radio Three men received second & third degree burns over 15% of body KNOP.R C . FIURELLI, G Region 3. Chicago. Office of the Director 80/03/17 1p
- 8004030177 Ack receipt of 800303 interim deficiency rept re reactor vessel broken anchor bolt Review will be completed on receipt at final rept FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Support Dranch
- 8004020085 Ack recupt of 800303 final deficiency rept re discrepant terminal block disconnect links Review will be completed during future insp FIDRELLI, 6 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/20 ip
- 8004210124 Immediate action 1tr re deficiencies in implementation of OA requirements concerning site work being performed by Zack Corp
 KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/21
- 8004010397 Interim deficiency rept re potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOMELL.8 H Consumers Power Co 80/03/27 ip
- --B004010404 Forwards add1 info to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by B&W TAYLOR, J H Babcock & Wilcox Co B0/03/03 6pp
- B004150356 Interim deficiency rept re safe shutdown boration capability Conceptual design completed for emergency boration sys, containing sufficient borom to independently maintain shutdown margin & transition
 HOWELL, S H Consumers Power Cd B0/04/11 2pp
- 8004170083 Interim deficiency rept re safe shutdown boration capability assuming restrictive core condition Delineates AE design criteria for separate sys to increase safety-grade boration capability Addl rept will be submitted by E00731 HOMELL.8 H Consumers Power Co. 60/04/11 2pp

- 8004210318 Interim deficiency rept he in-containment coatings of adhesion loss between successive layers of coating sys Root cause under evaluation Coating acceptance procedure being developed Bechtel rept encil
 HOWELL, S. H. Consumers Power Co. 80/04/15 3pp
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER
- F Security, medical, emergency of fire protection plans
- 8004220260 Forwards "Fire Endurance & Hose Stream Tests on Electrical Cable Penetration Fire Stop Designs " 8007, L.D. Iowa Electric Light & Power Co. 80/04/01 ip
- --8004220273 "Fire Endurance" Hose Stream Tests on Electrical Cable Penetration Fire Stop Designs ' HOLLENBACHER.R EDS Nuclear, Inc. 80/04/01 300pg
- 8004090449 Forwards fire protection teview Item 3 2 7 turbing bldg fires Recommends automatic sprinkler sys be provided throughout Zone 8D MALLIRE Brookhaven National Laboratory 80/04/04 3pp
- 8004240561 Confirms 800414 meeting at Region 3 ofc to discuss regulatory performance & security KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/07 to
- 8004250385 Forwards input on Item 5 19 6. diesel generator room, for fire protection ieview
 HALL. R E Brookhaven National Laboratory B0/04/17 2pg
- 8004280454 Forwards revision to modified amended security plan Encl withheld (ref 10CFR2 790) ROOT,L D Towa Electric Light > Power Co 80/04/25 1p
- G Adjudicatory correspondence
- 8004080576 Order granting extension.until 800428.for Commission to elect whether to review director's 800213 decision denying petition under 10CFR2 206.ie Mark I containment HDYLE.J C Office of the Secretary of the Commission 80/03/31
- P Operating license stage documents & correspondence
- 8004070395 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20.000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO,TA Operating Reactors Branch 3 80/03/10 3pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT.D 0 Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp
- 8004040112 Submits results of fuel assembly loading error evaluation involving fuel assemblies other than PBDPN289 in response to NRC request Only change in critical power ratio due to rotated PBDPN2899 is large enough to effect Cycle 5 limits MEYER.K General Electric Co 80/03/19 ip
- 8004070212 Forwards operating instructions & characteristics of NRC health physics telephone network Purpose of network is transmission of health physics into during incident or abnormal occurrence at facility
 KEPPLER. J O Region 3. Chicago. Office of the Director 80/03/17
 8pp
- 8004100170 Requests controlled set of P&IDs for both Region 3 & headquarters Submittals should be forwarded to attention of Region 3 incident response ctr. ? BH Weiss, headquarters incident response ctr.within 20 days KEFPLER.J 0 Region 3, Chicago, Office of the Director 80/03/20 ip
- B00421000B Forwards request for addl info re electrical aspects of engineered safety feautures per review of long-term resolution of containment purging 8 venting Info should be submitted within 30 days after receipt of ltr IPPOLITO.TA Operating Reactors Branch 3 80/03/28 4pp

- 8004250024 Forwards 800128 h 0211 ltrs to 6F re proposed control rod drive sys mods related to elimination of cracking in return line notities Mods should not be performed prior to issuance of NUREG-0619, scheduled for Apr 1980 IPPOLITO TA Operating Reactors Branch 3 80/04/07 2pp
- BOO4140380 Amend to 791022 application for amend of License DPR-49 Tech Specs Revisions add limiting conditions for operation & surveillance of instruments that trip recirculation pumps & change reactor high pressure trip level RODT.L D Towa Electric Light & Power Co 80/04/09 ip
- --8004140382 Proposed revisions to Tech Specs 3.2 g & 4.2 ©, adding limiting conditions for operation & surveillance for instruments that trip lecirculation pumps & changing reactor high pressure trip level from 1,135 to 1,120 psig # lowa Electric Light & Power Ca 80/04/07 App
- 8004220519 Submats review of Amend 57 to License DPR-49, changing Tech Specs to allow count rate in source range monitor channels to drop below three counts par second during removal or replacement of core No comment necessary WALLACE, A T lowa, State of 80/04/11 1p
- BOO4220507 Responds to NRC BOO110 ltr re control rod failing to fully insert on reactor scram No evidence found for CY7B & 79 of events occurring when reactor automatically or manually scrammed Cn 7903[3.control rod failed to scram ROOT-L D lowa Electric Light & Power Co BO/04/15 lp
- 8004280461 Responds to 800407 ltr re QA program for standby diesel generator fuel oil Fuel is checked monthly for viscosity, water & sediment Lists revisions to be made to appropriate test procedure to comply w/code & Reg Quide 1 137 RQOT.L D lowa Electric Light & Power Co 80/04/21 3pp
- Q Inspection reports: IE Bulletins & correspondence
- 8004040160 Forwards Waste Packaging Insp Rept 79-07A on 791219 & notice of violation DAVIS.A B Region 3. Chicago: Fuel Facility & Materials Gafety Branch 80/02/20 2pp
- --8004040164 Notice of violation from insp on 791219
 * Region 3, Chicago, Office of the Director 80/02/25 1p
- ~~B00404017| Waste Packaging Insp Rept 79-07A on 791219 Noncompliance noted cask shipped from facility not marked "Radioactive LSA:" as required POTIER.J P. BROWN.R A Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/25 4pp
- 8004100135 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/03/07
- 8004030259 Advises that item of noncompliance noted in NRC 800225 ltr % attached lnsp Rept 79 07A has been determined invalid No response necessary BAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/19 ip
- 8004160005 Responds to IE Builetin 80-03 re potential for loss of charcoal from ventilation sys tray-type charcoal adsorber cells Most charcoal units are deep-bed rather than tray-type Charcoal loss is negligible from tray-type cells ROOT, L D town Electric Light & Power Co 80/03/20 2pp
 - ifo Notice 80-12, "Instrument Failure Causes & Valve " No specific action or
 - Chicago, Office of the Director 80/03/31
 - lar 80-05. "Emergency Diosel Generator Onsite Supply " No written
 - icago, Office of the Director 80/04/01
 - Defective CAM Followers " No specific action or response requires KEPPLER. J O Region 3. Chicago. Office of the Director 80/04/02

- 8304180051 Forwards attachments to IE Circular 80-03, "Protection From Toric Gas Hajards," inadvartently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220140 Forwards IC Info Notice 80-14, "Safety Suggestions From Employees " No action required XEPPLER. J G Region 3. Chicago, Office of the Director 80/04/02 in
- 8004220373 Forwards IE Circular 80-07, "Problems W/HPGI Turbine Oil Sys " No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/04/03 10
- 8004110041 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07 to
- 8004230274 Forwards 1E Builetin 79-03A, "Longitudinal Weld Dafects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07
- 8004220087 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J. G. Region 3, Chicago, Diffice of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004030160 Forwards "Semiannual Rept Radioactive Effluent Releases, Jul-Dec 1979 " MINECK,D L lowa Electric Light & Power Co 80/02/21 ip
- --8004030161 "Semiannual Rept Radioactive Effluent Releases, Jul-Dec 1979 "
 - * Iowa Electric Light & Power Co 80/02/21 7pp
- BG04070252 Forwards "Annual Environ Rept, 1979"
 MINECK, D. L. lowa Electric Light & Power Co. 80/03/25 ip
- --8004070254 "Annual Environ Rept.1979 "
 * Jown Electric Light & Power Co 60/03/25 500pp
- BC04220385 Forwards monthly operating rapt for Mar 1980 MINECK, D.L. Iowa Electric Light & Power Co. BD/04/14 1p
- --8004220389 Monthly operating rept for Mar 1980
 VAN BICKEL, J I lowa Electric Light & Power Co 80/04/14 2
- 8304230344 Forwards corrected monthly operating rept for Feb 1980 MINECK,D L Jowa Electric Light & Power Co 80/04/14 1ρ
- --8004230348 Corrected monthly operating rept for Feb 1980 VAN BICKEL, J Towa Electric Light & Power Co 80/04/14 ip
- & Reportable occurrences, LERs & related correspondence
- BOO42:0429 PND-77-50A on 770329 & 30.six main steam relief valves failed No apparent cause noted Valves will be replaced by manufacturer, farget Rock Mod will delay plant startup for two wks
 WHITT, K W , ROY. O W , THOMPSON, D Region 3, Chicago, Office of the Director 77/04/19 lp
- 8004080664 PNO-111-80-047 on 800312, unanalyzed water was pumped from circulating water pit offsite, through dilution structure to river for 1-h & 45 minutes Preliminary data indicates radioactivity of release less than 1% of limit JACKIW, IN , LITTLE, W S Region 3, Chicago, Office of the Director. 80/03/14 2pp
- 8004040400 Forwards LER 80-011/01T-0 MINECK.D L lowa Electric Light & Power Co 80/03/31 1p
- --B004040413 LER 80-011/01T-0 on 800317, during annual inep of standby diesel generator 10-21, lower crankshaft main thrust bearing found wiped on both thrust & journal surfaces Gaused by low lube oil level Bearing replaced & crankshaft relapped TOOKER, D W lowa Electric Light & Power Co 80/03/31 2pp.
- 8004080518 Forwards LER 80-012/01T-0 MINECK.D L | Joue Electric Light & Power Co 80/03/31 1p

- --8004080531 LER 80-012/017-0 on 800317 during annual imap of diesel generator 10-31 lower crankshaft thrust 13 bearing found wiped on journal surface Caused by bearing/crankshaft clearance being out of spec TOOKER, D W Towa Electric Light & Power Co 80/03/31 2pp
- 8004080605 Ro during core loading operations, fuel assembly was loaded into cell 06-23 w/o control rod 06-23 being fully inserted Cause unstated Control rod Inserted & fuel moving plan reviewed prior to resuming core loading MINECK, D L Iowa Electric Light & Power Co 80/03/31 ip
- 8004150340 RD during core loading operations, fuel assembly loaded into cell 06-23 w/o control rod 06-23 being fully inserted Control rod inserted & fuel moving plan reviewed prior to resuming core loading MINECK, D. L. lowa Electric Light & Power Co. 80/03/31 ip
- 8004090447 RO on 800402, while preparing to change out cell in 125 volt dc battery, station electrician opened breaker between 1D2 % 125 buss causing loss of control power to essential buss & other loads Breaker reclosed MINECK, D L lower Electric Light & Power Co 80/04/02 1p
- --8004140369 LER 80-014/017-0 on 800402, while preparing to change out 125-volt dc battery cell, breaker between battery changer & 125-volt dc bus 10-20, resulted in loss of control power Caused by personnel error Dissel auto started TODKER, D W Iowa Electric Light & Power Co 80/04/10 2pp
- 8004140450 Forwards LER 80-013/017-0 MINECK, D L I I Dwa Electric Light & Power Co 80/04/10 ip
- ---8004140452 LER 80-013/01T-0 on 800330, during core loading operations, fuel assembly was loaded into cell 06-23 w/o control rod 06-23 being fully inserted Caused by personnel error Fuel moving plan reviewed before loading was resumed TOOKER, D W Iowa Electric Light & Power Co 80/04/10 2pp

DOCKET 50-332 BARNWELL REPROCESSING PLANT

- G Inspection reports, IE Bulletins % correspondence
- B004240226 Forwards IE Info Notice 80-14, "Bafety Buggestions From Employees" No action required CAREILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 to
- DOCKET 30-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- 8004070243 Forwards list of fire protection review items for which licensee info has been received MALL.R.E. Brookhaven National Laboratory 80/03/27 8pp.
- 8004240167 Requests proposed emergency plan be revised re criteria identified in encl per NUREO-0654 All elements specified essential for adequate radiological emergency planning IPPOLITO,T.A. Operating Reactors Branch 3 80/03/27 16pp
- J Insurance & indemnity information
- 8004020219 Forwards Endorsements 44 & 45 to NELIA Policies NF-208 & Endorsement 38 to MAELU Policy MF-77 DEEG.F H Power Authority of the State of New York 80/03/28 4pp
- P Operating license stage documents & correspondence
- 8004070400 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20,000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactors IPPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- BOO4030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Betheada Operations Ctr EIBENHUT,D G Division of Operating Reactors 80/03/12 Spp.
- --8004030i18 "Nuclear Data Link Specs"

 * Division of Operating Reactors 80/02/21 28pp

- 8004100602 Forwards evaluation of actions taken in response to TMI~2 Lessons Learned Task Force recommendations All requirements satisfactorily methercept installation of valve position indicating sys IE will verify adequacy of procedures & mods IPPOLITO.T A Operating Reactors Branch 3 80/03/25 1App
- BOO4010259 Notifies of delay in expected receipt of equipment concerning sys for direct indication of relief valve discharge Expected shipment date is BOO328 Reaffirms commitment for installation within 30 days of receipt EARLY, P. J. Power Authority of the State of New York BO/03/26 20p
- BOO4010367 Forwards illustrations of isolation valve configurations of high pressure piping connecting primary coolant sys piping to low pressure sys piping No Event 5 isolation valve configurations indicated EARLY, P. J. Power Authority of the State of New York 80/03/26
- BDD4NB0473 Forwards response to NRC 800307 request for addlinfo re spent fuel pool capacity expansion No changes proposed to spent fuel pool cooling sys in conjunction w/efforts to increase spent fuel storage capacity EARLY.P J Power Authority of the State of New York 80/04/01 4pp
- BOOA250032 forwards BOO128 to 0211 ltrs to GE re proposed control rod drive sys mods related to elimination of cracking in return line nozzlos Mods should not be performed prior to issuance of NURGO-0619, scheduled for Apr 1980 IPPOLITO, T A Operating Reactors Branch 3 BO/04/07 2pp
- 8004130364 Responds to NRC 800201 ltr Receipt of equipment associated w/sys for direct indication of relief valve discharge delayed until 800411 Delay caused by problem w/output relays uncovered by R&W Installation completed by 800601 EARLY,P J Power Authority of the State of New York 80/04/08 ip
- 8004170064 Forwards fee for 800202 application for Tech Spec changes re primary containment isolation Fee paid under protest EARLY.P J Power Authority of the State of New York 80/04/11 ip
- G Inspection reports. IE Duiletins & correspondence
- BO04220445 Responds to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas " Requests extentions to B00307 for response LEONARD, J D Power Authority of the State of New York B0/02/14 19
- 8004080419 Advises that response to IE Bulletin 79-27 re loss of instrumentation non-class IE will not be complete within 70-day period Requests add! 45 days for response LEONARD. J D Power Authority of the State of New York 80/02/26
- B004090125 Forwards response to IE Bulletin 79-01B re environ qualification of Class IE equipment Master list of Class IE electrical components encl Gualification data outstanding W/o encl LEDNARD. J D Power Authority of the State of New York 80/03/03
- 8004090452 Submits response to 1E Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys During Plant Operation "No mods required after review LEONARD, J D Power Authority of the State of New York 80/03/04
- 8004210334 Forwards Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted SMITH, G H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 2pp
- ---B004210337 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper requirements: DOT placarding requirements: radiation levels, removable contamination & DOT/NRC marking & labeling POTTER.JP, PEERY,WW, WOODRUFF.RL Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/18 7pp
- 8004070407 Advises that IE Builstin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCB) Holdup Tanks," was incorrectly sent for action No response required CRIER, B H Region 1, Philadelphia, Office of the Director BO/03/17 ip

- 8004080258 Ack receipt of 800312 lin informing NRC of steps taken to correct violations noted in IE Insp Rept 50-393/79-18 SHITH G H Region 1, Philadelphia, Evel Facility & Materials Safety Branch 80/03/19 ip
- ~-B0040B0266 Responds to MRC 800215 ltr re violations noted in IE Insp. Rept 50-333/79-18 Corrective actions review of administrative controls to retraining requirements has been conducted | FNAMED J. Power Authority of the State of New York | 80/03/12
 - LECHARD, J.D. Power Authority or the State of New York 80/03/12 2pp
- --- 8004080271 Forwards 1E Insp Rept 50-333/79-18 on 791212-14 & notice of violation SHITM C H Region 1, Philadelphia, Fuel Facility & Materials Sarety Branch 80/02/15 2pp
- ~-8004080274 Notice of .iolation from insp on 791212-14 & Region I, Philadelphia. Office of the Director 80/02/12 ip
- ---8004080262 IE Insp Rept 50-333/79-18 on 791212-14 Noncompliance noted records indicated that two employees had not received annual retraining in radiation protection THONUS, L.H. Region 1. Philadelphia. Office of the Director CROCKER: H.W. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/12 5pp
- 2004150286 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening or PORV & Block Valve " No specific action or response necessary GRIER, B H. Region 1. Philadelphia. Office of the Director R0/03/31 | 1p
- ©004040083 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 1p
- ₹3004110499 Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER.B H Region 1, Phitadelphia, Office of the Director 80/04/02 ip
- E3004240335 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required GRIER, B H Region 1, Philadelphia, Office of the Director BD/04/02 ip
- © 004180236 Forwards IE Circular 80-07. "Problems W/HPCI Turbane Oil Sys " No written response required GRIER.B H. Region 1. Philadelphia. Office of the Director 80/04/03 ip
- ⊕ GO4110061 Forwards IE Bulletin RO-O7, "BWR Jet Pump Assembly Failure " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director ⊞O/O4/O4 Ip
- \$3004230439 Forwards IE Sulistin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required GRIER B H Region 1. Philadelphia. Office of the Director 80/04/04 1p
- 8004180245 Forwards IE Bulletin 80-08. "Exam of Containment Liner Pemetration Welds" Written response required GRIER.B H Region i. Philadelphia. Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- BOO4070296 Forwards "Radiological Environ Surveillance Rept, 1979"
 LEDNARD, J D Fower Authority of the State of New York 80/03/28
 1p

- S. Reportable occurrences, LERs & related correspondence
- 8004030273 Forwards revised LER 79-038/03X-1 LEDNARD, J D Power Authority of the State of New York 80/03/27 to
- --8004030278 Revised LER 77-038/03X-1 on 790611 during cold shutdown surveillance revealed callbr instrument for main steam tunnel high temp switches could not be callbr Gaused by instrument 02-TIC-200 drift Alternate instrumentation used CHILDS.N V Power Authority of the State of New York 80/03/27 2nm
- 8004030216 Forwards LER 80-025/03L-0 LEDNARD, J D Power Authority of the State of New York 80/03/28 in
- --8004030218 LER 80-025/03L-0 on 800228, during normal operation while conducting surveillance tests, average power reactor monitor B remained inoperable when function switch was returned to operation position Caused by normal hystoresis effect CMELDS, W V Power Authority of the State of New York 80/03/28 2pm
- 8004090436 Forwards LER 80-026/03L-0 PASTERNAK.R J Power Authority of the State of New York 80/04/03
- --90040-90440 LER 80-026/03L-0 on 800307 during steady state operation, drifting low power range monitor caused process computer to indicate operation in excess of thermal limits Coused by drifting low power range monitor 44-37C, due to age CHILDS.W V Power Authority of the State of New York 80/04/03 200
- 6004140398 Responds to NRC 791213 request for addlinfore loss of offsite power events Two losses of offsite power identified since 1974 No partial losses & during both events, reactor in cold shutdown EARLY, P. J. Power Authority of the State of New York 80/04/08 200
- 9004150508 Submits summary of scrams from 780909-1231, in response to MRC request for more recent control rod failures Considering overhaul of control rod drives during upcoming outage EARLY.P J Pawer Authority of the State of New York 80/04/09 20n
- 8004220767 Ferwards LER 80-027/03L-0
 PASTERNAK, R J Power Authority of the State of New York 80/04/17
- --8004220771 LER 80-027/03L-O on 800322, HPCI was made inoperable to repair pipe support Caused by need to repair hanger re HPCI sys stands mode the stands in stands mode CHILDS.H V Power Authority of the State of New York 80/04/17 200
- 8004280552 Forwards LER 80-028/03L-0 PASTERNAK, R J Power Authority of the State of New York 80/04/23
- ---8004280559 LER 80-028/03L-0 on 800324, during normal operation, loop B of torus cooling was declared inoperable Caused by failure of base plate for hanger H10-49A per IE Bullatin 79-02 Temporary repair restored sys to operable status CHILDS.U V Power Authority of the State of New York 80/04/23
- 8004290504 Forwards LER 80-029/03L-0 PABTERNAK.R J Power Authority of the State of New York 80/04/24
- --8004290511 LER 80-027/03L-0 on 800325, condensate storage tank level switch 23-LS-74A set outside Tech Specs limit Event recurred one wt later Caused by dirt in switch Switch cleaned & lubricated CHILDS.W V Power Authority of the State of New York 80/04/24
- 8004290476 Forwards LER 80-030/03L-0 PASTERNAK/R J Power Authority of the State of New York 80/04/25

DOCKETED ITEMS

- --8004290462 LER 80-030/03L-0 on 800327, visual insp of more than 4,000 electrical fire svals revealed 330 scals missing or requiring resealing Caused by initial installation being missed in most cases New seals were installed CHILDS, W V Power Authority of the State of New York 80/04/25
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004040354 Forwards revision to 800305 draft emergency preparedness plan addressing areas of NUREG-0654 not included in original draft Plan will be appropriately revised when criteria requiring lead time are implemented DUNNIC N Duquesne Light Co 80/03/31 ip
- ~~B004040359 Revision to 800305 draft emergency preparedness plan * Duquesno Light Co 80/04/01 250pp
- Q Adjudicatory correspondence
- 8004010426 Forwards documents re investigation into extended outages at facility Documents include trial staff statement before PA Public Util Commission, consumer advocate statement & CN Dunn testimony LEVIN.J A Pennsulvania, State of 80/03/28 54pp
- I Financial information
- 8004070297 Forwards 1979 Annual Financial Rept. earnings statements for quarter ending 791231 & one-yr internal cash flow projection for 1980 w/actual cash flow for 1979 MILSON.M L. Pennsylvania Power Co. 80/03/31 3pp
- --8004070298 Annual Financial Rept 1979 * Pennsylvania Power Co 80/03/11 40pp
- BO04080499 Submits util earnings statement for quarter ending 791231, one-ur internal cash flow projection for 1980 & actual cash flow for 1979 Forwards Annual Financial Rept for 1979 FIRESTONE, L Ohio Edison Co 80/04/02 3pp
- --8004080502 Annual Financial Rept 1979 * Ohio Edison Co 80/03/19 48pp
- J Insurance & indemnity information
- 8004230517 Forwards cash flow statement re availability of funding for annual & quarterly payment of premiums
 CHRISTNER, R B Duquesnø Light Co 80/04/10 3pp
- P Operating license stage documents & correspondence
- 8004280065 Responds to 800128 request for info re testimony before Public Utils Commission & forwards LER 78-53/01T-0.781206 backup rept & list of documents on dockets for Oct 1978-Mar 1979 & Mar 1979-May 1979 Request list encl RUBBELL.W T Technical & Administrative Support Branch 80/02/05
- --8004280070 Forwards IE Insp Rept 50-334/78-34 on 781218-20 & notice of violation BRUNNER, E. J. Region 1. Philadelphia, Office of the Director Зпр 79/01/10
- --8004280098 Forwards QA Program Insp Rept 99900507/79-03 on 790501-04 & notices of violation 5 deviation Summarizes background info on related enforcement issue REINMUTH: 0 W Division of Reactor Construction Inspection 79/08/10 3pp
- --8004280078 LER 77-006/017-1 on 770126, hydraulic enubbers on feedwater lines found inadequate for seismic design condition Caused by design verification breakdown during const Hanger mods include increased anchor bult size & new hanger additions WERLING, J A Duquesne Light Co 79/03/14 2pp
- ---8004280079 Record of telcon w/D Ford (UCS) on 790320 re chronology of NRC activities re pipostress issue BECKMAN,D A Region 1, Philadelphia, Office of the Director 79/04/10 Эрр
- --8004280085 SRP, Section 3 7 2, "Seismic Sys Analysis" * Office of Nuclear Reactor Regulation NUREO-75/087 3 7 2 75/11/24 9pp

- --8004280090 Requests encl chronology or sarety injection piping stress analysis & reviews be forwarded to Engineering Branch for review Refs AITS-F14741H2. document record for dockets for Oct 1978-Mar 1979 & Mar-May 1979, respectively, encl KEIMIG, R. Region 1. Philadelphia, Office of the Director KEIMIG.R R Re 79/01/18 95pp
- 800415031B Forwards safety analysis supporting actions taken to correct cracking found in feedwater sys piping SCHWENCER, A Operating Reactors Dianch 1 80/02/25 App
- 8004140050 Advises that Commission has issued encl Amend 26 to License DPR-66 Tech Specs
 SCHWENCER: A Operating Reactors Branch 1 80/02/29 3pp
- --8004140054 Amend 26 to License DPR-66 adding condition requiring secondary water chemistry monitoring program & changing Tech Specs to prohibit containment purge by steam jet air ejector sys during hot shutdown SCHWENCER:A Operating Reactors Branch 1 80/02/29 15pp
- ---8004140055 Safety evaluation supporting Amend 26 to License DPR-66 # Office of Nuclear Reactor Regulation 80/02/29 4pp
- --8004140058 Notice of issuance t availability of Amend 24 to License SCHWENCER, A Operating Reactors Branch 1 80/02/29 2pp
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D.G. Division of Operating Reactors 80/03/12 Spp
- ---8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- 8004070264 Notification of 800326 meeting w/util & S&N in Bethesda.MD to discuss decay heat eichanger sys integrity & operation required for ECCS-LGCA WIGGINTON.D Operating Reactors Branch 1 80/03/24 2pp
- 8004010459 Forwards response to NRC 800122 request for add1 info re requirements for auxiliary feedwater sys Complete response not available until completion of engineering evaluation DUNN: Or Duquesme Light Co 80/03/25 21pp
- BOD4240087 Summary of 800307 meeting w/util re approval of site for long-term technical support ctr & short-term Lessons Learned Task Force implementation plan WIGGINTON, D. Operating Reactors Branch 1 80/03/25 4pp
- --8004240089 "Conceptual Design of Beaver Valley Power Station Technical Support Ctr " # Duquesne Light Co 80/03/04 lipp
- BOO4240445 Requests demonstration of qualifications re proposed changes to membership for onsite safety committee & offsite review committee, per ANSI 18 7-1976 requirements Response should be submitted within 30 days

 BCHMENCER.A Operating Reactors Branch 1 80/03/25 2pp
- 8004030201 Forwards Mar 1980 table w/current status of action items re short-term Lessons Learned requirements Items changed from Feb submittal concern emergency power supply pressurfizer heater & onsite tochnical support ctr DUNN,C N Duquesne Light Co 80/03/31 4pp
- 8004180045 Advises that 800131 proposed design basis re add1 smoke detectors for control room & 1-h fire tated barrier meet guidelines & are acceptable BCHMENCER, A Operating Reactors Branch 1 80/04/04 2pp
- 8004290002 Requests addl info & clarification re bypass & reset of engineered safety features as part of review of containment purge & ventilation sys at nuclear plants Response to Lessons Learned Task Force Criterian & should be included SCHWENCER.A Operating Reactors Branch 1 HD/04/04 4pp
- 8004110482 Discusses basic parameters of reload design for Cycle 2 & review of safety & operational aspects of reload design by Mestinghouse Duquesne Light Co 80/04/07 3pp
- 8004300162 Grants relief from ASME Section XI inservice insprequirements Forwards Amend 27 to OL Relief shall remain in affect until revoked by NRC or until end of 120-month period beginning 760930 SCHWENCER. A Operating Reactors Branch 1 80/04/07 4pp

- --8004300366 Amond 27 to License DPR-65, deleting refs to Table 4 4-4 from App A Tech Specs Wolves requirements for visual & surface or volumetric inservice insps examination of cladding or reactor vessel head Revised pages encil SCHWENCER, A Operating Reactors Branch : 80/04/07 11pp
- ~~8004300174 Safety evaluation supporting Amend 27 to License DPR-66 * Office of Nuclear Reactor Regulation 80/04/07 6pp
- --8004300183 Notice of granting of relief from ASME Section XI inservice inspirequirements A issuance of Amend 27 to License DPR-66 SCHWENCER. A Operating Reactors Branch 1 80/04/07 3pp
- 6004210283 Forwards revised Tables 18-1, 2-1 & 3-1 to util 600325 response relauxiliary feedwater sys
 DUNN.C N Doquesne Light Co 80/04/14 4pp
- 8004220594 Responds to NRC 800107 ltr re QA requirements for emergency diesel generator fuel oil Will implement Reg Quide 1 137. Sections C 2 a.C 2 b.C 2 c b.C 2 f during current refueling outage DUNN.C N Ducuesne Light Co 80/04/14 ip
- 0 Inspection reports. IE Bulletins & correspondence
- 7906010110 FDIA request by UCS for all documents re Task Action Plans A-40 & A-41, info on seismic issues prepared for BEP & insp repts for Beaver Valley WEISS, E R Sheldon, Harmon & Weiss 79/03/19 2pp
- B004170304 Forwards Public Enforcement Conference Rept 50-334/80-04 on 800122 ORIER, B H Region 1. Philadelphia, Office of the Director 80/02/07 2pp
- ---8004170307 Special Public Enforcement Meeting Rept 50-334/80-04 on 800122 Major areas discussed licensee actions pursuant to 791204 order modifyling license BECKMAN-D A , MCCABE.E C Region 1, Philadelphia, Office of the Director 80/02/05 4pp
- 8004100059 Forwards IE Insp Rept 50-334/79-28 on 791210-14 Np noncompliance noted MARTIN.W G Region i, Philadelphia, Safeguards Branch 80/02/11 2pp
- --8004100068 IE Insp Rept 50-334/79-28 on 791210-14 No noncompliance noted Major areas inspected security plan.program audit. organization.physical barriers.lighting.access control & alarm stations Details withheld (ref 10CFR2 790)
 DEVLIN.J W. Region 1. Philadelphia. Safeguards Branch LADUN,R
 Region 1. Philadelphia. Office of the Director 80/02/07 ip
- B004070195 Ack receipt of B00127 itr updating corrective action schedule re IE Insp Rept 50-334/79-18 ORIER.D H Region 1, Philadelphia, Office of the Director B0/02/26 1p
- --8004070199 Responds to NRC 791219 ltr re violations noted in IE Insp Rept 50-334/79 18 Requests extension until 800401 for compliance re Item 79-18-05 DUNN.C N Duquesne Light Co 80/01/29 1p
- B004100347 Ack localpt or B00213 ltr informing NRC of steps taken to correct violation noted in 1E Insp Rept 50-334/79-26 SMITH O H Region I. Philadelphia. Fuel Facility & Materials Safety Branch B0/02/27 tpp
- --8004100358 Responds to NRC 600118 ltr re violations noted in 1E Insp. Rept 50-334/79-26 Corrective actions type of respiratory equipment cited in violation has been removed from general tasue.

 DUNN.C N Duquesne Light Co. 60/02/13 3pp
- --B004100373 Forwards IE Insp Rept 50-334/79-26 on 791126-29 & notice of violation SHITM.G H Region 1. Philodelphia. Fuel Facility & Materials Safety Branch B0/01/18 2pp
- --8004100382 Notice of violation from insp on 791126-29 * NRC Regional Offices 80/01/11 ip
- ---B004100391 IE Insp Rept 50-334/79-26 on 791126-29 Moncompliance noted contrary to procedures, respirators issued to personnel not on training list
 THONUS, L. H. NRC Regional Offices 80/01/11 App

- 8004090009 Requests extension until 800331 for response to IE Bulletin 79-01B. Items 1.2 % 3 Station shut down for refueling & mods Delay would not cause undue risk to safety & health of public DUNN:C N Duquesne Light Co 80/02/29 1p
- GOO4150221 Submits interim rept re IE Bulletin 79-14 Drawing verification effort being compared against basis of seismic reamalysis Results indicated very good correspondence between as-built & as-installed sys
 DUNN, C N Duquesne Light Co GO/O2/29 2pp
- 8004110070 Responds to 791203 & 800222 ltrs re Enforcement Conference 50-334/79-21 Discusses responsibilities & authorities of general superintendent of power stations dept & director of nuclear operations GRIER.B H NRC Regional Offices 80/03/03 2pp
- 8004110160 Submits response to IE Bulletin 79-27 re loss of class IE &/ar Non-Class IE instrument & control power sys bus during aperation No mods necessary re alarm sys & emergency procedures Surficient instruments exist for coolant break DUNN,C N Duquesne Light Co 80/03/04 2pp
- E004040159 Ack receipt of 800227 ltr informing NRC of steps taken to correct violation noted in IE insp Rept 50-334/79-24 GRIER.B H Region 1, Philadelphia. Office of the Director 80/03/11 ip
- ---8004040165 Responds to NRC 800201 ltr re violations noted in IE Insp Rept 50-334/79 24 Corrective actions plant maint manual, Chapter 1. Section A 7 revised to insure that current procedures available for safety-related activities DUNN.C N Duquesne Light Co 80/02/27 5pp
- --8004040168 Forwards IE Insp Rept 50-334/79-24 on 791105-09.11-26 & 1203-14 & notice of violation DRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/01 2pp
- --8004040170 Notice of violation from insp on 791105-09,11-26 & 1203-14

 Region 1, Philadelphia, Office of the Director 80/01/30 3pp
- --B004040177 IE Insp Rept 50-334/79-24 on 791105-09,11-26 & 1203-14
 Noncompliance noted use of unapproved data for calibr of
 reactor protection instrumentation
 BECKMAN,D A. Region i, Philadelphia, Office of the Director
 MCCABE,E C. Region i, Philadelphia, Reactor Operations Nuclear
 Support Branch 80/01/30 22pp
- 8004110005 Ack receipt of 800229 ltr requesting extension of IE Bulletin 79-010 data submittal date Requests 24-h notification of any deviation from understanding that infouill be completed by 800331 & received no later than 800403 GRIER, BH Region 1, Philadelphia, Office of the Director 80/03/14 1p
- 6004150264 Forwards IC Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, BH Region I, Philadelphia, Office of the Director 80/03/31 ip
- E004090048 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating 041 Addition & Onsite Supply " No written response required GRIER, D H Region I, Philadelphia, Office of the Director 80/04/01 1p
- B004110131 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director B0/04/02 ip
- 8004240302 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required ORIER B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180167 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/03 ip
- 8004230408 Forwards IE Builoten 79-03A, "Longitudinal Weld Defects in ABME SA-312, Type 304 Stainless Steel Pipe " Action required, GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 ip

- 8004180144 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 8004030176 Forwards "NPDES Discharge Monitoring Rept for Feb 1780 " MODRE, Q W Duquesne Light Co 80/03/31 1p
- ---8004030197 "NPDES Discharge Monitoring Rept for Feb 1980 "
 * Duquesne Light Co 80/02/29 12pp
- 8004070277 Forwards "Rept of Facility Changes.Tests & Experiments for 1979" WIDLEVER,E J Duquesne Light Co 80/03/31 2pp
- --8004070280 "Rept of Facility Changes, Tests & Experiments for 1979 "
 * Duquesne Light Co 80/03/31 8pp
- B004210261 Forwards "Offsite Dose Estimates Third & Fourth Quarters, 1979 "
 DUNN,C N Duquesne Light Co 80/04/15 19
- ---8004210266 "Offsite Dose Estimates Third & Fourth Quarters,1979 " * Duquesne Light Co 80/04/15 2pp
- 8004290354 Forwards monthly operating rept for Mar 1980 DUNN, C N Duquesne Light Co 80/04/25 ip
- --8004290355 Monthly operating rept for Mar 1980 TIMKO D R Duquesne Light Co 80/04/02 ip
- 6 Reportable occurrences, LERs & related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 HHITT, X W Region 2, Atlanta, Office of the Director 77/08/12
- 8004020002 RO 80-12/01T on 800312.util informed of noncompliance re channel check not performed since Jul 1976 Caused by deletion of requirement Surveillance reinitiated & further checks will be made during startup WERLING.J A Duquesne Light Co 80/03/12 2pp
- 8004220997 RO 80-025/01T during tank mod project, field engineers reported that weld on 12-inch notice penetrations to refueling storage tank does not conform w/manufacturer design Cause unstated Add! penetrations being checked WERLING, J.A. Duquesne Light Co. 80/03/16. 1p
- 8004030198 RO 80-17/01T on 800326,5%W advised that reanalysis of seismic pipe stress on main steam piping indicates that for certain OBE conditions, long-term criteria allowable stress isvels may be exceeded WERLING, J A Duquesne Light Co 80/03/26 2pp
- 8004030191 RU 80-18/01T on 800326, during portable fire pump surveillance test, section of fire main failed During pump testing sys, pressure was maintained w/difficulty Caused by rupture in fire main header Rupture isolated, sys restored WERLING, J.A. Duquesne Light Co. 80/03/27. 2pp
- 8004070341 Forwards LERs 80-012/01T-0 & 80-016/03L-0 WERLING, J A Duquesne Light Co 80/03/31 2pp
- ---8004070346 LER 80-012/01T-0 on 800312, emergency shutdown panel auxiliary feedwater flow instrumentation readings were delated from surveillance testing Caused by meter reading zero in standby

 WERLING, J. A. Duquesne Light Co. 80/03/31 ip
- --8004070375 LER 80-016/03L-0 on 800311, while testing battery charger 2, at input breaker tripped Caused by 100se control wiring Lose wires resoldered MERLINO, J A Duquesne Light Co 80/03/31 1P
- B004110385 RO, on B00225, two frequencies on peak shock annunciator sysactuated visual alarms Cause unknown Problem w/70% (OBE) visual alarms may have been caused by reed switches or alarm circuitry Investigation is continuing WERLINO. J A Duquesne Light Co 80/04/03 2pp

- 8004140329 RD 80-22/OIT on 800407, during operational Mode 5, complete loss of RHR flow occurred during attempt to increase flow Operating procedure changed to require venting RHR during flow increase

 WERLING, J A Deques
- 800414038) RO 80-022/017 on 800407, W/plant in operational Mode 5 W/ steam generators drained 5 RCS level at mid span in loops, complete loss of RHR flow occurred while attempting to increase flow Pumps vented 5 transmitter calibr checked WERLING, J A Duquesne Light Co 80/04/08 2pp
- 8004150516 Forward's LERs 80-017/01T-0,80-018/01T-0 & 80-019/03L-0 WERLING, J A Duquesne Light Co 80/04/08 2pp
- --B004150529 LER 80-017/01T-0 on 800326, reanalysis of seismic pipe stress of main steam piping inside valva house for OBE lang-term criteria showed, for some conditions, allowable stress level may be exceeded in headers for main steam relited valves WERLING, J A Duquesne Light Ca 80/04/08 2pp
- --8004150534 LER 80-018/017-0 on 800324, plant operators were testing temporary fire pump when section of fire main failed Caused by piping failure Failed section of piping replaced WERLING. J A Duquesne Light Co 80/04/08 2pp
- --8004150545 LER 80-019/03L-0 on 800310, while steam flushing, crack found in channel head of liquid waste evaporator bottoms heat exchanger Caused by equipment failure, probably due to chioride stress cornosium Sleeve welded over channel head WERLING, J.A. Duquesne Light Co. 80/04/08 2pp
- B004230217 RO B0-022/01T on B00407, complete loss of RHR flow occurred when plant operators were attempting to increase RHR flow from 1,000 gpm to 6,000 gpm Operating procedure was modified to require venting at all times during evolution WERLING, J A Duquesne Light Co B0/04/08 2pp
- 8004170223 RO 80-023/01T during operational mode 5.w/steam generators & RCS level at mid-spen in loops.complete loss of RHR flow occurred while plant operators were increasing heat exchanger flow Procedure rewritten
 WERLING.J A Duquesne Light Co 80/04/11 2pp
- BOD423020B RO BO-023/01T on BO0411, w/steam generators drained & RCS level at mid-spam in loops, complete loss of RHR flow occurred Cause under investigation Problem may be connected w/deficiency in as-built piping layout
 WERLING, J A Duquesne Light Co BO/04/11 2pp
- 8004240385 RO 80-025/01T during tank mod project, field engineers reported that weld on 12-inch nozzle penetrations to refueling water storage tank does not conform w/manufacturer design Addl penetrations are being checked WERLINO, J A Duquesne Light Co 80/04/16 2pp
- 8004290503 Forwards LER 80-022/017-0 WERLING, J. A. Duquesne Light Co. 80/04/22 2pp

V Operator Elaminations

8004070048 Denies util 800304 request for administering written examinations uk of 800518 % ielaying oral operating miaminations until Jul 1980 due to lack of reactivity manipulations COLLINS.P F Operator Licensing Branch 80/03/19 2pp

DOCKET 50-335 ST LUCIE PLANT, UVIT 1 F Security, medical, emergency & fire protection plans

8004070279 Notifies of intention to use Kerite cable in underground duct bank sys for replacement of existing cross-linked polyethylene cables 8 mods to existing sys NRC approval of Kerite for use on Unit 2. also applies to Unit 1 UHRIO,R E Florida Power & Light to 80/03/31 2pp

8004140229 Informs that thermal/rute-of-risc fire detectors, instead of automatic early warning fire detectors, will be used to implement Section 3 13 2 of safety evaluation supporting Amend 53 to License DPR-67
UHRIG.R E Florida Power & Light Co 80/04/09 ip

! Financial information

8004150406 Forwards Annual Financial Rept 1979
WHRIG.R E Florida Power & Light Co 80/04/08 1p

--8004150411 Annual Financial Rept 1979 * Florida Power & Light Co 80/02/08 72pp

P Operating license stage documents & correspondence

8004030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to bransmit info from plants to Bethesda Operations Ctr EISEMHUT, D G Division of Operating Reactors 80/09/12 5pp

--8004030118 "Nuclear Data Link Specs"

Division of Operating Reactors 80/02/21 28pp

8004110510 Provides addl info re implementation of requirements set forth in Item 2 i 7a of NUREG-0578 Requests response by 800601 indicating commitment to install safety-grade sys to B10101 . Division of Operating Reactors 60/03/27 2pp

GOO4160160 Requests response to encl Lessons Learned Task Force Category A Items from 800324 & 25 review by 800401 Schedule for qualification of valve position indication circuits should be provided REID-R W Operating Reactors Granch 4 80/03/27 5pp

8004190151 Forwards EIA supporting amend to License DPR-67, deleting certain water quality requirements & revised ETS pages for Sections 2 % 4.App B
LEAR.O Environmental Specialists Branch 80/04/01 2pp

--B004150154 EIA supporting amend to License DPR-67, deleting certain water quality requirements from App B ETS
* Office of Nuclear Reactor Regulation B0/04/01 12pp

--8004:50:56 Revised Section 2 & 4 ETS pages for License DPR-67, deleting certain water quality requirements from App 8 * Florida Power & Light Co 80/04/01 4pp

8004080386 Responds to NRC 800327 ltr re Lessons Learned Task Force short—term requirements Forwards info re valve position indication, instrumentation for inadequate core cooling, containment isolation & auxiliarly feedwater flow indication UHRIC,R E Florida Power & Light Co 80/04/03 18pp

004150341 Forwards application for renewal of NPDES Permit FL0002208 UHRIG.R E Florida Power & Light Co E0/04/03 110pp

004230461 Forwards proposed Tech Spec changes, increasing combined secondary containment bypass leakage rates & intake of outside air into control room
UHRIG.R E Florida Power & Light Co 80/04/18 2pp

B004230464 Proposed Tech Spec changes increasing combined secondary containment bypass leakage rates & intake of outside air into control room

* Florida Power & Light Co 80/04/18 Spp

8004280269 Responds to NRC 800410 ltr requesting that info re use of NUKEN 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified caulk requested from Ameron Info will not be available by 8005730 Submittal expected 800730 UHRIGAR E Florida Power & Light Co 80/04/22 lp

O Inspection reports, IE Bulletins & correspondence

8004090344 Forwards 1E Bulletin 80-03. "Loss of Charcoal From 6td Type If. Two-Inch. Tray Adsorber Cells " Action required
O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/02/06 O'REILLY, J P

8004100178 Forwards IE Insp Rept 50-335/80-03 on 800122-24 No noncompliance noted LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/02/19 2pp

--8004100182 IE Insp Rept 50-335/80-03 on 800122-24 No noncompliance noted Major areas inspected small break loss of coolant procedures & training & followup on previously identified items UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch JOHNSON.A H , MCHENRY.T J Region 2. Atlanta, Office of the Director 80/02/19 App

8004280233 Forwards IE Insp Rept 50-335/80-02 on 800219-22 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/10 2pp

--8004280241 IE Insp Rept 50-335/80-02 on 800219-22 No noncompliance JOYARDON I INSPIRED TO 35780-02 ON BURDLYFEE NO NORCOMPLIANCE NO NORCOMPLIANCE TOURS, LER review & IE bulletin review MARTIN, R D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch DYER, JA, ELRODS A Region 2, Atlanta, Office of the Director 80/03/0/ 4pp

8004230537 Forwards response to IE Bulletin 80-03. "Loss of Charcoal from BYD Type II Two-Inch Tray Adsorber Cells" In-house sys have shown no screen sagging or charcoal loss problems since installation in 1972 according to periodic testing UHRIG.R E Florida Power & Light Co 80/03/26 2pp

8004150517 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31

8004080619 Forwards IE Circular 80-05, "Emergency Diesel Cenerator Lubricating Dil Addition & Onsite Supply " No written response required U'RELLY: J P Region 2, Atlanta, Office of the Director 80/04/01

8004150081 Forwards IE Info Notice 80-13, "GE Type ABM Control Switches Defective CAM Followers " No specific action or response O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/04/02

8004240260 Forwards iE Info Notice 80-14, "Safety Suggestions From Employees "No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02

8004180321 Forwards (E Circular 80-07, "Problems W/HPCI Turbine Gil Bys "No written response required

O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03

8004230165 Forwards IE Bulletin 79-03A "Lengitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe " Action required O'RELLLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04 B0/04/04

B004180417 Forwards IE Bulletin B0-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/07

8004300577 Updates 800304 response to IE Bullstin 79-018. "Environ Qualification of Class IE Equipment " Info re Item 7 a will be forwarded by 800601 Info re Item 7 b will be forwarded UKRIG.R E Florida Power & Light Co 80/04/09 ip

DOCKETED ITEMS

- R Periodic operating reports & related correspondence
- 8004240368 Forwards monthly operating repts for Mar 1978 SCHMIDT.A D Florida Power & Light Co 78/04/07 1p
- --8004240374 Monthly operating repts for Mar 1978 CHILSON, V F Florida Power & Light Co 78/04/06 1300
- 800424044B Forwards menthly operating repts for Apr 1978 BCHMIDT.A D Florida Power & Light Co 78/05/06 tp
- --8004240452 Monthly operating repts for Apr 1978 CHILSON, V.T. Florida Power & Light Co. 78/05/06
- 8004240350 Forwards monthly operating repts for May 1978 8CHMIDT, A D Florida Power / Light Co 78/06/03 ip
- --8004240396 Monthly operating repts for May 1978 CHILSON,V T Florida Power & Light Co 78/06/03 13pp
- 8004240470 Forwards monthly operating repts for June 1978 8CHMIDT, A D Florida Power & Light Co 78/07/01 ip
- --8004240474 Monthly operating repts for June 1978 CHILSON V T Florida Power & Light Co 78/07/01 14pp
- 8004240455 Ferwards monthly operating repts for Jul 1978 8CHMIDT, A D Florida Power & Light Co 78/08/10 ip
- --B004240459 Monthly operating repts for Jul 1978 CHILSON, V T Florida Power & Light Co 78/08/10 1200
- 8004240359 Forwards monthly operating repts for Aug 1978 BCHMIDT, A D Florida Power & Light Co 78/09/04 1p
- --8004240363 Monthly operating ropts for Aug 1978 CHILSON V T Florida Power & Light Co 78/09/04
- 8004240443 Forwards monthly operating repts for Sept 1978 SCHMIDT, A D Florida Power & Light Co 78/10/07 1p
- --8004240444 Monthly operating rapts for Sept 1978 CHILSON,V T Florida Power & Light Co 78/10/07 13pp
- 8004240464 Monthly operating repts for Oct 1978 CHILSON,V T Florida Power & Light Co 78/11/04 1500
- 8004240436 Forwards monthly operating repts for Nov 1978 SCHMIDT, A D Florida Power & Light Co 78/12/06 1p

--8004240440 Monthly operating repts for Nov 1978 CHILSON V T Florida Power & Light Co 78/12/06

- BOO424041B Forwards monthly operating repts for Dec 1979 SCHMIDT. A D Florida Power & Light Co 79/01/06 1p
- ---8004240422 Monthly operating repts for Dec 1978 CHILSON,V T Florida Power & Light Co 79/01/06
- 8004230330 Forwards monthly operating repts for May 1979 SCHMIDT, A D Florida Power & Light Co 79/06/09, 1p
- -8004230332 Monthly operating repts for May 1979 CHILSON•V T Florida Power & Light Co 79/06/09 1200
- 8004230484 Forwards monthly operating repts for June 1979 SCHMIDT.A D Florida Power & Light Co 79/07/07 1p
- --8004230490 Monthly operating repts for June 1979 CHILBON,V T Florida Power & Light Co 79/07/07
- 8004230321 Forwards monthly operating repts for Jul 1979 SCHMIDT, A D Florida Power & Light Co 79/08/04 ip
- ---B004230326 Manthly operating repts for Jul 1979
 CHILBON, V T Floride Power & Light Co 79/08/04 13pp
- 8004240463 Forwards monthly operating repts for Oct 1978 8CHMIDT.A D Florida Power & Light Co 78/11/04 ip

- BOO4180524 Forwards monthly operating repts for Jan 1980 BCHMIDT.A D Florida Power / Light Co 80/02/09 1p
- --8004(80528 Nonthly operating repts for Jan 1980 CHILSON, V T Florida Power ! Light Co 80/02/09
- 8004180529 Forwards monthly operating repts for Feb 1980 SCHMIDY, A.D. Florida Fower ! Light Co 80/03/08 ip
- --8004180530 Honthly operating repts for Feb 1780 CHILBON.V T Florida Power % Light Co 80/03/08
- BOO4080257 Forwards "1979 Annual Operating Rept"
 UHRIG, R.E. Florida Power & Light Co. 80/03/20
- --B004080265 "1979 Annual Operating Rept "
 * Florida Power & Light Co 60/02/29
- 8004040425 Forwards "Annual Nonradiciogical Honstoring Rept.1979," Vals 1.2 b 3 Val 1 summarizes abjects monitoring for 1979 b Vols 2 b 3 discuss biotic monitoring UHRIG.R E Florida Power b Light Co 80/03/28 ip
- --8004040434 "Annual Nomiadiological Monitoring Rept. 1978," Vol 1. # Florida Power & Light Co 79/12/31 42pp
- --- 8004040443 "Annual Nomiadiological Environ Monitoring Rept. 1979 " Vol 2.biotic monitoring # Applied Biology, Inc 80/02/29 100pp
- --80040448 "Annual Nomadiological Environ Monitoring Rept.1979." Vol 3.biotic monitoring * Applied Biology, Inc. 80/02/29 150pp
- 8004090217 Forwards "Annual Environ Radiological Monitoring Rept," for UHRIG.RE Florida Power & Light Co 80/03/31 1p
- --8004070219 "Annual Environ Radiological Monitoring Rept." for 1979 * Florida Power % Light Co 80/03/21 7pp
- BOO41BO373 Forwards monthly operating tepts for Mar 1780 SCHMIDT.A D Florida Power & Light Co 80/04/05 1p
- --8004180374 Monthly operating repts for Mar 1980 CHILBON.V T Florida Power & Light Co 80/04/05 9pp
- S. Reportable occurrences, LERs & related correspondence
- B004210441 PNO-77-1/4 an 7/1003, while conducting routine Surveillance testing of station batteries, 125 volt dc bus
 18 was inadvertently de-energized Cause unstated State of
 FL notified IE inspector is onsite
 KLINGER O, NOLAN,F , SNILZEK,J Region 2, Atlanta, Office of the
 Director 77/10/03 1p
- 8004020381 Forwards RD 335-B-80-01 re surface temp rise UHRIG.R E Florida Power & Light Co 80/03/12 tp
- ---8004020384 RG 335-B-B0-01 on 800212, site analysis of thermograph data indicated surface temp rise, in area of max ocean temp, in excess of 5 9 F on 800113 Possibly caused by thermograph maifunction Thermograph returned to venion*

 * Fiorida Power & Light Co 80/03/12 2pp
- 8004030167 RQ 335-80-13 on 800314, while plant was in cold shutdown, field leads to excitors on both diesel generator units were found undersized Caused by design error Field leads will be replaced & permanent repair studied WETHY.C M Florida Power & Light Co 80/03/17 1p
- 8004090051 PND-II-80-042 on 800317.while investigating wiring overheat problem in 120-volt dc circuit.from voltage regulator to field of emergency disest generator A. licensee identified incorrect wire size Licensee will replace w/correct wires ELROD, S. MARTIN.R. Region 2. Atlanta. Office of the Director 80/03/17 ip
- 8004030282 Forwards LER 80-013/09T-0 8CHMIDT, A D Florida Power & Light Co BD/03/25 ip

- --8004030285 (ER 80-013/097-0 on 80031/, during trouble shooting re inability of A diesel generator to accept full design load, hot excitor leads to generator field found w/burnt insulation Caused by firor in AE installation drawings SCHOPPMANN, M.A. Florida Power & Light Co. 80/03/25
- 8004240334 Forwards LER 80-015/03L-0 SCHMIDT, A D Florida Power & Light Co 80/04/15 1p
- --8004240343 LER 80-015/034-0 on 800316, while shutdown, periodic integrated test of engineered safety features revealed 10 BG loading timers out of tolerance. 2A & 18 cooling fans not starting 5 shield bldg vent sys not opening SCHOPPMANN, M A Florida Power 5 Light Co 80/04/15 1p
- 8004240369 Forwards LER 80-016/097-0 8CHMIDT, A D Florida Power / Light Co 80/04/16 1p
- ---8004240375 [ER 80-0]4/09T-0 on 8004(1, engineering evaluation determined DUG2NU3/3 Let 80-018/09/TO in Bouerly engineering evaluation that application of two Rosemount Model 1152 pressure transmitters resulted in reportable situation Caused by design problem Fransmitters to be replaced SCHOPPMANN.M A Florida Power & Light Co 80/04/16 2pp
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8004030269 Notifies that NRC review of util Feb 1980 revised safeguards contingency plan has been completed Forwards comments indicating need for addl info within 30 days Comments withheld (ref 10CFR2 790)
 21EMANN.D L Operating Reactors Branch 2 80/03/11 2pp
- 8004020408 Forwards "Feasibility Rept on Evacuation of Area Around Facility " CDUNSIL.W G Northeast Utilities 80/03/31 2pp
- --8004020418 "Feasibility Rept on Evacuation of Area Around Facility " One oversize drawing end! ROBOERS,L H , PELL,B M Storch Engineers MOLLOY,E J Northeast Utilities Service Co 60/09/33 58pp

H General correspondence

- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10CFR20 t App 1 to 10CFR50 Environ info available in stated LPBRS BALLARD.R L Environmental Projects Branch 1 80/04/01 2pp
- I Financial information
- 8004080557 Responds to NRC 800305 ltr re adequacies of cash flows to meet possible retrospective promium payments & forwards 1979 annual repts for CT Light & Power Co.Hartford Electric Light Co & Western MA Electric Co C'CONNOR.L A Northeast Utilities 80/04/01 1p
- --8004080564 Annual Financial Rept 1979 * Connecticut Light & Power Co 80/03/14 24pp
- ~-8004080581 Annual Financial Rept 1979 # Hartford Flectric Light Co 80/03/14 24pp
- --8004080590 Annual Financial Rept 1979 * Wastern Maria tests Electric Co 60/03/14 21pp

- --BG04030118 "Nuclear Data Link Specs "

 * Division of Operating Reactors 80/02/21 28pp
- 8004070266 Forwards safety evaluation re interim actions taken to eliminate feedwater piping cracks, performed in response to IE Bulletin 79-13 Operating Reactors Branch 4 80/03/13 2pp
- --8004070268 Sarety evaluation to interim actions taken to eliminate feedwater piping cracks, porformed in response to IR Dulletin 79-13 Repair method, nondestructive & visual insp & inherent toughness of piping matts are adequate * Commission 80/03/13 4pp
- 8004070138 Notification of 800318 meeting w/util in Bethesda.MD to discuss opcoming Cycle 4 reload CONNER.E L. Operating Reactors Branch 4 80/03/14 2pp
- 8004040249 Forwards "Basic Safety Rept " Proprietary version withheld (ref 100FR2 790) Affidavit previously submitted on 800229 & 760727 COUNSIL, U.G. Northeast Utilities 80/03/26 tp
- -~8004040254 "Basic Safety Rept " * Northeast Utilities 80/03/31 300pp
- 8004110528 Provides add1 into re implementation requirements set forth in Item 2 1 Za of NNREG-0578 Requests response by 800601 indicating commitment to install safety-grade sys by 810101 EISENHUT.D G Division of Operating Reactors 80/03/27 2pp
- 8004070265 Submits info re direct indication of PCRV & safety valve positions Recent discussions w/vendor revealed difficulty w/800401 completion date Revised date of completion is 810401 COUNSIL, # 0 Northeast Utilities 80/03/28 2pp
- 8004030232 Application to amend License DPR-65, in response to conterns expressed in NRC 791011 ltr Revisions add surveillance requirement for auxiliary feedwater flow test after cold shutdown exceeding one month Affidavit encl CDUNBIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/31 3pp
- --8004030290 Proposed revisions to Tech Specs 3 7 1 2 & 4 7 1 2, adding surveillance requirement for auxiliary feedwater flow test
 after cold shutdown exceeding one munth
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/03/31 3pp
- GOO4080307 Outlines plans for Cycle 4 reload outage steam generator insp gen Amend 52 to License DPR-65 Resolution of Cycle 3 startup commitments encl COUNSIL.N G Northeast Utilities GO/03/31 6pp
- BO04070274 Discusses current intentions to submit design for providing sampling capacity for primary coolant & containment air by B00429 Utils are currently engaged in finalizing design details Blight delay is required to optimize design COUNSIL.N G Connecticut Yankee Atomic Power Co B0/04/01 2pp
- 8004300078 Forwards comments re technical considerations leading to recommendations given to util at 791106 meeting about steam generator feedwater line repair Util presentation did not provide conclusive evidence that crack had not grown DENTON, H.R. Office of Nuclear Reacto; Regulation 80/04/04 4pg
- BOO4170012 Discusses problems w/implementation of Lessons Learned Task Force recommendation re automatic initiation of auxiliary feedwaters sys Requests NRC concurrence w/plan for implementing requirement during 1980 refueling outage CGUNSIL, W O Connecticut Yankee Atomic Power Co CGUNSIL, W, G Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/04/ii 4pp
- 8004220354 Submits info in support of continued operation w/sleeved guide tubes in Cycle 4 Anticipates that negligible guide tube sleeve wear will be measured CDUNSIL.H & Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/19 App
- @ Inspection reports. IE Bulletins & correspondence
- 8004090131 Forwards IE lnsp Repts 50~213/79-20.50-245/79-26 t 50-334/79-28 on 791127-30 t 1203-07 No noncompliance noted BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/08 2pp

- --B00409013B IE Insp Repts 50~213/79~20,50~245/79~26 & 50~336/79~2B on 791127~30 & 1203~07 No noncompliance noted Major areas inspected QA program implementation re QA/QC administration, design changes & mods & document control program BAUNACK, W H Region 1, Philadelphia, Reactor Operations Nuclear Support Branch NAPUDA, G Region 1, Philadelphia, Office of the Director E0/02/07 15pp
- 8004070213 Ack receipt of 800206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/79-25 & 50-336/79-27 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/28 1p
- --8004070218 Responds to NRC 800111 ltr re violations noted in IE Insp Repts 50-249/79-25 & 50-336/79-27 Corrective actions open trash can replaced w/covered trash can & no smoking signs posted at entryways to main control boards COUNSIL, W G , FEE, W F Northeast Utilities 80/02/06 2pp
- --8004070223 Forwards IE Insp Repts 50-245/79-25 & 50-334/79-27 on 791105-09 & notice of violation GARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --8004070226 Notice of violation from insp on 791105-09 * Region 1, Philadelphia, Office of the Director 80/01/08 lp
- ~-8004070231 IE Insp Repts 50-245/79-25 & 50-336/79-27 on 791105-09 Noncompliance noted failure to follow housekeeping procedure KOLTAY,P B Region 1, Philadelphia, Office of the Director EBMETER,S D Region 1. Philadelphia, Reactor Construction EBNETER, S.D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/08 8pp
- 8004090466 Forwards response to IE Bulletin 79-27 re loss of instrument control power & effect on ability to achieve cold shutdown Facility has two nonvital buses & four vital buses w/alarms responding to invertor trouble & emergency panel COUNSIL.W O Northeast Utilities 80/02/29 8pp
- 8004100417 Responds to IC Bulletin 79-01 Forwards partial listing of Class IE electrical sys.environ for component to operate & environ to which component has been qualified to operate Submittal scheduled for docketing by SOO417 M/a encl COUNSIL.N G Northeast Utilities BO/03/03 4pp
- 8004180138 Forwards IE lnsp Repts 50-245/79-29 & 90-336/79-30 on OPIDOTAL POPULATURE TO THE PROPERTY OF SURGESTION OF THE PROPERTY OF THE PROPE
- --8004180147 IE Insp Repts 50-245/79-29 & 50-334/79-30 on 791201-31 No JOHADOLAY IN INSPIRED SOCIALITY AND ASSOCIATION OF A CONTROL OF A CONT
- 8004030261 Bubmits response to IE Bulletin BO-04, re analysis of PWR main steam line break w/continued feedwater addition Efforts are in progress to finalize details of control grade automatic initiation of auxiliary feedwater scheme COUNBIL. W Q Northeast Utilities 80/03/05 1p
- 8004150279 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER B H Region I, Philadelphia, Office of the Director 80/03/31 ip
- 8004090074 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/04/01 ip
- 8004110156 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required ORIERIB.H Region I, Philadelphia, Office of the Director 80/04/02 ip
- 8D04240317 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required GRIER-B.H Region 1. Philadelphia. Office of the Director 8D/04/02 1p

- 8004180231 Forwards IE Circular BU-07, 'Problems W/HPC! Turbine Oil Sys " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/03 ip
- 8004230433 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004180201 Forwards IE Bulletin BO-OS, 'Exam of Containment Liner Penetration Welds "Written response required GRIER.B H Region 1, Philadelphia, Office of the Director BO/04/07 Ip
- A Periodic operating reports & related correspondence
- 8004040205 Forwards annual environ operating rept, "Monitoring Marine Environ of Long Island Sound" Requests rept be incorporated into proceedings for Unit 3 CDUNSIL/U G Northeast Utilities 80/03/30 ip
- --8004040206 "Monitoring Marino Environ of Long Island Sound." annual rept. 1979

 * Northeast Utilities 80/03/31 400no Northeast Utilities 80/03/31 400pp
- 8004150327 "Annual Environ Operating Rept.1979" * Northeast Utilities Service Co 80/03/31 80/03/31 100pp
- 8004220411 Forwards monthly operating rept for Mar 1980 OPEKA, J F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/14 1p
- --8004220413 Monthly operating rept for Mar 1980 HOWLETT.G H Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/08 App
- S Reportable occurrences. LFRs & related correspondence
- 8004090118 PNO-I-80-043 on 800318 one truck full of chlorine rail tank 00409011B PNO-1-80-043 on 80031B one truck full of chlorine rail car derailed at broken switch on licensee property Car presently located outside protected area, but is upright, intact. 3 stable Formulating plans to replace car on rail KEIMIG. R , BRUNNER, E J Region I, Philadelphia, Office of the Director 80/03/18 2pp
- 8004010407 Forwards LER 80-007/03L-0 OPEKA, J F Northeast Utilities 80/03/27 1p
- 8004010423 Forwards LER 60-006/03L-0 OPEKA, J. F. Northeast Utilities 80/03/27 ip
- --8004010429 LER 80-006/03L-0 on 800310.w/charging pump 8 inoperable for replacement, charging pump C placed out of svc to replace failed pump packing Caused by natural end-of-life of packing due to wear Pump packing replaced CRISCIONE, J L Northeast Utilities 80/03/27 ip
- 800409030B Forwards LER 80-008/03L-0 OPEKA, J. F. Northeast Utilities 80/04/02 1p
- --8004090311 LER 80-008/03L-0 on 800303 during routine operations, plant computer analog input values became erratic rendering pulse counting position indication sys inoperable Caused by faulty analog input driver card Sys restored FOSTER, ER Northeast Utilities 80/04/02 ip
- 8004170224 Forwards LER 80-010/03L-0 OPEKA.J F Northeast Utilities 80/04/09 ip
- --8004170226 LER 80-010/03L-0 on 800310 during surveillance, control element assembly exhibited erratic position indication & was declared inoperable Caused by Intermittent open conductor in table or connector from reed suitch a Northeast Utilities 80/04/09 1p
- B004170194 Forwards LER 80-009/03L-0 OPEKA:J F Northeast Utilities B0/04/10 ip

- --B004170199 LER 80-009/02L-0 on 80032L following plant trip from 100/power.A auriliary feed pump was round leaking excessively from gland packing Caused by natural end of life for pump packing Pump repacked CRISCIGNE.J L Northeast Utilities 80/04/10 19
- 8004180398 Forwards LER 80-011/03:-0 OPEKA.J F Northeast fuclear Energy Co (subs of Northeast Utilities) 80/04/11 ip
- --8004180404 LER 80-011/07L-0 on 800313 following full power plant trip, two broken saddle clamp bolts were found on hydraulic snubber hanger 490008 on MS lead to 4P turbine Caused by fatigue cracking due to high vibiation ? shear on trips * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 2pp
- 8004180408 Forwards LER 60-012/03L-0 OPEKA, J.F. Northeast Utilities 80/04/11 1p
- --8004(804)) LER 80-012/03L-0 on 8003(4, during routine power operation, hydraulic snubber on hanger 49000) found w/no visible fluid level Caused by seal deterioration due to high vibration Snubber replaced CROCKETT. J Northeast Utilities 80/04/11 ip
- 80042206/0 Forwards LER 80-015/03L-0 OPEKA,J F Northeast Auclear Energy Co (subs of Northeast Utilities) 80/04/18 1p
- --8004220679 LER 80-015/u3L-0 on 800321.following reactor trip, condensate storage tank lovel was below Tech Spec requirements Caused by gland seal header relief valve being stuck open, necessitating use of auxiliary feedwater sys STRATMAN,R A Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/18 1p
- 8004280525 Forwards LER 80-013/03L-0 OPERA.J F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/18 1p
- --8004280520 LER 80-013/03L-0 on 800320, while moving group 7 control element assemblies for axial shape index control assembly 1 dropped into rully inserted position Caused by failure of timer module in coil power programmer Timer replaced BATES.R & Northeast Utilities 80/04/18 ip
- DECKET 50-338 NORTH ANNA POWER STATION, UNIT 1

 F Security, medical, amergency & fire protection plans
- 8004030276 Notifies that NRC initial review of util 790904 safeguards contingency plan complete Requests add) info within 30 days in order to complete review Info request withheld (ref 10CFR2 790)
 SCHWENCER: A Operating Reactors Branch 1 80/02/27 2pp
- 8004140236 Notifies that review of util fire protection safety evaluation adequately reflects consultant concerns & recommendations Concurs w/NRC that implementation of mods with be acceptable BARNES.R D Gage-Babcock Associates, Inc. 80/04/08 1p
- BOO414025B Responds to NRC request at BOO326 & 27 meeting for emergency plans revised in accordance w/NUREG-0654 North Anna emergency plan will be submitted on BOO501 Surry plan will be submitted on BOO602 Burry plan will be submitted on BOO602 BAUM, F.A. Virginia Electric & Power Co. GO/04/08 1p
- G Adjudicatory correspondence
- 8004080418 Requests all mati sent to ASLAB re D Swanson 900225 itr forwarding NRC statement on turbine disc cracking & continued operation, be sent to UCS Mati is relevant to UCS anitus curies issue WEISS.£ R Sheldon, Harmon & Weiss 80/03/04 1p
 - 1080692 Advises that VEPCO will install device to detect pinhole saks from expansion joints per ASLAO opinion ALAB-578, Pages 1-66 Plans to install rubber jacket around joints to solve echnical problems
 .KRISTMAN, J N Hunton & Williams 80/03/12 2pp
- 80040103i1 Response to ASLAD 800303 memorandum & order Recent info re turbine disc cracking will not change NRC estimates of turbine missile risks NRC will indicate whether changes are needed re-testimony Questions re-cracking sent to licensees SWANSON; D.T. Rearing Branch (80/03/24 2pp

- --8004010313 "Derivation of Turbine Disc Crack Growth Rates " Certificate of Svc encl HAZELTON, 9 Engineering Branch 80/03/21 17pp
- BOO42503B1 Forwards JM Schmerling BOO320 arfidavit & five other documents re technical info on turbine disc cracking in response to ASLAB BOO303 memorandum & order VEPCO revised written testimony may be ready in mid-Oct W/o encl CHRISTMAILJ N Hunton & Williams BO/03/24 3pp
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK, V Office of the Executive Director for Operations 80/04/02 34pp
- BOO4280211 Petition for review of ALAB-584 on grounds of being erroneous as matter of law Expansion of spent fuel storage pool should not be permitted prior to consideration of effects subsequent to OL expiration Certificate of Svc encl DOUGHERTY, J B Potomac Alliance DOUGHERTY, J B Citizens Energy Forum DOUGHERTY, J B Dougherty, J B 80/04/14 9pp
- H General correspondence
- 8004040006 Requests immediate, than ough 1/2 intensive investigation of util operation re rate control Documentation of homeowner kw usage 1/2 charges encl ALVAREZ, K B Affiliation Unknown 80/02/28 5pp
- 8004020400 Forwards resumes of persons holding revised employment positions resulting from 800401 mgt reorganization to assist in review of proposed Tech Spec changes Also forwards job descriptions of positions Info withhold (ref Privacy Act)
 STALLINGS.C II Virginia Electric & Power Co 80/03/31 1p
- I Financial information
- BOO4010269 Forwards Annual Rept 1979
 BAUM.E A Virginia Electric & Power Co 80/03/27 ip
- --8004010275 Annual Rept 1979 * Virginia Electric & Power Co 79/12/31 32pp
- J. Insurance & indemnity information
- 8004250355 Unsigned Amend 7 to Indemnity Agreement B-80 deleting Itom 3 & substituting new info effective 800411 SALTZMAR, J Antitrust & Indemnity Group 80/04/11 tp
- 8004180232 Forwards check in payment for NRC Invoice 46B-80 Payment attends indemnity agreement for OL through 810415
 SYLVIA, R B Virginia Electric & Power Co 80/04/14 ip
- 8004250387 Forwards Amend 7 to Indomsity Agreement B-80 changing Item 3 re license numbers

 DAUM.E A Virginia Electric & Power Co 80/04/21 2pp
- 8004300436 Confirms 800425 teleon granting extension until 800515 to file info per guarantee requirements set forth in Alternative 5 of NRC 770615 for re implementation of certain provisions of 1975 amends to Price Anderson Act JOHNSON, B D Virginia Electric & Power Co B0/04/25 ip
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Nethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --H004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors | 80/02/21 28pp
- 8004010363 Application for amond to License NPF-4 consisting of proposed Change 27 to Tech Specs re safety-related hydraulic snubbers
 STALLINGS.C M Virginia Electric & Power Co 80/03/31 2pp
- --8004010366 Proposed Change 29 to Tech Specs Table 3 7 4 for safety-related hydraulic snubbers
 * Virginia Electric & Power Co 80/03/3i 6pp

- 8004030234 Forwards add1 info re implementation of TMI-2 Lossons Learned Task Force short-term Category A requirements, based on NRC onsite review SYLVIA.B R Virginia Clectric & Power Co 80/04/01 78pp
- 8004080621 Advises that info requested in NRC 800227 ltr will be provided by 800509
 SYLVIA R Virginia Flectric & Power Co 80/04/03 1p
- 8004210372 Application to amend License NPF-4 changing Tech Spec Surveillance Requirement 4 4 9 3 1 d to require testing of pressurizer power operated relief valves per ASME requirements for Category C valves Affidavit & fee encl FERGUBON.J H Virginia Electric & Power Co 80/04/16 3pp
- --8004210376 Tech Specs Change 32.proposing changes to Tech Spec Surveillance Requirement 4 4 9 3 1 d to require testing of pressurizer power operated relief valves per ASME requirements for Category C valves * Virginia Electric & Power Co 80/04/16 1p
- 8004230519 Forwards detailed schedule for completion of control room mode & training to familianize operators ω/ριοροχεί changes SYLVIA.B R Virginia Electric & Power Co. 80/04/21 5pp
- 8004300472 Forwards info re implementation of FM1 short-term Category A Lessons Learned Requirements Remaining info will be forwarded at later date SYLVIA:8 R Virginia Electric & Power Co 80/04/28 4pp
- O Inspection reports, IE Bulletins & correspondence
- 8004090398 Forwards IE Builetin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/06 200
- BO04040182 Forwards IE Insp Repts 50 338/80-02 & 50-339/80-02 on 800128-31 No noncompliance noted STDHR.J P Region 2, Atlanta. Fuel Facility & Materials Safety Branch B0/02/15 2pp
- --8004040194 IE Insp Repts 50-338/80-02 & 50-339/80-02 on 800128-31 No noncompliance noted Major areas inspected solid waste packaging & transportation & followup of worker concerns OIBSCN.A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch EWALD, B C Region 2, Atlanta, Office of the Director 60/02/13 6pp
- 8004080122 Forwards IE Insp Repts 50-338/80-08 & 50-339/80-06 on 800206-08 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/25 2pp
- --8004080129 IE Insp Repts 50-338/80-08 & 50-339/80-06 on 800206-08 No noncompliance noted Major areas inspected IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys "HERDIA R Region 2, Atlanta, Reactor Construction & Engineering Support Branch CCMPTON,R M Region 2, Atlanta, Office of the Director 80/02/21 4pp
- 8004090173 Forwards IE Insp Rept 50-338/80-01 on 800129-0201 No noncompliance noted 8TOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/26 2pp
- --8004090195 IE Insp Rept 50-338/80-01 on 800129-0201 No noncompliance noted Major areas inspected nonradiological environ protection requirements including water quality monitoring, biological surveillance & general ecological mgt JEMKINS, Q R Region 2, Atlanta, Fuel Facility & Materials Bafety Branch MCARTHUR, T C. CUNNINGHAM, A L. Region 2, Atlanta, Office of the Director 80/02/25 4p
- 8004240393 Forwards IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18,24-25 & 0131-0201 & notice of violation LEWIS:R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- ---8004240396 Notice of violation from insp on 800102-18,24-25 & 0131-0201 * Region 2, Atlanta, Office of the Director 80/02/28 2pp
- ---8004240398 IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18.24-25 & 0131-0201 Noncompliance noted failure to establish acceptance critorion for equipment tests

 KELL060.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch KIDD8.M 8 Region 2. Atlanta. Office of the Director 80/02/28 10pp

- 8004080270 Submits interim response to IE Bulletin 79-27, "Loss of Non-Class IE Institumentation / Control Power Sys Bus Buring Operation "Operator can be alorted to loss of power by combination of alarms or indications from equipment STALLINGS.C M Virginia Electric & Power Co 80/03/07 4pp
- 8004080356 Submits response to 1E Bulletin 79-01B re environ qualification of Class IF equipment Requested Master list will be ready by 800415 Equipment test repts in progress Review of facility svc conditions ready by 800705 STALLINGS.C fi Virginia Electric & Power Co 80/03/18 3pp
- 8004150164 Forwards response to IE Bulletin 80-03 re charcoal adsorber cells North Anna charcoal adsorber cells in use do not have potential for loss of chaicoal No evidence of degraded cells has been noted duing recharging at Surry STALLINGS, C.M. Virginia Electric 3 Power Co. 80/03/21 7pp
- 8004110547 Forwards evaluation of licensee responses to IE Bulletins 79-06A to 79-06A. Revision i provided by util 790426.0629 to 1015 ltrs Appropriate actions have been taken to meet requirements of bulletins SCHWENCER. A Operating Reactors Branch 1 80/03/25 16pp
- 8004030210 Responds to NRC 800314 itr re violation noted in IE Insp Repts 50-338/80-05 % 50-339/80-04 Corrective actions Procedure 1-PT-11 revised to ensure normal surveillance based on data from current plant status STALLINGS.C M Virginia Electric % Power Co 80/03/31 2pp
- 8004150540 Forwards IF Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004070282 Forwards response to IE Bulletin 79-13. "Cracking in Feedwater Bys Piping " No indications of cracking found in any insps performed All piping supports were verified operational & in conformance w/design criteria STALLINGS.C M Virginia Electric >> Power Co 80/04/01 8pp
- 8004080652 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004150105 Forwards 1E Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 200
- B0042402B4 Forwards IE Info Notice B0-14, "Safety Suggestions From Employees" No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/02
- 8004080392 Forwards response to NRC 800307 ltr re violations noted in IE Insp Repts 50~339/80-09 & 50~339/80-07 Corrective actions procedures written requiring periodic tests of health physics kits & verification of fire brigade presence SYLVIA, B R Virginia Electric & Pawer Co 80/04/03 3pp
- 8004180299 Forwards IE Circular 80-07, "Problems N/HPCI Turbine Gil Sys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/03
- 8004230108 Forwards IE Bulletin 79-03A "Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180401 Forwards JE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Writton response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 200
- 8004110202 Forwards response to IE Insp Repts 50-338/80-03 & 50-339/80-03 on 800212-15 Corrective actions conducted fire drills during first quarter of 1980 w/improved records Personnel instructed re importance of attention to detail BYLVIA.B R Virginia Electric Power Co 80/04/08 App
- 8004140446 Responds to IE Bulletin 79-13, Revision 2, "Cracking in Feedwater Sys Piping "Feedwater sys piping has been examined visually & inspected by magnetic particle No nonconformances or reportable indications were observed SYLVIA, B R Virginia Electric & Power Co 80/04/08 ip

All of Reports progress on erning IE Bulletsn 79-14 Estimated completion (aterial is of 50) teneconformances identified to nate have been reported by LERs for Unit 1 ℓ as deficiency repts for C if Z. Emint E_{ℓ} in Figure Electron 6.0

| 4221473 Firwards response to 191 B01016 ltm re 1E Insp Repts 50-3387 | O 11 1 5 | 117 du-01 c | H | 2 H=18 6 25-27 Mgt will | re emplasate requirements on special test program | mission C H | Jinguisa Electric 7 Power Co | B0704718 | 3pp

- * Periodic operating reports ! related correspondence
- 101403 215 Forwards Madicactive Effluent Release Rept Jul-Dec 1979 1 TA LINUE | M. Virginia Electric & Power Co. 80/04/01 | 1p
 - * 3240_02.3 Padicactive Effluent Release Rept Jul-Dec 1979 * GIEFRT J F MERFER, E M. CARTHRIGHT, N.R. Virginia Electric 5 Mouer fo C0704701 125pp
- For 4170050 Forwards Annual Environ Operating Rept (Radiological) ror 1977 SYLVIA B.R. - Gergenea Electric & Pouer Co.: 80/04/03 - Ep
- --83041/L052 Ar Jual Environ Operating Rept (Radiological) for 1979 " CILERT J D HOPER, D M , SMITH, E R Virginia Electric & Power Co E2704703 175pp
- 630417v210 Forwards monthly operating rept for Mar 1980 & revised monthly operating rept for Feb 1980 StLVIA.B & Virginia Electric & Power Co. 80/04/14 1p
- -800417021| Monthly operating rept for Mar 1980 MAD150N W R Virginia Electric & Power Co , 80/04/01 500
- -8034170212 Revised monthly operating rept for Feb 1980 MADISON H R Virginia Electric & Power Co 80/04/01
- S Reportable occurrences LERs & related correspondence
- 8304220384 Pt.0-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made or inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT.F U Region 2. Atlanta. Office of the Birector 77/08/12
- E004030242 RO 80-035/017-0 insps at roreign plant revealed stress correston cracking in Westinghouse control rod guide tube support pin solution heat-treated at 1825 F Ultrasonic insps will be done will be done

 * Virginia Electric & Power Co 80/03/17 ip
- 8004010504 Forwards LER 80-035/99x-0 STALLINGS C M Virginia Electric & Power Co 80/03/20 tp
- --8004010505 LER 80-035/97X-0 on 800313.Westinghouse informed util of outstitute Lek do-user/www.o an Subolla-Mestinghouse informed util potential for supplied control rad guide bube support pins to break due to stress corrosion cracking Caused by low solution heat treatment temp CARTKRIGHE W R Virginia Electric & Power Co 80/03/27 2pp
- 8004030219 Forwards LER 80-031/03L-0 STALLINGS, C H Virginia Electric & Power Co 80/03/28 1p
- --B004030221 LER 80-031/03L-0 on 800229 discovered Foxboro Model E170M transmitter, installed to replace Rosemount model on casing cooling tank level transmitter, was not seismically qualified as required Caused by misinterpretation of data CARTHREGHT, HR Virginia Electric & Power Co 80/03/28 3pp
- 1004030225 Forwards LER 80-030/03L-0 STALLINGS.C M Varginia Electric & Power Co 80/03/28 ip
- --8004030226 LER 80-030/03L-O on 800227 during normal operation, B gaseous wasts filter charcoal adsorber was operated for 934-h w/o leb analysis of carbon sample Caused by 720-h limit not being included in operator log after timer installation CARTHRIGHT. U.S. Virginia Electric & Power Co. 80/03/28 2pp
- B004070307 Forwards LER 80-024/03L-0 CARTMRIGHT, H R Virginia Electric & Power Co 80/04/02 ip

- --B004070309 LER 80-024/03L-0 on B00304, during testing, heater for train safeguards area ventilation sys filter failed to energize rendering filter imperable Causad by dirty Hepa filter prefilter & improper location of high side sensor CARTWRIGHT, H. R. Virginia Electric & Power Co. 80/04/02 RPP
- 8004080528 Forwards LER 80-033/03L-0 SYLVIA,8 R Virginia Flectric & Power Co 80/04/03 1p
- --8004080526 LER 80-033/03L-0 on 800303,during monthly verification of proper auxiliary feedwater sys valve lineup,discovered that position of valve MDV-FW1008 as written in procedure was incorrect Caused by typographical error in procedure CARTWRIGHT.W R Virgina Electric & Power Co 80/03/31 2pp
- 8004220646 Forwards LER 80-037/01T-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/04/16
- --8004220653 LER 80-037/01T-0 on 800403, at full power operation, ECCS was initiated due to full closure of main steam trip valve during part-stroke exercising of valve Caused by test boing performed at full steam flow CARTHRIGHT.N R Virginia Electric & Power Co 80/04/16 3pp
- 8004280549 Forwards LER 80-036/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/04/25 1p
- --8004280554 LER 80-036/03L-0 on B00330, during performance of preoperational test, control room bottled air sys inadvertently actuated & pressure depleted below Tech Specilimit Gaused by improper procedure instructions CARTWRIGHT, W R Virginia Electric & Power Co B0/04/25
- 8004280604 Forwards updated LER 80-016/01X-1 CARTHRIGHT.W R Virginia Electric & Power Co B0/04/25, 1p
- ---8004280608 Updated LER 80-016/01X-1 on 800116, during calculation review, two svc water screen wash pump discharge lines overstressed Caused by use of chart method in previous load calculations Trunsion replaced CARTWRIGHT,W R Virginia Electric & Power Co 80/04/25 2pp
- DECKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 800404003i Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS, D F Division of Project Management 80/02/21 3pp
- 800423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of DL W/encl. ROSS,D F Division of Project Management 80/03/10 \$3pp
- B004020247 Requests committment to perform described tests to obtain specific baseline hydraulic data w/core installed If accident occurs, similar data could be obtained & compared to baseline data to infer extent of core damage PARR, O D Light Water Reactors Branch 3 80/03/13 3pp
- 8004030179 Notification of 800317-20 site visit to discuss matters re DROMERICK, A W Light Water Reactors Branch 3. 80/03/13 3pp.
- B00404042B Discusses potential design deficiencies in bypass, override & reset circuits of engineered safety features Outlines deficiencies, safety significance & staff position Requests review of protection sys design PARR, O D Light Water Reactors Branch 3 80/03/19 5pp
- 8004080396 Submits info to assist NRC in obtaining proper OL fee. Facility will be ready for fuel loading & low power testing by 800331 First license to be issued will be for fuel loading & low power testing at 5% of power PARR.O D Light Water Reactors Branch 3 80/03/18 2pp
- B004100318 Notification of 800320 meeting w/util in Bethesda, MD to discuss matters related to operation of facility. DROMERICK, A W Light Water Reactors Branch 3 80/03/18 3pp

- 8004140079 Summary of 800306 meeting w/util t Hestinghouse in Bothesda MD re cold shutdown of facility Safety evaluation permitting issuance of full power license will be able to be prepared based on applicant presentation DROMERICK, A W Light Water Reactors Branch 3 80/03/20 4pp
- 8004140033 Notification of 800328 meeting w/util in Bethesda.MD refacility control room design
 DROMERICK.A W Light Water Reactors Branch 3 80/03/25 3pp
- 8004180194 Advises that review of site is almost complete Forwards Supp 10 to draft SER, including disposition of residual pre-TMI issues & list of requirements for near-torm DL Review identifies human factor deficiencies in control room DENTON, HR Office of Nuclear Reactor Regulation 80/03/26 7,
- --B004180160 Draft Supp 10 to SER,Part 1- "Review & Evaluation of Non-TMI-2 Issues" & Part II-"Review & Evaluation of TMI-2 Issues Related to Fuel Load & Low Power Test Program " * Office of Nuclear Reactor Regulation NUREG-0053 S10 B0/03/26 210pp
- 8004240092 Summary of 800320 meeting w/util in Bethesda, MD re importance of operator to safe operation DROMERICK, A Light Water Reactors Branch 3 80/03/26 4pp
- 8004010263 Forwards "Pressurizer Safety Valve or Power Operated Relief Valve Open" & "Loss of RCS Pressure," VEPCO proprietary
 - STALLINGS.C M Virginia Electric & Power Co 80/03/28 1p
- 8004140016 Notification of 800404 meeting w/utils in Nethesda, MD to discuss applicants' progress & status in design review re plant shielding & environ qualification of equipment for spaces/sys used in post-accident operations BUCKLEY, B C Light Water Reactors Branch 1 80/03/31 7pp
- 8004030234 Forwards add1 info re implementation of TMI-2 Lessons Learned Task Force short-term Category A requirements, based on NRC onsite review SYLVIA.B R Virginia Electric & Power Co 80/04/01 78pp
- 8004030183 Forwards seven of nine test procedures outlined in 800319 ltr for NRC review of facility special test program Bafety evaluation two remaining test procedures & revisions will be forward#d BYLVIA,B R Virginia Electric & Power Co 80/04/02 ip
- --80040301B5 Bpecial Test Procedure 2-ST-6 "Cooldown Capability of
 - emical & Vol Control Bys " Virginia Electric & Power Co 80/04/02 15pp
- --8004030190 Special Test Procedure 2-5T-7 "Forced Circulation Cooldown "

 * Virginia Electric & Power Co 80/04/02 Sipp
- ---8004030173 Special Test Procedure 2-87-8 "Natural Circulation Test"

 * Virginia Electric & Power Co B0/04/02 25pp
- --8004030195 Special Test Procedure 2-ST-9 "Natural Circulation w/Simulated Loss of Offsite Power" * Virginia Electric & Power Co 80/04/02 30pp
- --8004030200 Special Test Procedure 2-ST-10 "Natural Circulation w/Loss of Pressurizer Heaters "

 * Virginia Electric & Power Co 80/04/02 27pp
- --8004030205 Special Test Procedure 2-ST-11 "Effect of Steam Generator Secondary Bide Isolation on Natural Circulation " * Virginia Electric & Power Co B0/04/02 26pp
- --8004030206 Special Test Procedure 28T-12 "Natural Circulation at Reduced Pressure" * Virginia Electric & Power Co 80/04/02 27pp
- 8004070261 Responds to 800402 telcom re availability & adequacy of procedural guidance for shift supervisor of unaffected reactor when companion unit is undergoing emergency Util commits to establishing procedures
 SYLVIA.B R Virginia Electric & Power Co 80/04/03 i
- BOO4080312 Requests exemption from testing pressurizer power operated relief valves every three months Proposes alternate test program which will cycle valves once every three months & test at 18-month intervals during shutdown SYLVIA, B R Virginia Electric & Power Co 80/04/03 1p

- 8004080621 Advises that into requested in NRC 600227 [tr will be provided by 800509
 SYLVIA.8 R Virginia Electric Power Co 80/04/03 ip
- B004040302 Responds to NRC \u20040? telcon re availability & adequacy of procedural guidance for shift supervisor of unaffected reactor when companion unit undergoes emergency Commits to establishing procedures before criticality
 SYLVIA:B R Virginia Electric & Power Co 80/04/04 ip
- 8004290200 Discusses util application for low power GL Cracks found in reactor vessel noziles are within acceptance stds of Section XI of ASME boiler? pressure vessel code NRC evaluation of reactor vessel sinsp & revised proposed GL entl DENTON.H R Office of Nuclear Reactor Regulation 80/04/08 22pp
- 8004210177 Forwards response to 800313 ltm re potential design
- F Security, medical, emergency / fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAU clearance under Federal Repts Act GRIMES.R K Emergency Preparedness Task Force 80/03/11 4pp
- BOO4140236 Notifies that leview of util fire protection safety evaluation adequately reflects consultant concerns & recommendations Concurs w/NRC that implementation of mods will be acceptable BARNES,R D Gage-Babcock Associates, Inc. 80/04/08 ip
- 8004140258 Responds to NRC request at 900326 & 27 meeting for emergency plans revised in accordance w/NUREC-0654 North Anna emergency plan will be submitted on 800501 Surry plan will be submitted on 800602

 BAUM.E A Virginia Electric & Power Co 80/04/08 1p
- O Adjudicatory correspondence
- 8004080418 Requests all matl serit to ASLAB re I) Swanson 800225 ltr forwarding NRC statement on turbine disc cracking & continued operation, be sent to UCS Matl is relevant to UCS amicus curiae issue WEISS.ER Sheldon, Harmon & Weiss GO/03/04
- 80040B0492 Advises that VEPCO will install device to detect pinhole leaks from expansion joints.per ASLAB opinion ALAB-570.Pages る4-66 Plans to install rubbel jacket around joints to solve technical problems CHRISTMAN.J N Hunton た Williams 80/03/12 2pp
- BOO4010311 Response to ASLAR 800303 memorandum & order Recent info re turbine disc cracking will not change NRC estimates of turbine missile risks NRC will indicate whether changes are needed re testimony Questions re cracking sent to licensees SWANSON,D T Hearing Branch 1 80/03/24 2pp

H General orrespondence

- H004040006 Request, immediate thorough a intensive investigation of util operation is rate united followerstation of homeowner kw usage? Charges end ALVAREZ, K B Affiliation Unymoun Buy02/28 5pp
- BBUM11055/ Acsponds to enci Au6130 ltr to President Carter orging authorization of all orit plant, to operate Discusses safety evaluation being prepared to reculity & present operation of Unit 1 Assistant Director for Light Water Reactors 80/03/26 VARGALS A
- 8004140093 Responds to 791761 lim to Prosident Carter expressing concern relactions (elsen by VA good officials relative to licensing of facility forwards NRC limits VA Atty Gen Coleman discussing NRC position W/o encl VARGA, S.A. Assistant Director for Light Water Reactors 80/03/24
- --8004140077 forwards for MRL response, North Anna Environ Coalition 791201 lt: to President carter profesting pressure being everted by Governor (Falton? VA Atty Gen Coloman for licensing of facility SEALAM A President of Ut? Executive Offices 79/12/26 2pp
- 8004140186 Responds to 791129 lits to Picsident Canter & NRC expressing concern to VA govt officials actions leganding licensing of facility Foliasids NRC lit to Atty Gen Coleman discussing NRC posttion on Accility licensing like encl VARQA,5 A Assistant Director for Light Water Reactors 80/03/26
- 8004140190 Forwards for NRC response. Wil Scott it to President Cartel aspressing concern repressure being everted by VA govt officials for licensing of racility
 SEAL.M M President of UE 7 Executive Offices 79/12/26 2pp
- ~-B004140195 Expresses concern to VA Governor. Atty Gen & Corp Commission actions for licensing of facility Govt officials favoring util interests over welrare of civilens timed 791128 to "Goochland Gazette" encl
 SCOTT Affiliation Unknown 79/11/29 4pp
- 8004210028 Responds to 791211 ltm to President Carter requesting that facility be approved for operation Safety evaluation for facility being prepared Espected that low power discussions re facility will commence in late Mar 1980 VARGA.S A Assistant Director for Light Water Reactors 80/03/26
- ---B0042(003) Forwards, for NRC response. L. Brusso 791219 | tr requesting approval of facility for operation | SEAL.M.M. | President of US / Executive Offices | B0/01/14 | 2pp
- 8004020400 Forwards resumes or persons holding revised employment positions resulting from 800401 mgt reorganization to assist in review of proposed Tech Spec changes Also forwards Job descriptions of positions John withhold (Tef Privacy Act) STALLINGS C.M. Virginia Electric & Power Co. 80/03/31 p.

1 Financial intermation

- 8004010269 Forwards Annual Rept 1979

 BAUM E A Virginia Electric * Power Co 80/03/27 ip
 - 8004010275 Annual Rept 1979 * Viiginia Electric * Puwer to 79/12/31 32pp

Insurance / indemnity information

- /04P50355 Unsigned Amend 7 to Indomnity Agreement B-80, deleting Item 3 & substituting new info errective 800411 SALTZMAN J Antitrust & Indomnity Group 80/04/11 1p
- 800425038/ Forwards Amend / to Indemnity Agreement B-80.changing Item 3 re license numbers BAUM E A. Vinginsa Electric & Power Co. 80/04/21 2pp
- GOO4300436 Confirms 800425 teleon granting extension until 800515 to file into per guarantee requirements set forth in Alternative 5 of NRC 770615 ltr is implementation of certain provisions of 1975 amends to Price Anderson Act UCHNSON.8 & Virginia Electric / Power Co 80/04/25 lp

- P Operating license stag locuments / correspondence
- ROO4250031 Summary or 800028 meeting w/otil re results of human engineering audit of site confrol from Certain deficient design featules must be remedied prior to fuel loading CROMERICA.A W. Light Water Realtors Branch 3 80/04/11 5pj BO/04/11 5pp
- 8004220641 Advises that full response to 800219 request for change in review piocedures for equipment qualification documentation will be submitted by 800804 BROWN.S C Virginia Electric & Power Co 80/04/15 ip
- BOO4230337 Clarifies BOO403 test program proposal re pressurizer power operated relief valves Explains valves stroke times & reason why test interval exceeded three-month requirement SYLVIA.B L Virginia Flectric & Power Co BO/04/18 2pp
- 8004230231 Forwards "Special (Low Power) Test Requirements & Administrative Controls" > special test procedures to los of ac power, establishment of natural circulation from stagnant conditions / boron mixing / cooldown

 SYLVIA.B R Virginia Flectric / Power Co 80/04/21 ip
- --8004230238 "Special (Low Power) Tests Requirements & Administrative Controls," App C ontrols.' App C Virginia Electric 1 Pawer Co 80/04/21 14pp
- --8004230246 Startup Test Procedule P-31-13, "Simulated Loss of All Onsite & Offsite Power" * Virginia Electric & Power Co 90/04/21 31pp
- 8004230255 Startup Test Procedure 2-ST 14. "Establishment of Natural Circulation from Stagnant Conditions" * Virginia Electric & Power Co 80/04/21 15pp
- --8004230260 Startup Test Procedure 2-87-14, "Boron Mixing & Cooldown "

 * Virginia Electric / Power Co 80/04/21 16pp
- 8004300472 Forwards infolio implementation of TMI short-term Catetory A Lessons Learned Requirements Remaining into will be forwarded at later date BYLVIA, B. R. Virginia Electric & Powei Co. 80/04/28 4pp
- G. Inspection reports, if Bulletins & correspondence
- 8004090358 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type 11,Two-inch,Tray Adsorber Cells" Action required O'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/02/06
- 8004040182 Forwards IF Insp Repts 50-338/80-02 & 50-339/80-02 on 800128-31 No honcompliance noted STCHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/15 2pp
- --8004040194 IE Insp Repts 50-338/80-02 \$ 50-339/80-02 on 800128-31 No DANADITA IE Inspirepts 30-33870-02 & 30-33780-02 on BODIZE-31 i noncompliance noted Major areas inspected solid waste packaging & transportation & followup of worker concerns GIBSON.AF Region 2. Atlanta. Fuel Facility & Materials Bafety Branch EWALD, S C Region 2. Atlanta. Office of the Director BO/02/13 6pp
- 8004090130 Forwards IE Insp Repts 50-339/80-01.50-404/80-01 & 50-405/80-01 on 800129-0201 No noncompliance noted STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8004090134 IE Insp Repts 50-339/80-01,50-404/80-01 & 50-405/80-01 on 800129-0201 No noncompliance noted Major areas inspected erosion & Lundef Control, waste mgi, review of previous items & preoperational program
 JEMKINS, 0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch CUNNINGHAM, A L Region 2, Atlanta, Office of the Director 80/02/19 3pp
- 8004080122 Forwards IE Insp Repts 50-338/80-08 & 50-339/80-06 on 800204-08 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/02/25 2pp
- --8004080129 IE insg Repts 50-338/80-08 & 50-339/80-06 on 800204-08 No noncompliance noted Major areas inspected IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys "HERDT, A Region 2, Atlanta, Reactor Construction & Engineering Support Branch COMPTON, R M Region 2, Atlanta, Office of the Director 60/02/21 App

- 8004240393 Forwards IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18.24-25 & 0131-0201 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/03 2pp
- --8004240376 Notice of violation from insp on 800102-18,24-25 & 0131-0201
 - Region 2, Atlanta, Office of the Director 80/02/28 2pp
- --8004240378 IE Insp Repts 50-338/80-07 & 50-339/80-05 on 800102-18,24-25 & 0131-0201 Noncompliance noted failure to establish acceptance criterion for equipment tests KELLUGOP J Region 2, Atlanta, Reactor Operations Nuclear Support NELLUGGE V Region 2. Atlanta, Reactor Operations Nuclear Su Branch KIDDS.M B Region 2. Atlanta, Office of the Director 80/02/28 10pp
- 8004080270 Submits interim response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Operator can be alerted to loss of power by combination of alarms or indications from equipment STALLINGS.C M Virginia Electric & Power Co 80/03/07 4pp
- 8004080178 Discusses 800228 onsite meeting re NRC action plans for near-term OLs developed as result of TMI-2 accident IE Insp Rept 50-339/80-12 encl LEHES, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/19 1p
- --8004080183 IE Insp Rept 50-339/80-12 on 800128 No noncompliance noted Major areas inspected effect on plant safety re implementation of near-term OL action items presented in draft NVREG-0460 draft NOMEG-0860 LEWIG.R C Region 2, Atlanta, Office of the Director KELLOGG.P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/19 3pp
- BOO4150164 Forwards response to IE Bulletin 80-03 re charcoal adsorber cells North Anna charcaal adsorber cells in use do not have potential for loss of charcaal No evidence of degraded cells has been noted during recharging at Surry STALLINGS.C M Virginia Electric & Power Co 80/03/21 7pp
- 8004030210 Responds to NRC 800314 ltr re violation noted in IE Insp Repts 50-338/80-05 \$ 50-339/80-04 Corrective actions Procedure 1-PT-11 revised to ensure normal surveillance based on data from current plant status STALLINOS.C M Virginia Electric & Power Co 80/03/31 2pp
- B004190540 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary G'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/3i
- 8004070282 Forwards response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" No indications of cracking found in any insps performed All piping supports were verified operational & in conformance w/design criteria STALLINGS.C M Virginia Clactric & Power Co 80/04/01 8pp
- 8004080652 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Re Region 2. Atlanta, Office of the Director 80/04/01
- 8004150105 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240284 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004080392 Forwards response to NRC 800307 ltr re violations noted in IE Insp Repts 50-338/80-09 & 50-339/80-07 Corrective actions procedures written requiring periodic tests of health physics kits & verification of fire brigade presence SYLVIA,B R Virginia Electric & Power Co 80/04/03 3pp
- 8004180279 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Oil 8ys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 60/04/03

- 8004230109 Forwards If Bullett: 77-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required O'REILLY/J P Region 2 Atlanta Office of the Director 80/04/0 80/04/04
- 8004100410 Forwards assessment of reheat cracks in reactor vessel noizile regions discussing lesults of ultrasonic insps Rept concludes that reheat cracks round in vessel noiziles are within acceptance limits of ASME Code Section XI SLYVIA.B R Virginia Electric / Power Co 80/04/07 46pp
- 8004180401 Forwards [E Bulletin 80-08. 'Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004110202 Forwards response to IE Insp Repts 50-338/80-03 & 50-339/80-03 on 800212-15 Corrective actions conducted fire drills during first quarter of 1980 w/improved records Personnel instructed re importance of attention to detail SYLVIA.8 R Virginia Electric / Power Co 80/04/08 Spp
- 8004140446 Responds to IE Bulletin 79-13. Revision 2, "Cracking in Feedwater Sys Piping " Feedwater sys piping has been examined visually b inspected by magnetic particle No nonconformances or reportable indications were observed SYLVIA, B R Virginia Electric & Power Co 80/04/08 ip
- 8004290151 Forwards IE Insp Rept 50-339/80-16 on 800319 No noncompliance noted Region 2 Atlanta, Safeguards Branch 80/04/10 2pp KENNA, W B
- ---B004290197 IE Insp Rept 50-339/80-16 on 800316 No noncompliance noted Major areas inspected vital area alarm sys & communications equipment Details withheld (ref 100FR2 790)
 GILLEPIE: F P Region 2. Atlanta, Sefeguards Branch MODRE, D. E. HOWELL, J. C. Region 2. Atlanta, Office of the Director B0/04/10
- 8004220397 Reports progress concerning 16 Builetin 79-14 Estimated completion date now is 800501 Nonconformances identified to date have been reported by LERs for Unit 1 & as deficiency repts for Unit 2
 BROWN, 8 C Virginia Electric & Power Co 80/04/18 ip
- BOO4220493 Forwards response to NRC 800324 ltr re IF Insp Repts 50-338/80-11 & 50-339/80-09 on 800204-19 & 25-29 Mgt will re-emphasize requirements of special test program SYLVIA, 8 R Virginia Ejectric & Power Co. 80/04/18 3pp
- R Periodic operating reports & related correspondence
- 8004030236 Forwards "Radioactive Effluent Release Rept Jul-Dec 1979 " STALLINGS: C M Virginia Electric & Power Co 80/04/01 ip
- --800403023B "Radicactive Effluent Release Rept Jul-Dec 1979 " GIBERT, J D , HOPPER, D M , CARTNRIGHT, W R Virginia Electric & Pawer Co 80/04/01 125pp
- S Reportable occurrences. LERs & related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior math Cause unstated All utils w/pumps were notified NRC headquatters notified on 770812 WHITT.K W Region 2, Atlanta. Office of the Director 77/08/12
- 8004020328 Interim deficiency rept re stress analysis of Class II lines in low & high head safety injection sys Several lines have not been stress analyzed for fluid temps below 70 F New support designs for pipe restraints will be implemented STALLINGS.C M Virginia Electric & Power Co 80/03/14 2pp
- 8004020336 Interim deficiency rept re potential control rod guide tube support pin breakage due to stress corrosion cracking Westinghouse will conduct ultrasonic insps of guide tube support pins solution heat treated to less than 1800 F STALLINGS.C M Virginia Electric & Power Co 80/03/18
- 8004070019 Part 21 rept re potential for control rod guide tube support pins breaking due to stress corrosion cracking Results of support pin insp program & angoing matts text program will determine corrective actions STALLINGS.C M Virginia Electric & Power Co 80/03/18 3pp

- R00414014/ Final diriciency reptits stress analysis of certain lines in low A high head safety injection sys Affected pipe supports are being re-elamined under new loads Mods to existing design of three supports determined unnecessary SYLVIA.8 R Virginia Electric S Power Co. 80/04/08 1p
- 8004150342 Final deficiency rept re potential for Mestinghouse control rod guide tube support pins to break due to corrosion cracting Mestinghouse evaluation concludes that operation not jeopardized Pins replaced whigher temp resistant pins SYLVIA.B R Virginia Electric & Power Co 80/04/10 Ip
- 8004180446 Final deficiency tept re improper installation of shaft fans for pump motors Caused by improper location of drive fans causing eicessive motor 5 motor bearing temps Inboard & authorard shaft drive fans interchanged by contractor SYLVIA:8 R Virginia Electric & Power Co 80/04/14 1p
- 800A2804/P Final deficiency rept re improper installation of auxiliary feedwater pump motor shaft fans Both pump motors repaired by interchanging inboard 2 outboard shaft drive fens & undergoing eitensive testing SYLVIA.8 R Virginia Electric & Power Co 80/04/14 ip
- T Hearing transcripts on non-antitrust matters
- 8004210315 Transcript of 800401 briefing in Washington. BC Pp 1-121 * Commission 80/04/01 122pp
- --8004210320 Forwards documented evaluation of control room review Organizational changes outlined in util 800322 ltm are under review Proposed safety engineering group blending function of STAs is acceptable DENTON, HR Office of Nuclear Reactor Regulation 80/03/31
- U Congressional/Executive Correspondence
- 8004140297 Responds to B00304 ltr orging prompt review of util application for low level license to facilitate immediate operation when general moratorium on new OLs is lifted Application review & SER preparation underway DIRCKS N J Office of the Executive Director for Operations 80/03/21 lp
- DOCKET 50-041 ENRICO FERMI ATOMIC POHER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advisos of issuance of NUREG-0588, "Interim Btaff Position on Environ Gualification of Safety-Related Electricat Equipment, 'providing guidance re methods for compliance ROS8, D.f. Division of Project Management 80/02/05 7pp
- 6004040017 Submits add! guidance to NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 60/02/21 3pp
- 8004020245 Forwards NRC B00128 % 0211 ltms to GE discussing analysis of boileff rates ' mods to BMR control rod drive return line notifies to prevent cracking Mods should not be performed before issuance of NURG-001F or w/o NRC guidance STOLZ.J F Light Water Reactors Branch : 80/03/07 2pp
- JO4110088 Notification of 800325 meeting w/util in Monroe MI to visu safety-related piping sqs & select one for confirmatory piping analysis in GL application review KINTNER.L L. light Water Reactors Branch 1 80/03/20 3pp
- R004040278 Submits info re preservice examination of piping welds in partial response to NRC Question 121 13 in App C 5 to FSAR Util will provide complete tesponse upon completion of preservice insp TAUBER.H Detroit Edison Co 80/03/28 10pp
- --8004040280 "Survey of Class 1 Piping & Components "
 + Southwest Research Institute 78/03/31 400pp
- 8004230193 Furwards request for add1 info re review of FSAR Schedule based on assumption that info will be available by 800422 FSAR should be amended to comply w/requirements listed in encl 8TOL2.J F | Light Water Reactors Granch | 80/04/01 3pp

- d004290165 Forwards request for add1 into re high density fuel storage for NRC review of FSAR FSAR should be amended to comply w/requirements listed in encl Names of codes & stds used in design of fuel racks should be provided STOLZ, JF Light Nater Reactors Branch 1 80/04/10 4pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKE V Office of the Executive Director for Operations 80/04/02 34pp
- 8004150464 Notice of appearance in proceeding Certificate of Svc encl TURK,S E Hearing Branch 1 80/04/14 2pp
- 8004150484 Forwards IE Insp Rept 50-341/60-02 on 800121-23 & 0211-12 & notice of violation investigation resulted from ABC News allegations of GA program noncompliance TURK, S E Hearing Branch 1 80/04/14 ip
- ---8004150489 Forwards IE Insp Rept 50-341/80-02 on 800121-23 & 0211-12 & notice of violation KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/11 2pp
- ---8004150490 Notice of violation from insp on 800121-23 & 0211-12 + Region 3, Chicago. Office of the Director 80/03/07 1p
- --8004150496 IE Insp Rept 50-341/80-02 on 800121-23 & 0211-12
 Noncompliance noted personnel qualification requirements had
 not been established for onsite small bore pipe support
 design group & control for design work anadequate
 PHILLIP, G A . NURELION. C E Region 3. Chicago, Office of the
 Director DANIELION. D H Region 3. Chicago, Reactor Construction
 & Engineering Support Branch 80/03/07 7PP
- H General correspondence
- BOD4290111 FOIA request for info re NRC educational & training requirements for nuclear plant security force personnel & min requirements for weapaney & communication equipment use MURRAY.J.J. Affiliation Unknown BO/04/01 1p
- 8004290106 Responds to FOIA request for info re NRC educational & training requirements for nuclear plant security force personnel & min requirements for weaponry & communication equipment use forwards documents listed in App A Wy encls FELTON J M Division of Rules and Records 80/04/15 2pp
- G Inspection reports. IE Bulletins & correspondence
- 8004040022 Forwards IE Investigation Rept 50-341/79-26 on 790215-0302 & 800123 No noncompliance noted KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/12. Zoo
- ---8004040026 IF investigation Rept 50-341/79-26 on 790221-0302 & 800123 No noncompliance noted Major areas inspected allegation that stainless steel pipe was improperly cut & installed by work craw which was under influence of drugs MARBH, J. NORELIUS, C.E. Region 3, Chicago, Office of the Director 80/02/04 Spp
- 8004040050 Forwards IE Insp Rept 50-341/80-01 on 800115-18 No nancompliance noted FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --8004040052 IE Insp Rept 50-341/80-01 on 800115-18 No noncompliance noted Major areas inspected followup of previously identified noncompliances/unresolved items, project turnover electrical work activities t electrical records KMOP.R C , BARRITT, P A , HUGHES, J Region 3, Chicago, Office of the Director 80/02/13 6pp
- 8004070130 Ack receipt of 800131 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/79-24 FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/06 lp

- --8004070135 Responds to NRC ltr re violations noted in IE Insp Rept 50-341/79-24 Corrective actions to be reported in detail to NRC inspectors on next visit Discussion of infraction encl HINES,E Detroit Edison Co 80/01/31 4pp
- 8004080645 Ack receipt of 800228 litr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/79-25 Notes supplemental info will be submitted re site GA & integration of engineers w/contractor personnel FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/24 lp
- --B0040B0649 Responds to NRC B00114 ltr re violations noted in IE Insp Rept 50-341/79-25 Corrective actions GA procedures re bypass of holding points revised to assure compliance HINES,E Detroit Edison Co B0/02/28 Spp
- B004i50172 Forwards IE Info Notice B0-12. "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary KEPPLER.J Q Region 3. Chicago, Office of the Director B0/03/31
- 8004080708 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director BO/04/01 in
- 8004150040 Forwards 1E Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J Q Region 3. Chicago. Office of the Director 80/04/0⊋
- B004180050 Forwards attachments to IC Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800304 transmittal KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 800422013B Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/04/02 to
- 8004220354 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Dil 8ys " No written response required KEPPLER.J 9 Region 3. Chicago, Office of the Director 80/04/03 ip
- 8004110036 Forwards IE Bulletin 80-07. "BWR Jet Pump Assembly Failure " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/07
- 8004230245 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/04/07 in
- 8004220100 Forwards JE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/07 in
- 8004300382 Forwards response to infractions noted in IE Insp Rept 50-341/80-02 on 800121-23 & 0211-12 Corrective actions calculations verified by Edison Design Engineering & changes are being made in procedure manual addressing design muds HINES: E Detroit Edison Co 80/04/22 10pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004040048 PND-III-80-054 on 800318, licensee informed Region 3 that Channel 7 news in Detroit MI plans to televise 800321 interview w/site contractor employees re allegations of improper receipt inep of small bore pipe BARRETT.P A. KNOP.R C. FIGRELLI.G. Region 3. Chicago, Office of the Director 80/03/19 ip
- 8004020403 Interim deficiency rept re loose connections to terminals on QE receptacle pins for main reactor control panels. Number 20 wire to receptacles will be reterminated Final rept to be submitted prior to 800718 FAHRNER.W J Detroit Edison Co 80/03/21 ip

- 8004110526 Ack receipt of 800228 interim deficiency rept re laminations in raceway hanger support steel FIORLLLI.G Region 2, Atlanta, Office of the Director 80/03/27 lp
- B004230489 Final deficiency rept re limited heat number on A-36 steel Cause unstated Removal of supports initiated Deviation disposition request generated FAHMER, N.J. Detroit Edison Co. 80/03/28 1p
- BOO4;BO301 Ack receipt of BOO313 interim deficiency rept re final evaluation on misalighed assemblies not yet received from manufacturer. Tube Turns
 FIORELLIO Region 3, Chicajo. Reactor Construction & Engineering Support Branch BO/04/01 ip
- 8004270053 Ack receipt of 800321 interim deficiency rept re termination to receptacies in main control room panels 601/602 & 603 Awaits rept suppl identifying apparent cause for loose connections & broken strands
 FIBRELLIG Region 3. Chicago, Reacto; Construction & Engineering Support Branch 80/04/14 ip
- DOCKET BO-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

 F. Security, medical, emergency & fire protection plans
- BOD4240442 Bubmits evaluation of into submitted refire protection for Train B switchgear room & requirements for addl mods Requests response within 20 days to indicate selected option or to schedule meeting for discussion Requirements encl SCHWENCER, A Operating Reactors Branch 1 80/03/18 12pp
- 8004140066 Responds to 791130 request that primary spokesman be physically located at state capitol bldg in event of incident Experience demonstrates that best info obtained from location as close as possible to reactor DENTON, H R Office of Nuclear Reactor Regulation 80/03/25 2pp
- 8004210014 Forwards safety evaluation for incomplete fire protection items identified in 780309 safety evaluation requiring add1 design details prior to implementation of mods Items resolved SCHMENCER, A Operating Reactors Branch 1 80/03/25 4pp
- --8004210018 Safety evaluation for incomplete fire protection items identified in 760309 safety evaluation Items resolved * Operating Reactors Branch 1 80/03/25 App

9 Adjudicatory correspondence

8004020229 Mation suggesting filing of other parties' testimony on 800326 re adequacy of proposed modified complex & on 800317 re other subj.s Proposes matters to be considered at each hearing session Certificate of Svc encl AKELRAD, M. JOHNEGUN. R M. Portland General Electric Co. AXELRAD, M. Lowenstein, Newman, Reis, Axelrad & Toll 80/02/28 7pp

1

- 5004230293 Requests that encl 500925 daily highlight be forwarded to Trojan Control Bldg Unemaing Board & all parties on svc list for proceeding Certificate of Svc encl EISCHHOT (i.e. Division of uperating Reactors 30/04/02 App
- 8004280006 Forwards CE Gaskin arridavit in response to ASLB 800311 prehearing conference request to review effects of drugs on security re proposed mods to control bldg Protection during 2 after mods provided adequately 9RAY.J R Hearing Branch 1 80/04/11 2pp
- --8004280013 Afridavit stating that physical security measures provide adequate protection level during & after proposed mods to control bldg Prof qualification encl GASKIN.C E Reactor Safeguards Licensing Branch 60/04/10 6pp
- P Operating license stage documents & correspondence
- 8004030102 Forwards "Nuclear Data Kint Specs," study of digital communication sys to tiensmit info from plants to Bethesda Operations Ct: EISENHUT, D G Division or Operating Reactors 80/03/12 5pp
- ---B004030118 "Nuclear Data Link Specs "

 Davision of Operating Reactors 80/02/21 28pp
- B004220087 Forwards request for addl info re containment purge generic issues Addl into needed to continue review of 790103 ltm SCHWENCER.A Operating Reactors Branch 1 80/03/18 4pp
- B004100307 Notification of B00327 meeting w/util & Westinghouse in Bethesda.MD to discuss 'H" computer sys & data transmission for onsite technical support of & to discuss short-term THI-1 lessons learned implementation TRAMMELL.C Operating Reactors Branch i 80/03/19 2pg
- 8004010334 Forwards additinfo by Bethtel re A-frame support used in Plate 8 movement from equipment hatch in turbine bldg to position setured to plate support frames info assists in resolution of Item 1 of KS Herring & D Persinko testimony BRUEHL.D J Portland General Electric Co 80/03/27 3pp
- 8904020409 Describes program for sample tube removal & subsequent analyses Submits background info re tube plugging BROEHL, D. J. Portland General Electric Co. 80/03/27 49p
- 8004280296 Provides program description to removal of representative samples of steam generator tubes during Apr 1980 scheduled refueling outage.per util 791104 & 16 ltrs to NRC Bamples will be analyzed to determine cause of leak discovered BROEHL.D J Portland General Electric Co 80/03/27 4pp
- 8004080447 Submits info in response to NRC 800223 request re in-series check valves isolating high pressure RCS from LPIS piping Operating Test Procedure 2-4 will be modified to include second check valves for testing at refueling interval GOODHIN,C Pacific Oas ? Electric Co 80/03/31 5pp
- 8004030240 Forwards Change Application 58 to amend License NPF-1. Tech Spec Section 4 (3 3.allowing 25% extension of surveillance interval for rod drop time GODWIN.C Portland General Electric Co 80/04/01 1p
 - 04030243 Change Application 58 to amend License NPF-1.Tech Spec Section 4 5 3 3 allowing 25% extension of surveillance interval for rod drop time GODDWIM.C Portland General Electric Co GO/04/01 3pp
- JOC4080388 Notifies that GA program for operations has been reviewed re diesel generator fuel oil Fuel oil has been included in GA program for some time GOODWIN.C Portland General Electric Co 80/04/01 ip
- G0040B0306 Forwards Mar 1980 Addendum 1 to "Rept on Testing of Composite Masonry Walls.Nov 1979 " Test results described in addendum indicate that 40 psi is appropriate principle tensile stress value at block core interface of wall BROEHL.D J Portland General Electric Co B0/04/01 1p
- ~-8004080509 Addenoum 1 to "Rept on Testing of Composite Masonry Walls "
 * Portland General Electric Co 80/04/01 Spp
- B004100459 Forwards marked-up draft copy of proposed Tech Specs re second level undervoltage protection to expedite completion of safety evaluation concerning degraded grid voltage Also forwards corrected page of 800111 response G000MIN.C Portland General Electric Cq 80/04/03 7pp

- 8004210005 Requests that licensee remit addl sum per 10CFR170 requipments for Class III fee category re 791228 Tech Spec Changes revising B concentration & quantities Fee should be submitted within 15 days after secept of ltr MILLER.W O License Fee Management Branch 80/04/03 1p
- 6004300250 Forwards Amend 43 to License NPF-1, safety evaluation & notice or issuance & availability
 SCHMENGER.A Operating Reactors Branch 1 80/04/04 2pp
- ---8004300255 Amend 43 to License NPF-1, changing Tech Specs to allow onetime two-day extension of surveillance interval for control rod drop times SCHWEMCER, A Operating Reactors Branch 1 80/04/04 5pp
- -8004300259 Safety evaluation supporting Amend 43 to License NPS-1
 * Office of Nuclear Reactor Regulation 80/04/04 2pp
- --8004300264 Notice of issuance & availability of Amend 43 to License NPF-1 SCHWENCER, A Operating Reactors Branch 1 80/04/04 2pp
- 800418036; Forwards application to amond License NPF-1 authorizing mods to cable tray lests 5 containment fire suppression sys, submitted as Class III amend Certificate of Svc encl GOODWIN.C Portland General Electric Co 80/04/14 4pp
- --B004:B0362 Application to amend License NPF-1 authorizing mods to cable tray test & containment fire suppression sus-submitted as Class III amend Util safety evaluation encl OGODMIN.C Portland General Electric Co B0/04/14 5pp
- --8004180356 Proposed changes to Tech Specs 6 1 & 6 2 % Figure 6 2 1 for administrative controls % min shift crew composition * Portland General Electric Co 80/04/14 2pp
- 8004180466 Forwards responses, prepared by Bechtel, to NRC 800403 guestions re proposed mods to control bldg Also forwards proposed Tech Specs re control bldg mod connection bolts & proposed revision to Tcch Specs Section 5 7 i BROCHL, D J Portland General Electric Co 80/04/14 12pp
- --8004180467 Proposed Tech Specs, Section 3/4 7 11, re control bldg mod connection bolts Addl responses to NRC 800403 questions re proposed mods to control bldg encl * Portland General Electric Co 80/04/14 23pp
- --B004180470 Proposed revision to Tech Spec.Section 5 7 1,re seismic classification * Portland General Electric Co B0/04/14 1p
- 8004220675 Forwards supplemental info re short-term Lessons Learned Task Force recommendations BROCHL.D J Fortland General Electric Co 80/04/15 26pp
- 8004300380 Forwards revised Section 2 1 6 a.to 800415 ltr. "Integrity of Sys Outside Containment Likely to Contain Radioactivity." re implementation of NUR-0-057B requirements Revisions reflect clairlications discussed in 800417 telcon DROEHL.D J Portland General Electric Co 80/04/25 3pp
- Q Inspection reports. If Builetins & correspondence
- 8004180521 Forwards IE Insp Rept 50-344/80-01 on 800102-31 & notice of violation CREWS.J L. Region 5, San Francisco. Office of the Director 80/02/21 2pp
- ---8004180523 Notice of violation from insp on 800102-31

 * Region 5. San Francisco, Office of the Director 80/02/20 ip
- ---8004180527 IL Insp Rept 50-344/80-01 on 800102-31 Noncompliance noted failure to comply w/physical security procedure for securing of onsite vehicles
 STERMBERG, D I, MALMROS, M H Region 5, Ban Francisco, Office of the Director 80/02/20 Spp
- 8004010008 Forwards responses to 800215 notice of violation, notice of proposed imposition of civil penalties & request for identification & implementation of improvements in physical protection mgt Encls withheld (ref 10CFR2 790) WILLIAMS, J. L. Portland General Electric Co. 80/03/07 ip.
- 8004100264 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 30-344/80-02 CREW8, J L. NRC Regional Offices 80/03/13 1p

- --8604100273 Responds to NRC 800208 ltr re violations noted in IE Insp. Rept 50-344/80-02 Corrective actions training assistant assigned to follow licensee reactivity manipulations & ensure documentation GOODMIN.C. Portland General Electric Co. 80/02/27 3pp
- ---8004100282 Forwards IE Insp Rept 50-344/80-02 on 800121-23 & notices of violation & deviation CREMS.J L NRC Regional Offices 80/02/08 2pp
- --8004100288 Notice of violation from insp on 800121-23
 * NRC Regional Offices 80/02/07 ip
- --B004100295 Notice of deviation from insp on B00121-23
 * NRC Regional Offices B0/02/07 ip
- --B004100303 IE Inep Rept 50-344/B0-02 on 800121-23 Noncompliance noted failure to keep records of reactivity control manipulations & to prepare quarterly summaries of retraining programs STERNBERG.D M Region 5. Sam Francisco, Reactor Operations Nuclear Support Branch CARLSON, J. C., JOHNSON, P. H. Region 5. San Francisco, Office of the Director B0/02/07 Spp
- B004070322 Forwards request for add1 info for review of util 791228 ltr re inservice insp program Response requested within 45 days SCHWENCER.A Operating Reactors Branch 1 80/03/18 5pp
- B004280080 Forwards IE Insp Rept 50~344/80-04 on 800201-29 No noncompliance noted CREMB.J L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/03/24 2pp
- --B0042800B7 IE Insp Rept 50-344/80-04 on 800201-29 No noncompliance noted Major areas inspected plant operations maintiphysical security refueling preparations & procedures STERNBERS,D M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch JOHNSTON,G W., MALMROS,M H. Region 5. San Francisco, Office of the Director 80/03/20 App
- 8004150207 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of FORV & Block Valve " No specific action or response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/31 1p
- 9004100104 Forwards IE Circular 90-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 lp
- 8004110113 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/02 10
- 8004220046 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees " No action required ENGELKEN.R H. Region 5. San Francisco. Office of the Director 80/04/02 ip
- 8004180152 Forwards IE Circular 80-07, "Problems H/HPCI Turbine Oil 8ys " No written response required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/03 1p
- 8004080542 Provides schedule for 800426-0505 fuel insps during Cycle 2 refueling outage Insps will be performed by Westinghouse & Util in spent fuel pool area Preliminary oral rept will be made prior to return to operation GDODWIN, C Portland General Electric Co 80/04/04 2pp
- 8004230376 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME BA-312,Type 304 Stainless Steel Pipe" Action required ENGELKEN,R H Region 5, Ban Francisco. Office of the Director 80/04/04 ip
- 8004220179 Forwards IE Bulletin 80-08, "Exam of Containment Liner Panetration Welds " Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/07 in
- 8004300397 Responds to IE Info Notice 80-06, "Notification of Significant Events " Reporting guidance for events already defined in Reg Guide I 16 & specified in Tech Specs Need for new rulemaking unjustified BROEHL,D J Portland General Electric Co 80/04/25 3pp

- R Periodic operating reports % related correspondence
- 8004080442 Forwards monthly operating rept for Mar 1980 YUNDT,C P Portland General Electric Co 80/04/01 ip
- --B0040B0446 honthly operating tept for Mar 1780
 BAIR.G G Portland General Electric Co B0/04/01 4pp
- S Reportable occurrences, LERs & related correspondence
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior math Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT, X W Region 2, Atlanta, Office of the Director 77/08/12
- 8004210224 PNC-77-203 on 771117, pips caps were discovered on sensing lines for all four underange containment pressure sensors Condition existed since May 1977 Caps were removed from sensing lines immediately KLINGER, G., NOLAN, F., SMIEZEK, J. Region 2. Atlanta, Office of the Director 77741/18 ip
- 8004150440 Forwards LER 80-004/03L-0 YUNDT,C P Portland General Electric Co 80/04/07 2pp
- --8004150442 LER 80-004/03t-0 on 800309, during periodic testing, control room emergency ventilation sys failed to have required flow rate Caused by personnel error Manual ventilation damper placed in throttled position Damper signs posted PERRY, J. C. Portland General Electric Co. 80/04/07 ip
- B004270471 Forwards LER 80-005/01T-0 YUNDT.C P Postland General Electric Co 80/04/22 2pp
- --8004270478 LER 80-005/01T-0 on 800411.during periodic surveillance testing, three of four main steam isolation valves failed to respond to manually initiated closing signal Caused by component failure FERRY, J. C. Portland General Electric Co. 80/04/22 ip
- T Hearing transcripts on non-antitrust matters
- 8004040063 Forwards licensee testimony on matters other than structural adequacy of complex, testimony on structural adequacy of modified complex, leview of proposed design of mods for control bldg & response to NRC request for suppl info JOHNSON, R Portland General Electric Co 80/03/17 3pp
- --8004040065 Testimony re matters other than structural adequacy of madified complex Prof qualifications of DJ Broehl, LJ Erickson, RC Anderson & UM White encl BROEHL, DJ. ERICKSON, LW Pacific Gas & Electric Co ANDERSON, R C Bechtel Corp 80/03/17 150pp
- ---8004040067 Testimony re structural adequacy of modified complex Prof qualifications of RC Anderson.WH White.S Dimal & LC Chang-Lo encl ANDERSON.R C , BIMAL.S Bechtel Power Corp (subs of Bechtel Corp) WHITE.W W Bechtel Corp 80/03/17 105pp
- --8004040070 "Review of Proposed Mods for Control Bidg " HOLLEY,M J. Hanse, Holley & Briggs, Inc. BRESLER,D. Wiss, Janney, Elstner & Association, Inc. 80/03/13 17pp
- --8004040073 Forwards supplemental info responding to NRC request at 800307 meeting re structural considerations of proposed mods to control bldg BROCHL.D J Portland General Electric Co 80/03/17 50pp
- B004280002 Transcript of 800331 evidentiary hearing, Phase 2 in Portland, OR Pp 3640-3912
 # Commission 80/03/31 277pp
- 8004190311 Transcript of Phase Two evidentiary hearing in Portland.DR Pp 3913~4123

 * Commission 80/04/01 210pp
- B004170314 Transcript of 800402 hearing in Portland OR Pp 4,300-4,453 * Atomic Safety and Licensing Board Panel 80/04/02 154pp.
- 8004170326 Transcript of 800403 evidentiary hearing,Phase 2.in Portland.OR Pp 4,454-4,497 * Atomic Safety and Licensing Board Panel 80/04/03 43pp

- 8004280003 Transcript of £00416 healing in Portland OR Pp 4498-4658 * Atomic bafety and Licensing Board Panel 80/04/16 161pp
- 8004250253 Transcript of 800417 hearing in Portland DR Pp 4659-4828 * Atomic Sarety end Licensing Board Panel 80/04/17 197pp
- DOCKET 50-344 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8004240524 Forwards sys description & operating instructions for NRC health physics telephone network Sys designed for use during nuclear incident of AO Network may also be used for daily administrative & facsimilie traffic REPPLERIJ C Region 3, Chicago, Ofrice of the Director 80/03/20
- --8004240526 Sys description A operating instructions for NRC health physics telephone network + Government Services, Inc. 79/11/30 App
- 8004010419 Forwards upgraded emergency plan * response to 800219-21 onsite review of emergency planning Util will use updated version to smplement procedures & conduct training by Spring or Summer 1980 CROUSE.R P Toledo Edison Co 80/03/27 9pp
- --8004010427 Emergency plan
 * Toledo Edison Co 80/03/28 130pp
- 8004180353 Forwards description of fire protection sys mods scheduled for completion by 800422 in support of util 791222 request for delay until 800930 Delay is based on revised estimates of wort scope & manpower limitations
 CROUSE.R P Toledo Edison Co 80/04/11 3pp
- 8004280456 Forwards Revision 13 to industrial security plan, AD 1808 00 Encl withheld (ref 10CrR2 790) CRDUSE,R P Toledo Edison Co 80/04/22 1p
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDSSICKL V Office of the Executive Director for Operations 90/04/02 34pp
- H General correspondence
- 7906290854 Responds to 790411 ltr on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diable Canyon EISENHUT, D & Division of Operating Reactors 79/05/22 2pp
- I Financial information
- BOO415047i Forwards three documents as evidence of guarantee of share of retrospective premium which may be levied against licensees in CYBO Adequate cash flow can be generated, if required, for retrospective premium. MAUGANS, E H Cleveland Electric []]uminating Co BO/04/iO 2pp
- 8004280380 Forwards cash flow info for Toledo Edison & Cleveland Electric Illumination Co & Annual Financial Rept 1979 for Toledo Edison to demonstrate ability to pay combined retrospective premium for facility CROUSE.R P , ERTLE.R F Toledo Edison Co 80/04/18 6pp
- ---8004280382 Annual Financial Rept 1979 * Toledo Edison Co 80/04/18 26pp
- ---B004280386 Forwards cash flow info & Annual Financial Rept 1979 to demonstrate ability to pay retrospective premium for facility W/o annual rept MAUGANS.E H Cleveland Electric Illuminating Co 80/04/10 2pp
- J Insurance & indemnity information
- 8004140346 Forwards Endorsement 25 to MAELU Policy MF-92 CDRREA,C Marsh & McLennan, inc , M & M Nuclear Consultants, Inc Div 80/04/03 2pp

- P Operating license stage documents & correspondence
- 8004040005 Forwards outline of plant-specific questions to be addressed in addition to info required by IE Bulletin 79-27 re 800206 reactor trip at Crystal River Sequence of events & planned Corrective actions also enci DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 26pp
- 8004070215 Requests Class IV fees for review & approval of 800211 application proposing Yech Spec changes for Cycle 2 operation
 DIGOS,R M. License Fee Management Branch 80/03/06 1p
- BOO4030102 Forwards "Nuclear Data Link Specs." study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 5pp
- --8004030118 "Nuclear Data Link Specs "
 * Division of Operating Reactors 80/02/21 28pp
- B004030230 Notification of 800318 meeting u/all operating 86W reactor licensees in Bethesda.MD to evaluate implications of Crystal River Unit 3 event & response to IE Bulletin 79-27 REID.R W Operating Reactors Branch 4 80703/14 2pp
- 8004100176 Requests controlled set of PVIDs Submittal should be forwarded to attention of Region 3 incident response Ctr within 20 days KEPPLER J G Region 3. Chicago, Office of the Director 80/03/20
- 8004150103 Forwards Amend 23 to License NPF-3 safety evaluation & notice of issuance & availability REED.R W Operating Reactors Branch 4 80/03/27 ip
- --8004150110 Amend 23 to License NPF-3 modifying Tech Specs to allow for delay in testing of reactor vessel internals vent valves REID.R W Operating Reactors Branch 4 80/03/27 2pp
- --8004150114 Safety evaluation supporting Amend 23 to License NPF-3 * Office of Nuclear Reactor Regulation 80/03/27 2pp
- --8004150120 Notice of issuance & availability of Amend 23 to License NPF-3 REID,R W Operating Reactors Branch 4 80/03/27 2pp
- 8004080514 Forwards add1 responses to questions raised during 800225-26 site visit for review of implementation of NUREQ-0578 requirements CROVEE, R P
- Taleda Edison Co 80/04/01 4pp
- 8004210328 Summary of G00222 meeting w/B&W owners group in Bethesda,Md re abnormal transient operational guidelines SEIGEL,B L Reactor Systems Branch 80/04/02 4pp
- 900425036B Summary of 800403 meeting w/utils.B&W.NUS Corp & McGraw-Hill in Bethesda.MD re draft NUREC-0667. "Transient Response of B&W-Designed Reactors "CAPRA.R A Standardization Branch 80/04/04 7pp
- 8004180490 Notification of 800423 meeting w/utils & B&W in Bethesda,MD to discuss implementation of recommendations by B&W Reactor Transient Response Task Force CAPRA,R A Standardization Branch 80/04/05 2pp
- 8004220534 Advises that installation of proposed reactor vessel head vent is still under review Design requires vent path w/two isolation valves in series Installation scheduled for 1981 refueling outage CROUSE.R P Toledo Edison Co 80/04/15 ip
- 8004220457 Clarifies Items 1/2 of util 800324 ltr re-actions in response to transient at Crystal River 3 Pilot operated relief & pressurizer stray valve will close during loss of power Power source removed during testing procedure CROUSE,R P Toledo Edison Co 80/04/14 2pp.
- 8004250376 Forwards info re GA requirements for diesel generator fuel pil in response to NRC 800107 request.Util does not cover diesel generator fuel pil t does not include Reg Guide i 137 in QA program Excepts of procedures encil CRCUSE,R P Taledo Edison Co 80/04/18 4pp.

- Q Inspection reports, 1E Bulletins & correspondence
- BOO4020135 Forwards response to IE Insp Rept 50-346/79-23 re verification study of pipe whip restraints on RCS All analyses verify restraints are adequate CROUSE.R P Toledo Edison Co 79/12/07 76pp
- 8004040143 Forwards IE Insp Rept 50-346/79-33 on 791121,1212-14 & 800125 No noncompliance noted FIGRELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/14 2pp
- --B004040150 IE Insp Rept 50-346/79-33 on 791121,1212-14 & B00125 No noncompliance noted Major areas inspected resistance temp detector connection repair at hot leg risers & licensee implementation of IE Bulletins 79-02 & 79-14 DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch YIN,T Region 3, Chicago, Office of the Director 80/02/12 App
- 8004100013 Forwards IE Insp Rept 50-346/80-01 on 800102-04.07-11.14-18, 21-23,29-31 & 0201 & notice of violation HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/21 2pp
- --8004100016 Natice of violation from insp on 800102-04.07-11.14-18. 21-25.29-31 & 0201 * Region 3, Chicago, Office of the Director 80/02/20 ip
- --8004100022 IE Insp Rept 50-346/80-01 on 800102-04,07-11,14-18,21-25, 27-31 & 0201 Noncompliance noted improper switch lineup in control room emergency ventilation sys REYER, L. A. TAMBLINO, T. N. Region 3, Chicago, Office of the Director 80/02/20 7pp
- 8004100146 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07
- BOD4040455 Responds to IE Bulletin BO-O3, "Loss of Charcoal from 8td Type II.2 Inch.Adsorber Cells " Type II filtration charcoal tuploading adsorbers welded w/o charcoal leakage Torque setting adjusted to obtain proper compression CROUSE,R P Toledo Edison Co BO/O3/14 3pp
- 8004040115 Forwards IE Insp Rept 30-346/80-02 on 800114-18 & notice of violation Notice of violation witheld (ref 10CFR2 770) HIND, J A Region 3, Chicago, Safeguards Branch 80/03/18 2pp
- --8004040132 IE Insp Rept 50-346/80-02 on 800114-18 Noncempliance noted failure to adequately control access Portion of active intrusion detection alarm sys not tamper-indicating Details withheld (ref 10CFR2 790)
 HIND, J A Region 3, Chicago, Safeguards Branch USTICK, N R, BCHAPER, J F Region 3, Chicago, Office of the Director 80/03/07
- 6004090415 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/77-30 HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/24 ip
- --8004090424 Responds to NRC 800212 itr re violations noted in IE Insp Rept 50-346/79-30 Corrective actions, reorganized authorized access list, updated drawings & monitored distribution & control of drawings CROUSE, R P Toledo Edison Co 80/03/04 3pp
- 8004100081 Ack recuipt of 800314 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapt 50-346/80-01 HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/24 ip
- --8004100071 Responds to NRC 800221 itr re violations noted in IE Insp Rept 50-346/80-01 Corrective actions local/remote Switch HA 5261A handle removed & stored in adjacent location GROUSE, R P Toledo Edison Co 80/03/14 2pp
- 8004150191 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/31

- 8004080724 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/01 ip
- 8004150055 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/04/02
- 8004180060 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/02
- 8004220151 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3. Chicago. Office of the Director 80/04/02
- 8004220384 Forwards IE Circular 80-07. "Problems W/HPCT Turbine Gil Sys " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/03 to
- 8004300617 Forwards partial response to TE Bulletin 79-01B, "Environ Qualification of Class TE Equipment" Response to Items 1, 3 & 5 are complete; w/partial response to Item 2 W/o encl CROUSE, R P Toledo Edison Co 80/04/03 2pp
- 8004230285 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/07
- 800422007 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09 19
- R Periodic operating reports & related correspondence
- 8004140350 Forwards monthly operating tept for Mar 1980 MURRAY,T D Tolodo Edison Co 80/04/07 ip
- --8004140353 Monthly operating rept for Mar 1980 BARSOUR, B Toledo Edison Co 80/04/07 12pp
- S Reportable occurrences. LERs & related correspondence
- 8004180517 PND-111-78-117A review of failure of diesel generator sequencer circuit indicated that design error had occurred in translating logic drawing to contractor installation drawing Corrective action was documented in NRC 780612 ltr KLINGER, G , NOLAN, F , SNIEZEK, J Region 3, Chicago. Office of the Director 78/06/13 ip

800

- GUGALSHER Forward, ELR JUJULIN DE-O MURRAT, F. D. Toledo Edison Co. EC 04/10 - Lp
- 8004150570 LER Partial first from 800313 during diesel fine protection purp weetly restricted which not be stopped w/control button Ohre stopped by writing fort be started wave not determined by wither rheat feeting in purp probed successful FREGRER Tolego Edizon for 80/04/10 3pp
- E004210265 Forcards LER _0 022 036-0 MURRAY T D _ Toledo Fora n C _ 80/04 15 _ (p
- --8004210267 LER 80-022/vill-0 un RCQ317, operations personnel noticed loss of control room indication for containment dihydrogen analyzer 2 discharge line valve CV5010E Caused by const personnel accidentally opening breaker STOTZ, J.C. Toledo Edison Lo. 80/04/15 3pp
- 2004220457 Forwards revised LER 80-009/03L-1 MURRAY T D Toledo Edison Cc 80/04 16 1p
- 8004220752 Forcards revised LER 79 074/03L-1 MURRAY.T D Foledo Edison Co 80/04/16 10
- --80042ZU/61 Re.ised LFR 77-074/03L-1 on 790707, auxiliary feedwater pump suction pressure swit h inoperability made auxiliary reedwater train inoperable Caused by wrong type switch being installed Switches replaced HITCHENS.C C Toledo Edison Co 79/08/02 3pp
- 9004220765 Forwards revised LER 79-098/03L-0 MURRAY T D Toledo Edison Co 80/04/16 1
- --8004220772 Revised LER 79-098/03L-1 on 791004, during performance of component cooling water monthly test decay heat cooler i component cooling outlef value CC1467 would not operate Caused by valve linkage slippage Linkage realigned DEAKYNE.X Toledo Edison Co 79/10/30 2pp
- 8004280538 Forwards LER 60-023/03L-0 MURRAY, T D Toledo Edison Co 80/04/24 ip
- --8004280546 LER 80-023/03L-0 on 800327, discovered that control rod groups 3 f 4 were moinn; in on their own Group 3 was 0% uithdraum Group 4 was 90% withdraum Caused by component failure Component replaced WERNER, B J Toledo Edison Co 80/04/24 3pp
- 8004280572 Forwards LER 80-024/03L-0 MURRAY,T D Toledo Edison Co 80/04/24 1p
- --8004280575 LER 80 024/G3L-O on 800327, following normally initiated reactor trap, auxiliary feed pump turbine 1-2 main steam tsolation valve MS-107 closed Cause unknown Further investigation of valve 2 operator will be pursued MATHENY, D Toledo Edison Co 80/04/24 3pp
- DOCKET 50-348 JOSEPH M PARLEY NUCLEAR PLANT, UNIT I F Security, medical, emergency & fire protection plans
- 8004110573 Notefication or 806325,26 % 27 meetings w/util,States of AL, FL % GA & FEMA re emergency planning at facility REEVES.E. Operating Reactors Branch (80/03/18 2pp
- 9004070267 Forwards revised safeguards security contingency plan Plan withheld (ref 100FR2 790) CLAYTOR,F L Alabama Power Co 80/03/28 ip
- J Insurance & indennity information
- 8004080485 Forwards Endorsement 29 to NELIA Policy NF-238 FIELDER.J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/03/31 2pp

- Γ . Operating license stage documents δ correspondence
- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit into from plants to Bethasda Operations Ctr EISERHUT.D G Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs"

 * Bivision of Operating Reactors 80/02/21 28pp
- 8004010372 Forwards addl info re compressed air sys Piping & instrumentation drawing encl MCCRACKENIK W Alabama Power Co 80/03/24 App
- 8004010425 Forwards response to NRC 800223 request for info re intersystem LOCA No valve configurations conform to Event 5 Plant design 8 insp commitments are more than sufficient to ensure that Event 5 will not be problem at facility CLAYION.F.L. Alabama Power Co. 80/03/24 9pp
- 8004080403 Commits to install backup sys to normal instrument air supply for pressurizer power operated relief valves, in response to Lessons Learned Review Team installation will be completed by end of Ott 1960 second refueling outage CLAYTON, FL Alabama Power Co 80/03/26 1p
- 8004090192 Application to amend License NPF~2 Tech Specs Figures 6 2-1, 6 2-2 % Tech Specs 6 5 1 2.6 5 1 8.6 5 2 2 % 6 5 3 1, re organization % responsibilities % Figure 3 2-3 % Bases 2 1 1 re change in rod bow penalty calculation CLAYTON.F.L. Alabama Power Co. 80/03/28 2pp
- --8004030194 Proposed changes to Tech Spec Figures, 6 2-1.6 2-2 & Tech Specs 6 5 1 2.6 5 1 8.6 5 2 2 & 6 5 3 1 re organization & responsibilities & Figure 3 2-3 & Bases 2 1 1 re change in rod bow penalty calculation

 * Alabama Power Co 80/03/28 1000
- 8004080657 Responds to tIRC 800226 request Forwards summary of heat transfer calculations used to justify two inches of ref leg insulation associated w/change discussed in 790830 ltr CLAYTON.F L. Alabama Power Co. 80/03/31. 2pp
- BOO4080651 Forwards response to NRC 791013 request for info re auxiliary feedwater sys Identifies reactor conditions that impose safety-related performance requirements on sys design CLAYTON,F L Alabama Power Co 80/04/01 12pp
- 8004230042 Advises that Commission has determined waiver of Class III amend see for Tech Sper changes re fire protection is appropriate Refund will be processed MILLER.W O Licenso Fee Management Branch 80/04/03 ip
- 8004150447 Forwards draft ETS ie proposed Tech Spec amend CLAYTON F L. Alabama Power Co. 80/04/07 5pp
- --8004150452 Drafts ETS for radiological effluents * Alabama Power Co 86/04/07 84pp
- 8004250020 Forwards auxiliary feedwater sys evaluation status indicating portions currently acceptable per NRC 791013 ltr Requests addl into for certain items within 45 days Revised version of endurance test requirements end
- 8004280434 Confirms 800417 telcon re util intent to resolve auxiliary feedwater sys designs evaluation by following resolution on Unit 1 for Unit 2 CLAYTON,F L Alabama Power Co 80/04/21 1p
- BOO4290284 Forwards Revision 2 to inservice testing program CLAYTON.F.L. Alabama Power Co. 80/04/21 1p
- --8004290286 Revision 2 to inservice testing program re turbine driven auxiliary feedwater pump recirculation test line # Alabama Power Co 80/02/27 4pp
- G Inspection reports. IE Bulletins & correspondence
- B00416003B Forwards 1E Bulletin 79-01B, "Environ Qualification of Class
 IE Equipment " Action required IE Bulletin 79-01B dtd 800114
 should be disregarded
 O'REILLY, J P Region 3, Chicago, Office of the Director B0/01/17
 2pp

- 8004100096 Supplements 790726 5 0827 responses to Item 4 of IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" Radiography was performed on each feedwater piping wold beyond first support FSAR Figure 3 8-8 encl CLAYTON, FL Alabama Power Co 80/01/30 3pp
- 8004090284 Forwards IE Insp Rept 50-348/80-01 on 800130-31 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/02/21 2pp
- --8004090291 IE Insp Rept 5D-348/80-01 on 800130-31 No noncompliance noted Major areas inspected areas & activities re IE Bulletin 79-17
 HERDT.AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMIS, N Region 2. Atlanta, Office of the Director 80/02/19 App
- 8004080021 Ack receipt of 800221 itr in forming NRC of steps taken to correct violations noted in IE insp Rept 50-348/79-42
 BTOHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/03/11 2pp
- --8004080027 Responds to NRC 800204 ltr re violations noted in IE Insp Rept 50-348/79-42 Corrective actions Maint Work Request 19749 changed to accommodate plant conditions which whould affect procedure for proposed work CLAYTON: FL Alabama Power Co 80/02/21 2pp
- --8004080034 Forwards IE Insp Rept 50-348/79-42 on 791210-14 % notice of violation STDHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/02/04 2pp
- --8004080040 Notice of violation from insp on 791210-14 * Region 2, Atlanta, Office of the Director 80/01/29 ip
- --8004080043 IE Insp Rept 50-348/79-42 on 791210-14 Noncompliance noted failure to follow procedures for reviewing maint work request GIBSON, A F. HOSEY, C M Region 2, Atlanta, Office of the Director 80/01/29 6pp
- 8004280134 Forwards IE Insp Rept 50-348/80-05 on 800217-22 No noncompliance noted LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/12 2pp
- --8004280143 IE Insp Rept 50-348/80-05 on 800219-22 No noncompliance noted Major areas inspected areas of small break loss of coolant procedures & training UPRIOHT.C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch BRADFORD,W H. JOHNSON,A H Region 2, Atlanta, Office of the Director 80/03/10 App
- 8004110003 Forwards response to IE Bulletin 79-27 Loss of Class IE bus would not significantly affect instrumentation panels Some functions not related to achieving cold shutdown are temporarily lost CLAYTON.F.L. Alabama Power Co. 80/03/13 Spp
- 8004i903i3 Forwards IC Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080582 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'RETILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004i50064 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240242 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- BD04180272 Forwards IE Circular BD-07, "Problems W/HPCI Turbine Dil Bys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director BO/04/03

- 8004230113 Forwards IE Sullefin 75-03A 'Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required G'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/04 ip
- 8004180323 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Willten Lesponse required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300594 Submits quarterly tollowup status rept in response to IE Bulletin 79-14, "Seismic Analysis for As-Duilt Safety-Related Piping Sys" No deficient supports have been identified which affect operability of sys CLAYTON,F.L. Alabama Power Co 80/04/08 2pp
- R Periodic operating reports δ related correspondence
- 8004030212 Forwards "Annual Operating Rept for 1979 " CLAYTON,F L Alabama Power Co 80/03/26 1p
 - 8004030214 "Annual Operating Rept for 1979 " * Alabama Power Co 80/03/26 13pp
- 8004080492 Forwards "1979 Annual Environ Operating Rept.Part B Radiological" CLAYTUN:F L. Alabama Power Co. 80/03/31 1p
- 8004150426 Forwards monthly operating rept for Mar 1980 CLAYTON,F L. Alabama Power Co. 80/04/11 1p
- --8004150428 Monthly operating rept for Mar 1980 HAIRSTON,W G Alabama Power Co 80/04/01 7pp
- S Reportable occurrences, LERs / related correspondence
- 80042200B4 PNO-77-143 Pacific Pump Co supplied facilities w/production int of 40 pumps mfg using shafts made of inferior mati Cause unstated All stils w/pumps were notified NRC headquarters notified on 770B12 WHITT,K W Region 2, Atlanta, Office of the Director 77/0B/12
- 8004010507 Forwards LERs 80-018/03L-0 % 80-019/03L-0 CLAYTON, F L Alabama Power Co 80/03/21 1p
- --8004010510 LER 80-018/03L-0 on 800229. discovered bistable associated w/pressure transmitter 457 failed to meet trip setpoint requirements of surveillance test Caused by dirty gain potentiometer Potentiometer Canad HAIRSTON, W G Alabama Power Co 80/03/21 1p
- --8004010513 LER 80-019/03L-0 on 800229, during performance of control room Train A(B) ventilation operability test, recirculation fan 1B failed to start Caused by blown control power fuse & shorted alarm relay coil Coil & fuse replaced HAIRSTON,W O Alabama Power Co 80/03/21 ip
- B0040B0540 Forwards LERs B0-020/03L-0 \$ B0-022/03L-0 CLAYTON, F L Alabama Fower Co B0/04/02 1p
- ---8004080547 LER 80-022/03L-0 on 800303 during performance of FNP-1-8TP-16 7. discharge valve to containment spray header did not open as required Cause not determined Problem did not reoccur witesting Surveillance test completed HAIRSTONN 6 Alabama Power Co 80/04/02 1p
- ---8004080554 LER 80-020/03L-0 on 800303, inaccurate pressure signal noted from PT-494,1C 8/G pressure transmitter Caused by frozen sensing line due to abnormally cold weather & insufficient protection Sensing line thawed & channel check performed HAIRSTON, W G Alabama Power Co 80/04/02 1p
- E004220729 Forwards LER 80-021/03L-0 & updated LER 79-056/03L-1 CLAYTON, F L Alabama Power Co 80/04/09 1p
- --800422073B LER 80-021/03L-0 on 800316, during review of surveillance test schedule, found FNP-1-STP-9 O.RCS leakage test had not been performed within time interval Cause not stated Personnel instructed re test interval HAIRSTUN, W 9 Alabama Power Co 80/04/09 2pp

- --8004220746 Updated LER 79-056/03L-1 on 791108 twenty fire barrier penatrations were determined not functional Caused by improper interpretation of procedures Limiting conditions for operation met HAIRSTON.W G Alabama Power Co 80/04/09 Zpp
- 8004290367 Forwards LER 80-G24/03L-0 CLAYFON:F L Alabama Power Co 80/04/22 1p
- --8004270369 LER 80-024/03L-0 on 800330, while performing turbine startup, IB SGFP tripped due to 18 steam generator high level signal Caused by poor communication between plant operators Personnel instructed re-maintaining proper communication HAIRSTON, W G Alabama Power Co 80/04/22 1p

DOCKET 50-351 KOREA RESEARCH REACTOR

- 4 Inspection reports. IF Bulletins & correspondence
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/06

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8004040031 Advises or issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F Division of Project Hanagement 80/02/05 7pp
- 8003200214 Summary of 791218 meeting w/Pottstown Trap-Rock Quarries Inc.Perkins Run Blasting.Inc.Leet Associates.CVW Industries, USOS & MRC re evaluation of effects of blasting at Banatoga quarry on facility KANE.J D. Geosciences Branch 80/02/27 App
- 8004020466 Notification of 800326 / 27 meeting w/representatives from Mark II owners group in San Jose CA to discuss Mark II Creace Test Program, 47 c/o tests & foreign tests ELTAWILA.F Containment Systems Branch 80/03/10 12pp
- 8004030122 Natification of 800326-27 meeting w/Mark II owners group, NRC consultants & GE in San Jose CA to discuss Mark II Creare test program, 4T C/O & foreign tests Topics are proprietarly Agenda enci ELTAWILA.F Containment Systems Branch 80/03/10 12pp
- 8004020441 Forwards NRC 800128 t 0211 ltrs to GE re mods to BWR control rod drive sus & addl analyses of boiloff rates, respectively further anno & guidance to be issued in NUREO-0619 BAER.R L Light Water Reactors Branch 2 80/03/13 2pp

- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- H General correspondence
- 8004070030 Urges NRC to take into consideration that 3 8 million people population density, area could not be evacuated easily STOUDT.T Affiliation Unknown 80/02/13 1p
- 8004040224 Expresses concerns to util request for use of Delaware River water for facility W/3 8 million people in area & many obstacles, util continues to build plant Charges MRC w/responsibility to protect public from util POLLITT, K Affiliation Unknown 80/02/22 ip
- 9004040244 Approves favorable stand on public hearing request re evacuation plans at facility Power plant was mistake & const should be stopped before more money is wasted KEIL. J. Affiliation Unknown 80/02/22 ip
- 8004040251 Approves favorable stand on public hearing request re evacuation plans at facility Const should be stopped Plant should not be built in populated area KEIL. J Affiliation Unknown 80/02/22 ip
- 8004040119 Urges that all reactors come under new NRC regulations that do not allow reactors to operate in densely populated areas Facility is classified as second most dangerous location re population proximity Const should stop immediately LONGSHORE, M.L. Affiliation Unknown 80/02/23 ip
- BO04040216 Requests that NRC stop yower plant const Area surrounding facility is densely populated Questions whether NRC would reimburse people for property losses & health damage if another TMS accident occurred FRIEDMAN.C Affiliation Unknown 80/03/05 1p
- 8004070024 Suggests const of facility should be halted immediately Cites earthquake fault (lack of adequate water supply as groblems Facility is not needed by util now or in future CRAFER, J. Affiliation Unknown 80/03/06 ip
- BCO4020117 Responds to B00303 ltr requesting info re application of TMI-2 Lessons Learned Task Force to facility & certain other plants under const NTIB should be contacted for SER info ABLB proceedings announced in FR VARGA.B A Assistant Director for Light Water Reactors B0/03/22
- 8004180176 Responds to 800306 ltr re substituting coal plants for nuclear glants under const at site Since Unit 1 is 60% complete & Unit 2 40% complete little capital cost could be saved by stopping const YQUNGBLOOD, B J Cost Benefit Analysis Branch 80/04/02 2pp
- 8004:00471 Expresses concern re faulting at site Job interview in 1974 w/Gilbert Associates in Pottstown.PA revealed that proposed site ranked third or fourth of six site studies Also learned that site chosen due to ability to control public opinion ORLANDO.E Murphy & Parish 80/04/03 2pp
- BOO42502B3 Responds to BOO317 congressional referral of ltr re util failure to accept loan of cryogenic processing sys from Limerick facility rather than purging to atomosphere Purging chosen for expedience DENTON.H R Office of Nuclear Reactor Regulation BO/04/07 2pp
- I Financial information
- BOO4140317 Forwards Annual Financial Rept 1979
 BRADLEY, E.J. Philadelphia Electric Co. B0/04/08 ip
- --8004140317 Annual Financial Rept 1979 * Philadelphia Electric Co 80/02/25 34pp
- Q Inspection reports: If Bulletins & correspondence
- B004150139 Forwards IE Insp Repts 50-352/B0-01 & 50-353/B0-01 on 800109-11 & 16 No noncompliance noted CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch S0/02/12 2pp

- --B004150143 IE Insp Repts 50-352/B0-01 / 50-353/B0-01 on B00109-11 % 16
 No noncompliance noted Major areas inspected QA program for
 task of installing reactor pressure vessel internals &
 control rod drive hydraulic & neutron monitoring sys
 QAOE, L, WALTUN, G., EBNETER, S. Region 1, Philadelphia, Office of
 the Director B0/02/07 4pp
- 8004090435 Forwards IE Insp Repts 50-352/79-14 & 50-353/79-13 on 791220,21.2/ & 28 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/13 2pp
- --8004070438 IE Insp Repts 50-352/79-14 % 50-353/79-13 on 791220,21,27 % 28 No noncompliance noted Major areas inspected QA program work activities % records & QC records of nonconformance reporting sys

 QAGE, L. CHAUDHARY, S. Region 1. Philadelphia, Office of the Director EBNETERS Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/07 App
- 8004100099 Forwards IE Insp Repts 50-352/79-13 & 50-353/79-12 on 791212-13 & 17-21 No nuncompliance noted CARLBON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/13 2pp
- --8004100112 IC Insp Repts 50-352/79-13 % 50-353/79-12 on 791212-13 % 17-21 No noncompliance noted Major areas inspected GA procedures documentation & work activities pertaining to storage handling & surveillance of safety-related cables EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch PAVLIND.R T , VARELA, A A Region 1, Philadelphia, Office of the Director 80/20/07 App
- 800409039/ Advises that IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks." was incorrectly sent for action No response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/03/17 1p
- 8004100421 Responds to IE Bulletin 80-03 Charcoal filters used will not be susceptible to charcoal leakage problems Filters from American Air have not been delivered to job site, but when received will verify screen attachment sparing KEMPER, J 8 Philadelphia Electric Co 80/03/17 ip
- 8004230059 Ack receipt of B00214 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-11 & 50-353/79-10 CARLSON R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/20 ip
- ---8004230071 Responds to NRC 800111 ltr re violations noted in IE Insp Repts 50-352/79-11 & 50-353/79-10 Corrective actions superintendents have been instructed to keep equipment covered KEMPER, J S Philadelphia Electric Co 80/02/14 3pp
- --8004230079 Forwards IE Insp Repts 90-352/79-11 & 50-353/79-10 on 791015-31 & 1101-15 & notice of violation CARLSON:R T Region 1: Philadolphia Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --8004230089 Notice of violation from insp on 791015-31 & 1101-15 * Region 1, Philadelphia, Office of the Director 79/12/27 2pp
- --B004230114 IE Insp Repts 90-352/79-11 & 50-353/79-11 on 791015-31 & 1101-15 Noncompliance noted failure to protect safety-releted item from const activities when stored & to follow weld procedures requirements to prevent undercutting MATTIGA-J C Region i, Philadelphia, Diffice of the Director MCGAUGHYAR W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/12/27 14pp
- B004150293 Forwards (E Info Notice B0-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- 8004090093 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER B H Region 1. Philadelphia. Office of the Director 80/04/01 ip
- 8004110502 Forwards IE Info Natice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director BO/04/02 ip

- 8004240337 Forwards IE Into Notice 80-14. 'Safety Suggestions From Employees' No action required ORIER, B. R. Region 1. Philadelphia, Office of the Director 80/04/02 1p
- 8004180184 Forwards IE Circulat 80~0/, 'Problems N/HPCI Turbine Dil Sys " No written response required GRIER,B H. Region I. Philadelphia, Office of the Director 80/04/03 | jp
- 9004)10063 Forwards IC Bulletin 60-07 "SWR Jet Pump Assembly Failure " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- B004230399 Forwards IE Bulletin 79-03A: "Longitudinal Weld Defects in ASME BA-312, Type 304 Stainless Steel Pipe" Action required CRIER. B H Region 1. Philadelphia. Office of the Director 80/04/04 1p
- 8004180267 Forwards IC Builetin 80-08, 'Eram of Containment Liner Penetration Helds " Writton response required ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/04/07 1p
- S Reportable occurrences, LERs & related correspondence
- 8004300368 Forwards final deficiency rept re electrical receway separation
 KEMPER, J S Philadelphia Flectric Co 80/04/24 1p
- --8004300376 Final deficiency rept re electrical raceway separation Project QC Insp E-2 O has been revised to include final acceptance insp to verify that separation requirements have been maintained & training classes held # Philadelphia Flectric Co 80/04/30 4pp
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F Division of Project Management B0/02/05 7pp
- 8003200214 Summary of 791218 meeting w/Pottstown Trap-Rock Quarries Inc.Perkins Run Blasting.Inc.Leet Associates.CVW Industries. USQ8 & NRC re evaluation of effects of blasting at Sanatoga quarry on facility KANE.J D Geosciences Branch 80/02/27 4pp
- 8004020466 Notification of 800326 % 27 meeting w/representatives from Mark II owners group in San Jose.CA to discuss Mark II Creace Tast Program.47 c/o tests & foreign tests ELTAMILA, F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II owners group. NRC consultants & OE in San Jose,CA to discuss Mark II

14300064 Summary of 800126-27 meetings u/Hark II owners group in San Hose,CA to discussion of NRC conceins on data from Creare ests & foreign full-4cale test programs * relationships u/ Hark II designs LTAWILA F Containment Systems Branch 80/04/14 22pp

Security, medical, emergency * rire projection plans

14100006 Comments on propused rule 10CFR50 no examptions to license hould be given until emergency reponse plans are deamed idequate NRC should reconsider issuance of CP to facility (EIDTS:// G Arrisiation Unknown 80/03/03 ip

04080077 Advises that submittal date for evacuation time estimates, equested by NRC 791226 ltr.has been postponed pending GAO learance under Federal Repts Act RITES.B K Emergency Proparedness Task Force 80/03/11 4pp

General correspondence

14070030 Urges NRC to take into consideration that 3 8 million people eside within 30-mile radius of plant Considering apulation density, area could not be evacuated easily TOUBY. The Affiliation Unknown 80/02/13 ip

14040224 Figresses concerns regittlinequest for use of Delaware River later for facility W/3 8 million people in area & many lastacles, util continues to build plant Charges NRC l/responsibility to protect public from util OLCITT.V Affiliation Unknown 80/02/22 ip

4040244 Approves tayonable stand on public hearing request revacuation plans at facility Power plant was mistake b onst should be stopped before more money is wasted EH.J Affiliation Unknown 80/02/22 ip

4040251 Approves favorable stand on public hearing request revacuation plans at facility Const should be stopped Flant hould not be built in populated area ELL.J. Affiliation Unknown 80/02/22 ip

4040119 Urges that all reactors come under new NRC regulations that o not alimu reactors to operate in densely populated areas activity is classified as second most dangerous location a population proximity Const should step immediately ONGSHORE, M. L. Affiliation Uninpum BO/02/23 ip

4040216 Requests that NRC stop power plant const Area surrounding cility is densely populated Questions whether NRC would emburse people for property lasses & health damage if nother TMI accident occurred RIEDMAN, C. Affiliation Unknown 80/03/05 1p

1070024 Suggests const or facility should be halted immediately ites earthquake fault ' lack of adequate water supply as roblems Facility is not needed by util now or in future RATER. J. Affillation Unknown 80/03/06 lp

020117 Responds to 800303 its requesting info re application of fI-2 Lessons Learned Task Force to facility & certain other lants under const NTIG should be contacted for SER info LB proceedings amounted in FR NROA.8 A Assistant Director for Light Water Reactors 80/03/22

1180196 Responds to 800306 ltr re substituting coal plants for iclear plants under const at site Since Unit 1 is 60% implete & Unit 2 40% complete. Little capital cost could be ived by stopping const.
UNGBLOOD, B.J. Cost Benerit Analysis Blanch 80/04/02 2pp

100471 Expresses contern re raulting at site Job interview in 1974 'Gilbert Associates in Pottstown.PA remealed that proposed te ranked third or faveth or six site studies Also learned at site chosen due to ability to control public opinion LANDO.E Murphy 5 Parish 80/04/03 2pg

1250283 Responds to BAC317 congressional referral of ltr le utilitiume to accept loan of cryogenic processing sys from inserice facility rather than purging to atomosphere Purging losen for expedience ATON, H.R. Office of Nuclear Reactor Regulation 80/04/07 2pp

imancial intermation

140317 Forwards Annual Financial Rept 1979
ADLEY, E. J. Philadelphia Flectric Co. 80/04/08 ip

Q Inspection reports of Bulletins & correspondence

8004150139 Forwards IE Insp Repts 50 352/80-01 & 50-353/80-01 on 800109-11 & 16 No moncumpliance noted CARLEGER T Region i Philadelphia, Seactor Construction & Engineering Support Branch 00/02/12 dep

--8004150143 IE Insp Repts So 352/80-01? 50-353/80-01 on 800109-11 & 16
No noncompliance Noted Major Bleas Inspected GA program for
task or installing reactor pressure vessel internals &
control rod drive hydiaulir. * neutron monitoring sys
OAGL-L - MALTON, G - EBNETER, S - Region 1, Philadelphia, Office of
the Director - 80/02/07 - 4pp

8004090435 Forward: 1E Insp Repts 50-352/79-14 t 50-353/79-13 on 791220.21.27 t 28 No noncompliance noted CARLSON.R T Region i. Philadelphia. Reactor Construction t Engineering Support Branch 80/02/13 2pp

--8004090438 IE Insp Repts 50-352/79-14 / 50-353/79-13 on 791220,21,27 & 28 No noncompliance noted Major areas inspected GA program work activities & records & QC records of nonconformance reporting sys GAGE-L . CHAUDHARY-S Region i. Philadelphia, Office of the Director EBNETER-S Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/07 App

8004100099 Forwards IE insp Repts 50-352//9-13 & 50-353/79-12 on 791212-13 & 1/-21 No noncompliance noted CARLEGMAR T Region 1. Pasladelphia, Reactor Construction & Engineering Support Branch 80/02/13 2pp

--8004100112 IE Insp Repts 50-352/79-13 % 50-353/79-12 on 791212-13 & 17-21 No noncompliance noted Major areas inspected OA procedures documentation % work activities pertaining to storage handling % surveillance of safety-related cables EBNETER: S D Region I. Philadelphia. Reactor Construction & Engineering Support Bianch PAVLIND. R T. VARELA: A A Region I. Philadelphia. Office of the Director 80/02/07 App

8004090397 Advises that IE Bulietin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," was incorrectly sent for action No response required ORICE, B H. Region I. Philadelphia, Office of the Director 80/03/17 1p

8004i00421 Responds to IE Bulletin 80-03 Charcoal filters used will not be susceptible to charcoal leakage problems Filters from American Air have not been delivered to job site,but when received will verify screen attachment sparing KEMPER.J 5 Philadelphia Electric Co 80/03/17 ip

8004230059 Ack receipt or 800214 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-11 t 50-053/79-10 CARLSON R T Region 1, Philodelphia, Reactor Construction & Engineering Support Branch 80/03/20 1p

--8004P30971 Responds to MRC 800111 ltr re violations noted in IE Insp Repts 80-352/79-11 & 50-353/79-10 Corrective actions superintendents have been instructed to keep equipment KEMPER, J S Philadelphia Electric Co BO/02/14 3pp

--8004230079 Forwards IF Insp Repts 50-352/79-11 & 50-353/79-10 on /91015-31 & 1101-15 / notice of violation CARL80N.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/11 2pp

--8004230087 Notice of violation from insp on 791015-31 & 1101-15 * Region 1. Philadelphia, Office of the Director 79/12/27 2pp

--8004230114 IF Insp Repts 50-352/79-11 % 50-353/79-11 on 791015-31 & 1101-15 Noncompliance noted failure to protect safety-related item from constactivities when stored & to follow weld placedures requirements to prevent undercutting MATTIGALJ C Region 1. Philadelphia, Office of the Director MCGAUGHLY, R R Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/12/2/ 14pp

8004150293 Forwards IE Into Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/31 1p

1

- 8004090093 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER.8 H Region !, Philadelphia, Office of the Director 80/04/01 1p
- 8004110502 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004240337 Forwards IE Info Notice 80-14, "Safety Suggestions Flom Employees" No action required ORIER, B K Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180184 Forwards IE Circular 80~07, "Problems W/HPCI Turbine Oil 8ys " No written response required GRIER, B H. Region 1. Philadelphia, Office of the Director 80/04/03 1p
- 8004110063 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/04/04 |p
- 8004230399 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required GRIER.B H. Region 1. Philadelphia, Office of the Director 80/04/04 ip
- 8004180267 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/07 1p
- 8 Reportable occurrences, LERs & related correspondence
- 800430036B Forwards final deficiency rept re electrical raceway separation KEMPER, J. B. Philadelphia Electric Co. 80/04/24 ip
- --8004300376 Final deficiency rept re electrical raceway separation Project GC Insp E-2 O has been revised to include final acceptance insp to verify that separation requirements have been maintained & training classes held # Philadelphia Electric Co 80/04/30 4pp
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT t
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSS.D F Division of Project Management 80/02/05 7pp
- 8004020451 Forwards NRC 800128 & 0211 ltrs to GE re mods to BWR control rod drive sys & addl analyses of boiloff rates respectively Further info & guidance to be issued in NUREG-0619

 BAER,R L Light Water Reactors Branch 2 80/03/13 3pp
- 8004020154 Forwards additinfore shorthose sturgeon in Delaware River Concludes that continued operation of Unit 1, future operation of Unit 2 & const completion of Hope Creek units will not jeopardise existence of shorthose sturgeon REGAN, W H Assistant Director for Environmental Projects 80/03/14
- B004170250 Responds to NRC 800314 biological assessment of impact of continued operation or const of facilities Forwards biological opinion 8 summary of informal consultation w/NRC re Balem Unit 1 Shortnose sturgeon are not in juopardy LEITZELL.T L. Commerce. Dept of, National Marine Fisheries Service 80/04/15 20pp
- F Security, medical, emergency & file protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending CAO clearance under Federal Repts Act
 GRIMES, B.K Emergency Preparedness Task Forca 80/03/11 4pp

- G Adjudicatory correspondence
- 8004040207 Comments on irresponsible way intervenors are being treated Sites case of ruling to allow Salem Unit 1 to operate despite no evidence that licensee could protect endangered shorthose sturgeon COLEMAN.E G., COLEMAN.A C. Affiliation Unknown 80/03/05 3pp
- B004090192 Explains circumstances involving B00222 svc of BNWL draft rept is measurements of underground mining radon releases & NRC testimony of RM Wilde is same rept flissing Page 6 encl BORDENICK B M Heering Branch 4 80/03/05 4pp
- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICKLL V Office or the Executive Director for Operations 80/04/02 34pp
- 8004300585 Responds to 791018 petitions requesting that Commission issue show cause order to suspend or revoke OL for Galem 1 & CPs for Salem 2 & Hope Creek 1 & 2. & Stay issuance of OL for Salem 2 Request denied W/Director's decision DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 ip
- --8004300590 Director's decision under 100FR2 206 on E % A Coleman petition requesting that Commission Issue show cause order re facilities DL & CP issuances Request denied DENTON, H R Office of Nuclear Reactor Regulation 80/04/18 App
- --8004300598 Notice of issuance? availability of Director's decision under 10CFR2 206 on A > E Coleman petition requesting that Commission issue show cause order re facilities DL & CP issuances
 DENTON:H R Defice of Nuclear Reactor Regulation 80/04/18 2pp
- --8004300600 "Assessment or Impacts of Facilities on Shortnose Sturgeon, Acipenser Brevirostrum Lesuer" MARNIK.M T , WILSON, J H Office of Nuclear Reactor Regulation 80/03/31 ip
- H General correspondence
- 8004030123 Responds to 790816, its re plans to reopen TMI-1, nuclear plant const in NJ % nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from TMI DENTON, NR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restart of TMI-i.const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety
 FOSTER, K Affiliation Unknown 79/08/16 2pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004100152 Ack receipt of 800213 ltr informing NRC of steps taken to correct violations noted in If Insp Repts 50-354/79-09 & 50-355/79-08 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/12 1p
- --8004100157 Responds to NRC 800115 ltr re violations noted in IE Insp Repts 50-354/79-09 % 50-355/79-08 Corrective actions opened new pour cards, updated concrete repair filing sys & revised Tech Specs SMP/P-C-1 MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/02/13 2pp
- --8004100158 Forwards IC Insp Repts 50-354//9-07 & 50-355/79-08 on 791126-30 & notice of violation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/19 2pp
- --B004100160 Notice of violation from insp on 771126-30

 ** Region 1, Philadelphia, Office of the Director £0/01/11 1p
- --8004100168 IE Insp Repts 50-354/79-09 % 50-355/79-08 on 791126-30 Noncompliance noted failure to issue supplementary concrete pour card after signing off concrete placement checklist on pour w/deficient areas remaining to be repaired MCGAUCHY, R W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch VARELAIA A, BATEMAN, W. H. Region 1, Philadelphia, Office of the Director 80/01/11 10pp

- 8004090398 Advises that IE Bulletin 60-05, 'Vacuum Condition Resulting in Damage to Chemical 'ol Control Sys (CVCS) Holdup Tanks."

 was incorrectly sent for action to response required
 GRIER.B H. Region 1. Philadelphia. Office or the Director
 80/03/1/ Ip
- 8004250224 Responds to IF Sulletin 60-03 Completed investigation expected by 800501, pending response from Bechtel MARTIN.T.J. Public Service Electric? Gas Co. of New Jersey 80/03/21 1p
- 8004150299 Forwards it Into Notice 80-12, 'Instrument Failure Causes Opening of PORV / Block Valve ' No specific action or response necessary CRIER.B H Region 1, Philadelphia, Office of the Director 80/03/31 | Ip
- 8004090099 Forwards IE Circular 80~05, 'Emergency Dissel Generator Lubricating Gil Addition & Onsite Supply " No written response required ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/04/01 10
- B004110507 Forwards 18 Info Notice B0-13, "GE Type SBM Control Switches Defective CAM Follower," No orbitten response required GRIER.B H. Region I, Philadelphia, Office of the Director B0/04/02 Ip
- 800424034b Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ORIER, BH Region 1, Philadelphia. Office of the Director 80/04/02 19
- 8004180186 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine 013 Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/03 1p
- B004110071 Forwards IE Bulletin B0-07, "BWR Jet Pump Assembly Failure" No written response required GRIER:B H. Region i, Philadelphia, Office of the Director B0/04/04 ip
- 8004230455 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312.Type 304 Stainless Steel Pipe" Action required GRIER.B H. Region 1. Philadelphia. Office of the Director 80/04/04 | 1p
- 8004180276 Forwards IE Bulletin 60-08, "Exam of Containment Liner Penetiation Helds" Written response required ORIER.D H Region 1, Philadelphia. Office of the Director 80/04/07 (p
- S. Reportable occurrences, LERs & related correspondence
- 8004080109 Act receipt of 800303 interim deficiently rept re main steam pipe spools CARLSON.R T Region I. Philadelphia. Reactor Construction & Findingering Support Branch 80/03/12 1p
 - 14 Interim deficiency rept re main steam pipe spools GE issued tions to restore affected wall thickness to original equirement Final tept will be submitted by 800321 ubits Service Electric & Gas Co. of New Jersey 80/03/03

of 800314 Interim deficiency rept re discrepancy d wire 1. Philadelphia, Reactor Construction & annh 80/03/31 ip

> n procurement of sir of rewelding

MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/03/14 2pp

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

龖

8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing gouldance re methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp

- 8004020451 Forward: NRC 800128 % u211 ltrs to GE re mods to BWR control rod drive sys 2 add1 analyses of boiloff rates respectively Further info 2 guidance to be issued in NUREG-0619
 8AER, R.L. Light Water Reactors Brench 2 80/03/13 3pp
- 8004020154 Forwards addl info re shorthose sturgeon in Delaware River Concludes that continued operation of Unit 1, future operation of Unit 2 % const completion of Hope Creek units will not jeopardize existence of shorthose sturgeon REGAN, W H Assistant Director for Environmental Projects 80/03/14
- --8004020163 "Assessment of Impacts of Salem & Hope Creek Stations on Shortnose Sturgeon, Acipenser Brevirostrum Lesuer " MASNIX,M T Office of Nuclear Reactor Regulation 80/03/05
- 8004170250 Responds to NRC 800314 biological assessment of impact of continued operation or const of facilities Forwards biological opinion & summary of informal consultation w/NRC re Salem Unit 1 Shorthose sturgeon are not in jeopardy LEITZELL,T L. Commerce, Dept of, National Marine Fisheries Service 80/04/15 20pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by IRC 791226 ltm.has been postponed pending GAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004040207 Comments on irresponsible way intervenors are being treated Sites case of ruling to allow Salem Unit 1 to operate despite no evidence that licensee could protect endangered shortnose sturgeon COLEMANSE & Affiliation Unknown 80/09/05 3pp
- 8004090192 Explains circumstances involving 800222 svc of BNNL draft rept re measurements of underground mining radon releases & NRC testimony of RM Wilde re same rept Missing Page & encl
 BORDENICK, B M Hearing Branch 4 80/03/05 4pp
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GQSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8D04300589 Responds to 791018 petitions requesting that Commission issue show cause order to suspend or revoke OL for Balem 1 & CPs for Balem 2 & Hope Creek 1 & 2, & stay issuance of OL for Balem 2 Request denied W/Director's decision DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 ip
- --8004300590 Director's decision under 10CFR2 206 on A&E Colemen petition requesting that Commission issue show cause order re facilities OL & CP issuances Request denied DENTON.H R Office of Nuclear Reactor Regulation 80/04/18 6pp
- ---BODA30059B Notice of issuance & availability of Director's decision under 10CFR2 206 on ABE Coleman petition requesting that Commission issue show cause order re facilities OL & CP issuances

 DENTON, H R Office of Nuclear Reactor Regulation BO/04/18 2pp
- --8004300600 "Assessment of Impacts of Facilities on Shortnose Sturgeon, Acipenser Brevirostrum Lesuer " MASNIK, M T Office of Nuclear Reactor Regulation 80/03/31 1p
- H General correspondence
- 8004030123 Responds to 790816, itr we plans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resulved Provides info re plants in NJ No diseases resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030127 Opposes restart of TMI-1: const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety
 FOSTER, K. Affiliation Unknown 79/08/16 2pp

Q Inspection reports, IE Bulletins & correspondence

- 8004100152 Ack receipt of 800213 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/79-09 t 50-355/79-08 CARLSON.R T Region 1. Philadelphia. Reactor Construction t Engineering Support Branch 80/03/12 1p
- --8004100157 Responds to NRC 800115 ltr re violations noted in IE Insp Repts 50-354/79-09 & 50-355/79-08 Corrective actions opened new pour cards, updated concrete repair filing sys & revised Tech Specs SWP/P-C-1 MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/02/13 2pp
- --8004100158 Forwards IE Insp Repts 50-354//9-09 & 50-355/79-08 on 791126-30 & notice of violation CARLEON.R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/15 2pp
- --8004100160 Natice of violation from insp on 791126-30 * Region 1, Philadelphia, Office of the Director 80/01/11 1p
- --B004100168 IE Insp Repts 50-354/79-09 & 50-355/79-08 on 791126-30
 Noncompliance noted failure to issue supplementary concrete
 pour card after signing off concrete placement checklist on
 pour w/deficient areas remaining to be repaired
 MCGAUGHY,R W Region 1, Philadelphia, Reactor Construction &
 Engineering Support Branch VARELA:A A. BATEMAN,W H Region 1.
 Philadelphia, Office of the Director B0/01/11 10pp
- 8004090398 Advises that IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks," was incorrectly sent for action No response required QRIER, B H Region 1, Philadelphia, Office of the Director 80/03/17 10
- 8004250224 Responds to IE Bulletin 80-03 Completed investigation expected by 800501, pending response from Bechtel MARTIN,T J Public Service Electric & Gas Co of New Jersey 80/03/21 ip
- 8004150297 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ORIER.8 H Region 1, Philadelphia, Office of the Director 80/03/31 ip
- B004090099 Forwards IE Circular B0-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B. H Region 1, Philadelphia, Office of the Director B0/04/01 1p
- 8004110507 Forwards IE Info Notice 80-13, "OE Type 8BM Control Switches Defective CAM Followers" No written response required ORIER.8 H Region 1, Philadelphia, Office of the Director 80/04/02 lp
- 8004240346 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required ORIER, B. H. Region 1. Philadelphia. Office of the Director 80/04/02 19
- 8004180186 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Gii Sys " No written response required ORIER, B H Region i. Philadelphia. Office of the Director 80/04/03 ip
- 8004i1007i Forwards IE Bullstin 80-07, "BWR Jet Pump Assembly Failure " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/04/04 ip
- 8004230455 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-3i2, Type 304 Stainless Steel Pipe" Action required, ORIER, B H Region I, Philadelphia, Office of the Director 80/04/04 1p
- 8004180276 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response vequired ORIER,B H Region 1. Philadelphia. Office of the Director 80/04/07 ip

- S. Reportable occurrences, LERs & related correspondence
- B004090314 Ack receipt of ±00211 interim deficiency rept advising that investigation of suiface indication was not yet completed Complete rept should be submitted when required info is available CARLSON R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/06 by
- CONTOCOURT 1 A CONTOC
- --8004090317 Interim deficiency rept is surface indication on reactor pressure vessel Grinding rework to thivestigate indication will commence 800215 % be completed by 800228 MARTIN.T J. Public Service Electric % Gas Co. of New Jersey 80/02/11 2pp
- 8004080109 Ack receipt of 800303 interim deficiency rept re main steam pipe spools CARLSON:R T Region t. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/12 1p
- --8004080114 Interim deficiency rept is main steam pipe spools GE issued instructions to restore affected wall thickness to original GE spoc requirement Final rept will be submitted by 800321 MARTIN Public Service Electric & Gas Co. of New Jersey 80/03/03
- 8004280171 Ack receipt or 800314 Interim deficiency tept re discrepancy in procurement of weld wire CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/31 ip
- --8004280174 Interim deficiency rept re discrepancy in procurement of weld wire Pittsburgh Des Moines has completed repair of stiffeners where coupons were removed & removal & rewelding of seams of heat I D AB913 MARTIN-T J Public Service Electric ? Gas Co of New Jersey B0/03/14 2pe
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR

 G Inspection reports. IF Bulletins & correspondence
- 8004110259 Forwards IE Insp Repts 50-151/80-01 & 50-356/80-01 on 800204-06 No noncompliance nated DAVIS, A B Region J. Chicago. Fuel Facility & Materials Bafety Branch 80/03/03 2pp
- --8004110274 IE Insp Repts 50-151/80-01 ½ 50-354/80-01 on 800204-04 No noncompliance noted Major areas inspected emergency planning including support pracedures personnel interviews, review or training ½ drills ½ insp of equipment ESSIO, T H NRC Regional Offices OREER, R J Region 3, Chicago, Office of the Director 80/02/22 4pp
- DOCKET 50-358 WILLIAM H 71MMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREG-0588, "Interim Staff Pusition on Environ Gualification of Safety-Related Electrical Equipment "Requests review of equipment qualification socumentation to identify degree of compliance ROSS, DF Division of Project Management 80/02/21 3pp
- 8004020466 Notification of 800376 & 2/ meeting w/representatives from Mark II owners group in San Jose, CA to discuss Mark II Creace Test Program, 4T c/o tests & foreign tests ELTANILA.F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II owners group, NRC consultants & QE in San Jose,CA to discuss Mark II Creare test program,4T C/O & foreign tests Topics are proprietary Agenda enci ELTAWILA.F Containment Systems Branch 80/03/10 12pp
- BOD4040474 Summary of BOD227 meeting w/Mark II owners group re status of several long-term program tasks, including Tasks A 17.
 A 16 & task related to utilization of foreign test data ELTAWILA.F Containment Bystems Branch BO/03/18 104pp

- 8004086246 Requests revision of std form of notice for order estending const completion date for include addl statements re-envisor considerations Revision, should be enfective as of facility CHRISTENBURY, E. Hearings Division EO/03/27 1p
- 80042500% Notification or 8005%-2 meeting w/util in Moscow.OH to discuss forecast panel site visit PELTIER, I.A. Light Water Reactors Branch 1 80/04/08 4pp
- 800415030) Responds to NRC 800303 ltr re environ qualification of Class IE instrumentation belectrical equipment Completion of documentation review expected by 800615 Requests info on mods to NUREG-0588 resulting from Comment process FLYNNUJ D Cincinnati Gas & Electric Co. 80/04/10 ip
- 8004300064 Summary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of NRC concerns on data from Creare tasts 5 foreign full-scale test programs 5 relationships w/ Mark II designs ELTAWILAF Containment Systems Branch 80/04/14 22pp
- F Security, medical, emergency * fits protection plans
- BO040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791826 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B.K. Energency Preparedness Task Force 80/03/11 App
- 8004280317 Forwards Revision 15 to "Fire Protection Evaluation Rept." submitted as responses to questions BOROMANN, E.A. Cincinnati Gas & Electric Co. 80/04/25 ip
- --8004280322 "Fire Protection Evaluation Rept," Revision 15 * Cincinnati Gas & Electric Co 80/04/30 7pp
- G Adjudicatory correspondence
- 800403033B Response to State of KY 800304 petition to intervene as interested state if participation granted re emergency planning. State of KY must enter proceeding in present stage of development Certificate of Evc encl
 CONNER, T B . WETTERHARM, M J Cincinnati Gas & Electric Co
 CONNER, T B Conner. Moore & Corber 80/03/19 4pp
- B00410046B Petition for leave to intervene by Zimmer Area Citizens & Zimmer Area Citizens of MY Peritioner is concerned about proximity of elementary & secondary schools to nuclear power plant Certificate of Svc encl DENNISON A B Affiliation Unknown B0703/24 9pp
- B004070182 Response in support of State of KY participation as interested state State emergency preparedness plan in in safe operation of facility Recommends admission at present stage of development 80/03/26 4pp
- B0040B0592 Memorandum / order admitting State of KY as interested state, subj to taking proceeding as found in present stage Order taken w/o GO Bright participation BECHHOEFER.C Atomic Safety and Licensing Board Panel 80/04/01
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological energency planning & preparedness, distributed as Board notification COSSICK, L V Office or the Executive Director for Operations 80/04/02 34pp
- 8004220156 Requests denial of Zimmer Area Citizens & Zimmer Area Citizens in KY petitions to intervene as interested person Petitioner has failed to demonstrate good cause for late filling Certificate of Svc encl CONNER.TB Cincinnati Gas & Electric Co CONNER.TB Conner, Moore & Corber 60/04/07 28pp
- 8004180111 Responds to 800321 inquiry, on behalf of Miami Valley Power Projective cost of subpoending SH Handver to testify at OL proceedings NRC regulations do not permit NRC personnel to be subpoended for NRC proceedings BARTH.C A Rearing Branch 3 80/04/10 2pp
- --8004180208 Inquires on behalf of Miami Valley Power Project, re cost of subpoending SH Handwer to testify at OL proceedings on status of info available from Mark 11 owners group GILLMAN, D. Affiliation Uninown 80/03/21 1p

- 8004210445 Response recommending that Zimmer Area Citizens B00321 petition to intervene be granted, provided that contentions in emergency planning? Inadiological monitoring be filed in 20 days Centificate or Sec atcl.

 BARTH/C A. Hearing Branch 3 80/04/10 9pp
- H General correspondence
- 7908150559 Discusses 790530 ltr suggesting training of licensed operating personnel in handling casualty conditions & emergency situations Outlines possible future NRC role reconducting & observing in-plant drills MATTSON, R Division of Systems Bafety 79/07/17 2pp
- --7908150564 Submits suggestions to need for more operator training in handling casualty conditions.in-plant casualty training during refueling, butilization of emergency teams during extreme casualty conditions ADAMS.J E Arfiliation Uninoum 79/05/30 App
- 8004090157 Submits inquiry re see requirements if subpoenaed to testify at OL hearings on info available from Mark [I owners group GILLMAN, D. Miami Valley Power Project 80/03/21 ip
- I Financial information
- 8004040340 Forwards Annual Financial Rept 1979 for util.Columbus & Southern OH Electric Co / Dayton Power & Light Co BOROMANN.E A Cincinnati Gas & Electric Co 80/04/01 1p
- ~~8004040343 Annual Financial Rept 1979 * Cincinnati Gas & Flectic Co 8 80/01/23 32pp
- ~-8004040350 Annual Financial Rept 1979
 4 Columbus & Southern Ohio Electric Co 80/02/07 36pp
- --8004040355 Annual Financial Rept 1979 * Dayton Power & Light Co 80/02/06 25pp
- Q Inspection reports, 1E Bulletins & correspondence
- 8004210134 Forwards IC Inso Rept 50-358/80-03 on 800122-24 & notice of vinlation violation FIGRELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/29 2pp
- --8004210137 Natice of violation from insp on 800122-29 * Region 3. Chicago, Office of the Director 80/ B0/02/21 2pp
- --8004210142 IE Insp Rept 50-358/80-03 on 800127-24 Noncompliance noted failure to comply w/design requirements in approved test procedures E, GALLAGHER, EJ, KNOP, RC Region 3, Chicago, Office irector 80/02/21 App of the Director
- 8004300014 Forwards IE Insp Rept 50-358/79-36 on 791114-15,800128-31 & 0201 No moncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/29 2pp
- --8004300022 IE Insp Rept 50-358/79-36 on 791114-15,800128-31 & 0201
 No noncompliance noted Major areas inspected preoperational
 test program including test procedure review. license audits,
 unresolved items & fuel insp
 8TREETER JF, MAURA,F Region 3, Chicago, Office of the Director
 80/02/22 6pp
- 8004100123 Forwards If Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response KEPPLER, J G Region S, Chicago, Office of the Director 80/03/07
- 8004160009 Responds to IF Builetin 80-03 re loss of charcoal from std adsorber cells Plant has no charcoal adsorber filter beds supplied by Flanders Adsorbers supplied by CVI Penwalt Corp & American Air Filter BORGMANN.E A Cincinnati Gas & Electric Co 80/03/21 2pp
- 8004150163 Forwards IC Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/31

- 8004080694 Forwards JE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Dosite Supply " No written response required KEPPLER,J G Region 3, Chicago, Office of the Director 80/04/01
- 8004150024 Forwards IE Info Notice BO-13. "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER.J & Region 3. Chicago. Office of the Director 80/04/02
- 8004180037 Forwards attachments to IC Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J. G. Region 3, Chicago: Office of the Director 80/04/02
- 8004220113 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/02
- B004220344 Forwards IE Circulai 80-07, "Problems WHPCI Turbine Dil Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/03
- B004110032 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure" No written response required KEPPLER,J G Region 3, Chicago, Office of the Director B0/04/07
- 8004230207 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/07
- 8004220108 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/04/09 10
- 8004300592 Ack receipt of 800318 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-358/79-37 FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/11 ip
- --8004300404 Responds to NRC 800215 ltr re violations noted in IE Insp Rept 50-358/79-37 Corrective actions pipe support insp program revised & generation const dept requested to prepare procedure for preparation distribution & revision of dept BORGMANN.E A Cincinnati Gas & Electric Co 80/03/18 lp
- S Reportable occurrences, LERs & related correspondence
- 8004180215 Ack receipt of 800314 interim deficiency rept re Anchor/ Darling gate valves NRC will review matter upon roceipt of final rept FJORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/01 ip
- U Congressional/Executive Correspondence
- 8004140252 Responds to 800207 itr re constituent group concerns about facility Util required to comply w/financial protection & indemnity provisions of Price-Anderson Act & 100FR140 prior to OL issuance W/FES. Section 8. re need for power DIRCKS, W J Office of the Executive Director for Operations 80/03/29 2pp
- --8004140262 Requests info on behalf of constituent group re possible radiation exposure caused by accident similar to TMI-2 event Lists areas of concern HOPKINB.L J House of Rep 80/02/07 ip
- DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDS8.0 F Division of Project Management 80/02/05 7pp

- 8004040017 Submifs add) guidance to NURLG-0588. 'Interim Staff Position on Environ Qualification of Barety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree or compliance ROSS.D F Division of Project Management 80/02/21 Spp
- 800423005B Requests into ie auxiliary feedwater sys per Bulletins & Orders Task Foico review of 1MI-2 accident Info should be provided as amend to application Submittil schedule should include NRC approval priot to issuance of OL W/enci ROSS.D F Division of Project Management 80/03/10 53pp
- 8004110028 Forwards requests for addl info re FSAR review Addl open item concerns approval or analysis methods used for loss of flow transients depending on approval of CENBR code described in CENBPD-177-P BAER.R L Light Water Reactors Branch 2 80/03/20 15pp
- 8004030181 Forwards info requested by NRC 800117 felcon re confirmatory analysis of shutdown cooling line Index to piping layout, isometric sheet 8 pipe support drawings encl HAYNES.J G Southern California Edison Co 80/04/01 16pp
- --800403018& "Guality Class 1 3 II.ASME Code.Section III Design Spec for RCS Piping Components, Sys 1201 'Thirty-two oversize drawings oncl # Bechtel Corp 79/05/10 400pp
- 8004290133 Summary of B00305-07 meetings w/Friends of the Earth in San Biego,CA re seismology & emergency preparedness concerns ROOD:H Light Water Reactors Branch 3 80/04/10 App
- B004220570 Notifies that difficulties w/proposed memorandum of agreement re transmission project have been resolved to satisfaction of CA OFC of Historic Preservation NRC should forward agreement to advisory council for action MELLON, K. California, State of 80/04/15 1p.
- 8004290640 Forwards data on which review of seismic reflection profiles within 25 km San Chofre will be based Response to NRC 800320 request will be provided by approx 800425 BASKIN.K P Southern California Edison Co 80/04/10 App
- B004300011 Forwards LANDSAT photographs of southern CA to facilitate Geosciences Branch review Photographs will be referenced in FBAR. Section 1 9
 BASKIN, P Southern California Edison Co 80/04/18 1p
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8004300375 Responds to NRC 800317 request forwards revised tables from DES re-operation of facility including recorded data from 1976-79 & projections for 1980-85 Tables show production costs, peak demand.energy requirements & Peserve margins BASKIN.K P Southern California Edison Co
- Γ Becurity, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Foice BO/03/11 4pp
- 8004080515 Forwards review summary of fire protection covering Items 3 1 6, foam suppression sys. 3 1 7, gas suppression sys. 3 2 3, turbine bldg structure Items 3 1 1,3 1 2,3 1 5 are partially completed % summary will be provided accordingly HALL, R.E. Broothaven National Laboratory 80/03/31 16pp
- 8004080375 Notifies that combined response to NRC 791211 & 800324 ltrs re safeguards contingency plan will be sent by 800421 HAYNES.J Q Bouthern California Edison Co 80/04/01 1p
- 8004230320 Forwards revision to BNL 800331 ltr re ltems 3 1 1(5),3 1 2 (b),3 1 5(d),3 1 6,3 1 7(a),3 1 7(b),3 1 15(b) 2 3 2 3 for fire protection review HALL.R E Brookhoven National Laboratory 80/04/14 14pp
- 8004300363 Notifies NRC that util requires add1 time to revise safeguards contingency plan as described in NRC 800324 1tr Revised safeguards plan utll be forwarded by 800512 BASKIN.K P Bouthern California Edison Ca 80/04/21 1p

G Adjudicatory correspondence

- 30041004/7 Stipulation extending time for answers of intervenor Friends of the Earth third set or interrogatories Centificate of Skc enci PlOOTT, D.R. Southern California Edison Co. PIGOTT, D.R. Chickering & Gregory 80/03/05 4pp
- 8004100537 Response to third set of interrogatories inloudes info re persons answering interrogatories b time ported when applicant decided to construct nuclear plant Certificate of Sec & DR Pigott verification enc!
 Pigott.D R Southern California Edison Co Pigott.D R Chickering & Gregory 80/03/18 25pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological energency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp

H General correspondence

- 8004150188 Responds to 800221 ltr opposing issuance of OL for facilities Public hearings in vicinity of plants will probably be held neit year HAMCHETI.J G Region 5. San Francisco, Office of the Director 80/03/11 ip
- --B004150195 Requests that NRC not issue OL to util for proposed addl generating stations Continued operation of present facility represents immediate hazard to life & property All nuclear plants leak radiation // should be shut down SVESLOSXY.F Affiliation Unknown 80/02/21 3pp
- 8004020462 Forwerds Commission statement of policy on conduct of adjudicatory proceedings, published in 791109 FR W/o encl CHANDLER, L. J. Hearing Branch 1 BO/03/17 ip
- 9 Inspection reports. IE Bulletins % correspondence
- 8004210181 Forwards IE Insp Repts 50-361/80-02 & 50-362/80-01 on 800103-04 & 21-28 No noncompliance noted SPENCER, C S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/03/ii 2pp
- --8004210186 IE Insp Rept 50-361/80-02 2 50-362/80-01 on 800103-04 & 21-28 No noncompliance noted Major areas inspected const activities; including reactor pressure vessel 2 internals protection deficiency followups & fire in fuel pact area MAYNES, R C Region 5. San Francisco, Reactor Construction & Engineering Support Branch PATE, R J Region 5, San Francisco, Office of the Director 80/03/11 4pp
- 8004210412 Forwards IE lnsp Repts 50-361/79-32 % 50-362/79-29 on 791201-31 No noncompliance noted SPENCERG S Region 5. Sam Francisco, Reactor Construction & Engineering Support Branch 80/03/11 2pp
- --80042104)7 IE, Insp Repts 50-361/79-32 & 50-362/79-29 on 791201-31 No noncompliance noted Major areas inspected comst activities. including reactor pressure vessel & internals protection PATE.R J Region 5. San Francisco. Office of the Director HAYNEGS RC Region 5. San Francisco. Reactor Construction & Engineering Support Bianch 80/03/10 5pp
- 3004020045 Act receipt of 800304 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-361/79-29 & 50-362/79-27 SPENCER.G S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/03/17 ip
- --8004020049 Responds to NRC 800204 itr re violations noted in IE Insp Repts 50-361/79-29 & 50-362/79-27 Corrective actions cable will be replaced Open parts capped w/appropriate cover PAPAY,L T Southern California Edison Cq 80/03/04 Spp
- --8004020054 Forwards IE Insp Repts 50~361/79-29 % 50-362/79-27 on 791113-16 % 1211-14 % notice of violation SPENCER 0 S Region 5. San Francisco. Office of the Director 80/02/04 2pp
- --8004020058 Notice of violation from insp on 791113-16 \$ 1211-14 * Region 5. San Francisco. Office of the Director 80/02/04 2pp

- --80040200&2 IE Insp Rept 50-361//9-29 & 50-362/79-27 on 791113-16 & 1211-14 Noncompliance noted failure to use cleanliness caps on instrumentation lines & to control unused E7018 weld hods
 DUDDS: R T Region 5. San Francisco. Reactor Construction &
 - DODDS.R T Hegion 5. San Francisco. Reactor Construction & Engineering Support Branch HERNANDEZ.G , ELIN.J Q Region 5. San Francisco. Office of the Director 80/02/04 9pp
- B004280072 Forwards IE Insp Repts 50-361/80-04 % 50-362/80-02 on B00219-29 No noncompliance noted SPENCER OS Region 5. San Francisco, Peactor Construction & Engineering Support Branch B0/03/20 2pp
- --8004280095 IE insp Repts 50-361/80-04 % 50-362/80-02 on 800219-29 No noncompliance noted Major aleas inspected const activities, including reactol pressure vessel & internals protection, piping storage % previous item re corrective actions HAYNES,R C. Region 5. San Francisco. Reactor Construction & Engineering Support Branch PATE,R J. Region 5. San Francisco, Office of the Director 80/03/17 App
- 8004150214 Forwards IE Into Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELMENIR H Region 5, San Francisco, Office of the Director 80/03/31 1p
- 8004100107 Forwards IE Corculat 80-05, "Emergency Diesel Generator Lubricating Oil Addition A Onsite Supply " No written response required ENOELMEN, R H Region 5, San Francisco, Office of the Director 80/04/01 1p
- 8004110114 Forwards IE Info Notice 80-13, "GE Type GBM Control Switches Defective CAM Followers" No specific action or response required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/02 ip
- 8004220048 Forwards is Into Notice 80-14, "Safety Suggestions From Enployees" No action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02 1p
- B004:B0135 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Dil Sys " No written response required ENGELKEAR H Region 5, San Francisco. Office of the Director 80/04/03 1p
- 8004230368 Forwards IE Bulletin 79-03A, "Langitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required ENGELKEN, R H. Region 5. San Francisco, Office of the Director 80/04/04 to
- 8004220198 Forwards IE Bulietin 80-08, "Exam of Containment Liner Penetration Welds" Written response required ENGELKEN.R H Region 5. Ban Francisco. Office of the Director 80/04/07 ip
- R Periodic operating reports & related correspondence
- 800407033B Forwards info re occupational exposure & environ surveillance programs for 1979
 OTTOSON.H L Southern California Edison Co 80/03/31 3pp
- --8004070345 "1979 Annual Operating Rept.Vol 1.Oceanographic Data Rept "
 * Brown & Caldwell 80/03/31 400pp
- --8004070348 "1979 Annual Operating Rept, Vol 2.Biological Data Rept Intertidal Infauna, Subtidal Infaunal, Kelp, Ichthyoplankton " * Marine Biological Consultants, Inc., 80/03/31 300pp
- --8004070392 "1979 Annual Operating Rept.Vol 3:Biological Data Rept Flankton, Hard Benthos Rocky Intertidal " * Lockheed Center for Marine Research B0/03/31 500pp
- --B004070357 "1979 Annual Operating Rept. Vol 4.Biological Data Rept. Nekton " * Brown & Caldwell B0/03/31 250pp
- 8004140161 Forwards "Annual Operating Rept. 1979, " Vols 1-4 H/o encl DICTCH.R South Carolina Electric & Gas Co 80/04/04 2pp

ortable accurrences. LERs & related correspondence

0492 Ack receipt of 800310 interim deficiency rept re measuring & incal rocalibrat vendor facilities Anticipates receipt LKEN. R H Region 5, San Francisco, Office of the Director 1p

100500 Interim deficiency rept re measuring & test equipment calibr at vendor facilities final cept will be submitted

Southern California Edison Co 80/03/10 ip

0538 Forwards amended final deficiency tept re pipe support gn, updating 790706 rept Y.L. T Southern California Edison Co 80/04/07 lp.

1505-16 Amended final deficiency rept re design deficiencies related certain safety-related pipe supports Updates 790706 rept including six addl deficiencies Program initiated to view total design of sys prior to change

E TIME COLLEGE STATION OF SAC-OF lication/construction stage documents & correspondence

0031 Advises of issuance of NUREG-0588, "Interim Staff Position avir on Qualification of Safety-Related Electrical pmeat." providing guidance re methods for compliance , D F. Division of Project Management 80/02/05 7pp

0017 Submits addl guidance to NUREO-0588. "Interim Staff Position nvirum Qualification of Safety-Related Electrical pment." Requests review of equipment qualification ment attion to identify degree of compliance, D F. Division of Project Management 80/02/21 3pp

OOSB Requests info re auxiliary feedwater sys per Bulletins & rs Task Force review of TMI-2 accident Info should be ided as amend to application Submittal schedule should ude NRC approval prior to issuence of CL Wencl .D F. Division of Project Management 80/03/10 53pp

0028 Forwards requests for add1 info re FBAR review Add1 open CORE erns approval of analysis methods used for loss of transients, depending on approval of CENBR code ribed in CENPD-177-P
R L. Light Water Reactors Branch 2 80/03/20 15pp

0181 Forwards info requested by NRC 800117 telcon re confirmatory ysis of shutdown cooling line Index to piping layout, etric sheat & pipe support drawings encl ES. J. O Southern California Edison Co 80/04/01 16pp

OBO 1 84 "Quality Class I & II, ABME Code, Section III Design Spec for S Piping Components, Sys 1201 " Thirty-two oversits awings encl Bechtel Corp. 79/05/10 400pp

O133 Summary of 800305-07 meetings w/Friends of the Earth in San o, CA re saismology & emergency preparedness concerns , H Light Water Reactors Branch 3 80/04/10 app

0570 Modifies that difficulties w/proposed memorandum of 0570 Notifies that difficulties w/proposed memorandum of memors to the transmission project have been resolved to state tion of CA Ofc of Historic Preservation NRC should and agreement to advisory council for action ON. K. California, Btate of 80/04/15 ip

0640 Forwards data on which review of seismic reflection profiles in 25 km San Unofre will be based Response to NRC 20 request will be provided by approx 800425 IN. K. P. Southern California Edison Co. 80/04/18 App

ODII Forwards LANDSAT photographs of southern CA to facilitate clandes Branch review Photographs will be referenced in the ction 1 B N.K.P Southern California Edison Co 80/04/18 1p

Draft/Final Environmental Statements, suppls & correspondence

0375 Responds to NRC 800317 request forwards revised tables from operation of facility including recorded data from operations for 1980-85 Tables show production of projections for 1980-85 Tables show production speak demand energy requirements to reserve margins speak demand energy requirements to reserve margins S. P. Bouthern California Edison Co. 80/04/11 6pp IN. K. P.

F. Security, medical, emergency * rise protection plans

B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC /91226 lfr.has been postponed pending GAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp

8004080515 Forwards review summary or fine protection covering litems 3 1 6, feam suppression sys.3 1 7, gas suppression sys & 3 2 3, turbine bldg structure litems 3 1 1,3 1 2,3 1 5 are partially completed & summary will be provided accordingly HALL.R E Brookhaven National Laboratory 80/03/31 16pp

B0040B0395 Notifies that combined response to NRC 791211 % B00324 ltrs re-safeguards contingency plan will be sent by B00421 HAYNES, J G Bouthern California Edison Co B0/04/01 1p

8004230320 Forwards revision to 3NL 800331 ltm re Items 3 1 1(5),3 1 2 (b),3 1 5(b),3 1 6,3 1 /(a),3 1 7(b),3 1 15(b) & 3 2 3 for fire protection review HALL,R E Brookhaven National Laboratory 80/04/16 16pp

8004300363 Notifies NRC that util requires additime to revise safeguards contingency plan as described in NRC 800324 ltr Revised safeguards plan will be forwarded by 800512 BASKIN K P Southern California Edison Co 80/04/21 lp

G Adjudicatory correspondence

8004100477 Stipulation extending time for answers of intervenor Friends of the Earth third set of intervalues Certificate of Syc encl PIGOTT, D.R. Southern California Edison Co. PIGOTT, D.R. Chickering PIGOTT, D.R. Southern & Gregory BO/03/05

3004100537 Response to third set of interrogatories Inloudes info repersons answering interrogatories 2 time period when applicant decided to construct nuclear plant Certificate of Svc & DR Pigott verification encl
PIGOTT.D R Southern California Edison Co PIGOTT.D R Chickering & Gregory 80/03/18 25pp

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOBSICKL V Office of the Executive Director for Operations 80/04/02 34pp

H General correspondence

800415018B Responds to 800221 Iti opposing issuance of OL for facilities Public hearings in vicinity of plants will probably be held next year HANCHETI, J G Region 3, San Francisco, Office of the Director 80/03/11 1p

--B004i50i95 Requests that NRC not issue CL to util for proposed addl generating stations Continued operation of present facility represents immediate hazard to lire & property All nuclear plants leak radiation & should be shut down GVESLOSKY, F Affiliation Unknown 80/02/21 3pp

8004020462 Forwards Commission statement of policy on conduct of adjudicatory proceedings, published in 791109 FR W/o encl CHANDLER, L. J. Hearing Branch 1 80/03/17 1p

Q Inspection reports, IE Bulletins & correspondence

8004210161 Forwards JE lnsp Repts 50-361/80-02 & 50-362/80-01 on 800103-04 & 21-28 No noncompliance noted SPENCER,0 S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/03/11 2pp

--8004210186 IE Insp Rept 50-361/80-02 & 50-362/80-01 on 800103-04 & 21-28 No noncompliance noted Major areas inspected const activities, including reactor pressure vessel & internals protection, deficiency followups & fire in fuel pool area HANNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch PATE, R J Region 5, San Francisco, Office of the Director 80/03/11 App

8004210412 Forwards IF Inso Repts 50-361/79-32 % 50-362/79-29 on 791201-31 No noncompliance noted 8PENCER, 6 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/03/11 2pp

- -8604210117 IE. In ap Repres 50-351777 32 to 50-352777-29 on 791201-31 No noncompliance model Market areas inspected constructies, including reactor prosents esset internals protection PATE, R. J. Region 5, han Francisco, Office of the Director HAYMES, R. C. Region 5, han Francisco, Reactor Construction to Engineering Support Branch 80/03/10 Spp
- 8904020045 Act receipt or Condustrian informing NRC of steps taken to correct violations acts in IE linap Repts 50-361/79-29 t 50-362/79-27 SpenCeRo S Region 5. San Francisco Reactor Construction & Engineering Support Branch 60 Carls 1p

- --8004020049 Responds to NRC 305104 ltm is violations noted in 16 lnsp Repts 50-361/77-29 / 50-361/79-27 Corrective actions cable will be replaced Open parts capped s/appropriate cover PAPAY:L T Southern (alifornia Edison Co 80/03/04
- --B004020054 Jaruards IF Insp Repts 50-361//9-29 / 50-362//9-27 on 791113-16 / 1211-14 / native of violation SPENCER.0 S Region 5. San Francisco, Office of the Director B0/02/04 | 2pp
- 8004020058 Natice of violation from imap on 791113-16 & 1211-14

 * Region 5 San francisco, Office of the Director 80/02/04
- --8004020042 IF Into Rept 50-361//9-27 5 50-362//9-27 on 791113-16 & 1211-14 Noncompliance noted rations to use cleanliness caps on instrumentation lines & to control unused E7098 weld POODDS,R T. Region 5. San Francisco. Reactor Construction b Engineering Support Branch MERNANDEZ,G . ELIN.J D. Region Francisco, Office of the Director 80/02/04 9pp Region 5. San
- 8004280092 Forwards IF Insp Repts 50-361/80-04 % 50-362/80-02 on 800219-29 No honcompliance nuted SPENCER, G S Region 5 San Francisco, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004280075 IE Insp Repts 50-361/80-04 / 50-362/80-02 on 800219-29 No noncompliance noted Major aleas inspected constlactivities, including reactor pressure vessel // internals protection, piping storage // previous item re corrective actions HAVPES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch PATE, R J Region 5, San Francisco, Office of the Director 80/03/17 App
- 8004150214 Forwards If Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELERIA H. Region 5, San Francisco Office of the Biroctor 80/03/31 Ip
- 8004100107 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required ENSELERIR H Region 5, San Francisco, Office of the Director 80/04/01 Ip
- B004110114 Forwards IC Into Notice 80-13, "GE Type 98M Control Switches Defective CAM Followers 'No specific action or response required ENGELMEN R H Region 5. San Francisco. Office of the Director
- 800422004B Forwards 1E info Notice 80-14. "Bafety Suggestions From EMPloyees "No action required
 EMOELMEN, R H Region 5. San Francisco, Office of the Director
 80/04/02 1p
- 8004180135 Forwards IE Circular 80-07. 'Problems N/HPCI Turbine Oil Sys " No written response required EMOELKEN.R H Region 5. San Francisco, Office of the Director BO/04/03 !p
- 8004230368 Forwards IE Bulletin 79-034, "Longitudinal Weld Defects in ASME SA-312-Type 304 Stainless Steel Pipe " Action required ENGELKEN R Region 5. San Francisco, Office of the Director 80/04/04 1p
- 8004220198 Forwards IE Bulletin 80-08 "Exam of Containment Liner Penetration Welds" Written response required ENGELKERIR H Region 5. San Francisco. Office of the Director 80/04/07 ip

- A Periodic operating reports / related correspondence
- 8004070338 Forwards info to occupational exposure & environ surveillance programs for 1979
 OTTOSON.H L. Southern California Edison Co. 80/03/31. Jpp
- --B004070345 "1979 Annual Operating Rept.Vol 1.Oceanographic Data Rept "
 4 Brown & Caldwell 80/03/31 400pp
- --8004070352 "1979 Annual Operating Rept. Vol 3. Biological Data Rept Plankton Hard Benthos Rocky Intertidal " * Lockheed Cente: for Marine Research 80/03/31 500pp
- --8004070357 '1979 Annual Operating Rept. Vol 4, Biological Data Rept
 - Brown + Caldwell 80/03/31 250pp
- 8004140161 Forwards "Annual Operating Rept.1979," Vols 1-4 W/o encl DIETCH.R South Carolino Electric ' Gas Co 80/04/04 2pp
- S Reportable occurrences (ERs) related correspondence
- 8004100492 Ack receipt of 800310 interim deficiency rept re measuring & equipment recalibi at vendor facilities Anticipates receipt of final rept by 800530 ENGELKEILR H Region 5. San Francisco, Office of the Director 80/03/15 1p
- --8004(00500 Interim deficiency rept is measuring & test equipment recalibr at vendor facilities Final rept will be submitted by 800530 MINU-D E Southern California Edison Co 80/03/10 1p
- 8004150538 Forwards amended tinal deficiency rept re pipe support design, updating 790706 tept PAPAY, L.T. Southern Calitornia Edison Co. 80/04/07. 1p
- --8004150546 Amended final deficiency rept re design deficiencies related to certain safety-related pipe supports Updates 790706 rept by including six addi deficiencies Program initiated to review total design of sys prior to changeover to startup * Southern California Edison Co 80/04/07 4pp
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- GO04040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr. has been postponed pending QAO clearance under Federal Repts Act
 QRIMES, B K Emergency Preparedness Task Force 80/03/11 App
- H General correspondence
- 8004030123 Responds to 770816. Itr re plans to reopen TMI-1, nuclear plant const in NJ & nuclear accidents Plant will not reopen until safety-related issues are resolved Provides info re plants in NJ No diseases resulted from TMI DENTON, HR Office of Nuclear Reactor Regulation 80/03/03 2pp
- --8004030129 Opposes restart of TMI-1, const of nuclear plants in NJ & nuclear accidents due to health hazards & risks to public safety FOSTER, K. Affiliation Unknown 79/08/16 Rpp
- I Financial information
- 8004090477 Forwards supplementary financial info in support of TMI-1 restart proceedings
 HAFER, F. D. General Public Utilities - GPU Service Corp. 80/04/03
- --8004090482 Annual Pinancial Rept 1979. * General Public Utilities GPU Service Corp * Jersey Contral Power & Light Co * Metropolitan Edison Co 80/04/03, 44pp

Q Inspection reports, IE Bulletins & correspondence

- 8004020006 Responds to IE Bulletin 80-03 re visual insps of charcoal adsorber cells Equipment of this type has not been purchased to date FINFROCK, I R Jersey Central Power & Light Co 80/03/11
- 8004150271 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary GRIER.B.H. Region t. Philadelphia. Office of the Director response GRIER, BH R
- 8004090060 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, D H Region I, Philadelphia, Office of the Director 80/04/01 | Ip
- 8004110134 Forwards IE Info Natice 80~13, "GE Type SBM Control Switches Defective CAM Follows; " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- B004240306 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, BH Region 1, Philadelphia, Office of the Director B0/04/02 1p
- 8004180261 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Uil Sys " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/03 ip
- 8004230509 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required GRIER/B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004180196 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ORIER.B H. Region 1. Philadelphia, Office of the Director 80/04/07 p

DOCKET 50-344 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Gualification of Safety-Rolated Electrical Equipment," providing guidance re methods for compliance ROSB, D.F. Division of Project Management 80/02/08 7pp
- 8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance RDSB,D F Division of Project Management 80/02/21 Spp
- 8004230058 Requests info re auxiliary feedwator sys per Bulictins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to insuance of CL Wyencl ROSS,D,F Division of Project Management 80/03/10 53pp
- 8004020473 Forwards License SNM-1868 for util.authorizing receipt, possession & storage of U enriched in U-235 isotope & Pu Licensa also authorizes packaging of fuel assemblies for delivery to carrier Safety evaluation encl PAGE, R & Uranium Fuel Licensing Branch 80/03/12 2pp
- --8004020481 License SNM-1868 for util,authorizing receipt,possession, insp & storage of U enriched in U-235 isotope in fuel assemblies & fission counters. & Pu in encapsulated Puberyllium noutron sources & alpha sources PAOE,R G Uranium Fuel Licensing Branch 80/03/12 2pp
- ---8004020485 Safety evaluation supporting 790718 application for license for fuel % accessories Licensee should be granted exemption from 10CFR70 24 requirements
 DELANEY, J C Unantum Fuel Licensing Branch 80/03/12 2pp
- 8004250048 Forwards request for add1 info re review of OL application Schedule based on assumption that info will be available by 800505 Requests response within seven days after receipt of 1tr if date cannot be met 8TOLZ.J F Light Water Reactors Branch 1 80/04/01 11pp

- 8004100330 Forwards into the eismic qualification of safety-related non-MSC supplied electrical / mechanical equipment Summary equipment list encl
 CLAYTON.F.L. Alabams Pow-1 Co. 80/04/04 15pp
- 8004150447 Forwards didft ETS to proposed Tech Spec amend CLAYTON, F.L. Alabama Power to 80/04/07 5pp
- --8004150492 Diafts ETS +o: radiological ef+luents → Alabama Power Co BO/04/07 B4pp
- 8004280434 Confirms 800417 teleon is util intent to resolve auxiliary feedwater sys designs evaluation by following resolution on Unit 1 for Unit 2 CLAYTON, F. L. Alabama Power Co. 80/04/21 ip
- F. Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clanance under Federal Repts Act Emergency Praparedness Task Force 80/03/11 4pp
- 8004110573 Notification of 800325.26 & 27 meetings w/util.States of AL, FL & GA & FEMA re emergency planning at facility REEVES,E Operating Reactors Branch 1 80/03/18 2pp
- 8001070267 Forwards revised safeguards security contingency plan Plan withhold (ref 100FR2 790) CLAYTON.F & Alabama Power Co 80/03/28 1p
- G. Inspection reports, IE Bulletins 3 correspondence
- 8004150313 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/31 2pp
- 8004090592 Forwards IC Circular 80-05 "Fmorgancy Diesel Generator Lubricating Oil Addition > Onsite Supply "No written response required
 O'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/01 200
- 8004190064 Forwards IC Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers" No specific action or response Trequired

 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240242 Forwards IF Info Hotice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J P Region P. Atlanta, Office of the Director 80/04/02
- 8004180272 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/03
- 8004230113 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312,Type 304 Stainless Steel Pipe " Action required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180323 Forwards IE Rulletin 60-00 "Exam of Containment Liner Penetration Welds "Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/07
- 8004250401 Forwards add1 info re facility preservice insp program in response to NRC 800403 request insp plan for Class 1 & 2 components presented which identifies items to be nerted CLAYTON, F L. Alabama Power Co 80/04/21 100pg
- S Reportable occurrences, LERs & related correspondence
- 80042200B4 PNO-77-143 Pacific Fump Cd supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770B12
 WHITT,K W Region 2, Atlanta, Office of the Director 77/0B/12

- 04146242 Notifies that will his evaluated rod drop analysis discussed in Westinghouse 791115 for litrs to NRC Reportable deficiency exists Westinghouse topical rept re-solutions will be reviewed then issued in mid-1980 CLAYTON, Fil. Alabama Power to 80/04/03 2pp
- OCKET 50 366 COMIN ! HATCH NUCLEAR PLANT, UNIT 2
- 004290440 Forwards NRC confirmatory orders STELLO:V Orrice of Inspection & Enforcement, Office of the Director 80/04/04 ip
- -8004290466 Order confirming will commitment to perform review requested by IE Bulletin 79-27 by 800526 info required outlined in Attachment A STELLO, V Orfice of Inspection & Enforcement, Office of the Director 80/04/04 5pp
- -8004290477 Order confirming with commitment to perform review requested by IE Bulletin 79-27 by 800626 Into required contained in Attachment A STELLO, V Orfice of Inspection / Enforcement, Office of the Director 80/04/04 5pp
- Operating license stage documents A correspondence
- 004080189 Discusses NRC 761123 request that all LWR licensees assess higher fission gas release for fuel burnups above 20.000 MM-day per metric ton Responses indicate that no immediate licensing action is required for operating reactor IFPOLITO,T A Operating Reactors Branch 3 80/03/10 3pp
- 004030102 Forwards "Nuclear Da'a Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ctr EISENHUT, D G Division of Operating Reactors 80/03/12 Spp
- 8004030118 'Noclear Data Link Specs "

 Division of Operating Reactors 80/02/21 28pp
- 004030227 Destribes review of primary coolant sys pressure isolation valves in response to NRC 800223 ltm re-potential for LDCA forwards sketches of penetrations exhibiting Event 5 valve configuration for each unit WIDNER.W A Georgia Power Co 80/03/31 8pp
- 104270055 Forwards 800179 % 0211 ltis to QE re proposed control rod drive sys mode related to elimination of cracking in return line nozzles Guidelines for mode will be discussed in NUREG-0619, to be issued in "For Comment" form in Apr 1980 IPPOLITO.T A Operating Reactors Branch 3 80/04/07 2pp
- 04150358 Submits info is control rod operability, in response to NRC 800110 ltr During Sept 1978 to Dec 1979 no instances occurred of control rods failing to insert fully Only malfunctions were nitrogen cartridge valve loaks WIDNER, N.A. Georgia Pawer Co. B0/04/08 1p
- Inspection reports, IF Bulletins & correspondence
- 104070349 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-inch.Tray Adsorber Criis " Action required O'REILLY.J P Region 2. Atlanta Office of the Director 80/02/04
- O4010112 Partially responds to 1E Sulletin 79-010, "Environ valification of Class IF Equipment" Class IE components yield including environ analysis, inadequate qualification it test? accident temp profiles W/o encl
 "ER,W A Georgia Power Co 80/02/08 2pp
 - 215 Forwards IE Repts 50-321/80-08 \$ 50-366/80-08 on I-22 No noncompliance noted
 T.J C Region 2. Atlanta. Reactor Construction & Engineering of Branch 60/03/04 2pp
 - 04220221 IE Insp Repts 50-321/80-08 & 50-366/80-08 on 800221-22 No noncompliance noted Major areas inspected followup on items of noncompliance ro 1007821 BROWNLES, V. L. CONLON, T. E. Region 2, Atlanta, Office of the Director 80/03/04 3pp

- 8004070032 Ack receipt of 800310 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-01 & 50-366/80-01 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support
 - LEWIS.R C Region Branch 80/03/18
- --8004090035 Responds to NRC 800205 ltr re violations noted in IE Insp. Repts 50-321/80-01 % 50-366/80-01 Corrective actions data sheet revised to relocate rire pump fuel level checks & assignment sheet revised to use HMP-2-9503 WIDNER, W. A. Georgia Power Co. 80/03/10 1p
- ~-8004090036 Forwards IE Insp Repts 50-321/80-01 & 50-366/80-01 on 800108-11 ; notice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/05 2pp
- →-8004070041 Notice of violation from insp on 800108-11 ≠ Region 2. Atlanta. Office of the Director 80/0
- --8004050047 IE Insp Repts 50-321/80-01 & 50-366/80-01 on B00108-11 Noncompliance noted failure to follow surveillance Procedures

 UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch MODN, B T Region 2. Atlanta, Office of the Director

 BO/02/05 App
- 8004:10565 Submits response to IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " All filters are in good condition.all screens are stable & housing frames are solid No carbon lost through screens WIDNER.W A Georgia Power Co 80/03/21 3pp
- 8004150198 Responds to IT Bulletin 80-03 re charcoal adsorber cells Insp of all Util 1 ventilation sys indicate that all filters are in good condition Util 2 uses deep bed type carbon filter beds rather than cells WIDNER, W.A. Georgia Power Co. 80/03/21 3pp
- 8004170298 Responds to IC Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Review of emergency procedures required by Item 2, is now scheduled for completion by 800626 WIDNER, W.A. Georgia Power Co. 80/03/26. ip
- 8004190521 Forwards IE Info Natice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary D'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31
- 8004080674 Forwards IF Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01
- 8004150065 Ack receipt of 800211 1tr informing NRC of steps taken to correct violation noted in IE Insp. Repts 50-321/79-37 & 50-366/79-8 LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/01 ip
- --8004150072 Responds to NRC 800117 ltr re violation noted in IE Insp Rept 50-321/79-37 & 50-366/79-41 Corrective actions existing radiation work practices & procedures reviewed & modified WIDNER,W A Georgia Power Co 80/02/11 2pp
- ---8004150079 Forwards IE Insp Repts 50-321/79-37 & 50-366/79-41 on 791110-1207 & notice of violation LEWIS.R C NRC Regional Offices 80/01/17 2pp
- --8004150086 Notice of violation from insp on 791110-1207 * Region 2. Atlanta. Office of the Director 80/01/15 ip
- -BOO4150096 IF Insp Repts 50-321/79-37 & 50-366/79-41 on 791110-1207
 Nontempliance noted radiation work permits were not
 approved & posted prior to work contrary to procedures &
 Tech Specs
 DAMCE, H C NRC Regional Offices ROSERS, R F Region 2, Atlanta,
 Office of the Director BO/01/15 Spp
- 8004150126 Ack receipt of B00313 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/80-04 & 50-366/80-04 LENTS, R C Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch 80/04/01 ip

- --8004150136 Responds to NRC 800214 itr re violation noted in IE Insp Repts 50-321/60-04 & 366/80-04 Corrective actions shift foreman & operators involved were relieved of duties for special training WIDNER,W A Georgia Power Co 80/03/13 ip
- --8004150142 Forwards IE Insp Repts 50-321/80-04 \$ 50-386/80-04 on 791212-800104 & notice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/14 2pp
- --8004150147 Notice of violation from insp on 791212-800104 * NRC Regional Offices 80/02/13 ip
- --8004150155 IE Insp Rept 50-321/80-04 2 50-346/80-04 on 791212-800104 Noncompliance noted HPCI sys not proven operable as required by Tech Specs
 DANCE,H C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch ROSERS,R F Region 2, Atlanta, Defice of the Director 80/02/13 4pp
- 8004150093 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J P Region 2: Atlanta, Office of the Director B0/04/02
- 8004240265 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180303 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bya " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004110011 Forwards IF Bulletin 80-07, "BWR Jet Pump Assembly Failure " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004230173 Forwards IE Bulletin 79-03A "Longitudinal Weld Dufects In ABME BA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04 to
- 8004180436 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
- 8004230467 Submits info in response to 800121 ltr re IE Sulletin 80-02 Documentation associated w/receipt & installation of sparger assemblies & mods is on file at plant site MIDNER, N A Georgia Power Co 80/04/16 4pp
- 8004280452 Updates 800346 response to IE Bulletin 79-01B "Environ Qualification of Class IE Equipment " Enough info re Bachtel equipment will be available by 800801 to provide meaningful response Info needed from 0E will be complete by 801226 HIDNER, W A Georgia Power Co 80/04/21 2pp
- R Periodic operating reports & related correspondence
- 8004010321 Forwards "Annual Environ Surveillance Rept for CY77 " MANRY, M Georgia Power Co. 80/03/28 ip
- ---8004010324 "Annual Environ Surveillance Rept for CY79 " * Georgia Power Co 80/03/28 300pp
- 8004150383 Forwards monthly operating rept for Mar 1980 MANRY,M Georgia Power Co 80/04/10 1p
- --8004150385 Monthly operating rept for Mar 1980 RODEN, J W Georgia Power Co 80/04/10 10p
- BOO4150393 Forwards monthly operating rept for Mar 1980 MANRY,M Georgia Power Co BO/04/10 1p
- 8 Reportable occurrences, LERs & related correspondence
- 8004150454 Forwards LER 80-017/03L-0 MANRY,M Georgia Power Co 80/03/13 1p

- --8004150460 IEP 80-017/O3L-O on 800219 during instrument check. It d dihydrogen dioride recorder found reading low Caused by diaphragm facture in B analyzer vacuum pump Diaphragms replaced Analyzer recalibr 'returned to svc NIX.R T Georgia Power Co 80/03/13 2pp
- 8004020343 Folwards LER 80-020/03L-0 MANRY:M Georgia Power Co 80/03/24 1p
- --8004020347 LER 80-020/03L-0 on 800229 during normal operation, who performing HPC1 exhaust diaphragm pressure switch survexliance, two switches exceeded Tech Specs Caused by instrument drift Switches recallth NIX.R T Georgia Power Co 80/03/25 2pp
- 8004020361 Forwards LER 80-019/03L-0 MANRY, M. Georgia Power Co. 80/03/24 ip
- --8004020345 LER 80-019/03L-0 on 800227, during instrument check, A di H202 analyzer recorder found giving enconeous reading Caused by diaphragm failure in A analyzer vacuum pump Diaphragms replaced Analyzer calibr & returned to svc NIX,R T Georgia Power Co 80/03/24 2pp
- 804020315 Forwards LER 80-028/03L~0 MANRY, M Georgia Power Co 80/03/25 ip
- --8004020317 LER 80-028/03L-0 on 800228, during instrument chock, B dr H2-02 analyter recorder was found giving erroneous reading Caused by leakage in sys leak repaired Analytor calibr & returned to svc NIX, R T Georgia Power Co 80/03/25 2pp
- 8004020325 Forwards LER 80-827/03L-0 MANRY, M Georgia Power Co 80/03/25 ip
- --8004020330 LER 80-027/03t-0 on 800315, while performing, plant ave we pump auto function operability surveillance, isolation valve 2P41-F316A failed to actuate to isolation position upon signal Caused by instrument failure NIX, R T Georgia Power Co 80/03/25 2pp
- B004020428 Forwards LER 80-025/03L+0 MANRY, M Georgia Power Co 80/03/25 1p
- --8004020437 LER 80-025/03L O on B00308, during shutdown, while performance (LPCI) pump start timers calibrirelay 2C11-K75A metpoint exceeded Tech Specs Caused by setpoint drift Relay recalibr NIX,R T Georgia Power Co 80/03/25 2pp
- 6004150425 RO-50-366/1780-29 on 600324, battery chargers 20 & 2J. used while charging diesel batteries 2A & 2C, respectively, failed to maintain necessary load & voltage requirements Caused by possible testing component failure Batteries recharged MANRY, M Georgia Power Co 60/03/25 2pp
- 8004070314 Forwards LER 80-021/03L-0 MANRY, M Georgia Power Co 80/03/26 1p
- --8004070324 LER 80-02\$/03L-0 on 800303, while in shutdown, surveillen tests found MPCI turbine exhaust valve, feedwater check valve & equipment drain sump isolation valve w/unacceptable leakage Causes under investigation C0001N:CL Georgia Power Co 80/03/27 3pp
- 8004150410 RD-50-366/1980-031 on 900327.during cold shutdown.while performing 18-month surveillance.battery charges 2A.28 & 2C were unable to maintain loading requirements Caused by SCRs & current limiting modules being out of adjustment MANRY.M Georgia Power Co 80/03/28 2pp
- 8004040427 Forwards LER 80-024/03L-0 MANRY, M Georgia Power Co 80/03/31 1p
- --8004040438 LER 80-024/03L-0 on 800308.w/reactor in cold shutdown.wi performing ASME operability test on RHR water pumps, pump 2EII-C00ID dropped from 4,000 gpm to 3,600 gpm Caused by debris being drawn into suction of pump NIX.R T Georgia Power Co 80/03/31 2pp
- 8004110472 Forwards LER 80-026/03L-0 MANRY, M Georgia Power Co 80/04/02 ip
- ---8004110476 LER 80-026/03L-0 on 800314 during local leak rate testing hydrogen recombiner return isolation valve 2749-F0058 had unacceptable test results Caused by stratch on seat apparently due to valve closing on piece of debris CO001N.C L. Georgia Power Co. 80/04/02 2pp

ļ

```
BG041101/9 Fr. wards EER HT 01/ 01T 0
MANRY M. Georgia Polet to E0/04/03 Ip
- 8094110463 ((m mo 0.7/m)) to in 0.0525 during 18-nonth surveillance test on ereigency station birtary inargers 20° 2J/both failed to maintain respective loss. Caused by voltage control module & corrent limit module requiring rine tuning C09618 C L Georgia raper to 87/04/03 2pp
8004150451 Forwards tCR SURCESTAGEL FO MANRY, M. Georgia Power to 80 04/03 1p
- 8004150455 (ER 80-030/030 to an 800320, while performing turbine control valve rast closure pressure suitch calibri 2071-N005D found at less than Tech Bps limit Caused by instrument drift Instrument recalibr NIX R Y Georgia Power to 80/04/03 2pp
8004150476 Forwards LER 89-031/017-0
MARRY,M Georgia Power Co 80/04.
                                                                           80/04/07 15
--8004150481 LER 80 031/017-0 on 800327 during performance of 18-month tests on station baftery chargers 2A.28 % 2C, chargers were unable to maintain load limits Caused by imbalanced silicon control rectifiers / halajosted current limit module COGGIN/C L. Georgia Power Co. 80/04/06 | 2pp
8004150562 Forwards LER 80-032/01T-0
MANRY II Georgia Power Co 80/04.
                                                                        80/04/07 1p
--B004150572 LER 80-032/51T-0 on 800327 during maint outage & surveillance test-noted that 2D PSN pump sequenced to bus in 2 to 5-s Cause unknown COGGIN-C L Georgia Power Co B0/04/08 2pp
8004280531 RD 50-366/1980-045 on 800405, during cold shutdown, leak rate
     test on automatic depressurization sys valve air supply accumulator check valves indicated unacceptable leakage rates Cause under investigation No immediate action taken MANRY.M Georgia Power Co 80/04/07 2pp
8004220615 Forwards LER 80-039/03L-0
                                                                           80/04/15 1s
                             Georgia Power Co
  --8004220617 LER 80 039/03L-0 on 800325,while performing standby gas
treatment ventilation surveillance, no flow established at
2746-00016 filter train Caused by failure of 2746-00018 fan
motor viring Motor repaired
NIX.R T Georgia Power Co 80/04/t5 2pp
8004220620 Forwards LER 80-033/03L-0
MANRY, M Georgia Power Co 80/04/15 (a
 --8004220636 LER 80-033/03L-0 on 800331, while in cold shutdown, triaxial
         peak recording accelerometers on reactor pedestal & feedwater inlet line were not calibr within time limit Caused by instrument failure during calibr MKX.R T Georgia Power Co 80/04/15 2pp
B004220662 Forwards LER B0-034/03L-0
MANRY,M Georgia Power Co B3/04
                                                                         83/04/15 1p
--8004220667 LER 80-034/03L-0 on 800320, while performing calibr on main
steam line, temp switches 2321-N010A, N013A < N013D found to
have bad repeatability daused by instrument drift Calibr
procedure revised
NIX,R Y Georgia Power Co 80/04/15 2pp
         1220728 Forwards LER 80-045/017-0
         INRY, M Georgia Power Co 80/04/15 ip
    3004220736 LER GO-045/017-0 on 800404.while in cold shutdown, leak rate test was performed on auto depressurization sys valves air supply accumulator check valves Leaks word beyond acceptable rate Cause unknown Valves will be repaired prior to startup GUGGIN.C L. Georgia Power Co. 80/04/15 2pp
 004220664 Forwards LER 80-040/03L-0
MANRY,M Georgia Power Co 80/04/16 1p
    -8004220671 LER 80~040/03L-0 on 800331.during review of autage
        surveillance requirements, cycle surveillances required by Amend 12 to Tech Specs had not been conducted Caused by operational conflict Tests will be performed before startup COGGOIN.C.L. Georgia Power Co. BO/04/16 2pp
```

```
8004220652 Forwards LER 80-037/03L-0
                                                                                        90/04/17 in
     --8004220658 LER 80-037/03L 0 on 800328, while in cold shutdown &
              004220698 LER 80-037/03. O on 300326, unit is in columnia
perrorming reactor wafer chemistry, noted chloride
concentration was O 116 ppm Cause attributed to reactor
water cleanup sys out for 26-days Cleanup sys fixed
ROCERS, W. H. Georgia Power Co. 80/04/17 2pp
    8004220705 Forwards LER 80-043/03L-0
MANRY,M Georgia Power Co 80,04/17 ip
    --8004220717 LER 80 043/031-0 on 800401, while in cold shutdown 8 performing inspirequired by IE Bulletin 80-03, noticeable amount of carbon found on floor of both trains of refueling floor ventilation sys Probably caused by improper packing ROGERS, W.H. Georgia Power Co. 80/04/17 2pp
   8004220706 Forwards LFR 80-044/03L-0
MANRY.M Georgia Power Co 80/04/17 1p
    --8004220718 LER 80-014/03L-0 on 800402.during calibi procedure, found drywell sensor 2747-No/3 incorrectly connected to suppression pool vapor temp indicator $\times \temp sensor 2748-No/3 incorrectly connected to drywell temp indicator NIX.R T Georgia Power Co 80/04/17 2pp
   8004220724 Forwards LER 80-035/03L-0
MANRY.M Georgia Power Co 80/04.
                                                                                        80/04/17 1p
   --8004220735 LER 80-039/03L-0 on 800321, during calify procedure
HNP-2-5329, all but six accomplator pressure switches found
to be outside Tech Specs Caused by personnel error &
component failure Pressure switches recalify
NIX.R T Georgia Power Co. 80/04/17 2pp
   8004280416 Forwards LER 80-041/03L-0
MANRY, M Georgia Power Co 80/04/21 1p
   --B004280419 LER 80-041/03L-0 on 800401, during performance of LLRT, feeduater isolation valve 2B21-F077A did not have acceptable results during initial test Caused by natural wear & tear to valve seat Leak 1ste limit met by corrective maint C06013, C L Georgia Power Co 80/04/21 2pp
  8004280441 Forwards LER 80-036/03L-0
MANRY.M Opengia Power Co 80/04.
                                                                                     80/04/22 1n
   --8004280447 LER 80-036/03L-0 on 800326, during ILRTs, while shut down for surveillance vent/header deflector installation butage, feedwater check valve drywall purge inlet isolation valve & ILRT verfsfication flow isolation valve failed tests COGGIN.C Georgia Power Co 80/04/22 3pp
  DUCKET 50-367 BAILLY GENERATING STATION
  A Application/construction stage documents & correspondence
 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Pioject Management 80/02/05 7pp
  8004020466 Notification of 800326 & 27 meeting w/representatives from
       Mark II owners group in San Jose, CA to discuss Mark II
Creace Test Program, 4T c/o tests & foreign tests
ELTAWILA, F Containment Systems Branch 80/03/10 12
 8004030122 Notification of 800326-27 meeting w/Mark II owners group, NRC consultants & OE in San Jose.CA to discuss Mark II Creare test program.4T c/O % foreign tests Topics are proprietary Agenda encl ELTANILA.F Containment Systems Branch 80/03/10 12pp
8004040474 Summary of 800227 meeting w/Mark II owners group re status of several long-term program tasks, including Tasks A 17 & A 16 & task related to utilization of foreign tost data ELTAWILA,F Containment Systems Branch 80/03/18 104pp
8004100507 Requests add] info re methods used to measure corrosion potential of piles Info as to whether std ABTM tests or std NACE tests were used is required RUBENSTEIN.L 9 Light Water Reactors Branch 4 80/03/28 3p
```

- GOO4150047 Summary of GOO310 meeting w/Corps of Engineers & NRC consultants in Bethesda, MD re issues of pile driving at site
 THOMPSON, D U Geostiences Branch 80/04/02 7pp
- 8004150084 Natirication of 800417 meeting w/util in Chicago, IL re pile driving issues LYNCH,M D Light Water Reactors Branch 4 80/04/02 4pp
- 8004240502 Discusses status of plant review re foundation pilings Corps of Engineers is reviewing geotechnical engineering aspects of proposed plant Particular effort is being concentrated on Category I pile driving, suspended by NRC THOMPSON, O. Q. Geosciences Branch 80/04/03 2pp
- 8004300064 Summary of 800326-27 meetings w/Mark II owners group in San Jose.CA re discussion of NRC concerns on data from Create tests & foreign fuli-scale test programs & relationships w/ Mark II designs ELTANILA.F Containment Systems Branch 80/04/14 22pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0AO clearance under Federal Repts Act ORIMES, B K Emergency Preparedness Task Force 80/03/ii 4pp
- Q Adjudicatory correspondence
- B004230091 Requests to institute proceeding & to suspend or revoke CP Urges admittance of Porter County chapter of Izaak Walton League of America, Concerned Citizens Against Bailly Nuclear Site, et al. as parties W/Certificate of Svc & documentation VDLLEN.R J Vollen, R J OSANN, E W Osann, E W GRAHAM, R i Graham, R L 76/11/24 107pp
- --8004230093 Symmary of 760604 meeting w/util & Natl Park Svc to discuss Bailly & IN Dunes Natl Lakeshore Meeting re technical discussion will take place in future GEKLER.R P Environmental Projects Branch 1 76/06/29 4pp
- --8004230096 Bummery of 760603 meting at IN Dunes Natl Lakeshore on Bailly site to discuss fossil & planned units & monitoring efforts Urgos consideration of technical & mgt meetings GECKLER.R P Environmental Projects Branch 1 76/06/30 Spp
- ---8004230101 Request for hearing re CP amend extending completion to 850901 Certificate of 8vc encl VQLLEN,R J Vollow R J OSANN,E W Osann, E W GRAHAM,R L Graham, R L 79/02/27 4pp
- 8004040069 Joint intervenors response stating no objection to State of IL B00215 motion for continuance re CP extension proceeding Certificate of Bvc encl VOLLEN.R J Vollen. R J 80/02/20 3pp
- 8004080169 Opposes extention of facility const date ARNURIUS, G Affiliation Unknown 80/02/23 1p
- 8004020214 Natice advising of ASLB denial of Joint Intervenors' motion re CP extension Formal order will be issued on 800303 Cartificate of Svc encl VOLLEN'R J Vollen, R J 80/02/25 App.
- 8004010274 Contention by City of Gary, IN, United Steelworkers of America, Bailly Alliance, Save the Dunes Council & Critical Mass Energy Project Questions whether realistic evacuation & emergency plans may be implemented adequately, COHN, D B Cohn, D B SCHULTZ, W B Schultz, W B 80/02/26 1p
- --8004010300 Reply in opposition to NRC & Northern IN Public Svc Commission responses to petition to intervene re CP extension Supporting affidavits & Certificate of Svc encl COHN, D B Cohn, D B SCHULTZ, W B Schultz, W B 80/02/26
- 8004020478 First suppl to putition to intervene by joint intervenors, alleging that extension of completion date is not based on good cause required by Atomic Energy Act Certificate of Svc encl
 VDLLEN.R J Vollen, R J 80/02/24 22pp
- 8004020280 Responds to Eichhorn 800227 ltr Arrangements will be made re pick up of applicant responses to supplemental petitions at convenient time Certificate of Syc encl SHEA, K H Lowenstein, Newman, Reis, Axelrad & Toll 80/02/27 4pp

- 8004020092 Response in opposition to G Echulti, A ? G Grabowski, State of IL.City or vary 5 Porter County Chapter supplemented petitions to intervene riled in response to ASLB 800207 order Urges denial of hearing requests W/Certificate of Svc EICHHORN, W H. SHEA, J R. Horthern Indiana Public Service Co EICHHORN, W H. Eichhoin, Eichhorn & Link 80/03/07 75pp
- 8004040053 Notice of appearance in CP extension proceeding FRANTZ, S P Northern Indiana Public Service Co FRANTZ, S P Lowenstein, Newman, Reis, Aselrad 3 Toll 80/03/12 ip
- 8004140125 Forwards NRC 790926 memorandum re NUREG-0625, "Rept of Siting Policy Task Force" Memorantes that Barily alone of all nuclear plants farl, ill six siting criteria State of IL will assist pio se intervence filling HANSELL.D Illinois, State of 80703/19 4pp
- --8004140127 Discusses NUREC-0675, Pecommendation 2 Complete survey of OL & CP sites for hazardous facilities, airports A pipelings cannot be completed for 791004 briefing Approx 10-207 of existing sites would rail first three distance criteria HDUSTON, R W Accident Analysis Branch 79709/26 Epp
- 8004140130 Request for hearing re-aplicant 790207 request for extension until 850501 to complete const NRC cannot determine that amend involves no significant hazards consideration Centificate of Svc encl HANSELL, D. 111:nois, State of 79/03/05 App
- 8004300133 Supplemental statement re standing Contends that members of United Steel Workers of America Local 1010 are users of IN Dunes Natl Lakeshore in which site dewatering will take place due to const W/afridavit N. Certificate of Svc FRANTZ.J United Steelworkers of America 80/03/26 1p
- 8004230105 Draws attention to Commission 800313 order to be considered prior to issuance of prehearing conference order re-stds applied for standing to intervene SHEALK H Lowenstein, Newman, Reis, Axelrad % Toll 80/03/27 2pp
- 8004080567 Order requesting parties to submit views on apparent deficiencies in 800312-13 special preheating conference transcript by 800411.re Cf extension praceeding GRUSSMAN, H Atomic Mafety and Licensing Board Panel 80/03/28
- 8004230028 Motion for add1 time to file contentions & first suppl to intervention petition in CF extension proceeding Dewatering info should be reconsidered at 5-yr interval Affidavit, motion > Certificate of Svc enc!
 ROBBINS,R L Lake Michigan Federation 80/03/28 11pp
- GOO4110574 Responds to request for info ie CF extension proceeding Participant are sell-NRC adjudication may be relieved of requirement to file 20 copies of all documents on Socretary of Commission in accordance w/10CRR2 70G(d) GOLDBERG.S C Hearing Branch 2 80/03/31 2pp
- 8004030026 Nemorandum of understanding between NRC & FEMA re prompt improvement in rediciogical emergency planning & preparedness, distributed as Board notification gOSSICK, V Office of the Executive Director for Operations 80/04/02 34p
- B00410000B Order relieving G % A Grabowski from 20-copy requirement for pleading & documents filing in CP extension proceeding OROSSMAN,H Atomic Safety and Licensing Board Panel 80/04/02
- 8004210425 Brief in response to ARLB request during 800312-13 special prehearing conference Interrelationship between ash pond sagpage & const dewatering was fully litigated during CP hearings % is now baried from reconsideration GOLDBERG.8 C Hearing Branch & 82/04/10 5pp
- --8004210431 Affidavít stating observations on relationship between ash ponds for applicant coal-fired plants 2 facility const site dowatering Prof qualifications 3 Centificate of Svc encl GECKLER, R P Division of Site Safety 3 Environmental Analysis 80/04/09 9pp
- 8004150223 Position stating that good cause for CP extension need not be beyond control of permit holder under 10CFR50 55(b) Prior practice.ps: Diablo Canyon & other cases, has accepted need for applicant evaluation.as go

- 3004150258 Response to ARLS 800228 order seeking views re-pre-conference transcript or CP extension proceeding Suggests issuance of clarifying instructions due to inferior quality or transcript that may arrect indings MCCertificate of Svc GODDARD/R J. Hearing Branch 2 30/04/11 Spp.
- 8004210209 Response in opposition to Lake MI Federation 800328 motion to file contentions ? first suppl to petation to intervene If Federation is granted intervention, participation should be limited to issue of const devatering (//Certificate of Svc GOLDBERG, S C Hearing Branch 2 80/04/17 8pp
- 8004250415 Confirms 800502 meeting at IL Atty General Ofc, Chicago IL to discuss contentions ad anced in CP extension proceeding GOLDBERG. S C Hearing Branch 2 H0/04/23 ip
- 8004300388 States no objection to granting 0 & A Grabowski 800402 second supplied intervention potition in CP extension proceeding NRC has no intention to tile formal response GOLDBERG.S C. Hearing Branch 2 80/04/28 ip
- H General correspondence
- 8004080170 Opposes extension of CP Plant so close to homes of millions of people is too dangerous
 HECK.A E Affiliation Uninoum 80/02/22 ip
- 8004070364 Responds to 790916 request that LPDR be established in Indianapolis. IN IRC establishes LPDR in inmediate vicinity of proposed 5 operating commercial nuclear power plants Applicable LPDR locations 6 hours of operation enci Division of Rules and Records B0/03/13 3oo
- --8004070973 Requests establishment of LPDR in Indianapolis.IN Believes that LPDR would be approciated & well-used by citizens of Indianapolis BENNETT,C L Affiliation Unknown 79/09/16 2pp
- 8004080165 Opposes const of facility due to proximity to Chicago & increase in disaster potential CLARK, M , FRIGO.R , WHITSHURST.C Affiliation Unknown 80/03/65
- P Operating license stage documents & correspondence
- 8004150451 Pleading supplementing State of IL 791121 ltr treated under 10CFR2 205 Urges institution of hearing resiting adequacy to development of mergency evacuation plan Requests that issue be decided by Commission or ASLS Certificate of Svc encl SCOTT. U.J. HANSELL, D. 111; nois, State of 80/04/10 Spp
- O Inspection reports, IE Bulletins & correspondence
- 8004100139 Forwards IE Info Notice 80-09, "States Ca Sliding Link Electrical Terminal Black" No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/07
- 8004150180 Forwards IE Info Notice 80-12. "Instrument Failure Causes Dpening of PORV & Block Valve " No specific action or response necessary XEPPLER, J G Region G. Chicago, Office of the Director 80/03/31
- 8004080718 Forwards 1E Circular 80-05. "Emergency Diosel Generator Lubricating Oil Addition & Onsite Supply " No written response required EPPLER.J Q Region 3. Chicago. Office of the Director 80/04/01
- - 150048 Forwards IE Info Notice 80-13, "GE Type SEM Control Switches fective CAM Followers " No specific action or response EPPLER, J C Region 3, Chicago, Ofrice of the Director BD/04/02
 - 34180054 Forwards attachments to [E Circular 80-03, "Protection From Foxic Gas Hazards," inadvertently omitted from 800306
- (EPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 04220149 Forwards 1E Info Natice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02

- 8004220382 Forwards IC Circular 80-07, "Problems W/HPCI Turbine Oil Sys "No written response required
 KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/03
- 8004110043 Forwards IF Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required
 MEPPLER, J.G. Region 3, Chicago, Office of the Director 90/04/07
- 8004230280 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 9A-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07
- 8004220114 Forwards IE Builetin 80~08, "Exam of Containment Liner Penetration Walds" Written response required KEPPLER.J G Region J. Chicago, Office of the Director 80/04/09
- R Periodic operating reports & related correspondence
- 8004080331 Forwards well charts for 800313-19, Bailly wells w/o recorders, pond levels, pieumatic pressure transducers, water meter readings ? USGS wells for 800319 BOHM, R. J. Northern Indiana Public Service Co. 80/03/28 33pp
- 8004150453 Forwards well charts for 800319-26 & Bailly wells w/o recorders, pand levels, pneumatic pressure transducers, water meter readings & USGS wells for 800326 BOHN,R J Northern Indiana Public Service Co 80/04/07 33pp
- B004220553 Forwards well charts for B00326-0402.Bailiy wells w/o recorders.pand levels.pneumatic pressure transducers.water meter readings & USGS wells for B00402 BGHN.R J Northern Indiana Public Service Co B0/04/11 33pp
- 8004280494 Forwards well charts for 800402-10. Bailly wells w/o recorders for 800410.pond levels for 800410.pnewmatic pressure transducers.water meter readings for 800409. USGS wells for 800409 & rainfall data for 800401-0331 BOHN, R J Northern Indiana Public Service Co 80/04/18 3 80/04/18 34pp
- 8004300431 Forwards well charts for 800410-16. Beilly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS wells for 800416 BOHN, R J Northern Indiana Public Bervice Co 80/04/25 33pp
- DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2 F Security, medical, emergency & fire protection plans
- B004030107 Approves design of cable spreading room fire barrier, in response to util 800220 request Barrier located at cabling nexus of redundant sare shutdown divisions Status of fire protection review mods encl
 LAINAS.0 Plant Systems Branch 80/03/17 2pp
- 8004010386 Advises that all fire protection mods will be complete by 801001 except Unit 2 Items 3 14 & 3 18 Hardware mods for Item 3 18 scheduled for Mar 1781 cold shutdown Smoke detector sys for Item 3 14 will be installed when complete TRIMBLE, D C Arkansas Power & Light Co 80/03/26 2pp
- 8004150567 Forwards drawings & description of mods for containment bldg manual hose stations as required by fire protection safety evaluation Drawings available in Central Files only TRIMBLE.D C Arkansas Power & Light Co 80/04/09 20pp
- ---8004150579 "Hydravisc Calculation for Containment Hose Reel Project " HUFF.M , FRANCE,E R , SANDERG,D Arkansas Power & Light Co 80/02/04 17pp
- --8004150570 "FAAST Fluid Analysis & Simulation Technique, User Info * Control Data Corn 78/03/15 138an
- ---8004150601 "Hydraulic Calculations Containment Hose Reel Project (DCP-2089)(FAAST Output) " HUFF,M , FRANCE,E R , SANDERG,D Arkansas Power & Light Co 60/01/17 Bipp

H Ceneral correspondence

- 8004100581 Responds to 791212 ltr re computers & safety stds used in nuclear power plants Digital computers used for monitoring aperations & core protection calculator sys provides protection functions DENTON.H R Office of Nuclear Reactor Regulation 80/03/27 ip
- ~-8004100582 Requests info re reliability of computers that control nuclear plants & safety stds since accident BRADBHAW.M Affiliation Unknown 79/12/12. 1p
- 8004280347 Responds to 800321 ltr requesting summary sheets for operating reactors Forwards sheets prepared in months prior to issuance of CLs W/o encl
 DENTON, H R Office of Nuclear Reactor Regulation 80/04/04 1p
- --8004280352 Requests info re performance evaluations of all reactors since first CP was granted
 WEST.B Affiliation Unknown 80/03/01 1p
- B004170240 Requests that util be required to submit EIS before authority is granted to expand nuclear waste fuel storage pools at site Prior EIS insufficient PETERS.B. Affiliation Unknown 80/04/09 2pp

I Financial information

- 8004220535 Annual Financial Rept 1979 * Middle South Utilities, Inc. 79/12/31 40pp
- 8004150235 Forwards Annual Financial Rept 1979
 TRIMBLE.D C Arkanses Power & Light Co 80/04/10 1p
- --8004150239 Annual Financial Rept 1979
 * Arkansas Power & Light Co 80/04/10 46pp

P Operating license stage documents & correspondence

- 8004110508 Summarizes walkdown re identifying seismic Category I piping & safety-related sys attached to or in close proximity to concrete block walls Numbers are preliminary & may be adjusted upon survey completion on 800130
 TRIMBLE, D C Arkansas Power & Light Co 80/01/28 Ip
- B004070160 Forwards NRC evaluation of actions taken to satisfy Category A requirements of TMI~2 Lessons Learned All Category A requirements have been met satisfactorily w/exception of Item 2 1 7a for Unit 2 REID,R W Operating Reactors Branch 4 80/03/10 2pp.
- --8004070170 "Evaluation of Licenses Compliance W/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned " # Operating Reactors Branch 4 80/03/31 13pp
- 8004030102 Forwards "Nuclear Data Link Specs:" study of digital communication sys to transmit info from plants to Bethesda Dperations Ctr EISENHUT, D Q Division of Operating Reactors 80/03/12 5pp
- ~-8004030118 "Nuclear Data Link Epecs "
 * Division of Operating Reactors 80/02/21, 28pp.
- 8004030209 Provides descriptions of long-term Lessons Learned changes to plant shielding & modified sampling sys to minimize personnel exposure during worst case accident conditions TRIMBLE, D C Artansas Power & Light Co 80/03/31 7pp
- BOO40702B7 Forwards proposed change to Paragraph 15 2 2 constituting Ravision 5 to APL-TOP-1A, "GA Manual, Nonconforming Matl, Parts or Components "Parts Co Components TRIMBLE, D. C Arkansas Power & Light Co 80/03/31 ip
- ---8004070403 Proposed change to Paragraph 15 2 2 of "GA Manual, Nonconforming Mati.Parts or Components " # Arkansas Power & Light Co ALP-TOP-1A 80/03/31 2pp
- 8004180304 Forwards brief description of safety evaluation for design changes completed in 1979 which require safety evaluation per 100FR30 59 Mods include emergency cooling pond change, firehouse station addition & increase of sprinkler covarage TRIMSLE.D C Arkansas Power & Light Co 80/03/31 5pp.
- 8004170086 Forwards description of safety evaluation for design changes completed in 1979, TRIMBLE D C Arkansas Power & Light Co 80/03/31 6pp.

- 8004070344 Informs that Sertion 2 & 3.Revision 5 of QA manual re diesel generator fuel oil meets Tech Spec requirements per 800107 request
 TRIMBLE.D C Arkansas Power & Light Co 80/04/03 1p
- 8004280089 Forwards request for addl info re 790924 request for amend to License NPF-4 concerning response time for steam driven emergency feedwater pumbs Supporting analysis showing no decrease in safety margin from change should be provided REID.R W Operating Reactors Branch 4 80/04/04 Jpp
- & Inspection reports: IE Bulletins & correspondence
- 8004090151 Forwards IE Insp Repts 50-313/80-01 & 50-368/80-01 on 800107-18 3 notice of violation MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support Branch BD/02/01 2pp
- --8004070153 Notice of violation from insp on 800107-18
 * Region 4. Dallas. Office of the Director 80/02/01 2pp
- --8004090159 IE Insp Repts 50-313/80-01 & 50-348/80-01 on 800107-18 Noncompliance noted data sheets recorded relay setting only & did not contain sufficient info & colinh & testing program for protective relaying was deficient in procedures SPANGLER.R G . SMITH.R . HESTERMAN, T F Region 4. Dallas. Office of the Director 80/02/01 App
- 8004100315 Forwards IE Insp Repts 50-313/80-02 & 50-368/80-02 on 791222-800121 & notice of violation MADSEN, G L NRC Regional Offices 80/02/08 2pp
- --B00410D324 Notice of violation from insp on 791222-800121 * NRC Regional Offices 80/02/06 1p
- --8004100335 IE Insp Repts 50-313/80-02 & 50-368/80-02 on 791222-800121
 Noncompliance noted failure to adhere to requirements of
 test procedure
 JOHNSON, W D , CALLAN, L J , WESTERMAN, T F NRC Regional Offices
 80/02/06 Spp
- 8004040089 Forwards IE Insp Repts 50-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted MADSEN.O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/26 2pp
- --8004040094 IE Insp Repts 50-313/79-24 & 50-368/79-23 on 791109 No noncompliance noted Major areas inspected current NRC & DOT regulations, current requirements of Waste burial firms, instructions & operating procedures & audit program HARRISON.H C Region 4. Dallas, Office of the Director BROWN, O D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/01/16 App
- BOO4250103 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation 2 Control Power Sys Bus During Operation " Util has reviewed applicable buses No buses identified which could affect ability to achieve told shutdown TRIMBLE, D C Arkansas Power & Light Co BO/02/28 2pp

- 80.04250247 If the Proph. Coll 2.50.01 > 50-368/80-04 on 800131 & 0201. To indicompliture in Mary Land Great inspected practices of licensee has thirty Lorenza innel Propriet contracted.
 - personnel BRANKE vir Magion & Estas, foel facility & Materials Safety Branco WE Telefold 7 DOWED WE Region 4. Dallas, Office the Director 30 od), Ipp Region 4. Dallas, Office of
- 9004190231 Firmation L. Inc. Intice Stall. Instrument Failure Causes Opening of Cont. Alone Inc. The specific action or response necessary SEMFRITION Region & Callest Office of the Director 80/03/31
- 3004090666 Forward, IE Currular 20-05, "Fmergency Diesel Generator Lubricating oil Addition" diesele Supply 'No written response required
- Region 4. Utilis Office of the Director 80/04/01 SEYFRITA
- 8004110097 Forwards IE Info Natire 80-13, "GE Type SBN Control Switches Defective CAM Followers ' No specific action or response
- SEYFRIT.K ? Region 4 Dallas, Office of the Director 80/04/02
- 8004180493 Forwards It Into Notice 60-14, "Safety Suggestions From Employees No action required
 SEYFRIT,/ V Region 4. Dallas Office of the Director 80/04/02
- 8004180159 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Sys 'No written response required SEYFRIT.P V Rejion 4, Pallas, Office of the Director 80/04/03
- 8004230324 Forwards II. Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Action required SEYFRIT. X V Region 4 Units Office of the Director 80/04/04
- R Periodic operating teports & related correspondence
- 8004210274 Forwards monthly operating rept for Mar 1980 TRIMBLE.D C Arkansas Power & Light Co 80/04/11
- ---8004210280 Monthly operating rept for Mar 1980 PENDERGRAFT/R Arkansas Power / Light Co & BO/04/11 6pp
- 8004290450 Forwards corrections to monthly operating rept for Mar 1980 TRIMBLE D C Arkansas Power & Light Co 80/04/17 ip
- -8004240451 Corrections to monthly operating rept for Mar 1980 PENDERGRAFT.R Arkanaga Power ! Light Co 80/04/11 3pp
- S. Reportable Occurrences, LERS & related correspondence
- 7811100178 Describes 780916 event at subj facil auto transfer of autiliary loads on both units to startup transformer #2 w/consequent overload Recomments licensee be advised of nonconformance w/GDC-17 // modify his design ROBA-F Power Systems Branch SATTERFIELD,R Electric, Instrumentation & Control Systems Branch 78/11/01 8pp
- 3004280521 RD 50-368/80-014 on 800318 after reviewing C-E ltr re discrepancy in shutdown margin for boron dilution in Mode 5 /til notified NRC by tellon Tech Spec change request will be obmitted to ensure greater than 2% shutdown margin 3/HANLOW, J.P. Arkansas Power & Light Co. 80/03/19 ip
 - 24020342 Forwards LER 80-013/03L-0 IRIMBLE, D C Arkansas Power % 1:ght Co 80/03/28 1p
 - \$004020346 LER 80-013/03L-0 on 800229.during mode 5 operation, reactor cooling sys chloride concentration found to be approx 0 5 ppm. violating Tech Spers Probably caused by batch contaminated during maint on safety injection check valve PENDERGRAFT,R Arkansas Power & Light Co 80/03/28 ip
 -)4080577 Forwards LER 80-016/01T-0 RIMBLE, D.C. Arkansas Power & Light Co. 80/04/01 ip
 - 1004080576 LER 80-016/017-0 on 800318.inconsistency identified between Tech Specs & FSAR sarety analysis Caused by failure of initial Tech Specs to determine safety analysis limits Reactivity balance calculation procedure revised SHIVELY, C.N. Arkansas Power 3 Light Co. 80/04/01 2pp

- 8004150605 Forwards LER WO 014/03L-0 TRINBLE, D.C. Mittanses Power * Light Co. 80/04/11 ip
- -8004150618 | E.P. 80-0147031-0 on 800313 during mode 5 operation, local leak rate testing at containment penetration 2V2 revealed excessive leak rate totweek valve actuation & heatup processes Caused by partially open inside isolation valve SHIVELY.C N Arkansas Power & Light Co. 80/04/11 ip
- 8004220691 Forwards LFR 80-017/03L-0 TRIMBLE.D.C. Arkansas Power * Light Co. 80/04/15 ip
- -8004220703 LER 80-017/03L-0 on 800316 during mode 3 operation. A steam generator pressure indicator 2 PI-1041-4N on Channel D failed high Caused by electronic output of pressure transmitter plant protection sys failing high SHIVELY C N Artansas Power & Light Co 80/04/15 ip
- DOCKET 50-369 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical
 Equipment, providing guidance re methods for compliance
 ROSS:DF Division of Project Management 80/02/05 7
- 8004040017 Submits add] guidance to NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degiee of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 800423005B Requests info is auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include IRC approval prior to issuance of CL W/ent! ROSS.D F Division of Project Management 80/03/10 53pp
- 8004140123 Forwards request for addl info re NRC review of LGCA analyses provided in plant FSAR Revisions 29.33.34 & 36 Info should be provided by 800421 BARR.R. L. Light Water Reactors Branch 2 80/03/19 4pp
- 8004(70327 "Thi-Plus One Toward a Safer Nuclear Power Program "
 # Dute Power Co 80/03/26 13pp
- 8004070234 Forwards Page 3-10 / Table 3 1-1 of offsite dose caluculation manual correcting typographical errors Also forwards Page B-1 inadvertently omitted from 800317 submittal or manual PARKER.W O Duke Power Co 80/03/27 ip
- --8004070234 Pages 3-10 5 B-1 & Table 3 1-1 of offsite dose calculation manual * Duke Power Co 80/03/27 3pp
- 9004150051 Summary of BOD327 meeting w/util in Bethesda.MD.re scheduling of initial fuel loading & license application BIRKEL.R A Light Water Reactors Branch 2 80/03/28 5pp
- 8004080366 Forwards add1 info requested by NRC 800129 ltr.re emergency diesel generator reliability / implementation of NUREG-0660 recommendations PARKER, W O Duke Power Co 80/04/03 11pp
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS, D M Dute Power Co 80/04/03 11pp
- 8004080455 Forwards "316(b) Predictive Study of Impingement & Entrainment" A "Consolidated Overview, Baseline Yr 1978-79, " as requested PARKER, W O Duke Power Co 80/04/04 1p
- --8004080461 "Consolidated Overview, Baseline Yr 1978-79 " * Duke Power Co 80/03/31 300pp
- 6004140348 Forwards response to NRC 800219 request for info re environ Qualification of containment pressure transmitters to "Qualification Test Rept on Three Model 326A Differential Pressure Transmitters & Remote Sensors." Vols 1 & 2 PARKER, W D Duke Power Co 80/04/08 4pp

- --B004140354 "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vol 1, Revision D HATMAKER, D F. DAVIES, L. M. Wyle Laboratories 43904-1 V1 RD 78/07/06 43pg
- --8004140358 "Gualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vol 2.Revision C BROWN, J , CAMPBELL, E R Wgle Laboratories 43904 V2 RC 78/07/06 Loopp
- 8004280072 Discusses review of qualitative evaluation of combined failure of 10-inch accumulator line & impinged six-inch hot leg injection line Requests sensitivity analysis of 10-inch cold leg spiit break wisix-inch spiit break LOCA BAER.R L Light Water Reactors Branch 2 80/04/09 3pp
- 8004280076 Ack receipt of util 791226 response to NRC request for independent field audit of installed electrical sys & equipment Util review lacks performance of detailed field audit by independent group BAER.R L Light Water Reactors Branch 2 80/04/09 App
- 8004300142 Requests submittal of three listed items on NRC docket to provide retrievable technical ref sources on guide tube wear Info should be incorporated in next revision to FBAR BAER,R L. Light Water Reactors Branch 2 80/04/11 3pp
- 8004220720 Incorporates three 1tr refs into 791214 response to NRC 790911 request for info re fuel assembly guide thimble tube wear Refs consist of TM Anderson 780912, 1015 & 790627 ltrs to DO Eisenhut PARKER, W O Duke Power Co 80/04/16 1p
- 8004270493 Forwards "Statistical Analysis of Mechanical Properties for Containment Plates & Weld Filler Metal " & drawings re Ames Lab statistical design parameters for containment Drawings available in Central Files only PARKER.W O Duke Power Co 80/04/24 2pp
- --8004270501 "Statistical Analysis of Mechanical Properties for Containment Plates & Weld Filler Metal " HUFFAKER.T Duke Power Co IRLEYN.K & Consumers Power Co BO/04/21 Spp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0A0 clearance under Faderal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004030192 Forwards info in support of standby shutdown facility Encl withheld (ref 10CFR2 790) PARKER.W D Duke Power Co 80/03/31 1p
- 8004180273 Forwards Revision 7 to modified amended security plan Plan withheld (ref 1000R2 790) PARKER,W O Duke Power Co 80/04/14 1p
- 9 Adjudicatory correspondence
- 8004230078 Forwards 800328 SECY-80-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements If amend approved effect on NRC case re spant fuel transportation & storage will be provided HOEFLING, R K Hearing Branch 4 80/04/01 ip
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Soard notification OOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004180432 Forwards NRC 800403 ltr w/encl commercial newspaper advertisement re resumption of evidentiary hearings NRC wishes to notify public officials of counties in which proposed alternate routes are located KETCHEN
- --B004180441 Notifies of resumption of evidentiary hearings re amend of License BNM-1773 Proposed action is to transport up to 300 spent fuel assemblies from Oconee nuclear facility to McOutre nuclear facility Commercial newspaper notice encl ROUBE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/04/03

- 8004150197 Forwards in Spitalny, Un Donohew CR Harotta & E Lantz profiled testimonies re amend to License SNH-1773 for Oconee spent fuel transportation & storage at McGuite KETCHENIE G Hearing Brinch 4 80/04/11 2pp
- --8004160179 Prefiled textimony re 800428 hearing Updatos license ame record re spent fuel handling 's storage alternatives status of NRC spent fuel Cash review 'pin compaction application SPITALING S Advanced Fuel / Spent Fuel Licensing Branch 80704/11 Spp
- --8004160210 Supplemental NRC rept "Spent Fuel Storage of Oconee Spen Fuel at McGuire Nuclear Station - Unit 1 " * Commission 60/04/11 2pp
- --8004160219 Prefiled tostimony re doses caused by Oconee spent fuel assembly rupture while stored at McOurre spent fuel pool Converts MRC 800208 arridayits to question & answer format Profi qualifications encl DONDHEW. J N Environmental Evaluation Branch 80/04/11 13pp
- --8004160221 Testimony re ASLB questions at Transcript A027 & 4432-47 concerning whether fuel stored in McGuire spent fuel pool would remain subcritical it cask falls onto pool Converts NRC 600208 affidavits to question > answer format MARDITA.C R Office of Nuclear Material Safety & Safeguards 60/04/11 2pp
- --B004160224 "NRC Criticality Analysis of McGusre Spent Fuel Pool Containing Oconee Spent Fuel for Cask-Drop Accident " Prof qualifications encl MAROTTA.C R Office of Nuclear Material Safety & Safeguards 80/04/11 10pp
- ---BOD4160227 Testimony re ASLB questions at Transcript 4027 & 4432-47 concerning whether fuel stored in McGuire spent fuel pool would remain subcritical it cask falls onto pool Converts NRC BOD208 affidavits to question & answer format LANTZ.E Division of Operating Reactors BO/D4/11 2pp
- --B004i60230 "Supplemental Criticality Analysis for Proposed Transfer Spent Fuel From Occide to McGuire" Prof qualifications encl LANTZ.E Division or Operating Reactors 80/04/11 Spp
- --B004160235 Affidavit re occupational doses caused by Oconee spent fi assembly rupture, at 270 days in age, when stored in McGuire spent fuel pool Completes NRC response to ASLB 791031 order Supporting documentation enc! DDNUHEW, J.N. Environmental Evaluation Branch B0/04/10 &pp
- --B004160240 Affidavit re occupational doses caused by Occupa spent for assembly rupture, at 40 days in age, when stored in McQuire spent fuel pool Completes NRC response to ASLU 791031 order Supporting documentation encl
 DONOMEM.J N Convironmental Evaluation Branch 80/04/10 App

- 8004150070 Forwards IE Info Notice BD-13 "GE Type SBM Control Switches Defective CAM Followers 'No specific action or response required
- required
 G'REILLY, J F Region 2. Atlanta, Office of the Director 80/04/02
 200
- 8004240249 Forwards IE Into Notice 80~14 "Safety Suggestions From Employees" No action required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/02
- 8004180326 Forwards IE Circulai 80-07, "Problems W/HPCI Turbine Dil Sys "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03 200
- 8004230132 Forwards IE Bulletin 77-03A 'Longitudinal Held Defects in ASME SA-312 Type 304 Stainless Steel Pipe " Action required D'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/04/04
- 8004180358 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/07
- S Reportable occurrences. LERs 3 related correspondence
- 8004080101 Part 21 rept ie deviation which could result in reduction of integrity of RCPB Valve bonnet flange weldment was liquid penetrant examined on one side only Personnel will complete examination
 MILLER.H L Dute Power Co 80/03/11 3pp
- 8004020348 Forwards Significant Deficiency Rept SD 369-370/80-02 re steam generator narrow range level transmitter cables PARKER.N O Duke Power Co 80/03/27 tp
- --B00402035B Significant Deficiency Rept SD 349-370/80-02 re failure of steam generator narrow range level transmitter cables to meet environ qualification requirements Sixteen cables in Unit 1 uii) be replaced & new cables installed in Unit 2 a Duke Power Co 80/03/27 ip
- DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 9004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS.D F Division of Project Management 90/02/05 7pp
- 8004040017 Submits addi guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment" Requests review or equipment qualification documentation to identify degree of compliance RQSS.DF D'vision of Project Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Tast Force review of TML-2 accident info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of DL W/encl RGSS.D F Division of Project Management 80/03/10 33pp
- 8004140123 Forwards request for addl info re NRC review of LOCA analyses provided in plant FSAR Revisions 29.33.34 & 36 Info should be provided by 800421 BAER.R L Light Water Reactors Branch 2 80/03/19 4pp
- 9004170327 "THI-Plus One Toward a Safer Nuclear Power Program " * Duke Power Co 90/03/26 13pp
- BG04070234 Forwards Page 3-10 1 Table 3 1-1 of offsite dose caluculation manual.com; ecting typographical errors Also forwards Page B-1 inadvertently omitted from 800317 submittal of manual PARKER, H O Duke Power Co 80/03/27 ip
- --8004070236 Pages 3-10 2 B-1 & Table 3 1-1 of offsite dose calculation manual * Duke Poter Co 90/03/27 3pp
- 8004150051 Summary of B00327 meeting w/util in Bethesda.MD.re scheduling of initial fuel loading & license application review BIRKEL.R A Light Water Reactors Branch 2 80/03/28 5pp

- 8004080366 Forwards add1 info requested by NRC 800129 ltr.re emergency dissel generator reliability & implementation of NUREG-0660 recommendations
 PARKER. U D Duke Power Co 80/04/03 lipp
- BOO414043D Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS,D M Dute Power Co BO/04/03 lipp
- 8004080455 Forwards "316(b) Predictive Study of Impingement & Entrainment" & "Consolidated Overview Raseline Yr 1978-79."
- as requested
 PARKER, N D Duke Power Co 80/04/04 1p
- --8004080459 "316(b) Predictive Study of Impingement & Entrainment "

 4 Duke Power Co 78/10/31 300pp
- --8004680461 "Consolidated Overview, Baseline Yr 1978-79 "

 4 Duke Power Co 80/03/31 300pp
- BOO414034B Forwards response to NRC BOO219 request for info re environ qualification of containment pressure transmitters & "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vols 1 & 2 PARKER, H O Duke Power Co 80/04/08 4pp
- --B004140354 "Gualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors," Vol 1.Revision B HATMAKER, D. F., DAVIES, L. M. Wyle Laboratories 43904-1 VI RB 78/07/06 43pp
- ---B00414035B "Qualification Test Rept on Three Model 386A Differential Pressure Transmitters & Remote Sensors:" Vol 2.Revision C BROWN, J., CAMPBELL.E R Wyle Laboratories 43904 V2 RC 78/07/06 Loopp
- BOD42BOO72 Discusses review of qualitative evaluation of combined failure of 10-inch accumulator line & impinged six-inch hot leg injection line Requests sensitivity analysis of 10-inch cold leg split break wisix-inch split break LOCA BAER.R L Light Water Reactors Branch 2 BO/04/09 3pp
- HO04280076 Ack receipt of util 791226 response to NRC request for independent field audit of installed electrical sys & equipment Util review lacks performance of detailed field audit by independent group BAER,R L Light Water Reactors Branch 2 80/04/09 4pp
- B004300142 Requests submittal of three listed items on NRC docket to provide retrievable technical ref sources on guide tube wear Info should be incorporated in next revision to FBAR. BAER.R i. Light Water Reactors Branch 2 80/04/11 3pp
- 8004220720 Incorporates three ltr refs into 791214 response to NRC 790911 request for info re fuel assembly guide thimble tube wear Refs consist of TM Anderson 780912,1015 & 790627 Itrs to DD Eisenhut PARKER.N O Duke Power Ca 80/04/16 ip
- 8004290493 Forwards "Statistical Analysis of Mechanical Properties for Containment Plates & Weld Filler Metal " & drawings re Ames Lab statistical design parameters for containment Drawings available in Central Files only PARKER, N O Duke Power Co 80/04/24 2pp
- ---8004290501 "Statistical Analysis of Mechanical Properties for Containment Plates & Weld Filler Metal " HUFFAKER: T Duke Power Co TRLEYN. K S Consumers Power Co 80/04/21 5pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time setimates, requested by NRC 791224 ltr, has been postponed pending GAD clearance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 App.
- 8004030152 Forwards info in support of standby shutdown facility Encl withheld (ref 10CFR2 790) PARKER, H O Duke Power Co 80/03/31, 1p
- G Adjudicatory correspondence
- BO0423007B Forwards B0032B SECY-B0-166 requesting amend to irradiated reactor fuel in-transit physical protection requirements if amend approved affect on NRC case re spent fuel transportation & storage will be provided HOEF4.INO,R K Hearing Branch 4 B0/04/01 ip

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification QQSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004180516 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells " Lists charcoal filters for which visual insp was performed No significant charcoal leakage found PARKER.W O Duke Power Co 80/03/21 2pp
- 8004150511 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/31
- B0040B06ii Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oll Addition & Onsite Supply " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 60/04/01
- 8004i50070 Forwards IE Info Notice 80-13, *GE Type SBM Control Switches Defective CAM Followers * No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees " No action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 200
- 8004180326 Forwards IE Circular 80-07, "Problems H/HPCI Turbine 011 8ys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/03 2pp
- 8004230132 Forwards IE Bulletin 79-03A "Longitudinal Wald Defects in ASME 8A-312. Type 304 Stainless Staol Pipe " Action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180358 Forwards IE Bulletin BO-OB. "Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/07 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004080101 Part 21 rept re deviation which could result in reduction of integrity of RCPD Valve bonnet flange weldment was liquid penetrant examined on one side only fersonnel will complete examination
 MILLER, H. L. Duke Power Co 80/03/11 3pp
- 8004020348 Forwards Significant Deficiency Rept SD 369-370/80-02 re steam generator narrow range level transmitter cables PARKER, W O Duke Power Co 80/03/27 1p
- --8004020358 Significant Deficiency Rept SD 369-370/BO-02 re failure of steam generator narrow range level transmitter cables to meet environ qualification requirements. Sixteen cables in Unit 1 will be replaced & new cables installed in Unit 2 * Duke Power Co 80/03/27 ip
- DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Bafety-Related Electrical Equipment," providing guidance re methods for compliance ROSED F Division of Project Management.
- 8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp

- 8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II owners gloup in Sam Jose CA to discuss Mark II Consec Test Program, 4T c/o tests & foreign tests ELTANILA.F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II dwners group. NRC consultants & GE in San Jose.CA to discuss Mark II Creare test program.4T C/O & foreign tests Topics are proprietary Agenda encil ELTAWILA.F Containment Systems Branch 80/03/10 12pp
- 8004070097 Advises that ASME Code Case N-241 is acceptable & may be used in hydrostatic testing program to exempt certain piping from testing PARRIO D Light Water Reactors Branch 3 80/03/17 2pp
- 8004040474 Summary of 800227 meeting w/Mark II dwners group re status of several long-term program tasks, including Tasks A 17 & A 16 & task related to utilization of foreign test data ELTAWILA:F Containment Systems Branch 80/03/18 104pp
- B004100102 Requests contibled set of P&IDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days

 KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/20
- 8004150316 Ferwards revised pages constituting Revision 13 to CE-1-A, OA program Revisions reflect recent organization title changes NAUDHTON.W F Commonwealth Edison Co 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to GA program
 Revisions reflect recent organizational title changes
 4 Commonwealth Edison Co CE-1-A RIJ 80/04/04 7pp
- 8004190416 Forwards ASME Section XI repairs & revisions rept,Procedure L 9 0 P 3 f.Revision O HATTS.T E Componwealth Edison Co 80/04/03 fp
- --8004150419 Procedure for ASMC Section XI repairs & revisions Repair/ revision Repts 5-8 & 23-30 encl * Commonwealth Edison Co 79/04/11 17pp
- 8004280051 Discusses NRC caseload forecast panel 800324-27 site visit to review status of const & readiness for fuel loading at Unit 1 NRC projects fuel load date two months later than util List of attendees at 800326-27 meetings encl BOURNIA:A Light Water Reactors Branch 3 80/04/09 Spp
- 8004300064 Summary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of NHC concerns on data from Creare tosts & foreign full-scale test programs & relationships w/ Mark II designs ELTANILA.F Containment Bystems Branch 80/04/14 22pp
- 8004230479 Requests guidance on approach required to complete SER Fuel is scheduled for loading on 800930 NRC forecast panel audit approves Nov 1980 fuel loading Expediting review would be appreciated PEOPLES, D. L. Commonwealth Edison Co. 80/04/15 2pp
- BO04250427 Forwards response to NUREG-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lasalle County site-specific emergency plan PEOPLES,D L Commonwealth Edison Co 80/04/15 60pp
- ---8004250428 "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities "

 * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280410 Forwards draft radiological ETS & draft "Onsite Dose Calculation Manual" Urges that App I matis be reviewed in conjunction w/ongoing operating plant review PEOPLES, D. L. Commonwealth Edison Co. 80/04/21 2pp
- --8004280412 Draft radiological ETS, Sections 1-6 * Commonwealth Edison Co 78/10/31 100pp
- ---8004280414 Draft Unsite Pose Calculation Manual * Commonwealth Edison Co 79/12/20 150pp
- F Becurity, medical, emergency & fire protection plans
- B004020413 Forwards NRC 800306 trip rept re 800228 sits visit to complete fire protection review B0URNIA,A Light Water Reactors Branch 3 80/03/10 ip

- --B004020419 Submits trip rept re B00228 site visit to complete fire protection review Only one area of concern exists re need for sprinklers Applicant committed to correct situation using one of three specified alternatives HARRISDY G Auvillary Systems 3 manch 80/03/04 Jpp
- B004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791826 ltr.has been postponed pending GAO clearance under Foderal Repts Act GRIMES, B.K. Emergency Preparedness Task Force 80/03/11 App
- 8004010352 Forwards positions on fire protection issue Provides commitments made at 800207-08 meetings DELGEORGE, L O Commonwealth Edison Co 80/03/24 22pp
- 8004070273 Forwards Pages C-26 & C-27 of Revision 5 to security plans, omitted from 800321 submittal Encl withheld (ref 10CFR2 790)
 PEQPLES, D.L. Commonwealth Edison Co. 80/04/02 1p
- I Financial information
- 8004140213 Responds to 791013 request for financial info Prospectus for most recent security issue, exhibits / testimony re plant investment data, cost of capital, rate of return. & economic conditions encl
 DELGEORGE, L 0 Commonwealth Edison Co. 80/02/28 600pp
- ν Utility Final Sarety Analysis Report (FSAR) & amends
- 8004080522 Forwards affodavit stating that distribution of Amend 48 to FSAR has been made in accordance w/OD Parr 7/0526 ltr DELGEORGE.L O Commonwealth Edison Co 80/04/02 2pp
- @ Inspection reports: If Bulletins & correspondence
- B004070172 Forwards [E Insp Rept 50-373/80-01 on B00109-11 & 15 No noncomplianace noted DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/02/07 2pp
- --8004070174 IE Insp Rept 50-374/80-01 on 800109-11 & 15 No noncompliance noted Major areas inspected radiation protection & raduaste mgt programs FISHER.WL Region 3. Chicago, Fuel Facility & Materials Safety Branch MILLER.DE Region 3. Chicago, Office of the Director 80/01/31 4pp
- 8004040036 Forwards If Insp Repts 50-373/80-03 & 50-374/80-02 on 800117-18 No noncompliance noted FIGRELLI.G Region & Chicago, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8004040030 IE Insp Repts 50-373/80-03 \$ 50-374/80-02 on 800117-18 No noncompliance noted Major areas inspected status no safety-related portions of heating, entilation b air conditioning sys
 WILLIAMS, C C JUNES, C E Region 3. Chacago, Office of the Director 80/02/11 4pp
 - 94080629 Forwards IF Insp Repts 50-373/80-04 & 50-374/80-03 on 90129-31 & motice of violation IORELLI.G Region 3. Chicago, Reactor Construction & Engineering apport Branch 80/02/60 2p
 - 004080635 Notice of violation ≯rom insp on 800129731 ★ Region 3. Chacago. Office of the Director 80/02/15 i
 - 8004080647 IE insp Rept: 50~3/3/80-04 t 50~3/4/80-03 on 800129-31 Noncompliance noted inadaquate updating of specs & drawings YIN.I I , DANIELSON.D H Region 3, Chicago, Office of the Director 80/02/15 Spp
 - 04090272 Forwards IE Inep Repts 50-373/80-09 & 50-374/80-05 on 800207-08 No noncompliance noted FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/25 2pp
 - 8004090278 IE Insp Repts 50-973/80-09 & 50-374/80-05 on 800207-08 No noncompliance noted Major areas inspected suppression pool & reactor recirculating sys mods MILLIAMS.C C. NELSLER.J H. Region 3. Chicago, Office of the Director 80/02/21 App

- 8004080182 Forwards If Insp Repts 50-373/80-06 % 50-374/80-06 on 800130-31 1 0∠01 No noncompliance noted FIGRELLI.6 Region 3. Chicago Reactor Construction % Engineering Support Branch 83/02/27 2p
- --8004080190 IC Insp Repts 50-3/3/86-06 / 50-374/80-06 on 800130-31 & 0201 No noncompliance noted Major areas inspected const status, electrical testing / electrical records HAVES.D R Region 3. Chicago. Reactor Derrations Nuclear Support Branch BARRETT P n. Region 3. Chicago, Office of the Director 80/02/25 Spp
- BOO4180187 Forwards 1E Insp Rept 50-3/3/80-05 on 800101-31 & natice of violation HEISHMAN, R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/03/04 epp
- --8004180199 Notice of violation from insp on 800101-31 * Region 3, Chicago, Office of the Director 80/02/26 ip
- --8004180203 IE Insp Rept 50-3/3/80-05 on 800101-31 Noncompliance noted failure to control temporary electrical leads to permanent station equipment SPESSARD, R. L. WALKER R. D. Region G. Chicago, Office of the Director 80/02/28 17pp
- 8004100118 Forwards IC Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response regulared
- required

 KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/07
 to
- BO04140119 Forwards response to IE Bulletin BO-03, "Loss of Charcoal from Btd Type II, Two-Inch Tray Advorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES.D L Commonwealth Edison Co 80/03/20 Spp
- 8004180157 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/31
- BOD4080696 Forwards IE Circula: 80-05, "Emergency Diesel Generator Lubricating Dit Addition & Onsite Supply " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/01
- 8004150014 Forwards IF Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required KEPPLER, J G Region 3, Chicago. Dffice of the Director 80/04/02
- B0041B0030 Forwards attachments to IE Circular B0-03, "Protection From Toxic Gas Hazards," inadvertently umitted from 800304 transmittal KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/02
- 8004220073 Forwards 1E Info Notice 80-14, "Bafety Suggestions From Employees " No action lequired KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Bil Sys " No written response required KFPPLER.J C Region 3, Chicago, Office of the Director 80/04/03
- B004220069 Forwards IE Bullotin 60-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. 9 Region 3, Chicago, Office of the Director B0/04/09 In
- 8004110023 Forwards IF Bulletin 80-07, "BWR Jet Pump Assembly Failure" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/07
- B004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME BA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07 ip

- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0580, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS DF Division of Project Management B0/02/05 7pp
- 8004040017 Submits addl guidance to NUREC-0588, "Interim Staff Position on Environ Qualification of Saroty-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II owners group in San Jose CA to discuss Mark II Creace Test Program, 4T c/o tests & foreign tests ELTAWILA:F Containment Systems Branch 80703/10 12pp
- B004030122 Notification of B00326-27 meeting w/Mark II owners group. NRC consultants & GE in San Jose.CA to discuss Mark II Creare test program.4T C/O & foreign tests Topics are proprietary Agenda encl ELTAWILA.F Containment Systems Branch B0/03/10 12pp
- 8004070097 Advises that ASME Code Case N-241 is acceptable & may be used in hydrostatic testing program to exempt certain apping from testing PARR.O D Light Water Reactors Branch 3 80/03/17 2pp
- 8004040474 Summary of 800227 meeting w/Mark II owners group re status of several long-term program tasks, including Tasks A 17 & A 16 & task related to utilization of foreign test data ELTAWILA,r Containment Systems Branch 80/03/18 104pp
- 8004i0D102 Requests controlled set of PAIDs for each plant Submittal should be forwarded to attention of Region 3 incident response ctr within 20 days
 KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/20
- 8004150316 Forwards ravised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title changes NAUGHTON.W F Commonwealth Edison Co 80/04/02 1p
- ---8004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent dryamizational title changes * Commonwealth Edison Co CC-1-A RI3 80/04/04 7pp
- 8004150416 Forwards ABME Section XI repairs & revisions rept,Procedure LSQP 3 1.Revision D WATTS/T E Commonwealth Edison Co 80/04/03 ip
- ---B004150419 Procedure for ASME Section XI repairs & revisions Repair/ revision Repts 5-8 & 23-30 encl * Commonwealth Edison Co 79/04/11 17pp
- 8004280051 Discusses NRC caseload forecast panel 800326-27 site visit to review status of const & readiness for fuel loading at Unit 1 NRC projects fuel load date two months later than util List of attendees at 800326-27 meetings encl 800RNIA, A Light Water Reactors Branch 3 80/04/07 5pp
- 8004300064 Summary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of NRC concerns on data from Creare tests & foreign full-scale test programs & relationships w/ Mark II designs ELTAWILA:F Containment Systems Branch 80/04/14 22pp
- 8004250427 Forwards response to NUREG-0578 & "Design Criteria & Conceptual Design Description for Technical Support Ctrs for Facilities" for review Util emergency plan will be submitted w/Lesalle County site-specific emergency plan PEDPLES.D L Commanwealth Edison Co 80/04/15 &Opp
- --8004250428 "Design Criteria & Conceptual Besign Description for Technical Support Ctrs for Facilities " * Bechtel Power Corp (subs of Bechtel Corp) 79/12/26 32pp
- 8004280410 Forwards draft radiological ETS & draft "Unsite Dose Calculation Manual" Urges that App I matls be reviewed in conjunction w/ongoing operating plant review PEOPLES.D L Commonwealth Edison Co 80/04/21 2pp
- --8004280412 Draft radiological ETS.8sctions 1-6 * Commonwealth Edison Go 78/10/31 100pp

- ---8004280414 Braft Unsite Dose Calculation Manual
 # Commonwealth Edison Co 75/12/20 150pp
- F Security, medical, emirgency * fire protection plans
- B004020413 Forwards NRC 80030s trip tept re 800228 site visit to complete file protection review BOURNIA,A Light Water Reacfors Branch 3 80/03/10 1p
- --8004020419 Submits trip rept to 80022B site visit to complete fire protection review Only one area of concern exists re need for sprinklers Applicant committed to correct situation using one of three specified alternatives
 HARRISON.G Auxiliary Systems Branch 80/03/06 3pp
- 80040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr. has been postponed pending GAO clearance under Federal Repts Aut.

 GRIMES.B K Emergency Preparedness Tas' Force 60/03/11 4pp
- 8004010352 Forwards positions on fire protection issue Provides commitments made at 800P07-08 meetings DELGEORGF, L D Commonwealth Edison Co 80/03/24 22pp
- B004070273 Forwards Pages C-26 & C-27 of Revision 5 to security plans, omitted from B00324 submittal Enci withheld (ref 10CFR2 790)
 PEOPLES, D. L. Commonwealth Edison Co. B0/04/02 ip
- I Financial information
- 8004140213 Responds to 791013 request for financial info Prospectus for most recent security issue, exhibits & testimony re plant investment data, cost or capital, rate of return, & economic conditions end | DELOEDROE, LO Commonwealth Edison Co 80/02/28 600pp
- K Utility Final Safety Analysis Report (FSAR) 5 amends
- 8004080522 Forwards affidavit stating that distribution of Amend 48 to FSAR has been made in accordance w/OD Parr 770526 ltr DCLGEORGE, L O Commonwealth Fdison Co Ø0/04/02 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 8004040036 Forwards IE Insp Repts 50-373/80-03 & 50-3/4/80-02 on B00117-18 No noncompliance noted FIGRELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/02/15 2pp
- ---B004040040 IE Insp Repts 50-3/3/80-03 & 50-3/4/80-02 on B00117-18 No moncompliance noted Major aleas inspected status re safety-related portions of heating, ventilation & air conditioning sys
 HILLIAMS, C. C., JONES, C. E. Region 3, Chicago, Office of the Director B0/02/11 4pp

- ---B0040B0190 IE Insp Repts 50-3/3/B0-06 & 30-374/B0-06 on B00130-31 & 0201 No noncompliance noted Major areas inspected const status, electrical testing % electrical records HAYES.D W Region 3 Chicago, Reactor Operations Nuclear Support Branch BARRETT, P A Region 3, Chicago, Office of the Director B0/02/25 5pp
- 8004100118 Forwards IF Into Notice 80-08, "States Go Sliding Link Electrical Terminal Block ' No specific action or response required KEPPLER, J. G. Region 3, Chicago, Diffice of the Director 80/03/07
- 8004140119 Forwards response to IE Bulletin 80-03. "Loss of Charcoal from 8td Type II. Two-Inch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES, D.L. Communwealth Edison Co. 80/03/20 5pp
- BOO4150159 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31
- BO04080686 Forwards IF Circular 80-05, 'Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply "No written response required KEPPLER, J G Region G. Chicago Office of the Director BO/04/01
- B004150014 Forwards IE Info Notice B0-13, "GE Type SBH Control Ewitches Defective CAM Followers " No specific action or response required KEFPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Haiards," inadvertently omitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J. G. Region 3, Chicago, Office of the Birector 80/04/02 in
- 8004220324 Forwards LE Circular 80-07. "Problems W/HPC1 Turbine Gil Sys " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/03 to
- BO04220069 Forwards IE Bulletin 80-08. 'Eram of Containment Liner Penetration Welds " Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/09 19
- 8004110023 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required KEPPLER,J C Region 3. Chicago. Office of the Director 80/04/07 1p
- 304230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASNE SA-312. Type 304 Stainless Steel Pipe" Action required KEPPLER. J. G. Region 3. Chicago, Office of the Director 60/04/07 is
- S Reportable occurrences, LERs & related correspondence
- 8004030173 Ack receipt of 800227 final deficiency rept re reactor containment structural steel Review will be completed during future insp FiORELI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/03/19 ip
- DOCKET 50-376 NORTH COAST NUC PLANT
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in radiological emergency planning & preparedness distributed as Buard notification GDSSICKL V Office of the Executive Director for Operations

- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B004040031 Advises of issuance of NVREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSS_D F Division of Project Management B0/02/05 7pp
- 8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance RGSS.D F Division of Project Management 80/02/21 Spp
- 800423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include IRC approval prior to issuance of DL Wiencl ROSS.D F Division of Project Management 80/03/10 53pp
- B004020206 Refers to enc) ltr from EB Carrier.State Historic Preservation Officier.concerning field survey for archeological resources at plant const site Literature search should be made & NRC informed of survey results BALLARD.R L Environmental Projects Branch 1 80/03/19 2pp
- 8004150420 Forwards proposed revisions to "Prooperational Environ Surveillance Program "OL stage environ rept will be amended in future to include changes ASWELLD L Louisiana Power & Light Co 80/04/11 Spp
- --8004150424 Proposed revisions to "Preoperational Environ Surveillance Program " + Louisiana Power & Light Co 80/04/11 78pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.hos been postponed pending OACI clearance under Federal Repts Act
 ORINES.B K Emergency Preparedness Task Force 80/03/11 4pp
- O Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OBSBICK.L V Office of the Executive Director for Operations 80/04/02 34p
- 800417024B Forwards NRC 800229 interrogatories & request for documents directed to LA Consumer League Ack informal agreement to respond within one wk MCGURREN.II J Hearing Branch 1 80/04/19 1p
- H General correspondence
- 8004030352 FOIA request for info re facility FSAR & documents re NRC regulations including App I of 10CFR20 KRAUSE, L. Affiliation Unknown 80/03/07 1p
- 8004030395 Responds to FOIA request for info re facility FBAR & documents re NRC regulations including App I of 10CFR20 Forwards documents listed in App A Document 5 includes App I M/O encl FELTON, J K Division of Rules and Records 80/03/21 2pp
- I Financial information
- 8004220535 Annual Financial Rept 1979 * Middle South Utilities.Inc 79/12/31 40pp
- 8004250365 Forwards Annual Financial Rept 1979 ASWELL,D L. Arkansas Power & Light Co. 80/04/22 1p
- --8004250367 Annual Financial Rept 1979
 * Arkansas Fower & Light Co 80/02/15 24pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004240220 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required.
 SEYFRIT.K.V Region 4, Dallas, Office of the Director B0/04/02 to

- 8004220281 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/03 ip
- 8004220783 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 6A-312:Type 304 Stainless Steel Pipe " Action required BEYFRIT,K V Region 4, Dallas. Office of the Director 80/04/04 in
- 8004220228 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/07
- 8 Reportable accurrences, LERs & related correspondence
- 8004010343 Forwards final rept of Significant Deficiency 11 re switchgear breaker position switch operator defect ABWELL.D.L. Louisiana Power & Light Co 80/03/28 jp
- --8004010347 Final rept of Significant Deficiency 11,re switchgear breaker position switch operator defect Thirty-three breaker position switch perators replaced w/newly designed GE assembles Operators have guides preventing bending CRNICH.J. MILHISER.R.J. HART.J. Louisianu Power & Light Co 80/03/18 2pp
- 8004070308 Forwards final deficiency rept re noncompliance to welding requirements for heating, ventilation & air conditioning seismic support hanger to embedded plates
 ABMELL.D.L. Lowisiana Power & Light Co. 80/03/31 1p
- --8004070310 Final deficiency rept re noncompliance to welding requirements for heating, ventilation & air conditioning seismic support hanger to embodded plates All affected welds repaired & insps documented for QA files CRNICH.J. MILHIBER.R.J. HARTNETT.R.A. Louisiana Power & Light Co. 80/03/31 3pp
- 8004250347 Forwards final deficiency rept re Significant Const Deficiency 13 re reactor containment bldg dome concrete ASWELL.D L. Arkansam Power & Light Co. 80/04/21 ip
- --8004250352 Final deficiency rept re improper consolidation of concrete in lower portion of wall in reactor containment bldg dome Caused by improper random vibration during concrete placement CONICH.J. MILHISER.R.J. HARTNETT.R.A. Arkansas Power & Light Co. 80/04/08 App
- B0042B0574 Forwards final rept of Significant Const Deficiency 13 All corrective action repairs have been completed & verification testing accomplished ASMELL-D.L Louisiana Power & Light Co 80/04/21 ip
- --8004280605 Final rept of Significant Const Deficiency 13 re defects in containment bldg dome concrete Caused by improper random vibration due to vibrators that were inadequate in size & number Qualified job superintendent will be provided CRNICH, J. MILHISER, R. J., HARINETT, R. A. Louisiana Power & Light Co. 80/04/08 4pp

DOCKET 50-384 INDONESIA RESEARCH REACTOR

- P. Operating license stage documents & correspondence
- 8004220601 Request that License R-121 be amended to authorize possession only Core fuel will remain inside reactor until NRC approval for dismantling is obtained ADAMSON,R W California Polytechnic State Univ. 79/11/05 ip
- DOCKET 50-387 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 800404003i Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for Compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004040017 Bubmits addi guidance to NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSB,D F Division of Project Management, 80/02/21 Spp

- 8004020446 Notification of 800326 / 27 meeting w/representatives from Mark II owners group in 5an Jose,CA to discuss Mark II Creace Test Program,4T (/o tests // foreign tests ELTAWILA,F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-2/ meeting w/Mark II owners group, NRC consultants & QE in San Jose,CA to discuss Mark II Creare test program.4T C/O & foreign tests Topics are proprietary Agenda enci ELTAWILA,F Containment Systems Branch 80/03/10 12pp
- 8004080654 Forwards summary of 800228 meeting w/util re plant-unique containment program
 PARR.O D Light Water Reactors Branch 3 80/03/14 ip
- --8004080660 Summary of 900228 meeting w/util BNL,KWU,KFK,SRI Intl, Bechtelr,WS Corp & CNSNS to discuss plant-unique containment program List of attendees & agenda encl ELTAMILA:F Containment bystems Branch 80/03/07 18pp
- 8004040474 Gummary of 800227 meeting w/Mark II owners group re status of several long-term program tasks, including Tasks A 17 & A 14 & task related to utilization of foreign test data ELTANILA.F Containment Systems Branch 80/03/18 104pp
- 8004210410 Requests addl info re reactor sys to continue review of application for OL PARR.O D Light Water Reactors Branch 3 80/03/21 16pp
- B004100484 Responds to B00313 request for approval to use ABME Code Cases N-234 & N-235 during preservice examination of reactor pressure vessel Code cases acceptable PARR.D D Light Water Reactors Branch 3 B0/03/27 2pp
- 8004140352 Confirms NRC 800411 meeting w/util & ANL re operational biological monitoring programs & ET5 Proposed agenda encl CURTIS,N W Pennsylvania Power & Light Co 80/04/07 2pp
- 800414026B Comments on archaeology project at site Quotation for survey work is excessive Requests study to define satisfactory Phase I study of area
 KENT, BC Pennsylvania, State of 80/04/08 tp
- 8004300064 Bummary of 800326-27 meetings w/Mark II owners group in San Jose CA re discussion of NRC concerns on data from Creare tests & foreign full-scale test programs & relationships w/ Mark II designs. ELTAMILA,F Containment Sustems Branch 80/04/14 22pp
- 8004210335 Forwards Susquehanna River data in response to NRC 800407 request
 SKINNER: IF Pennsylvania Power & Light Co 80/04/15 ip
- --8004210340 "Demonstration for Brunner Island Steam Electric Station Units 1-3, Vols 1 & 2 " * EG & G. Inc. /7/05/19 200pp
- --8004210344 "Potential Effects of Brunner Island Steam Electric Station on Future Migrations of American Shad in Susquehanna River " * EQ & Q. Inc 77/08/13 23pp
- --8004210347 "Probabilities of Normal & Worst Case Conditions in
- ~-8004210347 "Probabilities of Normal & Worst Case Conditions in Susquehanna River during Critical Periods for Muskellunge Spawning & Smallmouth Bass Egg Survival & Development " * EQ & O. Inc 77/09/13 14pp
- --8004210349 "Assessment of Thermal Effects from Brunner Island Steam Electric Station Based on Newly Derived Max Neekly Average Temps " * EO & Or Inc 79/05/31 33pp
- ---B004210355 "Ecological Study of Effects of Brunner Island Steam Electric Station Cooling Water Intakes " JOHNSON, T D , PHOENIX, D R Roy F Weston, Inc. 77/11/18 78pp
- --8004210358 "Biological Burvey of Busquehanna River in Vicinity of York Haven,PA 1978 Terminal Rept " WURTZ,C B Charles B Wurtz 79/06/29 33pp
- ---8004210364 "Ichthyofaunal & Creel Census/Fishing Pressure Burveys in Vicinity of Brunner Island Steam Electric Station " DENONCOURT, R F R F Denancourt 78/05/31 141pp
- 8004280492 Comments on NUREG-0564, App B re archaelogical survey of Pond Hill Reservoir location Plan is preliminary rept containing no factual info re prehistoric met! that might be found SOLENBERGER: Bloomsberg State College BD/04/17 3pp

- D. NAC Draft/Finel Environmental Statements, supply / correspondence
- P004220079 Forwards diaff sup; to Mar 1980 DES 4/o enc1 SELLS D.F. Folimmental Projects Branch 2 80/03/31 8pp
- F Security, medical, emergency there protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 lis has been postponed pending GAG clearance under Feogral Repts Act GRIMES, B. K. Emergency Preparadness Task Force 80/03/11 App
- G Adjudicatory correspondence
- 8004080175 Requests to make limited appearance statement at 800320 hearing EMDRIZZI.D Affiliation Unknown 80/02/27 ip
- 8004100571 Notifies that N9C issued draft suppl to DES on 800331 Suppl b DES labelled NUREG-0564 DES issued b served on ASLB 5 all parties in June 1979 Draft suppl has been served on all persons on svr list Exceptions listed CUTCHINLUM Hearing Branch 3 80/03/03 1p
- 8004090571 Requests to make limited appearance statement on behalf of Taxpayers Association of Lackawanna County at licensing hearings Evening or weekend sessions should be held for citizen participation SCHUMACHER.K. Affiliation Unknown GO/O3/O7 ip
- BOO4080154 Requests to make limited appearance statement at)icensing hearings HEMMENDINGER, R Affiliation Univolum 80/03/10 2pp
- 8004300006 Requests notification of upcoming licensing hearings refacilities Hearings should be on weekends or evenings WESTON.K Affiliation Unknown 80/03/10 1p
- --8004300008 Requests notification of time & location of licensing hearing for facilities Portion of hearings should be scheduled on weekends or evenings to offer public better chance to attend FARBER.R C Affiliation Unknown 80/03/10 1p
- --8004300009 Requests notification of time & location of licensing hearings for facilities A to make limited appearance statement Hearings should be scheduled during evenings or weekends

 CAMILL. W. J. Affiliation Unknown 80/03/12 ip
- --8004300013 Requests notification of time 3 location of licensing hearings for familities & to make limited appearance statement Min of half of hearings should be scheduled at night or on weekends
 DORGUGH, R Affiliation Unknown 80/02/29 ip
- ---8004300019 Requests notification of time & location of licensing hearings for facilities & to make limited appearance statement Hearings should be scheduled on evenings & weekends

 LARING J Affiliation Unknown 80/03/12 ip
- --8004300023 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statement

 DETRICH B F Affiliation Unknown 80/03/10 ip
- 8004300025 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statement Postion of hearings should be held on evenings & weekends
 WINTER:A J. Affiliation Uninoum. 80/02/29 ip
- ---8004300029 Requests notification of time & location of licensing hearings for facilities Requests to make limited appearance statements Portion of hearings should be scheduled on on evenings of weekends FALLON-P Affiliation Uninoun 80/03/10 ip
- --B004300033 Requests notification or time & location of licensing hearings for facilities Requests to make limited appearance statement Portion of hearings should be scheduled for evenings on weekends
 LEM A Affiliation Unknown B0/03/10 ip

- --B004300035 Requests notification of time & location of licensing heatings for facilities Requests to make limited appearance statement Portion of heatings should be scheduled for evenings / weekends GRAY.PF Affiliation Unknown 83/03/10 (p
- --8004300037 Expresses concern that util is attempting to limit participation or intervendis at upcoming licensing hearings SKISLAK.5 Affiliation Unknown 80/03/10 1p
- ---8004300042 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings DUBJN.K J. Affiliation Unknown 80/02/29 1p
- --8004300046 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings DERAYMOND, J & Affiliation Unknown 80/03/10 Ip
- --8004300054 Requests making limited appearance statement concerning three motions on agenda of ASLS hearings in Wilkes-Barre,PA BUTCHKO,P R Affiliation Unknown 80/03/12 1p
- --B004300057 Requests notification of time & location of licensing hearings for facilities & to make limited appearance statement Poition of hearings should be held on evenings or weekends

 MERRILL.D K Affiliation Unknown 80/03/08 1p
- --8004300061 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Time for statements should be made available on weetends on evenings

 KRSYKWA,E J Affiliation Unknown 80/03/11 ip
- --8004300063 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Hearings should be held on evenings or weekends SMITH.D Affiliation Unknown 80/03/21 ip
- ---8004300066 Requests to make limited appearance statement at facility licensing hearings 5 notification of time & location of meeting Time should be made available on evenings or weekends for statements MACHAMER. G E Affiliation Unknown 80/03/10 1p
- --B004300067 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings HIGOINS.R M Affiliation Unknown B0/02/29 ip
- --8004300047 Requests to make limited appearance statement in favor of util motions at 800320 ABLB hearings in Wilkes-Barre,PA MURRAY.F Scranton, Univ of 80/03/12 ip
- --8004300070 Requests to make limited appearance statement at ASLB 800320 prehearing conference in Milkes-Barres PA THOMPSON,F Affiliation Unknown BO/03/12 1p
- --8004300971 Requests.on behalf of Citizens Lobby to make limited appearance statement at 800320 licensing hearing in Wilkes-Barre.PA
 BASALYOA.Q Affiliation Unknown 80/03/11 ip
- --B004300073 Requests to make limited appearance statement at facility licensing hearings & notification of time & location of meeting Time should be made available for statements on evenings & weekends
 BRAMSON.L Affiliation Unknown 80/03/13 ip
- --B004300074 Requests to make limited appearance statement at B00320 licensing hearing in Wilkes-Barre, PA ELLIGIT.C P Affiliation Unknown 80/03/17 1p
- --BDD4300080 Expresses concern re ASLB consideration of util motion to restrict public intervenors in licensing proceedings Full inquiry should be made re any attempts to demy public due process & rights within established NRC procedures BALZMAN,L. Friends of the Earth 80/03/13 ip
- --80043000B3 Requests to make limited appearance statement at facility licensing hearings & notification of time 8 location of meeting Time for statements should be made available on evenings or weekends SAUERS.M A. Affiliation Unknown 80/03/10 lp
- --8004300088 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings * Affiliation Unknown 80/02/29 1p

- 8004020040 Response to ASLB 800222 prehearing conference memorandum & order Allegos restrictive & biased agenda Urges discussion of onsite inspladvisability & reconsideration of denied contentions M/Centificate of Svc HALLIGAN, T. J. Citizens Against Nuclear Dangers 80/03/12 4pp
- 8004080143 Response to ASLB 800222 order setting oral argument re applicant motions to prohibit Susquehanna Environ Advocates 5 Environ Coalition on Nuclear Power from litigation of contentions Urgos to cancel argument W/Cortificate of Svc JONHERUD, J H Environmental Coalition on Nuclear Power 80/03/
- 8004080697 Request for expedited consideration of ASLB actions re discovery limits & decision-making Urges omission of util motions to restrict intervenois participation in 800320 oral argument Requests certification Certificate of Svc encl JDHNSRUD, J H Environmental Coalition on Nuclear Power 80/03/14
- 8004230006 Petition to raise specific issues at 800320 prehearing conference, re intervenors' motions for protective order on Contentions 1 & 2 % status as full party in proceeding SCHULTZ.0 R Susquehanna Environmental Advocates 80/03/14 2pp
- 8004080156 Requests to make limited appearance statement at licensing hearing BURNS,D Affiliation Unknown 80/03/15 ip
- 8004080161 Requests to make limited appearance statement at licensing hearing OEIOER.O Affiliation Unknown 80/03/15 2pp
- 8004180136 Responds to 800214 itr to Gilinsky re concern about treatment of public participant, Environ Coalition on Nuclear Power & director, J Johnsrud in license proceeding NRC regulations does not permit views off-the-record FITZGERALD, J A Office of the Executive Legal Director 80/03/20
- 8004080685 Memorandum re ASLB 800320-21 prehearing denial of applicants motions against Environ Coalition on Nuclear Power & Susquehanna Environ Advocates Delineates areas in which intervenors should supplement answers to interrogatories PARIG.O H . BECHHOLFER.C Atomic Safety and Licensing Board Penel 80/03/27 App
- 8004220032 Submits comments re NRC in post-TMI period & licensing situation at facilities Recommends suspension of CP until independent auditors assess need for power & alternatives PERKINS.J L Affiliation Unknown 80/03/27 3pp
- 8004180249 Requests to make limited appearance statement at licensing hearing SHELLY.F. L. Affiliation Unknown 80/03/31 ip
- 6004100331 Requests to make limited appearance statement at licensing prehearing LAMBON.L Affiliation Unknown 80/04/01 ip
- 8004100334 Requests to make limited appearance statement at licensing preharing MILLS B D Affiliation Unknown 80/04/01 1p
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OBSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004110014 Responds to ASLB 800320-21 prehearing conference request to examine possibility of making available in Wilkes-Barre area complete set of AEC & NRC repts of cases decided by Commission Repts will be loaned to Opterhout Free Library CUTCHIN.J M Hearing Branch 3 80/04/03 2pp
- --8004110019 Submits trip rept re 800313-14 visit to Deterhout Free Library, Wilkes-Barre, PA Library houses Susquehanns LPDR documents Library does not loan out documents to patrons Documents in good order but in need of revemping LOQAN, F Division of Rules and Records 80/04/03 2pp
- B004130049 Response in opposition to Environ Coalition on Nuclear Power 800315 petition for review of ASLB prehearing rulings Requests to address merits if appeal is granted Certificate of Svc encl CUTCHINJ M Hearing Branch 3 80/04/04 (ipp

- 8004230111 Second prohearing conterence order denying applicants' motions to restrict Susquehamna Finition. Advocates 'Environ Coalition on Nuclear Power participation, Citizens Against Nuclear Dangers environ contentions limited to our filing PARIS,O H. BECHHOEFER C. Atomic Safety and Licensing Board Panet 80704/11. 21pp
- 800a280P46 Forwards Univ of Heidelbeig levised Translation 520. "Radiological Assessment of Highl Nuclear Power Plant" "Review of Highl Rept" will be available to public in form of NUREO W/o enc!
 CUTCHIN. J M. Hearing Branch 4. 80/04/P4. Ip
- H General correspondence
- BOO4080065 Expresses concern to excessive number of interrogatories sent to Judnisrud as intervener in literating hearings Appears that NRC is frying to hinder Judnisrud effectiveness Certificate of Svc encl MANDEN, W.G. Affiliation Unknown 80/02/14 4pp
- 8004040176 Advises that news media? info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util efforts

 LEON: A Affiliation Unknown 80/02/29 Ip
- BOO4070185 Requests notification of time? Location of upcoming hearing on facility licensing Unges scheduling of hearings on weekends or evenings WIGGINS.R (S. Affiliation Unknown 80/02/29 2pp
- 8004070191 Requests notification of time & location of upcoming hearing on facility licensing Unged scheduling of hearings on weekends or evenings RHEINHCIMER.D Affiliation Unknown 80/02/29 2pp
- 8004040166 Requests notification or time & location of upcoming hearing on meekends or evening & limited appearance at hearing WESTNEDGE.T Affiliation Unknown 80703/03 2pp
- 8004070064 Advises that news media & info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Piotests util efforts
 RHEINHEIMER.D Affiliation Unknown 80/03/03 lp
- 8004070193 Requests notification or time & location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings Requests timited appearance at hearing BRISTOL.M Affiliation Unknown 80/03/04 2pp
- B004090184 Expresses feat for potential castastrophe resulting from const of facility RODACKM Affiliation Unknown 80/03/05 ip

- --7812110291 |E lasp Repts 50-287//8-15 & 50-388/78-13 on 780821-0921 engliowyl 16 Insp Repts 30-387/86-15 & 30-3887/86-13 on 780821-(Noncompliance noted eallore to qualify welders & failure to use specified curing compound for spray pond GALLOR M. Region 1. Philadelphia. Office of the Director MCGAUGHY, W. Region 1. Philadelphia. Reactor Construction & Engineering Support Dianch. 78/10/17. 13pp
- BD04076379 Atk receipt of 860227 ltr informing NRC of steps taten to correct violations noted in IF Insp Repts 50-387779-36 & 50-388779-19 CARLSON,R T Region & Philadelphia. Reactor Construction & Engineering Support Branch E2703707 ip

- --8004070382 Responds to NRC 800123 ltr ie violations noted in IE Insp Repts 50-387/79-36 & 50-388/79-19 Corrective actions amended Bechtel Field Insp Manual Procedure C-3:Revision & held training sessions for field engineers on bolt installation SABOL:A R Pennsylvania Power & Light Co 80/02/27 5pp
- --8004070385 Forwards 1E [nsp Repts 50-387/79-36 & 50-388/79-19 on 791029-1102 & notice of violation CARLSCN.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/23 Zpp
- --8004070391 Notice of violation from insp on 791029-1102

 * Region [. Philadelphia, Office of the Director Bi 80/01/11 200
- --8004070396 (E insp Repts 90-387/79-36 & 50-388/79-19 on 791029-1102
 Noncomptiance noted failure to provide adequate design
 review resulting in nonconforming installation & failure to
 follow procedure for tagging nonconforming items
 PACLINO.R J Region t. Philadelphia, Office of the Director
 EGNRTERS D Region i. Philadelphia, Reactor Construction &
 Engineering Support Branch 80/01/11 6pp
- 8004090402 Advises that IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks." was incorrectly sent for action No response required GRIER. B k Region i. Philadelphia, Office of the Director GRIER. B H R
- 8004100094 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/79-31 & 50-388/79-16 CARLSON,R f Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 60/03/17 Ip
- --8004100098 Responds to MRC 800118 itr re violations noted in IE Insp Repts 50-387/79-31 & 50-388/79-14 Corrective actions revised Tech Specs re correct welder qualification procedure & quenching method for N2 notife mods SABOL:A R Pennsylvania Power & Light Co 80/02/29 3pp
- --8004180103 Forwards IE insp Repts 50-387/79-31 & 50-388/79-14 on 790910-1005 & notice of violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/18 ip
- --B004100106 Notice of violation from insp on 790910-1005 # Region 1, Philadelphia, Office of the Director B B0/01/09 200
- --8004100111 IE Insp Repts 50-387/79-31 & 50-388/79-16 on 790910-1005
 Noncompliance noted failure to review SRSE 1-12.Revision 2
 & to provide documented instruction to control completion
 re water quenching of weld VRR-931-2-FH-13M
 MCGAUGH/, R W Region 1, Philadelphia, Reactor Construction &
 Engineering Support Branch H10GINS.J C. GALLOR M Region 1,
 Philadelphia, Office of the Director 80/01/09 12pp
- RO04150295 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER B M Region 1. Philadelphia. Office of the Director 80/03/31 lp
- 4004070097 Forwards 1E Circular 80-05. "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required GRIER, B H Region I, Philadelphia, Office of the Director BO/04/01 ip
- 8004110504 Forwards IE Info Notice 80-13, "GE Type SBN Control Switches Defective CAM Followers" No written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/04/02 ip
- 8004240341 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required CRIER, BH Region 1, Philadelphia, Office of the Director 80/04/02 1p

- 8004180187 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required GRIER.B H Region I, Philadelphia, Office of the Director 80/04/03 ip
- 8004110068 Forwards IE Builetin 80-07, '8WR Jet Pump Assembly Failure " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director BD/04/04 ip
- 800423048! Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASKE SA-312. Type 304 Stainless Steel Pipe " Action required GRIER.D H. Region 1. Philadelphia, Office of the Director BO/04/04 1p
- 8004180270 Forwards IE Sultetin 80-0B. "Exam of Containment Liner Penetiation Molds " Written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/07 ip
- S Reportable occurrences, LERs & related correspondence
- 8004080516 Final deficiency rept re hydramotor actuator springs Affected dampers have been identified & being controlled Actuators will either be replaced or tested to establish adequacy CURTIS.N W Pennsylvania Power & Light Co 80/03/28 2pp
- ---8004080921 Informs NRC of notification to 13 purchasers of NH model milliampere hydramotor actuators Actuators have been discovered to be mfg from incorrect mati FORMELLA:R L ITT General Controls, Division of Intl Tel & Tel Corp 79/12/07 4pp
- 8004080363 Interim deficiency rept re defective cast carbon steel swing check valves mfg by Pacific Valve.Inc Final rept will be forwarded during June 1980 CURTIS.N W Pennsylvania Power & Light Co 80/03/31 2pp
- 8004290394 Forwards final deficiency rept re Culter Hammer E-30 pushbutton sticking problem & dislodgement of Switch CH E-30AB from contact block Conditions of Amphenol female connectors not reportable under IOCFR50 Rationale encl CURTIS.N W Pennsylvania Power & Light Co 80/04/18 3pp
- --8004270397 Final deficiency rept re Cutler Hammer E-30 pushbutton sticking problem & dislodgement of Switch CH E-30AD from contact block Sticking pushbutton corrected by scraping edge Locking devices for CH E-30 switches retightened * Pennsylvania Power & Light Co 80/04/18 3pp
- 8004300374 Forwards final deficiency rept re Cutler-Hammer E-30 pushbutton switches CURTIS.N W Pennsylvania Power & Light Co 80/04/18 2pp
- --8004300383 Final deficiency rept re Gutler-Hammer E-30 pushbutton switches Sticking of pushbutton occurs on two-button modules Dislogement of operating module apparently caused by mechanical locking ring not being tightly locked * Pennsylvania Power & Light Co 80/04/18 4pp
- T Hearing transcripts on non-antitrust matters
- BOO40200B7 Transcript of BOO320 prehearing conference in Wilkes-Barre, PA Pp 375-645 BECHDEFER,C E Atomic Safety and Licensing Board Panel BO/03/20
- BO04180233 Transcript of 800320 prehearing conference P 375 only * Atomic Safety and Licensing Board Panel 80/03/20 tp
- --8004180238 Transcript of 800320 prehearing conference P 1 only * Atomic Safety and Licensing Board Panel 80/03/21 ip
- B004020146 Transcript of 800321 prohearing conference in Wilkes-Barre, PA Pp 646-757 BECHHOEFER.C E Atomic Safety and Licensing Board Panel 80/03/21
- U Congressional/Executive Correspondence
- 8004080212 Responds to J Ulma request for status of facility licensing Licensing process delayed due to post-TMI efforts to upgrade safety requirements NRC is evaluating available resources to re-establish applicant review schedules DIRCKS.W J Office of the Executive Director for Operations 80/03/06 3pp

- --8004080218 Forwards ltr re J Ulman request for status of facility licensing MCDADE.J M House of Rep 80/02/07 2pp
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588. "Interim Etaff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSE, D F Division of Project Management 80/02/05 7pp
- 8004040017 Submite addl guidance to NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004020466 Notification of 800326 & 27 meeting w/representatives from Mark II owners group in San Jose, CA to discuss Mark II Creace Test Program, 47 c/o tests & foreign tests ELYANILA.F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800324-27 meeting w/Mark II owners group, NRC consultants & GE in Ban Jose, CA to discuss Mark II Creame test program, 4T C/O & foreign tests Topics are proprietary Agenda encl
 ELYAWJLA.F Containment Bystems Branch 80/03/10 12pp
- 8004080654 Forwards summary of 800228 meeting w/otil re plant-unique containment program
 PARR, O D Light Water Reactors Branch 3 80/03/14 1p
- --8004080660 Summary of 800228 meeting w/util BNL,KWU,KFK,SRI Intl. Bechtel.NUS Corp & CNSNS to discuss plant-unique containment program List of attendees & agenda encl ELTAWILA,F Containment Systems Branch 80/03/07 18pp
- 8004040474 Summary of 800227 meeting w/Mark II owners group re status of several long-term program tasks, including Tasks A 17 & A 16 & task related to utilization of foreign test data ELTAMILA.F Containment Systems Branch 80/03/18 104pp
- 8004210410 Requests add1 info re reactor sys to continue review of application for DL PARR: D D Light Water Reactors Branch 3 80/03/21 16pp
- 8004100484 Responds to 800313 request for approvel to use ABHE Code Cases N-234 & N-235 during preservice examination of reactor pressure vessel Code cases acceptable PARR.O D Light Water Reactors Branch 3 80/03/27. 2pp
- 8004140352 Confirms NRC 800411 meeting w/util & ANL re operational biological monitoring programs & ETB Proposed agenda encl CURTIB:N W Pennsylvania Power & Light Co 80/04/07 2pp
- 8004140268 Comments on archaeology project at site Guotation for survey work is excessive Requests study to define satisfactory Phase I study of area KENT,B C Pennsylvania, State of 80/04/08 1p
- 8004300064 Bummary of 800326-27 meetings w/Hark II owners group in San Jose, CA re discussion of NRC concerns on data from Creare tests & foreign full-scale test programs & relationships w/Hark II designs
 ELTANIA.F. Containment Sustems Branch 80/04/14 22pp
- 8004210335 Forwards Busquehanna River data in response to NRC 800407 request
 BKINNER: F Pennsylvania Power & Light Co 80/04/15 lp
- ---8004210340 "Demonstration for Brunner Island Steam Electric Station Units 1-3, Vols 1 & 2 " # E9 & G. Inc 77/05/19 200pp
- --8004210344 "Potential Effects of Brunner Island Steam Electric Station on Future Migrations of American Shad in Susquehanna River."

 * E0 & 0: Inc 77/08/13 23pp
- --8004210347 "Probabilities of Normal & Worst Case Conditions in Susquehanna River during Critical Periods for Muskellunge Spauning & Smallmouth Bass Egg Survival & Development " * E0 & O. Inc 77/09/15 lipp

- --8004210349 "Assessment of Thermal Effects from Brunner Island Steam Electric Station Based on Newly Derived Max Weekly Average Temps " 4 EG & G, Inc. 79/05/31 33pp
- ---8004210355 "Ecological Study of Effects of Brunner Island Steam Electric Station Cooling Water Intakes " JOHNSON, T D . PHOENIX, D R Roy F Weston, Inc. 77/11/18 78pp
- --8004210358 "Biological Survey of Susquehanna River in Vicinity of York Haven PA 1978 Terminal Rept WURTS: C B Charles B Wurtz 79/06/29 33pp
- --8004210366 "Ichthyofaunal & Crael Census/Fishing Pressure Surveys in Vicinity of Brunner Island Steam Electric Station " DENGNCOURT,R F R F Denoncourt /8/05/31 161pp
- 8004280492 Comments on NUREG-0564. App B re archaelogical survey of Pond Hill Reservos: location Plan is preliminary rept containing no factual info re prehistuit matl that might be found SOLENBERGER.R Bloomsberg State College 60/04/17 3pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8004220079 Forwards draft supp to Mar 1980 DES W/o encl BELLS,D E Environmental Projects Branch 2 80/03/31 8pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0AD clearance under Federal Repts Act
 GRIMED, B. K. Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence

. . - - -

- 8004080175 Requests to make limited appearance statement at 800320 hearing ENDRIZZI,D Affiliation Unknown 80/02/27 lp
- 8004100571 Notifies that NRC issued draft suppl to DES on 800331 Suppl & DES labelled NUREG-0564 DES issued & served on ASLB & all parties in June 1979 Draft suppl has been served on all persons on svc list Exceptions listed CUTCHIN.J M Hearing Branch 3 80/03/03 1p
- 8004080871 Requests to make limited appearance statement on behalf of Taxpayers Association of Lackawanna County at licensing hearings Evening on weekend sessions should be held for citizen participation
 ECHUMACHER.K Affiliation Unknown 80/03/07 19
- 8004080154 Requests to make limited appearance statement at licensing hearings
 HEMMENDINGER. R Affiliation Uninoum 80/03/10 Spp

- --80043000P3 Request- notification or time b location of licensing hearings for the into the december to make limited appearance statement DEIPICH.D.F. Arriliania Motogue 50 63/10 ip
- --8004260025 Request- noisestation of time & location of licensing heatings for familities Regrests to make limited appearance statement Portion of reasons a should be held on evenings? weekends WINTER A ! Artillation On norm BU/02/29 ip
- --8004300029 Requests notification of time * location of licensing hearings for racilities Requests to make limited appearance statements Portion or learing thould be schooled on on evenings of weekends # Artiliation Unknown # 80/03/10 ip
- --8004300033 Requests notification or time? location or licensing hearings for rocalities Peque to to make limited appearance statement Portion or hearings should be scheduled for eveniings of Heckends Affiliation Unknown 80/03/10 1s
- --8004300036 Requests notification of time 'location of licensing hearings for facilities Requests to make limited appearance statement Portion of hearings should be scheduled for evenings 'weekends GRAY-P F Afrikation Unknown 80703/10 ip
- --8004300039 Expresses concern that util is attempting to limit participation of intervenors at opcoming licensing hearings SKISLAR, S. Affiliation Unknown 80/03/10 (p.
- --8004300042 Expresses concern that util is attempting to limit participation of interveners at uproming licensing hearings DUBIN K J. Aftiliation Unknown 80/02/29 ip
- --8004300946 Expresses concern that util is attempting to limit participation or intervenois at upcoming licensing hearings DERAYMOND, J.S. Attiliation Unanoun 80/03/10 Ip
- --800430054 Requests making limited appearance statement concerning three motions on agenia of ARLB hearings in Wilkes-Barre,PA BUTCHKO,P R Affiliation Unknown 80/03/12 tp
- --8004390057 Requests notification of time & location of licensing hearings for facilities? to make limited appearance statement Portion of bearings should be held on evenings or weekends MERRILL, D K Affiliation Unknown 80/03/08 is
- --8004300061 Requests to make limited appearance statement at facility licensing hearings % notification of time % location of meeting lime for slatuents should be made available on weekends or eventing KRSYAWALE J Affiliation Unknown 80/03/11 ip
- --B004300063 Requests to make limited appearance statement at facility licensing hearings 's nothing after of time 2 location of meeting Hoarings should be held on evenings or weekends SMITH, D. Afrillation Uninown. B0003/21 lp
- 8004300066 Requests to make limited appearance statement at facility licensing hearings > notification of time 2 location of meeting Time should be made available on evenings or weekends for statements

 MACHAKER.6 C Affiliation Unknown 80/03/10 lp
 - 8004309067 Expresses concern that util is attempting to limit participation of intervenors at upcoming licensing hearings WIGGINS.R M. Affiliation Unknown 80/02/29 ip
- --8004300059 Requests to make limited appearance statement in favor of util motions at 800320 ASLB hearings in Wilkes-Barre,FA MURRAY,F Screnton Univ or 80/03/12 ip
- ---B004300070 Requests to make limited appearance statement at ASLE 800320 prefearing conference in Wilkes-Barre, PA THAMBERNE Asset --- on Unknown B0/03/12 1p

f of Citizens Lobby, to make limited USEO licensing hearing in Wilkes-

0known 80/03/11 1p

- --80043Guu73 Requests to make limited appearance statement at facility licensing hearings % notification of time & location of meeting Time should be made available for statements on venings t weekends RAMSON,t Arfiliation Unknown 80/03/13 ip
- -8004300676 Requests to hake limited appearance statement at 800320 licensing hearing in Wilkes-Barre, PA ELLIOTTIC P. Arriliation Unknown 80/03/1/ ip
- --8004300080 Expresses concerning /SLE consideration of util motion to restrict public intervenors in licensing proceedings Full inquiry should be made in any attempts to demy public due process / rights within, restablished NPC procedures SALZMAN, E. Friends of the Earth 60/03/13 ip
- ~-80043000B3 Requests to make limited appearance statement at facility licensing healings to notification of time to location of meeting Time for statements should be made available on evenings or weekends SAULR5.KA Affiliation Unkno⊿n ≅0/03/10 ip
- --8004J00088 Expresses concern that util is attempting to limit participation of intervenors at opcoming licensing hearings * Affiliation Unknown 80/02/29 ip
- 8004020040 Response to ASIR 800622 prehearing conference memorandum & order Alleges restrictive & biased agenda Urges discussion of onsite inspladvisability & reconsideration of denied contentions W/Certificate of Syc HALLIGAN, T.J. Citizens Against Nuclear Dangers 80/03/12 4pp
- 8004080143 Response to ASLB 800222 order setting oral argument re applicant motions to prohibit Susquehama Environ Advocates & Environ Coalition on Nuclear Power from litigation of contentions Urges to cancel argument M/Certificate of Svc JONHSRUD-J H Environmental Coalition on Nuclear Power 80/03.
- 8004080697 Request for expedited consideration of ASLH actions re of the control of the
- 8004230006 Petition to raise specific issues at 800320 prehearing conference, re intervenors' motions for protective order on Contentions 10 % % status as full party in proceeding SCHULTZ.0 R Gusquehanna Environmental Advocates 80/03/14 B0/03/14 20p
- 8004080156 Requests to make limited appearance statement at licensing hearing BURNS:D Affiliation Unknown 80/03/15 ip
- 8004080161 Requests to make limited appearance statement at licensing hearing GEIGER.G Affiliation Unknown 80/03/15 2pb
- 8004180136 Responds to 800214 ltr to Gilinsky re concern about treatment of public participant. Environ Coalition on Nuclear Power & director. J Johnstod in license proceeding NRC regulations does not permit views off-the-record FITZGERALD, J A Office of the Executive Legal Director 80/03/20
- 8004080685 Memorandum re ASLB 800320-21 prehearing denial of applicants motions against Environ Coalition on Nuclear Power & Susquehanna Environ Advocates Delineates areas in which intervenors should supplement answers to interrogatories PARIS,O H., DECHHOEPER.C Atomic Safety and Licensing Board Panel 80/03/27 6pp
- 8004220032 Submits comments to NRC in post-TM1 period & licensing situation at facilities Recommends suspension of CP until independent auditors assess need for power & alternatives PERKINS, J. Affiliation Unknown 80/03/27 3pp
- 8004180249 Requests to make limited appearance statement at licensing hearing SHELLY:FL Affiliation Unknown 80/03/31 ip
- 8004100331 Requests to make limited appearance statement at licensing prehearing LAWSON,L Affiliation Unknown 80/04/01 1p

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004110016 Responds to ASLB 800320-21 prehearing conference request to examine possibility of making available in Wilkes-Barre area complete set of AEC & NRC repts of cases decided by Commission Repts will be loaned to Osterhout Free Library CUTCHIN. J M Hearing Branch 3 80/04/03 2pp
- --8004110019 Submits trip rept re 800313-14 visit to Osterhout Free Library, Wilkes-Barre, PA Library houses Susquehanna LPDR documents Library does not loan out documents to patrons Documents in good order but in need of revamping LOGAN, F Division of Rules and Records 80/04/03 2pp
- 8004150069 Response in opposition to Environ Coalition on Nuclear Power 800315 petition for review of ASLB prehearing rulings Requests to address menity if appeal is granted Certificate of Svc encl CUYCHIN, J M Hearing Branch 3 80/04/04 11pp
- 6004230111 Second prehearing conference order denying applicants' motions to restrict Susquehanna Environ Advocates & Environ Coalition on Nuclear Power participation Citizens Against Nuclear Dangers environ contentions limited to dwn filing PARIS, D H , BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/04/11 2ipp
- 8004280246 Forwards Univ of Heidelberg revised Translation 520, "Radiological Assessment of Wyhl Nuclear Power Plant" "Review of Wyhl Rept" will be available to public in form of NUREO W/o oncl CUTCHIN, J M Hearing Branch 4 80/04/24 ip

H General correspondence

- 8004080045 Expresses concern re excessive number of interrogatories sent to J Johnsrud as intervenor in licensing hearings Appears that NRC is trying to hinder J Johnsrud effectiveness Certificate of Svc encl
 WARDEN.W 0 Affiliation Unknown 80/02/14 4pp
- 8004040176 Advises that news media & info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util efforts

 LEON, A Affiliation Unknown 80/02/27 ip
- 8004070185 Requests notification of time % location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings useskends or evenings used and additional wildown MOOINS.R M Affiliation Unknown MOOINS.R M
- 8004070191 Requests notification of time & location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings RHEINHEIMER.D Affiliation Unknown 80/02/29 2pp
- 8004040166 Requests notification of time & location of upcoming hearing on facility licensing, scheduling hearing on weekends or evening & limited appearance at hearing WESTNEDOE, T. Affiliation Unknown 80/03/03 2pp
- 8004070064 Advises that news media & info groups show util attempting to mixuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util efforts
 RHEINHEIMER.D Affiliation Unknown 80/03/03 ip
- B004070193 Requests notification of time & location of upcoming hearing on facility licensing Urges scheduling of hearings on weekends or evenings Requests limited appearance at hearing BRISTOL.M Affiliation Unknown B0/03/04 2pp
- 8004090184 Expresses fear for potential castastrophe resulting from const of facility RODACK.M Affiliation Unknown 80/03/05 Ip
- 8004030334 Buggests util is attempting to limit participation of intervenors at open licensing hearings All interested parties should be heard NRC should be aware of situation CREE.R E Affiliation Unknown 80/03/15 ip

- 8904040108 Advises that news media 2 info groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing hearing for facility Protests util errors KULICH.D J Affiliation Unknown 80703/15 IP
- 8004040226 Advises that news media & into groups show util attempting to misuse interrogatory process to limit participation of intervenors at upcoming licensing heating for facility Protests util efforts
 FASCIO,P Affiliation Unknown 80/03/15 1p
- 8004040333 Expresses concern about prospect of plant in Berwick area Nuclear power is impractical? dangerous Future generations will be untainly saddled w/responsibility of our energy consumption NELSON, K. J. Afriliation Unknown 80/03/15 ip
- θ . Inspection reports, 10 Bulletins λ correspondence
- /812(10287 Forwards IC losp Repts 50-38//78-15 % 50-388/78-13 on 780821-0921 % notice or violation CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 78/10/17 2pp
- --7812110289 Notice of violation from insp on 780831-0921 * Region 1 Philadelphia, Office of the Director 78/10/17 2pp
- --7812110291 IE Insp Repts 50-387/78-15 % 50-388/78-13 on 780821-0921 Nancompliance noted railure to qualify wolders & failure to use specified curing compound for spray pond GALLO.R N Region 1, Philadelphia, Office of the Director MCGAUGHY.R W Region 1, Philadelphia, Reactor Construction & Engineering Support Blanch 78/10/1/ 13pp
- 8004070379 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in If Insp Repts 50-387/79-36 දී 50-388/79-19 CARLSON.R T Region 1, Philadelphia, Reactor Construction දී Engineering Support Branch පි0/03/07 1p
- --8004070382 Responds to NRC 800123 ltr re violations noted in IE Insp Repts 50-387/79-36 t 50-388/79-19 Corrective actions amended Bochtel Field Insp Manual Procedure G-3.Revision 6 k held training sessions for field engineers on bolt installation SABOL: A R Pennsyl-ania Power t Light Co 80/02/27 5pp
- --8004070385 Forwards LE Insp Repts 50-39///9-36 % 50-388/79-19 on 791029-1102 % notice of violation CARSON.R T. Region L. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/23 2pp
- ---8004070391 Notice of violation from insp on 791029-1102
 * Region 1, Philadelphia, Office of the Director 80/01/11 2pp
- --8004070396 IE Insp Repts 90-397/79-36 & 50-388/79-19 on 791029-1102
 Noncompliance noted failure to provide adequate design
 review resulting in nonconforming installation & failure to
 follow procedure for Lagging nonconforming items
 PACLING.R J. Region 1. Philadelphia. Office of the Director
 ESNETER.S D. Region 1. Philadelphia. Reactor Construction &
 Engineering Support Branch

- --8004100111 [E Insp Repts 50-337/79-31 & 50-388/79-16 on 790910-1005 Noncompliance noted failure to review SRBE 1-12.Revision 2 & to provide documented instruction to control completion re water quenching of weld VRR-331-2-FW-13M MCOAUGHY.R W. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch HIGGINS.J C., GALLO.R M. Region 1. Philadelphia. Gffice of the Director 80/01/09 12pp
- 8004)50£95 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening or PORV & Block Valve ' No specific action or response necessary GRIER, B H Region 5. Phyladelphia. Office of the Director 80/03/31 | Ip
- 8004090097 Forwards IE Circulai 80-05, 'Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply 'No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/01 ip
- 8004110504 Forwards If Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER, B H Region J. Philadelphia, Office of the Director 80/04/02 Ip
- 8004240341 Forwards 1E Info Notice 80-14. "Safety Suggestions From Employees" No action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004180189 Forwards JE Circular 80-07, "Problems W/MPCI Turbine Oil Sys " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/04/03 ip
- 8004110068 Forwards IE Builetin 80-07, 'SWR Jet Pump Assembly Failure " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004230481 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required ORIER, B H Region 1. Philadelphia. Office of the Director 80/04/04 | 1p
- 8004180270 Forwards LE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required ORIER.B II Region J. Philadelphia. Office of the Director 80/04/07 ip
- S Reportable accurrences, LERs & related correspondence
- 8004080516 Final deficiency rept re hydramotor actuator springs Affected dampers have been identified 5 being controlled Actuators will either be replaced or tested to establish adequacy CURTIS.N W Pennsylvania Power & Light Co 80/03/20 2pp
- --8004080521 Informs NRC of notification to 13 purchasers of NH model milliampere hydramotor actuators Actuators have been discovered to be mfg from incorrect matl FORMELLA,R L ITT Openeral Controls, Division of Intl Tel & Tel Corp 79/12/07 4pp
- 8004080363 Interim deficiency rept re defective cast carbon steel swing check valves mfg by Pacific Valve. Inc Final rept will be forwarded during Jone 1980

 CURTIS. N W Pennsylvania Power & Light Co 80/03/31 2pp
 - 04290394 Forwards final deficiency rept re Culter Hammer E-30 pushbutton sticking problem & dislodgement of Switch CH E-30AB from contact block Conditions of Amphenol female connectors not reportable under 102FR50 Rationale encl. CURTIS.// U Pennsylvania Power & Light Co 80/04/18 Spp.
- -8004270399 Final deficiency rept re Cutler Hammer E-30 pushbutton sticking problem % dislodgement of Switch CH E-30AB from contact block Sticking pushbutton corrected by scraping adge Locking devices for CH E-30 switches retightened * Pennsylvania Power % Light Co 80/04/18 3pp
- 8004300374 Forwards final deficiency rept re Cutler-Hammer E-30 pushbutton switches CURTIS, N.W. Pennsylvania Power & Light Co. 80/04/18 2pp
- --8004300383 Final deficiency rept re Cutler-Hammer E-30 pushbutton switches Sticting of pushbutton occurs on two-button modules Dislodgement of operating module apparently caused by mechanical locking ring not being tightly locked # Pennsylvania Power & Light Co 80/04/18 4pp

- T Hearing transcripts on non-antitrust matters
- B004020087 Transcript of 800320 prehearing conference in Wilkes-Barre, PA Pp 375-645 BECMOFFER.C E Atomic Safety and Licensing Board Panel 80/03/20 27200
- 8004180233 Transcript of 800320 prehoaring conference P 375 only
 * Atomic Safety and Licensing Board Panel 80/03/20 ip
- ---800418023B Transcript of 800320 prehearing conference P 1 only

 * Atomic Safety and Licensing Board Panel 80/03/21 ip
- E004020146 Transcript of 800321 prehearing conference in Wilkes-Barre, PA Pp 646-757 BECHHOEFER,C E Atomic Safety and Licensing Board Panel 80/03/21
- U Congressional/Executive Correspondence
- 8004080212 Responds to J Uima request for status of facility licensing Licensing process delayed due to post-TMI efforts to upgrade safety requirements NRC is evaluating available resources to re-ostablish applicant review schedules DIRCKS:W J Diffice of the Executive Director for Operations. 80/03/04 3pp
- ---B0040B02iB Forwards 1tr re J Ulman request for status of facility licensing MCDADE.J M House of Rep. B0/02/07 2op
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROBS-DF Division of Project Management 80/02/05 7pp
- 8004220239 Forwards general info section of application for OL UHRIG-R E $\,$ Florida Power & Light Co $\,$ 80/03/24 $\,$ 1p
- --8004220243 General info section of application for DL UHRIO.R E Florida Power & Light Co 80/03/31 10pp
- B00425003B Requests technical basis analysis & experimental data re use of Ameron NUKEM 750 cault as expansion joint filler inside containment Info should be provided by B00930 or NRC should be informed in seven days if unable to meet schedule BAER.R L Light Water Reactors Branch 2 80/04/10 2pp
- 8004280267 Responds to NRC 800410 ltr requesting that info re use of NUKEM 750 be provided by 800530 Technical basis for use of NUKEM 750 as qualified caulk requested from Ameron Info will not be available by 800530 Submittal expected 800730 UHRIG.R E Florida Power & Light Co 80/04/22 ip.
- C Utility Environmental Report (ER), amends & correspondence
- 8004220313 Forwards environ rept for plant, Vols 1 & 2 Rept available in PDR
 UMRIG.R E Florida Power & Light Co 80/03/24 ip
- --8004220317 Environ rept. Vol 1 # Florida Power & Light Co 80/03/24 700pp
- --8004220321 Environ rept. Val 2 * Florida Power & Light Co 80/03/24 700pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending OAU clearance under Federal Repts Act ORIMES, B K Emergency Preparedness Task Force 80/03/11. 4pp
- 8004030229 Provides status of response to 791226 request for evacuation time estimates Draft inputs from consultants expected by 800331 Final draft circulation to state & local officials will proceeds 800430 submittal of final rept to NRC, UNRIG.R E Florida Power & Light Co 80/03/31 1p

G Adjudicatory correspondence

- 8004210109 Motion re Commission 790914 order, requesting issuance of FES suppl giving consideration to environ consequences of Class 9 accidents
 - 9 accidents HODDER,M H Affiliation Unknown 79/12/12 4pp
- 8004220141 Requests denial or intervenor 791212 motion re Class 9 accidents Class 9 issue was dispused of in CP proceeding Intervenors should invoke different procedural remedy Supporting documentation encl REIS.H F Florida Power & Light Co REIS.H F Lowenstein, Newman, Reis. Axelrad & Toll 80/01/16 23pp
- 8004190160 Response to intervenors RE Roberts, et al.800118 motion to consider Class 9 accidents Intervenors may potition NRC per 10CFR2 206, due to ASLAB lack of jurisdiction to grant request

 OLMSTEAD, W J , PATON, W D Hearing Branch 4 80/01/18 11pp
- 8004150148 Memorandum & order re intervenors' 791212 motion for consideration of Class 9 accidents Motion dismissed & documents referred to director of Nuclear Reactor Regulation to be treated under IOCFR2 2 6 BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/02/14
- 8004020218 Informs that motion for consideration of Class 9 accidents will be handled as request for action under 10CFR2 206
 Response to motion within 30 days cannot be guaranteed Supporting documentation encl DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 2pp
- ---8004020222 Notice that MH Hodder & TJ Anderson request for action has been referred to Director of Nuclear Reactor Regulation for consideration under 10CFR2 206 DENION,H R Office of Nuclear Reactor Regulation 80/03/06 1p
- ---8004020228 Forwards formal ASLAB referral of intervenors' motion to consider environ effects of Class 9 accidents Requests consideration under 10CFR2 206
 NURRAY, J P 9ffice of the Executive Legal Director 80/02/22
- ~~9004020231 Forwards intervenors' motion to consider environ consequences of Class 9 accidents Supporting documentation encl BIBHOP,C J Atomic Safety and Licensing Appeal Panel 80/02/14
- --B004020237 Motion for order to consider environ consequences of Class 9 accidents in determination of environ impact of proposed plant const Certificate of Svc & marked-up Commission 770914 memorandum & order re floating nuclear plants encl HDDDER.H H Hodder,M H ANDERSON,T J Miami, FL, Univ of 79/12/12 18pp
- --8004020265 Response in opposition to interveners' motion for consideration of environ impact of Class 9 accidents. Certificate of Svc & supporting documentation enci REIS,H F . COLL.N A Florida Power & Light Co REIS,H, F Lowenstein,Newman,Reis,Axelrad & Toll 80/01/16 29pp
- --8004020277 Response to RE Roberts, at al, motion to consider Class 9 accidents ABLAB lacks jurisdiction to grant motion Alternative forms of relief are available Class 9 accidents should not be addressed in proceeding W/Certificate of 8vc DLMSTEAD, W J . PATON, W D Hearing Branch 4 80/01/18 13pp
- --8004020272 Reply to applicant & NRC response to intervenors' motion for consideration of environ effects of Class 9 accidents Proximity between proposed plant on Hutchinson Island & Atlantic Gulfstream requires Class 9 consideration ANDERSON, T J Miami, FL, Univ of HODDER, M H Hodder, M H BO/02/05 19pp
- --B004020282 Order for dismissal of intervenors' motion for consideration of Class 9 accidents ASLAB is without authority to consider issues Motion referred to Director of Nuclear Reactor Regulation for consideration under 10CFR2 206
 BIGHOP.C J Atomic Safety and Licensing Appeal Panel 80/02/14
- 8004020005 Forwards applicant affidavit of OF Lieber re performance of Unit 1 diesel generator Certificate of Svc encl. COLL,N A Steel, Hector & Davis 80/03/14 3pp
- --8004020011 Affidavit re performance of Unit 1 diesel generator Supporting documentation encl LIEBLER, O E Florida Power & Light Co 80/03/14 17pp

- 8004090043 Advises that no addi NRC response necessary to util 800413 submittal re-performance of Unit 1 diesel generator NRC perspective re-relevance of Unit 1 diesel data to proceeding reported at Transcript 732-734 PATON.W D Hearing Branch 1 60/03/28 1p
- 8004030026 Memorandum of understanding between NPC & FEMA re prompt improvement in radiological emergency planning ?
 preparedness distributed as Board notification
 GOSSICKL V Office of the Creditive Director for Operations
 BO/04/02 34pp

I Financial information

- 8004150406 Forwards Annual Financial Rept 1979 80/04/08 to Florida Power & Light Co
- --800415041: Annual Financial Rept 1979 + Florida Power & Light Co 80/02/08 72pp
- K. Utility Final Samety Analysis Report (FBAR) & amends
- 8004220248 Forwards FSAR Vols 1-11 FSAR available in PDR UHRIG.R E Florida Power & Light Co 80/03/24 ip
- ---8004220250 FSAR for Saint Lucie Unit 2. Vols 1-11 * Florida Power & Light Co 80/03/24 11.26
- 8004220256 Chapter 1 of Saint Lucie FSAR." Introduction & General Description of Plant Site Characteristics " * Florida Power & Light Co 80/03/24 400pp
- 8004220258 Chapter 2 of Saint Lucie FSAR-* Florida Power 3 Light Co 80/03/24 "Site Characteristics " 3000рр
- 8004220261 Chapter 3 of Saint Lucie FSAR, "Design of Structure, Components, Equipment & Sys "

 * Florida Power & Light Co 80/03/24 2000pp
- 8004220264 Chapter 4 of Saint Lucie FSAR. * Florida Power & Light Co 80/03/24 "Reactor '
- 8004220264 Chapter 5 of Saint Lucie FSAR, * Florida Power & Light Co 80/03/24 "RCS & Connected Sus "
- "Engineered Safety Features " 1000pp 8004220271 Chapter 6 of Saint Lucie FSAR, * Florida Power & Light Co 80/03/24
- 8004220275 Chapter 7 of Saint Lucie FSAR, * Florida Power & Light Co 80/03/24 "Instrumentation & Control " 400pp
- 8004220279 Chapter 8 of Saint Lucie FSAR * Florida Power 9 Light Co 80/03/24 "Electric Power " 200ap
- 8004220283 Chapter 9 of Saint Lucie FSAR. * Florida Power & Light Co 80/03/24 "Auxiliary Sys " 1000pp
- 8004220287 Chapter 10 of Saint Lucie FSAR, "Steam & Power Conversion
- 8ys " * Florida Power % Light Co 80/03/24
- 8004220296 Chapter 11 of Saint Lucie FSAR. * Florida Power 'Light Co 80/03/24 "Radwaste Mgt "
- 8004220298 Chapter 12 of Saint Lucie FSAR. * Florida Power % Light Co 80/03/24 "Radiation Protection " 400np
- 8004220300 Chapter 13 of Saint Lucie FSAR, * Florida Power & Light Co 80/03/24 "Conduct of Operations " 150pp
- 8004220305 Chapter 14 of Saint Lucie FBAR, * Florida Power & Light Co 80/03/24 "Initial Test Program " 200aa
- 8004220306 Chapter 15 of Saint Lucie FBAR, * Florida Power & Light Co 80/03/24 "Accident Analysis " 1000pp
- 8004220308 Chapter 16 of Saint Lucie FSAR, "Tech Specs" * Florida Power & Light Co 80/03/24 ip
- 8004220309 Chapter 17 of Saint Lucie FBAR, "QA" * Florida Power & Light Co 80/03/24 10pp

M. Antitrus: correspondence

- B004230176 Response to B0C411 ltm ticense condutions referenced in ltm have not been received Centurinate of SVC encl JABLON & A. Florida Caties B0/04/15 2pp
- G Inspection reports IE Sulletin⇒ % correspondence
- 8004090344 Forwards IF Bull-'in 60-03. 'Loss of Chancoal From Std Type 11. Two-inch.Tray Adsorber Cells " Action required G'REILLY.J F Region 2. Atlants. Orfice of the Director 80/02/06
- 8004040167 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 50-389/79-18 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/21 lp
- --8004040173 Responds to NRC 791105 ltr re violations noted in IE linsp Rept 50-389/79-18 Corrective actions lot numbers for resin & cure containers verified as same Surveillance verified delivery & segregation of matis UHRIG.R C Florida Power & Light Co 80/03/04 1p
- 8004240217 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys " Relays noted in bulletin are not used or planned for use in safety-related sys at facility UMRIG, R E Florida Power & Light Co 80/03/28 ip
- 8004190517 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening or PORV & Block Valve " No specific action or response necessary D'REILLY/JP Region & Atlanta, Orfice of the Director 80/03/\$1
- 8004080619 Forwards IE Circular 80-05, "Emergency Dieset Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004150081 Farwards IE info Notice BC-13, "GE Type SDM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 200
- 6004240260 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pg
- 8004180321 Forwards 1E Circulas 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required O'REBLLY J P Region 2, Atlanta, Office of the Birector 80/04/02
- 8004230165 Forwards IE Bulletin 79-03A "Longitudinat Weld Defects in ASME SA 312,Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180417 Forwards IE Bulletin 80-08. 'Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/07 2pp
- Reportable occurrences, LERs & related correspondence
- 3004210170 Forwards 80032: interim deficiency rept re spring in certain hydramotor accustors for dampers being mfg from incorrect matl & possibility of selection nomegraphs being interpreted incorrectly Final rept will be submitted by 800430 UHRIG.R E Florida Power 5 Light Co 80/03/25 ip
- ~~8004210184 Interim deficiency rept re spring in certain hydramotor actuators for dampers being mfg from incorrect math & possibility or solection nomographs being interpreted incorrectly Affected dampers being placed on hold # Florida Power & Light Co 90/03/21 4pp

- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment "providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 800423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of THI-2 accident Info should be provided as amend to application Submittal schedule should include HRC approval prior to issuance of OL W/encl ROSS, ID F Division of Project Management 80/03/10 SJpp
- 8004020385 forwards "Operational Stage Nonradiological Fisheries Monitoring Program " Info supplements operational water quality & aquatic biology monitoring program provided on 791012 EL-ASBRY.M T Tennessee Valley Authority 80/03/24 2pp
- --8004020390 "Operational Stage Nonradiological Fisheries Monitoring Program " * Tennessee Valley Authority 80/03/24 7pp
- 8004110425 Forwards application for renewal of NPDES Permit TN0020168 Supporting documentation encl EL-ASHAY.M T Tennessee Valley Authority 80/04/07 100pp
- 8004170213 Requests meeting between NRC & util to ensure that qualification requirements for reactor operators & senior reactor operators are met Forwards licensing & training criteria for license candidates
 MILLS,L M Tennessee Villey Authority 80/04/14 2pp
- 8004290453 Responds to NRC 790730 1tr by forwarding comments on NRC-proposed ETS A status of transmission lines Repts supporting suggested mods encl MILLS.L M Tennessee Vailey Authority 80/04/22 19pp
- --8004290458 "Evaluation of Volunteer Vegetation Along Newly Cleared Rights of Way " FOHLER,D K , ADKIGSION,L F , TURNER,L J Tennessee Valley Authority RW 2 79/07/31 31pp
- --8004290462 "Preoperational Sounds Levels" * Tennessec Valley Authority 80/04/22 13pp
- --B004290467 "Cooling Touer & Steam Plant Plume Mergence at Site " KNUDSON.D A Tennessee Valley Authority TVA/AGB-179/13 79/07/31 52pp
- F Security, medical, emergency & fire protection plans
- B004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr.has been postponed pending GAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- 8004240482 Forwards comments on safeguards contingency plan Comments withheld (ref 10CFR2 790) ROBENSTEIN:L S Light Water Reactors Branch 4 80/04/10 2pp
- @ Inspection reports. IE Bulletins & correspondence
- 8004090392 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type 11.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/04.
- 8004230036 Forwards IE Insp Repts 50-370/80-03 & 50-371/80-02 on 800129-0201 No noncompliance noted BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/22 2pp

- --8004230046 IE Insp Repts 50-390/60-03 & 50-391/80-02 on B00129-0201 No noncompliance noted Major areas inspected 10CFR50 55(e) items.chipping activities in auxiliary bldg.vital battery rooms & diesel generator bidg CANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch THOMAS.M Region 2, Atlanta, Office of the Director 80/02/21 App
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC \$ util in Atlanta-0A to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/12 205
- 8004210178 Forwards response to IE Sulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Culls" Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS, L. If Tennessee Valley Authority 80/03/21 App
- BO04180106 Forwards response to IC Bulletin 77-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS, L M Tennessee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2. Atlanta. Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-03, "Emergency Diesel Generator Lubricating Oil Addition > Onsite Supply " No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director BO/04/Oi 200
- 8004150097 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/07 360.
- 8004300462 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/79-47 & 50-391/79-40 MVRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/07 2pp
- --8004300474 Submits revised response to NRC 800114 ltr re violations noted in IE Insp Repts 50-390/79-47 & 50-371/79-40 Corrective actions incorrectly tagged cable has been properly certified & recorded in certification status rept MILLS.L.M Tennessee Valley Authority 80/03/14 3pp
- 6004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLS, L. M. Tennossee Valley Authority. 80/04/23. 3pp
- R Periodic operating reports & related correspondence
- 8004180331 Forwards "Preoperational Fisheries Monitoring Rept.1977-79 "
 Preoperational rept describing water quality & nonFisheries
 biological monitoring results will be submitted by 800627
 EL-ABHRY.M T Yennessee Valley Authority 80/04/15 2pp

- --8004180337 "Preoperational Fisheries Monitoring Rept.1977-79 "
 BUCHANAN, J P , KIRBY, M S , PECK, G E Tennessee Valley Authority
 80/03/31 157pp
- 5 Reportable occurrences, LERs 3 related correspondence
- 8004020312 Forwards final deficiency rept re Ruskin fire dampers MILLS.L M Tennessee Valley Authority 80/03/28 ip
- --8004020316 Final defictency rept re spring slipping problem on Ruskin fire dampers Mod packages will be installed w/connection of Number 6 screw using washer, star lockwasher 8 hex nut through narrow portion of spring slot * Tennessee Valley Authority 80/03/28 ip
- 8004150413 Second interim deficiency rept re contiol red drop events yielding less conservative DHSR than stated in FSAR Westinghouse investigation in progress Next rept will be submitted by 800506 MILLS, LM Tennessee Valley Authority 80/04/01 ip
- 8004150437 Forwards final deficiency rept re potential lubrication problem in diesel generator turbocharger MILLS:L M Tennessee Valley Authority 80/04/01 (p
- --R004150450 Final deficiency rept re potential lubrication problem in generator turbocharger Diesel generators will not be unnecessarily started between 15 minutes & 3-h following shutdown from previous run at full operating temp
 * Tennessee Valley Authority GO/04/01 3pp
- BOO4280537 Forwards second interim deficiency rept re incorrect bore in Dravo transmitter bosses HILLSIA M Tennessee Valley Authoraty 80/04/07 ip
- --8004280544 Second interim derictency rept re incorrect bore in five Dravo transmitter bosses Caused by breakdown in Dravo GA insperogram Flow restrictor util be installed between one boss & valve Remaining bosses will be checked # Tennessee Valley Authority 80/04/07 ip
- 8004280536 Third interim deficiency rept re surface crack in loop one steam generator Westinghouse investigation has not been campleted Next rept will be submitted by 800613 MILLS.L.M Tennessoe Valley Authority 80/04/09 ip
- 8004180377 Farwards final deficiency rept re grouted anchor bolts on main steam line support HILLS.L M Tornossec Valley Authority 80/04/10 ip
- ---80041803Bi Finel deficiency rept re grouted anchor bolts on main steam line supports Original anchor bolt design will be replaced w/redesigned bolts fabricated from A193 steel w/A194 nuts by 800801 for Unit i & 8(07)1 for Unit 2 MILLS.t. M Tennessee Valley Authority 80/04/10 1p

- 8004290346 Forwards first interim deficiency rept to defective reactor vessel upper internals guide tube support pins MILLS.L IS Tennesses valley Authority 80/04/23 1p
- --8004270.353 First interim deficiency meptine generic problem w/defective reactor vessel upper internals guide tube support pins.
 Caused by heat treatment Westinghouse will investigate to determine in design changes are lequired.

 # Tennessee Valley Authority 80/04/23 Ip
- 8004270596 Informs of error in dates re submittal of interim deficiency rept re control rod drap events yielding less convervative DNBRs than stated in FSAR Hert rept will be submitted by 8006060 inct 800506 as erroreously stated in 800401 ltr MILLG.L M Tennossee Valley Authority 80/04/24 ip
- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance he methods for compliance RDSS D. F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- B00423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amond to application Submittal schedule should include NRC approval prior to issuance of CL Wencl ROSS,D F Division of Project Management BD/03/10 53pp
- 8004020385 Forwards "Operational Stage Nonradiological Fisheries Monitoring Program" Info supplements operational water quality & aquatic biology monitoring program provided on 791012 EL-ASBRY, N T Tennessee Valley Authority 80/03/24 2pp
- --8004020388 "Operational Stage Nonradiological Fisheries Monitoring Program " * Tennessee Valley Authority 80/03/24 7pp
- 8004110425 Forwards application for renewal of NPDES Permit TN0020168 Supporting documentation encl EL-ASHRY, M T Tennessee Valley Authority 80/04/07 100pp
- 8004170213 Requests meeting between NRC & util to ensure that qualification requirements for reactor operators & senior reactor operators are met Forwards licensing & training criteria for license candidates
 MILLS.C. M. Tennessee Valley Authority 80/04/14 App
- B004290453 Responds to NRC 790730 itr by forwarding comments on NRC-proposed ETS & status of transmission lines Repts supporting suggested mods encl
 MILLS,L M Tennessee Valley Authority 80/04/22 19pp
- --8004290458 "Evaluation of Volunteer Vogetation Along Newly Cleared Rights of Way " FORLER,D.K., ADKISSION,L.F., TURNER,L.J. Tennessee Valley Authority RW 2 79/07/31 31pp
- --8004290462 "Preoperational Sounds Levels " * Tennessee Valley Authority 80/04/22 13pp
- ~-8004290467 "Cooling Tower & Steam Plant Plume Mergence at Bite " XNUDSON.D A Tennessee Valley Authority TVA/AGB-179/13 79/07/31 32pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending CAC clearance under Federal Repts Act ORINES, B K Emergency Preparedness Task Force 80/03/ii 4pp
- 8004240482 Forwards comments on safequards contingency plan Comments withheld (ref 1005R2 790) RUDENSTEIN L.S. Light Hater Reactors Branch 4 80/04/10 2pp

- Q Inspection reports, IE Builetins & correspondence
- 8004090352 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type 11. Two-Inch, Tray Adsorber Colls" Action required 0'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/06
- 8004230036 Forwards IE Insp Repts 50-390/80-03 & 90-391/80-02 on BO0129-0201 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/22 2pp
- --B004230044 IE insp Repts 50-390/B0-03 & 50-391/80-02 on 800129-0201 No noncompliance noted Najor areas inspected 10CFR50 55(e) items, chipping activities in auxiliary bldg, vital battery rooms & diesel generator bldg CANTRELL,F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch THOMAS.M Region 2, Atlanta, Office of the Director 80/02/21 4pp
- 8004070025 Confirms B00310 telcon arranging B00320 meeting between NRC butil in Atlanta. GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program C/REILLY, J P Region 2. Atlanta. Office of the Director 80/03/12 20p
- B00421017B Forwards response to IE Bulletin B0-03, "Loss of Charcoal from Std Type II. Two-Inch. Tray Adsorber Cells " Encl lists results of Insps at facilities to determine if putential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EAIBO limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS, LM Tennessee Valley Authority 80/03/28 2pp
- 8004;50527 Forwards IE [nfo Notice 80-12, "Instrument Failure Gauses Opening of PORV & Block Valve" No specific action or response necessary O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/31
- B004080634 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating 0:1 Addition % Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/01 20p
- 8004150097 Forwards IE Info Notice 80-13. "GE Type BBM Control Switches Defective CAM Followers" No specific action or response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/02
- 8004240274 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees "No action required O'REILLY. J P Region 2. Atlanta, Office of the Director 80/04/02
- 8004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required O'REILLY-J P Region 2. Atlanta. Office of the Director 80/04/03
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312.Type 304 Stainless Steel Pipe " Action required O'REILLY-J P Region 2. Atlanta. Orfice of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Halds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07,
- 8004300462 Ack receipt of 800314 ltr informing NRC of steps taten to correct violations noted in 1E Insp Repts 50-390/79-47 & 50-391/79-40 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/07 2pp
- --8004300474 Submits revised response to NRC 800114 ltr re violations noted in IE Insp Repts 50-390/79-47 & 50-391/79-40 Corrective actions incorrectly tagged cable has been properly certified & recorded in certification status rept MILLS.L M Tennessee Valley Authority 80/03/14 3pp

- 8004270379 Requests approval of ASME Code Cases N=234 & N=235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp
 - MILLS, L M Tennessee Valley Authority 80/04/23 3pp
- R Periodic operating reports & related correspondence
- 8004180331 Forwards "Preoperational Fisheries Monitoring Rept, 1977-79 " Preoperational rept describing water quality & nonfisherips biological monitoring results will be submitted by 800627 EL-ASHRY,M T Tennessee Valley Authority 80/04/15 2pp
- --8004180337 "Preoperational Fisheries Monitoring Rept,1977~79 " BUCHAMAN, J.P., KRBY, M.S., PECK, O.E. Tennessee Valley Authority 80/03/31 157pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004020312 Forwards final deficiency rept re Ruskin fire dampers MILLS,L M Tennesses Valley Authority 80/03/28 ip
- --8004020316 final deficiency rept re spring slipping problem on Ruskin fire dampers Mod packages will be installed w/connection of Number 6 screw using washer star lockwasher & her nut through narrow portion of spring slot # Tennessee Valley Authority 80/03/28 19
- 8004150413 Second interim deficiency rept re control rod drop events yielding less conservative DNBR than stated in FBAR Westinghouse investigation in progress Next rept will be submitted by 800506
 MILLB/L M Tennessee Valley Authority 80/04/01 ip
- 8004150437 Forwards final deficiency rept re potential lubrication problem in diesel generator turbocharger MILLS.L M Tennessee Valley Authority 80/04/01 1p
- --8004150450 Final deficiency rept re potential lubrication problem in generator turbucharger Diesel gererators will not be unnecessarily started between 15 minutes & 3-h following shutdown from previous run at full operating temp * Tennessee Valley Authority 80/04/01 3pp
- B0041B0377 Forwards final deficiency rept re grouted anchor bolts on main steam line support MILLS/L M Tennessee Valley Authority B0/04/10 Ip
- ---B0041B03B1 Final deficiency rept re grouted anchor bolts on main steam line supports Original anchor bolt design will be replaced w/redesigned bolts fabricated from A173 steel w/A174 nuts by B00801 for Unit 1 & B10711 for Unit 2 MILLS.L M Tennessee Valley Authority B0/04/10 ip
- 8004280948 Forwards final deficiency rept re grouted anchor bolts on main steam line supports
 MILLB.L M Tennessee Valley Authority 80/04/10 1p
- 8004180444 Fourth interim deficiency rept re fabrication of refueling water storage tank overflow line, in violation of ASME code Final rept will be submitted upon receipt & subsequent evaluation of repair procedures from steel company MILLS,L M Tennesses Valley Authority 80/04/ii ip
- 8004280388 Fourth interim deficiency rept re refueiing water storage tank overflow line not fabricated to ASME code Repair procedures not received from vendor Next rept will be submitted by 800616, MILLS.L M Tennessee Valley Authority 80/04/11 1p
- 8004240405 Interim deficiency rept re shock arrestor strut assembly interference Next rept will be submitted by 800530 MILLS,L.M. Tennessee Valley Authority 80/04/18 1p
- 8004250413 Forwards final daficiency rept re TPIPE computer user failure to check frequency analysis of piping sys MILL8.L M Tennessee Valley Authority 80/04/21 ip
- --8004250424 Final deficiency rept re TPIPE computer user failure to check frequency analysis No erroneous design info has resulted Program mod to stop any program run when frequency analysis not converging

 * Tennessee Valley Authority 80/04/21 6p
- 8004270346 Forwards first interim deficiency rept re defective reactor vessel upper internals guide tube support pins
 MILLS/L M Tennesses Valley Authority 80/04/23 ip

- --8004270353 First interim deficiency Lept re generic problem w/defective reactor vessel upper internals guide tube support pins. Caused by heat treatment Westinghouse will investigate to determine if design changes are required.

 # Tennessee Valley Authority 80/04/23 Ip
- 8004290296 Informs of error in dates re submittal of interim deficiency rept re control rod drop events yielding less convervative DNBRs than stated in FBAR Nest rept will be submitted by 800606.not 800906 as erroneously stated in 800401 ltr MILLS.L.M. Tennessee Valley Authority 80/04/24 ip
- DOCKET 50-395 VIRGIL C SUMMER MUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- BO04040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment" Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Pioject Management 80/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TM1-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of DL Wencil ROSS, D F Division of Project Management 80/03/10 53pp
- 8004090054 Summary of 800222 meeting w/util 8 NVS Corp re draft of Tech Specs Attendee list encl TIBBITS.D Light Water Reactors Branch 1 80/03/21 5pp
- 8004090286 Summary of 800221 meeting \$ site visit w/util.Dames & Moore & LASE re geology & seismology review for site Attendee list & log of boring adjacent to USGS strong motion accelerator encl
 TIMBETTS.D L & Light Water Reactors Branch 2 80/03/21 800
- 8004300468 Forwards request for add1 info per review of recent FSAR amends
 DAER, R L Light Water Reactors Branch 2 80/04/04 5pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Fedoral Repts Act GRIMES B K Emergency Preparedness Task Force 80/03/11 4pp

Antitrust correspondence

- 004280004 Responds to T Conner 800314 ltr Nothing presented by applicant indicates that State or SC is actively supervising use by CARVA Lartel of economic market power over exchange sics
 BRAND.W E Brand ! Hall 80/03/21 3pp
- Inspection reports If Bulletins 2 correspondence
- 004020029 Ack receipt or 791217 ltr informing NRC of steps taken to correct violations noted in IE lasp Rept 50-395/79-34 BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/16 Ip
- -8004020035 Responds to NRC 791120 ltr re violations noted in IE Insp Rept 50-395/79-34 Corrective actions documented as-built condition of pipe support CSH-019 to procedural violations involved documented Add1 GA steps created JOHNSON, M.C. South Carolina Electric & Gas Co. 79/12/17 4pp
- -8004020036 Forwards IE Insg Rept 50-395/79-34 on 791030-1101 & notice of violation MURPHY, C.E. Region 2 Atlanta. Reactor Construction & Engineering Support Branch 79/11/20 2pp
- *8004020039 Notice of violation from insp on 791030~1101 * Region 2, Atlanta, Office of the Director 79/11/19 ip
- 8004020043 IE Insp Rept 50-375/77-34 on 791030-1101 Noncompliance noted inadequate insp of pipe support CSR-019 HERDIAR Region 2. Atlanta. Reactor Construction & Engineering Support Branch ANG.W P Region 2. Atlanta. Office of the Director 79/11/17 4pp
- 04070340 Forwards IC Bulletin BO-03. "Loss of Charcoal From Std Type II.Two-lnch.Tray Adsorber Cells " Action required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/06
- 04090343 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch, Tray Adsorber Cells " Action required B'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06
- 04110572 Forwards IE Insp Rept 50-395/80-02 on B00108-11 No noncompliance noted BRYANTA J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- 8004110575 IE Inep Rept 50-395/80-02 on 800108-11 No noncompliance noted Major areas inspected work activities & quality records for electrical components & instrumentation CONLON.TE Region 2. Atlanta. Reactor Construction & Engineering Support Branch GIBBOUST D. HARDMICK.R J Region 2. Atlanta, Office of the Director 80/02/25 7pp
- 04020201 Ack receipt of 1E Insp Rept 50-395/79-38 on 791119-29 No proprietary info JOHNSOWAM C South Carolina Electric & Gas Co 80/02/29 ip
- 3004020211 Forwards IE Insp Rept 50-395/79-38 on 791119-29 No noncompliance noted O'REILLUJ P Region 2, Atlanta, Office of the Director 80/02/07 2pp
- 100402020 IF Insp Rept 50-395/79-38 on 791119-29 No noncompliance noted Major areas inspected allegations re-cold joint in reactor bidg ring girder & cracks in svc water tunnel O'REILLY, J. P. MARSH, R. LEMAHAN, J. J. Region 2, Atlanta, Office of the Director 80/02/07 11pp
- 4040467 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std ype II, 2 Ench, Tray Adsorber Cells " Visual insp of safety nonsafety filter plenums revealed that spot welding used n cell const & screen sagging or degradation not noted REWS, E H South Carolina Electric & Oas Co 80/03/11 2pp
- 4100359 Responds to IF Bulletin 79-13 Hot functional testing cheduled for 800501 & fuel loading scheduled for 801201 perating & emergency operating procedures for main steam fine break & main feeduater line break & mein feeduater line break are being finalized REMS.E M. South Carolina Electric & Qas Co 80/03/12 2pp
- 1280005 Forwards IE Insp Rept 50-395/80-01 on B00101-31 & notice of iolation IMIS.R C Region 2. Atlanta Reactor Operations Nuclear Support vanch 80/03/13 2pp

- --B004250009 Natice of violation from insp on 800101-31 * Region 2, Atlanta, Office of the Director B0/03/10 ip
- --8004280014 IE Insp Rept 50-395/80-01 on 800101-31 Noncompliance noted failure to perform audit of lifted lead % jumper log KELLOGO.F J Region 2. Atlanta. Reactor Operations Nuclear Support Branch SKOLDS, J.L. Region 2 Atlanta, Office of the Director 80/03/10 4pp
- 8004070J91 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/14
- 8004100395 Ack receipt of 800205 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-395/79-41 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/17 ip
- --8004100402 Responds to NRC 800118 ltr re violation noted in IE inap Rept 50-395/79-41 Corrective actions attached safety tags to correct valves & wrote Startup Field Rept 1972 NICHOLS: T C South Carolina Electric & Gas Co 80/02/05 Spp
- --8004100409 Forwards IE Insp Rept 50-395/79-41 on 791110-1231 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/18 2pp
- --8004100412 Notice of violation from insp on 791110-1231
 * Region 2, Atlanta, Office of the Director 80/01/11 ip
- --8004100416 IE Insp Rept 50-395/79-41 on 791110-1231 Noncompliance noted improperly positioned safety tags & failure to document deficiency in main steam hydrostatic test KELLOGO.P J. SKOLDS.J L. Region 2. Atlanta. Office of the Director 80/01/11 8pp
- B004160110 Ack receipt or IE Insp Rept 50-395/80-02 on 800227 No proprietary info JOHNSON.M C South Carolina Electric & Qas Co 80/03/28 ip
- 8004150492 Forwards 1E Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004150495 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/31 2bn
- 8004080583 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Olf Addition & Onsite Supply " No written response required O'REILLY, J P Region 2: Atlanta, Office of the Director 80/04/01,
- 8004080587 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Dusite Supply " No written responso required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- 8004150089 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers" No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/02 to
- 8004150091 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02,
- 8004240269 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240271 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02

DOCKETED ITEMS

- 269 Forwards IE Circular 80-07, "Problems H/HPCI Turbine Oal No written response required LY,J P Region 2. Atlanta, Office of the Director B0/04/03
- 27; Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil No written response required Ly.JP Region 2, Atlanta, Office of the Director 80/04/03
- 09 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in A-312.Type 304 Stainless Steel Pipe " Action required LY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 58 Forwards IE Bulistin 79-03A "Longitudinal Weld Defects in A-312, Type 304 Stainless Steel Pipe" Action required LY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 32 Forwards IE Bulletin 80-08, "Exam of Containment Liner atton Welds " Written response required LY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 35 Forwards IE Bulletin 80-08, "Exam of Containment Liner ation Welds" Writton response required LLYJP Region 2, Atlanta Office of the Director 60/04/07,
- 12 Ack receipt of 800312 ltr informing NRC of steps taken to tivications noted in IE Investigation Repts 50-395/ k 50-395/80-03
 C. E. Region 2. Atlanta, Reactor Construction & Engineering t Branch 80/04/07 ip
-)119 Responds to violations noted in IE Investigation Repts 78/79-35, & 50-395/80-03 Corrective actions Drawing 202 revised on 791102 to incorporate ASME code rements for weld fillet size of socket welding flanges :0N, M C South Carolina Electric & Gas Co 80/03/12 3pp
- 124 Forwards IE Investigation Rept 50~395/79~35 on 790910~1219 & e of violation LLY.JP Region 2. Atlanta. Office of the Director VI3 2pp
- 128 Notice of violation from insp on 790910-1219 gion 2. Atlanta, Office of the Director 80/02/12 ip
- 135 IE Investigation Rept 50-398/79-35 on 790910-1219 mpliance noted procedures did not include fillet weld requirements per ASME Section III for socket welding es & sample weld failed to must ASME code RE.D R. MARSH, R J. LONG.F J. Region 2, Atlanta, Office of irector 80/02/12 24pp.
- 9 Ack receipt of IE Insp Rept 50-395/80-05 No proprietary
 .M C South Carolina Electric & Oas Co 80/04/08. 1p
- 484 Forwards IE Insp Rept 50-395/80-05 on 800225-28 1compliance noted f,J C Region 2. Atlanta, Reactor Construction & Engineering 1 Branch 80/03/12 2pp
- i93 IE Insp Rept 50-395/80-05 on 800225-28 No noncompliance Major areas inspected deficiency items, IE bulletins. IE are & const activities
 TE.T E. Region 2. Atlanta, Office of the Director.
 IJ K. Region 2. Atlanta, Reactor Construction & Engineering t Branch 80/03/12 App
- · Forwards preliminary preservice insp program for weld insps tatic tests H South Carolina Electric & Gas Co BO/04/15 ip
- 59 Preliminary preservice insp program for weld insps & tatic tests, including basic insp program, inspures, lists of items inspected & preliminary list of requests th Carolina Electric & Qas Co BO/Q4/15 400pp

- S. Reportable occurrences. LERs : related correspondence
- 8004020292 Part 21 rept on 800114-Colt Industries reported failure of thrust bearing in diesel generator due to omission of plugs from oil supply sys Thiust bearing & thiust collar are being replaced & plugs installed CREMS.E H South Carolina Electric & Gas Co 80/03/05 2pp
- 9004020455 Part 2) rept insp completed on crackshaft thrust bearing on generator A Plugs proposly installed & unit free of potential defect MORIARTY, J M Colt Industries, Inc. 80/03/06 tp
- 8004140174 Part 21 rept re emergency reedwater pump, turbine governor valve linkage Governor linkage modified to accommodate spring which preloads valve linkage so governor valve remains open during standby CREWS,E R. South Carolina Electric v. Gas Co. 80/03/07. 3pp
- 8004020321 Forwards deficiency rept re-problems identified in Berger-Patterson Part 2540 strut issembly used w/Pacific Scientific mechanical shock arrestors
 CREMG.E.H. South Carolina Electric 2 Gas Co. 80/03/10 2pg
- --8004020322 Deficiency rept re problems identified in Bergon-Patterson Part 2540 strut assembly used w/Pacific Scientific mechanical shock arrestors Cause unstated Larger assemblies being replaced Smaller assemblies modified a South Carolina Electric / Gas Co 80/03/10 3pp
- 8004220049 Part 21 rept on 800304, received notification of potential problems w/Dergen-Patterson mechanical shock arrestor assemblies Defective assemblies located on RCS, safety-related component cooling sys 5 reactor bldg spray sys CREMS,E H South Carolina Electric & Gas Co 80/03/10 5pp
- 8004170085 Deficiency Rept 50-399/80-05-07 re piping supplier drawings of reinforcing fillet weld for branch connections & contractor revisions not providing min throat thickness for specified weld sites Caused by program deviation JOHNSON,M C South Carolina Electric & Gas Co 80/03/21 3pp
- 8004170004 Interim deficiency rept re potential strees corrosion cracking of control rod guide tube support pine Cause unstated Mestinghouse will perform ultrasonic insp of support pins in two or more operating domestic plants CREWS.E H South Carolina Electric & Gas Co 80/03/27 App
- 8004300561 Part 21 rept re-control rod guide tube support pin cracking due to possible stress corrosion cracking Bioken support pin could prevent proper control rod operation
 CREMS,C H South Carolina Electric & Gas Co 60/03/27 5pp
- 8004150501 Final deficiency rept re failure of thrust bearing on diesel generator mfg by Colt Industries Forwards Colt Industries 800305 ltr regarding successful completion of shop tests CREMS.E H South Carolina Electric 5 Gas Co. 80/04/08 2pp
- 8004i50548 Final deficiency rept re measurement of steam generator water level Steam generator impulse lines are being thermally insulated to minimize heatup Mod will ensure proper accuracies w/o requiring large setpoint increase CREMS.E H South Carolina Diectric & Gas Co 80/04/08 2pp
- 8004280498 Final deficiency rept re measurement of steam generator water level Steam generator level impulse lines being thermally insulated to minimize heatup during time required to perform trip function, after high energy line break CREWS,E H South Carolina Electric & Qas Co 80/04/08 2pp
- 8004230404 Final deficiency rept re #3000 fittings instalted where piping specs required #6000 fittings Caused by failure to perform & comply w/procedures to verify matl prior to installation.

 JOHNSON M C South Carolina Electric & Gas Co 80/04/18 3pp
- 8004250429 Final deficiency rept re welding of safety-related instrument hanger/supports Caused by failure to perform & comply w/procedures controlled reinsp program instituted JOHNSON.M C South Carolina Cleatric & Gas Co BO/04/18 3pp
- DOCKET 50-397 WPPSS NUCLEAR PROJECT: UNIT 2
- A Application/construction stage documents & correspondence
- BD04040031 Advises of issuance of NUREG-05BB. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp

- if the first the second of the
- 4,1 '- card ': 1 I':211 litts to GE discussing analysis of til form sylf to strong not drive return line times to the well not be performed after some till to 1 the guidance of till 1 the sylf and the sold and the sylf and the
- INVITED AT WEST THAT THE TIME IS THE PART FOR SACRIFICIAL SHIELD USED TO THE TECHNICAL MEND 1173 JUSTINGLY SET OF THE TRANSPORT OF THE TRANSPORT OF THE TRANSPORT OF THE TRANSPORT SUPPLY SYSTEM BOYONZES

- UNITORAL Project engagement of stot welds a re-replacement of stot welds arearisal genetration cases.

 * Durms f Rea to 1 (3/10 cpp)
- to 140 of 2 induced engineering directive to proparation of partial generation held joint to be used on eachificial wall of Homes? As c=(-3)(4-6pp)
- 50340"(1)"4 Fragect engineering directive re preparation for welding by dual smooth Flow process
 Burns / Roe Co 3 103/14 to
- 73.04170.07 Forwards responses to Round One questions, Set 7 from Pachalical Engineering Science Religious Supply System 80/03/26
- C3:4110345 Summary of Emniod meeting u/util in Bethesda, MD re potential conflict of interest arrecting QA program MGC datased that conflict of interest involvement would addensel, arfect (ublic Saver), Lobble MCC Light Water Reactors Branch + 80/04/02 15pp
- FCH4280517 Atvises that "F1220 request for approval of alternative test method to verify has -fisture in low hydrogen electrode coating is accepted Regrests that notarized version of request as tent in addition to specific sites for use FUCKASTEP. L.S. Cliffic Nates Reactors Branch 4 80/04/04 5pp
- GG14490118 Att receipt or (10395 ltr re corrective action plan resolving quality problems identified w/joining sacrificial shield Lall rings | Gamma Francisco, Office of the Director GG/04 04 to
 - 24160285 Advises of fundamental misstatement in 800402 minutes of 332104 exeting object to refer that fart had no influence on Local SPB election to Debevaise > Liberman 80/04/10 is
- CSC4210285 Responds to Bu2221 ltr re schedule for completing review of qualification of tafety-related electrical equipment schedule for completion of review will be provided after final issuance of NUREC-CASS REMBERGER.D L. Washington Public Power Supply System 80/04/11
- G-0-043000&# Summary of #30325-27 machings w/Mark II owners group in San Jose CA re discussion of PRC concerns on data from Greare tests & foreign full scale rest programs & relationships w/ ELTAWICA f Londainment Systems Branch 80/04/14 30-2 Containment Systems Branch 80/04/14 22pp
- F Security, medical, emergency t fire protection plans
- EIGC4080D27 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr has been postponed pending GAD clearance under Federal Repts Act GRIMES B K Emergency Preparedness Task Force 80/03/11 4pp

- · Adjudicatory correspondence
- Bu040300.5 Memorandum of understanding between NRC & FEMA re prompt improvement in ladiological emergency planning & preparedness, distilluted as Board notification COSSICK.L V Office of the Frecutive Director for Operations 80/04/02 34p
- k Utility Final Safety Analysis Report (FSAR) & amends
- ECC4020339 Forwards Amend 8 to FSAR
 REPRESER, D.L. Washington Public Power Supply System 80/03/10
- --8004U20341 Amend & to FCAR

 → Washington Public Power Supply System 80/02/29 820pp
- 9004140345 Forwards Certificate of Syc for Amend 0 to FSAR RENBERGER.D L Washington Public Power Supply System 60/04/04
- G. Inspection reports, IF Bulletins & correspondence
- 8004300293 Forwards IE Insp Ropt 50-397/80-01 on BOO115-18 SPENCER.G E Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004300798 IE Insp Rept 50-397/80-01 on 800115-18 Nuncompliance noted inadequate closure of sensing lines b failure to control veiding filler math DODDS:R f , ELIN J O , HAIST, D P Region 5, San Francisco: Office of the Director 80/02/26 8pp
- 8004280272 Forwards IE Insp Rept 50-39//80-05 on 800310-12 No honcompliance noisd CREWS, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/03/24 2pp
- --8004280277 IE Insp Rept 50-397/80-05 on 800310-12 No nancompliance noted Major areas inspected preoperational test procedures & overall preoperational program Inspectors toured plant for independent update of const status STERNBERG, D M. Region 5. San Francisco, Reactor Deretions Nuclear Support Branch CARLSON, J D., JOHNSON, P. H. Region 5. Ban Francisco, Office of the Director 80/03/21 3pp
- 8004150220 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary EMSELVELLE H Region 5. San Francisco, Office of the Director 80/03/31 Ip
- 8004100107 Forwards IE Circular 80-05. "Emergency Diosel Generator Lubricating Gil Addition 5 Onsite Supply " No written response required ENGELMEN.R H Region 5. San Francisco, Office no the Dioceans H Region 5. San Francisco, Office of the Director 80/04/01
- 8004110119 Forwards IE Info Notice 80~13, "QE Type SBM Control Switches Defective CAM Followers " No specific action or response Derective of the Director ENGELKEN, R H. Region S. San Francisco. Office of the Director
- 8004220052 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" "No action required ENDELKEN,R H. Region 5, San Francisco: Office of the Director 80/04/02 ip
- BOO4180137 Forwards IC Circular BO-07, "Problems H/HPC! Turbine Dil Sys " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director. BO/04/03 lp
- 8004110007 Forwards IE Bulletin 90~07. "BHR Jet Pump Assembly Failure "No written response required ENDELMEN'R H Region S. San Francisco. Office of the Director. 90/04/04 | 1p
- 8004230970 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ABME SA-312. Type 304 Stainless Steel Pipe " Action required ENGELBENE H Region 5, San Francisco, Office of the Director
- 8004720201 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKER H Region 5, Ban Francisco, Office of the Director 80/04/07 1p

- S Reportable occurrences, LERs & related correspondence
- 8004020293 Forwards interim deficiency rept re-potential missile~producing nonsafety-related equipment installed in Class IE area RENBERGER, D. L. Washington Public Power Supply System 80/03/21 ip
- ~~BO04020294 Interim deficiency rept re potential missile-producing nonsafety-related equipment installed in Class IE area Protective barriers are being designed to proclude damage to Class IE equipment in event of flywheel failure * Washington Public Power Supply System * 80/03/21 1p
- 8004020302 Forwards final deficiency rept re pipe whip restraint problems RENBERGER, D.C. Washington Public Power Supply Bystem 60/03/21 2pp
- --8004020305 Final deficiency rept re pipe whip restraint 9A records & fabrication deficiencies Documentation deficiencies have been identified All restraints will be reinspected by ultrasonic magnetic particle E visual methods

 * Washington Public Power Supply System 80/03/21 2pp
- 8004100488 Ack receipt of 800314 ltr fowarding deficiency rept re condensate collection in reactor core isolation piping ENGELKEN,R H Region 5. San Francisco, Office of the Director 80/03/25 ip
- 8004280466 Forwards deficiency rept re small tore piping design RENBERGER, D. L. Washington Public Fower Supply System 80/04/21 io
- --8004280469 Deficiency rept re small bore piping design Piping & support drawings have been released for fabrication of incomplete & unchecked design calculations Independent engineering firm will complete remaining designs # Washington Public Power Supply System 80/04/21 1p
- 80042B0475 Forwards interim deficiency rept re violation of min wall thickness on small bore piping RENBERGER, D. L. Hashington Public Power Supply System 80/04/21
- ---8004280476 Interim deficiency rept re carbon steel small diameter pipe installed w/loss than min allowable wall thickness Caused by contractor utilizing grinders to remove oxide & mill scale from pipe in preparation for welding # Washington Public Power Supply System 80/04/21 1p
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D F Division of Project Management 80/02/03 7pp
- BOQ4170047 Discusses deficiency re defective seismic Class I hanger walds Deficiency no longer considered reportable under IOCFR50 55(a) Corrective action completed & found to be acceptable CHIANGI.N J. Carolina Power & Light Co. 80/02/22 ip
- 8004080451 Forwards const milestones & activities schedule, updated to 800331 MCDUFFIE.M A Caroline Power & Light Co 80/04/02 13pp.
- BO04220451 Bubmits info in response to NRC 800324 questions reelectrical field gradients surrounding proposed Harris-Harnett 500-kV line MCDUFFIE,M A Carolina Power & Light Co B0/04/15 2pp
- 8004230328 Submits info re electrical field gradients surrounding proposed 500 kV line requested in NRC 800324 ltr MCDUFFIE M A Carolina Power & Light Co 80/04/15 2pp
- F Becurity, medical, emergency & fire protection plans
- B0040B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 1tm, has been postponed pending QAO clearance under Federal Repts Act ORIMES.B K. Emergency Preparedness Task Force 80/03/11 4pp

- G Adjudicatory correspondence
- 8004010519 Petition for review of ASLAB 800220 decision denying applicant motion for mod of ALAB-577 re mgt capability Supports NRC argument that ACLAB exceeded authority re staff procedures to treat OL Certificate of Svc encl TROMBRIDGE, 67, 0. NEILL, J.H. Carolina Power & Light Co. TROMBRIDGE, 6 F. Shaw, Pittman, Potts & Trowbridge 80/03/11 13pp
- 8004030026 Memorandum of understanding between NRC & FEMA re groupt improvement in radiological emergency planning & preparedness distributed as Board notification GCSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension until 800418 for Commission to take action re review of ALAB-577 & ALAB-591
 CHIEK, S. J. Office of the Secretary of the Commission 80/04/11
- BO04280178 Memorandum 5 order reversing portions of ALAB-577 & ALAB-581 re performance of administrative tasks in separate proceeding Declines to review applicant issues re ALAB-581 Directs NRC to conduct preliminary assessment re ALAB-577 CHILK, S.J. Office of the Secretary of the Commission BO/04/17 5pp
- G Inspection reports, IF Bulletins & correspondence
- 8004070058 Ack receipt of IE Insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No proprietary info HOWER W Carolina Power & Light Co 80/02/28 tp
- --9004090071 Forwards IE Insp Repts 50-400/80-02,50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance noted BRYANTJ C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004070084 IE Insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 \$
 50-403/80-02 on 791228 \$ 800121-25 No noncompliance noted
 Major areas inspected const status, licensee action on
 previous findings & IE Bulletin 79-25
 BRADELY.R D. Region 2. Atlanta. Office of the Director HUNT, H D
 Region 2. Atlanta, Reactor Construction & Engineering Support
 Branch 80/02/20 5pp
- 8004070275 Ack receipt of IE Insp. Repts 50-400/80-04, 50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No propietary info HOWE.P W Carolina Power & Light Co. 80/03/06 tp
- --8004070315 Forwards IE Insp Repts 50-400/80-04,50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 ^

- BOO4080598 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply ' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/01
- BOOA150067 Forwards IE Into Notice 80-13, "GE Type SBM Control Suitches Defective CAM Followers" No specific action or response
 - required O REILLY, J P Region 2, Atlanta, Orfice of the Director 80/04/02
- 8004240245 Forwards IE Info Notice 80-14, "Safety Suggestions From " No action required
 P Region 2, Atlanta Orfice of the Director 80/04/02 Employees " P
- 8004180378 Forwards 1E Circular 80-07. Problems W/HPCI Turbine Oil Sys "No written response required
 O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/03
- BOO4230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2. Atlanta, Orrice of the Director 80/04/04
- BOO4180340 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J. P. Region 2, Atlanta, Orfice of the Director 80/04/07
- S Reportable occurrences, LERs > related correspondence
- 8004170053 Interim dericiency lept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embodment & support of safety-related loads Estimates corrective action will be completed by 800601 CHIANGLIN J Carolina Power & Light Co 80/02/29 ip
- 8004280560 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall Caused by unique ref notation of "addl steel" (25 bars) on main reinforcing drauing Significance not fully recongnized on drawing JONES. J A Carolina Power & Light Co 80/04/16 Spp
- 8004280561 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall, adjacent to const opening for equipment hatch Review will be expanded to include drawing review of reinforcing steel in Class I structures JONES. J A Carolina Power 2 Light Co 80/04/18 2pp
- DOCKET 50-401 SHEARON HARRIS MUCLEAR POWER PLANT, UNIT 2 A Application/construction stage documents & correspondence
- BOD4040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,DF Division of Project Management 80/02/05
- 304170047 Discusses deficiency re defective seismic Class I hanger welds Defitiency no longer considered reportable under 10CFR50 55(e) Corrective action completed & found to be CHIANGI R J Carolina Power & Light Co 80/02/22 1p.
- 3004080451 Forwards const milestones & activities schedule, updated to MCDUFFIE.M A Carolina Power \$ Light Co 80/04/02 13pp
- 800A220451 Submits info in response to KRC 800324 questions re electrical field gradients surrounding proposed Harris-Harnett 500-kV line MCDUFFIE,M A Carolina Powar & Light Co 80/04/15 2pp
- 8004230328 Submits info re electrical field gradients surrounding proposed 500 kV line, requested in NRC B00324 ltr MCDUFFIE,M A Carolina Power & Light Co 80/04/15 2pp
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 Itr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp

- G Adjudicatory correspondence
- 8004010519 Petition for review of ASLAU 800220 decision denying applicant motion for mod of ALAB-577 re mgt capability Supports NRC argument that ASLAB exceeded authority is staff procedures to treat OL Certificate of Svc encl TROMBRIDGE, G.F. D'NEILL, J.H. Carolina Power 5 Light CoTROMBRIDGE, G.F. Shaw, Pittman, Potts & Trowbridge 80/03/11
- 8001030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office or the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension until 800418 for Commission to take action re review of ALAB-577 t ALAB-581 CHILK.S J Office of the Secretary of the Commission 80/04/11
- 8004280178 Memorandum % order reversing portions of ALAB-577 & ALAB-581 re performance of administrative tasks in separate proceeding Declines to review applicant issues re ALAB-581 Directs NRC to conduct preliminary assessment re ALAB-577 CHILK,5 J Office of the Secretary of the Commission 80/04/17
- G Inspection reports, IE Bulletine & correspondence
- 8004070056 Ack receipt of IE lnsp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No proprietary info HOWE,P W Carolina Power & Light Co 80/02/28
- --8004090071 Forwards IE Insp Repts 50-400/80-02.50-401/80-02. 50-402/80-02 % 50-403/80-02 on 791228 % 800121-25 No noncompliance noted

 BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Busport Branch 80/02/20 200
- --8004090084 IE Insp Repts 50-400/80-02,50-401/80-02,50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance noted Major areas inspected const status.licensee action on previous findings & If Bulletin 79-25 BRADELY.R D Region 2. Atlanta. Office of the Director HUNT, Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/02/20 Spp
- B004070275 Ack receipt of IE Insp Repts 90-400/80-04, 50-401/80-04, 50-402/80-04 % 50-403/80-04 on 800205-07 No propietary info HOME.P W Carolina Power & Light Co 80/03/06 ip
- --8004070315 Forwards IE Insp Repts 50-400/80-04.50-401/80-04. 50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted Region 2. Atlanta, Reactor Construction & Engineering ch 80/02/27 2pp BRYANT. I C Support Branch
- --800407033i IE Insp Repts 50-400/80-04.50-401/80-04.50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted Major areas inspected const progress & licensee action on previously identified items
 HUNTIM D Region 2. Atlanta. Office of the Director BRADLEY, R D NRC Regional Offices 80/02/22 Spp
- 8004070035 Ack reseipt of 1E Insp Repts 80-400/80-05, 50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No proprietary HOWE, PW Carolina Power & Light Co 80/03/07 ip
- --8004070039 Forwards IE Insp Repts 50-400/80-05, 50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance noted

 BRYANTIJ C Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch 60/02/28 2pp Support Branch
- --8004070043 IE Insp Repts 90-400/80-05.50-401/80-05.50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance noted Major areas inspected structural concrete & lakes dams & canals HARRIS J R Region 2. Atlanta, Office of the Director CONLON,T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 4pp
- B004150497 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/31

- 8004080598 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Gasite Supply " Na written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04
- Region 2, Atlanta, Office of the Director 80/04/01
- B004150067 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240245 Forwards IE Info Notice BO-14. "Safety Suggestions From Employees "No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director
- BOD4180378 Forwards IE Circular 80~07, "Problems W/HPCI Turbine Cil Sys " No written response required C'REILLY, J P Region 2. Atlanta, Office of the Director BO/04/03
- 8004230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME BA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180340 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Writton response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/07
- S Reportable occurrences, LERs & related correspondence
- B004170033 Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Estimates corrective action will be completed by 800601 CHIANGI,N J Carolina Power & Light Co 80/02/29 1p
- 8004280840 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall Caused by unique rof notation of "add1 steel" (28 bars) on main reinforcing drawing Significance not fully recongnized on drawing JCNES: J A Caroline Power & Light Co 80/04/16 Spp
- 8004280561 Interim deficiency rept re omission of rebar in Unit i containment bidg exterior wall adjacent to const opening for equipment hatch Review will be expanded to include drawing review of reinforcing steel in Class I structures JONES, J A Carolina Power & Light Co 80/04/18 2pp
- DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." praviding guidance re methods for compliance ROSS,D F Division of Project Management
- 8004170047 Discusses deficiency re defective seismic Class I hanger welds Deficiency no longer considered reportable under 10CFR30 55(e) Corrective action completed & found to be acceptable CHIANGI,N J Carolina Power & Light Co 80/02/22 1p
- 8004080451 Forwards const milestones & activities schedule, updated to MCDUFFIE, M A Carolina Power & Light Co 80/04/02 13pp
- 8004220451 Bubmits info in response to NRC 800324 questions re electrical field gradients surrounding proposed Harris-Harnett 500-kV line. Carolina Power & Light Co. 80/04/15 2pp MCDUFFIE, M A
- 8004230328 Submits info re electrical field gradients surrounding proposed 500 tV line, requested in NRC 800324 ltr MCDUFFIE,M A Carolina Power & Light Co 80/04/15 2pp
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791224 ltr.has been postponed pending CAO clearance under Federal Repts Act
 ORIME8.B K Emergency Preparedness Task Force 80/03/11 4pp

G Adjudicatory correspondence

- 8004010517 Petition for review of ASLAB 800220 decision denying applicant motion for mod of ALAB-577 re mgt capability. Supports RRC argument that ASLAB exceeded authority re staff procedures to treat OL Centificate of Svc encl. TROMBRIDGE, G. F. O'NEILL, J.H. Carolina Power & Light Co. TROMBRIDGE, G.F. Shaw, Pittman, Potts & Trombridge 80/03/11 80/03/11 1300
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radialogical emergency planning ½ preparedness distributed as Board notification ODSTICKL V Defice of the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension, until 800418, for Commission to take action re review of ALAH-577 & ALAH-581 CHILK, S. J. Office of the Secretary of the Commission 80/04/11
- 8004280178 Memorandum & order reversing portions of ALAB-577 & ALAB-581 re performance of administrative tasks in separate proceeding Beclines to leview applicant issues in ALAB-581 Directs NRC to conduct preliminary assessment re ALAB-577 CHILK, B J Office of the Secretary of the Commission 80/04/17
- @ Inspection reports, If Bulletins & correspondence
- 8004090058 Ack receipt of IE Insp Repts 50-400/80-02,50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No proprietary info HOWE.P W Carolina Power & Light Co 80/02/28
- --8004090071 Ferwards IE Insp Repts 90-400/80-02,50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 600121-25 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004090084 IE Insp Repts 50-400/80-02.50-401/80-02.50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No moncompliance noted Major areas inspected const status. licensee action on previous findings & IE Bullotin 79-25 BRADELY.R D. Region 2. Atlanta, Office of the Director HUNT, Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 Spp
- 8004070295 Ack receipt of IE Insp Repts 50-400/80-04,50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No prepietary info HOME,P W Carolina Power & Light Co 80/03/06 1p
- --8004070315 Forwards IE Insp Repts 50-400/60-04,50-401/60-04, 50-402/80-04 \$ 50-403/60-04 on 800205-07 No noncompliance BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004070331 IE Insp Repts 50-400/80-04.50-401/80-04.50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted Major areas inspected const progress & licensee action on previously identified items HUNT/M D Region 2, Atlanta, Office of the Director BRADLEY/R D NRC Regional Offices 80/02/22 Spp
- 8004070035 Ack receipt of 1E Insp Repts 50-400/80-05, 90-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No proprietary HOWE,P & Carolina Power & Light Co 80/03/07
- --8004070039 Forwards IE Insp Repts 50-400/80-05, 50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No nancompliance BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8004070043 IE insp Repts 50-400/B0-05.50-401/B0-05.50-402/B0-05 & 50-403/B0-05 on B00214-15 No noncompliance noted Major areas inspected structural concrete & lakes, dams & canals HARRIS, J. R. Region 2. Atlanta, Office of the Director CONLON-TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 App
- B004150497 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/3: Region 2. Atlanta. Office of the Director 80/03/31

- 8004080598 Forwards IF Circilal 80-05. Emergency Divisel Generator Lubricating Uil Addition? Unsile Supply "No written response require? G/REILLI, J.P. Region D. Atlanta Orfice of the Director B0/04/
 - Region 2 Atlanta Office of the Director 80/04/01
- BOO4150067 Forwards If I Fro Notice SU-13, 'GE Type SBM Control Suitches Defective CAM Followers No specific action or response required O'REILLY J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240245 Forwards IE Info Notice 80-14, 'Safety Suggestions From No action required
 P Region 2 Atlanta, Orfice of the Director 80/04/02 Employees ' !
 O'REILLY J P
- 8004180378 Forwards IE Cir ular 80-07, "Problems W/HPC: Turbine Dil Sys "No written response required O'REILLY, J.P. Region 2, Atlanta, Orrice of the Director 80/04/03
- 8004230117 Forwards 1E Bullefin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe : Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180340 Forwards IE Bulletin 80-08. 'Eram of Containment Liner Penetration Welds " Written response required O'REILLY, J. P. Region 2. Atlanta Orfice of the Director 80/04/07
- S. Reportable occurrences, LERs ' related correspondence
- 8004170053 Interim deficiency rept re deficiencies in procurement. fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Estimates corrective action will be conpleted by 800601 CHIAPOI II J Carolina Power & Light Co 80/02/29 ip
- 8004280540 Interim deficiency rept re omission of reber in Unit 1 containment bldg exterior wall Caused by unique ref notation of 'addl skeel" (25 bars) on main reinforcing drawing Significance not fully recongnized on drawing JONES. J A Carolina Power & Light Co 80/04/16 5pp
- 8004280561 Interim deficiency rept re omission of reber in Unit i containment bldg exterior wall, adjacent to const opening for equipment batch Review will be expanded to include drawing review of reinforcing steel in Class I structures JONES, J. A. Carolina Power & Light Co. 80/04/18 2pp
- DOCKET 50~403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4 A Application/construction stage documents & correspondence
- BOO4040031 Advises of issuance of NUREG-0588 "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment." providing guidance re methods for compliance ROSS.D F Division of Project Management BO/02/05 7pp
- JO4170047 Discusses deficiency re-defective seismic Class I hanger welds Deficiency no longer considered reportable under 10CFR50 55(e) Corrective action completed % found to be chianging J Carolina Power & Light Co 80/02/22 1p
- 800408045: Forwards const milestones / activities schedule.updated to MCDUFFIE, M A Carolina Power & Light Co 80/04/02 13pp
- ina Power 5 Light Co 80/04/15 2pp

re electrical field gradients surrounding equested in NRC 800324 ltr "wer & Light Co 80/04/15 2pp

fire protection plans

- e for evacuation time estimates. n postponed pending GAD
 - Tast Force 80/03/11 4pp

- G Adjudicatory correspondence
- 8004010519 Petition for review of ASLAB 800220 decision denying applicant motion for mod of ALAB-577 re mgt capability Supports NRC argument that ASLAB exceeded authority re staff procedures to treat OL Continicate of Svc encl TROMBRIDGE: G F Carolina Power * Light Co D Pittman Potts & Troubridge 80/03/11 13pp D'NEILL, J.H. Shaw,
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Noard notification Operations ODSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004210180 Order granting extension until 800418, for Commission to take action relevieu of ALAB-577 & ALAB-581 CHILK,S J Office of the Secretary of the Commission 80/04/11
- 8004280178 Memorandum / order reversing portions of ALAB-577 & ALAB-581 re-performance of administrative tasks in sevarate proceeding Declines to review applicant issues of ALAB-591 Directs NRC to conduct preliminary assessment re-ALAB-577 CHILK, S. J. Office of the Secretary of the Commission 80/04/17
- G Inspection reports, IF Bulletins ₺ correspondence
- 8004070058 Ack receipt of IE Insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 % 50-403/80-02 on 791228 % 800121-25 No proprietary info HOME.P W Carolina Power % Light Co 80/02/28 ip
- --9004090071 Forwards IE Insp Repts 50-400/80-02,50-401/80-02, 50-402/80-02 \$ 50-403/80-02 on 791228 & 800121-25 No noncompliance noted BRYNNI,J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/02/20 2pp
- --8004090084 IE insp Repts 50-400/80-02, 50-401/80-02, 50-402/80-02 & 50-403/80-02 on 791228 & 800121-25 No noncompliance moted Major areas inspected const status, licensee action on previous findings & IE Bulletin 79-25 BRADELY, R D Region 2, Atlanta, Office of the Director 80/02/20
- 8004070295 Act receipt of IE Insp Repts 50-400/80-04, 50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No propietary info HOWE.P W Carolina Power & Light Co 80/03/06 1p
- --8004070315 Forwards IE Insp Repts 50-400/80-04, 50-401/80-04, 50-402/80-04 & 50-403/80-04 on 800205-07 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- 8004070035 Ack receipt of IE lnsp Repts 50-400/80-05,50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No proprietary HOWE, P W Carolina Power & Light Co 80/03/07
- --8004070037 Forwards IE insp Repts 50-400/80-05,50-401/80-05, 50-402/80-05 & 50-403/80-05 on 800214-15 No noncompliance Region 2. Atlanta, Reactor Construction & Engineering ch 80/02/28 2pp BRYANT, J C Support Branch
- ---8004070043 IE Insp Repts 50-400/80-05.50-401/80-05.50-402/80-05 & 50-402/80-05 on 800214-15 No noncompliance noted Major areas inspected structural concrete & lakes dams & canals HARRIS.J R Region 2. Atlanta. Office of the Director 80/02/28.
- 8004150497 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080398 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required
 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/01

- 8004150067 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required
 - O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240245 Forwards IE Info Notice 80-14. "Sørety Suggestions From Employees" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02
- BD041B0378 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 2no
- B004230117 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004;80340 Forwards IF Bulletin 80-08. "Exam of Containment Liner Penetration Wolds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- S Reportable occurrences, LERs & related correspondence
- 8004170053 Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Estimates corrective action will be completed by 800601 CHIANGI,N J Garolina Power & Light Co 80/02/29 ip
- 8004280560 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall Caused by unique ref notation of "addl steel" (25 bars) on main reinforcing drawing Significance not fully recognized on frawing JONES, J A Carolina Power & Light Co 80/04/16 5pp
- 8004280561 Interim deficiency rept re omission of rebar in Unit 1 containment bldg exterior wall, adjacent to const opening for equipment hatch Review will be expanded to include drawing review of reinforcing steel in Class I structures JONES, J A Carolina Power & Light Co 80/04/18 2pp
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B004040031 Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RUSS.D F Division of Project Hanagement 80/02/05 7pp
- 8004220234 Forwards response to NRC 800306 request for add1 info re review of design groundwater levels BRQWN.8 C Virginia Electric & Power Co 80/04/18 5pp
- f Becurity, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 ORIMES B K Emergency Preparedness Task Force 80/03/11 4pp
- I Financial information
- BO04010269 Forwards Annual Rept 1979
 BAUM,E A Virginia Electric & Power Co 80/03/27 1p
- --8004010275 Annual Rept 1979
 * Virginia Electric & Power Co 79/12/91 32pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004090358 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II,Two-Inch.Tray Adsorber Calls," Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/06 2pp.
- B004090130 Forwards IE Insp Repts 50-339/H0-01,50-404/80-01 & 50-405/80-01 on 800129-0201 No noncompliance noted STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/22 2pp

- --8004070134 IE Insp Reptr 40-15-780-01,50-404/80-01 & 50-405/80-01 on 800127-0201 No noncompliance noted Major areas inspected erosion 's runoef controll-waste mgt,review of previous items b prooperational program

 JENKIIIS, G. R. Region 2, Atlanta Fuel Facility & Materials Safety Branch CUNNINGHAM', At Region 2 Atlanta, Office of the Birector 80/02/19 pp
- 8004010465 Notifies of suspension of review or IF Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Suspension due to feasibility study BROWN.S C Virginia Fictric & Power Co 80/03/28 ip
- 8004190540 Forwards IF Into Notice 80-17, "Instrument Failure Causes Opening or PORV ' Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Orrice of the Director 80/03/31 2nn
- 8004080652 Forwards IE Circular A0-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply ' No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01 2pp
- 8004150105 Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- BOO4240284 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees "No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004180299 Forwards IE Cliculat 80-07, "Ploblems U/HPCI Turbine Dil Bys " No written response required D'REJLLY, J.P. Region P. Atlanta, Orfice of the Director 80/04/03 2pp
- 800423010B Forwards IC Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Urfice of the Director BD/04/04 1p
- 8004180401 Forwards [E Rulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required O'REILLY, J.P. Region & Atlanta, Office of the Director 80/04/07 2nn
- 8004300415 Informs NRC that response to 1F Bulletin 79-03. "Longitudinal Weld Defects in ASME Type 304 Stainless Steel Pipe." has been suspended due to feasibility study at facility All nuclean-related activities have been curtailed BROWN S C Virginia Electric & Power Co 80/04/25 ip
- R. Periodic operating reports δ related correspondence
- 8004020157 Forwards, "Annual Update Rept-1980 on Const Settlement Monitoring Program" Due to limited amount of data obtained during present period of const activity, second update rept will be forwarded one yr after const is resumed BROWN,8 C Virginia Electric & Power Co 80/03/31 1p
- --8004020161 "Annual Update Rept-1980 on Const Settlement Manitoring Program " * Virginia Electric & Power Co 80/02/29 17pp
- 8 Reportable occurrences, LERs & related correspondence
- BOO4220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 HMITT, K N Region 2, Atlanta, Office of the Director 77/08/12
- 8004020459 Part 21 rept on 800728.88W made telephone rept re defect concerning potentially overstressed supports on reactor coplant letdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR.J H Babcock & Wilcox Co 80/03/03 App
- B004010397 Interim deficiency tept re potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOWELLIS H Consumers Power Co 80/03/27 (p

- --8004010404 Forwards addl info to Part 21 rept re potentially overstressed supports on macher coolant letdown coolers at facilities under const by BBN TAYLOR. J H Babcock * Wiltor Co 80/03/03 App
- 8004220611 Interim deficiency meptine overfilling steam generators by excessive addition of auxiliary feedwater Potential results include excessive steam generator tube stress t containment pverpressurization BROWN SiG Virginia Electric to Power Co. 80/04/18 2pp
- DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0988, "Interim Staff Position on Environ Qualification of Sarety-Rolated Electrical Equipment," providing guidance is methods for compliance ROSS.D F Division of Project (Management 80/02/05 7pp
- 8004220234 Forwards response to NRC 800306 request for addl info re review of design groundwater levels BROWN S C - Virginia Electric & Power Co - 80/04/18 - 5pp
- F Security, medical, emergency 2 fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 1tr.has been postponed pending GAO clearance under Federal Repts Act ORIMES.B V Emergency Preparedness Task Force 80/03/11 4pp
- I Financial intermation
- 8004010269 Forwards Annual Rept 1979 BAUM,E A Virginia Electric & Power Co 80/03/27 1p
- --8004010275 Annual Rept 1979

 * Virginia blectric * Poyet Co 79/12/31 32pp
- G. Inspection reports. If Bulletins & correspondence
- 8004090358 Forwards IE Bulletin 80 03. "Loss of Charcoal From Std Type 11. Two-Inch.Tray Adsorber Cells " Action required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/06 20p
- 8004090130 Forwards LE Insp Repts 50~339/80~01.50~404/80~01 & 50~405/80~01 on 800129~0201 No noncompliance noted STDHR, J P Region P. Atlanta, fuel Facility & Materials Safety Branch 80/02/22 Ppp
- --8004090134 IE Insp Repts 50-339/80-01,50-404/80-01 & 50-405/80-01 on BO0129-0201 No noncompliance noted Major areas inspected erosion & runof* control, waste mgt. review of previous items & preoperational program
 JENKINS,0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch CUNNIGHAM*, At. Region 2, Atlanta, Office of the Director 80/02/19 3pp
- BO04010465 Notifies of suspension of review of LE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Suspension due to feasibility study BROWN-S C Virginia Electric & Pouer Co 80/03/28 ip
- 8004150540 Forwards IE Into Notice 80-12. 'Instrument Failure Causes Opening of PORV 2 Block Valve 'No specific action or response necessary O'REILLY, J.P. Region 2 Atlanta, Ortice of the Director 80/03/31 208
- 8004080652 Forwards IF Carcular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onaite Supply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- B004150105 Forwards IB info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/02
- 8004240284 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/02 200

- 8004180299 Forwards IE Circulat 80-07. 'Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/04/03 200
- BO04230108 Forwards IE Sulletin 79-03A 'Longitudinal Weld Defects in ABME 8A-312.Type 304 Stainless Steel Pipe " Action required O'REILLY.J P Region 2. Atlanta. Office of the Director BO/04/04 to
- BOO4180401 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILL'(JP Region 2. Atlanta, Orfice of the Director 80/04/07 2pp
- BOO4300415 Informs NRC that response to IE Bulietin 79-03, "Longitudinal Wold Derects in ASME Type 304 Stainless Steel Pipe," has been suspended due to reasibility study at facility All nuclear-related activities have been curtailed BROWN, B.C. Virginia Electric & Power Co. 80/04/25 ip
- R Periodic operating reports & related correspondence
- BOO4020157 Forwards. "Annual Update Rept-1980 on Const Settlement Monitoring Program " Due to limited amount of data obtained during present period of const activity, second update rept will be forwarded one yr after const is resumed BROWN.S C Virginia Electric & Power Co BO/03/31 1p
- --8004020161 "Annual Update Rept-1980 on Const Settlement Monitoring Program " * Virginia Electric & Power Co 80/02/27 17pp
- S Reportable occurrences, LERs & related correspondence
- 8004220084 PNO-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770612 WHITT.X W Region 2. Atlanta, Office of the Director 77/08/12
- B004020457 Part 21 rept on 800228,850 made telephone rept re defect concerning potentially overstressed supports on reactor coolant letdown coolers due to inadequate aupport design Corrective action redesign of support stand TAYLOR.J H Dabcock & Wilcos Co 80703702 App
- BOO4010397 Interim deficiency tept re-potential overstress condition in letdown cooler supports Nozile loads will be analyzed for effects on support structure to determine if mads are required to cooler support sys.

 HONELL, S. H. Consumers Power Co. 60/03/27 ip
- --B004010404 Forwards addl into to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by B&W TAYLOR. J H Babcock & Wilcox Co B0/03/03 App
- 8004220A11 Interim deficiency rept re overfilling steam generators by excessive addition of auxiliary freedwater Potential results include excessive steam generator tube stress & containment overpressurization DROWN S C Virginia Electric & Power Co 80/04/18 2pp
- DUCKET 50-409 LA CROSSE BUILING WATER REACTOR
- A Application/construction stage documents & correspondence
- 7809270003 Forwards addl info in response to request of Dairyland Power Comperative representatives at 780808 meeting re SEP STEPP, J C Geosciences Branch 78/09/11 3pp
- 800404076 Notification of 800325-26 meeting w/util in La Crosse.WI to discuss inservice besting program SHEA.J J. Operating Reactors Branch 2 80/03/05 2pp
- F Security, medical, emergency & fire protection plans
- 8004010410 Forwards discussion of info received from licensee on fire protection review items includes info re interior hose stations, fixed suppression systheat circuit supervision & breathing air

 HALL-R E Brookhaven National Laboratory 80/03/26 9pp

G Adjudicatory correspondence

- 8004220417 Forwards Decision DD-80-9, granting partial acceptance of AK Morse 79052; petition for issuance of older to suspend provisional DL Adequate basis for suspension does not exist Order to show cause has been lessued DENTON, HR Office of Nuclear Reactor Regulation 80/02/29 2pp
- --8004220422 Decision DD-80-9, granting partial acceptance of AK Horse 790521 petition for issuance of order to suspend provisional DL Adequate basis for suspension does not exist Order to show cause has been issued DENTON H R Office of Nuclear Reactor Regulation 80/02/29
- --8004220430 Notice of issuance of Director's Decision DD-80-9, granting partial acceptance of AK Norse petition for issuance of order to suspend provisional DL Adequate basis for suspension does not exist Request handled under 10CFR2 206 DENTON, H R Office of Nuclear Reactor Regulation 80/02/27 2pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OUSSICK.i V Office of the Executive Director for Operations 80/04/02 34pp
- BOOA100364 Notifies that issuance of FES will be delayed for approx two wks WCIODHEAD: C P Hearing Branch 3 80/04/03 ip
- 8004210091 Order granting NRC 800313 motion to compel Coulee Region Energy Coalition to respond to NRC 791214 interrogatories, by 800425 Intervenor failed to comply w/ASLB 791130 order setting discovery schedule refull-term DL proceeding BECHMOEFER.C Atomic Safety and Licensing Board Panel 80/04/04 200
- 8004210174 Order granting extension, until 800415, for Commission to elect whether to review Director's 800227 decision CMILK.B J Office of the Secretary of the Commission 80/04/10

H General correspondence

- 800417030; Responds to 800124 ltr to HR Denton requesting all future meetings re facility be held in WI & ASLD decision to allow expansion of facility spent fuel storage pool No secrecy involved in NRC activities Documents & meetings accessible DIRCKS, W J Office of the Executive Director for Operations 80/03/28 3pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8004040261 Forwards certified summary of ACRS Subcommittee on LACSHR 791026 meeting in Washington.DC re proposal to enlarge storage apacity of spent fuel storage pool MCKINLEY,J C ACRS -- Advisory Committee on Reactor Safeguards 80/02/06 1p
- --8004040267 Certified summary of ACRS Subcommitte on LaCrosse BWR 791026 meeting in Washington.DC re proposal to enlarge capacity of spent fuel storage pool

 # ACRS Advisory Committee on Reactor Safeguards 80/01/08
- P Operating license stage documents & correspondence
- 7812060303 Notification of 781207 meeting w/SEP Owner's Group in Nethesda,MD to discuss plans to address seismic input for use in SEP seismic review LEVIN.H A Systematic Evaluation Programs Branch (Pre 790625) 78/11/24 2pp
- 8004100314 Advises that responses to 741123 ltrs re LMR assessment of enhancement of fission gas release at higher burnups have been reviewed No immediate licensing action required for operating reactors, per typical fuel bundle & batch burnups ZIEMANN, D L. Operating Reactors Branch 2 80/02/29 3pp
- 8004080195 Forwards NUREG-0969, "Evaluation of Integrity of SEP Reactor Vessels," completing review of SEP Topic V-6 W/o encl ZIEMANN.D L. Operating Reactors Branch 2 80/03/05 2pp
- 8004020003 Forwards review schedule for environ qualification of Class IE electrical equipment per 800221 meeting Resubmittal of info is unnecessary Refs or updates to info previously submitted are acceptable ZIEMANN,D L. Operating Reactors Branch 2 80/03/06 5pp

- 8004030102 Forwards "Nuclear Data Link Specs," study of digital communication sys to transmit info from plants to Bethesda Operations Ct: EISENHUT.D G Division of Operating Reactors 80/03/12 Spp
- --8004030118 "Nuclear Data Link Specs " * Division of Operating Reactors 80/02/21 28pp
- 8004070321 Forwards operating instructions 5 characteristics of NRC health physics telephone network furpose of network is transmission of health physics info during incident or abnormal occurrence at facility KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/19
- 8004100114 Requests that uncontrolled set of P&IDs be placed on controlled distribution list to any future revisions . Revisions should be forwarded to attention of Region 3 incident response ctr KEPPLER. J G Region 2, Chicago, Office of the Director 80/03/20
- 8004210409 "Response to NRC Concerns on Liquefaction Potential " * Dames & Moore 80/03/21 32pp
- 8004090369 Forwards "Safety Evaluation & Compilance w/NRC Staff Positions ie LACBUR Emergency Power Sys," App A rø test procedures for annual tests of emergency diesel generators IA & 18 Procedures inadvertently omitted from 800/03/28 ipp
- ---BOO4090376 "Safety Evaluation & Compliance w/NRC Staff Positions re LACGUR Emergency Power Sys." App A re tost proceudres for annual tests of emergency diesel generators 1A & 1B # Nuclear Energy Service, Inc. 80/03/28 10pp
- 8004170290 Forwards request for add) info is environ qualification of olectrical equipment ZIEMANN.D L. Operating Reactors Branch 2 80/03/28 14pp
- 8004140312 Requests that Toch Specs 4 2 4 2 5 ½ 5 2 17 5 be amended so that exposure limitation applies only to fuel assemblies in core interior & exposure limit on peripheral assemblies is deleted Forwards proposed revision to Tech Specs LINDER, F Dairyland Power Cooperative 80/04/01 4pp
- --8004140314 Proposed revision to Tech Specs 4 2 4 2 5 & 5 2 17 5
 applying exposure limitation only to fuel assemblies in core
 interior & deleting exposure limit on peripheral assemblies
 Supporting documentation encl
 * Dairyland Power Cooperative 80/04/01 11pp
- 8004070303 Forwards corrected Pages 3 % & of util response to show cause order & corrected Table 2 % Figures 1-3 of Dames % floore rept which accompanied lesponse HIESTAND G \$2 florgan, Lewis & Buckius 80/04/03 9pp
- 8004150204 Forwards response to request for add1 info resulting from NRC site review of compliance w/NVREG-0578 Revised pages to 800131 Its also encl LINDER.F Dairyland Power Cooperative 80/04/09 15pp
- Q Inspection reports, IF Bulletins & correspondence
- BOD4100134 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Black " No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/07
- BOO4010108 Responds to IF Bulletin 80-02, "Inadequate QA for Nuclear Supplied Equipment " No Marvin Engineering Co equipment installed at facility LINDER, F Dairyland Power Cooperative 80/03/10 2pp
- 8004150170 Forwards It Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/31 10
- 800A0B07Q4 Forwards IE Circular 80-05, "Emergency Dissel Generator Lubricating Oil Addition 5 Onsite Supply "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01 ip

- 8004150027 Foluards If Inc. Helic 80-11 'GE Type SBM Control Switches Defective CAM Followers 163 specific action or response required

 XEPPLER Jr. Region 7 Phicago Office of the Director 80/04/02
- 8004180048 Forwards Attarburnt, on IE Circulai 80-03, "Protection From Toxic Gas Haiarids" inad ertaintly omitted from 800306 transmittal REPPER J v. Reginn 3 th, ago, Orrice or the Director 80/04/02
- 8004220135 Forwards IF Into Notice 80-14, "Safety Suggestions From Employees 'No action required KEPPLER, J.G. Region 3 Chicago, Office of the Director 80/04/02
- 8004220357 Forwards 16 circular 80-07. Problems N/MPCI Turbine Oil Sys "No written response required KEPPLER, J.G. Region 3, Chicago Office of the Director 80/04/03
- 8004110035 Forwards 18 Builletin 80-07. PWR Jet Pump Assembly Failure " Written response required KEPPLER, J G Region 3 Chicago, Office of the Director 80/04/07
- 8004230199 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/04/07
- 8004220104 Forwards 1E Bullefin 80-08, 'Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Orfice of the Director 80/04/09
- A Periodic operating reports & related correspondence
- B004140365 Forwards monthly operating rept for Mar 1980 LINDER,F Dairyland Power Cooperative 80/04/07 1
- --8004140367 Monthly operating rept for Mar 1980 GOBDMAN.L S Dairyland Power Cooperative
- S Reportable occurrences. LERs & related correspondence
- BOO41504BB RO on BOO409 while in shutdown condition abnormal degradation was discovered in primary reactor containment during periodic. Type B 'C surveillance leak rate testing unstated Reapirs underway R.F. Dairyland Power Cooperative 80/04/10 2pp LINDER
- 8004220584 RO 80-01 800410, during periodic Type B leak rate tests, electrical penetrations 3.4 2 5 exceeded permissible rates. Caused by abnormal degradation Flectrical penetrations being LINDER, F Dairyland Power Cooperative 80/04/10 2pp
- 8004210200 RD-80-02 on 800415 during periodic Type C surveillance leakage rate testing, leak flow rates determined from exhaust dampers exceeded permissible leak flow rates Repairs to exhaust dampers being accomplished & retests will be made LINDER: F Dairyland Power Cooperative 80/04/16 2pp
- 8004290341 RO 80-03 on 800417 during periodic Type C surveillance leakage rate testing on containment bldg heating sys valve, leak flow rates found in ercess or permissible leak flow rates Cause unstated Valve repairs & adjustments planned LINDER,F Dairyland Power Cooperative 80/04/17 2pp
- BO04300456 Forwards LER 80-901/01T-0 LINDER:F Dairyland Power Cooperative 80/04/21 Spp
- --8004300463 LER 80-001/01T-0 on B00409, during periodic leakage rate testing, electrical penetration units 3.4, & 5 did not meet type 8 test criteria Caused by cracked penetration glands individual penetrations replaced G00DMAN.L S Dairyland Power Cooperative 80/04/21 1p
- U Congressional/Executive Correspondence
- 8004080260 Responds to 800128 ltr concerning Coulee Region Energy Coalition inquity re facility full-term OL proceeding DOE should be contacted for federal funding info Coalition environ evidence will be considered at ASLB hearing DIRCKS: N J Office of the Executive Director for Operations 80/03/10 2pp

- 8004080204 Requests response to encl Coulee Region Energy Coalition ltr te facility roll-term Ol proceeding PROXMIRE,W Senate 80/01/20 App
- 8004140235 Forwards response to Badger Safe Energy Alliance 800126 ltr of concern re facility in response to 800208 request W/o
 - enci DIRCKS,W J Office of the Executive Director for Operations 80/03/28 ip
- --8004140238 Requests info on encl Badger Safe Energy Alliance 900126 ltr requesting that future NRC meetings ie facility be held in LaCrosse.MI area REDELMAN, J MELSON: G Senate 80/02/08 2pp
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8004040031 Advises or issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Sareby-Related Electrical Equipment," providing guidance te methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004020466 Notification of 800326 ½ 27 meeting w/representatives from Mark II owners group in San Jose.CA to discuss Mark II Creace Test Program.41 c/o tests ½ foleign bests ELTAWILA.F Containment Systems Branch 80/03/10 12pp
- 8004030122 Notification of 800326-27 meeting w/Mark II owners group, NRC consultants & GE in San Jose, CA to discuss Mark II Creare test program. 4T C/O & foreign tests Topics are proprietary Agenda enci ELTAWILA,F Containment Systems Branch 80/03/10 12pp
- 8004010014 Forwards NRC 800128 % 0211 Itrs to GE re mods to BWR control UNAULUDIA FORMATOS NKC BUDIZES & UZI I ITA 60 UR FE MOSS TO BWK EI GTIVE Sys Mods should not be performed prior to issuance of NUREO-O619 Appropriate sys mods & supporting analyses should be incorporated into FSAR RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/11 2pp
- BOO4100301 Notification of 800403 meeting w/GE in Bethesda, MD to discuss BMR & safety relief valves mfg by G Dickens & Co & supplied by GE to facilities HENDERSON, J B Division of Reactor Construction Inspection 80/03/13 200
- 8004040474 Bummary of 800227 meeting w/Mark II coners group re status of several long-term program tasks.including Tasks A 17 & A 16 & task related to utilization of foreign test data ELTAWILA.F Containment Systems Branch 80/03/18 104pp
- B004100297 Requests add1 info re 790809 proposal to use alternative method of splicing reinforcing steel bars than described in facility PSAR Reply must be notarized RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/25 3pp
- 8004300061 Summary of 800326-27 meetings w/Mark II owners group in San Jose,CA re discussion of NRC concerns on data from Crears tests & foreign full-scale test programs & relationships w/ Mark II designs ELTAWILA,F Containment Systems Branch 80/04/14 22pp
- 8004250419 Requests authorization to use ASMC Section III Code Case N-242, "Matis Certification " Code case approved for SNUPPB by OD Parr in 790713 itr BARLETT, J. Niagara Mohauk Power Corp. 80/04/21 ip
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr.has been postponed pending GAD clearance under Federal Repts Act GRIME8.8 K Emergency Preparedness Task Force 80/03/11 App
- B004070034 Forwards copy of NRC 771121 generic 1tr re upgraded emergency plans Document also available in local PDR W/o RUBENSTEIN, L.S. Light Water Reactors Branch 4 80/03/25 1p
- H General correspondence
- 8004280374 Informs of mgt changes BARTLETT, J Niagara Mohawk Power Corp 80/04/22 ip

- G Inspection reports, IE Bulletins 5 correspondence
- 8004150285 Forwards IE. Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/31 ip
- 8004300282 Ack receipt of 800319 ltr informing NRC of steps taken to correct violations noted in IE insp Rept 50-410/80-01 CARLSON, R T Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 60/03/31 ip
- --8004300290 Responds to NRC 800214 Itr re violations noted in IE Insp Rept 90-410/80-01 Corrective actions increased training of preventive maint personnel will be instituted, using formal & on-job sessions BARTLETT. J. Niagara Mohawk Power Corp. 80/03/19 3pp
- --8004300296 Forwards IE Insp Rept 50-410/80-01 on 800109-11 & notice of violation CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/14 2pp
- --B004300301 Natice of violation from insp on 800109-11
 * Region 1, Philadelphia, Office of the Director 80/02/08 2pp
- --B004300309 IE Insp Rept 50-410/80-01 on 800109-11 Noncompliance noted failure to perform required equipment maint, to furnish recorded evidence of maint & to control equipment storage MCOAUGHY, R W Region 1. Philadelphia, Reactor Construction & Engineering Support Branch CERNE, A C Region 1. Philadelphia, Office of the Director 80/02/08 7pp
- 8004090077 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required ORIER, B H Region I. Philadelphia, Office of the Director 80/04/01 ip
- 8004110159 Forwards IE Info Notice BO-13, "GE Type SBM Control Switches Defective CAM Followers" No written response required GRIER, B M. Region 1, Philadelphia. Office of the Director BO/04/02 1p
- 8004240330 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required GRIER, B H Region I, Philadelphia, Office of the Director 80/04/02 ip
- 8004180180 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Dil 8ys " No written response required ORIER.D H Region i, Philadelphia, Office of the Director 80/04/03 1p
- 8004110058 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required ORIER.B H Region i, Philadelphia, Office of the Director 80/04/04 lp
- 8004230486 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312,Type 304 Stainless Steel Pips " Action required ORIER,B H Region I. Philadelphia, Office of the Director 80/04/04 ip
- 8004180205 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required ORIER, B H. Region 1. Philadelphia. Office of the Director 80/04/07 tp
- 8 Reportable occurrences, LERs & related correspondence
- 8004100580 Ack receipt of 800205 interim deficiency rept re possible future movement of radwaste bidg geologic feature CARLEGUR.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/21 1p
- 8004220559 Forwards interim deficiency rept re defects in biological shield wall shop welds previously reported 790530 Final rept summarizing test & analyses & identifying possible safety implications will be provided by 800801 TERRY, J H Niagara Mohawk Power Corp 80/04/15 ip
- ---8004220577 Interim deficiency rept re defects in biological shield wall shop welds Cause unstated Defect sizes & locations will be mapped, based on engineering evaluation to determine allowable defects Repairs will be performed as required * Niagara Mohawk Power Corp 80/04/15 25pp

- DOCKET 50-412 BEAVER VALLEY POWER STATION. UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises or issuance of NUREG-0588, 'Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance is methods for compliance ROSS, D.F. Division of Project Minagement 80/02/05 7pp
- 6004070336 Advises that due to studies of electric svc requirements % const expenditure forecasts, buel load date was deferred from 831231 to 851231 Commercial operation date scheduled for 860531 FSAR & environ tept submittal scheduled for 821231 WODLEVER.E J. Duquesne Light Co. 80/03/26 tp
- F Security, medical, emergency % fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Ropts Act ORIMES, BK Emergency Prepaledness Task Force 80/03/11 4pp
- G Inspection reports. 1E Bulletins & correspondence
- 7906010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41, into on seismic issues prepared for SEP & insp repts for Beaver Valley WEISS, E.R. Sheldon, Hermon & Weiss /9/03/19 2pp
- 8004280188 Responds to II. Bulletin 80-03 Insp of chargoal adsorber cells shall be performed when received WODLEVER.E J Duquesne Light Co 80/03/19 tp
- 8004150266 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 | 19
- 8004090052 Forwards IE Chicular BG-05, "Emergency Diesel Generator Lubricating Oil Addition » Onsite Supply " No written response required GRIER, B *# Region i, Philadelphia, Office of the Director 80704/01 ip
- 8004110133 Forwards IF info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required ORIER.B H Region 1, Philadelphia. Office of the Director 80/04/02 1p
- 8004240303 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required GRIER.II H Region 1. Philadelphia, Office of the Director 80/04/02 ip
- 8004180192 Forwards IF Circulor 80-07, 'Problems W/HPCI Turbine 0:1 Sys " No witten response required CRIER.D H Region 1, Philadelphia, Office of the Director 80/04/03 | 1p
- 8004230475 Forwards IE Builetin 79-03A. "Longitudinal Wald Defects in ABME SA-312, Type 304 Stainless Steel Pipe " Action required ORIER, B H. Region J. Philadelphia. Office of the Director 80/04/04 ip
- 8004180134 Forwards IE Bulietin 80-08, "Exam of Containment Liner Penetration Welds" Writton response required ORIER.B R Region 1, Philadelphia, Office of the Director 80/04/07 1p
- 8004220483 Responds to NRC 800313 ltr re unresolved items & allegations noted in IE insp Rept 30-412/80-02 Corrective actions util initiated QA audits to confilm piping fabricator actions prior to 800601 WQQLEVER.E J Duquesne Light Co 80/04/14 22pp
- 8 Reportable occurrences, 1ERs & related correspondence
- 8004220084 PND-77-143 Pacific Pump Co supplied facilities w/production lot of 40 pumps mfg using shafts made of inferior matl Cause unstated All utils w/pumps were notified NRC headquarters notified on 770812 WHITT, K W Region 2, Atlanta, Office of the Director 77/08/12

- EU04230159 Requests extension From BC1413 to 0615 for final nept on Significant Deficiency (2-15 fe weld discrepancies in reaction reset structured asspirat More time required for tampling analysis in the Lution or deficiency GCDLEVER Editor Disqueere Lighton (80.04/17) Ip
- Operator Examinations
- 8004070043 Denie, int 8007 4 request for administering unitten examination. User Bookhi i delaying oral operating examinations until 501 179, due to lack or reactivity manipulations. CCCLLIPS P.F. Operator Liberaring Smanch 80/03/19 2pp
- BOCKET 50-413 CATARGA NULLEAR STATION, UPIT 1

 A Application/constructs in stage documents & correspondence
- #3040406731 Ad ises of issuance or NUREG-0588, "Interin Staff Position on Environ Gualification of Sarety-Related Electrical Equipment, pro iding guidance ie methods for compliance ROSS D.F. Ulvision of Project Management 80/02/05 7pp
- 8004040017 Submits add1 pridance to NuREG-0588, "Interim Staff Position on Environ Qualification or parety-Related Electrical Equipment ' Requests relieu or equipment qualification documentation to identify degree of compliance 805S.D F. Division of Project Management 80/02/21 3pp
- B004090155 Summary of B00314 meeting w/otils.Westinghouse & Sargent & Lundy re Westinghouse optimized fuel assembly Comm Ed requested to amend FSAR as soon as possible to show plant will use optimized fuel assembly KINTNER.L Light Water Reactors Branch 1 80/03/18 Bpp
- B004170327 'TMI-Plus One Toward a Safer Nuclear Power Program "

 Duke Power Co 80/03/26 13pp
- 8004140430 Forwards companison or draft STS w/snubber functional test sampling plan COLLINGS, D. M. Duke Power Co. 83/04/03 11pp
- F Security, medical emergency & tire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by MRC 791226 ltr.has been postponed pending GAD cleanance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- G Inspection reports, IE Bulletins 3 correspondence
- B004020019 Discusses completed diesel generator factory test per IE Bulletin 79-23 Voltage & frequency requirements maintained during test & cooling sys runctioned within design limits PARVER.W O Duke Power Co B0/03/20 ip
- 8004210164 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type 11. Two-Inch. Tray Adsorber Cells " Containment cleanup is only unit using design described in bulletin No sign of sagging screens or other derect that would permit leakage PARKER, W.O. Dute Power Co. 80/03/24 1p
- 8004210234 Ack receipt of 1E Insp Repts 50-413/80-03 & 50-414/80-03, on 800214-15 No proprietary info PARKER, W D Duke Power Co 80/03/28 1p
- --B004210242 Forwards lE Insp Repts 50-413/B0-03 % 50-414/B0-03 on B00214-15 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/03/10 2pp
- --B004210247 IE insp Repts 50-413/80-03 \$ 50-414/80-03 on 800214-15 No noncompliance noted Major areas inspected indoctrination of new resident inspector for const BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch MCFARLAND.C R Region 2. Atlanta, Office of the Director B0/03/10 4pp
- 8004150511 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Biock Valve ' No specific action or response necessary O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/31

- 5004080511 Forwards IE Circular 80-05, "Emorgency Diesel Generator Lubricating 0:1 Addition & Onsite Supply "No written response required O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/04/01
- 8004160116 Ack receipt of IF Insp Repts 50-413/80-02 & 90-414/80-02 on 800212-14 No proprietary info PARKER, W D Duke Power Co 80/04/01 1p
- --B004160118 Forwards IE Insp Repts 50-413/80-02 & 50-414/80-02 on B00212-14 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/03/12 2pp
- --8004160122 IE Insp Repts 50-413/80-02 & 50-414/80-02 on 800212-14 No noncompliance noted Major areas inspected RCPB piping, safety-related piping, vendor pipe welds w/rejectable indications & safety-related structures HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS, N Region 2, Atlanta, Office of the Director 80/03/11 7pp
- 8004150070 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director BD/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004180326 Forwards IE Circular 80-07, "Problems H/HPCI Turbine Dil Sys " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/03 2pg
- 8004230132 Forwards IE Bulle... 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- B004180358 Forwards IE Bulletin B0-08, "Exam of Containment Liner Penetration Weids " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07
- DUCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NURCO-0588, "Interim Staff Position on Environ Qualification of Safoty-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- B004170327 "TMI-Plus One Toward a Safer Nuclear Power Program " * Duke Power Co 60/03/26 13ep
- BCO4140430 Forwards comparison of draft STS w/snubber functional test sampling plan CULLINGS.D M Duke Power Co 80/04/03 iipp
- F Security, medical, emergency & fire protection plans
- BODAOBOO77 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- Q Inspection reports, IF Bulletins & correspondence
- 8004020019 Discusses completed diesel generator factory test per IC Bulletin 79-23 Voltage & frequency requirements maintained during test & cooling sys functioned within design limits PARKER.N O Duke Power Co 80/03/20 1p

DOCKETED ITEMS

- 80042i0164 Responds to 1E Bulletin 80-03, "Loss of Charcoal from Std Typs II. Two-Inch. Tray Adsorber Cells " Containment cleanup is only unit using design described in bulletin No sign of sagging screens or other defect that would permit leakage PARKER. W O Duke Power Co 80/03/24 1p
- 8004210234 Ack receipt of IE Insp Repts 50~413/80~03 & 50~414/80~03. on 800214~15 No proprietary into PARKER, W O Duke Power Co 80/03/28 ip
- --8004210242 Forwards IE Insp Repts 50-413/80-03 & 50-414/80-03 on BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch SO/03/10 2pp
- --8004210247 IE Insp Repts 50-413/80-03 & 50-414/80-03 on 800214-15 No noncompliance noted Major areas inspected inductrination of new resident inspector for const BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND, C R Region 2, Atlanta, Office of the Director 80/03/10 4pp
- 8004150511 Forwards JE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response nacessary O'REJILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080611 Ferwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04, Region 2, Atlanta, Office of the Director 80/04/01
- 8004160116 Ack receipt of IE Insp Repts 90~413/80~02 & 50-414/80~02 on 800212~14 No proprietary info PARKER,W O Duke Power Co 80/04/01 Ip
- --8004140118 Forwards IE Insp Repts 50-413/80-02 & 50-414/80-02 on BOO212-14 No noncompliance noted
 BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering
 Bupport Branch 90/03/12 2pp
- --8004160122 IE Insp Repts 50-419/80-02 & 50-414/80-02 on 800212-14 No noncompliance noted Major areas inspected RCPB piping, safety-related piping, vendor pipe welds w/rejectable indications & safety-related structures HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2. Atlanta, Office of the Director 80/03/11 7pp
- 8004150070 Forwards IC Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response D'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02
- 8004240249 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180326 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Cil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230132 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 9A-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04 BD/04/04
- 8004180358 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penstration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- DOCKET 50-416 GRAND OULF NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSS.D F Division of Project Managament 80/08/05 7pp

- 800404001/ Submits add1 guidance to NUREG-0588, "Interim Staff Position on Environ Qualification or Carety Related Electrical Equipment 'Requests review or equipment qualification documentation to idvolviny degines of compliance RDSS.D F Division of Project Management 80/02/21 App
- 8004020446 Forwards NRC BROOLER' (211 lins to GE re mods to BWR control rod drive sys ? addl analyses or boiloff rates respectively Further info / guidance to be issued in NUREG-0619 Light Water Reactors Branch P 80/03/13 2pp
- BOO4100301 Notification or BAO403 meeting w/GC in Bethesda.MD to discuss BMR & safety relief valves mfg by G Dickens & Co & supplied by GE to facilities HENDERSON IB Division of Reactor Construction Inspection 80/03/13
- 8004030149 Requests addi into to complete facility environ review Forwards specific list of required info Reply should consist of sequentially numbered revision to final environ rept BALLARD, R. L. Frysrommental Projects Branch 1 80/03/14 3pp
- 8004090341 Forwards application for amend of Licenses CPPR-118 & CPPR-119 Also forwards 1007850 App L antitrust info STAMPLEY.N L Mississippi Power & Light Co 80/04/03 2pp
- --8004090345 Application for amend of CPPR 118 % CPPR-119 adding South MI Electric Fower Association as co-owner Drafts of joint constracquistion % ownership agreement operating agreement to substitute power agreement encl

 * Mississippi Power % Light Co 80/04/03 240pp
- --8004090350 Annual Financial Rept 1978 Addl financial info attached # Gouth Mississippi Electric Power Association 78/12/31 150pp
- 8004210228 Forwards info per NRC 800214 request, supporting confirmatory Detailed Treguest Supplied on South of the County of the Properties of Safety Tollief Valve 16 itscharge line Revision 6 to piping design Spec 9645—8220 0 other supporting info 6 drawings available in Central Files on DALE, L.F. Mississippi Power / Light Co. 80/04/09 4pp
- 8004280084 Forwards Instrumentation & Control Branch request for addl info re FSAR Sections 7 4 % 7 5 FSAR should be amended to reflect responses to requests BAER.R L Light Water Reactors Branch 2 80/04/09 9pp
- 8004170243 Forwards fee re 740710 request for approval of deletion of stage monitoring requirement in environ protection program DALE, L.F. Mississippi Power & Light Co. 80/04/16. 1p
- C Utility Environmental Report (ER), amends & correspondence
- BOO4220421 Forwards correspondence between util & State of MI Natural Heritage Program per Guestion 340 l4 on final environ rept DALE, LF Mississippi Power & Light Co 80/04/16 App
- BOD4220289 Forwards Amend 3 to environ rept.consisting of responses to 800122 requests for add1 info STAMPLEY,N L Mississippi Power & Light Co 80/04/18 1p
- --8004220293 Amend 3 to environ rept
 * Mississippi Power % Light Co 80/04/18 40pp
- f Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estima requested by NRC 791226 lti.has been postponed pending QAO cleanance under Fedesal Repts Act GRIMEG.B K Emergency Preparedness Task Force 80/03/11 4pp estimates,
- B0041005B4 Notification of postponement of 800414-16 meeting w/util. Bechtel % Gage Babcock in Port Dibson.NS to review facility fire protection HDUGHTDN,T C Light Water Reactors Branch 2 80/03/11 2pp
- H General correspondence
- 8004100362 Responds to NRC 780627 ltr by forwarding affidavit of svc redistribution of Amend 37 to CPPR-118 & CPPR-119
 DALE, L F Mississippi Power & Light Co 80/04/07 2pp
- I Financial information
- 8004220535 Annual Financial Rept 1979 Middle South Utilities. Inc 79/12/31 40pp

- m (Amilian, film), where it is a sport (FMAR) A amends
- if APP 3-1 figure when, it is application for OL Also forwards piping instruct thick trap is the first all drawings blockmand in wings to an interpret to the instance of the stance of
- FUGALT 1 Internation that Arism for OL Consists of responses to 1.00 guestions in Fig. this seek of design into Collectiff the arism of the collectiff that the collectiff the collectification of the collectification of the collectiff the collectification of the collectificati
- = 3004FF 'A Figury' 1 fours forion Diagram Reactor Water Cleanup Sys • Pechhalicop (A46 TG.12 II Ip
- n 827423 mm1 (Hend mm + h for Riverstating of responses to NRC questions & missellaneous respondents or design this missellaneous respondents of design this missellaneous follows to the following the missellaneous follows the following section of the following section of
- M Antifrust corresponder e
- LORAGRIZER Response to Tr. Conner 200312 ltm to NRC me interconnection agreement Absence to see wheeling to execution of Gulf States (Vil C. Intiviate agreement of interned to be operative Requests resolution before DL stage MCDIAPMID R C. Chiegel / McDiarmid 80/04/04 2pp
- ~-8004090253 fetition to intervene in proceeding Urges Commission to accept intercorner tion agreement for Filing, suspend agreement operation for one day? set issue for immediate conference? hearing MCDIARMID, R.C. Michigan "tate or MCDIARMID, R.C. Spregel & McDiarnid 80/03/28 App
- 8004150197 Finds antitrust info submitted 800403 acceptable for dorketing? distribution TQALSTOR, A Antitrust Indemnity Group 80/04/14 ip
- --BOD4150200 Forwards antitiust info per application for amend of Licenses CPPR-118 / CPPR-119 STAMPLE/,N L Mississippi Power / Light Co BO/04/03 10pp
- 8004180283 Forwards info re South M5 Electric Power Association, submitted per App L of 10CFREO or Commission Rules of Practice Info transmitted to orren opportunity to render advice re findings to be nade by Commission M/o encl SHAPAR, H w. Orfice of the Ejecutive Legal Director 80/04/16 1p
- 3 Inspection reports IF Sulletins & correspondence
- 8004070337 Forwards IF Bullistin 80-03. Loss of Charcoal From Std Type II. Two-Inch Tray Asserber Fells ' Action required O'REILLY, J.P. Region 2 Atlanta, Orfice of the Director 80/02/04 2pp
- EOD404084 Forwards IF Irsp Repts 50-416/80-01 & 50-417/80-01 on 600122-24 No noncompliance noted BRYANTJ C Region 2 Atlanta Reactor Construction & Engineering Support Branch 60/02/12 2pp
- --8004040125 IE Insp Repts 50-416/80-01 * 50-417/80-01 on 800122-24 No noncompliance noted Major areas inspected offsite warehouse insp t observation or safety-related activities Followup on IE builetin.inspector ; licensee identified items CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch RAUSCH, J K Region 2. Atlanta, Office of the Director 80/02/11 App
- BOC4040201 Forwards IF Repts 50-416/80-06 5 50-417/80-05 on 800129-31 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/15 2pp
- ---8004040222 IE Insp Repts 50-416/80-06 & 50-417/80-05 on 800129-31 No noncompliance noted Major areas inspected safety-related pipe welding, reactor pressure boundary pipe handling & deling & followed on previously identified items HERDY, A R Region 2 Atlanta Reactor Construction & Engineering Support Branch VANDOGRN P K Region 2, Atlanta, Office of the Director 80/02/15 4pp
- BOO4100045 Forwards IE Insp Rept 50-416/80-03 on B00129-0201 No noncompliance noted BRYANI.J C Region 2. Atjante, Reactor Construction & Engineering Support Branch 80/02/20 2pp

- -2004(10005) [E insp kept 50 444/80-03 on 800129-0201 No noncompliance noted Major areas insperted protection 5 maint of sarety-related electrical equipment instrumentation work 7 review or associated records COLONITE Region 2. Atlanta Reactor Construction & Engineering Support Branch RUFFLAD Region 2. Atlanta, Office of the Director 80/02/19 Jpp
- BC042300/0 Responds to 1E Bulletin 80-03, "Loss of Charcoal from Std Type 11.Two-luch.Tray Adsorber Cells " Insp revealed improvement in design/const or tray type charcoal adsorber cells DALE.L F Mississippi Power * Light Co 80/03/20 2pp
- 8004150491 Forwards IE Into Notice 80-12, "Instrument Failure Causes Opening of FORV / Block Valve ' No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/03/31
- 8004080587 Forwards IE Circular 80-05, "Emergancy Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 200
- 8004150088 Forwards IC Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240268 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004180268 Forwards IE Circular 80-07. "Problems U/HPC1 Turbine Oil Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03 2pp
- 8004110014 Forwards It Bulletin 80-07. "BWR Jet Pump Assembly Failure "
 No written response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/04/04
 2pp
- 8004230181 Forwards IE Builetin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainlass Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180328 Forwards IE Bulletin 80~08. "Exam of Containment Liner Penetration Helds " Written response required U'REELLY, J.P. Region P. Atlanta, Office of the Director 80/04/07 2pp
- 8004230322 Forwards Ii insp Rept 50-416/79-34-01 supplemental response clarifying previous response transmitted in 800414 ltm MCOAUGH7, J Mississippi Power & Light Co 80/04/15 2pp
- S Reportable occurrences. LERs & related correspondence
- 8004090183 PNO-11-80-044 on 800319, site ambulance, en route to hosp w/laborer, heart attack victim, involved in accident Three of four occupants tilled Status of Laborer unknown HURT.M D. RAUSCH.J K. Region 2, Atlanta, Office of the Director 80/03/19 [p
- 8004170071 Forwards final rept for Potentially Reportable Deficiency 79/12 re Rosemount Model 510 DU master & slave trip units DALE, L. F. Mississippi Power & Light Co. 80/03/21 1p
- ---8004170074 Final rept for Potentially Reportable Deficiency 79/12 re
 Model 510 DU master * slave trip units w/max current drain
 in excess of original specified value Deficient power
 supplies being replaced Details found in GE rept
 4 Mississippi Power & Light Co 80/03/21 Ip
- 8004280517 Forwards interim deficiency rept re damaged instrumentation cables under reactor pressure vessel DALE, L. F. Mississippi Power & Light Co. 80/03/31 1p
- --8004280522 Interim deficiency rept re damaged instrumentation cables
 Under reactor pressure vessel During installation of control
 rod drive assembly housings, insulation on 132 cables was
 damaged Cause under investigation
 * Mississippi Power & Light Co 80/03/31 ip

- 8004280501 Farwards summary overview of deficiency PRD-80/04 re effects of loss of site power on rod position indication & neutron monitoring indication Util is re-evaluating position on reportability of deficiency final rept will be issued DALE, L.F. Mississippi Power & Light Co. 80/04/03 3pp
- 8004150548 Forwards history & description of deficiency re to valve manifolds supplied by Dragon Valbe, Inc Deficiency improperly evaluated Re-evaluation underway, w/determination of potentially reportable deficiency by 800402 DALE, L.F. Mississippi Power & Light Co. 80/04/04 2pp
- 8004280484 Confirms 800328 telcon concerning deficiency PRD-80/02 re defective glbow in control rod drive hydraulic sys Problem does not constitute reportable deficiency Elbow does not adversely affect plant safety Elbow will be replaced DALE.L F Mississippi Power & Light Co 80/04/04 4pp
- 8004280541 Deficiency rept re William Powell valves which may not meet seismic requirements of original purchase order Vendor re-analysis of valve natural frequencies still in progress final rept will be submitted by 800813 DALE.L F Mississippi Power & Light Co 80/04/04 ip
- 8004280520 Deficiency rept re malfunctioning Limitorque motor operators Cause of deficiency apparently related to excessive threading of stem protector investigation continuing Final rept should be submitted by 800728 DALE, L.F. Mississippi Power & Light Co. 80/04/11 1p
- 8004280610 Forwards interim rept for Potentially Reportable Deficiency 80/05 re electrical cable insulation damage sustained during cable pulling process DALE.L F Mississippi Power & Light Co 80/04/11 ip
- --8004280618 Interim rept for Potentially Reportable Deficiency 80/05 re cable damage substained during cable pulling process Nature of damage ranges from jacket chafing to insulation cut through to conductor Cables replaced # Mississippi Power & Light Co 80/04/11 1p
- BOO42B04B1 Second interim deficiency rept re faulty GE CR2940-US203E hand switch in plant svc water sys Switch returned to GE for failure analysis Final rept will be forwarded on 80061B DALE.L F Mississippi Power & Light Co 80/04/15 1p
- 8004280499 Submits status rept for deficiency PRD-80/09 re pipe hanger nonconformances Possibly caused by inadequate training & insp procedures Noncomformances are being evaluated DALE.L F Mississippi Power & Light Co 80/04/18 2pp
- 8004280606 Submits status rept for deficiency PDR-80/10 re unqualified cable insulation repairs in Rockbestos cable Cable splices were not involved Supplier conducting qualification tests on repair matls

 DALE.L F Mississippi Power & Light Co 80/04/18 2pp
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0888, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment " Requests review of equipment qualification documentation to identify degree of compliance ROSS, D. F. Division of Project Management 80/02/21 Spp
- 8004020446 Forwards NRC 800128 & 0211 ltrs to 0E re mods to BWR control rod drive sys \$ add1 analyses of beiloff rates respectively Further info & guidance to be issued in NUREO-0619

 BAER/R L Light Water Reactors Branch 2 80/03/13 2pp
- 8004i00301 Notification of 800403 meeting w/QE in Bethesda.MD to discuss BWR 6 safety relief valves mfg by G Dickens & Co & supplied by GE to facilities HENDERSON.J B Division of Reactor Construction Inspection 80/03/13 2pp
- 8004030149 Requests addl info to complete facility environ review Forwards specific list of required info Reply should consist of sequentially numbered revision to final environ rept BALLARD, R. L. Environmental Projects Branch 1 80/03/14 3pp

- 8004090341 Forwards application for anend of Licenses CPPR-118 & CPPR-119 Also forwards 1000R50 App L antitrust info STAMPLEY.N L Mississipp) Power & Light Co 80/04/03 2pp
- --8004090345 Application for amend of CPPR-118 % CPPR-119 adding South MI Electric Power Association as co-owner Drafts of joint constraction's ownership agreement operating agreement % substitute power agreement end % substitute power agreement end % Kississippi Power % Light Co 80/04/03 240pp
- --8004090353 Annual Financial Rept 1978 Addl +inancial info attached

 * Bouth Mississippi Flectiic Power Association 78/12/31 150pp
- B004210228 Forwards info per NRC 800214 request supporting confirmatory piping analysis of safety relief Valve 16, discharge line Revision & to piping design Spec 9645-H-220 0, other supporting info & drawings available in Central Files only DALE.L F Mississippi Power & Light CO 80/04/09 App
- 80042800B4 Forwards Instrumentation & Centrol Branch request for addlinfo re FSAR Sections 7 4 & 7 5 FSAR should be amended to reflect responses to requests BAER.R.L. Light Water Reactors Branch 2 80/04/09 9pp
- 8004170243 Forwards fee re 790710 request for approval of deletion of stage moniforing requirement in environ protection program DALE.L.F. Mississippi Power & Light Co. 80/04/16 1p
- C Utility Environmental Report (ER), amends & correspondence
- 8004220421 Forwards correspondence between util & State of MI Natural Heritage Program per Question 340 14 on final environ rept DALE: L F Kississippi Power & Light Co 80/04/16 App
- 8004220287 Forwards Amend 3 to environ lept.consisting of responses to 800122 requests for addl info STAMPLEY,N L Mississippi Power & Light Co 80/04/18 [p
- --8004220293 Amend 3 to environ rept * Mississippi Power & Light Co 80/04/18 40pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Popts Act GRIMES. B K Emergency Proparedness Task Force 80/03/11 4pp
- 8004100584 Notification of postponement of 800414-16 meeting w/util. Bachtel & Gage Babcock in Port Gibson,MS to review facility fire protection HOUGHTON,T C Light Hater Reactors Branch 2 80/03/11 2pp
- H General correspondence
- 8004100362 Responds to NRC 780627 ltr by forwarding affidavit of svc re distribution of Amend 37 to CPPR-118 & CPPR-119 BALE, L F Kississippi Power & Light Co 80/04/07 2pp
- I Financial information
- 8004220535 Annual Financial Rept 1979 * Middle South Utilities, Inc 79/12/31 40pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004280365 Forwards Amend 38 to application for QL Also forwards piping & instrumentation diagrams * electrical drawings Electrical drawings not enci LUTKCN.D C Mississipp Power & Light Co 80/04/25 ip
- --8004280371 Amend 38 to application for UL Consists of responses to NRC questions re FSAR & miscellaneous refinements of design info LUTKEN.D C Mississippi Power & Light Co 80/04/21 2pp
- ---8004280381 Amend 38 to FSAR, consisting of responses to NRC questions & miscellaneous refinements of design info
 * Mississippi Power & Light Co 80/04/25 230pp

M Antifrust correspondence

- 8004090363 Responds to TB Conner 100312 ltr to NRC re interconnection agreement Absonce of s.c schedule 5 execution of Gulf States Uril Co indicate agreement not intended to be operative Requests resolution before GL stage MCDIARMID, R G Epiegel F REDiarmid 80704704 2pp
- --800405036B Petition to intervene in proceeding Urges Commission to accept interconnection ignoement for filing, suspend agreement operation for one day / set issue for immediate conference & hearing
 MCDIARRIDER C Michigan, State of MCDIARRIDER C Spragel & McDIARRIDER GO/03/28 Bpp
- 8004150197 Finds antitio,t info submitted 800403 acceptable for docketing & distribution TOALSTON A Antitrust & Indemnity Group 80/04/14 ip
- ---B004150200 Forwards autitiust info per application for amend of Licenses CPPR-118 / CPPR-119 STAMPLEY,N L Mississippi Power // Light Co 80/04/03 10pp
- 8004180283 Forwards info ie South MS Electric Power Association, submitted per App L or 10CFR50 of Commission Rules of Practice info transmitted to offer opportunity to render advice re findings to be made by Commission Wo encl SHAPAR.H K Office or the Erecutive Legal Director 80/04/16 ip
- G Inspection reports. IE Bulletins 5 correspondence
- 8004090339 Forwards IE Bulletin 80-03, "Loss of Charcoal From Sto Type II.Two-Inch, Tray Adsorber Coils " Action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/02/06 20g
- 8004040084 Forwards IE Insp Repts 50-416/80-01 % 50-417/80-01 nn 800122-24 Nn noncompisance noted BRYANT, J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 60/02/12 2pp
- --8004040125 IE Insp Repts 50-416/80-01 & 50-417/80-01 on B00122-24 No noncompliance noted Major areas inspected offsite warehouse insp & observation of safety-related activities Followup on IE bulletin.inspector & licensee identified items CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch PAUSCHJ K Region 2. Atlanta, Office of the Director B0/02/11 App
- 8004040201 Forwards IE Repts 50-416/80-06 & 50-417/80-05 on 800129-31 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8004040222 IE Insp Repts 50-416/80-06 % 50-417/80-05 on 800129-31 No noncomplance noted Major areas inspected safety-related pipe welding, reactor piessure boundary pipe handling & welding to followup on previously identified items HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch VANDDORN P K Region 2. Atlanta. Office of the Director 80/02/15 3pp
- BOO4230070 Responds to IE Sulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch,Tray Adsorber Cells " Insp rovealed improvement in design/const or tray type charcoal adsorber cells DALE.L F Mississippi Power & Light Co 80/03/20 2pp
- 8004150491 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PDRV 5 Block Valve " No specific action or response nocessary D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080589 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 2pp
- 8004150088 Forwards IE info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers → No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 2pp
- 8004240268 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/02

- 8004180g68 Forwards II Circular 80~07, "Problems W/HPCI Turbine Qil Sys " No written response required D'REILLY, J.P. Region P. Atlanta, Office of the Director B0/04/03 2pp
- 8004110014 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04 200
- 8004230181 Forwards IE Bulletin 74-03A "Longitudinal Held Defects in ASME 8A-312 Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/04
- 8004180328 Forwards IC Bulletin 80-08, "Exam of Containment Liner Penetration Welds' Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/07
- 8004230322 Forwards IE Inep Rept 50-416/79-34-01 supplemental response clarifying previous response transmitted in 800414 ltr MCGAUGHY.J Mississippi Power & Light Co 80/04/15 2pp
- S Reportable occurrences, LERs & related correspondence
- 8004070[83 PNO-11-80-044 on BO0317, site ambulance, en route to hosp w/laborer, heart attack victim, involved in accident Three of four occupants xilled Status or laborer unknown HUNT, M D , RAUSCH, J K Region 2, Atlanta, Office of the Director BO032[9] 10
- 8004170071 Forwards final rept for Potentially Reportable Deficiency 79/12 re Rosemount Model 510 DU master & slave trip units DALE.L F Mississippi Power & Light Co 80/03/21 1p
- --8004170074 Final rept for Potentially Reportable Deficiency 79/12 re
 Model 510 DU master / slave trip units w/max current drain
 in excess of original specified value Deficient power
 supplies being replaced Details found in GE rept
 * Mississippl Power 3 Light Co 80/03/21 ip
- 8004280517 Forwards interim deficiency rept re damaged instrumentation cables under reactor pressure vessel
 DALE,I F Mississippi Power & Light Co 80/03/31 1p
- --B004280522 Interim deficiency rept re damaged instrumentation cables under reactor pressure vessel During installation of control rod drive assembly housings, insulation on 132 cables was damaged Cause under investigation

 * Mississippi Power & Light Co 80/03/31 1p
- 8004280501 Forwards summary overview of deficiency PRD-80/04 re effects of loss of site power on rod position indication & neutron monitoring indication Util is re-evaluating position on reportability of deficiency Final rept will be issued DALE.L F Hississippi Power & Light Co 80/04/03 3pp
- 8004i50568 Forwards history & description of deficiency re to valve manifolds supplied by Dragon Valbe, Inc Deficiency improperly evaluated Re-evaluation underway, w/determination of potentially reportable deficiency by 800602 DALE.L F Mississippi Power & Light Co 80/04/04 2pp
- 8004280484 Confirms 800328 telcon concerning deficiency PRD-BD/02 re defective elbow in control rod drive hydraulic sys Problem does not constitute reportable deficiency Elbow does not adversely affect plant safety Elbow will be replaced DALE,L. F Mississippi Power & Light Co 80/04/04 4pp
- B004280541 Deficiency rept re William Powell valves which may not meet seismic requirements of original purchase order Vendor re-analysis of valve natural frequencies still in progress Final rept will be submitted by B00813

 DALE.L F Mississippi Power & Light Co 80/04/04 ip
- 8004280520 Deficiency rept re malfunctioning Limitorque motor operators Cause of deficiency apparently related to excessive threading of stem protector Investigation continuing final rept should be submitted by 800728 DALE.L.F. Mississippi Power & Light Co 80/04/11 ip
- 8004280610 Forwards interim rept for Potentially Reportable Deficiency 80/05 re electrical cable insulation damage sustained during cable publing process DALE, L.F. Mississippi Power & Light Co. 80/04/11 ip

- --8004280618 Interim rept for Potentially Reportable Deficiency 80/05 re cable damage substained during cable publing process Nature of damage ranges from jacket chaffing to insulation cut through to conductor Cables replaced * Mississippi Power & Light Co 80/04/11 1p
 - ANDROAM Company of the company of th
- 800428048: Second interim deficiency rept re faulty GE CR2940-US203E hand switch in plant svc water sys Switch returned to GE for failure analysis Final rept will be forwarded on 800418 DALE, L.F. Mississippi Power & Light Co. 80/04/15 ip
- 8004280499 Submits status rept for deficiency PRD-80/07 re pipe hanger nonconformances Possibly caused by inadequate training & insp procedures Noncomformances are being evaluated DALE.L F Mississippi Power & Light Co 80/04/16 2pp
- 8004280606 Submits status rept for deficiency PDR-80/10 re unqualified cable insulation repairs in Rockbestos cable Cable splices were not involved Supplier conducting qualification tests on repair matts

 DALE, L. F. Mississippi Power & Light Co. 80/04/18 2pp
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

 A Application/construction stage documents & correspondence
- BO04040031 Advises of issuance of NUREO-058B. "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSB.D F Division of Project Management
- 8004230413 Notifies of intent to invoke provision of Code Case N-245 re use of copper alloy castings meg from ASTM 861-76 & 862-76 matls specs for use in ASME III Class 3 component installation COUNSIL, W G , FEE, W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 ip
- F Security, medical, emergency & fire protection plans
- BD04080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending QAO cleanance under Federal Repts Act QRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004020408 Forwards "Feasibility Rept on Evacuation of Area Around Facility " CDUNBILLY 0 Northeast Utilities 80/03/31 2pp
- --8004020418 "Feasibility Rept on Evacuation of Area Around Facility "
 One oversize drawing encl
 RDD0ERG.L M Affillation Unknown 80/03/31 58pp
- H General correspondence
- 8004210048 Responds to 800307 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10CFR20 & App 1 to 10CFR30 Environ info available in stated LPDR8 BALLARD, R L Environmental Projects Branch 1 80/04/01 2pp
- I Financial information
- 8004080557 Responds to NRC 800305 ltr re adequacies of cash flows to mest possible retrospective premium payments & forwards 1979 annual repts for CT Light & Power Co, Hartford Electric Light Co & Western MA Electric Co O'GUNNOR, L A Northeast Utilities 80/04/01 ip

- --8004080590 Annual Financial Rept 1979

 * Western Massachusetts Electric Co 80/03/14 2ipp
- 8004i50320 Forwards Annual Financial Repts 1979 BIBHOP,R W Northeast Utilities 80/04/02 1

- J. Insurance % indemnify information
- 8004160254 Forwards Endorsements 57 % 58 MAELU Policy NF-52 IFFLAND,R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 60/04/11 3pp
- O Inspection reports, IE Bulletins & correspondence
- 8004210003 Forwards IE Insp Rept 50-423/80-01 on 800213-15 No noncompliance noted CARLSCIR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/06 20p
- --800421001) IE Insp Rept 50-423/80-01 on 800213-15 No noncompliance noted Major areas inspected velder qualifications weld rod issue controls unresolved them status tours & interviews MCGAUCHY.R W. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch CERRE.A C. Region 1. Philadelphia. Office of the Director 80/03/05 App
- 8004150279 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1, Philadelphia, Office of the Director 80/07/31 in
- 8004090074 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/01 1p
- 8004110156 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004240319 Forwards IE Info Notice 80-14, 'Safety Suggestions From Employees' No action required ORIER.3 H Region 1. Philadelphia, Office of the Director 80/04/02 ip
- B0041B0231 Forwards IE Circular B0-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required ORIER,B H Region 1, Philadelphia, Office of the Director 80/04/03 ip
- 8004230433 Forwards IE Bulletin 79-03A; "Longitudinal Weld Defects in ABME SA-312. Type 304 Stainless Steel Pipe " Action required ORIER. B H. Region 1, Philadelphia, Office of the Director 80/04/04 ip
- BOO4180201 Forwards IE Bulletin 80-08, "Fxam of Containment Liner Penetration Helds" Written response required GRIER.B H Region 1. Philadelphia, Office of the Director BD/04/07 1p
- R Periodic operating reports b related correspondence
- 8004040205 Forwards annual environ operating rept, "Monitoring Marine Environ or Long Island Sound ' Requests rept be incorporated into proceedings for Unit 3 GDUNBILIN 9 Northeast Utilities 80/03/30 1p
- --8004040206 "Monitoring Marine Environ of Long Island Sound," annual rept,1979
 * Northeast Utilities 80/03/31 400pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004100606 Ack receipt of 800225 interim deficiency rept re error in 3/8-inch orifice design Requests that final rept discuss planned or completed corrective actions CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/12 Ip
- --8004100608 Interim deficiency rept 3/8-inch orifices shown on flow diagram failed to appear on fabrication isometric StW isometrics also found deficient Coused by transfer of info Drawings will be corrected & orifices added by rework CGUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/02/25 2pp

- DOCKET 50-424 ALVIN W VM TLE NUCLEAR PLANT, UNIT 1

 A Application on the time stage documents ' correspondence
- 8004040031 Advises of is-large of NURFO-0588. "Interim Staff Position on Environ Qualification of Eafety-Related Electrical Equipment," providing guidance to methods for compliance ROSS D F Division of Froject Management B0/02/05 7pp
- BOO4220042 Responds to Arneric memo re structural aspects of as-built foundation defails Erferto or erosion should not be significant re safety-related structures Structures should be analysed for as-built onditions SCHAUER, F.P. Structural Engineering Branch 80/03/31 ip
- G004140335 Submits info requested by NRC G00327 felcon Descibes mod of acceptance citieria? justification for removal of fines by temporary well point devatering sys
 DUTTON D Georgia Fower Co G0/04/07 2pp
- F Security, medical, emergenry & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force B0/03/11 4pp
- G Adjudicatory correspondence
- 6004170292 Forwards supplemental Director's decision to 791012 denial of Georgians Against Nuclear Energy petition to reconsider util need for power Following review of submittals. Commission finds no basis for reconsideration DENTON.H R Office of Nuclear Reactor Regulation 60/03/26 2pp
- ---8004170276 Supplemental Director's decision under 100FR2 206 Supplements 791012 denial of Georgians Against Nuclear Energy petition re suspension of CP & re-examination of need for power Review finds no basis for reconsiderations DENTON-HR Office of Nuclear Reactor Regulation 80/03/26 10pp
- 8004240145 Supplemental Director's Decision under 100FR2 206 denying Georgians Against Nuclear Energy request to suspend licenses & institute new proceeding DENTON:H R Office of Nuclear Reactor Regulation 80/03/26 3pp
- Q Inspection reports. If Bulletins & correspondence
- 8004070198 Responds to IE Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps " Supplier taking measures to prevent use of defective switches DUTTON D Georgia Power Co 80/01/25 6pp
- 8004040420 Ack receipt of 1E Insp Repts 50-424/79-19 & 50-425/79-19 on 791227 No proprietary info DUTTON D Georgia Power Co 80/02/06 ip
- --8004040424 Forwards 1E Insp Repts 50-424/79-19 % 50-425/79-19 on 791227 No noncomptiance noted BRYANT.J C Region 2. Atlanta: Reactor Construction & Engineering Support Branch 80/01/23 2pp
- ~~B004040430 IE Imap Repts 50-424/79-19 & 50-425/79-19 on 791227 No noncompliance noted Major areas inspected soils & concrete lab & const status CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch LENAHAN, J J Region 2. Atlanta, Office of the Director B0/01/22 4pp
- 8004090347 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II. Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/02/06 2pp
- 8004020187 Ack receipt of IE Insp Repts 50-424/80-01 & 50-425/80-01 on 800130-0201 No proprietary info DUTTON, D Georgia Power Co 80/03/11 1p
- --8004020188 Forwards IE Insp Repts 50-424/80-01 & 50-425/80-01 on 800130-0201 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/21 Spp

- --8004020194 IF Insp Repts 50-424/60-01 / 50-425/80-01 on 800130-0201 No noncompliance noted Major areas inspected erasion of back-rill, bldg foundation, concrete embeds, voids in concrete, reactor vessel orfloading / IE bulletins HUNT-M D Region 2. Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND.C R Region 2, Atlanta, Office of the Director 80/02/21 5pp
- 8004100348 Responds to IE Bulletin 80-03 No std Type II tray or drawer adsorber cells will be used Facility adsorber cells are vertical fill type b use perforated metal sheets welded not tiveted to filter casings

 DUTTON D Georgia Power Co 80/03/20 ip
- 8004150521 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Palve " No specific action or response necessary O'REILLY J P Region 2. Atlanta, Office of the Director BO/03/31
- 8004080624 Forwards IF Circular 80-05, "Emergency Diesel Generator Lubicating Gil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/04/01 20p
- 8004150093 Forwards IE Into Notice 80-13, "GE Type SBM Control Switches
 Defective CAM Followers " No specific action or response
 required
 GEORGIA Control Control
- required

 G'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02

 2pp
- 8004240265 Forwards IE Info Notice 80-14. "Safety Buggestions From Employees" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 2pp
- 8004240344 Ack receipt of IE Insp Repts 50-424/80-04 & 50-429/80-04, an 800311 No proprietary info DUTFON.D Georgia Pawer Co 80/04/02 ip
- --8004240352 Forwards IE Insp Repts 50-424/80-04 & 50-425/80-04 on BO0311 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8004240340 IE insp Repts 50-424/80-04 & 50-425/80-04 on 800311 No noncompliance noted Major areas inspected underlining of control blog electrical tunnel 2 foundation, surface & subsurface drainage controls & slope stabilization measures CDLON, J E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch HARRIS, J R Region 2, Atlanta, Office of the Director 80/03/21 3pp
- 8004180303 Forwards IE Circular 80-07, "Problems W/HPCI Turbine 0:1 Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03
- 8004230173 Forwards IC Bulletin 79-03A "Longitudinal Held Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180436 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/07 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004020335 Forwards deficiency rept re voids in concrete placements on auxiliary bldg interior walls DUTTON:D Georgia Power Co BO/O3/O3 2pp
- --8004020340 Deficiency rept re voids in concrete placements on auxiliary bldg interior walls No cause stated Voids patched & wat cured for min of three days Tremio placement will be preplanned to allow better concrete flow in congested areas * Georgia Power Co 80/03/03 3pp
- 8004010349 Informs NRC that util is unable to establish definite completion date for final deficiency rept re dewatering & erosion of backfull Addl update & possible date for final rept will be provided by 800415 DUTTON.D Georgia Power Co 80/03/24 2pp

- 8004020370 Interim deficiency rept re backfill dewatering & erosion No definite completion date established for final rept Addi update will be submitted by 800415 DUTTON.D Georgia Power Co 80/03/24 2pp
- 8004150427 Advises of discrepancy in 800307 deficiency rept re status of corrective action Corrective action had not been completed as of rept date for embed plate assemblies Final rept will be filed by 800530 DUTTON.D Georgia Power Co DUTTON.D Southern Co Services, Inc 80/04/10 2pp
- 8004280491 Significant deficiency rept re discrepancies in 791121 deficioncy rept on embed plate assemblies Status of corrective action incorrect Should Indicate that corrective action is incomplete Final rept to be submitted 800430 DUTTON, D Georgia Power Co 80/04/10 2pp
- DOCKET 50-425 ALVIN W VUGTLE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004140336 Submits info requested by NRC 800327 telcon Descibes mod of acceptance criteria & justification for removal of fines by temporary well point dewatering sys DUTTON,D Georgia Power Co 80/04/07 2pp
- F Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES, B K Emergency Preparedness Task Force BO/03/11 4pp
- Q Adjudicatory correspondence
- B004170292 Forwards supplemental Director's decision to 791012 denial of Georgians Against Nuclear Energy petition to reconsider util need for power Following review of submittals. Commission finds no basis for reconsideration DENTON, HR Office of Nuclear Reactor Regulation 80/03/26 2pp
- --8004170276 Supplemental Director's decision under 10CFR2 206
 Supplements 791012 denial of Georgians Against Nuclear
 Energy petition re suspension of CP & re-examination of need
 for power Review finds no basis for reconsiderations
 DENTON, HR Office of Nuclear Reactor Regulation B0/03/26
 1000
- 8004240145 Supplemental Director's Decision under 10CFR2 206 denying Opengians Against Nuclear Energy request to suspend licenses & institute new proceeding DENION.H R Office of Nuclear Reactor Regulation 80/03/26 Jpp
- G Inspection reports, IE Bulletins & correspondence
- 800407019B Responds to IC Bulletin 79-28, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temps " Supplier taking measures to prevent use of defective switches. DUTTON D Georgia Power Co 80/01/25 6pp
- 800404020 Ack receipt of IE Insp Repts 50-424/79-19 & 50-425/79-19 on 791227 No proprietary info DUTTON, D Georgia Power Co 80/02/06 ip
- --8004040424 Forwards IE Insp Repts 50-424/79-19 & 50-425/79-19 on 791227 No noncompliance noted BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/01/23 2pp
- --8004040430 IE insp Repts 50-424/79-19 & 50-425/79-19 on 791227 No noncompliance noted Major areas inspected soils & concrete lab & const status CUNLON,TE Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch LENAHAN,JJ Region 2, Atlanta, Office of the Director 80/01/22 App
- 8004090349 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II, Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/04

- 8004020187 Ack receipt of IE Insp Repts 50-424/80-01 % 50-425/80-01 on 800130-0201 No proprietary into DUTTON, D. Georgia Power Co. 60,03/11 ip
- --8004020189 forwards IE Inap Repts 50-424/80-01 5 50-425/80-01 on 800130-0201 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/21 2pp
- ---B004020194 IE Insp Repts 50-424/B0-01 / 50-425/B0-01 on 800130-0201 No noncompliance noted Major areas inspected erosion of backfill, blidg foundation, concrete embeds, voids in concrete, reactor vessel offloading & IE bulletins
 HUNT, M D Region 2, Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND, C R Region 2, Atlanta, Office of the Director B0/02/21 5pp
- 8004100348 Responds to IF Bulletin 80-03 No std Type II tray or drawer adsorber cells will be used Facility adsorber cells are vertical fill type 2 use perforated metal sheets welded, not riveted, to filter casings

 DUTTON, D Georgia Power Co 80/03/20 ip
- 8004150521 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080624 Forwards IE Circular 80-05, "Emergency Dipsel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01
- 8004150093 Forwards IE Info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- B004240265 Forwards IE Info Notice 80~14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/04/02
- B004240344 Ack receipt of IE Insp Repts 50-424/80-04 & 50-425/80-04, on 800311 No proprietary info DUTTON, D Georgia Power Co 80/04/02 1p
- --8004240352 Forwards IE Insp Repts 50-424/80-04 & 50-425/80-04 on B00311 No noncomptiance moted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch B0/03/24 2pp
- --8004240360 IE Insp Repts 50-424/40-04 \$ 50-425/80-04 on 800311 No nancompliance noted Major areas inspected underlining of control bldg electrical tunnel 2 foundation surface \$\mu\$ subsurface drainage controls \$\mathbf{s}\$ stope stabilization measures COLON. \$J E Region 2. Atlanta. Reactor Construction \$\mathbf{E}\$ Engineering Support Shanch MARRIS. \$J R Region 2. Atlanta. Office of the Director \$00/03/21 Spp
- 8004180303 Forwards IE Circular 80-07, "Problems N/HPCI Turbine Dil Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004230173 Forwards 1E Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/04 is
- 8004180436 Forwards IE Bulletin 80-08, "Evam of Containment Liner Penstration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 2pp
- S Reportable occurrences, LERs & related correspondence
- 8004020335 Forwards deficiency rept re voids in concrete placements on auxiliary bidg interior walls
 DUTTON,D Georgia Power Cu 80/03/03 2pp
- --8004020340 Deficiency tepf re voids in concrete placements on auxiliary bldg interior walls No cause stated Voids patched & wet cured for min of three days Tremie placement will be preplanned to allow better concrete flow in congested areas 4 Georgia Power Co 80/03/03 3pp

- 3004010349 Informs NRC that util is unable to establish definite completion data for final deficiency rept re dewatering A erosion of backfull Addi update & possible date for final rept will be provided by 800415 DUTTON.D Georgia Power Co. 80/03/24 2pp
- 3004020390 Interim deficiency rept re backfill dewatering & erosion No definite completion date established for final rept AddJ update will be submitted by 800415 DUTTON.D Georgia Fower Co 80/03/24 2pp
- ROD4:50421 Deficiency rept re erosion under cable tunnel documented in IE Insp Rept 50-425/80-05 Repairs completed & backfilling activities resumed Complete rept will be filed by 800430 DUTTON.D Georgia Power Co 80/04/10 2pp
- BOO4150427 Advises of discrepancy in 800307 deficiency rept re status of corrective action Corrective action had not been completed as of rept date for embed plate assemblies Final rept will be filed by 800530 DUTTON.D Georgia Power Co OUTTON.D Southern Co Services.Inc 80/04/10 2pp
- BOO428049; Significant deficiency rept re discrepancies in 791121 deficiency rept on embed plate assemblies Status of corrective action incorrect Should indicate that corrective action is incomplete Final rept to be submitted 800430 DUTTON, D. Georgia Power Co. 80/04/10. 2pp
- JOCKET 50-427 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 4
- Application/construction stage documents & correspondence
- BOO4220042 Responds to B00206 memo re structural aspects of as-built foundation details Effects of erosion should not be significant re safety-related structures Structures should be analyzed for as-built conditions

 SCHAUER, F.P. Structural Engineering Branch 80/03/31 1p
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR
- Periodic operating reports & related correspondence
- 3004070328 Forwards "Annual Rept of Operations, 1979 "
 KROES,R J Catifornia, Univ o+, Santa Barbara 80/03/31 Ip
- -8004070327 'Annual Rept of Operations, 1979 "
 PROFIG.A & California, Univ of, Santa Barbara 80/03/31 App
- DOCKET 50-434 SURRY POWER STATION, UNIT 3
- Application/construction stage documents & correspondence
- 3004150249 Notification of ACRS Subcommittee on Surry Nuclear Station B00123 meeting in Washington BC to continue review of steam generator replacement program HOYLE, JC ACRS Advisory Committee on Reactor Safeguards 79/12/20 3pp
- IDCKET 50-495 SURRY PONER STATION, UNIT 4
- Application/construction stage documents & correspondence
- 3004130249 Notification of ACRS Subcommittee on Surry Nuclear Station 800123 meeting in Washington DC to continue review of steam generator ceplacement program HDYLE, JC ACRS Advisory Committee on Reactor Safeguards 79/12/20 3pp
- MOCKET STN-50-437 FLOATING NUCLEAR PLANT
 - Application/construction stage documents & correspondence
- 3004040031 Advises of issuance of NUREG-0588, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp

- G Adjudicatory correspondence
- 8004090021 Advises that NRC ½ applicant met w/ACRB to discuss applicant proposed core ladio design Views will be reflected in written ltrs NRC reorganization may affect completion of technical review SOHINKI/S M Hearing Branch 3 80/03/31 2pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK. V Office of the Executive Director for Operations
- 8004290231 Notice of withdrawl from proceeding Certificate of Byc encl STAENBERG,N R Regulations Division 80/04/25 3pp
- @ Inspection reports. IE Bulletins & correspondence
- B004090360 Forwards IE Bulletin B0-03, 'Loss of Charcoal From Std Type I(.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2. Atlanta, Office of the Director B0/02/06 2pp
- 8004150550 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of FORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 2pp
- 8004080658 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY.J P Region 2. Atlanta, Orfice of the Director 80/04/01 2pp
- 8004150107 Forwards IE Info Notice 80-13, "GE Type SRM Control Switches Defective CAM Followers" No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240238 Forwards IE Info Notice 80-14. "Safety Buggestions From Employees " No action required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/02 to
- 8004180382 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03 io
- 8004230102 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/04
- 6004180476 Forwards IE Dulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Rogion 2, Atlanta, Office of the Director 80/04/07
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004240201 Forwards License SNM-1865, authorizing receipt possession, insp & storage of U-235 fuol assemblies & max of 100 fuel rods License also allows packaging & shipping for transfer Safety evaluation encl
 PAGE, R O Uranium Recovery Licensing Branch 80/01/30 2pp.
- --8004240207 License SNM-1865, authorizing receipt, possession, insp. storage & transfer of max of 2.110 kg u-235 fuel assemblies & 100 fuel rods Licensee is exempt from matls provisions of 100FR70 24 PAGE.R G Uranium Recovery Licensing Branch 80/01/30 2pp
- ---8004240217 Safety evaluation re util application for license to receive mar 2.110 kg U-235 fuel assemblies & 100 fuel rods License should be granted w/exemption from 100FR70 24 CROW,N T , DELANEY,J L Uranium Recovery Licensing Branch, 80/01/30 2pp
- 8004040031 Advises of issuance of NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp

DOCKETED ITEMS

- B004040017 Submits addl guidance to NUREQ-OSBB, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 8004280308 Forwards request for add1 info re power sys, for CL application review Requests date that response will be available for review PARR.O D Light Mater Reactors Branch 3 80/03/17 25pp
- B004110046 Requests addl info on changes & studies proposed in App F of 791203 response to NRC 791025 10CFR50 54 requests redesign adequacy of B&W NSSS utilizing once-through steam generators
 PARR.O D Light Water Reactors Branch 3 80/03/25 5pp
- F Security, medical, emergency & fire protection plans
- BO040B0077 Advises that submittal date for evacuation time estimates, requestéd by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 ORIMEB.B K Emergency Preparadness Task Force 80/03/11 4pp
- 8004070052 Forwards request for info re util 790301 safeguards contingency plan & 790901 Revision 1 Encl withheld (ref 10CFR2 790) PARR.O D Light Water Reactors Branch 3 80/03/14 2pp
- G Inspection reports, IE Bulletins & correspondence
- B004090352 Forwards IE Bulletin B0-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/06
- 8004090388 Forwards IE Insp Repts 50-438/80-03 & 50-439/80-03 on 800206-08 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- ~-B004090392 IE Insp Repts 50-438/80-03 & 50-439/80-03 on 800206-08 No noncompilance noted Major areas inspected containment prestressing GA/GC controls, work performance, const status & quality records CONLON, T.E., LENAHAN, J.J. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 4pp
- 8004070025 Confirms 800310 telcon arranging 800320 meeting between NRC & util in Atlanta, CA to discuss accuracy of written repts provided to IE NRC will provide overall avaluation of util handling of deficiences identified by GA program O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/12 200
- 8004070150 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50~438/80~01 & 50~439/80~01 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/03/17 2pp
- --8004070138 Forwards IE Insp Repts 50-438/80-01 & 50-439/80-01 on 800108-11 & notice of violation BRYANT, J G Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/02/11 2pp
- --8004070168 Notice of violation from insp on 800108-11 # Region 2, Atlanta, Office of the Director 80/02/11, 1p
- ---B004070177 IE Insp Repts 50-438/80-01 & 50-439/80-01 on B00108-11 Noncompliance noted failure to follow procedure for visual insp of welds HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch VANDURN, P K Region 2. Atlanta, Office of the Director B0/02/01 4pp
- B00421017B Forwards response to IE Bulletin B0-03, "Loss of Charcoal from Btd Type II. Two-Inch. Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority B0/03/21 4pp.
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches. At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS.L M Tennessee Valley Authority 80/09/28. 2pp

8004150527 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PDRV & Block Valve "No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 2ap

;

- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80-13, "GE Type SDM Control Switches Defective CAM Followers " No specific action of response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/02 2nd
- 8004240274 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03
- 8004230142 Forwards IE Bulletin 79-03A "Longitudinal Wald Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08, "Cram of Containment Liner Penetration Welds " Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/07
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLS.L. M. Tonnessee Valley Authority 80/04/23 3pp
- S Reportable occurrences, LERs & related correspondence
- 8004020459 Part 21 rept on 800228, B&W made telephone rept re defect concerning potentially overstressed supports on reactor coolant letdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR, J H Babcock & Wilcox Co 80/03/03 /pp
- 8004080563 PNO-II-80-045 on 800317, util notified Region 2 of B&W notification re potential for failure of main steam lines in event of feedwater overflow of steam generators. Region 2 investigating generic aspects
 WRIGHT.R W. CONTRELL.F S. Region 2, Atlanta, Office of the Director 80/03/19 ip
- BOO4190209 Forwards deficiency mept me support braces for cooling water supply header used for seactor bidg coolers being incongrous w/seismic analysis
 TAYLDR.J H Babcock & Wilcox Co BO/03/24 ip
- ---9004150210 Deficiency ropt re support braces for cooling water supply header used for reactor bidg coolers being incongruous \(\psi \) seismic analysis Cause unstated Braces returned to vendor for mod to conform to seismic analysis design \(\psi \) Babcock & Wilcox Co \(\text{BO/O3/24} \) 3pp
- 8004300570 Part 21 rept re support braces for reactor bldg coolers that are nonconservative w/respect to brace design assumed in seismic analysis Support braces are to be modified to conform to seismic design
 TAYLOR, J H Babcock & Wilcox Co 80/03/24 5pp
- 8004020375 Seventh interim deficiency rept re expansion anchors not passing qualification tests Final rept MILLS.L M Tennessee Valley Authority 80/03/25 1p
- 8004010397 Interim deficiency rept re potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOWELL
- r-8004010404 forwards add1 info to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by B&W TAYLOR, J H Babcock & Wilcox Co 80/03/03, App

- 6004020414 Forwards interim dericiency rept re-potential defects in WKM central valves in decay heat cooler outlet Next rept will be submitted by 800514
 MILLS.L.M. Tennessee Valley Authority 80/03/27 ip
- --8004020416 Interim deficiency rept to potential defects in WAM central valves in decay heat cooler outlet BAW has begun investigation to determine extent & cause of defects tennessee Valley Authority 80/03/27 ip
- 9004020431 Forwards second interim deficiency rept re makeup & purification // decay heat removal pumps u/damaged thermocoupie wiring Neit rept will be submitted by 800508 MILLS.L M Tennessee Valley Authority 80/03/27 lp
- ---B004020436 Second interim deficiency lept re makeup & purification & decay heat removal pump motors w/damaged thermocouple wiring Heeting planned w/BBW to discuss scheduling of repairs & testing of pump motors * Tennessee Valley Authority 80/03/27 ip
- 8004040377 Forwards final deficiency rept re makeup & purification letdown cooler supports
 MILLS.L M Tennessee Valley Authority 80/03/27 ip
- --8004040391 Final deficiency rept agreement reached by AE & vendors that combination of AE support platform & cooler support bracket would result in overstressed condition in lowest of three cooler supports Completian of support mods expected 800930 Tennessee Valley Authority 80/03/27 1p
- 8004020417 Forwards interim deficiency rept re violation of INRYCD field installation procedures Next rept will be submitted by 800618
 - MILLE, i M Tennessee Valley Authority 80/03/28 15
- --8004020421 Interim defictency rept re violation of INRYCO field installation procedures Revisions to QC procedures have been recommended % new inspector instructed in following Tennessee Valley Authority 80/03/28 to
- 8004160291 Forwards final deficiency rept re voids in primary tainment dome LS.L M Tennessee Valley Authority 80/03/31 1p
- --8004160296 Final deficiency rept re voids in primary containment dome Suspect areas result from lack of bond between liner plate & concrete Holes in liner plate repaired MILLS.L M Tennessee Valley Authority 80/03/31 19
- 8004280432 Forwards second interim deficiency rept re defective seat ring seal welds on Borg-Warner valves Final rept will be submitted by 800428 MILLS,L M Tennessee Valley Authority 80/04/07 ip
- --8004280436 Second interim deficiency rept re defective seat ring seal welds on Borg-Karner valves Util & manufacturer have established required acceptance criteria for welds Insp of valves is in progress Results until be in final rept * Yennessee Valley Authority 80/04/07 tp
- 8004220420 Notifies that correct date of initial notification on NRC 1070 was 790928 Repts dtd 791026.1211 3 8000331 erroneously stated date as 790528 MILLS.L M Tennessee Valley Authority 80/04/15 ip
- 8004220541 Forwards final deficiency rept re Borg-Warner three-inch Mills, t K Tennessee Valley Authority 80/04/16 ip
- --G004220546 Final deficiency rept re Norg-Warner three-inch motor operated gate valves Gate valve failed to close fully when actuated under operating conditions during recent test program Borg-Warner is redesigning std gate valve.
 * Tennessee Valley Authority 80/04/16 ip
- 8004280438 Forwards final deficiency rept re Borg-Warner 3-inch motor operated gate valves
 MILLB.L.M Tennessee Valley Authority 80/04/16 ip
- ~-8004280442 Final deficiency rept re Horg-Warner 3-inch motor operated gate valves Binding will be corrected by mod of valves * Tennessee Valley Authority 80/04/16 ip
- 8004230380 Forwards final deficiency rept re header supports for HILLS, L M Tennessee Valley Authority 80/04/17 ip

- --8004230382 Final deficiency rept re header supports for reactor bldg coolers Manufacturer performed seismic analysis & discovered braces fabricated from box cross section tubing Braces returned for mod
 * Tennessee Valley Authority 80/04/17 1p
- B004230503 Forwards first interim deficiency rept re Intl Telephone & Telegraph actuator for Ruskin dampers Next rept will be submitted by B00813
 MILLS.L M Tennessee Valley Authority B0/04/17 1p
- ---8004230507 First interim deficiency rept re Intl Telephone & Telegraph actuator for Ruskin dampers Upon receipt of Intl Telephone & Telegraph actuator data. Ruskin will provide corrective procedures to util

 * Tennessee Valley Authority 80/04/17 1p
- 8004230527 Forwards first interim deficiency rept re Intl Telephone & Telegraph controls for American Warming & Ventilation dampers Nect rept will be submitted by 800814 MILLS.L M Tennessee Valley Authority 80/04/17 ip
- --8004230529 First interim deficiency rept re Intl Telephone & Telegraph controls for American & Warming & Ventilation dampers Upon receipt of Intl Telephone & Telegraph actuator data-American Warming & Ventilation will provide corrective procedures * Tennessee Valley Authority 80/04/17 1p
- 800424038A Forwards first interim deficiency reat re failure of main steam lines MILLS.L M Tennessee Valley Authority 80/04/17 ip
- --8004240388 First interim deficiency rept re failure of main steam lines Caused by main feedwater overfill Deficiency undergoing evaluation Util & B&W working to incorporate mitigative instrumentation into facilities * Tennessee Valley Authority 80/04/17 ip
- 8004280516 Forwards first interim deficiency rept re defective springs used in ITT General Control actuators supplied to Ruskin MILLS,L M Tennessee Valley Authority 80/04/17 1p
- --B004280524 First interim deficiency rept re defective springs used in ITT General Control actuators supplied to Ruskin Bpring does not possess designed strength & forco Ruskin uill inform util of corrective actions, pending receipt of accurate data

 * Tennessee Valley Authority B0/04/17 ip
- 8004250380 Forwards final deficiency rept to TPIPE computer user failure to check frequency analysis of piping sys MILLS, L. M. Tennessee Valley Authority 80/04/21 ip
- --8004250384 Final deficiency rept re TPIPE computer user failure to check frequency analysis No erroneous design info has resulted frogram mod to stop any program run when frequency analysis not converging # Tennessee Valley Authority 80/04/21 ip
- DUCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits add1 guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance RDSS,D F Division of Project Management 80/02/21 3pp
- 8004280308 Forwards request for add1 info re power sys.for OL application review Requests date that response will be available for review PARR.O D Light Water Reactors Branch 3 80/03/19 25pp
- 8004110046 Requests addl info on changes & studies proposed in App F of 791203 response to NRC 791025 10CFR50 54 requests redesign adequacy of IBW NSSS utilizing once-through steam generators PARR: D Light Water Reactors Branch 3 80/03/25 5pp

- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO cleanance under Federal Repts Act ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- B004070052 Forwards request for info re util 790301 safeguards contingency plan & 790701 Revision 1 Encl withheld (ref 10CFR2 790)
 - PARR. D D Light Water Reactors Branch 3 80/03/14 2pp
- Q Inspection reports: IC Bulletins & correspondence
- 8004070352 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II, Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/04 20p
- 8004090388 Forwards IE Insp Repts 50-438/80-03 & 50-439/80-03 on 800204-08 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 2pp
- --8004070392 IC Insp Repts 50-438/80-03 & 50-437/80-03 on 800206-08 No noncompliance noted Major areas inspected containment prestressing GA/GC controls, work performance, const status & quality records
 CCNLON, T E, LENAHAN, J J Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 App
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC 5 util in Atlanta.OA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by OA program O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/12 2pp
- 8004070150 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-01 & 50-439/80-01 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/17 2pp
- --8004070158 Forwards IE Insp Repts 50-438/80-01 & 50-439/80-01 on 800108-11 & notice of violation BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/11 2pp
- --8004070168 Notice of violation from insp on 800108-11 * Region 2, Atlanta, Office of the Director 80/02/11 ip
- --8004070177 IE Insp Repts 50-438/80-01 & 50-439/80-01 on 800108-11 Noncompliance noted failure to follow procedure for visual insp of welds HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch VANDOURN.P K Region 2. Atlanta, Office of the Director 80/02/01 4pp
- 8004210178 Forwards response to IE Bulletin 80-03. "Loss of Charcoal from Std Type II. Two-Inch.Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists.

 MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS,L.M. Tennessee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 20p
- 8004080636 Forwards IE Circular 80-05, "Emergency Dissel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 2pp
- 8004150097 Forwards IE Info Notice 80-13, "GE Type SEM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02

- 8004240274 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required D'REILLY. J.P. Region 2. Atlanta. Office of the Director 80/04/02 3pp
- B004180275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Cil Sys " No written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/03 20p
- B004230142 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME SA-312. Type 304 Stainless Steel Pipe" Action required O'REILLY. J.P. Region 2. Atlanta. Office of the Director 80/04/04 ip
- BO04180445 Forwards IE Bulletin BO-OB, "Exam of Containment Liner Penetration Welds" Written response required D'REILLY. J P Region 2. Atlanta. Office of the Director BO/04/07 300
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLS, L. M. Tennessee Valley Authority 80/04/23 3pp
- S Reportable occurrences, LERs & related correspondence
- 8004020457 Part 21 rept on 800228.8&W made telephone rept re defect concerning potentially overstressed supports on reactor coolant latdown coolers due to inadequate support design Corrective action redesign of support stand TAYLOR.J H Babcock & Wilcox Co 80/03/03 6pp
- BO04080563 PND-II-B0-045 on 800319, util notified Region 2 of B&W notification re potential for failure of main steam lines in event of feedwater overflow of steam generators Region 2 investigating generic aspects WRIGHT, R W . CONTRELL.F S Region 2, Atlanta, Office of the Director 80/03/19 ip
- B004150209 Forwards deficiency rept re support braces for cooling water supply header used for reactor bldg coolers being incongrous w/seismic analysis
 TAYLOR, J H Babcock & Wilcox Co B0/03/24 1p
- --8004150210 Deficiency rept re support braces for cooling water supply header used for reactor bldg coolers being incongluous w/ seismic analysis Cause unstated Braces returned to vendor for mod to conform to seismic analysis design # Babcock & Wilcox Co 80/03/24 3ep
- 8004300870 Part 21 rept re support braces for reactor bldg coolers that are nonconservative w/respect to brace design assumed in seismic analysis Support braces are to be modified to conform to seismic design
 TAYLOR, J H Babcock & Wilcox Co 80/03/24 Spp
- 8004020395 Seventh interim deficiency rept re expansion anchors not passing qualification tests Final rept
 MILLS,L M Tennessee Valley Authority 80/03/25 ip
- 8004010397 Interim deficiency rept re potential overstress condition in letdown cooler supports Nozzle loads will be analyzed for effects on support structure to determine if mods are required to cooler support sys HOWELL,S H Consumers Power Co 80/03/27 1p
- --B004010404 Forwards addi into to Part 21 rept re potentially overstressed supports on reactor coolant letdown coolers at facilities under const by B5H TAYLOR, J H Babcock & Wilcox Co 80/03/03 App
- 8004020414 Forwards interim deficiency rept re potential defects in WKM central valves in decay heat cooler outlet Next rept will be submitted by 800514
 MILLS.L M Tennessee Valley Authority 80/03/27 ip
- --8004020416 Interim deficiency rept re potential defects in WKM central valves in decay heat cooler outlet BM has begun investigation to determine extent % cause of defects * Tennessee Valley Authority 80/03/27 ip
- 8004020431 Forwards second interim deficiency rept re makeup & purification & decay heat removal pumps w/damaged thermocouple wiring Next rept will be submitted by 800508 MILLS, L. M. Tennessee Valley Authority 80/03/27 ip

- --800402043& Second silterim dericiency lept re makeup & purification & decay heat removal pump motors w/damaged thermocouple wiring fleeting planned w/880 to discuss scheduling of repairs & testing of pump motors # Tennessee Valley Authority 80/03/27 ip
- 8004040377 Forwards final deficiency tept re makeup & purification letdown cooler supports
 MiLLS.L M Tennessee Valley Authority 80/03/27 ip
- --8004040371 Final deficiency rept agreement reached by AE & vendors that combination of AE support platform & cooler support bracket would result in overstrassed condition in lowest of three cooler supports Completion of support mods expected 800930 * Tennessee Valley Authority 80/03/27 ip
- 8004020417 forwards interim deficiency rept re violation of INRYCO field installation procedures Next rept will be submitted by 800618
 - MULE, L M Tennessee Valley Authority 80/03/28
- --8004020421 Interim deficiency rept re violation of INRYCO field installation procedures Revisions to GC procedures have been recommended & new inspector instructed in following procedures
 - oceoures Tennessee Valley Authority 80/03/28 ip
- 8004280432 Forwards second interim deficiency rept re defective seat ring seal welds on Borg-Warner valves Final rept will be submitted by 800428 MILLS.L M Tennessee Valley Authority 80/04/07 1p
- --8004280434 Second interim deficiency rept re defective seat ring seal welds on Borg-Warner valves Util & manufacturer have established required acceptance criteria for welds insp of valves is in progress Results will be in final rept

 # Tennessee Valley Authority 80/04/07 ip
- 8004220541 Forwards final deficiency rept re Borg-Harner three-inch motor operated gate valves MILLS.L M Tennessee Valley Authority 80/04/16 ip
- --8004220546 Final deficiency lept re Borg-Warner three-inch mator operated gate valves Gate valve failed to close fully when actuated under operating conditions during recent test program Borg-Warner is redesigning std gate valve * Tennessee Valley Authority 80/04/16 ip
- 8004280438 Forwards final deficiency tept re Borg-Warner 3-inch motor operated gate valves MILLS.L M Tennessee Valley Authority 80/04/16 ip
- --8004280442 Final deficiency rept re Borg-Warner 3-inch motor operated gate valves Binding will be corrected by mod of valves * Tennessee Valley Authority 80/04/16 ip
- 8004230380 Forwards final deficiency rept re header supports for reactor bldg coalers MILLS.L M Tennessee Valley Authority 80/04/17 ip
- --8004230382 Final deficiency rept re header supports for reactor bldg coolers Manufacturer performed seismic analysis & discovered braces fabricated from box cross section tubing Braces returned for mod

 * Tennessee Valley Authority 80/04/17 1p
- 8004230503 Forwards first interim deficiency rept re Inti Telephone & Telegraph actuator for Ruskin dampers Next rept will be submitted by 800813 MILLS. 4 Tennessee Valley Authority 80/04/17 ip
- --8004230507 First interim deficiency rept re Intl Telephone & Telegraph actuator for Ruskin dampers Upon receipt of Intl Telephone & Telegraph actuator data. Ruskin will provide corrective procedures to util
 # Tennessee Valley Authority 80/04/17 1p
- 8004230527 Forwards first interim deficiency rept re Intl Telephone & Telegraph controls for American Warming & Ventilation dampers Neit rept will be submitted by 800814 MILLS:L M Tennessee Valley Authority 80/04/17 ip
- --8004230529 First interim deficiency rept re intl Telephone & Telegraph controls for American & Marming & Ventilation dampers Upon receipt of Intl Telephone > Telegraph actuator data, American Warming & Ventilation will provide corrective procedures * Tennessee Valley Authority 80/04/17 ip

ź

- 8004240386 Forwards first interim deficiency rept re failure of main steam lines MILLS, L M Tennessee Valley Authority 80/04/17
- --8004240388 First interim deficiency rept re failure of main steam lines Caused by main feedwater overfill Deficiency undergoing evaluation Util & B&W working to incorporate mitigative instrumentation into facilities

 * Tennessee Valley Authority 80/04/17 ip
- 8004280516 Forwards first interim deficiency rept re défective springs used in ITT General Control actuators supplied to Ruskin MILLS.L M Tennessee Valley Authority 80/04/17 ip
- --8004280524 First interim deficiency rept re defective springs used in ITT General Control actuators supplied to Ruskin Spring does not possess designed strength & force Ruskin will inform util of corrective actions, pending receipt of accurate data * Tennessee Valley Authority 80/04/17 ip
- 8004250380 Forwards final deficiency rept re TPIPE computer user failure to check frequency analysis of piping sys
 MILLS:L M Tennessee Valley Authority 80/04/21 ip
- --8004250384 Final deficiency rept re TPIPE computer user failure to check frequency analysis No erroneous design info has resulted Program mod to stop any program run when frequency analysis not converging * Tennessee Valley Authority 80/04/21 ip
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004070041 Farwards NRC 800128 & 0211 ltrs to GE re mads to BWR control rod drive sys re elimination of clacking in return line nozzle Mods should not be performed until issuance of NUREG-RUSENSTEIN L S Light Water Reactors Branch 4 BO/03/11 200
- 8004100301 Notification of 800403 meeting w/GE in Bethesda, MD to discuss BWR 4 safety relief valves mfg by 0 Dickens & Co & supplied by GE to facilities HENDRREGN. J B Division of Reactor Construction Inspection 80/03/13 2pp
- F Security, medical, emergency & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification SOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- BC04240364 Responds to 791129 ltr requesting review of DD Wilt concerns re licensee const practices 2 NRC insp approach Const defects must be corrected prior to OL issuance NRC sampling insp program assures compliance w/NRC requirements DIRCKB,W J Office of the Frecutive Director for Operations B0/03/05 3pp Зрр
- @ Inspection reports. IE Bulletins & correspondence
- 8004110150 Forwards IE Insp Repts 50-440/80-01 & 50-441/80-01 on 800123-25 & notice of violation FIGRELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/26 2pp
- --8004110152 Notice of violation from insp on 800123-25
 * Region 3. Chicago, Office of the Director 80/02/20 ip

- --8004110176 IE Inep Repts 50-440/80-01 & 50-441/80-01 on 800123-25 Noncompliance noted failure to qualify inspector personnel records WILLIAMS, C C , KONKLIN, J E , KEY, W J Region 3, Chicago, Office of the Director 80/02/20 10pp
- 8004100125 Forwards IE Info Notice 80-08. "States Co Silding Link Electrical Terminal Block " No specific action or response
- required
 KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/07
- 8004150165 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary
- response necessary
 KEPPLER, J. G. Region 3. Chicago, Office of the Director BO/03/31
 to
- 8004080698 Forwards IE Circular 80-05, "Emergency Dissel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director B0/04/01
- 8004150034 Forwards IE Info Notice 80-13. "GE Type SSM Control Switches Defective CAM Followers " No specific action or response required
- required

 KEPPLER, J Q Region 3, Chicago Office of the Director 80/04/02

 ip
- 8004180038 Forwards attachments to IE Circular 80-03, "Protection From Toxic Qae Hazards," inadvertently omitted from 800305 transmittal KEPPLER.J Q Region 3, Chicago, Office of the Director 80/04/02
- BD0422011B Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPFLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220347 Forwards IE Circular 80-07, "Problems W/HPC1 Turbine Gil Sys " No written response required. KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/03 in
- 8004110033 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/07 to
- 8004230201 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07 to
- 8004220139 Forwards IE Bulletin BO-OB, "Exam of Containment Liner Penetration Welds" Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09
- S. Reportable occurrences. LERs & related correspondence
- 8004070167 Ack receipt of 800229 final deficiency rept re omission of Class B fill waterstops FIDRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/17 ip
- 8004230353 Final deficiency rept re cracks & tears in bottom of steel encls of ITE switchgear caused by meismic environ Holms drilled & welds run along bend line Min of three switchgear frames will be bolted together for future shipments

 DAVIDSON, D R Cleveland Electric Illuminating Co 80/04/15 Spp
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- BO04040031 Advises of issuance of NUREQ-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROS8.D F. Division of Project Management
- 8004070041 Forwards NRC 800128 & 0211 ltrs to GE re mods to BWR control rod drive sys re elimination of cracking in return line nortle Mods should not be performed until issuance of NUREG-0619.
 RUBENSTEIN.L B Light Water Reactors Branch 4 80/03/11 2pp

- 8004100301 Notification of 800403 meeting w/OE in Bethesda.MD to discuss BMR & safety relief valves mrg by Q Dickens % Co & supplied by GE to facilities HENDERSON J B Division of Peactor Construction Inspection
- F Security, medical, emergency & rire protection plans
- BO04080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO cloarance under Foderal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OBSIGKL V Office of the Executive Director for Operations B0/04/02 34pp
- H General correspondence
- BOO4240364 Responds to 791129 ltr requesting review of DD Wilt concerns re licenses const practices \$ NRC insp approach Const defects must be corrected prior to OL issuance NRC sampling insp program assures compliance w/NRC requirements DIRCKS/N J Office of the Executive Director for Operations BO/03/05 3pp
- Q Inspection reports, IF Bulletins & correspondence
- HOO411D150 Forwards IE Insp Repts 50-440/80-01 & 50-441/80-01 on HOO123-25 & notice of violation FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/26 2pp
- --8004110152 Notice of violation from insp on 800123-25 * Region 3, Chicago, Office of the Director 80/02/20 1p
- --B004110176 IE Insp Repts 50-440/80-01 & 50-441/80-01 an B00123-25 Nancompliance hoted failure to qualify inspector personnel records WILLIAMS.C C. KONKLIN, J E. KEY, W J Region J. Chicago, Office of the Director 80/02/20 10pp
- 8004100125 Ferwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/07 in
- 8004150165 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/31
- 8004080498 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/01
- 8004150034 Forwards IE Info Notice 80-13. "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004180038 Forwards attachments to IC Circular 80-03. "Protection From Toxic Oas Hazards," inadvertently omitted from 800306 transmittal
 - KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220118 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/04/02 in
- 8004220347 Forwards IE Circular 80-07, "Problems W/MPCI Turbine Dil Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03 in

DOCKETED ITEMS

- 8004110033 Forwards IF Bulletin PO-07, "RWR Jet Pump Assembly Failure" No written response tequired KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/04/07
- B004230E01 forwards [E Bulletin 79-03A "Longitudina] Held Defects in ASME 6A-312 Type 304 Stuniless Steel Pipe" Action required KEPPLFR.J 0 Region 3 Chicago Office of the Director 80/04/07 ip
- 8004220139 Forwards IE Bulletin 80-08. 'Frem of Containment Liner Penetiation Welds - Written response required KEPPLER, J.G. Region 3. 'hicago, Office of the Director - 80/04/09 ip
- 5 Reportable occurrence . (ERs > related correspondence
- 8004090167 Act receipt of 800229 final deficiency rept re omission of Class B fill waterstops FIORELLI, 6 Kegion 3, Chicago, Reactor Construction & Engineering Support Branch 80703417 1p
- 8004230353 Final deviciency rept to cracks & tears in bottom of steel encis of ITE switchgear caused by seismic environ Holes drilled & welds run along bend line Min of three switchgear frames will be bolted together for future shipments

 DAVIDSON D.R. Cleveland Electric Illuminating Co. 80/04/15 3pp
- DOCKET 50-443 SEABROOK NUTLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B004040031 Advises of issuance or MUREG-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Hanagement B0/02/05 7pp
- 8004020124 Advises that steps have been taken to initiate review of G4W-FSD-2538 re main steam isolation valve, per 800108 ltr. Review will be conducted on schedule consistent w/QL application review VARGA/S A Assistant Director for Light Water Reactors 80/03/25
- F Security, medical, emergency 2 fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004210316 Submits statement of B00320 meeting re status of city emergency evacuation plan Present plan insufficient to ensure human sarety State 9 federal runding & technical assistance needed to bring plan to required to stds BHERIDAN.C F Affiliation Unknown 80/03/24 Ip
- G Adjudicatory correspondence
- B0040B0364 Discusses 800122 board notification re re-evaluation of 1732 Montreal earthquake & impact on facility NRC conclusion promature & reassessment of seismic experts may be subj to conflict of interest SHELDON.K.P. Sheldon. Harmon & Weiss 80/03/05 4pp
- 8004010472 Notifies that vote of people at annual town meeting supported withholding issuance of OL until safe evacuation plan established No town funds will be spent on evacuation plan tOCKE,E U , FALCONER, J C , EATON, J Affiliation Unknown 80/03/28 2pp
- 8004070045 Order granting extension until 800416 for Commission to consider whether to review ALAB-422 t ALAB-561 CHILK.S J Office of the Secretary of the Commission 60/03/28 fp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning to preparedness, distributed as Board notification GOSSICK. V Office of the Executive Director for Operations 80/04/02 GApp
- 8004280165 Order granting extension until 800507 for Commission to consider whether to review ALAB-422 & ALAB-561 CHILMS J. Diffice of the Secretary of the Commission 80/04/17

H General correspondence

- 7907170211 Requests halt to plant const until util & NRC can devise adequate e-acuation plans
 BATES.A W. Affiliation Uninoum 79/07/11 lp
- 7907250345 Requests suspension or const pending improved evacuation planeas residence is only 12 miles from proposed plant WILLIAMSON F W Affiliation Unknown 79/07/17 jp
- 7907250327 Requests suspension of const pending improved evacuation plan GALLAGHER, V.C. Affiliation Unknown 79/07/18 1p
- 8004110052 Responds to 79071; itr re emergency planning Will review applicant responses to Commission requirements prior to decision to issue OL Opportunity will be provided for public intervention prior to decision VARGA-5 A Assistant Director for Light Water Reactors 80/03/27
- 8004110060 Responds to 790717 note re emergency planning & consequences of Class 9 accidents Will review applicant responses to Commission requirements Opportunity will be provided for public intervention prior to decision to issue OL. VARGA. S. A. Assistant Director for Light Water Reactors 80/03/27
- 8004110047 Responds to 790718 itr re emergency planning for areas near facility Will review applicant responses to Commission requirements b provide apportunity for public intervention prior to decision to issue OL VAROA.5 A Assistant Director for Light Water Reactors 80/03/27 Jpp
- 8004150131 Responds to 740710 ltr re omeigency planning Will review applicant responses to Commission requirements prior to decision to issue OL Opportunity will be provided for public intervention prior to decision

 VARGALS A Assistant Director for Light Water Reactors 80/03/27
 3pp
- B004240529 Responds to 790407 itr of opposition to plant const Forwards B00211 Itr containing Director's decision not to issue order to show cause NRC will review applicant responses to requirements prior to decision no DL issuance ROSS,D F Division of Project Management B0/04/09 2pp
- ---8004240534 Opposes plant const due to lack of evacuation plan & threat of disaster EATDN.L. Affiliation Unknown 79/06/07 ip
- I Financial information
- 8004070299 Forwards revised source of funds schedule.omitted from 800314 Suppl 4.Amend 40 request for partial transfer of CPs RITSHER, J A Ropes & Gray 80/03/31 ip
- ---8004070302 Revised source of funds schedulo.omitted from Suppl 4.Amend 40 of OL application for partial transfer of CPs * Public Service Co of New Hampshire 80/03/31 2pp
- 8004170263 Forwards request for addl rinancial info NRC requires info to complete evaluation of financial capability of applicants proposing to increase ownership participation & evaluation of financial capability of proposed new owners RUBENSTEIN.L S Light Water Reactors Branch 4 80/04/02 8pp
- M Antitrust correspondence
- BOO414009B Forwards Attorney General BOO317 itr providing addl antitrust advice re CP application Ltr will be published in FR SALTZMAN, J Antitrust & Indemnity Group BO/03/21 1p
- --8004140104 Advises NRC to CP for power plants per Section 105 of amended Atomic Energy Act of 1954 Antitrust hearing not necessary LITYACK.S M Justice.Dept of, Attorney General's Office 80/03/17 1p
- 8004140279 Forwards DDJ 800317 ltr providing addl antitrust advice re CP application Ltr concludes that no basis for antitrust hearing was disclosed during review of info re Bangor ownership of 50 MM share in facility SALTZMAN.J Antitrust & Indemnity Group 8D/03/26 2pp

O Inspection reports, IE Bulletins & carrespondence

- 8004090432 Forwards IE Mgt Meeting Repts 50-443/80-02 & 50-444/80-02 on 800206 CARLSONAR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/26 ip
- ~-8004090441 IE Mgt Meeting Repts 50-443/80-02 & 50-444/80-02 on 800206 Areas discussed & results establishment of onsite ofc to place full-time resident inspector MCOAUGHY, R W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MCDBCAR, J J. CERNC, A C. Region 1, Philadelphia, Office of the Director 80/02/26 3pp
- 8004070102 Ack receipt of 800201 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-443/79-09 & 50-44479-09 CARLEON R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/05 2pp
- --B004070106 Responds to NRC B00111 ltr re violations noted in 1E Insp Repts 50-443/79-09 & 50-444/79-09 Corrective actions revised Perini Procedure BAP-15-0 to require corrective action determination on each rept DEVINCENTIS, J Public Service Co of New Hampshire B0/02/01
- --8004070109 Forwards IE Insp Repts 50-443/79-09 & 50-444/79-09 on 791113-16 & notice of violation CARLSON; R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --8004070110 Notice of violation from insp on 791113-16
 * Region 1. Philadelphia, Office of the Director 80/01/03 ip
- ---B004070111 IE Insp Repts 50-443/79-09 & 50-444/79-09 on 791113-16
 Noncompliance noted failure to prescribe corrective actions
 by Perini & UE&C to preclude placement of concrete until all
 reinforcing steel has been installed
 EBMETER.S D Region 1. Philadelphis. Reactor Construction &
 Engineering Support Bianch SANDERS.W F. VARELA.A A Region 1.
 Philadelphis. Office of the Director 80/01/03 8pp
- 8004100035 Forwards IE Inap Repts 50-443/80-01 & 50-444/80-01 on 800122-25 No moncompliance noted CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/11 2pp
- --8004100040 IE Insp Repts 50-443/80-01 & 50-444/80-01 on 800122-25 No noncompliance noted Major areas inspected QC controls on rebar installation & cadwelding, equipment maint & storage & plant insp tour
 KERNE.A C , VARELA.A A Region I, Philadelphia, Office of the Director MCGAUGHY, R W Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/04 9pp
- 8004080385 Forwards IE rept per CJ Reis 800303 ltr Draws attention to Pages 3 & 4 M/o encl REIS.E J. Hearing Branch 3 00/03/25 1p
- 8004190302 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER.19 H Region 1. Philadelphia. Office of the Director 80/03/31 1p
- BD04090103 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 90/04/01 ip
- 8004110511 Forwards IG Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/04/02 ip
- BO0424034B Forwards IE Info Notice 80-14, "Gafety Buggestions From Employees" No action required ORIER,B H Region 1, Philadelphia, Office of the Director 80/04/02 ip
- 8004180173 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil 8ys " No written response required ORIER B H Region 1. Philadelphia, Office of the Director 80/04/03 ip

- B004230502 Forwards IE Bulletin 79 0 M. "Longitudinal Weld Defects in ASHE SA-312. Type 304 Stainless Steel Pipt "Action required ORIER. B.H. Region 1. Chiladelphia Orrice of the Director B0/04/04 ip
- 8004180284 Forwards IF Bulletin 80-08 'Cram of Containment Liner Penetration Welds' Mritten esponse required GRIER, B.H. Region 1. Philadelphia. Office of the Director 80/04/07 ip
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUPEG-0988. "Interim Staff Position on Environ Qualification of Sately-Related Electrical Equipment," providing guidance is methods for compliance ROSS.D f Division of Project Management 80/02/05 7pp
- 8004020124 Advises that steps have been taken to initiate neview of GFM-FBD-2538 no main steam isolation valve, per 800108 ith Review will be conducted on schoole consistent w/DL application review VARGA. S A Assistant Director for Light Water Reactors 80/03/25 to
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- 8004210316 Submibs statement of 800320 meeting re status of city omergoncy ovacuation plan Present plan insufficient to ensure human safety State 5 rederal fouding 5 technical assistance needed to bring plan to required to stds SHERIDAN, C F Affiliation Unknown 80/03/24 (p
- G Adjudicatory correspondence
- 8004080364 Discusses 800122 board notification re re-evaluation of 1732 Montreal earthquake & impact on facility NRC conclusion premature & reassessment of seismic experts may be subj to conflict of interest SHELDON.K P Sheldon, Harmon & Weiss 80/03/05 4pp
- 8004010472 Notifies that vote of propie at annual town meeting supported withholding issuance of CL until safe evacuation plan established No town funds will be spent on evacuation plan LOCKE, E. U., FALCONER, J. C., EATON, J. Affiliation Unknown 80/03/25
- B004070045 Order granting extension until 800418 for Commission to consider whether to review ALAB-122 % ALAB-561 CHILKIS J. Office of the Secretary of the Commission 80/03/28 in
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & proparediness distributed as Board notification ODSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004280165 Order granting extension until 800509 for Commission to consider whether to review ALAB-422 & ALAB-561
 CHILKS J. Office of the Socretary of the Commission 80/04/17
- If General correspondence
- 7907170211 Requests halt to plant const until util & NRC can devise adequate evacuation plans
 BATES, A K Affiliation Unknown 79/07/11 1p
- 7907250345 Requests suspension of const pending improved evacuation plantas residence is only 12 miles from proposed plant WILLIAMSON.P N Affiliation Unknown 79/07/17 1p
- 7907250327 Requests suspension of const pending improved evacuation plant GALLACHER, V.C. Affiliation Unknown 79/07/18 ip

- encid110052 Responds to finite for emergency planning Will review applicant responses to formal, for requirements prior to decision to issue OL Opiniton, you'll be provided for public interventing prior to decision to decision.

 VAPOA. ⊆ A Assistant Lit if the Port Light Mater Reactors 60/03/27
- 8004110060 Responds to 750/17 note to emergency planning b consequences of Class 9 accident. Will review applicant itsponses to Commission requirement, apportunity will be provided for public intervention prior to decision to issue OL VARON.S A Assistant Director for Light Water Reactors. 80/03/27
- 8004110067 Responds to 790718 l+1 to emergency planning for areas hear facility Will review applicant responses to Commission requirements // plovide apportunity for public intervention prior to decision to issue OL UARGA/S A Assistant Firector For Light Water Reactors 80/03/27
- 8004150131 Responds to 770710 ltm relemengency planning Will review applicant responses to Commission requirements prior to decision to assue OL Opportunity will be provided for public intervention pitor to decision.

 VARGALS A. Assistant intercor for Light Mater Reactors. 80/03/27
- 8004240529 Responds to 79050/ its or opposition to plant const Forwards 800211 its containing (practor > decision not to issue order to show cause NRC will review applicant responses to requirements prior to decision to D. issuance ROSS.D F. Division of Project Management. (8) ROSS D F 80/04/09 2pp
- --8004240534 Opposes plant const due to lack of evacuation plan & threat of disaster EATON:L. Afriliation Unknown 79/06/07 ip
- l Financial information
- 8004076299 Forwards revised source of runds schedule, omitted from 800314 Suppl 4. Amend 40 request for partial transfer of CPs RITSHER. J A Ropes 4 Gray 80/03/31 1p
- --8004070302 Revised source of tunds schedule,omitted from Suppl 4,Amend 40 of OL application for partial transfer of CPs 4 Public Service Co of New Hampshire 80/03/31 2pp
- 8004170263 Forwards requist for add1 financial into NRC requires info to complete evaluation of financial capability of applicants proposing to increase ownership participation to evaluation of financial capability of proposed new owners RUBENSTEINLES Light Water Reactors Branch 4 80/04/02 8pp
- M Antitrus* correspondence
- 800414009B Forwards Attorney General 800317 ltr providing addl antitrost advice re CP application Ltr will be published in FR
 - SALTZKAN, J Antitrost . Indemnity Group 80/03/21 1p
- --8004140104 Advises MRC re CP for power plants per Section 105 of emended Atomic Energy Act of 1954 Antitrust hearing not mecessary LITVACK,S M Justice, Dept of, Attoiney General's Office 80/03/17 ip
- 8004140279 Forwards DDJ 860317 its providing addl antitrust advice ro CP application Ltr concludes that no basis for antitrust hearing used during review of info re Bangor ownership of 50 MH shale in facility SALTZMAN, J. Antitrust? Indemnity Group 80/03/26 2pp
- Q Inspection reports: IF Bulletins & carrespondence
- 8004090432 Forwards IE Mgt Meeting Repts 50-443/80-02 & 50-444/80-02 on BOC205 CARLSOIN R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/26 ip
- --800409044) IE Mgt Meeting Repts 50-443/80-02 & 50-444/80-02 on 800206 Areas discussed & results establishment of onsite of: to place full-time resident inspector MCGAUGHY, R & Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MCOSCAH. J J., CERNE. A C. Region 1, Philadelphia, Office of the Director 80/02/24 3pp

- 8094070102 Ark receipt or 800201 ltr informing NRC of steps taken to correct rightions noted in IF Insp Repts 50-443/79-09 & 50-444/79-09 CARLEGIA, R 1 Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/05 2pp Engineering Support Blanch
- --B0040/0106 Responds to NRC 800111 ltr ie violations noted in IE lnsp Repts 50-443/79-09 f 50-444/79-09 Corrective actions revised Perini Procedure QAP-15-0 to require corrective action determination on each impt
 DEVINCENTIS, J. Public Service Co. of New Hampshire 80/02/01
- ---8004070109 Forwards LE Insp Repts 50-443/79-09 & 50-444/79-09 on 791113-16 * notice of violation CARL SOULR T Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --8004070110 Notice of violation from insp on 791113-16
 * Region 1, Philadelphia: Office of the Director 80/01/03 1p
- B004100035 Forwards IE Insp Repts 50-443/80-01 & 50-444/80-01 on BD0122-25 No noncompliance noted CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch B0/03/11 2pp
- --8004100040 IE Insp Repts 50-443/80-01 & 50-444/80-01 on 800122-25 No noncompliance nated Major areas inspected QC controls on rebar installation & cadwelding, equipment maint & storage & rebar installation & cadwelding, equipment meshed 2000, age oplant into tour plant into tour kennes. A C. VARELA, A A Region 1, Philadelphia, Defice of the Director MCGAUCHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/04 9pp
- 8004080355 Forwards IE rept per FJ Reis 800303 ltr Draws attention to Pages 3 δ 4 W/o encl REIS E J. Hearing Branch 3. 80/03/25. 1p
- 8004150302 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Diock Valve " No specific action or response necessary GRIER, D H. Region 1, Philadelphia, Office of the Director 80/03/31 p
- 8004090103 Forwards IC Circular BO-05, "Emergency Diesel Generator Lubracating Oil Addition & Onsite Supply " No written response required
 GRIER.B H Region 1. Philadelphia. Office of the Director
 BO/04/01 | 1p
- 8004110511 Forwards II. Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No written response required GRIER, B B Region I. Philadelphia, Office of the Director 80/04/02 ip
- HOO424G3AB Forwards IF Info Notice 80-14. "Safety Buggestions From Employees " No action required ORIER, B H Region I. Philadelphia. Office of the Director 80/04/02 | p
- 8004180173 Forwards IE Circular 80-07. "Problems (J/HPCI Turbine Oil Sys " No written response required GRICE, B H Region 1. Philadelphia, Office of the Director BO/04/03 1p
- 8004230502 Forwards IF Bulletin 77-03A. "Longitudinal Weld Defects in ASME SA-312,Type 304 Stainless Stoel Pipe " Action required GRIER, B H. Region i. Philadelphia, Office of the Director 80/04/04 | Ip
- 8004180284 Forwards IF Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response lequired GRIER, B. H. Region 1. Philadelphia, Office of the Director 80/04/07 ip

- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-058B, "Interim Staff Position on Environ Qualification or Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D.F. Division of Project Management 80/02/05 7pp
- 8004040017 Submits addi guidance to NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review or aquipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management B0/02/21 3pp
- 8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amond to application Submittal schedule should include NRC approval prior to issuance of CL Wenci ROSS, D.F. Division of Project Management 80/03/10 53pp
- 8004150001 Notifies that IE Insp Repts 50-455/80-04, 50-446/80-04, 50-445/80-05 & 50-446/80-05 contain no proprietary info GARY.R J Texas Utilities Generating Co 80/03/25 ip
- 8004290521 Forwards addl electrical, instrumentation & control drawings to assist in facility review List of drawing submittals & revision status enc!

 OARY.R J Texas Utilities Generating Co BO/04/(8 19pp
- 8004290634 Forwards addi electrical.instrumentation & control drawings to assist in facility review List of drawings & revision status encl Drawing available in Central Files only GARY.R J Texas Utilities Generating Co 80/04/22 32pp
- 8004300526 Forwards add1 electrics), instrumentation 5 contiol drawings to assist in facility review List of drawings & revision status encl
 CARY, R J Texas Utilities Generating Co 80/04/22 2pp
- F. Security, medical, emergency \star fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr. has been postponed pending GAO clearance under Federal Repts Act
 ORIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004090053 Notification of postponement of 800326 meeting w/util in Bethesda,MD to discuss fire protection criteria for review of facility Heeting will be rescheduled BURWELL.B B Light Water Reactors Branch 2 80/03/14 App
- G Adjudicatory correspondence
- 8004040088 Response in opposition to Citizens for Fair Util Regulation B00219 request for order requiring NRC to provide documents re change of position & for postponement of prehearing Rationale of position undiscoverable M/Certificate of Bvr REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 80/03/04 Spp
- 8004080221 Response in apposition to Citizens Association for Sound Energy 800225 request for order compelling production of documents & for postponement of prehearing conference Cartificate of Syc encl REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 80/03/04 Spp
- BOD4080726 Forwards NRC statement of position on admissibility of TX Association of Community Organizations for Reform Now contentions, re parties 800319 conference call OM Gay will be contacted on 800404 re applicant & NRC stipulations ROTHSCHILD, M U Hearing Branch 1 80/03/27 1p
- 8004090015 Forwards statement reflecting NRC views on admissibility of Citizens for Fair Util Regulation contentions per 800317 telcon NRC will contact intervenor on 800402 re compliance w/ABLB 800319 order W/o encl ROTHBCHILD, M U Hearing Branch 1 80/03/28 2pp
- 8004090018 Forwards statement reflecting NRC views on admissibility of Citizens Association for Bound Energy contentions per 800319 telcon NRC will contact intervenor on 800404 re compliance w/ABLB 800319 order W/o encl ROTHCHILD,M U Hearing Branch 1 60/03/28 2pp

- 8004030026 Memorandom or understanding metween NRC ? FEMA re prompt improvement in radiological emergency planning * preparedness, distributed at Miard notification GOSSICKL V Office of the Executive Mirector for Operations BO/04/02 34pp
- G004210424 Rept re position on admissibility of intervenors'contentions per ASLB 800319 order scheduling 800430 prehearing conference Notices of SA Treby & SE Turk appearance. LJ Chandler withdrawall & Certificate or Sv. encl ROTHSCHILD.M M , TURK.S. E. Hearing Branch (80/04/10 101pp
- BO0425034B Confirms 80040B telcon re Tx Association of Community Organizations for Reform Now position re NRC % applicant proposed stipulation covering intervenor contentions NRC position will address contentions as negotiated ROTHSCHILD.() U Hearing Branch 1 80/04/10 1p
- 8004240421 Notion for approval of 800410 stipulation executed by NRC, applicants & Citizens for Fair Util Representation, reintervenor contentions Parties' positions are stated in 800410 repts filed per ABLB 800319 order ROTHSCHILD, (I U Hearing Branch 1 80/04/22 2pp
- ---8004240424 Stipulation renumbering / rewording Citizens for Fair Utils Regulation contentions Supersedes * supplements intervenor 790507,0529 % 1031 motions to intervene * suppls Stipulated statement of intervenor contentions end; FOUKEIR L Citizens for Fair Utility Regulation ROTHSCHILD, M U Hearing Branch L REYNOLDS, N S Texas Utilities Generating Co 80/04/10 lipp
- --8004240433 Response stating no objection to Citizens Association for Sound Energy 800411 request for extension until 800411 to file motion for consideration of Contention 8 * to file position on contentions Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 80/04/22 2pp
- H General correspondence
- 8004240428 Forwards 800221 Itr from TX Senator R Clower w/encl Itr from constituent MW McMutt Requests pertinent info to answer constituent fears of cancer from low level radiation exposure DENISEN, L Senate 80/03/05 3pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004160237 Forwards Amend 10 to FSAP Affidavit encl GRAY,R J Texas Utilities Generating Co 80/03/31 2pp
- --8004160243 Amend 10 to F5AR Gversize drawings enci * Texas Utilities Generating Co 80/03/31 1400pp
- 8004220426 Forwards affidavit of sic for FSAR Amend 10 GARY, R. J. Texas Utilities Generating Co. 80/04/14 Gpp
- M Antitrust correspondence
- 80040202000 Response to Central & South West Corp et al second request for production of documents Stagg Sys Inc workpapers available for insp & copying Documents re transactions already produced Certificate or Svc encl COPELAND, J G Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/02/25 App
- BOO4040072 Notice of appearance in proceeding Certificate of Svc encl FABRIKANTIR Justice Dept of 80/02/25 4pp
- 8004110030 Discusses add1 request for documents located in Chalter personal files Request is untimely & deficient feiling to specify relevancy to proceeding No obligation to respond to request by 800227, per Commission Rules of Piactice STANL, D M Isham, Lincoln & Beale 80/02/25 2pp
- 8004020149 Forwards DOJ 2 NRC 800228 joint motion for mod of ASLB order re-settlement discussions 2 for issuance of order to compal production of certain documents 2 testimony Proposed order encl CYPHERT, 8 A Justice, Dept of CHANANIA, F.D. Antitrust Division 80/02/28 4pp
- --8004020164 Joint motion for mod of ASLB 790416 order re protection of aettlement discussions & fai issuance of older to compal production of documents & testimony from Houston Lighting & Power & TX Utils W/Certificate of Svc CYPBERT.S B . DDPSUVIC.D A Justice. Dept of CHANANIA.F D Antitrust Division 60/02/28 120pp

- --8004020175 Gral deposition of ED Scarth te certification of questions Pp 2-8
 * Atomic Safety and Lirensing Board Panel SCARTH/E D
 Affiliation Unknown 60/08/22 7pp
- --- 8004020181 Motion to compel Tk Utils Cos to supplement Apr & Jul 1979 responses to first set of internogatories & requests for production of documents Urges performance of current new obligations by 800780 A/Certificate of Sec & proposed order CYPHEGI.S B LUQUE.h Justice: Dept of 80/02/28 7pp
- --8004020190 Motion to compel Houston Lighting & Power to supplement 790111 % 0427 answers to 701122 interrogatories Organ fulfillment of current obligations arising from development of new info Certificate of Svc / proposed order encl CYPHERT, S.B., LUQUE, N. Justice, Dept of 80/02/28 7pp
- --8004020198 Joint application for issuance of subpoena directed to ED Scarth of TX Utils Generating Co.) DF Simmons of Houston Lighting 7 Power Requests extension until 800402 to depose DE Simmons Draft subpoenas 7 Certificate of Svc encl CYPHERT, S D. DDESOVIC, D.A. Justice, Dept of BLUME, M. Antitrust Division ROVID/288 200 80/02/28 700
- 8004020098 Motion for protective order re disclosure of Diamond Shamrock Corp documents, 2n response to ASLB 800118 subpoend duces tecum Documents in question are sub, of contractual obligations Certificate of Suc & proposed order enci CYPHERT.S B Justice.Dept of 80/02/29 10pp
- 8004080174 Notifies of change of address for counsel of South TX Electric Cooperative Inc. & Medina Electric Cooperative Inc. effective 800310 Akin, Gump, Hauer ' Feld 80/03/04 1p
- 8004100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative Inc & Medana Electric Cooperative Inc neither initiated nor received any discovery requests Certificate of SVE ENCT JOHN, D. F. Akin, Gump, Haver & Feld 80/03/04 4pp
- 8004110574 Confirms 800229 Felcon re DDJ subpoena of documents from Gulf States Utils Subpoena covers certain areas also covered in Grounsville Public Utils subpoena Util documents will be available to all parties RADERIR M. Conner, Moore / Corber 80/03/04 2pp
- 8004080859 Requests pretrial converence to clarify procedural matters re ASLB 791214 order, filing testimony summaries & designation of trial exhibits CYPHERIS B Justice, Dept of CHAMANIA.F D Antitrust Division RITTS.F H Telas-Louisiana Electric Cooperative, Inc. 80/03/05
- 8004090204 Discovery rept for Feb 1980 Deposed W Taylor, M Hebb, DE Simmons 5 El Hatson Participated in depositions noticed by TX-LA Electric Cooperative 5 City of Brownsville, TX Reviewed Diamond Shamnock documents Filed application for subpoemas CYPHERT, S B . PARMENTER, F H Justice, Dept of 80/03/05 Spp
- 8004070387 Discovery rept for Feb 1980 Participated in A Gerber,M Hebb, E Simmons,V Robertson & GW Beams depositions Attended J Turk. & S Phillips depositions Filed motion for additime to respond to TX Utils interrogatories W/Certificate of Svc CARNEY,J A Central & Southwest Corp CARNEY,J A Isham, Lincoln & Beale 80/03/05 7pp
- 8004110056 Response to Houston Lighting & Power 800219 motion to compel interrogatory answers by DGJ re C Stover proposed expert testimony DGJ has no additioned to provide except for facts stated in this response M/Stover ltr & Certificate of Svc CYPHERT, S B Justice. Nept of 80/03/05 App
- 8004030344 Comments by Public Utils Board of City of Brownsville,TX on NRC & DOJ motion for mod of AELB order re protection of settlement discussions & rol order to compel documents & testimony Urgss clarification of scope U/Certificate of Svc POIRIER,M R Texas, State of 80/03/06 18pp
- 8004080273 Response in opposition to DOU & NRC joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents Negotiations for settlement purposes are protected from discovery per case law & per rules SDUMNIGHT, J & Houston Lighting & Power Co + Baker & Botts + Lowenstein, Newman, Reis, Arelrad & Toli NRC 80/03/06 15pp
- --8004080285 Response seeking dismissal of DUJ 800228 motion to campel supplementation of interrogatories, as most Answers were served one day prior to this motion Addl suppl will be filed if further responses are appropriate W/Certificate of Svc FRANKLIN.W J Houston Lighting & Power Co * Baker & Botts * Lowenstein.Newman.Reis.Axeirad & Toll 80/03/06 App

- 8004080360 Response in opposition to DBJ & NRC joint motion for mad of ASLB order re-settlement discussions & for order to compel production of documents NRC policy favoring settlement is designed to protect sources involved W/Certificate of Svc Central & Southwest Corp # Isham, Lincoln & Beale 80/03/04
- 8004080638 Response in opposition DDJ & NRC 800228 joint motion for mod JANGUIGHE RESPONSE IN OPPOSITION DUTY AND SOURCE JUING MOTION FOR MOU OF ASLED Order to settlement discussions & for order to compel production of documents Negotiations must be protected per Rule of Fridence 408 W/Certificate of Svc AHEARN, C D Teras Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/06 30pp
- 8004090185 Notice of appearance on behalf of Public Utils Board of City of Brownsville.TX, in consolidated discovery Certificate of Svc encl SPIEGEL.G Texas, State of SPIEGEL.G Spiegel & McDiarmid 80/03/06 App
- 8004090434 Discovery rept by Public Utils Board of City of Brownsville, T.A. for Feb 1980 Disposed M Borchelt or Central Power & Light Participated in R Edelstein deposition Received documents from Central & South West Corp Certificate of Svc encl POIRIER.M R Texas. State of POIRIER.M R Spiegel & McDiarmid 80/03/06 App
- BOO4100218 Notifies that POJ received Houston Lighting & Power Co supplemental answers to Central Power & light Co first interrogatories w/o apps Requests Attachment A to Houston Power & Light Co second set of add1 answers to NRC CYPHERT. S B Justice. Dept of 80/03/06 1p
- BO04100433 Notice of appearance of G Spiegel on behalf of Public Utils Commission of Brownsville.TX Centificate of Svc encl SPIEGEL G Brownsville.TX SPIEGEL,G Spiegel & McDiarmid BO/03/06 6pp
- 8004100595 Discovery rept for Jan & Feb.1980,City of Austin has neither initialed nor received any discovery requests BALDUOH,R C Austin, TX 80/03/07 5pp
- 8004080044 Response by Public Utils Board of City of Brownsville,TX, in apposition to Central & Southwest Corp 800222 motion for protective older re-second set of interrogatories & production of documents W/Certificate of Svc & 800207 ltr POIRICE M R Texas, State of POIRIFR M R Spiegel & McDiarmid 80/03/10 12pp
- 8004100514 Forwards notice of taking of deposition of D Springs AHEARN C D Debevoise & Liberman 80/03/10 1p
- --B004100525 Notice of taking of deposition of D Bprings on B00313-14 in Atlanta, GA Deponent will be examined on matters re bulk power supply & transmission ** wheeling svcs in TX Certificate of Svc encl AHEARN: C D Texas Utilities Generating Co AHEARN: C D Debavoise & Liberman B0/03/10 Spp
- B004110169 Notifies that W Scott deposition scheduled for Mar is cancelled Cancellation based on DOJ representation that Scott would be called as expert withness BALDHIN.J M Baker & Botts B0703/10 Spp
- BCC4080018 Updated response to first set of interrogatories & document requests includes info re witnesses, competitive utils, product & geographic market & petitions to intervene Prof qualifications of DA Springs : Certificate of Svc encl BURCHETTF.W H Texas-Louisiane Electric Cooperative, Inc BURCHETTE.H H Northcutt Fly 80/03/11 29pp
- 8004090164 Second supplemental response to first set of interrogatories & document requests Includes info re projected loads, capacity & reserves as of 800215 SLICKER,F K Texas Utilities Co SLICKER,F K Worsham, Forsythe & Sampels 80/03/11 Spp
- 8004090175 Supplemental response to thild set of interrogatories & document requests Supplemental answer to Interrogatory 18 encl (//o encl SLICKER.F K Texas Utilities Co SLICKER.F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004090180 Supplemental response to first set of interrogatories & document requests Includes info re monthly fuel cost adjustments for 1979
 8LICKER: FK Texas Utilities Co SLICKER: FK Worsham, Forsythe & Sampels 80/03/11 4pp

- 8004100084 Forwards DOJ subposes requiring DE Simmons, util vice presidentito testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subposes N/o encl CYPHERT.S B Justice.Dept of 80/03/i1 ip
- 8004100221 Fourth supplemental response to first set of interrogatories & document requests Includes info re cities & utils which have explored power alternatives offered by TX Utils Co SLICKER, FK Texas Utilities Co SLICKER, FK Worsham, Forsythe & Sampels 80/03/11 3pp
- 800403025B Response in opposition to schedule proposed by NRC for reply to motion to quash 800221 subpoena directed to R Frame Merit of NRC argument will be better evaluated after Lerner deposition Suggests 800321 for reply W/Certificate of Svc KNDTTS.J B Texas Utilities Generating Co 80/03/12 5pp
- 8004020113 Forwards Houston Lighting & Power 800313 petition for directed certification of ASLB 800307 order re confidential documents of settlement negotiations 8DUKNIGHT, J.A. Lowenstein, Newman, Reis, Axelrad & Toil 80/03/13-2nd
- --8004020119 Patition for directed certification, interim stay & review of ASLB 800307 order requiring Houston Lighting & Power to produce settlement negotiations documents Urges reversal of ruling W/excerpts of 800307 prehearing transcript BQUKNIGHT, J A. GREEN, D.O. Houston Lighting & Power Co. BOUKNIGHT, J A. Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13
- --8004020122 Order to NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privileged documents Orders responses to majority of questions W/excerpts of 790601 prehearing MILLER, M E Atomic Bafety and Licensing Board Panel 79/04/16 500
- 8004080028 Forwards POJ third supplemental response to Houston Lighting & Power Co first set of interrogatories Documents responsive to util 770204 second set of interrogatories encl Documents respond interrogatories not encl CYPHERT, S B Justice, Dept of 80/03/13 ip
- --8004080033 Third supplemental response to first set of interrogatories & document requests includes info re QT Taylor testimony re four relevant product markets in proceedings
 CYPHERT. 8 B Justice. Dept of 80/03/13 30pp
- 8004080073 Application for issuance of subposes directed to FG Arey of Webster Engineering Corp. to be deposed & to produce documents re interconnections & interconnected sys Braft subposes & Certificate of Svc encl
 GREEN.D O Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Azeirad & Toll 80/03/13 13pp
- 8004090439 Ack receipt of & accepts 800312 itr in lieu of interrogatory enswer per 800307 prehearing ruling LEr dows not solve Houston Lighting & Power problems ro C Stover deposition DOJ 800311 it 12 itrs & Certificate of Svc encl QREEN.D O Lowenstein.Newman.Reis.Axelrad & Toll 80/03/13 10pp
- BOO4100545 Response to third set of interrogatories Includes info re electric power & energy delivered to various utils during Dec 1979 Certificate of Svc enci * Taxas Electric Bervice Co BO/03/13 14pp
- 8004080370 Discovery rept for Feb 1980 Deposed J Wilson, GC Campbell & V Robertson et al Attended DGJ & NRC depositions Berved G00201 first set of interrogatories to NRC Received addl responses to interrogatories Certificate of Svc encl FRANKLIN, W J Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll G0/03/14 7pp
- BOO404007B Comments by Public Utils Board of City of Brownsville, TX, stating no position re consolidation for trial advised by ASLB during BO0307 prehearing If consolidation ordered right of cross-examination must be preserved W/Zertificate of svc POIRIER, M R , POIRIER, M R Texas, State of 80/03/17 7pp
- 8004080153 Statement in apposition to consolidation of proceedings for hearing purposes, per ASLB 800307 prehearing conference request Issues not identical & evidence in South TX Project may not be related to Commanche Peak W/Certificate of Svc STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Beale 80/03/17 7pp

- B004080401 Submits TX Utils Generating Co response to ASLA 800307 request reviews on consolidation of proceedings for hearing purposes Urges complete consolidation KNOTTS, J. B. Debevoise & Liberman 80/03/17 4pp
- B004080563 Order confirming results of 800307 oral argument NRC & POJ joint motion, re-mod of order concerning protection of settlement discussions, granted in part Parties may not engage in further discovery re-documents included in motion OLASER, M.C. Atomic Sarety and Licensing Board Panel 80/03/17
- 8004090427 Discovery tept for Jan-Feb 1980 Participated in M Olymy deposition No discovery requests initiated Certificate of Svc encl BURCHETIC, W H Texas-Louisiana Electric Cooperative, Inc BURCHETIE, W H Northcutt Ely 80/03/19 3pp
- 8004010517 Order denying NRC 800311 motion to quash subposma of R Frame TX Utils Generating Co entitled to tost ND Lerner credibility by questioning work? documents prepared by Frame for Lerner review WOLFE:S J Atomic Safety and Licensing Board Panel 80/03/20 2pp
- 8004030347 Response in apposition to TX Utils Generating Co. Houston Lighting & Pawer Co & South West Corp 800313 petitions for directed centrification of order compelling production of dacuments News article & Certificate of Syc encl CHANAMIA, F D. BLUME, M D. HODGOOM, A P. Antitrust Division 80/03/20 21pp
- 8004108177 Memorandum in opposition to petitions for directed certification filed by TX Utils Generating Co. Houston Lighting & Power Co & Central % South West Corp et al.re ASLB 800307 order Certificate of Svc encl CYPHERT. B B. DOPSOVIC. D A. GLAZIER. K M Justice. Dept of 80/03/20 26pp
- 8004100534 Response to DOJ first set of interrogatories includes info re TX electric cooperatives & wholesale suppliers Cartificate of Syc encl * Texas Electric Service Co 80/03/20 21pp
- BOD4010267 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents BLUME, M B Antitrust Division 80/03/21 200
- 800.4040184 Motion to quash subpoens directed to GW Stagg upon DGJ & NRC joint request Absent evidentiary reliance upon Stagg Sys. Inc work, nontestifying outside consultants are not subj to discovery process, per established rule FRANKLIN.W J Houston Lighting & Power Co 60/03/21 4pp
- --8004040198 Advises that Houston Lighting & Power does not intend to rely on Stagg Sys, Inc. studies as part of defense in proceeding NRC & Central & Southwest Corp contensions re Stagg study based on misconception M/Certificate of Svc GREEN, D. G. Lowenstein, Newman, Reis, Axelrad & Toll 80/03/21 7pp
- 8004160111 Responds to NRC & Central & South West Corp comments re consolidation Severance arguments based on belief that util will rely on skudy by Stagg Sys. Inc as part of defense Util will not rely on Stagg study Certificate of Svc encl GREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/03/21 6pp
- 8004030360 Response by Public Utils Board of City of Brownsville, TX in apposition to nonconsolidation of proceeding suggested by NRC 3 Central 3 South West Corp In event of separation, South TX case should be heard first Centificate of Svc encl SPIECEL. O Texas, State of 80/03/24 9pp
- 8004250049 Response in opposition to Public Utils Board of City of Brownsville.TX 800317 comments requesting admittance as party in consolidated proceeding Statement of interest untimely & vague Certificate of Svc encl AHEARN.C D Texas Utilities Generating Cp AHEARN.C D Debevoise & Libernan 80/03/25 7pp

- BOO4100271 fintion to compal arrifu tion of documents by Southwest TX Electric Cooperative or subpreha directed to general manager & Accionnes Pequests to tribe M Ginnes 2001221 deposition if documents are not produce MVdraft subpoena & documentation GREEN D.G. Houston Lighting * Power Co. * Baker & Botts * Lowerstein/Heuman, Reisericliai * Toll ±0/03/26 (18pp
- ---BO0410027B Notice to compel production or documents by Midwest Electric Cooperative re-subported affected to general manager.

 P Metrel Request- to revie Metrel rescheduled deposition of documents are not produced M subpoema? Certificate of Svc GREEN.D G Houston righting? Power Co & Baker & Botts & Lowenstein, Nowman Reis Apali ad 1 Toll 80/03/26 15pp
- 8004080420 Application for issuance or subpoend directed to Guif States
 Utils Co re-settlement documents Documents not produced in
 response to 790749 & 804118 subpoends Urges production to
 extent allowed by ASLAB
 BLUNE, KB Antitust Division 80403/27 2pp
- --8004080424 Subposes directed to Gulf States Utils Co requesting settlement documents for imap 5 copying in Washington DC on 800402 Subposes amay be quashed or modified upon request Certificate of Svc encl MILLER M E Atomic Sarety and Licensing Board Panel 80/03/27 App
- 8004090126 Order denying Houston Lighting ? Power 800321 motion to quash subpoena discreted to 6W Stagg upon DOJ request Prior rulings, re-nontestifying outside consultants, do not apply in this proceeding due to relevancy of Stagg studies WOLFE.S J Atomic Sefety and Licensing Board Panel 80/03/27 3pp
- 8004210386 Forwards Houston Lighting 3 Power 800327 motions to compel production of documents by NRC expert witnesses RH Hartley & NC Lorner Requests 800371 conference call prior to scheduled depositions
 FRANKLIN N J Lowenstein, Neuman, Reis, Axelrad & Toll 80/03/27 ip
- --8004210392 Motion to compel testimonial questions answered by NRC expert witness RH Hartley Discoverability of questions established on Pages 421-423 of preheating conference transcript re ASLB 800425 order FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowenstein, Neuman, Reis, Aighrad & Toll * Baker & Botts 90/03/27 4pp
- --8004210374 Submits preparation study for 800220-21 meeting re intraregional interconnections, transmission lines & Other pooling matters HARTLEY, R.H. Affiliation Unknown 80/01/29 25PP
- --8004210397 Forwards RH Hartley 8002(i memo to NRC re 800129 answers in preparation for 800220-21 meeting Requests questions to which answers were stated, per rule established in 790601 prehearing conference Pages 421-423 of transcript encl FRANKLIN.W J Lowenstein.Newman, Reis, Axelrad % Toli 80/03/20
- --B004210400 Motion to compel electric util industry testimonial antitrust analyses prepared by NRC expert economic witness N Lerner re Midland proceeding Urges production per prior rulings, subj to enci protective order W/Certificate of Svc FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowenstein, Newman, Reis, Aielrad & Toll * Baker & Botts 80/03/27 14pp
- 8004090123 Order giving parties one white provide addl authority re existence of settlement privilege Memoranda addressing issue should be received by 800404 & response thereto by 800409 BISHOP.C J. Atomic Safety and Licensing Appeal Panel 80/03/28 200
 - 04090456 Protective order, in Favor of Houston Lighting & Power, reconfidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeking judicial review per FOIA WOLFE, S.J. Atomic Safety and Licensing Board Panel 80/03/31 4pp
 - 04100243 Order granting in part NRC motion to compel add1 responses by Houston Lighting & Power (HL&P) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions re RH Hartley testimony AGLFE,S J Atomic Safety and Licensing Board Panel 80/03/31 3pp
 - 04100429 Public Utils Board of Brownsville motion for leave to file affidavit as amicus curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Svc encl pricedly Certificate of Svc encl pricedly Generally Springer & McDiarmid 80703/31 Bpp

- --B004100430 Arridavil of RE Roundtree, general manager of Biownsville Public Utils Board re agreement among T/ "IOUs" for const of two de interstate ties of 500 MM 5/250 MM Brownsville prepared to enter settlement negotilations ROUNDTREE, R E Brownsville, TX 80/03/27 3pp
- 8004090172 Updated response to Houston Lighting & Power second set of interrogatories & TY Util, first set of interrogatories Anticipates RE Corder participation as uitness re areas discussed during Corder deposition Certificate of Svc encl CHANANIA.F D. Antitrust Division 80/04/01 5pp
- 8004100240 Order requesting parties in directed certification proceeding to respond to Utils Board of City of Brownsville, TX 800301 motion by 800409
 BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/04/02
- 800418015; Forwards joint motion for extension of time Motion is joined in by all parties to proceeding except DOJ & City Public Utils Board of Brownsville.TK
 WHOTTS, J.B. Debevoise? Liberman 80/04/02 ip
- ~-8004|80|67 Joint motion for 30~day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotalions which could lead to resolution of part or all of
 proceedings Certificate of Svc encl
 CHANANIA,F D Antitrust Division COPELAND,J G Houston Lighting
 ₹ Power Co STAHL, D M Central Power ₹ Light Co 80/04/02 App
- 8004140007 Third set of addl answers to NRC 790115 initial interrogatories Simmons & Woodson are expected to testify re interconnections
 FRANKLIN, W J Houston Lighting & Power Co & Baker & Botts & Lowenstein, Nowman, Reis, Azelrad & Toll 80/04/03 2pp
- --B00414000B Second supplemental answers to Central Power & Light Co 790223 interrogatories Simmons & Woodson are expected to testing re interconnections Certificate of Svc encl FRANKLINIA J Houston Lighting & Power Co * Baker & Botts * Lowenstein Rewman, Reis, Azelrad & Toll 80/04/03 App
- 8004(50032 Forwards opposition by Brownsville to joint motion for extension of time & request for prehearing conference, miscellaneous atty & ufil correspondence, affidavit & Brownsville rate estimates Certificate of Syc encl
 SPIECEL, G. POIRIER, M.R. Spiegel & McDiarmid 80/04/03 19pp
- --B004150650 Opposition to joint motion for extension of time & request for prehearing conference Brownsville has been excluded from negotiations on which request for extension is based Certificate or Svc encl SPIECEL 9. POTRIER MR Brownsville, TX SPIECEL, 9. Potriegel & McDiarmid 80/04/03 2pp
- BOO4230066 Forwards Houston Lighting & Power 800403 motion to compet production of documents? JW Wilson testimony by Public Utils Board or City of Brownsville, TX Proposes expedited schedule to permit completion of expert witness discovery GREEN. D & Lowenstein, Newman, Rais, Axelrad & Toll 80/04/03 2pp
- ---8004230074 Motion to compel production of documents & JW Wilson expert testimony by Public Utils Board of City of Brownsville, TX
 If motion not granted requests order precluding Wilson from hearing W/proposed order ie schedule & Cartificate of Svc
 BALDWIN. JM Houston Lighting & Power Co * Baker & Botts *
 Lowenstein, Newman, Reis, Axelrad & Toll 80/04/03 11pp
- 8004300126 Memorandum in response to ASLAR 800328 order requesting addit authority to recognition of settlement privilege Courts & case law do not recognize existence of privilege Certificate of Svc entil BLUME.M B : HODODON.A P Antitrust Division 89/04/04 App
- 8004150083 Order setting 600411 conference at NRC Hearing Room.

 Bethesda.MD Oral argument will address NRC & DOJ joint
 motion for 30-day extension b Houston Lighting & Power
 800403 motion to compel Utils Roard of Brownsville
 WOLFE.S J Atomic Safoty and Licensing Board Panel 80/04/04 2pp
- 8004170312 Memorandum of authorities re discoverability of settlement documents Urges reversal of ASLB 800307 ruling due to privilege recognized per case law & federal rules of evidence Supporting documentation & Certificate of Svc encl BOUKNIGHT: J A , GREEN, D G Houston Lighting & Power Co BOUKNIGHT: J A Baker & Botts 80704704 Sipp

- 8004170340 Response stating no position ie joint motion for 30-day extension in proceeding filed by NRC, Central & South West Corp. Houston Lighting & Power, TX Utils Generating Co. City of Austin & other parties Certificate of Svc encl DDPSQVIC, D.A., LUQUE, N., PARMENTER, F. Justice, Dept of 80/04/04 500
- 8004220128 Memorandum of authorities in support of settlement privilege Documents prepared in connection w/settlement pracess should be protected from discovery under work product privilege Certificate of Svc encl STAHL, D Central & Southwest Services, Inc. STAHL, D Isham, Lincoln & Beale 80/04/04 10pp
- B004240043 Consent motion for two~wk extension to respond to Houston Lighting 5 Power Co motion to campel groduction of documents Represents that util consents to extension O'NEILL:R A Southwest Texas Electric Cooperative O'NEILL:R A Miller, Dails & O'Neil 80/04/04 3pp
- 8004240045 Certifies see of consent motions for extension to respond to Houston Lighting & Power Co motion to compel production of documents from Midwest Electric Cooperative & Southwest TX Electric Cooperative on 800404

 O'NEILL.R A Miller, Balis & O'Neil 80/04/04 App
- 8004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compol production of documents Represents util consent to extension O'NEILL:R A Southwest Texas Electric Cooperative O'NEILL:R A Miller:Balls & O'Neil 80/04/04 3pp
- 80042401/3 Memorandum.per ASLAB 800328 request.stating add1 authorities re directed certification of settlement document issue
 Treatises & modern trend hald inadmissibility of privileged documents as evidence Cortificate of Svc enc1
 KMOTTS, J B . AMEARN.C D Texas Utilities Generating Co KNOTTS, J B Debavoise & Liberman 80/04/04 22pp
- 8004290106 Advises of arrangement to deliver Houston Lighting & Power pleadings moving to compol documents to E McGinnes & P Wetzel subpoenas Consents to I-1-day extension for responses Cortificate of Svc encil GREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/04/04 Spp
- 8004100552 Motion to issue order compelling Bouthwest TX Electric Cooperative & general manager & McGinnes to produce, for imp & copying documents set forth in motion Draft subpoena & Certificate of Svc encl GREEN, D O Houston Lighting & Power Co GREEN, D G Baker & Botts 80/04/07 18pp
- --8004100560 Motion to issue order compelling Midwest Electric Cooperative & general manager P Netrel to produce for insp & copying, documents responsive to subpoena served on Wetrel Draft subpoena & Certificate of Svc encl GREEN.D O Houston Lighting & Power Co GREEN.D O Baker & Botts 80/04/07 15pp
- 8004230154 Mution to preclude DOJ from filing principal brief re ASLAB 800328 order DOJ failed to file principal brief by 800404 DOJ seeks to obtain unfair tactical advantage by untimely filing BOUKNIGHT.J A . OREEN.D G Houston Lighting & Power Co BOUKNIGHT.J A . Baker & Botts 80/04/07 3pp
- ---8004230162 Order directing all parties to furnish ASLAB w/addl authority re privilege against discovery of documents Memoranda due on 800404 BIBHDP.C J Atomic Safety and Licensing Appeal Panel 80/03/28
- 8004240061 Motion for ASLE to reconsider extending procedural dates for 30 days Requests 800408 conference call to rule on extention TX Utils Generating Co is only party to be prejudiced by extending dates CHANANIA.F Antitrust Division BOUKNIGHT.J A Houston Lighting & Power Co BURCHETTE.W H Texas-Louisiana Electric Cooperative.Inc 80/04/07 3pp
- --8004240071 Supplemental argument & representations Addl time required by utils to make progress in settlement discussions Discussions began Sept 1977 Parties are optimistic about possibility of reaching quick settlement BURCHETTE, W H Texas-Louisiana Electric Cooperative, Inc KMOTTE, J B Texas Utilities Generating Co 80/04/07 Spp
- 8004210147 Discovery rept for Mar 1980 Deposed JA Bruggeman. JT Wenders, AJ Wood & DA Springs Moved to compel NRC deposition of ND Lerner Responded to DOJ motion to compel supplemental answers to first interrogatories W/Centificate of Svc FRANKLIN. W J Houston Lighting & Power Co FRANKLIN. W J Lowenstein. Neuman. Reis. Areirad & Toll SO/04/08 App

- 8004150157 Response to Houston Lighting & Power, TX Utils Generating Co & Central & South West for 60404 memoranda of authorities no sottlement privilege Higes affilmation of ASLB 800307 order to production of documents M/Colfiblicate of Svc CHANANIA F D. HUNGDON, A P. Antitust Division 80/04/09 10pp
- 8004170347 Response to Public Utils Board of City of Brownsville.TX 800331 motion to rile RE Roundtree afridavit as amicus curiae Disclosure of documents should not affect potential for settlement Certificate of Scenci CHANANIA:FD Antitiust Division 80/04/09 6pp
- 8004226031 Response to Public Utils Bhard of City of Brownsville, TX 800331 motion to rile Roundtiee effidavit Requests to file counter-affidavit, re status or setilement, if Roundtree affidavit is accepted by ASLAS Certificate of Svc enc) KNOTTS, J 8 Texas Utilities Generating Co 80/04/09 App
- 8004220152 Response to Houston Lighting & Fower 800409 motion to compel production of documents % deposition of Public Utils Board of City of Brounswiller (TX Poes not oppose motion if subj to enci protective order Apparance & Certificate of Svc enci ROTH, A.J., JACOBS, J.C. Florida Cities ROTH, A.J. Spiegel & HcDiarmid 80704707 ldpp
- 8004240562 Response in opposition to NRC 800404 memorandum of addl authorities is existence of setflement documents privilege Congress did not intend to ricese developing law of privilege W/Certificate of Svc KNOTTS, J B., AHEARN, C P. Teras Utilities Generating Co. KNOTTS, J D Debevoise A Liberman. 60/01/09 Gpp
- 8004170351 Order granting 30-day entonsion for procedural matters, amending ASLB 791214 order to discovery schedule 5 directing consolidation of proceedings for proteinal 5 evidentiary hearings Consent motions for extension to 800404 granted MILLER, M E Atomic Safety and Licensing Board Panel 80/04/10 Son
- BO04210141 Order denying Houston Lighting * Power motion seeking to preclude DOJ memorandum of addit authorities filed per ASLAB BO0328 order
 BISHOP, C. J. Atomic Barety and Licensing Appeal Panel 80/04/10 200
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Fikar requested during 800409 oral argument KNOTTS.J B Debevoise & Liberman 80/04/10 tp
- ---B004230041 Affidavit stating that Central & South West Corp. Houston Lighting & Power Co & TX Utils Co Sys have reached agreement in principle re interconnection disputes Agreement may form basis for discussions w/other parties W/Certificate of Syc FIKAR, L F Texas Utilities Generating Co B0/04/10 Spp
- BOO4230002 Responds to Public Utils Doard of City of Brownsville, TX opposition to joint motion for extension of time Objects to alleged refusal to wheel 'submits IL Borchelt affidavit in response to alleged exclusion from discussions STAHL, D.M. Central's Southwest Corp. STAHL, D.M. Jeham, Lincoln & Beele 80/04/11 3pp
- ---8004230007 Affidavit responding to Public Utils Board of City of Brownsville, TX allegation that Brownsville has been excluded from discussions re interconnection Clarifies statement made at B00327 meeting Certificate of Svc ancl BORCHELT, M. L. Carolina Power / Light Co. 80/04/10 10pp
- 8004270227 Discovery rept for Mar-Apr 1780 Participated in FJ Meyer, HH Waddson & GN Stage depositions Filed opposition to petitions for directed cortification & reversal of ABLB 800307 order Joined other parties in moving for procedural extension CHANANIALF D., BLUME, M.B., HÖDODON, A.P. Antitrust Division 80/04/25 3pp
- N Antitrust hearing transcripts
- 8004030346 Pages 690 % 691 ommitted from original transcript * Commission 80/03/07 3pp
- 800415029B Transcript of 800409 hearing in Bethe>da.MD Pp 1-140 # Commission 80/04/09 140pp
- Q Inspection reports. IF Bulletins 3 correspondence
- 8004010147 Responds to JE Bulletin 79-28, "Possible Malfunction of NAMCO Model EAISO Limit Switches at Elevated Temps" Requests extension until 800331 to inspect safety-related equipment & implement necessary corrective actions GARY, R J Texas Utilities Generating Co 80/01/23 ip

- BOO4270492 Discussor IE Insp Repts 50-445/80-01 & 50-446/80-01 on BOO18 & rangers notice of violation SFIDLE, H C Region 4, Italias, Reactor Construction & Engineering Support British Region 4, Pall 24 Page 100 Page 100
- --8004290498 Notice or violation from inspirent S00118 Noncompliance noted procedures for securing Class IE battery chargers inappropriate fillet welds too small due to mat! thickness a Region 4, Ballas, Reactor Construction & Engineering Support Branch HO 01/2 1 p
- 800416004) Forward: IF Insp Repts 50-445/80-05 & 50-446/80-05 on 800214-15 17 21 No norrompliance noted SEIDLE, N.C. Region 4. Pallat. Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004160050 lE Into Repts 50~445/80~05 * 50~446/80~05 on 800214~15 & 19~21 No noncompliance noted Major areas inspected followup review or Unit 1 RCPB pring welding % of QA/QC records re Unit 2 containment blys structural Concrete installations HALL R C Region 4. Dallas. Reactor Construction & Engineering Support Branch CRESCMAN.UA , TAPIA.J I Region 4. Dallas. Office of the Director 80/02/28 5pp
- 8004210175 Forwards IF Insp Repts 50-445,80-06 / 50-446/80-06 on B00220-21 Nn noncompliance noted MADSEN G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/29 ip
- --8004210179 IE Insp Repts 50-445/80-06 & 50-446/80-06 on B00220-21 No noncompliance noted Major areas inspected preoperational testing, GA & operational staffing WESTERMAN, T.F.: SMITH R. Region 4. Dallas, Office of the Director B0/02/29 5 ps
- 800422023? Forwards IE Insp Repts 50-445/80-04 & 50-446/80-04 on 800211-15 No noncompliance noted SEIDLE W C Region 4. Pallas, Reactor Construction & Engineering Support Branch 80/02/27 Jpp
- --8004220244 IE Insp Repts 50-445/80-04 to 50-445/80-04 on 800211-15 No noncompliance noted Major aleas inspected procedures for controlling changes to approved design documents HALE.C J. CROSSMAN.W A. BRICKLEY.R H. Region 4. Dallas. Vendor Inspection Branch 80/02/28 8pp
- 8004210432 Advises that numbers of inspirepts transmitted by 800229 ltr should be corrected to read 50-445/80-06 & 50-446/80-06 MADSEN G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/03/10 ip
- --8004210443 Forwards IE Insp Repts 50-445/80-06 & 50-446/80-06 on 800220-21 No noncompliance noted MADSEN, G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/29 ip
- --8004210438 JE insp Repts 50-445/80-05 & 50-446/80-05 on 800220-21 No noncompliance noted Major areas inspected preoperational testing, GA & operational staffing WESTERMAN.T F Region A. Dallas, Reactor Operations Nuclear Support Branch SMITH.R Region A. Dallas, Office of the Director 80/02/29 Spp
- 8004040081 Ack receipt of 800305 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-03 & 50-445/80-03 SEIDLE-W C Region 4. Dellas, Reactor Construction & Engineering Support Branch 80/03/11 ig
- --8004040063 Responds to NRC 600207 IE insp Repts 50-445/80-03 & 50-446/80-03 Corrective actions engineering personnel reviewed cable lubrication requirements w/key const personnel involved w/cable pulling GARY.R J Teras Utilities Generating Co 60/03/05 3pp
- 8004040098 Ack receipt of 600220 ltm informing NRC of steps taken to correct violations noted in IE Insp Rept 50-445/79-31 & 50-446/79-29 SEIDLE, W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/03/11 lp
- 8004040101 Responds to NPC 800127 IE Insp Repts 50-445/77-31 & 79-446/79-29 Corrective actions tackwelds removed. General Piping & Welding Procedure CP-CPM-6 7 revised & reorganized GARY.R J Texas Utilities Generating Co 80/02/20 3pp
- 8004250079 Forwards iE Investigation Repts 50~445/80~02 & 50~446/80~02 on 800121~0205 No noncompliance noted SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/03/20 2pp

- --8004250093 IE Investigation Repts 50-445/80-02 & 50-446/80-02 on 800121-0205 No noncompliance noted Major areas inspected allegations re law QC procedures, welding problems & weld defects CROSSMAIN, W A . GLBERT, L D . HALL, R E Region 4, Dallas, Office of the Director 80/03/18 7pp
- 8004240225 Forwards IE Into Notice 80-14, "Safety Suggestions From Employees" No artion required SEYFRIT.X V Region 4. Dallas, Office of the Director 80/04/02 to
- 6004220320 forwards IE Circular 80-07. "Problems W/HPCI Turbine Dil Sys " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/03
- 8004220779 Forwards IE Rulletin 79-03A "Longitudinal Weld Defects in ASME SA 312. Type 304 Stainless Steel Pipe " Action required SEYFRIT.K V Region 4 Dailas, Orrice of the Director 80/04/04 ip
- BO04220208 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds" Written response required SEYFRIT, X V Region 4. Dailas: Office of the Director BO/04/07 in
- S Reportable occurrences, LERs & related correspondence
- G004010295 Forwards deficiency rept re control board welded connections GARY,R J Texas Utilities Conerating Co B0/03/21 ip
- --8004010297 Deficiency rept on 800228, GA inspreaded control board welded connections not meeting seismic design criteria Cause unstated Control board suppliers & AE reviewing as-built weld configurations Rework will be completed by 800501 * Teras Utilities Conerating Co. 80/03/21 2pp
- 8004150199 Forwards deficiency rept re control board welded connections GARY:R J Texas Utilities Generating Co 80/03/21 ip
- --8004150202 Deficiency rept re control board weided connections
 Specified 8-inch spacing of welds from end to end was found
 to vary from sixteen to eighteen inches on several panels
 As-built weld configurations under review
 * Texas Utilities Generating Co 80/03/21 2pp
- B004010276 Forwards rept of actions taken to correct deficiencies in mfg of discs for svc water control valves Supporting documentation is available at site for inspector review GARY.R J Toyas Utilities Generating Co 80/03/25 2pp
- 8004070278 Supplemental RD violation found re piping min wall thickness Cause unstated Engineering roview in progress Progress rept will be submitted by 800418 OARY.R J Teras Utilities Generating Co 80/03/28 1p
- 8004220423 Interim deficiency rept re piping min wall thickness Review of weld & base metal repair records is continuing Another progress rept will be submitted by 800620 GARYR J Texas Utilities Generating CO 80/04/15 ip
- E004270250 Forwards deficiency rept re concrete honeycomb condition encountered in steam generator compartment walls of Unit 2 reactor containment bldg OARY:R J Teras Utilities Generating Co 80/04/21 1p
- --8004290254 Deficiency rept re concrete honeycombing in steam generator compartment walls of Unit 2 reactor containment bldg Consultant survey showed no critical internal defects Util to repair 'condition w/dry-pack mortar-grout & concrete Texas Utilities Generating Co 80/04/21 3pp
- 8004270271 Interim deficiency rept re installation of drilled-in expansion anchors Matter was corrected 790616 by revision to installation procedure Formal rept to be filed by 801215 GARY.R J Foxas Utilities Generating Co
- 80042704il Provides status of interim deficiency rept re installation & insp requirements for Class V non-nuclear safety-related piping supports Final rept will be forwanded by 800715 OARY.R J Texas Utilities Generating Co 80/04/21 lp
- 8004270430 Forwards interim deficiency rept re installation & insp of welded conduit supports Final rept to be filed by 800801 GARY.R J Texas Utilities Generating Co 80/04/21 ip

- --8004290437 Interim deficiency rept re installation & insp of welded conduit supports Major support was fabricated w/o formalized instructions & insp records for number of smaller weided supports were not directly traceable to as-built conditions GARY,R J Texas Utilities Generating Co 80/04/21 1p
- T Hearing transcripts on non-antitrust matters
- 8004210312 Transcript or 800327 hearing in Bethesda, MD Pp 1-127 * Atomic Safety and Licensing Appeal Panel 80/03/27 130pp
- DOCKET 50-446 COMANCHE PEAK STCAM ELECTRIC STA .UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Clectrical Equipment," providing guidance re methods for campliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 Spp
- B00423005B Requests into re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident into should be provided as amend to application Bubmittal schedule should include NRC approval prior to issuance of OL W/encl ROBB.D F Division of Project Management 60/03/10 53pp
- 8004150001 Notifies that IE Insp Repts 50-495/80-04, 50-446/80-04, 50-445/80-05 & 50-446/80-05 contain no proprietary info GARY, R J Texas Utilities Generating Co 80/03/25 1p
- 8004270921 Forwards add) electrical, instrumentation & control drawings to assist in facility review List of drawing submittals & revision status encl
 OARY,R J Texas Utilities Generating Co 80/04/18 19pp
- B004270634 Forwards add! electrical, instrumentation & control drawings to assist in facility review List of drawings & revision status encl Drawing available in Central Files only QARY,R J Texas Utilities Generating CO B0/04/22 32pp
- 9004300526 Forwards add1 electrical, instrumentation & control drawings to assist in facility review List of drawings & revision status encl
 OARY.R J Texas Utilities Generating Co 80/04/22 2pp
- f Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 9AO clearance under Federal Repts Act
 ORIMES, B K Emergency Preparedness Task Force 80/03/i1 4pp
- 8004070053 Notification of postponement of 800326 meeting w/util in Bethesda,MD to discuss fire protection criteria for review of facility Meeting will be rescheduled BURMELL.8 8 Light Water Reactors Branch 2 80/03/14 App
- 9 Adjudicatory correspondence
- 8004040088 Response in opposition to Citizens for Fair Util Regulation 800219 request for order requiring NRC to provide documents re change of position & for postponement of prehearing Rationale of position undiscoverable W/Certificate of Svc REYNOLDS,N 8 Texas Utilities Generating Co REYNOLDS,N 9 Debevoise & Liberman 80/03/04 Spp
- 8004080221 Response in opposition to Citizens Association for Sound Energy 800225 request for order compelling production of documents & for postponement of prehearing conference Certificate of Svc encl REYNOLDS.N.8 Texas Utilities Generating Co REYNOLDS.N.8 Debevoise & Liberman 80/03/04 Spp
- 8004080726 Forwards NRC statement of position on admissibility of TX Association of Community Organizations for Reform Now contentions, re-parties 800319 conference call GM Gay will be contacted on 800404 re-applicant t NRC stipulations. ROTHSCHILD, M U Hearing Branch 1 80/03/27 ip

- 800-4090015 Forwards statement reflecting NRC views on admissibility of Citizens for Fair Util Regulation contentions per 800317 telcon IRC will contact intervenor on 800402 re compliance w/ASLB 800319 order W/o encl ROTHSCHILD.M U Hearing Bianch 1 80/03/28 2pp
- 8004090018 Forwards statement reflecting NRC views on admissibility of Citizens Association for Sound Energy contentions per 800319 telcon NRC will contact intervenor on 800404 re compliance w/ASLD 800319 order W/o enc! ROTHCHILD.M U Hearing Branch 1 80/03/28 2pp
- GOO4030026 Memorandum of understanding between NRC & FEMA is prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- BOO4210424 Rept re position on admissibility of intervenors'contentions per ASLB 800319 order scheduling BOO430 prehearing conference Notices of SA Troby & SE Turk appearance. LJ Chandler withdrawal & Certificate of Svc enc) RØTHSCHILD,M M . TURK, S & Hearing Branch 1 80/04/10 101pp
- 8004250348 Confirms 800408 telcon re TX Association of Community Organizations for Reform New position re NRC & applicant proposed stipulation covering intervenor contentions NRC position will addiess contentions as negotiated ROTHSCHILD.N U Hearing Branch 1 80/04/10 tp
- BOO4240421 Motion for approval of BOO410 stipulation executed by NRC, applicants & Citizens for Fair Util Representation, reintervenor contentions Parties' positions are stated in BOO410 repts filed per ASLB BOO319 order ROTHSCHILD, M U Hearing Branch (BO/04/22 2pp
- --8004240424 Stipulation renumbering & fewording Citizens for Fair Utils Regulation contentions Supersedes & supplements intervenor 790507, 0527 & 1031 motions to intervene & supple Stipulated statement of intervenor contentions enci FOUME.R L Citizens for Fair Utility Regulation RDTHSCHILD, M U Hearing Branch 1 REYNDLDS, N S Texas Utilities Generating Co 80/04/10 11pp
- ---8004240433 Response stating no objection to Citizens Association for Bound Energy 800411 request for extension until 800411 to file motion for consideration of Contention 8 & to file position on contentions Certificate of Svc encl ROTHSCHILD, M V Hearing Branch (80/04/22 2pp
- H General correspondence
- 8004240428 Forwards 800221 itr from TX Senator R Clower w/encl ltr from constituent MN McNutt Requests pertinent info to answer constituent fears of cancer from low level radiation exposure BENTSEN.L Senate 80/03/05 3pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B004160239 Forwards Amend 10 to FSAR Affidavit ancl QRAY,R J Teras Utilities Generating Co 80/03/31 2pp
- --B004160243 Amend 10 to FSAR Oversize drawings encl * Texas Utilities Generating Co 80/03/31 1400pp
- 8004220426 Forwards affidayit of svc for FSAR Amend 10 GARY.R J Texas Utilities Generating Co 80/04/14 3pp
- M Antitrust correspondence
- 800402020B Response to Central & South West Corp et al second request for production of documents Stage Sys Inc workpapers available for insp & copying Documents re transactions already produced Certificate of Syc encl COPELAND, J & Houston Lighting & Power Co COPELAND, J & Baker & Botts 80/02/25 App
- 8004040072 Notice of appearance in proceeding Certificate of Svc encl FABRIMANTAR Justice Dept of 80/02/25 4pp
- BOO4110030 Discusses addl request for documents located in Chalker personal files Request is untimely & deficient, failing to specify relevancy to proceeding No obligation to respond to request by BOO227, per Commission Rules of Practice BTAHL.D M Isham. Lincoln & Beale 80/02/25 2pp

- 3004020149 Forward, FOJ / NAC Er3228 joint motion for mad of ASLB order re-settlement discussions f for issuance of order to compet production of certain incurents f testimony Proposed order
 - CYPHERI,S B Justice, Rept of CHANAMIA, F D Antitrust Division 80/02/28 4ps
- 8004020164 foint notion for mid of ASLB 790416 order to protection of settlement discussions? For insuance or order to compel production or secument, ? restimony from Houston Lighting & Power ! TX Utils & Certificate of Svr CypBERT, S. B. COPPOVIC F. A. Justice Dept of CHANANIA. P. D. Antitrust Division 60702/08 120pp
- ~~8004020175 Dial jeposition of ED Starth re certification of questions
 - rp 2-5 4 Atomic Safety and Licensing Board Panel SCARTH, E.D. Affiliation Unknown 80/02/22 9pp
- --800402018) Notion to compel Tx UF:13 Cos to supplement Apr & Jul 1979 responses to first set or interrogatories & requests for production of documents tiges performance of current new obligations by 800300 M.Centificate of Svc & proposed order CYPHERT, S B LUQUE, N Justice, Dept of 80/02/28 7pp
- ~8004020190 Motion to compel Houston Lighting © Power to supplement 790111 & 0427 answers to 781122 interrogatories Urges Fulfillment of current obligations arising from development of new into Certificate of Sic & proposed order enci CYPHERT, S.B., LUJUE, N. Justice, Dept of 80/02/28 7pp
- --8004020198 Joint application for issuance of subpoena directed to ED Scarth of TX Utils Generating Co # DE Simmons of Houston Lighting & Power Requests extension until B00402 to depose DE Simmons Draft subpoenas & Certificate of Svc entil CYPHERT, S B . DOPSOVIC, D A Justice, Dept of BLUME, M Antitrust Division 80/02/28 7pp Division
- B00402009B Motion for protective order re disclosure of Diamond Shannack Corp documents in response to ASLB 80011B subposna duces tecum Documents in question are subj of contractual obligations Certificate of Svc / proposed order encl CYPHERT.S B Justice Dept of 80/02/29 10pp
- BO04080174 Notifies of change of address for counsel of South TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc. effective B00310 Akin, Gump, Haver & Feld 80/03/04 ip
- 8004100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative. Inc 3 Medina Electric Cooperative. Inc meither initiated nor recoived any discovery requests Certificate of Svc encl JOHN, D.F. Akin, Gump Hauer & Feld 80/03/04 App
- BOO4110974 Confirms BOO279 telcon re DOJ subpoena of documents from Gulf States Utils Subpoena covers certain areas also covered in Brownsville Public Utils subpoena Util documents will be available to all pattics RADER.R M Councer. Moore ! Corbet BO/03/04 2pp
- 8004080959 Requests pretrial conference to clarify procedural matters re ASLB 791214 order filing testimony summaries to designation of trial exhibits CYPHERT. S B Justice. Dept of CHAMANIA. F D Antitrust Division RITES. F H Texas-Louisiana Electric Cooperative Inc. 80/03/05
- 8004090E04 Discovery rept for Feb 1980 Deposed W Taylor,M Hebb.DE Simmons & FL Watson Participated in depositions noticed by TX-LA Electric Coopsiative & City of Brownsville.TX Reviewed Diamond Shamrock documents Filed application for subpoenss CYPHERT.S B , PARMENTER F H Justice.Dept of 80/03/05 5pp
 - 04090387 Discovery rept for Feb 1980 Participated in A Gerber M Hebb, E Simmons V Robertson & GN Beams depositions Attended J Turk & S Phillips depositions Filed motion for add1 time to respond to TX Utils interrogatories W/Certificate of Svc ZARNEY, J A Central & Southwest Corp CARNEY, J A Isham, Lincoln & Beale 80/03/05 7pp
- 8004110054 Response to Houston Lighting ? Power 800219 motion to compel interrogatory answers by 00J re C Stover proposed expert testimony DOJ has no aidi info to provide except for facts stated in this response MyStover ltm ? Certificate of 8vc CYPHERT,S B Justice. Dept of 80/03/05 8pp
- 8004030344 Comments by Public Utils Board of City of Brownsville,TX on NRC & DOJ motion for mod of ASLB order re protection of settlement discussions & for order to compel documents & testimony Urges clarification of scope M/Certificate of Svc POIRIFR.M R Teras. State or 80/03/04 18pp

- 8004080273 Response in opposition to DOJ tiRC joint motion for mod of ASLB order to settlement discussions & for order to compel production of documents Negotiations for settlement purposes production of occuments regulated as for sectionary purposes are protected from discovery per case law & per rules
 50UMNIGHT J # Houston Lighting ' Power Co * Baker & Botts
 Lovenstein, Newman, Reis, Arelrad & Toll MRC 89/03/06 15pp
- --8004080285 Response secking dismissal of DOJ 800228 motion to compel DIANUSCIAD Response secting dismissal of DAD BUCKER motion to a supple-nentation of interiogatories, as most Answers were served one day pilor to this motion Add! suppl will be filed if further responses are applicate WiCertificate of Svc FRANKLIN, U. Houston Lighting & Power Co. * Baker & Bott: Lowenstein, Newman, Reis: Arelrad & Toll 80/03/06 App
- 8004080360 Response in opposition to DBU % NRC joint motion for mod of ASLB order re-settlement discussions % for order to compel production of documents NRC policy favoring settlement is designed to protect sources involved M/Certificate of Svc * Central * Southwest corp * Isham, Lincoln & Beale GO/03/06
- 8004080638 Response in opposition DOJ & NRC 800228 joint motion for mad of ASLN order re-settlement discussions & for order to compel production of documents Negatiations must be protected per Rule of Evidence 408 W/Certificate of Svc AHEARIA, C D Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/06 30pp
- 8004070199 Notice of appearance on behalf of Public Utils Board of City of Brownsville, TX.in consolidated discovery Certificate of of Brownsviller.co... Svc encl SPIEGEL,G Teram, State of SPIEGEL.O Spiegel & McDiarmid 80/03/06 Spp
- 8004090434 Discovery rept by Public Utils Board of City of Brownsville, TX.for Feb 1980 Deposed M Borchelt of Central Power & Light Participated in R Edelstein deposition Received documents from Central & South West Corp Certificate of Svc encl PDIRIER.N R Texas, State of PDIRIER.N R Spiegel & NcDiarmid . 6pp
- 800410021B Notifies that DOJ received Houston Lighting & Power Co supplemental answers to Central Power & Light Co first interrogatories w/o apps Requests Attachment A to Houston Power & Light Co second set of add answers to NRC CYPHERT, S B Justice, Dept of 80/03/06 1p
- B004100433 Notice of appearance of Q Spiegel on behalf of Public Utils Commission of Brownsylle-TX Certificate of Svc encl SPIEGEL, G Brownsylle-TX SPIEGEL, G Spiegel & McDiarmid 80/03/06 App
- 8004100535 Discovery rept for Jan & Feb.1980.City of Austin has neither initialed nor received any discovery requests BALQUGH.R C Austin, TK 80/03/07 Spp
- B0040B0044 Response by Public Utils Board of City of Brownsville, TX, in opposition to Central & Southwest Corp B00222 motion for protective order, re second set of interrogatories & production of documents W/Certificate of Bvc & B00207 ltr POIRIER, MR Teras, State of POIRIER, MR Spiegel & McDiarmid B0/03/10 12pp
- 8004100514 Forwards notice of taking of deposition of D Springs AHCARN.C D Debevoise & Liberman 80/03/10 ip
- --8004100525 Notice of taking of deposition of D Springs on 800313-14 in Atlanta: GA Deponent will be examined on matters to bulk power supply & transmission & wheeling sycs in TX Certificate of Syc encl AHEARN, C D Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/10 Spp
- 8004110149 Notifies that W Scott deposition scheduled for Mar is cancelled Cancellation based on DDJ representation that Scott would be called as expert withness BALDMIN.J M Baker 5 Botts 80/03/10 5pp
- BOD40BD018 Updated response to first set of interrogatories & document DAUGHOUS Opaces response to first set or interrogatories requests faciludes info re witnesses, competitive utills, product & geographic market? petitions to intervene Prof qualifications of DA Springs & Certificate of Bvc encl BURCHETTE.W H Texas-Louisiana Electric Cooperative, Inc BURCHETTE.W H Northcutt Ely 80/03/11 29pp
- 8004090164 Second supplemental response to first set of interrogatories & document requests includes info re projected loads, capacity & reserves as of 800215 SLICKER, F K Teras Utilities Co SLICKER, F K Worsham, Forsythe & Sampels 80/03/11 Spp

- 8004090175 Supplemental response to third set of interrogatories & document requests Supplemental answer to Interrogatory 18 ancl Wide encl SLICKER, F K Texas Utilities Co SLICKER, F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004090180 Supplemental response to first set of interrogatories & document requests Includes info re monthly fuel cost adjustments for 1979
 SLICKER,F K Texas Utilities Co SLICKER,F K Worsham, Forsythe & Sampels 80/03/11 App
- 8004100084 Forwards DOJ subpoens requiring DE Simmons util vice president, to testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subpoens W/o encl
 CYPHERT, S B Justice. Dept of 80/03/11 fp
- 8004100221 Fourth supplemental response to first set of interrogatories & document requests Includes info re cities & utils which have explored power alternatives offered by TX Utils Co SLICKER, F K Texas Utilities Co SLICKER, F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004030298 Response in opposition to schedule proposed by NRC for reply to motion to quash 800221 subpoena directed to R Frame Merit of NRC argument will be better evaluated after Lerner deposition Suggests 800321 for reply W/Certificate of Svc KNOTTS.J B Texas Utilities Generating Co 80/03/12 Spp
- B004020113 Forwards Houston Lighting & Power B00313 petition for directed certification of ASLB 800307 order re confidential documents of settlement negotiations BCUKNIOHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13
- --8004020119 Petition for directed contification, interim stay & review of ASLO 800307 order requiring Houston Lighting & Power to produce settlement negotiations documents Urges reversal of ruling W/excerpts of 800307 prehearing transcript BOUKNIGHT, J A . GREEN, D G . Houston Lighting & Power Co BOUKNIGHT, J A . Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13
- ---8004020122 Order re NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privileged documents Orders responses to majority of questions W/ascerpts of 790401 prehearing MILLER, M E Atomic Safety and Licensing Board Panel 79/04/16
- 80040B002B Forwards DOJ third supplemental response to Houston Lighting & Power Co first set of interrogatories Documents responsive to util 790204 second set of interrogatories encl Documents respond interrogatories not encl CYPHERT, B B Justice, Dept of 80/03/13 ip
- ---8004080033 Third supplemental response to first set of interrogatories & document requests includes info re GT Taylor testimony re four relevant product markets in proceedings

 CYPHERTIS B Justice, Dept of 80/03/13 30pp
- 8004080073 Application for issuance of subpoens directed to FG Arey of Webster Engineering Corp. to be deposed & to produce documents re interconnections & interconnected sys Draft subpoens & Certificate of Syc encl OREEN, D G Houston Lighting & Power Co * Baker & Botts * Lowenstein, Neuman. Reis, Axelrad & Toll 80/03/13 13pp
- 8004070437 Ack receipt of & accepts 800312 Itr in lieu of interrogatory answer per 800307 prehearing ruling Ltr does not solve Houston Lighting & Power problems re C Stover deposition DDJ 800311 & 12 ltr & Certificate of Svc encl OREEN.D G Lowenstein.Newman.Reis.Axelrad & Toll 80/03/13 10pp
- 8004100945 Response to third set of interrogatories Includes info rs electric power & energy delivered to various utils during Dec 1979 Certificate of Svc encl * Texas Electric Service Co 80/03/13 16pp
- 80040B0370 Discovery rept for Feb 1980 Deposed J Wilson, GC Campbell & V Robertson et al Attended DOJ & NRC depositions Berved 800R01 first set of interrogatories to NRC Received addites responses to interrogatories Certificate of Svc encl FRANKLIN, W J Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/03/14 7pp
- 8004040078 Comments by Public Utils Board of City of Brownsville, TX, stating no position re consolidation for trial advised by A8LB during B00307 prehearing If consolidation ordered right of cross-examination must be preserved MYCertificate of svc POIRIER, M R . POIRIER, M R . Texas, State of 80/03/17 7pp

- 8004080153 Statement in opposition to consolidation of proceedings for hearing purposes, per ASLB 800307 prehearing conference request Issues not identical *h* evidence in South TX Project may not be related to Commanche Peak W/Certificate of Svc STAHL, D II Central / Southwest Corp STAHL, D M Isham, Lincoln & Beale 80/03/17 9pp
- BO040B0247 Discovery rept for Feb 1980 Participated in Ammons, Beams, Borcheit, Campbell, & Yaibiough depositions Inspected DDJ documents Received & opposed Central & Southwest motion for addline to reply to interrogatories W/Certificate of Svc AHEARN, C D Texas Utilities Co AHEARN, C D Debevoise & Liberman BO/03/1/ Spp
- 8004080401 Submits TX Utils Generating Co response to ASLB 800307 request re views on consolidation of proceedings for hearing purposes Urges complete consolidation KNDTTG, J B Debevoise & Liberman 60/03/1/ 4pp
- 8004080669 Order confirming results of 800307 oral argument NRC & DOJ joint motion, re mod of order concerning protection of settlement discussions, granted in part Parties may not engage in further discovery re documents included in motion GLASER, M L. Atomic Safety and Licensing Board Panel 80/03/17
- 8004090427 Discovery rept for Jan-Feb 1980 Participated in M Drymy deposition No discovery requests instrated Certificate of Svc encl BURCHETTE, W H Texas-Louisiana Electric Cooperative, Inc BURCHETTE, W H Northoutt Ely 80/03/19 3pp
- B004010517 Order denying NRC 800311 motion to quash subposns of R Frame TX Utils Generating Co entitled to test ND Lerner credibility by questioning work 2 documents prepared by Frame for Lerner review WDLFE,S J Atomic Safety and Licensing Board Panel 80/03/20 2pp
- 8004030347 Response in opposition to TX Utils Generating Co.Houston Lighting & Power Co & South West Corp 800313 petitions for directed certification of order compelling production of documents News article & Certificate of Svc encl CHANANTA.F D . BLUME.M B . HODGBON.A P Antitrust Division 80/09/20 21pp
- 8004100177 Memorandum in opposition to petitions for directed certification filed by TX Utils Generating Co. Houston Lighting & Power Co & Central & South Nest Corp et al.re AGLB 800307 order Certificate of Svc encl CYPHERT. S 8. DOPBOVIC.D A. GLAZIER.K M Justice, Dept of 80/03/20 26pp
- BOO4100834 Response to DOJ first set of interrogatories Includes info re TX electric cooperatives & wholesale suppliers Certificate of Svc anc1 * Texas Electric Service Co 80/03/20 21pp
- B004010262 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents
 BLUME.M B Antitrust Division B0/03/21 2pp
- BOOAO40184 Motion to quash subpoens directed to GN Stagg upon DOJ & NRC joint request Absent evidentiary reliance upon Btagg Sys. Inc work montestifying outside consultants are not subj to discovery pincess, per established rule FRANKLIN.N J Houston Lighting & Power Co 80/03/21 4pp
- ---BCO4040198 Advises that Houston Lighting & Power does not intend to rely on Stagg Sys. Inc studies as part of defense in proceeding NRC & Central & Southwest Corp contensions re Stagg study based on misconception W/Certificate of Syc GREEN.D Q Lowenstein.Newman.Reis.Axelrad & Toll 80/03/21 7pp
- 8004160111 Responds to NRC & Central & South West Corp comments re consolidation Severance arguments based on belief that util will rely on study by Stagg Sys.Inc as part of defense Util will not rely on Stagg study Certificate of Svc encl QREEN,D G Lowenstein, Newman, Rois, Axelrad & Toll 80/03/21 App
- 8004030340 Response by Public Utils Board of City of Brownsville.TX in opposition to nonconsolidation of proceeding suggested by NRC & Central & South West Corp In event of separation. South TX case should be heard first Certificate of Svc encl SPIEGEL.G Texas. State of 80/03/24 7pp

- 8004250049 Response in apposition to Public Utils Board of City of Brownsville TY 800317 comments requesting admittance as party in consolidated profeeding Statement of Interest untimely & vague Certificate of Svc encl AHEARN, C D Teas Utilities Cenerating Co AHEARN, C D Debevoise & Liberman 80/03/25 Tpp
- 8004:0027: Motion to compel production of documents by Southwest TX Electric Cooperative re subpoend directed to general manager E McGinnes Requests to strike McGinnes 800:22: deposition if documents are not produce! Widnaft subpoend & documentation GREEN.D O Houston Lighting & Power Co # Baker & Botts * Lowenstein.Newman.Reis Aleirad & Toll 80/03/26 18pp
- --B004100278 Motion to compel production of documents by Midwest Electric Cooperative re subpoens directed to general manager P Wetiel Requests to strike Wetiel rescheduled deposition if documents are not produced Wisubpoens & Certificate of Svc GREEN.D G Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reps. Aleired & Toll 80/03/24 15pp
- 8004080420 Application for issuance of subpoens directed to Gulf States Utils to re settlement documents Documents not produced in response to 790709 % 800118 subpoens Urges production to extent allowed by ASLAB BLUME.M B Antitust Division 80/03/27 2pp
- --B004080424 Subpoena directed to Gulf States Utils Co requesting settlement documents, for insp % copying, in Washington, DC on 800402 Subpoena may be guashed or modified upon request Certificate of Svc encl WILLER, M E Atomic Safety and Licensing Board Panel 80/03/27 6ap
- 8004090126 Order denying Houston Lighting & Power 800321 motion to quash subpoens directed to GN Stagg upon DOJ request Prior rulings, re nontestifying outside consultants, do not apply in this proceeding due to relevancy of Stagg studies WOLFE, S J Atomic Safety and Licensing Board Panel 80/03/27 3p.
- 8004210386 Forwards Houston Lighting & Power 800327 motions to compet production of documents by NRC expert witnesses RH Hartley & NC Lerner Requests 800331 conference call prior to scheduled depositions
 FRANKLIN.H J Lowenstein, Newman, Reis, Azelrad & Toll 80/03/27 19
- --8004210392 Motion to compst testimonial questions answered by NRC expert witness RM Hartley Discoverability of questions established on Pages 421-423 of prehearing conference transcript re ASLB 800625 order FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowenstein, Newman, Reis, Axeirad & Toll & Baker & Botts 80/03/27 App
- --8004210394 Submits preparation study for 800220-21 meeting re intraregional interconnections transmission lines & other pooling matters HARTLEY:R H Affiliation Unknown 80/01/29 25PP
- --8004210397 Forwards RH Hartley 800211 memo to NRC re 800127 answers in preparation for 800220-21 meeting Requests questions to which answers were stated per rule established in 790601 prehearing conference Pages 421-423 of transcript encl FRANKLIN.W J Lowenstein.Neuman.Reis.Axelrad & Toll 80/03/20
- --B004210400 Hotion to compel electric util industry testimonial antitrust analyses prepared by NRC expert economic witness N terner re Hadland proceeding Urges production per prior rulings, subj. to encl protective ander W/Certificate of Svc FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll + Baker & Botts B0/03/27 14pp
- 1004090123 Order giving parties one wit to provide addit authority re existence of settlement privilege Memoranda addressing issue should be received by 800404 & response thereto by 800409 BISHOP,C J Atomic Bafety and Licensing Appeal Panel 80/03/28 2pp
- 8004090456 Protective order, in favor of Houston Lighting & Power, reconfidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeking Judicial review per FDIA WOLFE, S. J. Atomic Safety and Licensing Board Panel 80/03/31 4pp
- 8004100243 Order granting in part NRC motion to compel addit responses by Houston Lighting & Power (MLMP) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions re RH Hartley testimony HOLFE.S J Atomic Safety and Licensing Board Panel 80/03/31 3p

- 8004100428 Public Utils Board of Brownsville motion for leave to file affidavit as amicUs curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Sv. encl SPIEGEL, O Brownsville, TX SPIEGEL, O Spiegel & McDiarmid 80/03/31 Bao
- ---8004100430 Affidavit of RE Roundtree general manager of Brownsville
 Public Utils Board is agreement among TX "10Us" for
 const or two do interstate ties of 500 NM & 250 NM
 Brownsville prepared to enter settlement negotilations
 ROUNDTREE.R E Brownsville.TX 80/03/27 3pp
- 8004080172 Updated response to Houston Lighting & Power second set of interrogatories & TX Utils first set of interrogatories Anticipates RE Corder participation as witness re areas discussed during Corder deposition Cestificate of Svc enc1 CHANANIA.F D Antitrust Division 80/04/01 5pp
- 8004100240 Order requesting parties in directed certification proceeding to respond to Utils Board of City of Brownsville, TX 800331 motion, by 800409
 BISHOP, C.J. Afomic Safety and Licensing Appeal Panel 80/04/02 200
- BOO4180151 Forwards joint motion for extension of time Motion is joined in by all parties to proceeding except DOJ & City Public Utils Board of Brownsville, TX KKOTTS, J B Debevoise & Liberman BO/04/02 1p
- --B0D41B0167 Joint motion for 30-day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotations which could lead to resolution of part or all of
 proceedings Certificate of Bvc encl
 CHANANIA.F D Antitrust Division COPELAND.J O Houston Lighting
 & Power Co STAHL.D M Central Power & Light Co 80/04/02 dep
- 8004140003 Third set of add1 answers to NRC 790115 initial interrogatories Simmons & Woodson are expected to testify reinterconnections FRANKLIM, W.J. Houston Lighting & Power Co. * Baker & Botts Lowenstein, Neuman, Reis, Axelrad & Toll 80/04/03 2pp
- --800414000B Second supplemental answers to Central Power & Light Co 790223 interrogatories Simmons & Hoodson are expected to testify re interconnections Certificate of Svc encl FRANKLIN, W J Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman Reis, Arelrad & Toll 80/04/03 App
- 8004i50032 Forwards opposition by Brownsville to joint motion for extension of time & request for prehearing conference, miscellaneous atty & util correspondence.affidavit & Brownsville rate estimates Certificate of Syc encl
 SPIECEL.O , POIRICE.M.R. Spiegel & McDiarmid 80/04/03 19pp
- --8004150050 Opposition to joint motion for extension of time & request for prehearing conference Brownsville has been excluded from negotiations on which request for extension is based Certificate of Svc encl SPIECEL. 9. POIRIER, M.R. Brownsville, TX. BPIECEL, 9. Spiegel & McDiarmid 80/04/03. 2pp
- 8004230366 Forwards Houston Lighting & Power 800403 motion to compel production of documents & JW Wilson testimony by Public Utils Board of City of Brownsville, TX Proposes expedited schedule to permit completion of expert witness discovery GREEN.D & Lowenstein.Neuman.Reis,Axelrad & Toll 80/04/03 2pp
- --B004230074 Motion to compel production of documents & JW Wilson expert testimony by Public Utils Board of City of Brownsville, TX
 If motion not granted requests order precluding Wilson from hearing W/proposed order re schedule & Certificate of Svc
 BALDMIN.J M Houston Lighting & Power Co * Baker & Botts *
 Lowenstein, Newman, Reis. Axelrad & Toll 80/04/03 11pp.
- 8004100126 Memorandum in response to ASLAB 800328 order requesting add1 authority re recognition of settlement privilege Courts & case law do not recognize existence of privilege Certificate of 8vc enc!

 BLUME.H B . HODODON.A P Antitrust Division 80/04/04 App
- 8004150083 Order setting 800411 conference at NRC Hearing Room, Bethesda,MD Oral argument will address NRC & DOJ joint motion for 30-day extension > Houston Lighting & Power 800403 motion to compel Utils Board of Brownsville WCLFE.8 J Atomic Safety and Licensing Board Panel 80/04/04

- 8004170312 Memorandum of authorities re discoverability of settlement documents Urges reversal of ASLB 800307 ruling due to privilege recognized per case law & federal rules of evidence Supporting documentation & Certificate of Svc encl BOUKNIGHT, J A . GREEN. D G Houston Lighting & Power Co BOUKNIGHT, J A . Daker & Botts 80/04/04 Bipp
- 8004170340 Response stating no position re joint motion for 30-day extension in proceeding filed by NRC.Central & South West Corp. Houston Lighting & Pawer, TX Utils Generating Co. City of Austin & other parties Certificate of Syc encl DDPSOVIC, D.A., LUGUE, N., PARMENTER, F. Justice, Dept of 80/04/04
- 8004220128 Memorandom of authorities in support of settlement privilege Documents prepared in connection wisettlement process should be protected from discovery under work product privilege Certificate of Svc encl STAHL.D Central & Southwest Services. Inc STAHL.D Isham. Lincoln & Beale 80/04/04 iOpp
- 8004240043 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents that wtil consents to extension O'NEILL, R A Southwest Texas Electric Comperative O'NEILL, R A Miller, Balis & O'Neii 80/04/04 3pp
- 8004240045 Certifies svc of consent motions for extension to respond to Houston Lighting & Power Co motion to compel production of documents from Midwest Electric Cooperative & Southwest TX Electric Cooperative, on 800404
 O'NEILL,R A Miller, Balis & O'Neil 80/04/04 App
- 8004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents util consent to extension O'NEILL, R A Southwest Texas Electric Cooperative O'NEILL, R A Miller, Dalis & O'Neil 80/04/04 3pp
- B004240173 Memorandum.per ASLAB 800328 request, stating add1 authorities re directed certification of settlement document issue Treaties & modern trend hold inadmissibility of privileged documents as evidence Certificate of 8vc encl KNOTTB.J B , AHEARN.C D Texas Utilities Generating Co KNDTTB.J B Debevoise & Liberman 80/04/04 22pp
- 8004290106 Advises of arrangement to deliver Houston Lighting & Power pleadings moving to compel documents re & McGinnes & P Metzel subpoenas Consents to 14-day extension for responses Certificate of Suc anci GREEN, D & Lowenstein, Newman, Reis, Axelrad & Toll 80/04/04 5pp
- 8004100552 Motion to issue order compelling Southwest TX Electric Cooperative & general manager E McGinnes to produce, for insp & copyling, documents set forth in motion Draft subpoena & Certificate of Evc encl OREEN.D.O Houston Lighting & Power Co OREEN.D.O Baker & Botts 80/04/07 18pp
- --8004100860 Motion to issue order compelling Midwest Electric Cooperative & general manager P Wetzel to produce, for insp & copying, documents responsive to subpoena served on Wetzel Draft subpoena & Certificate of Svc encl OREEN, D Q Houston Lighting & Power Co GREEN, D Q Daker & Botts 90/04/07 15pp
- 8004230154 Motion to practude DOJ from filing principal brief re ASLAD 800328 order DOJ failed to file principal brief by 800404 DOJ seeks to obtain unfair tactical advantage by untimely filing DOUKMICHT, J A . GREEN, D O Houston Lighting & Power Co BOUKNICHT, J A . Baker & Botts 80/04/07 3pp
- --8004230162 Order directing all parties to furnish ASLAB w/addl authority re privilege against discovery of documents Memoranda due on 800404 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/28 6pp.
- 8004240061 Motion for ABLB to reconsider extending procedural dates for 30 days. Requests 800408 conference call to rule on extention TX Utils Generating Co is only party to be prejudiced by extending dates CHANANIA,F Antitrust Division BOUKNIGHT, J A Houston Lighting & Power Co BURCHETTE, H H Texas-Louisiana Electric Cooperative, Inc 80/04/07 3pp
- --8004240071 Supplemental argument & representations Addl time required by utils to make progress in settlement discussions.

 Discussions began Sept 1979 Parties are aptimistic about possibility of reaching quick settlement BURCHETYE, WH Texas-Louisians Electric Cooperative, Inc KNOTTS, J B Taxas Utilities Generating Co 80/04/07 5pp

- 8004210147 Discovery rept for Mar 1980 Deposed JA Bruggeman, JT Wenders, AJ Wood & DA Springs Moved to compel NRC deposition of ND Lerner Responded to DOJ motion to compel supplemental answers to first interrogatories W/Certificate of Svc FRANKLIN, W J Houston Lighting > Power Co FRANKLIN, W J Lowenstein, Newman, Reis-Arelrad & Toll 80/04/08 App
- 8004;50157 Response to Houston Lighting > Power, TX Utils Generating Co > Central & South West Cos 800404 memoranda of authorities re settlement privilege Urges affirmation of ASLB 800307 order re production of documents W/Certificate of Svc CHANANIA, F D . HODGDON, A P Antitrost Division 80/04/09 10pp
- 8004170347 Response to Public Utils Board of City of Brownsville,TX 800331 motion to file RE Roundtree affidavit as amicus curiae Disclosure of documents should not affect potential for settlement Certificate of Sic encl CHANANIA.F D Antitiust Division 80/04/09 6pp
- B004220021 Response to Public Utils Board of City of Brownsville,TX 800331 motion to file Roundtree affidavit Requests to file counter-affidavit, re status or settlement.if Roundtree affidavit is accepted by ASIAB Centinicate of 8vc encl KNDTTS,J B Texas Utilities Generating Co B0/04/09 App
- B004220192 Response to Houston Lighting & Power 800403 motion to compel production of documents & deposition of Public Utrls Board of City of Brownsville.TX Does not appose motion if subj to encl protective order Appearance & Certificate of Svc encl ROTH.A J. JACOBS, J C. Florida Cities ROTH.A J. Spiegel & McDiarmid 80/04/09 14pp
- BD04240562 Response in opposition to NRC 800404 memorandum of addl authorities re existence of settlement documents privilege Congress did not intend to freeze developing law of privilege M/Certificate of Svc KNOTTS, J B , AHCARN, C D Terus Utilities Generating Co KNOTTS, J D Debevoise & Liberman 80/04/09 Bpp
- 8004170351 Order granting 30-day extension for procedural matters, amending ASLB 791214 order no discovery schedule & directing consolidation of proceedings for pretrial & evidentiary hearings Consent motions for extension to 800404 granted MILLER,N E Atomic Safety and Licensing Board Panel 80/04/10
- 8004210141 Order denying Houston Lighting & Power motion seeking to preclude DOJ memorandum of addl authorities filed per ASLAB 800328 order BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/04/10
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Fikar requested during 800409 oral argument KNQTT8, J.B. Debevoise & Liberman 80/04/10 lp
- --8004230041 Affidavit stating that Central & South West Corp. Houston Lighting & Power Co & TX Utils Co Sys have reached agreement in principle re interconnection disputes Agreement may form basis for discussions w/other parties M/Certificate of Svc FIKAR.L F Tevas Utilities Generating Co 80/04/10 Spp
- 8004230002 Responds to Public Utils Board of City of Brownsville,TX opposition to joint motion for extension of time Objects to alleged refusal to wheel & submits ML Borchelt affidavit in response to alleged exclusion from discussions STAHL.D M Contral & Gouthwost Corp STAHL.D M Ieham, Lincoln & Beale 80/04/11 3pp
- --8004230007 Affidavit responding to Public Utils Board of City of Brownsville,TX allegation that Brownsville has been excluded from discussions re interconnection Clarifies statement made at BOG327 meeting Certificate of Svc encl BGRCHELT:M L Carolina Power & Light Co 80/04/10 10pp
- 8004290227 Discovery rept for Mar-Apr 1980 Participated in FJ Heyer, HH Moodson & GN Stagg depositions Filed opposition to petitions for directed certification & reversal of ASLB 800307 order Joined other parties in moving for procedural extension CHANANIA, FD , BLUME, M B , HODGDON, A P Antitrust Division 80/04/25 3pp
- N Antitrust hearing transcripts
- 8004030344 Pages 490 \$ 491 ommitted from original transcript * Commission 80/03/07 3pp
- B004150298 Transcript of B00409 hearing in Bethesda, MD Pp 1-140 * Commission B0/04/09 140pp

- Q Inspection reports. IF Sulletins 1 correspondence
- 8004010147 Responds to IE (ulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit", witches at Elevated Temps "
 Requests extension until 800331 to inspect safety-related equipment 5 implement necessary corrective actions GARV, R. J. Teras Utilitie. Generating Co. 80/01/23. 1p
- 8004290492 Discusses IE Insp Rept. 59-445/80-01 & 50-446/80-01 on 800118 / forwards notice of violation SEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/01/23 2pp
- --8004290498 Notice of vaciation from insp on 800118 Noncompliance noted procedures for securing Class IE battery chargers inappropriate Fillet welds too small due to natl thickness

 * Region 4 Dallas, Reactor Construction & Engineering Support Brack 800123
- 8004160044 Forwards If Insp Repts 50-445/80-05 % 50-446/80-05 on 800214-15 % 19-21 No nancompliance noted SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Dranch 80/02/2/ 2pp
- --8004160050 IE Insp Repts E0-445/80-05 % 50-446/80-05 on 800214-15 & 19-21 No noncompliance noted Major areas inspected followup review of Unit I RCPB piping welding & of QA/QC records to Unit 2 containment bldg structural concrete installations HALL-R C Region 4. Dallas, Reactor Construction & Engineering Support Branch CROSSMAN, W A. TAPIA. J I Region 4. Dallas. Office of the Director 80/02/28 5pp
- 8004210175 Forwards IE Insp Repts 50-445/80-06 & 50-446/80-06 on B00220-21 No noncompliance noted MADSEN O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/29 ip
- --8004210179 IE Insp Repts 50-445/80-06 # 50-446/80-06 on 800220-21 No nuncompliance noted Major areas inspected preoperational testing. GA *> operational staffing MESTERMAN.T F. SMITH.R Region 4. Dallas. Office of the Director 80/02/29 5pp
- 8004220232 Forwards IE Insp Repts 50-445/80-04 & 50-446/80-04 on 800211-15 No noncompliance noted SEIDLE W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004220244 [E Insp Repts 50-445/80-04 & 50-446/80-04 on 800211-15 No noncompliance noted Major areas inspected procedures for controlling changes to approved design documents HALE, C J , CROSSMAN, M A , BRICKLEY, R H Region 4, Dallas, Vendor Inspection Branch 80/02/28 8pp
- 8004210432 Advises that numbers of inspirepts transmitted by 800227 ltr should be corrected to read 50-445/80-06 % 50-446/80-06 MADSEN,G L. Region 4. Dallas. Reactor Operations Nuclear Support Branch 60/03/10 ip
- --8004210443 Forwards IE Insp Repts 50-445/80-06 & 50-446/80-06 on 800220-21 No noncompliance noted MADSEN.G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/02/29 ip
- --8004210438 1E insp Repts 50-445/80-05 % 50-446/80-05 on 800220-21 No noncompliance noted Major areas inspected preoperational testing. GA & operational staffing WESTERFAN. T.F. Region & Dallas, Reactor Operations Nuclear Support Branch SMITH. P. Region 4. Dallas. Office of the Director 80/02/29 Spp
- 8004040081 Ack receipt or 800305 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-03 \$ 50-446/80-03 SEIBLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/03/11 1p
 - R0040+0083 Responds to NRC 600207 IE Insp Repts 50-445/80-03 & 50-446/80-03 Carrective actions engineering personnel reviewed cable Jubrication requirements w/key const personnel involved w/cable pulling GARY.R J Texas Utilities Generating Co 60/03/05 dpp
 - J4040098 Ack receipt of B00220 ltr informing NRC of steps taken to correct violations noted in EE Insp Rept 50-445/79-31 & 50-446/79-29 SEIDLE.N C Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/03/11 ip

- --8004040101 Responds to HRC 800127 IE Insp Repts 50-445/79-31 & 79-446/79-29 Corrective actions tackwelds removed General Piping & Welding Procedure CP-CPM-6 9 revised t reorganized OARLR J Teras Utilities Generating Co
- 8004250079 Forwards IF Investigation Repts 50-445/80-02 to 50-446/80-02 on B00121-0205 No noncompliance noted SEIDLE.W C Region 4. Dailas, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004250053 IE Investigation Repts 50-445/80-02 & 50-446/80-02 on 800121-0205 No moncompliance noted Major areas inspected allegations re lax GC procedures welding problems & weld defects CROSSMAN, A A CILEERT.L. D . HALL, N E Region 4. Dallas. Office of the Director 80/03/18 700
- 8004240225 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees " No action required SEFFRIT, K v Region 4. Dallas, Office of the Director 80/04/02 by
- 8004220320 Forwards 1E Circular 80-07, "Problems W/HPCI Turbine 0:11 Sys " No written response required SEYFRIT, K V Region 4. Dallas, Office of the Director 80/04/03 to
- B0042207/9 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASHE SA-312. Type 304 Stainless Steel Pipe" Action required SEYFRIT, K.V. Region 4. Dallas, Office of the Director B0/04/04 in
- 9004220208 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Panetration Welds " Written response required SEYPRIT,K V Region 4, Dallas, Office of the Director 80/04/07
- S Reportable accurrences, LERs & related correspondence
- 8004010275 Forwards deficiency rept re control board welded connections of the Connection of the Connection of the Control of the Connection of the Connecti
- --90040:0279 Deficiency rept on 800228. GA inspressed control board welded connections not meeting seismic design criteria Cause unstated Control board suppliers & AE reviewing as-built weld configurations Rework will be completed by 80050:

 * Texas Utilities Generating Co 80/03/2: 2pp
- 8004150199 Forwards deficiency rept re control board welded connections GARY,R J Texas Utilities Generating Co 80/03/21 ip
- --B004150202 Deficiency rept re control board welded connections Specified B-inch spacing of welds from end to end was found to vary from sixteen to eighteen inches on several panels As-built weld configurations under review # Texas Utilities Generating Co 80/03/21 2pp
- 8004010296 Forwards rept of actions taken to correct deficiencies in mfg of discs for svc water control valves Supporting documentation is available at site for inspector review GARY.R J Texas Utilities Concreting Co 80/03/25 2pp
- 8004070278 Supplemental RO violation found re piping min wall thickness Cause unstated Engineering review in progress Progress rept will be submitted by 800418 GARY-RJ Texas Utilities Generating Co 80/03/28 ip
- 9004220423 Interim deficiency rept re piping min wall thickness Review of weld & base metal repair records is continuing Another progress rept will be submitted by 800620 OARY.R J Texas Utilities Generating Co 80/04/15 ip
- 8004290250 Forwards deficiency reptile concrete honeycomb condition encountered in steam generator compartment walls of Unit 2 reactor containment bldg GARY.R J Taxas Utilities Generating Co 80/04/21 ip
- --8004270254 Deficiency rept re concrete honeycombing in steam generator compartment walls of Unit 2 reactor containment hldg Consultant survey showed no critical internal defects Util to repair condition w/dry-pack mortar.grout & concrete * Texas Utilities Generating Co 80/04/21 3pp
- 8004290271 Interim deficiency rept re installation of drilled-in expansion anchors Matter was corrected 790616 by revision to installation procedure Formal rept to be filed by 801215 GARY.R J Tevas Utilities Generating Co

DOCKETED ITEMS

- 80042904ii Provides status of interim deficiency rept re installation & insp requirements for Class V non-nuclear safety-related piping supports Final rept will be forwarded by 800715 GARV. R J Texas Utilities Generating Co 80/04/21 ip
- 8004290430 Forwards interim deficienty tept re installation & insp of welded conduit supports Final rept to be filed by B00801 GARY.R J Texas Utilities Generating Co 80/04/21 ip
- ~~8004290437 Interim deficiency rept re installation & insp of welded conduit supports Major support was fabricated w/o formalized instructions & insp records for number of smaller welded supports were not directly traceable to as-built conditions GARY,R J Texas Utilities Generating Co 80/04/21 ip
- T Hearing transcripts on non-antitiust matters
- 8004210312 Transcript of 800327 hearing in Bethesda.MD Pp 1-127

 * Atomic Bafety and Licensing Appeal Panel 80/03/27 130pp

DOCKET 50-448 DOUGLAS FOINT NUCLEAR STATION, UNIT 1

- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emorgency planning & preparedness distributed as Board notification 00SSICK.L V Office of the Executive Director for Operations 80/04/02 34pp

M Antitrust correspondence

8004170340 Response stating no position re joint motion for 30-day extension in proceeding filed by NRC, Central & South West Corp, Houston Lighting & Power, TX Utils Generating Co. City of Austin & other parties Certificate of Syc encl DOPSOVIC.D A , LUGUE, N , PARMENTER, F Justice, Dept of 80/04/04

DOCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2

- O Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- # Antitrust correspondence
- 8004040072 Natice of appearance in proceeding Certificate of Syc encl FABRIKANT, R Justice, Dept of 80/02/25 4pp
- 8004080559 Requests pretiial conforence to clarify procedural matters re ASLB 791214 order.filing testimony summaries & designation exhibits CYPHERT.S B Justice.Dept of MILLER.M J Central & Southwest Carp 80/03/05 2pp
- 8004090204 Discovery rept for Feb 1980 Deposed W Taylor, M Hebb.DE Simmons & EL Matson Participated in depositions noticed by TX LA Electric Cooperative & City of Brownsville, TX Reviewed Diamond Shamrock documents Filed application for subposnas CYPHERT, 6 B Justice, Dept of 60/03/05 Spp
- 8004170351 Order granting 30-day extension for procedural matters, amending ASLB 791214 order re discovery schedule & directing consolidation of proceedings for pretrial & evidentiary hearings Consent motions for extension to 800404 granted MILLER, M.E. Atomic Safety and Licensing Board Panel 80/04/10 Spp

DOCKET 90-452 GREENWOOD ENERGY CENTER, UNIT 2

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp

- G Adjudicatory correspondence
- 8004030026 Remorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board hotification GOSSICKL V Office of the Evecutive Director for Operations 80/04/02 34pp
- DOCKET 50-453 GREENWOOD EPERG, CENTER, UNIT 3
- A Application/construction stage documents & correspondence
- BOOAOAOO31 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS, D. F. Division of Project Management BO/02/05 7pp
- Q Adjudicatory correspondence
- 800:1030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET 50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-mothods for compliance ROSB.D F Division of Project Hanagement 80/02/05 7pp
- 8004040017 Submits add) guidance to NURFG-0588. "Interim Staff Position on Environ Gualification of bafety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS, D.F. Division of Project Management 80/02/21 3pp
- 80001230058 Requests info to auriliary feedwater sys per Builetins & Orders Task Force review of TMI-2 accident info should be provided as amond to application Submittal schedule should include NRC approval prior to issuance of DL Wencl ROSS:DF Division of Project Management 80/03/10 53pp
- 8004090155 Summary of 800311 meeting w/utils. Hestinghouse & Sargent & Lundy re Westinghouse optimized fuel assembly Comm Ed requested to amend FSAR as soon as possible to show plant will use optimized fuel assembly KINTNER. L. L. Light Water Reactors Branch 1 80/03/18 8pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. AA program Revisions reflect recent organization title changes NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02 1p
- --8004150328 Revised pages constituting Revision 13 to QA program Revisions reflect recent organizational title changes * Commonwealth Edison Co

F

- 8004020033 First interrogatories directed to MRC Includes request for specific description of deliation, honconformity or change occurring after CF issuance Proof of Evc encl CHERRY, M M League or Moven Voters of Rockford, IL CHERRY, M M Cherry, Fignn / Manter 80/03/12 10pp
- 8604080429 Forwards League of Women Votets of Rockford.IL interrogatories * motion sceling ASLB authorization W/o interrogatories Cherry, M. M. /Cherry, Flynn & Kanter 80/03/12 lp
- --8004080435 Motion unging presiding officer to issue order requesting NRC to answer intervenor 803312 interrogatories Proof of Svc enci CHERRY, I.M. League of Momen Voters of Rockford, IL. CHERRY, M. M. CHERRY, II M. League of Momen Voters of Rockford, IL. Cherry, M. M. /Cherry, Flynn & Manter 80/03/12 4 4pp
- 8004090177 First sot of interrogatories includes questions reintervenors' revised contentions? deviations occurring since issuance of CP Proof of svc enclichtersy, M M League of Wimen Voters of Rockford. | L CHERRY Cherry, M M /Cherry, Flynn & Kanter 80/03/12 10pp
- 8004100322 Objects to intervenor League of Women Voters of Rockford.IL 800312 first set of interrogatories ASL9 has not ruled on admissibility of proposed contentions to which interrogatories refer Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincoln & Beale 80/03/19 3pp
- BOO4080428 Mution for order setting BOO418 for applicant & BO0425 for NRC to respond to Roctford League of Women Voters revised contentions Time is needed to perform preliminary evaluation re possible stipulation Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincotn & Beale BO/03/20 App
- 8004090448 Order setting 800448 for Comm Ed to respond to League of Women Voters of Rockford revised contentions
 MILLER, M.E. Atomic Safety and Licensing Board Panel 80/03/26 ip
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- B004290217 Response to intervenor Rockford League of Homen Voters B00310 revised contentions Recommends acceptance of 19 separate contentions 5 two consolidation contentions Certificate of Syc encl KARMAN.M . 00DDARD.R J Hearing Dranch 2 80/04/25 23pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004080397 Forwards affidevit stating that distribution of Amend 25 to FSAR has been made in accordance w/RS Boyd 791020 1tr NAUGHTON.W F Commonwealth Edison Co 60/04/01 2pp
- G Inspection reports: IF Bulleting & correspondence
- 8004280066 Forwards 16 Insp Repts 50-454/80-02 % 50-455/80-02 on 800207-08 No moncompliance noted FIDRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/06 2pp
- -8004280074 IE Insp Repts 50-454/80-02 \$ 50-455/80-02 on 800207-08 No noncompliance noted Major aleas inspected licensee corrective actions on previous insp findings & storage of safety-related mechanical & electrical maths & components MILLIAMS, C.C., KONMLIN, J.E., JONES, C.E. Region G. Chicago, Office of the Director 80/03/04 11pp
- 04100118 Forwards IE Info Notice 80-08, "States Co Bliding Link lactrical Terminal Block " No specific action or response
- quired PPLER,J G Region 3, Chicago, Office of the Director 80/03/07
- 4280031 Forwards 1E Insp Repts 50-454/80-03 & 50-455/80-03 on 300220.21 & 27 No moncompliance noted FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 60/03/12 2pp
- --8004280039 lE Insp Repts 50-454/80-03 & 50-455/80-03 on 800220,21 & 27
 No noncompliance noted Major areas inspected RCPB piping
 work activities welding & procedures
 DANIELSON.D H Region 3, Chicago, Reactor Construction &
 Engineering Support Branch LEE,E W Region 3, Chicago, Office of
 the Director 80/03/10 4pp

- 8004140119 Forwards response to IF Bulletin 80-03. "Loss of Charcoal from Std Type II. Two-Inch Tray Adsorber Cells" Visual eramination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES.D L Commonwealth Edison Co 80/03/20 Spp
- 8004150159 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Walve " No specific action or response necessary KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/03/31
- 8004080686 Forwards IE Circular 80-05. "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required Region 3. Chicago, Office of the Director 80/04/01 KEPPLER, J G
- 8004190014 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently emitted from 800306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220093 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220324 Forwards IE Corcular 80-07, "Problems W/HPCI Turbine Dil Sys " No written response required

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004220069 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Wolds" Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/09
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07
- S Reportable occurrences, LERs & related correspondence
- 8004070228 Ack receipt of 800227 second interim rept re failure of post-tensioning tendon field anchor heads Rescheduled date of 800515 for submittal of final rept is acceptable FIORELLI/O Region 3. Chicago Reactor Construction & Engineering Support Branch 80/03/19 ip
- DOCKET 50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS.D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info re auriliary foedwater sys par Bulletins & Orders Task Force review of TMI-2 accident info should be provided as amend to application. Submittal schedule should include NRC approval prior to issuance of DL W/enci ROSS. D F Division of Project Management 80/03/10 53pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A, GA program Revisions reflect recent organization title changes. NAUOHYON,W F Commonwealth Edison Co 80/04/02 ip
- --B004150328 Revised pages constituting Revision 13 to GA program Revisions reflect recent organizational title changes * Commonwealth Edison Co CE-1-A R13 80/04/04 7pp

- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 ORINES.B K Emergency Preparedness Task Force 80/03/11 4pp
- BOO4140118 Forwards request for add1 info consisting of fifth set of round one questions re safeguards contingency plan Encl withheld (ref 10CFR2 790) RUBENSTEIN,L S Light Water Reactors Branch 4 80/03/28 2pp

9 Adjudicatory correspondence

- 8004100027 Notice of appearance in proceeding Certificate of Svc encl LEVIN.K F DeKalb Area Alliance for Reaponsible Energy LEVIN.K F Sinnissippi Alliance for the Environment (SAFE) LEVIN.K F Beatty.Levin.Holland, Basofin & Barsany 80/02/29 Jpp
- 8004090411 Discusses League of Homen Voters of Rockford 800213 motion re admissibility of contentions Requests ASLB to vacate 800221 order & permit filing of revised contentions on 800310 Proposes schedule for briefing MURPHY.P M Isham, Lincoln & Beale 80/03/05 App
- 8004020033 First interrogatories directed to NRC Includes request for specific description of deviation, nonconformity or change occurring after CP issuance Proof of Svc encl CHERRY, M M League of Women Voters of Rockford, IL CHERRY, M M Cherry, Flyan & Kanter 80/03/12 10pp
- 8004080429 Forwards League of Women Voters of Rockford, IL interrogatories & motion seeking ASLB authorization W/o interrogatories CHERRYMM M Cherry, M M /Cherry, Flynn & Konter 80/03/12 ip
- --8004080435 Motion urging presiding officer to issue order requesting NRC to enswer intervenor 800312 interrogatories Proof of Svc encl CHERRY, M M League of Women Voters of Rockford, IL CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter 80/03/12 4pp
- 8004090177 First set of interrogetories Includes questions re intervenors' revised contentions & deviations occurring since issuance of CP Proof of svc encl CHERRYM M League of Women Voters of Rockford, IL CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter 80/03/12 10pp
- 8004100322 Objects to intervenor League of Women Voters of Rockford.IL 800312 first set of interrogatories ASLO has not ruled on admissibility of proposed contentions to which interrogatories refer Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincoln & Beale 80/03/19 3pp
- 8004080428 Motion for order setting 800418 for applicant & 800425 for NRC to respond to Rockford League of Women Voters revised contentions Time is needed to perform pre-liminary evaluation re-possible stipulation Certificate of Svc encl MURPHY.P M Commonwealth Edison Co MURPHY.P M Isham, Lincoln & Beale 80/03/20 4pp
- 8004090448 Order setting 800418 for Comm Ed to respond to League of Women Voters of Rockford revised contentions MILLER, M E. Atomic Safety and Licensing Board Panel. 80/03/26 ip
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSIGKL V Office of the Executive Director for Operations B0/04/02 34pp
- 8004270217 Response to intervenor Rockford League of Women Voters 800310 revised contentions Recommends acceptance of 17 separate contentions & two consolidation contentions. Certificate of 8vc encl KARMANM, GUDDARD, R. J. Hearing Branch 2, 80/04/25 23pp
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8004080397 Forwards affidavit stating that distribution of Amend 25 to FBAR has been made in accordance w/RB Boyd 791020 ltr NAUOHTUN.W F Commonwealth Edison Co BO/04/01 2pp

- @ Inspection reports, 10 Bulletins & correspondence
- 8004280066 Forwards If Insp Repts 50-454/80-02 % 50-455/80-02 on 800207-08 No moncompliance noted FIGRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/06 App
- --8004280074 IE insp Repts 50-454/80-02 \$ 50-455/80-02 on 800207-08 No noncompliance noted Major areas inspected licensee corrective actions on previous insp findings & storage of safety-related mechanical & electrical matls / components WILLIAMS.C C , KONKLIN.J E , JONES.C E Region 3, Chicago. Office of the Director 60/03/04 lipp
- 8004100118 Forwards IE Info Notice 80-09, "States Co Sliding Link Electrical Terminal Block ' No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- 8004280031 Forwards If Insp Repts 50-454/80-03 & 50-455/80-03 on 800220,21 & 27 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/12 App
- --8004280037 IE Insp Repts 50-454/80-03 & 50-455/80-03 on 800220.21 & 27 No noncompliance noted Hajar areas inspected RCPB piping work activities, welding & procedures DANIELSON.D H Region 3. Chicago, Reactor Construction & Engineering Support Branch (EE,E W Region 3, Chicago, Office of the Director 80/03/10 App
- 8004140119 Forwards response to IE Bulletin 80-03, 'Loss of Charcoal from Std Type II.Two-lnch Tray Adsorber Cells " Visual examination determined that contact between casing & screen is adequate to prevent charcoal grainule escape
 PEOPLES.D L Commonwealth Edison Co 80/03/20 Spp
- 8004150159 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PDRV / Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31
- BD04080686 forwards IE Circular 80-05, "Emergency Diese) Generator Lubricating Oil Addition & Onsite Supply "No written response required KEPPLER.J G Region S. Chicago, Office of the Director B0/04/01
- 8004150014 Forwards IE Info Notice 80~13, "OE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02
- 8004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Haiards." inadvertently omitted from 800306 transmittal KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- B004220093 Forwards IE Info Notice B0~14, "Safety Suggestions From Employees " No action required KEPPLER, J 9 Region 3, Chicago, Office of the Director B0/04/02
- 8004220324 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Cil Sys " No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/04/03 to
- 8004220069 Forwards IC Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J 9 Region 3, Chicago. Office of the Director 80/04/09 1p
- 8004230224 Forwards 16 Bulletin 79-03A: "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required KEPPLER, J.G. Region 3. Chicago. Office of the Director 80/04/07
- 8 Reportable occurrences, LERs & related correspondence
- 8004070228 Ack receipt of 800229 second interim rept re failure of post-tensioning tendon field anchor heads Rescheduled date of 800515 for submittal of final rept is acceptable FIORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 60/03/19 Ip

- DOCKET 50-455 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issurnce or NUREG-0588. "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment." providing guidance be methods for compliance ROSS. D.F. Division of Project Management. 80/02/05 7pp
- B004040017 Submits add1 guidance to RUREG-0588, "Interim Staff Position on Environ Qualification of barety Related Electrical Equipment "Requests review or equipment qualification documentation to identify degree of compliance ROS8.D F Division or Project Management 80/02/21 3pp
- 8004230058 Requests info ie auriliary feedwater sys per Bulletins & Orders Task Force review of FMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC applicat prior to issuance of OL Wienci FOSS. D. F. Division of Project Management 80/03/10 S3pp
- 8004(4044) Forwards QA plan implemented during Sept 1979 to Fob 1980 const suspension in response to NRC 800303 request Plan will prevent degradation of quality of safety-related equipment, components & structures
 PEOPLES.D L. Commonwealth Edison Co. 80/03/25 2pp
- --8004140449 OA Plan during eitended const delay CABARD,R., FARR,R.J., MARCUS,G.F. Commonwealth Edison Co 79/10/24 Zipp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A. GA program Revisions reflect recent organization title changes
 NAUGHTON.W F Commonwealth Edison Co. 80/04/02 is
- --8004150328 Revised pages constituting Revision 13 to 9A program Revisions reflect recent diganizational title changes • Commonwealth Edison Co CE-1-A R13 80/04/04 7pp
- F Security, medical, emergency & fire protection plans
- 8004090077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending QAO clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 App
- 8004140115 Forwards request for add1 into consisting of fifth set of round one questions re safeguards contingency plan Encl withheld (ref 10CFR2 790)
 RUBENSTEIN-L S Light Water Reactors Branch 4 80/03/28 2pp
- G Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK.L V Office of the Crecutive Director for Operations 80/04/02 34pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004080397 Forwards affidavit stating that distribution of Amend 25 to FSAR has been made in accordance w/RS Boyd 791020 ltr NAUGHTON, W F Commonwealth Edison Co 80/04/01 23p
- laspection reports, IE Bulletins & correspondence
 -)4110284 Forwards IE Insp Repts 50-496/80-01 & 50-457/80-01 on 300116-17 & notice of violation TIQRELLI, © Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- -8004110271 Notice of violation from insp on 800115-17 * NRC Regional Offices 80/02/27 1p
- --8004110300 IE Insp Repts 50-456/80-01 % 50-457/80-01 on 800116-17 No noncompliance noted failure to property store OA records WILLIAMS, C.C. NRC Regional Offices SCHWEIBINZ, E.R. Region 3, Chicago, Office of the Director 80/02/27 4pp
- BO0410011B Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEFPLER, J G Region 3, Chicago, Office of the Director BO/03/07 in

- 800Ai40ii9 Forward, response to IE Bulletin 80-03, "Loss of Charcoal from 5td Type II, Two-Inch Tray Adsorber Cells " Visual examination determined that contoc' between casing \$\frac{t}{2}\$ screen is adequate to prevent charcoal granule escape PEOPLES.D t. Commonwealth Edison Co. 80/03/20. 5pp
- 8004150159 Forwards IF Into Notice 80-12. "Instrument Failure Causes Opening or PORV & Block Valve" No specific action or response necessary KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/31 to
- 8004080686 forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply "No written response required KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/04/01
- 8004150014 Forwards [E Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/02
- B004180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from 800306 transmattal KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/02
- 8004220093 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J 0 Region 3, Chicago, Defice of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07. "Problems W/HPC1 Turbine Oil Sys " No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/03 in
- 8004220069 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/09
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/07
- DOCKET 50-497 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS.D F Division of Project Management
- B004040017 Submits addl guidance to NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Clectrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSS,D F Division of Project Management 80/02/21 3pp
- 8004230058 Requests info is auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of GL W/encl RGSS,D F Division of Project Management 80/03/10 33pp
- 8004140441 Forwards QA plan implemented during Sept 1979 to Feb 1980 const suspension in response to NRC 800303 request Plan will prevent degradation of quality of safety-related equipment, components & structures
 PEOPLES.D L Commonwealth Edison Co 80/03/25 2pp
- --8004140447 QA Plan during extended const delay CASARO.R , FARR.R J , MARCUS.O F Commonwealth Edison Co 79/10/24 21pp
- 8004150316 Forwards revised pages constituting Revision 13 to CE-1-A, QA program Revisions reflect recent organization title changes
 NAUGHTON, W.F. Commonwealth Edison Co. 80/04/02 ip
- --8004150328 Revised pages constituting Revision 13 to QA program
 Revisions reflect recent organizational title changes
 * Commonwealth Edison Co CE-1-A RI3 80/04/04 7pp

- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAU clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp
- 8004140115 Forwards request for add1 info consisting of fifth set of round one questions re safeguards contingency plan Encl withheld (ref 10CFR2 790) RUBENSTEIN, L S Light Water Reactors Branch 4 80/03/28 2pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004080377 Forwards affidavít stating that distribution of Amend 29 to FSAR has been made in accordance w/RS Boyd 791020 ltr NAUGHTON,W F Commonwealth Edison Co 80/04/01 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 8004110284 Forwards IE Insp Repts 50-456/80-01 & 90-457/80-01 on 800116-17 & notice of violation FIORELLI.Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/29 2pp
- ---8004110291 Notice of violation from insp on 800116-17 * NRC Regional Offices 80/02/27 lp
- ---B004110300 IE Insp Repts 50-456/80-01 & 50-457/80-01 on B00116-17 No noncompliance noted failure to properly store GA records WILLIAMS, C.C. NRC Regional Offices SCHWEIBINZ, E.R. Region G. Chicaga, Office of the Director B0/02/27 4pp
- 8004100118 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/07
- 8004140119 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II, Two-Inch Tray Adsorber Cells" Visual examination determined that contact between casing & screen is adequate to prevent charcoal granule escape PEOPLES D L. Commonwealth Edison Co. 80/03/20 5pp
- 8004180157 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J O Region G. Chicago. Office of the Director 80/03/31
- 8004080686 Forwards IE Circular 80-05, "Emergancy Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/0 Region 3. Chicago, Office of the Director 80/04/01
- 8004150014 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/04/02
- BOO4180030 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Mazards," inadvertently omitted from BO0306 transmittal KEPPLER.J O Region 3, Chicago, Office of the Director B0/04/02
- 8004220093 Forwards IE Info Natice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220324 Forwards IE Circular 80-07. "Problems W/HPCI Turbins Gil Sys " No written response required
 KEPPLER, J G. Region 3. Chicago, Office of the Director 80/04/03

- 8004220069 Forwards IF Bulletin Bir-08 'Exam or Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago Office of the Director 80/04/09
- 8004230224 Forwards IE Bulletin 79-03A, "Longitudinal Weld Derects in ASME SA-312.1ype 304 Stainless Steel Pipe " Action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/07
- DOCKET 50-458 RIVER BEND STATION, UNIT I
- A Application/constitution stage documents & correspondence
- 8004040335 Forwards 3-month test results of Pittsburgh Test Lab Repts 800985 & 800986. "Rept of Potential Alvali Reactivity, ASTM C227 & C-289 " Results within limits for 3 & 6-month test WEIGAND. J G Gulf States Utilities Co 80/01/22 ip
- ~~8004040345 "Rept of Potential Alkali Reactivity.ASTM C227 & C-289 "

 ★ Pittsburgh Testing Laboratory 80/01/15 ip
- --8004040356 "Rept of Potential Alkai Reactivity,ASTM C227 % C-289 " * Pittsbuigh Testing Laboratory 80/01/15 ip
- 8004040363 Forwards 3-month test results of Pittsburgh Test Lab Repts 800785 & 800786. "Rept or Potential Alkali Reactivity. ASTM C227 " Results within limits for 3 & 6-month tests WEIGAND, J G Oulf States Utilities Co 80/01/30 Ip
- --8004040364 "Rept of Potential Alkali Reactivity. AGTM C227 "

 * Pittsburgh Testing Laboratory 80/01/23 lp
- --B004040367 "Rept of Potential Alkali Reactivity.ASTM C227 " * Pittsburgh Testing Laboratory 80/01/23 lp
- GOO4040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 8004040370 Forwards 4-month results of Pittsburgh Testing Lab Repts 800985 & 800986, "Rept of Potential Alkali Reactivity, ASTM C227 & C289 " Results within limits for 3 & 6 Month test durations
 WEIGAND, J G Gulf States Utilities Co 80/02/22 to
- --8004040372 "Rept of Potential Alkali Reactivity, ASTM C227 & C289 " Pittsburgh Testing Laboratory 80/02/12
- --8004040373 "Rept of Potential Alkall Reactivity,ASTM C227 & C289 "
 * Pittsburgh Testing Laboratory 60/02/12 lp
- B004040378 Forwards four-month results of Pittsburgh Testing Lab Repts B00985 & 800984, "Rept of Potential Alkali Reactivity. ASTM C227" Results within limits for 3 & &-month test durations WEIGAND, J G Gulf States Utilities Co 80/02/28 ip
- --8004040384 "Rept of Potential Alkali Reactivity.ASTM C227 "
 * Pittsburgh Testing Laboratory 80/02/20 1p
- --B004040386 "Rept of Potential Alkali Reactivity, ASIM C227 "
 * Pittsburgh Testing Laboratory 80/02/20 Ip
- 8004180102 Notifies NRC that shop mods are being made to reactor pressure vessel Work involves plugging control rod driveling return majzle 8 ieplacement of safe-ends or feedwater & recirculation majzles
 WEIGAND, J G Gulf States Utilities Co 80/03/14 ip
- F Security, medical, emergency & fire protection plans
- 8004090077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp

6 Adjudatatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA is prompt improvement in radiological energency planning A preparedness, distributed as Sound notification GOSSICK.L V Office or the Executive Director for Operations 80/04/0≥ 34pp

1 Financial information

8004210182 Forwards Annual Financial Rept 1979 WEIGAND, J. G. Gulf States Utilities Co. 80/04/14 ip

--8004210185 Annual Financial Rept 1979
* Gulf States Utilities Co 80/04/14 35pp

M Antitrust correspondence

8004230466 Comments on antitrust review re Cajun Electric Power Cooperative.Inc ownership interest in facility.on behalf of the Consumer League.Inc Commission should request add) info & hold hearings to determine it antitrust implications exist IRVING.S M. Public Law Utilities Group. 80/04/18 13pp

O Inspection reports, IF Bulletins b correspondence

8004040106 Confirms 800215 telcon advising that no proprietary info contained in 1E lnsp Rept 50 450/79-08 WEIGAND, J G Gulf States Utilities Co 80/02/15 ip

8004010018 Responds to IE Bulletin 79-28, "Possible Maifunction of NAMCO Model EA180 Limit Switches at Elevated Temps " No suitches purchased or intended to be purchased for use at facilities WEIGAMID. J G Oulf States Utilities Co 80/02/28 to

8004010023 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys " No relays referred to in bulletin are to be used in facility WEIGAND, J G Gulf States Utilities Co 80/02/28 ip

8004010041 Responds to IE Builetin 79-02. Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "Concrete block walls in sessaic Category 1 % 2 structures shall not be designed to support pipes or sys WEIGAND. J G Gulf States Utilities Co 80/02/28 2pp

8004140046 Forwards IF Investigation Rept 50-458/80-03 on 800212-15 No noncompliance noted SEIDLE,N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/02/28 2pp

--8004140049 IE Investigation Rept 50-458/80-03 on 800212-15 No noncompliance noted Major areas inspected allegations re conflict between const cost & nuclear safety CROSSMAN,W A . OBERG.C R Region 4. Dalias. Office of the Director 80/02/26 8pp

8004220206 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/02 in

8004220288 Forwards IE Carcular 80-07. "Problems W/HPCI Turbine Oil Sys " No written response required SEYFRIT.X V Region 4. Dallas. Office of the Director 80/04/03 is

1004220770 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 6A-312.Type 304 Stainless Steel Pipe " Action required SEYFRIT.X V Region 4. Dallas, Office of the Director 80/04/04 p

8004220237 Forwards IF Bulletin 80-08. "Exam of Containment Liner Penetration Weids" Written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/07

R Periodic operating reports & related correspondence

8004280539 Forwards "1979 Groundwater Usage & Industrial Growth Burvey " Rept constitutes third submittal in fulfillment of PSAR commitment WEIGAND.J G Gulf States Utilities Co 80/04/21 1p

- --8004280543 "1979 Groundwater Usage & Industrial Growth Survey " WEIGAND, J. G. Gulf States Utilities Co. 80/04/21 23pp
- S Reportable occurrence. LERs & related correspondence

8004040056 Advises of commitment to rework questionable weld areas as final resolution of reportable deficiency reimfg of containment to embedment-plate T-welds StW & Graver Energy Sys.Inc. assessments of deficiency encl
WEIQAND.J G Gulf States Utilities Co 80/02/01 1p

--8004040057 Interim deficiency rept re subsurface defects in containment corner junction T-welds Caused by undestrable weld nugget or bead shape deposited at roof Resultant cavity areas will rewelded KIRKEBO, J.A. Stone & Webster Engineering Corp. 80/01/14 54pp

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREC-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance remethods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp

F Security, medical, emergency & fire protection plans

8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp

Q Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 90891CK.L V Office of the Executive Director for Operations 80/04/02 34pp

I Financial information

8004210182 Forwards Annual Financial Rept 1979 WEIGAND, J G Oulf States Utilities Co 80/04/14 ip

--8004210185 Annual Financial Rept 1979
* Oulf States Utilities Co 80/04/14 35pp

G Inspection reports, IF Bulletins & correspondence

8004010016 Responds to IE Bulletin 79-28, "Possible Malfunction of NAMCO Hodel EAIBO Limit Switches at Elevated Temps" No switches purchased or intended to be purchased for use at facilities
WEIOAND. J G Gulf States Utilities Co 80/02/28 ip

8004010023 Responds to IF Bulletin 79-25, "Failures of Westinghouse BFD Relays in Bafoty-Related Gys " No relays referred to in bulletin are to be used in facility WEIGAND, J G Gulf States Utilities Co 80/02/28 ip

80040i004f Responds to JF. Builetin 79~02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "Concrete block walls in seismic Category 1 & 2 structures shall not be designed to support pipes or sys WEIGAND, J G Oulf States Utilities Co 80/02/28 2pp

8004220206 Forwards IE Info Notice 80-14, "Safety Suggestions From Emplayees " No action required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/02 ip.

80042202BB Forwards IE Circular BO-07, "Problems W/HPCI Turbine Oil Sys " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director BO/04/03 ip

8004220770 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required SEYFRIT.K V Region 4, Dallas, Office of the Director BO/04/04 ip

- 8004220237 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required SEYFRITIK V Region 4, Dallas, Office of the Director 80/04/07
- R Periodic operating reports & related correspondence
- B004280539 Forwards "1979 Groundwater Usage & Industrial Growth Survey " Rept constitutes third submittal in fulfillment of PBAR commitment WEIGAND, J G Gulf States Utilities Co B0/04/21 1p
- --8004280543 "1979 Groundwater Usage & Industrial Growth Survey " WEIGAND, J G - Gulf States Utilities Co - 80/04/21 23pp
- S Reportable occurrences, LERs & related correspondence
- BD04040056 Advises of commitment to rework questionable weld areas as final resolution of reportable deficiency re mfg of containment to embedment-plate T-welds S&W & Graver Energy Sys. Inc assessments of deficiency encl
 WEIGAND, J G Gulf Status Utilities Co B0/02/01 ip
- --8004040057 Interim deficiency rept re subsurface defects in containment corner junction Y-welds Caused by undesirable weld nugget or bead shape deposited at roof Resultant cavity areas will rewelded KIRKEBG.J A Stone & Webster Engineering Corp. 80/01/14 54pp
- DDCKET 50-460 MPPSS NUCLEAR PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re mothods for compliance ROSS D F Bivision of Project Management 80/02/05 7pp
- 8004210408 Requests addl info rv changes & studies proposed in App F of 791203 reply to NRC 791025 10CFR50 54 requests concerning design adequacy of B&W NSSS utilizing once-through steam generators
 PARR.O D Light Water Reactors Branch 3 80/03/25 6pp
- 8004280619 Advises that 791220 request for approval of alternative test method to verify max moisture in low hydrogen electrode coating is accepted Requests that notarized version of request be sent in addition to specific sites for use RUBENSTEIN.L S Light Water Reactors Branch 4 80/04/04 5pp
- B004160289 Advises of fundamental misstatement in B00402 minutes of 800104 meeting w/util re GA program unionization Requests correction to reflect that fact had no influence on Local 598 election REYNOLDS,N 8 Debeyoise & Liberman 80/04/19 ip
- 8004210285 Responds to 800221 itr re-schedule for completing review of qualification of safety-related electrical equipment Schedule for completion of review will be provided after final issuance of NUREO-0588 RENDEROER, D.L. Washington Public Power Bupply System 80/04/11 in
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 ORIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- Q Adjudicatory correspondence
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparadness, distributed as Board notification QUBSICKL V Office of the Executive Director for Operations BO/04/02 34pp
- G Inspection reports. IE Bulletins & correspondence
- BO04280083 Forwards IE Insp Repts 50-460/80-02 & 50~513/80-02 on B00211-15 No noncompliance noted BPENGER. G S Region 5, San Francisca, Reactor Construction & Engineering Support Branch 80/03/17 2pp

- --8004280094 IE Insp Repts 50-460/80-02 & 50-513/80-02 on 800211-15 No noncompliance noted Major areas inspected safety-related components, safety-related piping installation, welder training & weld filler matl control DODDS, R T Region 5. Sam Francisco, Reactor Construction & Engineering Support Dranch McGNER, W J , HAIST, D P Region 5. San Francisco, Office of the Director 80/03/18 Bpp
- 8004150220 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENSELKEN.R H Region 5. San Francisco. Office of the Dijector 80/03/31 ip
- 8004100109 Forwards IE Circulai 80-05, 'Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written résponse required ENGELKEU.R H Region 5, San Francisco. Office of the Director 80/04/01 lp
- 8004110119 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required ENGELMEN.R H Region 5, San Francisco, Office of the Director BD/04/02 10
- 8004220052 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required EMGELKEN.R H Region 9, Ban Francisco, Office of the Director BD/04/02 1p
- B004180139 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Oil Sys " No written tesponse required ENGELKEN,R H Region 5. San Francisco. Office of the Director B0/04/03 lp
- 8004230370 Forwards IE Bulletin 79-03A. "Longitudinal Held Defects in ABME 8A-312, Type 304 Stainless Steel Pipe" Action required EMCLKEN, R H Region 5, San Francisco, Office of the Director BD/04/04 1p
- 8004220201 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required ENOBLEMIA H Region 5, San Francisco, Office of the Director BO/04/07 Ip
- 8004230239 Ack receipt of 800318 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-460/79-13 & 50-513/79-13 SPENCER, 0 S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/04/08 1p
- --B004230248 Responds to NRC B00228 ltr re violations noted in [E Insp Repts 50-460/79-13 % 50-513/79-13 Corrective actions identified & described nature & extent of referenced administrative & security controls RENBERGER.D L Washington Public Power Supply System 80/03/18

- OCCRET 50-461 CLINION POWER STATION, UNIT 1

 A Application/construction stage focuments & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Qualification of Parety-Related Electrical Equipment," providing guidance to methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004150225 Forwards LRv. 800118 * 0211 lins to GE discussing analysis of boil off rates mods to BWR control rad drive return line noirles to prevent cracking Mods should not be performed before issuance of NNREG-0619 or w/o NRC guidance STOLY, J.F. Light Water Reactors Branch 1 80/03/07 2pp
- 8004100301 Notification of 800403 realing w/GE in Bethasda, MD to discuss BWR & hafety relief valves and by G Dickens & Co & supplied by GE to facilities HENDERSCH J B Division of Reactor Construction Inspection BO/03/13 2pp
- 8004010249 Forwards comments on NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," in response to NRC 800205 ltr Certain sections need revision 2 clarification WULLER, G E Illinois Power Co 80/03/24 App
- F Security, medical, emergency / fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 QRIMES,B K Emergency Preparedness Task Force 80/03/11 4pp
- 8004010328 Submits evacuation time estimates in response to NRC 800226 1tm Map of area and WULLER, G E Illinois Power Co 80/03/24 4pp
- Q Adjudicatory correspondence
- 9004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK/L V Office of the Executive Director for Operations 80/04/02 34pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004100138 Forwards IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block" No specific action or response required KEPPLER. J. G. Region 3. Chicago, Office of the Director 80/03/07
- BO04140109 Responds to IE Builotin 79-09. "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " GE type AK-2 circuit breakers will not be used with any safety-related sycs at facility HULLER.G E 11] inois Power Co 80/03/24 ip
- 8004;50190 Responds to IF Bulletin 80-03 re charcoal adsorber cells Liscensee does not use adsorber trays discussed in bulletin but uses vertical gasketless adsorbers mfg by American Air Filter Co MULLER, G E Illinois Power Co 80/03/24 fp
- 8004150175 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary MERPLERIJ & Region 3. Chicago. Office of the Director 80/03/31
- 8004080714 Forwards IE Circulai 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER.J G. Region G. Chicago, Office of the Director 80/04/01
- 8004150045 Forwards IE Info Natice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02

- 8004180052 Forwards attachments to IE Circular 80-03, "Protection From Tour Gas Hazards, inideertently omitted from 800306 transmittal VEPPLER, J & Region 3. Chicago, Office of the Director 80/04/02
- BOO4220142 Farwards IE Info Notice 80-14, "Safety Suggestions From Employers" No action required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/02 to
- 8004220368 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Sys " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/03
- 8004110042 Forwards IF Bulletin 80-07, "BWR Jet fump Assembly Failure " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/07
- 8004230266 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director BO/04/07
- 8004220149 Forwards IE Bullstin 80-08. "Exam of Containment Liner Penetration Welds " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/09
- S Reportable occurrences, LFRs & related correspondence
- 8004040039 PND-111-80-053 on 900318 pipefitter working on turbine bldg roof drain piping fel) from 65 ft scaffolding, hitting crane support girder & was killed MESCOTTH , KKOP,R C , FIORELLI,O Region 3, Chicago, Office of the Director 80/03/19 ip
- 8004300048 Act receipt of 800331 interim deficiency rept re incorrect soil characteristic value FIGRELLI,9 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/14 1p
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0388. "Interim Staff Position on Environ Qualification of Safety-Related Cleatrical Equipment." providing guidance re methods for compliance RDSS.D F Division of Project Hanagement 80/02/05 7pp
- B004150225 Forwards NRC 800128 to 0211 ltrs to 0E discussing analysis of boil off rates mods to BWR control rod drive return line nozzles to prevent cracking Mods should not be performed before issuance of NUREG-0619 or w/o NRC guidance STOLZ.J F Light Water Reactors Branch 1 80/03/07 2pp
- 8004100301 Notification of 800403 meeting w/QE in BethesdarMD to discuss BWR & safety relief valves mfg by G Dickens & Co & supplied by QE to facilities HENDERSON.J B Division of Reactor Construction Inspection 80/03/13
- 8004010249 Forwards comments on NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," in response to NRC 800205 ltr Certain sections need revision & Clarification WULLER, O E Illinois Power Co 80/03/24 App
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested Sy NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 ORIMES.B K Emergency Preparedness Task Force 80/03/11 App
- 8004010328 Submits evacuation time estimates, in response to NRC 800226 ltr Map of area encl MULLER.O E 111mois Power Co 80/03/24 4pp

- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning a preparedness distributed as Board notification GUSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- Q Inspection reports, IE Bulletins % correspondence
- 8004100138 Forwards IE Info Notice 80-08. "States Co S)iding Link Electrical Terminal Block " No specific action or response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/07
- 8004140107 Responds to IE Bulletin 79-09, "Failures of QE Type AK-2 Circuit Breaker in Safety-Related Sys " QE type AK-2 circuit breakers will not be used with any safety-related sycs at facility MULLER.0 E Illinois Power Co 80/03/24 1p
- 8004150190 Responds to IE Bulletin 80-03 re charcoal adsorber cells Liscensee does not use adsorber trays discussed in bulletin but uses vertical gasketless adsorbers mfg by American Air Filter Co WULLER.O E Illinois Power Co 80/03/24 1p
- 8004i50i75 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J Q Region 3, Chicago, Office of the Director 80/03/31
- 8004080714 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/04/01
- 8004150045 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/04/02
- 8004180092 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently emitted from 800306 transmittal KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220142 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER.J Q Region 3. Chicago. Office of the Director 80/04/02
- B004220368 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Cil Bys " No written response required KEPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004110042 Forwards IE Bulletin 80-0/, "DWR Jet Pump Assembly Failure " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/07 io
- 8004230266 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312,Type 304 Stainless Steel Pipe" Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/07 ip
- 8004220144 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/09

DOCKET 50-443 FULTON GENERATING STATION, UNIT 1

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSBICKL V Offica of the Executive Director for Operations BO/04/02 34pp

- DOCKET 50-464 FULTON GENERATING STATION, UNIT 2
 G Adjudicatory correspondence
- 8004030026 Nemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning % preparedness distributed as Board Hotification GOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT I
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Ejectrical Equipment," providing guidance le methods for compliance RUSS, D.F. Division of Project Management 80/02/05 7pp
- 8004010242 Forwards "Environ Assessment & Responses to NRC Questions Transportation of Reactor Pressure Vessel," prepared by Dames & Moore MCGUIRE.W F Houston Lighting & Power Co 80/03/26 3pp
- --B004010250 "Environ Assessment & Responses to NRC Guestions Transportation of Reactor Pressure Vessel " * Dames & Moore 4490-057-12 80/03/31 70pp
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda, MD re evaluation of progress made to date establishing proposed requirements stemming from THI-2 accident
 THOMAS, C.O. Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800317 meeting w/near-term CP applicants in Bethasda, MD re resumption of CP application review activities associated w/TM1~2 accidents THOMAS, C O Standardization Branch 80/04/03 12pp
- 8004240557 Summary of 800402 meeting w/Near-Teim CP Applicants Group in Bethesda,MD re progress made establishing proposed requirements stemming from TMT-2 accident Proposed requirement category assignments enct THOMAS:C II Light Water Reactors Branch 1 80/04/07 47pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- BD04150076 Forwards assessment of impact of proposed facility on endangered species residing or migrating throughout site Project will not affect endangered species & no further assessment is necessary BALLARD, R L Environmental Projects Branch 1 80/04/02 3pp
- G Adjudicatory correspondence
- 8004080244 Requests that Public Utils Board provide full & complete answers to incomplete interrogatories COPELAND.J G Baker & Botts 80/02/07 2pp
- 8004020232 Response to JF Daherty twelfth request for production of documents NEOO 23, 785; NEOO 21, 778; APED 5750, 1 & 2 & NEOO 20, 358A available for insp & copying Remaining documents not available Certificate of 8vc encl
 BIDDLE, C T . NEWMAN. J R Houston Lighting & Power Co BIDDLE, C T Baker & Botts 80/02/28 App
- BOO4140281 Response by State of TX to fourth set of interrogatories Includes info re availability of natural gas & impact of air quality on fue) switching Cortificate of Svc encl LOWERRE.R W Texas, State of 80/02/28 7pp
- 800410007B Responds to seventh set of interrogatories Includes info re MSIVs. feedwater pumps & possible hydrogen explusion in TMI-2 containment during accident Notice of appearance of D Hancock on behalf of util & Certificate of Svc encl HANCOCK D Houston Lighting & Power Co HANCOCK, D Baker & Botts 80/03/03 2ipp
- BDD409010D Requests to make limited appearance statement at next public meeting on behalf of Citizens Antinuclear Info Team BISHOP, M Affiliation Unknown 80/03/05 ip

- 6004140415 Answers to intervenor of Doheity second request for admissions Includes questions ie authenticity of certain documents b info concerning GF diesel generators Certificate of Exc encil
 BIDDLE.C T Houston Lighting 3 Power Co RIDDLE.C T Baker & Botts 80/03/07 9pp
- 8004100532 Response to eighth set of interrogatories Includes inforce control room displays for valves to other manually apparated renotely controlled instruments Certificate of Svc encl HANCOCK, D. Houston Lighting & Power Co. HANCOCK, D. Baker & Botts 80/03/10. 19pp
- 8004080687 Response to thirteenth set of interrogatories Includes infore weight of thermal shielding & insulation in drivell & in containment bldg Certificate of Svc encl SIDDLE.C T Houston Lighting & Power Co BIDDLE.C T Baker & Botts 80/03/11 26pp
- 800411055: Intervenor Contention 47 Applicant main generator turbine is not designed sufficiently to prevent turbine missiles from damaging critical components of sys Certificate of Syc encl DOMERTY, J.F. Affiliation Unknown 80/03/12 2pp
- B004210153 Notice of appeal from ASLB B00310 order rejecting WJ Schuessier Contentions 1,2,3 % 5-(3 Requests extension, Until B00325 to file amend to appeal re admissibility of contentions SCHUESSLER.W J. Affiliation Uningum. B0/03/20 ig
- BOO4100557 Response to intervenor JF Doherty fifteenth request for documents firsts documents available for insp & copying at applicant Energy Development Complex in Houston, TX Certificate of Svc encl
 BIODLE, C T Houston Lighting & Power Co BIDDLE, C F Baker & Botts 80/03/21 Soo
- B004230024 Notice of intent to appeal ASLB 800310 order rejecting B Bater 790918 Contention 2 re cost/benefit analysis BAKER:B Affiliation Unknown 80/03/21 4pp
- 8004240548 Requests reversal of ASLB 800311 denial of FH Potthoff petition to intervene Latitude should be granted to layperson authoring legal document Supports admittance of contention re marine biomass energy production DOHERTY, J F Doherty, J F 80/03/21 3pp
- ---8004240555 Submits Contention 5 re need for power & contention re biomass production operating marine biomass farm would be environmentally preferable to nuclear plant ASLB should deny CP under NCPA POTTHOFF.F. H Affiliation Unknown 79/06/01 2pp
- 8004030076 Memorandum / order dismissing MJ Behvessler appeal re ASLB B00310 order rejecting majority of intervenor contentions Rules of practice do not permit interlocutory appeal unless petition is denied in entirety BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/25
- 800424018B Response in opposition to JF Doherty motion seeking applicant admission of Contentions 20,25,26,30,31,40,41,43 & 44 Motion is w/o substance re timely request Relevance to FOIA requests not clear W/Certificate of Svc COPELAND, JO, NEWMAN, JR Houston Lighting & Power Co COPELAND, JO, NEWMAN, JR Houston Lighting & Power Co COPELAND, JO, NEWMAN, JR Botts 80/03/26 7pp

- BOO4230022 Response in opposition to intervenor JF Daherty second motion to compel further responses to interrogatories Clarifies previous objections & urges ASLB to deny motion to compel for being deficient Certificate of Svc encl BIDDLE.C T., NEWHAN, J. R. Houston Lighting & Power Co. BIDDLE.C T Baker & Botts.
- 8004230035 Response in support or R Potthoff appeal re denial of petition to intervene Potthorf contention should be regarded as allegation that EIS did not address biomass conversion W/Certificate of Svc SCOTT.J Teras Public Interest Research Gloup 80/03/31 3pp
- 8004080016 Response in opposition to JF Doherty 800312 Contention 47 returbine design inadequaties NRC safety evaluation concluded likelihood of resultant radioactive release sufficiently small W/Certificate of Svc SOHINKI,S M Hearing Branch 3 80/04/01 4pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emoigency planning & preparedness, distributed as Board notification GOSSICK.L V Diffice of the Executive Director for Operations CAMM.F Federal Emergency Management Agency 80/04/02 34pp
- BOO424053B Motion for issuance of protective order re TX PIRO request for public disclosure of util Jan 1980 rept, "South TX Nuclear Project GA & QC, Mgt Assossment Burvey for Brown & Rook Inc " Draft protective order & Certificate of Bvc encl BIDDLE,C Y Houston Lighting & Power Co 80/04/02 9pp
- B00415018: Discusses JF Doherty B0032: appeal on behalf of FH Potthoff Pro se intervenor has no standing to assert rights of another party per Project Mgt Corp case Doherty appeal should be treated as brief in support of Potthoff appeal SOHINKI.S M Hearing Branch 3 80/04/07 2pp
- 8004170307 Brief in opposition to FH Potthoff 800326 appeal Urges affirmation of ASLB 800310 order denying petition to intervene Contention is economic in nature & need not be considered per 1978 ALAP-458 Certificate of Svc encl SOHINKI,S M Hearing Branch 3 80/04/07 10pp
- 8004100474 Appeals ASLAB 800320 decision to deny standing on Contention 6 re environ preferability of biomass farm to nuclear plant Biomass farm would release less radioactivity to environ & would alter landscape less
 POTTHOFF:F H Affiliation Unknown 80/04/08 2pp
- 8004230055 Order directing that discovery re intervenor J Doherty Contention 47 be initiated & completed in 120 days after svc on ASLB 800310 order TX PIRO 800314 motion re consolidation granted J Doherty 800318 motion denied WDLFC.S J , LINENBERGER, G Atomic Safety and Licensing Board Panel 80/04/10 5pp
- 8004230094 Order advising intervenor J Doherty to reply to NRC & applicant answers to Doherty 800408 motion re Contentions 48 % 49, within 10 days of answers ASLB should be immediately notified if replies are not to be filed WOLFE.8 J Atomic Safety and Licensing Board Panel 80/04/14 tp
- BOO4300403 Response to JF Doherty BO0407 new Contentions 48 & 49 & amend to Contention 17 Urges admittance of Contention 48 & demial of both Contention 47 & amend to Contention 17 Certificate of Svc encl WOODHEAD.C P Hearing Branch 3 BO/04/28 17pp

DOCKET STN-50-470 CESSAR SYSTEM BO

- A Application/construction stage documents & correspondence
- 8004110522 Advises of docketing of facility FSAR Forwards FR notice of receipt of standardized FSAR KANE,W F Btandardizetion Branch B0/03/06 1p
- DOCKET 80-471 PILORIM NUCLEAR POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0598, "Interim Staff Position on Environ Ovalification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RUSS, D.F. Division of Project Management 80/02/05 7pp
- 8004280167 Forwards video taps of fuel assemblies in fuel pool provided by util on 800321 for NRC review W/o encl ORIER.8 H Region i, Philadelphia. Office of the Director, 80/03/31 ip

- 8004210405 Summary of 800328 meeting w/hear-term CP applicants in Bethesda MD re evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident
 - THOMAS, C O Standardization Branch 80/04/03 43pp
- B004300074 Summary of B00319 meeting w/near-term CP applicants in Bethesda.MD re resumption of CP application review activities associated w/TMI-2 accidents THOMAS.C 0 Standardization Branch 80/04/03 12pp
- 8004240557 Summary of 800402 meeting w/Near-Term CP Applicants Group in Bethosda.MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl TMOMAB,C O Light Water Reactors Branch 1 80/04/07 47pp

G Adjudicatory correspondence

- 8004090412 Order re review of statements filed in response to ASLB 800117 order re emergency plaining hearing Directs parties to advise ASLB within 30 days re filing time of testimony & skhibits, in preparation for hearings 9000HDPE, A C Atomic Safety and Licensing Board Panel 80/03/27 2ng
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK, U Office of the Executive Director for Operations
- 8004270237 Provides info in response to ASLB B00327 order re emergency planning testimony NRC is awaiting evacuation time estimates for future nuclear plant areas in order to perform analysis No specific schedule can presently be made QUDDARD, R J Hearing Branch 2 B0/04/25 2pp

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance, ROSB, D F Division of Project Management 80/02/05 7pp
- 8004040016 Forwards request for add1 info to complete review of QA program PARR: D Light Water Reactors Branch 3 80/03/20 App
- 8004110577 Advises that tendered application for OL is being sent under separate cover Due to TMI priorities.acceptance review will be performed in late spring or early summer SOUDER.J L Division of Rules and Records 80/03/26 ip
- 8004i80352 Forwards add1 info re std plant QA programs for design & const. in response to NRC 800i22 request Util commits to Reg Quide 1 94 w/exception of requirements re structural boit tightening & number of threads exposed beyond nut BEIKEN.8 J Standardized Nuclear Unit Power Plant System 60/04/14
- 8004280463 Updates 800401 meeting w/util & NRC re OL applications Bubmits program for start of NRC review.including initial meeting w/util project manager Applicants exploring other steps to aid NRC review PETRICK.N A Standardised Nuclear Unit Power Plant System 80/04/23 2pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAO clearance under Federal Repts Act GRIMES,B K. Emergency Preparedness Task Force 80/03/11 4pp
- Q Adjudicatory correspondence
- 8004040268 Order granting extension until 800321 for Commission to elect whether to review director's 800131 decision denying relief under 10CFR2 206 CHILM, 8, J. Office of the Secretary of the Commission 80/03/14

- 8004030026 Hemorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning to preparedness distributed as Board notification GDSBICK. V Office of the Executive Director for Operations 80/04/02 34pp
- I Financial information
- BOO40904B2 Annual Financial Rept 1979
 # General Public Utilities GPU Service Corp 80/04/03 44pp
- --8004070483 "Proposal to Conduct Analysis of Strategic Options for JCP&L ' * Anthur Young & Co 80/02/29 125pp
- BOO4220730 Forwards Annual Financial Repts 1979 Certificate of Svc encl KDESTER, C L Kansas Gas / Flectric Co BO/04/15 19pp
- ---8004220747 Annual Financial Rept 1979 * Kansas Gas & Electric Co 80/03/03 36pp
- --8004220759 Annual Financial Rept 1979 * Kansas Gas & Electric Co 80/02/13 32pp
- M Antitrust correspondence
- B004030207 Informs that review of available info has disclosed no basis for conclusion that antitrust hearing is necessary re KS Gas & Electric ownership of 195 MKT share in Unit i
 LITVACK.S M Justice.Dept of Attorney General's Office B0/03/28
- 8004110121 Forwards DOJ Atty General 800328 ltr providing addl antitrust advice per Atomic Energy Act, re CP application Advice in guestion has been transmitted to FR for publication TOALSTON, A Antitrust & Indemnity Group 80/04/02 ip
- --8004110139 Submits add1 antitrust advice per Atomic Energy Act,rs CP application Licensee agreement to accept license conditions mads antitrust hearing unnecessary LITVACK.S M Justice.Dapt of 80/03/28 ip
- G Inspection reports: IE Bulletins & correspondence
- B004010030 Supplements util 771108 response to IE Bulletin 77-02, "Potential Failure Mechanism in Certain Mestinghouse AR Relays "Relays not used in safety-related applications KDEBTER.G L Kansøs Gos & Electric Co 80/02/12 lp
- 8004100280 Responds to IE Bulletin 79-28 Investigation re planned use of NAMCO EAIBO switches, identification in SNUPPS design & development of plans for corrective action requires more time than anticipated Will forward response later PETRICK, N A Brandardized Nuclear Unit Power Plant System 80/03/06 ip
- 8004240218 Forwards IF Info Notice 80-14, "Safety Suggestions From Employees" No action required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/02 in
- 8004220257 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/03 to
- 8004230392 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe " Action required ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/04 1p
- 8004220241 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/07 in
- S Reportable occurrences, LERs & related correspondence
- 8004040267 Forwards supplemental rept on potential deficiency re qualification of control sys discussed in util 790928 ltr No unrespived safety concerns re pressure controllers & main steam line atmospheric relief valve PETRICKIN A Standardized Nuclear Unit Power Plant System, pp.09265 200

- B004040264 Discusses incorrect testing or concrete test cylinders on Timous-Olson test machine Twelve-Inch head was used when head no longer than 10-Inches should have been used Indicated strength was probably not significantly affected KGESTER.O L Kansas Gos "Electric Co 80/02/08 ip
- 8004100533 Ack receipt of 800205 interin deficiency rept re qualification of control sys CARLSOWR T Region 1, Philadelphia, Reactor Construction & Engineering Support Granch 80/02/21 ip
- 8004090127 Ack receipt or 800215 final deficiency mept he Huskin Mfg Co fire dampers CARLSOMR T Region (Philadelphia, Office of the Director BO/03/04 ip
- 8004010034 Interim deficiency rept re out-of-tolerance threads for NSSS support anchor bolt nots Analytical bempirical test data will be correlated to establish more precise methods for determining strongth of threads on not KOESTER, G.L. Kansas Gas & Electric Co. 80/03/05 2pp
- BO04170172 Followup deficiency reptile broken actuator shaft of NAMCO furnished limit switch installed on anchor Darling main steam isolation valve Fillore attributed to excessive force applied during shipping/handling No generic deficiency KOESTER.G ! Fansas Gas * Electric Co 80/03/13 ip
- B004150179 Discusses undetectable railurs in engineered safety features actuation sys Utils are investigating hardware changes that may proclude further testing provided that changes are feasible Otherwise, tests will continue PETRICK.N A Standardized Nuclear Unit Power Plant System B0/03/20 ip
- B004070292 Third interim deficiency rept re flood damaged equipment Many valves & pumps cleaned & inspected Rework of electrical items & preassembled piping formations will continue through 1980 KOESTERNG L. Mansas Oas & Electric Co. 80/03/31 2pp
- 8004150369 Interim deficiency rept re vertical fire dampers furnished by Ruskin Mfg Co Addl problems identified requiring new design mods Mods being developed & will be described in rept to be issued by 800515 PETRICK.II A Standardized Nuclear Unit Power Flant System 80/04/03 2ac
- DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of Issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.DF Division of Project Management 80/02/03 7pp
- 8004070189 Forwards request for add1 info to complete review of OA program
 PARR.D D Light Water Reactors Breach 3 80/03/20 App
- 8004180352 Forwards add1 info re std plant QA programs for design & const. in response to NRC 800122 request Util commits to Reg Guide 1 74 w/exception of requirements re structural boilt tightening & number of threads exposed beyond nut SEIKEN.8 J Standardized Nuclear Unit Fower Plant System 80/04/14
- 8004280463 Updates 800401 meetsing w/util 8 NRC re OL applications Submits program for start of NRC review including initial meeting w/util project manager Applicants exploring other steps to aid MRC review PETRICKIN A Standardized Nuclear Unit Power Plant System 80/04/23 2pp
- F Security, medical, emergency t fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 itr. has been postponed pending GAO clearance under Federal Repts Act
 ORIMES.B.K Emergency Preparedness Task Force 80/03/ii 4pp
- H Ceneral correspondence
- 8004070070 Discusses NRC program of upgrading emergency preparedness in anvirons of nuclear power plants in response to 800102 ltr. Bys for alerting public must be demonstrated effective prior to OL issuance.

 DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/17 ip

- --8004070071 Expresses concern re proposed evacuation plan for facility Alerting farmworkers to emergency within required time would be difficult UEILL.6 M Affiliation Unknown 80/01/0⊇ 1p
- Q Inspection reports, 18 Bulletins & correspondence
- 8004040060 Forwards IF Insp Rept 50-489/79-16 on 791203-21 & notice of violation FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/12 2pp
- --8004040061 Notice of violation from insp on 791203-21
 # Region 3, Chicago, Office of the Director 80/02/07 ip
- --8004040062 IE Insp Rept 50-483/79-16 on 791203-21 Noncompliance noted tailure to follow prescribed procedure re measurement of purge flow rate during welding of root pass HANSER, W H. KNOP, R C. Region 3, Chicago, Office of the Director 80/02/07 5pp
- B004070167 Forwards IE Insp Rept 50-483/80-02 on 800123-25 & notice of violation FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8004070171 Natice of /iolation from insp on 800123-25

 * Region 3. Chicago, Office of the Director 80/02/11 ip
- --8004070173 IE Insp Rept 50-483/80-02 on 800123-25 Noncompliance noted failure to maintain low hydrogen electrodes in heated containers when welder was not working in inaccessible area DANIELSON.D H Region 3. Chicago, Reactor Construction & Engineering Support Branch CORDERO.Z. LEE.E W K Region 3, Chicago, Office of the Director 80/02/11 5pp
- 8004100280 Responds to 1F Bulletin 79-28 Investigation re planned use of NAMCO EA180 suitches, identification in SNUPPS design & development of plans for corrective action requires more time than anticipated Will forward response later PETRICK: N A Standardized Nuclear Unit Power Plant System 90/03/04 ip
- 800410014B Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/07 ip
- B004040064 Forwards 1E Insp Rept 50-483/80-06 on B00227-29 & notice of violation F1GRELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004040071 Notice of violation from insp on 800227-29
 * Region 3. Chicago, Office of the Director 80/03/12 ip
- --8004040079 IE Insp Rept 50-483/80-06 on 800227-29 Noncompliance noted failure to follow site procedures re poor vibration practices
 HAYES.D W Region 3. Chicago. Reactor Construction & Engineering Support Branch SCHAPER.J F. LANDSMAN.R B Region 3. Chicago.
 Office of the Director 80/03/12 5pp
- 8004150192 Forwards IE Info Notice 90-12. "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/31 ip
- 8004080725 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/04/01
- 9004110318 Ack receipt of 800314 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50~883/80~02 FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/01 ip
- --8004110327 Responds to NRC 800215 ltr re violation noted in IE Insp Rept 50-483/80-02 Corrective actions work procedure WP-503 has been revised to reflect OA manual requirements allowing electrodes to be taken from portable heaters for 4-h BRYAN.J K Union Electric Co 80/03/14 3pp

- 8004150057 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER.J G Region 3, Chicago, Ofrice of the Director 80/04/02
- 8004180063 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards." inadvertently omitted from 800306 transmittal KEPPLER.J G Region 3, Chicago. Orfice of the Director 80/04/02
- 8004220153 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02
- 8004220388 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Dil Bys "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/03
- 8004230282 Forwards IE Bulletin /9-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/07
- 8004220098 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required XEPPLER, J O Region 3, Chicago, Office of the Director 80/04/09
- 8004300166 Notification of 800423 meeting in Fulton, MO to discuss resident inspector program KEPPLER, J G Region 3, Chicago, Office of the Director BO/04/14
- --8004300178 Notification of 800423 meeting in Culton,MD to discuss resident inspector program KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/14
- --8004300184 Notification of 800423 meeting in Fulton.MD to discuss resident inspector program KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/14
- --8004300189 Notification of 800423 meeting in Fulton, MO to discuss resident inspector program KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/14
- --8004300194 Notification of 800423 meeting in Fulton, MC to discuss resident inspector program Agenda encl KEPPLER.J Q Region 3. Chicago, Office of the Director BO/04/14
- S Reportable occurrences, LERs & related correspondence
- 8004040269 Forwards supplemental rept on potential deficiency re qualification of control sys discussed in util 790928 ltr No unresolved safety concerns repressure controllers & main steam line atmospheric relief valve PETRICK.N A Standardized Nuclear Unit Power Plant System
- 8004100533 Ack receipt of 800205 interim deficiency rept re qualification of control sys CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/21 ip
- 8004090127 Ack receipt of 800215 final deficiency rept re Ruskin Mfg Co fire dampers CARLSON, R T Region 1. Philadelphia, Office of the Director 80/03/04 ip
- BOO4140196 Supplemental Part 21 rept re failed engine thrust bearing Insp of crankshaft thrust bearings installed on two PC-2 5 generator sets indicate pluge properly installed & free of reported potential defect Load during shop tests too light MCRIARTY, J M Colt Industries, Inc., Fairbanks Morse Engine Div BO/03/05 3pp
- 8004070230 Ack receipt of 800229 interim rept re NBSS lateral support anchor bolt nuts NRC will review final rept upon receipt FIGRELLI, 0 Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/03/19 ip

- 8004080672 Ack receipt or 8002.9 Final deficiency rept re undetsize sacket welds NRC will complete review of matter during future insp FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/19 ip
- 8004150177 Discusses undatectable failure in engineered safety features actuation sys Utils are investigating hardware changes that may preclude further testing provided that changes are feasible Otherwise tests will continue PETRICKIN A Standardised Nuclear Unit Power Plant System 80/03/20 1p
- 8004030208 Interim deficiency rept to electrical penetration assembly wire terminations Initiated Bunker-Ramo insp to determine cause Final rept will be submitted by 800430 BRYAN, J.K. Union Electric Co. 80/03/26 ip
- 8004040362 Forwards final deficiency rapt re potentially defective GE induction disc-type relays
 BRYAN.J K Union Electric Co 80/03/27 ip
- --8004040368 Final deficiency rept investigation in response to IE Circular 80-01 revealed GE induction disc-type relays w/ higher than normal pickup voltage Caused by petroleum jelly lubricant Airangements made for GF replacement or mods + Union Electric Co 80/03/27 ip
- 8004(80486 Ack receipt of 800229 final deficiency rept re undersized field welds on small piping installed at plant NRC will complete review of matter during future insp FIORELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/01 lp
- 8004180369 Interim deficiency rept re vertical fire dampers furnished by Ruskin Mfg Co Addl problems identified requiring new design mods Mods being developed & will be described in rept to be issued by 800515 PETRICK,N A Standardized Nuclear Unit Power Plant System PETRICK, N A ! 80/40\03
- 8004290050 Ack recespt of 800326 interim deficiency rept re apparent crimping of terminal lugs for containment electrical penetration assemblies FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/14 ip
- 8004300060 Ack receipt of 800327 final rept re GE protective relay svc advice FIDRELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/14 ip
- BOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1 G Adjudicatory correspondence
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK, L. V. Office of the Executive Pirector for Operations BO/O4/O2 34pp
- DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT 1 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0589. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for Compliance ROSG D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 771226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Emergency Pieparedness Task Force 80/03/11 4pp
- Q Adjudicatory correspondence
- 8004090192 Explains circumstances involving 800222 svc of BNWL draft rept re measurements of underground mining radon releases & NRC testimony of RM Wilde re same rept Missing enc i BORDENICK, B.M. Hearing Branch 4 80/03/05 4pp

- N 04030726 Memilandin or industrialistics between NRC 5 FEMA me prompt improvement in reducing all energetry planning 2 preparedness distributed as Shar motification 6cc3018 to theire by the Executive Director for Operations 80/04/02 14pp
- I Financial information
- UG34150502 Ann al Firancial Fept 1979 ◆ Rochester Gas * Electric Comp - 80/03/14 - 35pp
- 4 Inspection reports to cultering a correspondence
- FOR-GOODER Responds to 16 Dulletin 79-28 Investigation re-planned use of NAMCO EA133 suitches identification in SNUPPS design & development of plans for corrective action requires more time than anticipated Will forward response later PETRICK N.A. Syandardized Nuclear Unit Power Plant System 80/03/05 1p.
- 8004159300 Forwards IE Into Notice 80-12 Instrument Failure Causes Opening or P09V 5 Block Valve 'No specific action or response necessary GRIER BH Region 1 Philadelphia, Office of the Director 80/03/31 15
- 8004070105 Forwards IE Circilar 20-05, 'Emergency Diesel Generator Lubricating Oil Addition 5 Onsite Supply No written response required GRIER I H Pegion 1 Philadelphia, Office of the Director 80/04/01 lp
- 8004110512 Forwards IE Into Notice 80-13 'GE Type SBM Control Switches Defective CAM Followers No written response required GRIER.B H. Region | Philadelphia, Office of the Director 80/04/02 | 19
- 8004240351 Forwards IE Info Notice 80-14. "Safety Suggestions From Enployees No action required GRIER, B H Region 1 Philadelphia, Office of the Director 80704702 1p
- 9004180243 Forwards IE Circular 60-67, 'Problems W/HPCI Turbine Oil Sys ' No written response required GRIER.0 H Region i. Philadelphia, Office of the Director 60/04/03 p
- 8004230472 Forwards IE Builetin 79-03A "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe" Action required GRIER, B H Region 1. Philadelphia Office of the Director 80/04/04 | p
- 8004180291 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds "Written response required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/04/07 1p
- S Reportable occurrences, LERs & related correspondence
- 80040402AY Forwards supplemental rept on potential deficiency re qualification of control sys discussed in util 790928 ltr No unresolved safety concerns re pressure controllers & main steam line atmospheric relief valve PETRICK.N A Standardized Nuclear Unit Power Plant System 80/02/05 2pp
- BGO4100533 Act receipt of BGO205 interim deficiency rept re qualification of control sys CAMLSGN.R T Region 1 Philadelphia, Reactor Construction & Engineering Support Branch BG/02/21 1p
- 6004150179 Discusses undetectable failure in engineered safety features actuation sys Utils are investigating hardware changes that may preclude further testing provided that changes are feasible Otherwise, tests will continue PETRICK, N A Standardized Nuclear Unit Power Plant System 80/03/20 ip
- DOCKET SIN-50-484 CALLONAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- BOO4040031 Advises of issuance of NUREC-058B, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Hanagement BO/02/05 7pp

- 8004070189 Forwards request for add) into to complete review of GA program
 PARR, D D iight Water Reactors Branch 3 80/03/20 4pp
- 8004180352 Forwards add1 info re std plant QA programs for design & const.in response to NRC 800122 request Util commits to Rag Guide 1 74 w/exception of requirements re structural bolt tightening & number of threads exposed begind nut SEIKEN E J Standardized Nuclear Unit Power Plant System 80/04/14
- 8004280463 Updates 80040: meeting w/util & NRC re OL applications Submits program for start of NRC review including initial meeting w/util project manager Applicants exploring other steps to aid NRC review PETRICK.N A Standardized Nuclear Unit Power Plant System 80/04/23 2pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Emergency Proparedness Task Force 80/03/i1 4pp
- Q Adjudicatory correspondence
- 8004210145 Order granting extension, until 800416, for Commission to elect whether to review Director's 800310 decision per 10CFR2 206
 CHILK-S J Office of the Secretary of the Commission 80/04/10 is
- H Coneral correspondence
- 8004070070 Discusses NRC program of upgrading emergency preparedness in environs of nuclear power plants in response to 800102 ltr Sys for alerting public must be demonstrated effective prior to OL issuance DENTON: HR Office of Nuclear Reactor Regulation 80/03/17 ip
- --8004070071 Expresses concern re proposed evacuation plan for facility Alerting farmworkers to emergency within required time would be difficult WEILL, SM Affiliation Unknown 80/01/02 1p
- G Inspection reports, 18 Bulletins & carrespondence
- 8004100280 Responds to IF Bultetin 79-28 Investigation re planned use of NAMCO EAIBO switches, identification in SNUPPS design & development of plans for corrective action requires more time than anticipated Will forward response later PETRICK.N A Standardized Nuclear Unit Power Plant System B0/03/06 1p
- 800410014B Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07 lp
- 8004150192 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Black Valve " No specific action or response necessary KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/31, 1p
- 8004080725 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Bupply "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/01
- 8004i50057 Forwards IE Info Notice 80-i3, "QE Type SBM Control Switches Defective CAM Followers " No specific action or response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/02 ip
- B004180063 Forwards attachments to 1E Circular 80-03, "Protection From Toxic Gas Hazards," inadvertently omitted from G00306 transmittal KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/02 ip
- 8004220153 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/04/02 1p

- 8004220388 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " Na written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/03
- 8004230282 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Action required KEPPLER. J 0 Region 3. Chicago. Office of the Director 80/04/07 ip
- 8004220098 Forwards IE Bulletin 80-08, "Exem of Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09
- 8004300144 Notification of 800423 meeting in Fulton,MD to discuss resident inspector program
 KEPPLER,J G Region 3. Chicago, Office of the Director 80/04/14
- --8004300178 Notification of 800423 meeting in Fulton,MD to discuss resident inspector program
 KEPPLER,J 0 Region 3, Chicago, Office of the Director 80/04/14
- --B004300184 Notification of 800423 meeting in Fulton,MD to discuss resident inspector program KEPPLER,J G Region 3, Chicago, Office of the Director 80/04/14 to
- --8004300189 Notification of 800423 meeting in Fulton,MO to discuss resident inspector program
 KEPPLER,J G Region 3, Chicago, Office of the Director 80/04/14
- ---B004300194 Notification of B00423 meeting in Fulton, MD to discuss resident inspector program Agenda encl KEPPLER, J G Region 3, Chicago, Office of the Director B0/04/14
- S Reportable occurrences, LERs & related correspondence
- 8004040267 Forwards supplemental rept on potential deficiency re qualification of control sys discussed in util 770928 ltr No unresolved safety concerns re pressure controllers & main steam line atmospheric relief valve PETRICK.N A Standardized Nuclear Unit Power Plant Bystem 80/02/05. 2pp
- 8004100533 Ack receipt of 800205 interim deficiency rept re qualification of control sys CARLSON,R T. Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/21 ip
- 8004090127 Ack receipt of 800215 final deficiency rept re Ruskin Mfg Co fire dampers CARLSON,R T Region i, Philadelphia, Office of the Director 80/03/04 ip
- 8004150179 Discusses undetectable failure in engineered safety features actuation sys Utils are investigating hardware changes that may preclude further testing provided that changes are feasible Otherwise, tests will continue PETRICK, N A Standardized Nuclear Unit Power Flant System 80/03/20 ip
- 8004180486 Ack receipt of 800227 final deficiency rept re undersized field welds on small piping installed at plant NRC will complete review of matter during future insp FIDRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/01 ip
- 8004150367 Interim deficiency rept re vertical fire dampers furnished by Ruskin Mfg Co Addl problems identified requiring new design mods Mods being developed & will be described in rept to be issued by 800515 PERICK,N A Standardized Nuclear Unit Power Plant System 80/04/03 2pp
- S0043D0060 Ack receipt of 800327 final rept ra GE protective relay svc advice FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/04/14 1p

- DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment," providing guifance re-methods for compliance RUSS, D.F. Division of Project Management 80/02/05 7pp
- 8004170327 "TMI-Plus Dne Toward a Sarær Nuclear Power Program "
 * Duke Power Co 60/03/26 13pp
- 8004140430 Forwards companison of draft STS w/snubber functional test sampling plan COLLINGS.D M Duke Power Co 80/04/03 line
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda, MD re evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident
 THO(MAS, C O Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800319 meeting w/near-term CP applicants in Bethesda. MB re resumption of CP application review activities associated w/TMI-2 accidents THDMAS.C 0 Standardization Branch 80/04/03 12pp
- BO04240557 Summary of BO0402 meeting w/Near-Term CP Applicants Group in Bethesda,MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl THOMAS,C D Light Water Reactors Branch I 80/04/07 47pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GUSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- q Inspection reports, IE Bulletine & correspondence
- 8004230085 Submits response to IE Bulletin 80-03 Review revealed that no charcoal adsorber cells have been received from manufacturers

 DAILL C Duke Power Co 80/03/17 ip
- 8004150808 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/03/31 2no
- 8004080604 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01 200
- B004150075 Forwards IE Info Notice B0-i3. "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240254 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/02
- 8004180375 Forwards IE Circular 80-07, "Problems WHPCI Turbine Dil Sys " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/03 2pp
- 8004230122 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180351 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07

- I was gift " 40) gost 11 Jean Station UNIT 2
- . . pli arti c netri fiir stage documents à correspondence
- 476 131 HJ/Ises or issuance of NIREC-0988 Interin Staff Position is prived habitication in sety-fielded Electrical Equipment of iding , iding the nethods for compliance with LT Livision of original Management 80/02/05 7pp
- T4; 1:327 TM: Flis File Founds a Earer Nuclear Power Program "
 Nice rough Chill Elvid To 13pp
- C004210405 Surrany of C0 23 meeting g/near-term CP applicants in Befreada.MD relevaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident.

 TelMAS C0 Ctandardication Sharch 80/04/03 63pp
- Tiu4201074 S.-Hary or Bu J19 meeting winear-Term CP Applicants Group in Betheefa HU ne matters related to resumption of CP application review arts stress associated w/TMI-2 accidents THOMS 5 G Ctandardization Granch B0/04/03 12pp
- G (14240557 Simmany or Mild) I meeting u/Near-Term CP Applicants Group in Bathesda M5 re-progress hade establishing proposed requirements steming from TMT-2 accident Proposed requirements estending from TMT-2 accident Proposed requirement category assignments encil Tm1483 F Q Light Water Reactors Branch 1 80/04/07 47pp
- annethodeservo, correspondence
- 0504030526 Memoranium of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GDESICH-L V Office of the Executive Director for Operations 90/04/CQ 34pp
- 4 Inspection reports, If Bulletins & correspondence
- EC04239195 Submits response to IE Bulletin 60-03 Review revealed that no charcoal adsorber cells have been received from manufacturers.

 EAIL C Dute Power Co 80/03/19 ip
- SC04150505 Forwards IE Into Notice 80-12, "Instrument Failure Causes Deening of PORV 5 Block Valve No specific action or response necessary O REILLY, J.P. Region 2 will anta Office of the Director 80/03/31
- 8204080604 Forwards IE Cirrular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O REILLY J.P. Region 2. Atlanta, Office of the Director 80/04/01
- #304150075 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers has specific action or response required O'REMLLY J.P. Region 2 Atlanta, Office of the Director 80/04/02 2pp
- GGO4240254 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required O REILLY J.P. Region 2, Atlanta, Office of the Director 80/04/02 Rep
- BGO4180375 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Sys " No written response required O'REILLY J.P. Region 2 Atlanta Office of the Director BO/04/03 2pp
- 8004230122 Forwards IE Bulletin 79-03A 'Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/04/04 is
- BOO4180351 Forwards IE Suiletin 80-08, "Exam of Containment Liner Panatration Welds " Written response required D'RELLLY. J P Region 2. Atlanta, Office of the Director 80/04/07 2pp

- DOCKET STN-50-190 FERKINS NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 2004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RGSS.D F Division of Project Management 80/02/05 7pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program "
 * Dute Power Co 80/03/26 1350
- 8004210405 Summary of 600328 meeting w/near-term CP applicants in Bethesda.MD re evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident THOMAS.C O Standardization Branch 80/04/03 A3pp
- 8004300071 Summary of 800319 meeting w/Near-Torm CP Applicants Ordup in Bethesda. HD re matters related to resumption of CP application review activities associated w/YMI-2 accidents THOMAS. C O Standardization Branch 80/04/03 12pp
- BOO4240957 Summary of BOO402 meeting w/Near-Term CP Applicants Group in Bethesda MD re progress made establishing proposed requirements stemaing from TMT-2 accident Proposed requirement category assignments encl THOMAS.C O Light Water Reactors Branch 1 BO/04/07 47pp
- G Adjudicatory correspondence
- 8004030626 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GDSBICKL V Office of the Executive Director for Operations BO/04/02 34pp
- P Operating license stage documents & correspondence
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINGS,D M Duke Power Co 80/04/03 11pp
- G Inspection reports, IE Bulletins & correspondence
- 8004230085 Submits response to IE Bulletin 80-03 Review revealed that no charcoal adsorber cells have been received from manufacturers DAIL, L C Duke Power Co 80/03/19 1o
- 8004150505 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31 2pp
- 8004080604 Forwards IE Circular 80-05. "Emergency Diesei Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/04/01 2pp
- 8004150075 Forwards If Info Notice 80-13, "GE Type 8DM Control 8witches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BD/04/02 2pp
- 8004240254 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees " No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 90/04/02
- 8004180375 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Cil Sys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/03 2pp
- 8004230122 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2. Atlanta, Office of the Director B0/04/04 is
- 8004180351 Forwards IF Sulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 2pp

DOCKETED ITEMS

- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project hanagement 80/02/05 7pp
- 8004170327 "TMI-Plus One Toward a Safer Nuclear Power Program" * Duke Power Co 80/03/26 13pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 ORIMES B K Emergency Preparedness Task Force 80/03/ii 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSBICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- P Operating license stage documents & correspondence
- 8004140430 Forwards comparison of draft STS w/snubber functional test sampling plan CDLLINGS.D M Dute Power Co BO/04/03 lipp
- G. Inspection reports, IE Bulletins & correspondence
- B004230085 Submits response to IE Bulletin 80~03 Review revealed that no charcoal adsorber cells have been received from manufacturers

 DAIL, L. C. Duke Power Co. 80/03/19 ip
- 8004220105 Ack receipt of IE Insp Repts 50-491/80-02,50-492/80-02 & 50-493/80-02 an 800224-29 No proprietary info DAIL, L C Duke Pawer Ca 80/03/28 1p
- --8004220117 Forwards IE Insp Repts 50-491/80-02,50-492/80-02 & 50-493/80-02 on 800226-29 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8004220134 IE Insp Repts 50-471/80-02.50-492/80-02 & 50-493/80-02 on 800226-29 No noncompliance noted Major areas inspected GA program implementation.const program changes & GA audits MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch RAUSCH.J K Region 2, Atlanta, Office of the Director 80/03/24 Spp
- 8004240426 Ack receipt of IE Insp Repts 50-491/80-03.50-492/80-03 & 50-493/80-03 on 800303-05 No proprietary info DAIL, L C Duke Power Co 80/03/28 1p
- --8004240430 Forwards IE Insp Repts 80-491/80-03.50-492/80-03 & 80-493/80-03 on 800303-05 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/20 2pp
- --8004240434 IE Inep Repts 50-491/80-03.50-492/80-03 & 50-493/80-03 on BOO303-05 No noncompliance noted Major areas inspected structural concrete & steel QA & QC.settlement monitoring program CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch LENAHAN.J J Region 2. Atlanta, Office of the Director 80/03/19 Spp
- 8004150505 Forwards IC Info Notice 80-12, "Instrument Failure Gauses Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/31
- 8004080604 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/01 20s

- 8004150075 Forwards IC Into Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/02 2nd
- B004240254 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180375 Forwards IE Circulai 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03
- 8004230122 Forwards IE Bulletin 79-03A 'Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Action required O'REILLY, J P Region 2, Atlanta, Ortice of the Director 80/04/04 in
- 8004180351 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREC-0588. "Interim Staff Position on Environ Qualification of Safety-Related Ejectrical Equipment." providing guidance re methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004170327 "TMI-Plus One Toward a Sater Nuclear Power Program " * Duke Power Co 80/03/26 13pp
- 8004140430 Forwards comparison or draft STS w/snubber functional test sampling plan CQLLINOS.D M. Duke Power Co. 80/04/03 11pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates. requested by NRC 791226 ltr.has been postponed pending GAG clearance under Federal Repts Act RIMES B K Emergency Proparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GUSBICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- G Inspection reports, IF Bulletins & correspondence
- 8004230085 Submits response to IE Bulletin 80-03 Review revealed that no charcoal adsorber cells have been received from manufacturers

 DAILL C Duke Power Co 80/03/17 ip
- 8004220105 Ack receipt of [C Insp Repts 50 491/80-02,50-492/80-02 & 50-493/80-02 on 800226-29 No proprietary info DAIL, L C Duke Power Co 80/03/28 ip
- --8004220117 Forwards IC Insp Repts 50-491/80-02.50-492/80-02 & 50-493/80-02 on 800226-29 No noncompliance noted MURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8004220134 IE Insp Repts 50-491/80-02, 50-492/80-02 & 50-493/80-02 on 800226-29 No noncompitance noted Major areas inspected GA program implementation, const program changes & GA audits MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch RAUSCH, J K Region 2, Atlanta, Office of the Director 80/03/24 3pp
- 8004240426 Ack receipt of IE Insp Repts 50-491/80-03, 50-492/80-03 & 50-493/80-03 on 800303-05 No proprietary info DAIL, L C Duke Fower Co 80/03/28 Ip

- Cid. . 34 % In a hept, 437:20-03 50 492/80-03 & 50-493/80-03 on CO hard replaced Major areas inspected services area in sected major areas inspected services area in section of Construction of Engineering program
- program

 Cultill Fegin 2 Arlanta Reacton Construction & Engineering

 Laupport Franch 1704 At 1 1 Pegion 2 Atlanta, Office of the

 Director 2 3 17 Sp.
- un wifolus Forwards IE Info Natice Bo-12 "Instrument Failure Causes Opening of No." ! Plock of e. No specific action or response recessor, [MAILLY 1] Region a milanta Office of the Director 80/03/31
- * 14070*04 Firushas (Elústrolar ED 05 Emergency Diese) Generator Literating (6:1 Addition * Unsite Supply * No unitten response required O Atlanta Orfice of the Director 80/04/01 Dag
- 6734150 75 Forwards IE Into Artice 80:13 'GE Type SBM Control Switches Lefective CAM Followers to specific action or response required O RELLLY J. F. Region 2 Artiantal Orfice of the Director 80/04/02 200
- "SC4240,54 Forwards IE [16a Motice 20-14, "Safety Suggestions From Employees" No action required O PENLY U.P. Region 2 Atlanta Defice of the Director 80/04/02 2pp
- 8004180375 Forwards IE Circular 80-07, 'Problems W/MPCI Turbine Oil Sys ' No written response required O REICLY J. F. Region 2, Atlanta, Office of the Director 80/04/03 2pp
- 8504230122 Forward: IE Bulletin 79-03A 'Longitudinal Held Defects in ASME SA-312 Type 324 Stainless Steel Pipe " Action required D REILLY, J P Region 7 Atlanta, Office of the Director 80/04/04 ip
- වාගි4(8005) Forwards IE Bulletin 80-08 "Exam of Containment Liner Penetration Helds" Hritten response required O'REILLY J.P. Region 2. Atlanta, Office of the Director 80/04/07 වුණු
- EOCKET 3TN-50-497 CHEROZEE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 0004040031 Advises of lisuance of NUREC-058B. "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment, providing golfance re methods for compliance FOSS.D F Division of Project Management 80/02/05 7pp
- 6304170327 "THI-Plus Une Toward a Safer Nuclear Power Program " • Duke Pawer Co 60/03/26 13pp
- 6004140430 Forwards comparison of draft STS w/snubber functional test sampling plan COLLINOS.D M Duke Power Co 80/04/03 11pp
- F Security, medical emergency & fire protection plans
- 8004080077 Advises that submithal date for evacuation time estimates, requested by IRC 791926 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Mamorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed at Roard notification GOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp

- @ Inspection reports, If Pulletins & correspondence
- 2004230085 Submits response to IE Bulletin 80-03 Review revealed that no charcoal adsorber cells have been received from manufacturers
 DAILL C Dute Power Co 80/03/19 1p
- 8004220105 Ack receipt of 1E Insp Repts 50-491/80-02,50-492/80-02 & 50-493/80-02 on 800226-29 No proprietary info DAIL, L C Duke Power Co 80/03/28 1p
- --8004220117 Forwards IE Insp Repts 50-491/80-02,50-492/80-02 & 50-493/80-02 on 800226-27 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/03/24 2pp
- --B004220134 IE Insp Rep+s 50-491/B0-02.50-492/B0-02 & 50-493/B0-02 on B00226-29 No noncompliance noted Major areas inspected GA program implementation.const program changes & GA audits MJRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch RAUSCH, J K Region 2. Atlanta. Office of the Director B0/03/24 3pp
- B004240426 Ack receipt of IE Insp Repts 50-491/80-03.50-492/80-03 & 50-493/80-03 on B00303-05 No proprietary info DAIL, L C Duke Power Co B0/03/28 1p
- --8004240430 Forwards IE Insp Repts 50-491/80-03.50-492/80-03 & 50-493/80-03 on 800303-05 No noncompliance nated BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/03/20 2pp
- ---8004240434 IE Insp Repts 50-491/80-03,50-492/80-03 & 50-493/80-03 on 800303-05 No noncompliance noted Major areas inspected structural concrete & steel QA & GC:settlement monitoring program CONLON.TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAHAN.J J Region 2, Atlanta, Office of the Director 80/03/19 5pp
- B004150505 Forwards 1E Info Notice 80-12. "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary O'REILLY, J P Region 2, Atlanta, Office of the Director H0/03/31
- 8004080604 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/01
- 8004150075 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240254 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004180375 Forwards IE Circular 80-07. "Problems W/HPCI Turbine Dil Sys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/03.
- 8004230122 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME 6A-312. Type 304 Stainless Steel Pips" Action required. D'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/04 ip
- 8004180351 Forwards IF Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/07 2pp

DOCKET STN -50-495 SWESSAR-P1

- A Application/construction stage documents & correspondence
- 8004280065 Responds to 800128 request for info re testimony before Public Utils Commission & forwards LER 78-53/01T-0.781206 backup rept & list of documents on dockets for Oct 1978-Mar 1979 KMar 1979-May 1979 Request list encl RUSBELL.N T Technical & Administrative Support Branch 2pp

~-8004280098 Forwards OA Program Insp Rept 99900509/79-03 on 790501-04 & notices of violation & deviation Summarizes background info on related enforcement 1950e REINMUTH.0 W Division of Reactor Construction Inspection 79/08/10 3pp

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSE.D F Division of Project Management 80/02/05 7pp

I Financial information

8004180320 Forwards Annual Financial Repts 1979 BISHOP, R W Northeast Utilities 80/04/02 1

J Insurance & indemnity information

8004160254 Forwards Endorsements 57 & 58 MAELU Policy MF-52 IFFLAND,R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 3pp

DOCKET 90-497 MONTAGUE NUCLEAR POWER STATION: UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D F Division of Project Management 80/02/09 7pp

I Financial information

8004150320 Forwards Annual Financial Repts 1979 BISHOP,R W Northeast Utilities 80/04/02 1

J Insurance & indemnity information

8004160254 Forwards Endorsements 57 & 58 MAELU Policy MF-52 IFFLAND,R R Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/11 3pp

DOCKET STN-80-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREO-0589, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROBS, D.F. Division of Project Management 80/02/05 7pp

8004040017 Submits addl guidance to NUREG-0589. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROS8, D.F. Division of Project Management 80/02/21 Spp

8004040240 Updates nine point action program re GA program identified in util 791228 ltr & 800125 status rept Actions 1-3 & 5-8 have been implemented Proposes to begin placement of safety-related complex concrete on 800303

8004230058 Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident Info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of OL W/enc1 ROS8, D. F Division of Project Management B0/03/10 53pp

8004150128 Forwards request for add1 info concerning review of facility FBAR PARR.O D. Light Water Reactors Branch 3 80/03/18 5pp

8004010377 Advises that instrumentation & control diagrams for review of FBAR Chapter 7 have been transmitted to OW Burke of ORNL in response to NRC request
BARKER, D. G. Houston Lighting & Power Co 80/03/28 3pp

8004140463 Forwards Lower CO River Authority data re South TX Interconnected Sys interchange for 1979 Data should provide index re types & magnitude of member interchange within South TX Interconnected Sys WEST.NE Texas. State of 80/04/07 14pp

F Secusity, medical, emergency / rire protection plans

8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
GRIMES B K Emergency Preparedness Task Force 80/03/11 4pp

G Adjudicatory correspondence

8004100274 No objection to intervenor Citizens Concerned About Nuclear Power, Inc 800302 motion for extension to answer applicant second set of interrogatories Objects to mischaracterizations made in motion Certificate of Syc encl BIDDLE: C T Houston Lighting 9 Power Co BIDDLE; C T Baker 8 Botts 80/03/06 5pp

8004020136 Response to ASLB 800310 memorandum inviting views re feasibility of early hearing Concurs w/ASLB suggestions & desires to participate in hearing within memorandum conditions Certificate of Svc encl CULP,R H, SCHUARZIM D Houston Lighting & Power Co CULP,R Lowenstein, Newman, Reis, Axelrad & Toll 80/03/19 App

8004280069 Response to ASLB 800310 memorandum re hearing to consider issues on alleged const 2 QA/QC deficiencies Early hearing may foreclose possibility of raising similar issues at later time Certificate of Svc encl
SINKIN.L Citizens Concerned About Nuclear Power, Inc 80/03/24

B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparednoss distributed as Board notification GUSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp

8004210414 Response to ASLB 800310 memorandom inviting views re feasibility of separating admitted contentions Views will be submitted when IE investigation re assessment of QA/QC effectiveness.is completed W/Certificate of Svc TREBY.S A Hearing Branch 1 GO/04/10 2pp

K Utility Final Bafety Analysis Report (FSAR) & amends

8004220743 Forwards Amend 10 to FSAR.consisting of responses to first round review questions concerning initial startup testing Affidavit encl TURNER.E A Houston Lighting & Power Co 80/04/21 3pp

--8004220749 Amend 10 to FSAR * Hauston Lighting & Power Co 80/04/21 125pp

M Antitrust correspondence

800402020B Response to Central & South West Corp et al second request for production of documents Stagg Sys Inc workpapers available for insp & copying Documents re transactions already produced Certificate of Syc encl COPELAND, J Q Houston Lighting & Power Co COPELAND, J Q Baker & Botts 80/02/25 App

BOO4040072 Notice of appearance in proceeding Certificate of Syc encl FABRIKANT,R Justice, Dept of 80/02/25 App

8004110030 Discusses add) request for documents located in Chalker personal files Request is untimely & deficient, failing to specify relevancy to proceeding No obligation to respond to request by 80027, per Commission Rules of Practice STAHL.D M Isham, Lincoln & Beale 80/02/25 2pp

8004020147 Forwards DDJ & NRC 800228 jaint motion for mod of ASLB erdar re settlement discussions & for issuance of order to compet production of certain documents & testimony Proposed order encl CYPHERT, S B Justice, Dept of CHANANIA, F, D Antitrust Division 80/02/28 400

--8004020164 Joint motion for mod of ASLB 790416 order re protection of settlement discussions & for the summer of order to compel production of documents & testimony from Houston Lighting & Power & TX Utils W/Certificate of Evc CYPBERTIS B , DOPSDVIC, D A Justice, Dept of CHANANIA, F D Antitrust Division 80/02/28 120pp

- 1004020175 Oral Republicant or ED Granth te certification of questions The Atomic Sizety and Licensing Board Panel SCARTH, E.D.

 Aftiliation Unknown 70 CC 22 Spp.
- -3034CFutR1 Mohip in compet Trittis Cos to supplement Apr & Jul 1979 response, to first set in interrogatories & requests for production as facurers tries performance of current new obligations & ECORDA Mohamithicate of Svc & proposed order CYFEERT S B 1030F : Justice Dept of 80/02/20 7pp
- --8004920170 Mation to compet Houston Lighting & Power to supplement 790111 / 0427 ensures to 781122 interrogatories Urges Fulfillment of current abilitations arrising from development of new into certificate of Scc / proposed order enci CYPHERT, 3 B , LUGUE N Justice Dept of 80/02/28 7pp
- --BOD46C2019d Joint application for issuance of subpoena directed to ED Scarth or Tx Utils Generating Co & DE Simmons of Houston Lighting & Poucer Requests entension until BOD402 to depose DE Simmons Drart subpoenas & Certificate of Svc encl CYPHERT S B DDF5DVIC.D A Justice.Dept of BLUME.M Antitrust Division BO/02/28 7pp
- G004020098 Motion for protective order re disclosure of Diamond Shamfoot Corp documents, in response to ASLB 800118 subpoena duces tecum Documents in question are subj or contractual obligations Certificate of Suc 5 proposed order encl CYPHERT, S.B. Justice Dept or 60/02/29 10pp
- 8004080174 Notifies of change of address for counsel of South TX Electric Cooperative, Inc. * Medina Electric Cooperative, Inc. effective 800310
 - Akin, Gump. Haver & Feld 80/03/04 1p
- 8004100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative, Inc / Medina Electric Cooperative, Inc neither initiated nor received any discovery requests Certificate of Svc enci JOHN, D F Akin Gump. Hauer / Feld B0/03/04 4pp
- 8004110574 Confirms 800779 telcon re DOJ subpoena of documents from Golf States Utils Subpoena covers certain areas also covered in Brownsville Public Utils subpoena Util documents will be available to all parties RADER R M Conner. Moore t Corber 80/03/04 2pp
- 8004080559 Requests pretrial conference to clarify procedural matters re ASLB 791214 order, filing testimony summaries & designation of trial exhibits
 CYPHERT, B B Justice. Dept or CHAHANIA, F D Antitrost Division RIITS, F H Texas-Louisiana Electric Cooperative, Inc. 60/03/05
- 8004090204 Discovery rept for Feb 1980 Deposed W Taylor,M Hebb,DE Simmons A EL Watson Participated in depositions noticed by TX-LA Electric Cooperative E Orty of Brownsville,TX Reviewed Diamond Shamioci documents Filed application for subpoemas CYPHERT,S B , PARKENTER,F H Justice,Dept of 80/03/05 Spp
- 8004090387 Discovery rept for Feb 1980 Participated in A Gerber, M Hebb, E Simmons, V Robertson & GW Beams depositions Attended J Turk & S Phillips depositions Filed motion for additime to respond to TX Utils interrogatories W/Certificate of Svc CARNEY, J A Central & Southwest Corp CARNEY, J A Isham, Lincoln & Beale 83/03/05 7pp
- 8004090421 Discovery rept for Feb 1980 No discovery requests received nor initiated Certificate of Svc encl WOOD.J C San Antonio, TX WODD.J C Matthews, Nowlin, Macfarlane 8 Barrett 80/03/05 4pp
- 8004110024 Discovery rept for Feb.1980 City of San Antonio, acting by & through City Public Svc Board of San Antonio, neither initiated nor received any discovery requests Certificate of Soc and Svc enc1 WOOD, J C San Antonio, TX 80/03/05 4pp
- 8004110056 Response to Houston Lighting & Power 800219 motion to competinterrogatory answers by DOJ re C Stover proposed expert testimony DOJ has no add1 info to provide except for facts stated in this response W/Stover Itr & Certificate of Svc CYPHERT. B Justice, Dept of 80/03/05 Spp
- 8004030344 Comments by Public Utils Board of City of Brownsville, TX on NRC & DOJ motion for mod of ASLB order re-protection of settlement discussions & for order to compel documents & testimony Urges clarification of scope W/Certificate of Svc POIRIER, M R Texas, State of 80/03/06 18pp

- BOO4080273 Response in opposition to DOJ # NRC joint motion for mad of ASLB order re-settlement discussions & for order to compel production of documents Negotiations for settlement purposes are protected from discovery per case law & per rules SOUKNIGHT. J A Houston Lighting & Power Co # Baker & Botts # Lowenstein, Newman, Reis, Akeliad & Toll NRC 80/03/06 15pp
- JUGGUOLED Response seering dismissal of DDU GUOLED motion to co supplementation of interrogatories,as moot Answers were served one day prior to this motion Add) suppl will be filed if further responses are appropriate W/Certificate of Svc FRANKLIN-W J Houston Lighting & Power to & Baker & Botts Lowenstein, Newman, Reis, Axelrad & Toll 80/03/06 App
- 8004080360 Response in opposition to DBJ % NRC joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents NRC policy favoring settlement is designed to protect sources involved W/Certificate of SVC * Central / Southwest Corp * Isham, Lincoln & Beale 80/03/04 1100
- 8004080638 Response in opposition DOJ & NRC 800228 joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents Negotiations must be protected per Rule of Evidence 408 W/Cortificate of Svc AMEARN.C D Toyas Utilities Generating Co AMEARN.C D Debovoise & Liberman 80/03/04 30pp
- 80040701B5 Notice of appearance on behalf of Public Utils Board of City of Brownsville, TX, in consolidated discovery Certificate of
- 9004090434 Discovery rept by Public Utils Board of City of Brownsville.

 TX.for Feb 1980 Deposed M Borchelt of Central Power & Light
 Participated in R Edelstein deposition Received documents
 from Central & South West Corp Certificate of Svc encl
 POIRIER,M R Texas, State of POIRIER,M R Spiegel & McDiarmid
 80/03/06 App
- GOO4100218 Notifies that DOJ received Houston Lighting & Power Co supplemental answers to Central Power & Light Co first interrogatories w/o apps Requests Attachment A to Houston Power & Light Co second set of addl answers to NRC CYPHERT, S B Justice, Dept of 80/03/06 ip
- 8004100433 Notice of appearance of O Spiegel on behalf of Public Utils Commission of Brownsville.TX Certificate of Svc encl SPIEGEL, O Brownsville.TX SPIEGEL, O Spiegel & McDiarmid 80/03/06 bp
- 8004100535 Discovery rept for Jan & Feb,1980,City of Austin has neither initialed nor received any discovery recuests BACDUSH,R C Austin, TX 80/03/07 5pp
- 8004080044 Response by Public Utils Board of City of Brownsvills.TX, in opposition to Central & Southwest Corp 800222 motion for protective order re second set of interrogatories & production of documents WiCertificate of Svc & 800207 itr PURIER,M R Texas, State of PUBLIER,M R Spiegel & McDiarmid 80003070 1020 12թթ
- 8004100514 Forwards notice of taking of deposition of D Springs AHEARN,C D Debevoise & Liberman 80/03/10 ip
- ----B004100925 Notice of taking of deposition of D Springs on B00313-14 in Atlanta, GA Deponent will be examined on matters re bulk power supply & transmission & wheeling svcs in TX Certificate of Svc encl
 AHEARN, C D Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman B0/03/10 Spp
- 8004110169 Notifies that W Scott deposition scheduled for Mar is cancelled Cancellation based on DOJ representation that Scott would be called as expert withness BALDWIN, J M Baker 2 Botts 80/03/10 5pp
- 8004080018 Updated response to first set of interrogatories & document requests includes info re untresses competitive utils, product & geographic market & petitions to intervene Programifications of DA Springs & Certificate of Svc encl BURCHETTE.W H Texas-Louisiana Electric Cooperative.Inc BURCHETTE.W H Northcutt Ely 80/03/11 27pp.
- 8004090164 Second supplemental response to first set of interrogatories & document requests includes info re projected loads. capacity & leserves as of 800215 SLICKER,F K Texas Utilities Co SLICKER,F K Worsham, Forsythe & Sampels 80/03/11 5pp

- 8004070175 Supplemental response to third set of interrogatories & document requests Supplemental answer to Interrogatory 18 encl W/o encl SLICKER.F K Texas Utilities Co SLICKER.F K Worsham, Forsythe & Sampels 80/03/11 Spp
- 8004090180 Supplemental response to first set of interrogatories & document requests includes info re monthly fuel cost adjustments for 1979
 SLICKER.F K Texas Utilities Co SLICKER.F K Worsham, Forsythe & Sampels 80/03/ii 4pp
- 8004100084 Forwards DOJ subpoens requiring DE Simmons util vice president, to testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subpoens W/o encl CYPHERY.6 B Justice.Dept of 80/03/11 1p
- 8004100221 Fourth supplemental response to first set of interrogatories & document requests Includes info re cities & utils which have explored power alternatives offered by TX Utils Co SLICKER, F K Texas Utilities Co SLICKER, F K Worsham, Forsythe & Sampels 80/03/11 3pp
- 8004030258 Response in opposition to schedule proposed by NRC for reply to motion to quash 800221 subpoens directed to R Frame Merit of NRC argument will be better evaluated after Lerner deposition 8uggests 800321 for reply W/Certificate of Svc KNOTTB, J B Texas Utilities Generating Co 80/03/12 5pp
- 8004020113 Forwards Houston Lighting 5 Power 800313 petition for directed certification of ASLB 800307 order re confidential documents of settlement negotiations BOUKNIGHT, J A Lowenstein, Newman, Ress, Axelrad & Toll 80/03/13
- --8004020119 Petition for directed certification, interim stay & review of ASLS 800307 order requiring Houston Lighting & Power to produce selflement negotiations documents Urges reversal of ruling W/excerpts of 800307 prohearing transcript BOUKNIGHT. J A . GREEN. D & Houston Lighting & Power Co BOUKNIGHT, J A . Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13
- -- 8004020122 Order to NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privileged documents Orders responses to majority of questions Wexcerpts of 790601 prehearing HILLERM E Atomic Safety and Licensing Board Panel 79/04/16
- 8004080029 Forwards DDJ third supplemental response to Houston Lighting & Power Co first set of interrogatories Documents responsive to util 790204 second set of interrogatories encl Documents re second interrogatories not encl
 CYPHERT.8 B Justice.Dopt of 80/03/13 1p
- --8004080033 Third supplemental response to first set of interrogatories & document requests Includes info re GT Taylor testimony re four relevant product markets in proceedings CYPHERT, 8 B Justice, Dept of BO/03/13 30pp
- 8004080073 Application for issuance of subpoena directed to FG Arey of DUMONDOYS Application for issuance or supposed a directed to Mebster Engineering Corp. to be deposed & to produce ducuments re interconnections & interconnected sys Draft subpoema & Certificate of Svc encl
 OREEN, D Houston Lighting & Power Co * Baker & Bott Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 13pp Baker & Botts * 3/13 13pp
- 8004090437 Ack receipt of & accepts 800312 ltr in lieu of interrogatory answer per 800307 prehearing ruling Ltr does not solve Houston Lighting & Fower problems re C Stover deposition DOJ 800311 & 12 ltrs & Certificate of Svc encl Lowenstein, Nauman, Reis, Axelrad & Toll 80/03/13 10pp GREEN, D. Q.
- 8004100545 Response to third set of interrogatories Includes info re electric power & energy delivered to various utils during Dec 1979 Certificate of Svc enci * Texas Electric Service Co 80/03/13 16pp
- 8004080370 Discovery rept for Feb 1980 Deposed J Wilson, CC Campbell & V Robertson et al Attended DOJ & NRC depositions, Served 800201 first set of interrogatories to NRC Received additesponses to interrogatories Certificate of Svc encl FRANKLIN.W J Houston Lighting & Fower Co # Baker & Botts # Lowenstein, Newman, Reis, Axelrad & Toll 80/03/14 7pp
- 800404007B Comments by Public Utils Board of City of Brownsville, TX, stating no position re consolidation for trial advised by ABLB during 800307 prehearing If consolidation ordered, right of cross-examination must be preserved W/Certificate of syc POIRIER, M R , POIRIER, M R. Texas, State of 80/03/17 7pp.

- 8004080153 Statement in opposition to consolidation of proceedings for hearing purposes, per ASLB 800307 prehearing conference request Issues not identical ! evidence in South TX Project may not be related to Commanche Peak M/Certificate of Svc STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Beale 80/03/17 9pp
- 8004080247 Discovery rept for Feb 1980 Participated in Ammons, Beams, Borchelt, Campbell, Vaibrough depositions Inspected DDJ documents Received 2 opposed Central & Southwest motion for addlitime to reply to interrogatories M/Certificate of Svc AHEARN, C D Teras Utilities Co AHEARN, C D Debovoise & Liberman 90/03/17 5pp
- 8004080401 Submits TX Utils Generating Co response to ASLB 800307 request re views on consolidation or proceedings for hearing pulposes Urges complete consolidation KKOTTS. J B Debevoise 5 Liberman 80/03/17 4pp
- 8004080663 Order confirming results of 800307 oral argument NRC & DOJ Joint motion, re mod of order concerning protection of settlement discussions, granted in part Parties may not engage in further discovery re documents included in motion GLASER, M.L. Atomic Safety and Licensing Board Panel 80/03/17
- 8004210497 Notice of appearance in proceeding Certificate of Svc encl GLAZIER, K. M. . Justice, Dept of 80/03/17 4pp
- 8004070427 Discovery rept for Jan-Feb 1980 Participated in M Orymy deposition No discovery requests initiated Certificate of Svc encl BURCHETTE, W H Teras-Louisiana Electric Cooperative Inc BURCHETTE, W H Northcutt Ely 80/03/19
- 8004010517 Order denying MRC 800311 motion to quesh subpoema of R
 Frame TX Utils Generating Co entitled to test ND Lerner
 credibility by questioning work & documents prepared by
 Frame for Lerner review
 WOLFE,S J Atomic Safety and Licensing Board Panel 80/03/20 2pp
- 8004030347 Response in opposition to TX Utils Generating Co. Houston Lighting & Power Co & South West Corp 800313 potitions for directed contribution of order compelling production of documents News article & Certificate of Svc encl CHANANIA.F D . BLUNE, M B . HODODON, A P . Antitrust Division 80/03/20 21pp
- 8004100177 Memorandum in opposition to petitions for directed certification filed by TX Utils Generating Co.Houston Lighting & Power Co & Central & South West Corp et al.re ASLD 800307 order Certificate of Svc encl CYPHERT. S B. DOPSOVIC, D A. GLA71FR. K M Justice, Dept of 80/03/20 26pp
- 8004100442 Supplemental response to first set of interrogatories & request for production of documents Includes info re utils which purchased caal-fired economy energy from City Public Svc Board of Sam Antonio HILSON.W R Matthews, Nowlin, MacParlane & Barrett 80/03/20 12pp
- ---B004100444 Supplemental response to first set of interrogatories & requests for production of documents includes info re San Antonio refusal to transmit or receive interstate electrical power. Exhibits responsive to interrogatories encl WILSQN, W.R. San Antonio, TX WILSQN, W.R. Matthews, Nowlin, Macfarlane & Barrett 80/03/20 14pp
- --8004100447 Supplemental response to Brownsville Public Util Board JO4100447 Supplemental response to Brownsville Public Util Boa initial interrogatories % first request for production of documents includes info re joint action contemplated by members of TX interconnected Bys Certificate of Svc encl WILSDN.W R San Antonio, TX WILSDN.W R Matthews, Nowlin, Macfarlane & Barrett 80/03/20 66pp
- 8004i00534 Response to DDJ First set of interrogatories includes info re TX electric couperatives & wholesale suppliers Certificate of Svc enci * Teras Electric Service Co 80/03/20 2ipp
- 8004010262 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents BLUME, M B Antitrust Division 80/03/21 2pp
- 8004040184 Motion to quash subpoena directed to GW Stagg upon DOJ \$
 NRC joint request Absent evidentiary reliance upon Stagg
 Sys. Inc work nontestifying outside consultants are not subj
 to discovery process, per established rule
 FRANKLIN.W J Houston Lighting \$ Power Co 80/03/21 4pp

- 5004040198 Advises that Houston Lighting 5 Power does not intend to rely on Stage Jis In. studies as part of defense in proceeding IRC 1 Central 5 Southwest Corp contensions re Stage study based on misconception H/Certificate of Svc GREEN 0 0 Lowerstein Neural Reis Arelrad 5 Toll 80/03/21 7pp
- Cu34160111 Response to NRC ¹ Centra) & South West Corp comments reconsolidation Severance arguments based on belief that util util rely on study by 3tag; Sys. Inc as part of defense Util util not rely on Etags study Certificate of Swc encl
 GREEN D G Lovenstein, New-an Reis Arelrad & Yoll 80/03/21 App
- E004030360 Response by Public Utils Board of City of Brownsville, TX in opposition to nonconsolidation or proceeding suggested by NRC / Central & South West Corp In event of separation. South It Case should be heard first Centificate of Svc encl SPIEGFL.G Telas. State of 80/03/24 9pp
- GC04250049 Response in opposition to Public Utils Board of City of Brownsville.TX BC0317 corrects requesting admittance as party in consolidated proceeding Statement of interest untimely & vague Certificate of Svc encl
 AHEARN.C D Texas Utilities Generating Co AHEARN.C D Debevoise & Liberman 80/03/25 7pp
- 8CO4100271 Motion to compel production of documents by Southwest TX Electric Cooperative re subpoens directed to general manager E McGinnes Requests to strike McGinnes 8001221 deposition if documents are not produced M/draft subpoens & documentation GREEN D G Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis Azelrad & Toll 80/03/26 18pp
- --- 200410027B Motion to compel production of documents by Midwest Electric Cooperative re subpoena directed to general manager. P Metrel Requests to strike Wetzel rescheduled deposition if documents are not produced Wisubpoena & Certificate of Syc GREEN D G Houston Lighting & Power Co * Baker & Botts * Lowenstein. Neuman. Reis. Azelrad & Toll 80/03/28 15pp
- 8004080420 Application for issuance of subpoena directed to Gulf States Utils Co re settlement documents Documents not produced in response to 770709 & 800118 subpoenas Urges production to extent allowed by ASLAB BLUME, M B Antitrust Division 80/03/27 2pp
- --8004080424 Subpoena directed to Gulf States Utils Co requesting settlement documents, for insp & copying, in Mashington, DC on 800402 Subpoena may be quashed or modified upon request Certificate of Svc enc!

 MILLER, M E Atomic Safety and Licensing Board Panel 80/03/27
- 8004090126 Order denying Houston Lighting & Power 800321 motion to quash subpoens directed to GH Stagg upon DDJ request Prior rulings re nontestifying outside consultants, do not apply in this proceeding due to relevancy of Stagg studies MOLFE S J Atomic Safety and Licensing Board Panel 80/03/27 3pp
- 8004210384 Forwards Houston Lighting & Power 800327 motions to compel production of documents by NRC expert witnesses RH Hartley & NC Lerner Requests 800331 conference call prior to scheduled depositions
 FRANKLIN.W J Lowenstein, Newman, Reis, Axelrad & Toll 80/03/27 1p
- ~-8004210392 Motion to compel testimonial questions answered by NRC expert witness RH Hartley Discoverability of questions established on Pages 421-423 of prehearing conference transcript re ASLB 800420 order FRANKLIN, W J Houston Lighting & Power Co FRANKLIN, W J Lowerstein, Newman, Reis, Axelrad & Toll * Baker & Botts 80/03/27 app
- --8004210394 Submits preparation study for 800220-21 meeting re intraregional interconnections, transmission lines & other pooling matters HARTLEY,R H Affiliation Unknown 80/01/29 25PP
- --B004210397 Forwards RH Hartley B00211 memo to NRC re B00129 answers in preparation for B00220-21 meeting Requests questions to which answers were stated, per rule established in 790401 prehearing conference Pages 421-423 of transcript enci FRANKLIN.H J Lowenstein.Neuman,Reis,Azelrad & Toll 80/03/20
- --8004210400 Motion to compel electric util industry testimonial antitrust analyses prepared by NRC expert sconomic witness N Lerner re Midland proceeding Urges production per prior rulings, subj to encl protective order W/Certificate of Byc FRANKLIN.W J Houston Lighting & Power Co FRANKLIN.W J Lowenstein, Newman, Reis, Axelrad & Toli * Baker & Botts B0/03/27 14pp

- 8004070123 Order giving parties one wk to provide add1 authority resistence of settlement privilege Memoranda addressing issue should be received by 800404 / response thereto by 800409 BIGHOP.C J Atomic Sarety and Licensing Appeal Panel 80/03/28 2pp
- 8004070456 Protective order, in favor of Houston Lighting & Power, re confidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeking judicial review per FOIA WOLFE, S.J. Atomic Bafety and Licensing Board Panel 80/03/31 4p
- 8004100243 Order granting in part NRC motion to compel add1 responses by Houston Lighting & Power (HL&F) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions re RH Hartley testimony WOLFE.S J Atomic Safety and Licensing Board Panel 80/03/31 3pp
- 8004100428 Public Utils Board of Brownsville motion for leave to file affidavit as amicus curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Svc encl SPIECEL, O Brownsville, TX SPIECEL, G Spiegel & McDiarmid 80/03/21 Bpp
- ---BOO4100430 Affidavit of RE Roundtree, general manager of Brownsville
 Public Utils Board re agroement among TX "IOUs" for
 const of two do interstate ties of 500 MW & 250 MW
 Brownsville prepared to enter settlement negotiations
 ROUNDTREE, RE Brownsville, TX 80/03/27 3pp
- 8004080172 Updated response to Houston Lighting & Power second set of interrogatories & TX Utils first set of interrogatories Anticipates RE Corder participation as witness re areas discussed during Corder deposition Certificate of Syc encl CHANANIA,F D Antitrust Division 80/04/01 5pp
- 8004100240 Order requesting parties in directed certification proceeding, to respond to Utils Board of City of Brownsville, TX 800331 motion, by 800409 BIGHOP.C J Atomic Safety and Liconsing Appeal Panel 80/04/02 2pp
- 8004180151 Forwards joint motion for extension of time Motion is joined in by all parties to proceeding except DOJ & City Public Utils Roard of Brownsville, TX XNOTTG-J B Debevoise & Liberman BO/04/OZ ip
- --8004180167 Joint motion for 30-day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotations which could lead to resolution of part or all of
 proceedings Certificate of Svc encl
 CHANANIA: F D Antitrust Division COPELAND, J. G Houston Lighting
 & Power Co STAHL, D H Central Power & Light Co 80/04/02 Spp
- 8004i40003 Third set of addt enswers to NRC 770i15 initial interrogatories Simmons & Woodson are expected to testify reinterconnections
 FRANKLIN.W J Houston Lighting & Power Co # Baker & Botts # Lowenstein, Newman, Rejs. Axelrad & Toll 80/04/03 2pp
- 8004150032 Forwards opposition by Brownsville to joint motion for extension of time & request for prehearing conference, miscellaneous atty & util correspondence, affidavit & Brownsville rate estimates Certificate of Byc encl BPIEGEL, 0 , POIRIER, M R Spiegel & McDiarmid 80/04/03 17pp
- --B004150050 Opposition to joint motion for extension of time & request for prehearing conference Brownsville has been excluded from negotiations on which request for extension is based Certificate of Svc encl SPIEGEL, 0, POIRIER, MR Brownsville, TX BPIEGEL, 0 Bpiegel & McDiarmid B0/04/03 2pp
- B004230066 Forwards Houston Lighting & Power B00403 motion to compet production of documents & JW Wilson testimony by Public Utils Board of City of Brownsville, TX Proposes expedited schedule to permit completion of expert witness discovery GREEN, D.G. Lowenstein, Newman, Reis, Axelrad & Toll 80/04/03 2pp
- --8004230074 Motion to compel production of documents & JH Wilson expert testimony by Public Utils Board of City of Brownsville, TX If motion not granted requests order precluding Wilson from hearing W/proposed order re schedule & Certificate of BYC BALDMIN. J M Houston Lighting & Power Co * Daker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/04/03 lipp
- 8004100126 Memorandum in response to ABLAB 800328 order requesting add1 authority re recognition of settlement privilege Courts % case law do not recognize existence of privilege Cartificate of Svc encl BLUME, M B , HDDQDDN, A P Antitrust Division 80/04/04. Opp

- 8004150083 Order setting 800411 conference at NRC Hearing Room. Bethesda, MD Oral argument will address NRC & DOJ joint motion for 30-day extension & Houston Lighting & Power 800403 motion to compel Vtils Board of Brownsville WOLFE, S J Atomic Sefety and Licensing Board Panel 80/04/04
- 8004170312 Memorandum of authorities re discoverability of settlement documents Urges reversal of ABLB 800307 ruling due to privilege recognized per case law & federal rules of evidence Supporting documentation & Certificate of SVc encl BOUKNIGHT, J A , GREEN. D G Nouston Lighting & Power Co BOUNIGHT, J A , Daker & Botts 80/04/04 Bipp
- 8004220128 Memorandum of authorities in support of settlement privilege Documents prepared in connection w/settlement process should be protected from discovery under work product privilege Certificate of Svc encl STAHL.D Central & Southwest Services, Inc. STAHL.D Isham. Lincoln & Beale 80/04/04 10pp
- 8004240043 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compal production of documents Represents that util consents to extension O'NEILL,R A Southwest Texas Electric Cooperative O'NEILL,R A Miller, Balis & O'Neil 80/04/04 3pp
- 8004240045 Certifies svc of consent motions for extension to respond to Houston Lighting & Power Co motion to compel production of documents from Midwest Electric Cooperative & Southwest TX Electric Cooperative, on 800404 O'NEILL.R A Miller, Balis & O'Neil 80/04/04 App
- 8004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents util consent to extension O'NEILL.R A Southwest Texas Electric Cooperative O'NEILL.R A Miller.Balis & O'Neil 80/04/04 3pp
- 8004240173 Memorandum, per ASLAB 800328 request, stating add1 authorities re directed certification of settlement document issue Treatises & modern trend hold inadmissibility of privileged documents as avidence Certificate of Svc encl KNDTTB, J B , AHEARN, C D Texas Utilities Generating Co KNDTTB, J B Debevoise & Liberman 80/04/04 22pp
- BOO4250104 Advises of arrangement to deliver Houston Lighting & Power pleadings moving to compel documents re E McGinnes & P Wetzel subpoenss Consents to 14-day extension for responses Certificate of Bvc encl OREEN, D Q Lowenstein, Newman, Reis, Aselrad & Toll BO/04/04 Spp
- GOO4100552 Motion to issue order compelling Southwest TX Electric Cooperative & general manager E McGinnes to produce, for insp & copying, documents set forth in motion Draft subpoena & Certificate of Svc encl OREEN, D O Houston Lighting & Power Co OREEN, D G Baker & Botts 80/04/07 18pp
- --8004100560 Motion to issue order compelling Midwest Electric Cooperative & general manager P Metrel to produce for insp & copying documents responsive to subposens served on Wetrel Draft subposens & Certificate of Svc enci GREEN.D G Houston Lighting & Power Co OREEN.D G Baker & Botts 80/04/07 15pp
- 8004230154 Motion to preclude DDJ from filing principal brief re ASLAB 800328 order DDJ failed to file principal brief by 800404 DDJ seeks to obtain unfair tactical advantage by untimely filing BDUKNIGHT, J A., GREEN, D Q Houston Lighting & Power Co BDUKNIGHT, J A Baker & Botts 80/04/07 3pp
- --8004230162 Order directing all parties to furnish ABLAB w/addl authority re-privilege against discovery of documents, Memoranda due on 800404 BIBHDP,C U Atomic Safety and Licensing Appeal Panel 80/03/28 App
- 8004240041 Motion for ASLB to reconsider extending procedural dates for 30 days. Requests 800408 conference call to rule on extention TX Utils Generating Co is only party to be prejudiced by extending dates CHANANIA.F Antitrust Division BOUKNIGHT. J A Houston Lighting & Power Co. BURCHETTE.W H Texas-Louisiana Electric Cooperative. Inc 80/04/07 3pp.
- --8004240071 Supplemental argument & representations Addl time required by utils to make progress in settlement discussions Discussions began Sept 1979 Parties are optimistic about possibility of reaching quick settlement BURCHETYE.W H Texas-Louisiana Electric Cooperative, Inc KNOYTS, J B. Texas Utilities Generating Co 80/04/07 5pp

- B004210147 Discovery tept for Mar 1980 Deposed JA Bruggeman, J7 Wenders, AJ Wood & DA Springs Moved to compel MRC deposition of ND Lerner Responded to DDJ motion to compel supplemental answers to first interrogatories W/Ceitificate of Svc FRANKLIN, N J Houston Lighting / Powel Co FRANKLIN, N J Lowenstein, Neuman, Reis, Axelrad & Toil B0/04/08 6pp
- BOO4150157 Response to Houston Lighting & Power, TX Utils Generating Co & Central & South West Cos BOO404 memoranda of authorities resettlement privilege Urgos affirmation of ASLB BOO307 order is production of documents W/Certiricate of BVC CHANANIA,F D., HONGDON,A P. Antitrust Division BO/04/09 10pp
- B004170347 Response to Public Utils Board of City of Brownsyille.TX 800331 motion to file RE Roundtree affidavit as amicus curiae Disclosure of documents should not affect potential for settlement Certificate of Szc encl CHANANIA,F D Antitrust Division 80/04/09 App
- 8004220021 Response to Public Utils Board of City of Brownsville.TX 800331 motion to file Roundtree affidavit Requests to file counter-affidavit,re status of settlement if Roundtree affidavit is accepted by ASLAB Certificate of Svc encl KNOTTS.J B Teras Utilities Generating Co 60/04/09 App
- 8004220152 Response to Houston Lighting & Power 800403 motion to compel production of documents & deposition of Public Utils Board of City of Brownsville. TX Does not appose motion if subj to encl protective order Appearance & Certificate of Svc encl ROTH, A J. JACOBS, J C. Florida Cities ROTH, A J. Spiegel & McDiarmid 80/04/09 14pp
- 8004240562 Response in opposition to NRC 800404 memorandum of addl authorities re-existence of settlement documents privilege Congress did not intend to freeze developing law of privilege W/Certificate of Svc KNOTTS, J. B., AHEARN, C. D. Teras Utilities Generating Co. KNOTTB, J. D. Debevoise & Liberman 80/04/09 Spp
- 8004170351 Order granting 30-day extension for procedural matters, amending ASLB 791214 order re discovery schedule & directing consolidation of proceedings for pretrial & evidentiary hearings Consent motions for extension to 800404 granted MILLER.M E Atomic Safety and Licensing Board Panel 80/04/10 500
- 8004210141 Order denying Houston Lighting & Power matian seeking to preclude DDJ memorandum of addl authorities filed per ABLAB 800328 order BISHQP,C J Atomic Safety and Licensing Appeal Panel 80/04/10
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Fikar requested during 800409 oral argument KNOTTS:J B Debevoise & Liberman 80/04/10 ip
- ~-8004R30041 Affidavit stating that Central & South West Corp. Houston
 Lighting & Power Co & TX Uiils Co Sys have reached agreement
 in principle re interconnection disputes Agreement may form
 basis for discussions w/other partics W/Certificate of Bvc
 FIKAR.L F Texas Utilities Generating Co 80/04/10 5pp
- 8004230002 Responds to Public Utils Board of City of Brownsville.TX opposition to joint motion for extension of time Objects to alleged refusel to wheel & submits ML Borcheit affidavit in response to alleged exclusion from discussions STAHL.D M Central & Southwest Corp STAHL.D M Isham, Lincoln & Beale 8000411 30c
- --8004230007 Affidavit responding to Public Utils Board of City of Brownsyille:TX allegation that Brownsyille has been excluded from discussions re interconnection Clarifiles statement made at 800327 meeting Certificate of Svc encl BDRCHELT.M i. Carolina Power & Light Co 80/04/10 10pp
- BO04290227 Discovery rept for Mar-Apr 1980 Participated in FJ Meyer.HH Woodson & GW Stagg depositions Filed apposition to petitions for directed certification & reversal of ASLB B00307 order Joined other parties in moving for procedural extension CHANANIA.F D. BLUME.M B. HDD0DDN.A P Antitrust Division 80/04/25 3pp
- N Antitrust hearing transcripts
- HOO4150298 Transcript of BOO409 hearing in Bethesda,MD Pp 1-140 * Commission BO/04/09 140pp

- . Inspection reports If 3 Herina * correspondence
- F1040706-3 Re conds to JE dilletin 79-28 "Possible Malfunction of NHMTO Model FAID, plots uper nes at Elevated Temps " Util util triprogress rups, se stem-rounted limit switch impact on socialists at Tripy intervals TURNER & A Houseon Lip ring & Power to 80/02/01 Ip
- GC04189714 Forwards IE Insp Aepts 50-498/80-02 & 50-499/80-02 on 300205 G3 No Honocompliance incred EELU E 14 Pegron 4 Tallas Reactor Construction & Engineering Support Brainn 180/07/71 Zpp
- --3004180218 IE insp Repts 50-498/80-02 % 50-499/80-02 an B00205-08 No noncepliance notes Major areas inspected const activities re-relieu of procedures observation of work re-reactor coulant piping of licensee actions on previous insp findings HALL R E TOTLINSON D P Region 4. Dallas, Reactor Construction & Engineering Support Branch (ROSSMAN, M A Region 4, Dallas, Office of the Director B0.02/20 Tpp
- B104010126 Responds to IE Bulletin 79-28. "Possible Malfunction of MAMOU Mudel EAlby Limit Suitches at Elevated Temps." Updates B00201 response to IMC Fisher Controls initiated corrective action. Westinghouse suitches not affected TURNER E.A. Houston Lighting & Power Co. B0/02/27. Opp
- EDG4140107 Corrects typographical error in util response (BT-ML-AE-417) to NRC Insp Repts 50-488/79-19 % 50-489/79-19 TURNER E A Houston Lighting & Power Co 80/02/28 1p
- 8004076057 Ack receipt or 791113 & 800212 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-15 & 50-499/79-15 SEIDLE W C Region 4. Dalias. Reactor Construction & Engineering Support Branch 60/03/11 lp
- ~-8004070060 Responds to NRC 800124 ltr re violation noted in IE Insp Rapts 50-498/79-15 & 50-499/79-15 Corrective actions concrete placement was revibrated satisfactorily Vibrator operators will be retrained every 90 days TURNER.É A Houston Lighting & Power Co 60/02/12 2pp
- 8004300028 Forwards IE Insp Repts 50-498/80-03 & S0-499/80-03 on 800226-29 No incrempliance noted EffEL: N C Region 4. Pallas. Reactor Construction & Engineering Support Branch 80/03/11 2pp
- --BOD4300035 IE Insp Repts 50-498/80-03 / 50-499/80-03 on 800226-29 No noncompliance noted Major areas inspected site tour reactor welding & other safety-related welding records review & procedures for piping fabrication

 HALL R S CROSSMAN, W A GILBERT, L D Region 4, Dallas, Office of the Director 80/03/11 App
- 8004300514 Act receipt of 800226 % 791102 ltrs informing NRC of steps taken to correct violations noted in JE Jusp Repts 50-498/79-13 % 50-499/79-13 % 50-499/79-13 % 50-499/79-13 % 50-499/79-13 % 50-499/79-13 % 50-499/79-13 % 50-499/79-13 % Figure Nation & Engineering Support Branch 80/03/21 Ip
- --80043005E3 Responds to NRC 800131 ltr requesting addl info re violations noted in IE lnsp Repts 50-498/79-13 & 50-499/79-13 Corrective actions Pittsburgh-Des Moines QA manual revised adding info re QA coordinator authority TURNER E A Houston Lighting & Power Co 80/02/24 2pp
- 8004240216 Forwards IE Info Natice 80-14. "Safety Suggestions From Employees" No action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/02 ip
- 8004220260 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Gil Sus " No written response required EEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/03
- 8004220777 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312-Type 304 Stainless Steel Pipe " Action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/04 p
- 8004220233 Forwards IE Bulletin 80-08, "Exam of Containment Liner Fenetration Welds " Written response required SEYFRIT,K V Region 4. Dallas, Office of the Director 80/04/07

- S Reportable occurrences, LERs & related correspondence
- 8004010332 Disrusses possible reportable deficiency re backfill matl Extent of nonconforming backfill compaction has not been fully defined Initial tosting indicates that nonconformances are focalized incident unil be reviewed further TURNER, E. A. Houston Lighting & Power Co. 80/03/21. Spp
- BOO4040394 Forwards first interim deficiency rept consisting of schematic drawing of logic for liner plate bulgo repair OPREA:0 W Houston Lighting & Power Co BO/03/24 Jap
- ---8044940409 First interim deficiency rept consisting of schematic drawing of lagic for liner plate bulge repair * Houston Lighting & Power Co 80/03/24 Ip
- 8004040390 Advises that patential deficioncy reported on 800224 involving main feedline rupture w/assumed failure in steam generator blowdown sys does not constitute safety concern Considers matter closed OPREA:Q W Houston Lighting & Power Co 60/03/27 3pp
- 8004180384 Final deficiency rept is voids detected under crossover leg embed plates Evaluation shows that condition would not affect safety of plant therefore not reportable per 10CFR50 55(e)

 TURNER,E A Houston Lighting & Power Co 00/04/07 3pp
- 8004180423 Interim deficiency reptire wolds in essential cooling water sys Methods to verify integrity of weld joints are being evaluated Second interim reptivally be submitted by 800613 Oversize drawling indicating weld incations enclifurnment of Houston Lighting & Power Co. 80/04/10. 4pp
- 8004180421 Deficiency rept re unqualified motor operator for trip & throttle valve of turbine driven auxiliary feedwater pump Defective motor operators will be replaced w/IE qualified pumps off by Terry corp.prior to plant startup TURNER.E A Houston Lighting & Power Co. 80/04/11. 4pp
- 8004270378 Interim deficiency rept re broken tie-down studs in Unit i polar trane rail Caused by wolding w/low range parameters Encl plan issued for insp & testing of selected studs & associated plates Failures examined by stud supplies TURNER, E.A. Houston Lighting & Power Co. 80/04/16. 16pp
- T Hearing transcripts on non-antitrust matters
- 8004210312 Transcript of D00327 hearing in Bethesda:MD Pp 1-12/ * Atomic Gafety and Licensing Appeal Panel 80/03/2/ 130pp
- DOCKET STN-50-499 SOUTH TEXAS PROJECT. UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Btaff Position on Environ Gualification of Bafety-Related flectrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- 6004040017 Submits addit guidance to NUREQ-0988, "Interim Staff Position on Environ Qualification of Safety-Related Listrical Equipment "Requests review of equipment qualification documentation to identify degree of compliance ROSE, D.F. Division of Project Management 80/02/21 3pp
- 8004040240 Updates nine point action program to GA program identified in util 791828 ltr & 800125 status rept Actions 1-3 & 5-0 have been implemented Proposes to begin placement of safety-related complex concrete on 800303 GPREA, O W Houston Lighting & Power Co 8007280 Gpp
- 800423005B Requests info re auxiliary feedwater sys per Bulletins & Orders Task Force review of TMI-2 accident info should be provided as amend to application Submittal schedule should include NRC approval prior to issuance of OL Wiencl ROSS, D.F. Division of Project Management 80/03/10 53pp
- 8004150128 Forwards request for addl info concerning review of facility FSAR PARR.O D Light Water Reactors Branch 3 80/01/10 5pp
- 800A010377 Advises that instrumentation & control diagrams for review of FBAR Chapter 7 have been transmitted to CM Burks of DRNL in response to NRC request BARKER.D G Houston Lighting & Power Co 80/03/28 3pp

- 8004140463 Forwards Lower CO River Authority data re South TX Interconnected Sys interchange for 1979 Data should provide index re types & magnitude of member interchange within South TX interconnected Sys WEST,W E Texas. State of 80/04/07 14pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending 0AD clearance under Federal Repts Act GRIMES, B K Emergency Preparedness Task Force 80/03/11 4pp

Q Adjudicatory correspondence

- 8004080360 Response in apposition to DOJ & NRC joint motion for mod of ASLB order re-settlement discussions & for order to compel production of documents NRC policy favoring settlement is designed to protect sources involved W/Certificate of Svc * Central & Southwest Corp 80/03/06 11pp
- 8004100274 No objection to intervenor Citizens Concerned About Nuclear Power. Inc 800302 motion for extension to answer applicant second set of interrogatories Objects to mischaracterizations made in motion Certificate of Svc encl BIDDLE, C T Houston Lighting & Power Co BIDDLE, C T Baker & Botts 80/03/06 5pp
- B004020136 Response to ABLB 800310 memorandum inviting views re feasibility of early hearing Concurs w/ASLB suggestions & desires to participate in hearing within memorandum conditions Certificate of Svc enc! CULP.R H . SCHWARZ,M D Houston Lighting & Power Co CULP.R Lawenstein, Newman, Reis, Axelrad & Toll B0/03/19 App CULP, R. H.
- B004280069 Response to ASLB B00310 memorandum re hearing to consider issues on alleged const & QA/QC deficiencies Early hearing may foreclose possibility of raising similar issues at later time Certificate of Byc encl
 BINKIN:L. Citizens Concerned About Nuclear Power, Inc. B0/03/24
- B004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification QOSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- 8004210414 Response to ASLB 800310 memorandum inviting views re feasibility of separating admitted contentions Views will be submitted when IE investigation re assessment of GA/GC affectiveness; is completed W/Certificate of Svc TREBY.8 A Hearing Branch i 80/04/10 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004220763 Forwards Amend 10 to FSAR consisting of responses to first round review questions concerning initial startup testing Affidavit encl TURNER E A Houston Lighting & Power Co 80/04/21 3pp Houston Lighting & Power Co 80/04/21 3pp
- --8004220767 Amend 10 to FBAR
 * Houston Lighting & Power Ca 80/04/21 125pp

M Antitrust correspondence

- 8004020208 Response to Central & South West Corp et al second request for production of documents Stage Sys Inc workpapers available for insp & copying Documents re transactions already produced Certificate of 80¢ encl COPELAND, J O Houston Lighting & Power Co 80/02/25 6pp
- 8004ii0030 Discusses addl request for documents located in Chalker personal files Request is untimely & deficient, failing to specify relevancy to proceeding No obligation to respond to request by 80027, per Commission Rules of Practice STAHL, D M Isham, Lincoln & Beala 80/02/25 2pp
- 8004020147 Forwards DOJ & NRC 800228 Joint motion for mod of ASLB order re-settlement discussions & for issuance of order to compet production of certain documents & testimony, Proposed order CYPHERT, 8, B Justice, Dept of 80/02/28 4pp
- --8004020164 Joint motion for mod of ABLB 790416 order re protection of settlement discussions & for issuance of order to compel production of documents & testimony from Houston Lighting & Fower & TX Utils W/Certificate of Svc CYPBERT, B B Justice, Dept of 80/02/28 120pp

- -8004020175 Oral deposition of ED Scarth is certification of questions Pp 2-8
 * Atomic Safety and Licensing Board Panel 80/02/22 9pp
- --8004020181 Motion to compel TX Utils Cos to supplement Apr & Jul 1979 responses to first set of interrogatories & requests for production of documents Urges performance of current new obligations by 800306 W/Certificate of Rv. / proposed order CYPHERTS 8 Justice Dept of 80/02/28 /pp
- --8004020190 Motion to compel Houston Lighting & Power to supplement 790111 > 0427 answers to 701122 interrogatories Urges fulfillment of current abligations arising from development of new info Certificate of 800 & proposed order encl CYPHERT, S.B. Justice, Dept of 80/07/28 7pp
- --8004020198 Joint application for issuance of subpoend directed to ED Scarth of TX Utils Gonerating Co & DE Simmons of Houston Lighting & Power Requests extension until 800402 to depose DE Bimmons Draft subpoends & Certificate of Sycienci CYPHERTS B. Justice. Dept of CHANANIA. F. Antitrust Division 80/02/28 /pp
- BOO4020078 Metion for protective order re disclosure of Diamond Shamrock Corp documents in response to ASLB HO011B subpoena duces tecum Documents in question are subject contractual abligations Certificate of Suc & proposed order end CYPHERT.B B Justice.Dept of BO/02/29 tOpp
- BOO4080174 Notifies of change of address for counsel of South TY Electric Cooperative Inc. / Medina Flectric Cooperative Inc. effective BOO310 JOHN D.F. Akin. Gump. Hauer & Feld BO/03/04 1p
- 8084100498 Discovery rept for Feb 1980 Southwest TX Electrical Cooperative.Inc & Medina Flectric Cooperative.Inc neither initiated nor received any discovery requests Certificate of Svc encl JOHN,D F Akin, Gump, Hauer & Feld 80/03/04
- 8004110574 Confirms GOD229 telcon re DUJ subpoens of documents from Ouif States Utils Subpoens covers certain areas also covered in Brownsville Public Utils subpoens Gulf States documents will be available to all parties RADER.R M Conner, Moore & Corber GO703/04 2pp
- BO04090387 Discovery rept for feb 1980 Participated in A Gerber, M Hebb. E Simmons, V Robertson & GW Beams depositions Attended J Turk. & S Phillips depositions Filed motion for addl time to respond to IX Utils suberrogatories by Vertificate of Gyc CARNEY, J A Central & Southwest Corp. 80/03/05 7pp
- 8004090421 Discovery rept for Feb 1980 No discovery requests received nor initiated Certificate of Svc encl MODD.J C San Antonio, TX MODD.J C Matthows, Nawlin, Macfarland & Barrett 80/03/05 4pp
- 8004110024 Discovery rept for Feb. 1980 City of San Antonio, acting by & through City Public Svc Board of San Antonio, neither initiated nor received any discovery requests Certificate of Byc encl WOOD, J.C. San Antonio, TX 80/03/05 4pp

- PID ACC HOME ANA PROMISE IN 1915 SET ON EQUITY NAC 600228 joint notion for moder ACCP order reservice entilisymment? For order to compel productions of 10 newly Negotiations now to be protected for Bulle of Extenne 408 Whotestricate of Svc AHEARN (C) Telas Unities Generating Co. 80/03/06. 30pp
- 60:4070185 Nursice of appearance un behalf of Public Utils Board of City of Brownsvi}le To in consultrated discovery Certificate of of Browners,... Sec enci GPIEGEL G Texas, State of 60,0370a App

- E104096434 Discovery rept by Public Utils Board of City of Brownsville, To for Feb 1980 Deposed M Borchelt of Central Power & Light Participated in R Edelstein Jeposition Recrived documents from Central 1 South West Corp Lertificate or Svc encl POIRIER. It R Telas. State or E0/03/05 6pp
- ELO410321B Notifies that DOJ received Houston Lighting & Power Co supplemental answers to Central Power & Light Co first interrogationies U/o apps Requests Attachment A to Houston Power & Light Co second set of add answers to NRC CYPHERT. S B Justice. Dept of 80/03/06 ip
- 6004100433 Nutice of appearance of G Spiegel on behalf of Public Utils Commission of Brownsville.Tr Certificate of Svc encl SPIEGEL G Brownsville.Tr 80 03/06 App
- 8004100535 Discovery rept for Jan / Feb. 1980. City of Austin has neither initialed nor reveived any discovery requests BALDUGH R C Austin, Ti. 80/03/07 5pp
- 8004080044 Response by Public Utils Board of City of Brownsyille, TX, in apposition to Central & Southwest Corp 800222 metion for profective order, re-second set of interiogatories & production or documents M/Corrificate of Suc & 800207 ltr POIRIER, N R Telas. State of 80/03/10 12pp
- BOO4100514 Forwards notice of taking of deposition of D Springs AHEARN.C D Debevoise & Liberman 80/03/10 lp
- --B004100525 Natice of taking of deposition of D Springs on B00313-14 in Atlanta.GA Deponent will be examined on matters re bulk power supply & transmission D wheeling svcs in TX Certificate of Svc end AHEARN.C D Texas Utilities Generating Co B0/03/10 5pp
- SC04110169 Notifies that W Scott Jeposition scheduled for Mar is cancelled Cancellation based on DOJ representation that Scott would be called as expert withness BALDWIN.J M Bater & Botts 80/03/10 5pp
- 8004080018 Updated response to first set of interrogatories & document requests includes info re witnesses, competitive utils, product & geographic market & petitions to intervene Prof qualifications of DA Springs & Certificate of Svc encl BURCHETTE, WH Telas-Louisiana Electric Cooperative, Inc. 80/03/11
- 8004090164 Second supplemental response to first set of interrogatories & document requests includes 1640 re projected loads, capacity & reserves as of 800215
 SLICKER,F K Tesas Utilities Co 80/03/11 5pp
- BOO4090175 Supplemental response to third set of interrogatories & document requests Supplemental answer to Interrogatory IB enci W/o enci SLICKER.F K Taxas Utilities Co 80/03/11 3pp
- B0040901B0 Supplemental response to first set of interrogatories & datument requests includes into re monthly fuel cost adjustments for 1979
 BLICKER,F K Teras Utilities Co B0/03/11 4pp
- 8004100084 Forwards DDJ subpoens requiring DE Simmons, util vice president to testify 800331-0402 Confirms that Simmons will be available for deposition on 800404-05 instead of dates listed in subpoens H/o encl CYPHERT, S B Justice, Dept of 80/03/11 1p
- BOO410022I Fourth supplemental response to first set of interrogatories & document requests includes into recrities & utils which have explored power alternatives offered by TX Utils Co SLICKER, F K Texas Utilities Co BO/03/II 3pp
- BOO403025B Response in opposition to schedule proposed by NRC for reply to motion to quash BOO221 subpoens directed to R Frame Herit of NRC argument will be better evaluated after Lerner deposition Buggests BOO321 for reply W/Certificate of Svc KNOTTS.J S Telas Utilities Generating Co BO/03/12 5pp

- B004020113 Forwards Houston Lighting * Power B00313 petition for directed certification of ASLB B00307 order re confidential documents of settlement negotiations B0UKNIGHT, J A Lowenstein Newman, Reis, Axelrad & Toll B0/03/13
- --8004020119 Petition for directed certification, interim stay & review of ASLB 800307 order requiring Houston Lighting & Power to produce settlement negotiations documents Urges revensal of ruling Myaxcerpts of 800307 pre-hearing transcript BQUKNIOHT, J A Houston Lighting & Power Co 80/03/13 19pp
- --8004020122 Order re NRC 790323 motion to compel further answers to Houston Lighting & Power first interrogatories Directs util to furnish list of privilaged documents Orders responses to majority of questions Westerpts of 790401 prehearing MILLER,M E Atomic Safety and Licensing Board Penel 79/04/16
- 800408002B Forwards DOJ third supplemental response to Houston Lighting 2 Power Co first set of interrogatories Documents responsive to util 790204 second set of interrogatories encl Documents respond interrogatories not encl
 CYPHERT, S B Justice, Dept of 800/03/13 1p
- --B004080033 Third supplemental response to first set of interrogatories to document requests Includes in force GT Taylor testimony refour relevant product markets iπ proceedings CYPHERT,S D Justice,Dopt of 80/03/13 30pp
- B004080073 Application for issuance of subpoena directed to FG Arey of Webster Engineering Corp. to be deposed & to produce documents re interconnections & imterconnected sys Draft subpoena & Certificate of Svc enc! GREEN, D 9 Houston Lighting & Power Co 80/03/13 13pp
- 8004090437 Ack receipt of & accepts 800312 ltr in lieu of interragetory answer per 800307 prehearing ruling Ltr does not solve Houstan Lighting & Pawer problems re C Stover deposition DOJ 800311 & 12 ltr & Certificate of Swc encl GREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/03/13 10pp
- 8004100545 Response to third set of interragetories Includes info re electric power & energy delivered to various utils during Dec 1977 Certificate of Svc encl * Texas Electric Service Co 80/03/13 16pp
- 8004080370 Discovery rept for Feb 1980 Deposed J Wilson, OC Campbell & V Robertson et al Attended DOJ & NRC depositions, Berved 800201 first set of interrogatories to NRC Received addl responses to interrogatories Certificate of Svc encl FRANKLIN, W J Houston Lighting & Power Co 80/03/14 7pp.
- 8004040078 Comments by Public Utils Board of City of Brownsyills, TX, stating no position re-consulidation for trial advised by ASLB during 800307 prehearing If consolidation ordered, right of cross-examination must be proserved W/Certificate of svc POIRIER, M R Texas, State of 80/03/17 7pp
- B004080153 Statement in opposition to consolidation of proceedings for hearing purposes, per ASLB 800307 prehearing conference request Issues not identical & evidence in South TX Project may not be related Commanche Peak Certificate of Svc encl. STAHL, D M Central & Southwest Corp 80/03/17 9pp
- 8004080247 Discovery rept for Feb 1780 Participated in Ammons, Neams, Borchelt, Campbell, & Yambrough depositions Inspected DDJ documents Received & opposed Central & Southwest motion for addlitime to reply to interrogatories W/Certificate of Svc AHEARN, C.D. Texas Utilities Co. 80/03/17 5pp
- BOO4080401 Submits TX Utils Generating Co response to ABLB 800307 request re views on consolidation of proceedings for hearing purposes Urges complete consolidation KNOTTS. J B Debevoise & Liberman 80/03/17 4pp
- 8004080663 Order confirming results of 800907 oral argument NRC & DOJ joint motion, re-mod of older concerning protection of settlement discussions, granted in part Parties may not engage in further discovery re-documents included in motion GLASER, M.L. Atomic Safety and Licensing Board Panel 80/03/17
- 8004210437 Notice of appearance in proceeding Certificate of Svc encl OLAZIER, K M Justice, Dept of BO/03/17 4pp
- B004070427 Discovery rept for Jan-Feb 1980 Participated in H Drymy deposition No discovery requests initiated Certificate of BURCHETTE, W H Texas-Louisiana Electric Cooperative, Inc 60/03/19

- 8004010517 Order denying NRC 800311 motion to quash subpoena of R Frame TX Utils Generating Co entitled to test ND Lerner credibility by questioning work & documents prepared by Frame for Lerner review WOLFE.S J Atomic Safety and Licensing Board Panel 80/03/20 2pp
- 8004030347 Response in opposition to TX Utils Generating Co. Houston Lighting & Power Co & South West Corp 800313 petitions for directed certification of order campelling production of documents News article & Certificate of Svc encl CHANANIA: FD Antitrust Division 80/03/20 21pp
- 8004100177 Memorandum in opposition to petitions for directed certification filed by TX Utils Generating Co.Houston Lighting & Power Co & Central & South West Corp et al.re ABLB 800307 order Certificate of Svc encl CYPHERT.8 B Justice Dept of 80/03/20 26pp
- 8004100442 Supplemental response to first set of interregatories & request for production of documents includes info re utils which purchased coal-fired economy energy from City Public Svc Board of San Antonio HILBON, W R San Antonio, TX WILSON, W R Matthews, Nowlin, MacFarlane & Barrett 80/03/20 12pp
- --8004100444 Supplemental response to first set of interrogatories & requests for production of documents Includes info re San Antonio refusal to transmit or receive interstate electrical power Exhibits responsive to interrogatories encl WILSON, W R Ban Antonio, TX WILSON, W R Matthews, Nowlin, Macfarlane & Barrett 80/03/20 16pp
- --8004100447 Supplemental response to Brownsville Public Util Board initial interrogatories & first request for production of documents Includes info re joint action contemplated by members of TX Interconnected Sys Certificate of Syc encl WILBON, W R San Antonio, TX WILBON, W R Matthews, Nowlin, Macfarlane & Barrett 80/03/20 66pp
- 8004100534 Response to DOJ first set of interrogatories Includes info re TX electric cooperatives & wholesale suppliers Certificate of Svc ancl * Yesas Electric Service Co 80/03/21 2ipp
- B004010262 Clarifies NRC updated response to Houston Lighting & Power first set of interrogatories & request for production of documents

 BLUMEN B Antitryst Division 80/03/21 2pp
- BOD4040184 Motion to quash subpoens directed to GW Stagg upon DOJ & NRC joint request Absent evidentiary reliance upon Stagg work nontestifying outside consultants are not subj to discovery process, per established rule
 FRANKLIN, W J Houston Lighting & Power Co BO/03/21 4pp
- --8004040198 Advises that Houston Lighting & Power does not intend to rely on Stage Bys. Inc studies as part of defense in proceeding NRC & Central & Southwest Corp contentions re Stage study based on misconception W/Certificate of Byc GREEN.D O Lowenstein. Newman. Reis. Axeirad & Toll 80/03/21 7pp
- 8D04160111 Responds to NRC & Central & Southwest Corp comments reconsolidation Severance arguments based on belief that util will rely on study by Stagg Sys. Inc as part of defense Util will not rely on Stagg study Certificate of Syc encl GREEN.D O Lowenstein. Newman. Reis. Axelrad & Toll 80/03/21 6pp
- 8004030360 Response by Public Utils Board of City of Brownsville,TX in opposition to nonconsolidation of proceeding suggested by NRC & Central & South West Corp In event of separation, South TX case should be heard first Certificate of Svc encl SPIEGEL.0 Texas, State of 80/03/24 7pp
- 800A250047 Response in opposition to Public Utils Board of City of Brownsville.TX 800317 comments requesting admittance as party in consolidated proceeding Statement of interest untimely & vague Certificate of Svc encl A
- 8004100271 Motion to compel production of documents by Southwest TX Electric Cooperative re subpoems directed to general manager E McOinnes Requests to strike McGinnes 8001221 deposition if documents are not produced M/draft subpoems & documentation OREEN,D G Houston Lighting & Power Co 80/03/26 18pp
- --8004100278 Motion to compel production of documents by Midwest Electric Cooperative re subpoens directed to general manager P Wetzel Requests to strike Metzel rescheduled deposition if documents are not produced Wisubpoens & Certificate of Svc OREEN.D Q Houston Lighting & Power Co 80/03/26 15pp

- 8004080420 Application to issuance of subpoena directed to Gulf States
 Utils Co re settlement documents Documents not produced in
 response to 790709 & B00118 subpoenas Urges production to
 extent allowed by ASLAB
 BLUME, M B Antitrust Division 80/03/27 2pp
- ~-8004080424 Subpoeno directed to Gulf States Utils Cos requesting 800402 availability of settlement documents, for insp & copying, in Washington, DC Subpoena may be quashed or modified upon request Certificate of Svc enci MILLER, M E Atomic Safety and Licensing Board Panel 80/03/27 600
- 8004090126 Order denying Houston Lighting & Power 800321 motion to quash subpoens directed to GN Stagg upon DOJ request Prior rulings, re-nontestifying outside consultants, do not apply in this proceeding due to relevancy of Stagg studies WOLFE.8 J Atomic Safoty and Licensing Board Panel 80/03/27 3pp
- 8004210386 Forwards Housian Lighting 5 Power 800327 mations to compel production of documents by NRC expert witnesses RH Hartley & NC Lerner Requests 800331 conference call prior to scheduled depositions
 FRANKLIN.N J Lowenstein, Newman, Reis, Axelrad & Toll 80/03/27 ip
- --8004210392 Motion to compel testimonial questions answered by NRC expert witness RH Hartley Discoverability of questions established on Pages 421-423 of prehearing conference transcript re ASLB 800625 order FRANKLIN, W J Houston Lighting & Power Co 80/03/27 App
- --BD04210394 Submits preparation study for B00230-21 meeting re intraregional interconnections transmission lines & other pooling matters HARTLEY.R H Affiliation Unknown 80/01/29 25PP
- --B004210397 Forwards RH Hartley B00211 memo to NRC re 800129 answers in preparation for B00220-21 meeting Requests questions to which answers were stated, per rule established in 79601 prehearing conference Pages 421-423 of transcript encl FRANKLIN, W. J. Lowenstein, Neuman, Reis, Axelrad & Toll 80/03/20
- --8004210400 Motion to compel electric util industry testimonial antitrust analyses prepared by NRC expert economic ultness N Lerner re Midland proceeding Urges production per prior rulings, subj to encl protective arder W/Certificate of Svc FRANKLIN,W J Housten Lighting & Power Ca 80/03/27 14pp
- 8004090123 Order giving parties one wk to provide add1 authority re existence of settlement privilege Memoranda addressing issue should be received by 800404 & response thereto by 800409 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/28 2pp
- 8004090456 Protective order, in favor of Houston Lighting & Power, re confidential corporate study produced in response to NRC initial interrogatories Parties may challenge claimed confidentiality by seeking judicial review per FOIA WQLFE, 8 J Atomic Safety and Licensing Board Panel 80/03/31 4pp
- 8004100243 Order granting in part NRC motion to compel addit responses by Houston Lighting & Power (HL&P) Accords confidentiality to N Lerner analysis re Midland settlement Grants HL&P motion to compel NRC questions; a RH Hartley testimony WOLFE.S J Atomic Bafety and Licensing Board Panel 80/03/31 Spp
- 8004100428 Public Utils Board of Brownsville motion for leave to file affidavit as amicus curiae Brownsville is party to proceeding but has not formally appeared in appellate proceeding Certificate of Evc encl
 SPIEGEL.

 Brownsville. TX 80/03/31 8pp
- --B004100430 Affidavit of Ro Roundtrag, general manager of Brownsvills
 Public Utils Board re agreement among TX "IOUs" for
 const of two dc interstate tips of 500 MW & 250 MW
 Brownsville prepared to enter settlement negotiations
 ROUNDTREE,R E Brownsville,TX B0/03/27 3pp
- BOO4080172 Updated response to Houston Lighting & Power second set of interrogatories & TX Utils first set of interrogatories Anticipates RE Corder participation as witness re areas discussed during Corder deposition Certificate of Evc encl CHANANIA,F D Antitrust Division 80/04/01 5pp
- 8004100240 Order requesting parties in directed certification proceeding to respond to Utils Board of City of Brownsville, TX 800331 motion by 800409 BIGHOP, C J Atomic Safety and Licensing Appeal Panel 80/04/02 200

- B0041B0151 Forwards joint motion for eitension of time Motion is joined in by all parties to picceeding except DDJ & City Public Utils Board of Brownsylle, lX FARTS, J.B. Debevoise & Liberman B0/04/02 ip
- --8004180167 Joint motion for 30-day extension for all procedural dates
 Motion is based on progress of meaningful settlement
 negotations which could lead to resolution of part or all of
 proceedings Certificate of Svc enc!
 CHANANIA,FD Antitrust Division 80/04/02 App
- 8004140003 Third set of add1 answers to NRC 790115 initial interrogatories Simmons & Woodson are expected to testify reinterconnections
 FRANKLIN: 1 J Houston Lighting & Power Co 80/04/03 2pp
- --800414000B Second supplemental answers to Central Power & Light Co 790223 Interrogatories Simmons ! Woodson are expected to testify re interconnections Certificate of Svc enci FRANKLIN.W J Houston Lighting & Power Co 80/04/03 6pp
- 8004190032 Forwards opposition by brownsville to jount motion for extension of time & request for prehearing conference, miscellaneous atty & util correspondence, affidavit & Brownsville rate estimates Certificate of Sv. encl
 SPIEGEL.6 Spiegel & McDearmid 80/04/03 19pp
- **-9004150050 Opposition to joint motion for extension of time & request for prehearing conference Brownsyllle has been excluded from negotiations on which request for extension is based Certificate of Svc encl SPIECELIO Brownsvilte, TX POIRIER, MR Spiegel & McDiarmid BO/04/03 24pp
- 8004230066 Forwards Houston Lighting & Power 800403 motion to compel production of documents & JW Wilson testimony by Public Utils Board of City of Brownsville, TX Proposes expedited schedule to permit completion of expert utitless discovery OREEN, D & Lowenstein, Neuman, Reis, Axelrad & Toll 80/04/03 2pp
- --8004230074 Motion to compel production of documents & JN Wilson expert testimony by Public Utils Board of City of Brownsville,TX If motion not granted requests order precluding Wilson from hearing W/proposed order re schedule & Certificate of Svc BALDWIN. J M Houston Lighting & Power Co 80/04/03 11pp
- B004100126 Memorandum in response to ASLAB 800329 order requesting add1 authority re recognition of settlement privilege Courts & case law do not recognize existence of privilege Certificate of Syc encl BLUME, M B Antitrust Division 80/04/04 App
- 80041500B3 Order setting 800411 conference at NRC Hearing Room, Bethesda,MD Oral argument will address NRC & DDJ joint motion for 30-day extension & Houston Lighting & Power 800403 motion to compel Utils Board of Brownsyille WOLFE,S J Atomic Safety and Licensing Board Panel 80/04/04
- 8004170312 Memorandum of authorities re discoverability of settlement documents Urgas reversal of ASLB 800307 ruling due to privilege recognized per case law & federal rules of evidence Supporting documentation & Certificate of Svc encl BOUKNIGHT. J A Houston Lighting & Power Co 80/04/04 81pp
- 8004170340 Response stating no position re joint motion for 30-day extension in proceeding filed by NRC.Cential & South West Corp.Houston Lighting & Power.TX Utils Generating Co.City of Austin & other parties Certificate of &vc encl DOPSQVIC.D A Justice.Dept of 80/04/04 5pp
- 8004220128 Memorandum of authorities in support of settlement privilege Documents prepared in connection w/settlement process should be protected from discovery under work product privilege Certificate of Svc enci
- 8004240043 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents that util consents to extension O'NEILL.R A Southwest Texas Electric Cooperative 80/04/04 3pp
- B004240045 Certifies svc of consent motions for extension to respond to Houston Lighting & Power Co motion to compel production of documents from Midwest Electric Cooperative & Bouthwest TX Electric Cooperative; on B00404 O'NEILL, R A Miller, Bulis & O'Neil B0/04/04 App
- B004240053 Consent motion for two-wk extension to respond to Houston Lighting & Power Co motion to compel production of documents Represents util consent to extension G'NEILL, R A Gouthwest Texas Electric Cooperative 80/04/04 3pp

- BO04240173 Memorandum, per ASLAB 800328 request, stating add1 authorities re directed certification of settlement document issue Treatises 5 modern frend hold inadmissibility of privileged documents as evidence Certificate of Svc encl KNOTTS, J B Teras Utilities Generating Co AMEARN, C D Dubevoise & Liberman 80/04/04 22pp
- 8004250106 Advises of arrangement to deliver Houston Lighting & Power pleadings moving to compel documents to E McGinnes & P Hetiel subpoenas Consents to 14-day extension for responses Certificate of Svc encl GREEN, D Q Lowerstein, Newman, Reis, Axeliad & Toll 80/04/04 5pp
- 8004100552 Motion to issue order compelling Southwest TX Electric Cooperative & general manager E McGinnes to produce, for insp & copying, documents set forth in motion Draft subpoena & Certificate of Svc enc! GREEN, D G Houston Lighting & Power Co 80/04/07 18pp
- --8004100560 Motion to issue order compeliing Midwest Electric Cooperative & general manager P Wetrel to produce, for insp & copying documents responsive to subpoena served on Wetrel Draft subpoena & Certificate of Svc encl GREEN,D & Houston Lighting & Power Co 80/04/07 15pp
- 8004230154 Motion to preciude DDJ from filing principal brief re ASLAB 800328 order DDJ failed to file principal brief by 800404 DDJ seeks to obtain unfair tactical advantage by untimely filing BOUKNIGHT, J A Houston Lighting & Power Co GREEN, D O Baker & Botts 80/04/07 3pp
- --8004230162 Order directing all parties to furnish ASLAD w/addl authority re-privilege against discovery of documents Memoranda are due on 800404 B16HDP/C J Atomic Safety and Licensing Appeal Panel 80/03/28 5pp
- 800424006t Motion for ASLB to reconsider extending procedural dates for 30 days Requests 800408 conference call to rule on extention TX Utils Generating Co is only party to be prejudiced by extending dates CHANANIA.F Antitiust Division 80/04/07 3pp
- --8004240071 Supplemental argument & representations Addl time required by utils to make progress in settlement discussions. Discussions began Sept 1979 Parties are optimistic about possibility of reaching quick settlement. BURCHETTE.W.H. Teras-Louisiana Electric Cooperative, Inc. 60/04/07 Spp.
- 8004210147 Discovery rept for Mar 1980 Deposed JA Bruggeman, JT Wenders, AJ Wood & DA Springs Moved to compel NRC deposition of ND Lerner Responded to DOJ motion to compel supplemental answers to first interiogatories W/Certificate of Bvc FRANKLIN, W J Houston Lighting & Power Co 80/04/08 App
- BO04150157 Response to Houston Lighting & Power, TX Utils Qenerating Co & Central & Bouth West Cos BO0404 memoranda of authorities re settlement privilege Urgos affirmation of ABLD BO0307 order re production of documents UrCentificate of Boc CHANANIA, F D Antitrust Division BO/04/09 10pp
- BOO417034/ Response to Public Utils Board of City of Brownsville, TX BOO331 motion to file RE Roundtree affidavit as amicus curiae Disclosure of documents should not affect potential for settlement Cartificate of Svc encl CHANANIA, FA Antitrust Division 80/04/09 6pp
- 800A220021 Response to Public Utils Board of City of Brownsville, TX B00331 motion to file Roundtree affidavit Requests to file counter-affidavit.re status of settlement.If Roundtree affidavit is accepted by ASLAB Certificate of Byc encl KNOTTS.J B Texas Utilities Generating Co B0/04/09 6pp
- 8004220152 Response to Houston Lighting & Power 800403 motion to compel production of documents & deposition of Public Utils Board of City of Brownsville, TX Does not oppose motion if subj to encl protective order Appearance & Certificate of Svc encl ROTH, A J Florida Cities JACOBS, J C Fivin, Varn, Jacobs, Odom & Kitchen 80/04/07 14pp
- 8004240542 Response in opposition to NRC 800404 memorandum of add1 authorities re existence of settlement documents privilege Congress did not intend to freeze developing law of privilege W/Certificate of Svc KNOTTS, J B Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/04/09 8pp

- 8004210141 Order denying Houston Lighting & Power motion seeking to preclude DDJ memorandum of addl authorities filed per ASLAD 800328 order
 - BIGHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/04/10 200
- 8004230033 Forwards TX Utils Generating Co affidavit of LF Fikar requested during 800407 oral argument KNOTS:J B Debevoise & Liberman 80/04/10 ip
- --B004230041 Affidavit stating that Central & South West Corp.Houston Lighting & Power Co & TX Utils Co Bys have reached agreement in principle re interconnection disputes Agreement may form basis for discussions wother parties W/Certificate of Svc FIKAR.L F Texas Utilities Generating Co 60/04/10 Spp
- BOO4230002 Responds to Public Utils Board of City of Brownsville, TX opposition to joint motion for extension of time Objects to alleged refusal to wheel & submits ML Borchelt affidavt in response to alleged exclusion from discussions STAHL, D M Central & Southwest Corp BO/04/11 3pp
- --B004230007 Affidavit responding to Public Utils Board of City of Brownsyille, TX allegation that Brownsyille has been excluded from discussions re interconnection Clarifies statement made at B00327 meeting Certificate of Svc enc. BORCHELT, M.L. Carolina Power & Light Co. B0/04/10 10pp
- 8004290227 Discovery rept for Mar-Apr 1980 Participated in FJ Meyer, HH Woodson & GH Stage depositions Filed apposition to patitions for directed certification & reversal of ASLB 800307 order Joined other parties in moving for procedural extension CHANANIA, FD Antitrust Division 80/04/25 3pp

N Antitrust hearing transcripts

- 8004150298 Transcript of 800409 hearing in Bethesda, MD Pp 1-140 * Commission 80/04/09 140pp
- @ Inspection reports, IE Bullstins & correspondence
- 8004070062 Responds to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Util will submit progress repts re stem-mounted limit switch impact on facilities at 30-day intervals TURNER, E A Houston Lighting & Power Co 80/02/01 ip
- BO04180214 Forwards IE Insp Repts 50-498/80-02 & 50-499/80-02 on 800205-0B No noncompliance noted BEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/02/21 2pp
- --8004180218 IE Insp Repts 50-498/80-02 & 50-499/80-02 on 800205-08 No nancompliance noted Major areas inspected const activities re review of procedures & observation of work re reactor coolant piping & licensee actions on previous insp findings HALL-RE, TOM.INSON.DP Region 4. Dallas, Reactor Construction & Engineering Support Branch (ROSSMAN, M A Region 4. Dallas, Office of the Director 80/02/20 7pp
- 8004010126 Responds to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Updates 800201 response to NRC Fisher Controls initiated corrective action & Westinghouse switches not affected TURNER, E A Houston Lighting & Power Co 80/02/27 3pp
- 8004140107 Corrects typographical error in util response (ST-HL-AE-417) to NRC Insp Repts 50-498/79-19 & 50-499/79-19 TURNER, E. A. Houston Lighting & Power Co. 80/02/28, ip
- 8004070057 Ack receipt of 791113 & 800212 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-498/79-15 & 50-499/79-15 & 50-499/79-15 & SCIDLE,W C Region 4, Dailas, Reactor Construction & Engineering Support Branch. 80/03/11 ip
- ---B004070060 Responds to NRC B00124 ltr re violation noted in IE Insp Repts 50-498/79-15 & 50-499/79-15 Corrective actions concrete placement was revibrated satisfactorily Vibrator operators will be retrained every 90 days TURNER, E A Houston Lighting & Power Co 80/02/12 2pp
- 8004300028 Forwards IE Insp Repts 50-498/80-03 & 50-499/80-03 on 800226-29 No noncompliance noted BEIDLE:W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/03/ii 2pp

- --B00430093 IE Insp Repts 50-498/80-03 5 50-499/80-03 on 800226-29 No nuncompliance noted Major aleas inspected site topy, reactor welding k other safety-related welding, records review & procedures for piping rabrication HALL-R E . CROSHMAN, A . GILBERT. L D Region 4, Dallas, Office of the Director 80/03/11 4pp
- 8004300514 Ack receipt of 800226 & 791102 ltrs informing NRC of steps taken to correct violations noted in IE Imap Repts 50-498/79-13 & 50-499/79-13 SEIDLE.W C Region 4, Pallas, Reactor Construction & Engineering Support Branch 80/03/21 19
- --8004300523 Responds to NRC 800131 ltr requesting addl info re violations noted in IE lnsp Repts 50-498/79-13 & 50-499/79-13 Corrective actions Pittsburgh-Des Moines QA manual revised adding info re QA coordinator authority TURNER.E A Houston Lighting & Power Co 80/02/26 2pp
- 8004240216 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/02 in
- 8004220260 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine 011 Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/03
- 8004220777 Forwards IE Bulletin 79-03A "Longitudinal Weld Defects in ABME SA-312.Type 304 Stainless Steel Pipe " Action required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/04 in
- 8004220233 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/07
- S. Reportable occurrences, LFRs ≠ related correspondence
- 8004010332 Discusses possible reportable deficiency re backfill matl Extent of nonconforming backfill compaction has not been fully defined initial testing indicates that nonconformances are localized incident will be reviewed further TURNER, E.A. Houston Lighting & Power Co. 80703/21 Spp
- 8004040394 Forwards first interim deficiency rept consisting of schematic drawing of logic for liner plate bulge repair OPREA,6 N Houston Lighting & Power Co 80/03/24 3pp
- --8004040407 First interim deficiency lept consisting of schematic drawing of logic for liner plate bulge repair
 * Houston Lighting & Power Co 80/03/24 1p
- 8004040390 Advises that potential deficiency reported on 800226 involving main feedling rupture w/assumed failure in steam generator blowdows sys does not constitute safety concern Considers matter closed OPREA.O W Houston Lighting & Power Co 80/03/27 3pp
- 8004180394 Final deficiency rept ie voids detected under crossover leg embed plates Eveluation shows that condition would not affect safety of plant, therefore not reportable per 10CFRSO 55(e)

 TURNER, E. A. Houston Lighting & Power Co. 80/04/09. 3pp
- 8004180423 Interim deficiency rept re welds in essential cooling water sys Methods to verify integrity of weld joints are being evaluated Second interim rept will be submitted by 800513 Oversize drawing indicating weld locations end!

 TURNER, E. A. Houston Lighting & Power Co. 80/04/10. 4pp
- 8004180421 Deficiency rept re unqualified motor operator for trip & throttle valve of turbine driven auxiliary feedwater pump Defective motor operators unil de replaced w/IF qualified pumps mfg by Terry corp.prior to plant startup TURNER, E A Houston Lighting & Power Co 80/04/11 4pp
- 8004290398 Interim deficiency rept re broten tie-down studs in Unit i polar crane rail Caused by welding w/low range parameters Encl plan issued for insp & testing of selected studs & associated plates failures examined by stud supplier TURNER.£ A Houston Lighting & Power Co 80/04/16 16pp
- T Hearing transcripts on non-antitrust matters
- 8004210312 Transcript of 800327 hearing in Bothesda.MD Pp 1-127
 * Atomic Safety and Licensing Appeal Panel 80/03/27 130pp

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION. UNIT 2

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NURFG-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment," providing guidance re nethods for compliance ROSS, D.F. pivision of Project Management B0/02/05 7pp

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in radiological emergency planning & preparedness, distributed as Board notification QUSSICK, V Office of the Executive Director for Operations 80/04/02 34pp

@ Inspection reports: IE Bulletins & correspondence

8004040145 Forwards IE Insp Repts 50-500/80-01 & 50-501/80-01 on 800206 No noncompliance noted FIORELLI. G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/29 2pp

--B004040149 IE Insp Repts 50-500/B0-01 & 50-501/B0-01 on B00206 No noncompliance noted Major areas inspected condition of site const re limited work authorization HILLIAMS.C C , JONES.C E , GRANT, W B Region 3, Chicago, Office of the Director B0/02/26 4pp

DOCKET 50-901 DAVIS-BESSE NUCLFAR POWER STATION. UNIT 3

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance ie methods for compliance ROSS, D F Division of Project Menagement 80702709 7pp

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOBBICK. V Office or the Executive Director for Operations 80/04/02 34pp

G. Inspection reports, IE Bulletins & correspondence

8004040145 Forwards IE Insp Repts 50-500/80-01 & 50-501/80-01 on 800204 No noncompliance nated FIORELLI-Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/29 2pp

--8004040149 IE Insp Repts 50-500/60-01 % 50-501/80-01 on 800206 No noncompliance noted Major areas inspected condition of site const re limited work authorization MILLIAMS,C C . JONES,C E . GRANT, W B Region 3, Chicago, Office of the Director 80/02/26 App

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSS.D F Division of Project Management 80/02/05 7pp

8004010340 Forwards mod to NPDES Permit WA-002496-1 Mod does not involve adverse environ impact of safety issues & does not require mod to CP RENBERGER.D L. Washington Public Power Supply System 80/03/21

--8004010345 Mod to NPDES Permit WA-002496-1, issued to WA Public Power Supply Sys LEWIS.N D Environmental Protection Agency 76/10/27 11pp

8004280619 Advises that /91220 request for approval of alternative test method to verify max moisture in low hydrogen electrode coating is accepted Requests that notarized version of request be sent in addition to specific sites for use RUBENSTEIN, L E Light Water Reactors Branch 4 80/04/04 5pp

8004160285 Advises of fundamental misstatement in 800402 minutes of 800104 meeting w/util re GA program unionization Requests correction to reflect that fact had no influence on Local 598 election REYNOLDS.N.S. Deboyoise & Liberman 80/04/10 ip

8004150443 Requests concurrence in use of ABME. Section III. Code Case N-242 re mails cortification to resolve apparent conflicts in ABME interpretations of certification of code mails RENBERGER. D. L. Washington Public Power Supply System 80/04/11

8004210285 Responds to B00221 ltm re schedule for completing review of qualification of safety-related electrical equipment Schedule for completion of review will be provided after final issuance of NUREO-0588 RENBERGER.D L. Washington Public Power Supply System 80/04/11 ip

F Becurity, medical, emergency & fire protection plans

8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending CAO clearance under Federal Repts Act QRIMES, B K Emergency Preparedness Task Force 20/03/11 4pp

Q Inspection reports. IE Bulletins & correspondence

8004150220 Forwards IE Info Natico 80-12, "Instrument Failure Causes Opening of PORV & Hlock Valve " No specific action or response necessary ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/31 ip

8004100109 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco. Office of the Director, 80/04/01 ip

8004110119 Forwards IF Info Notice 80-13, "OE Type BBM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN,R H Region 5, San Francisco, Office of the Director, 80/04/02 1p

8004220052 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees" No action required ENGELKEN,R H Region S. San Francisco, Office of the Director 80/04/02 ip

B004:B0137 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director B0/04/03 ip

8004230370 Forwards IE Bulletin 79-03A, "Longitudinal Held Defects in ABME SA-312.Type 304 Stainless Steel Pipe" Action required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80/04/04 ip

- 8004220201 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/04/07 1p
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSE.D F Division of Project Management
- 8004010340 Forwards mod to NPDES Permit WA-002496-1 Mod does not involve adverse environ impact or safety issues & does not require mod to CP RENBEROER.D L. Washington Public Power Supply System 80/03/21
- --B004010345 Mod to NPDES Permit WA-002476-1, issued to WA Public Power Supply Bys LEMIS:N D Environmental Protection Agency 76/10/27 11pp
- 8004280619 Advises that 791220 request for approval of alternative test method to verify max moisture in low hydrogen electrode coating is accepted Requests that notarized version of request be sent in addition to specific sites for use RUBENSTEIN.L B Light Water Reactors Branch A 80/04/04 5pp
- 8004160285 Advises of fundamental misstatement in 800402 minutes of 800104 menting w/util re GA program unionization Requests correction to reflect that util had no influence on Local 598 election REYNOLDS N 8 Debevoise & Liberman 80/04/10 ip
- BOD4150443 Requests concurrence in use of ASME. Bection III. Code Case N=242 re matis certification, to resolve apparent conflicts in ASME interpretations of certification of code matis RENBEROER, D.L. Washington Public Power Supply System 80/04/11 to.
- 8004210285 Responds to 800221 itr re-schedule for completing review of qualification of safety-related electrical equipment Schedule for completion of review will be provided after final issuance of NUREO-0588 RENBEROER.D.L. Washington Public Power Supply System 80/04/11
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, raquested by NRC 791226 ltr.has been postponed pending GAD clearance under Faderal Repts Act GRIMES, BK Emergency Preparedness Task Force 80/03/11 4pp.
- O Inspection reports. IE Bulletins & correspondence
- 8004150220 Forwards IE Info Notice 80-12, "Instrument Feilure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/31 ip
- 8004100109 Forwards IE Circular BO-05, "Emergency Diesel Generator Lubricating Gii Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 ip
- 8004110119 Forwards JE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN.R.H. Region 5, San Francisco, Office of the Director 80/04/02 ib
- 8004220052 forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/02 ip
- B004180139 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Sys " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/03 1p

- BOO4220201 Forwards IE Bulletin 80~08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN,R H Region 5. San Francisco, Office of the Director BD/04/07 ip
- 600.4230370 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/04/04 ip
- DOCKET 50-510 BLUE HILLS STATION UNIT 1
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OCSSICK, L V Office of the Executive Director for Operations 60/04/02 34pp
- DOCKET 50-511 BLUE HILLS STATION, UNIT 2
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification QCBSICK, L V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET 50-513 WPPBS NUCLEAR PROJECT, UNIT 4

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment." providing guidance re-methods for compliance ROSB:DF Division of Project Management 80/02/05 7pp
- 8004210408 Requests add1 info re changes & studies proposed in App F of 791203 reply to NRC 791025 10CFR50 54 requests concerning design adequacy of BNN N68S utilizing once-through steam generators
 PARR.O D Light Water Reactors Branch 3 80/03/25 App
- 8004280619 Advises that 791220 request for approval of alternative test method to verify max moisture in low hydrogen electrode coating is accepted Requests that notarized version of request be sent in addition to specific sites for use RUBENSTCIN.L B Light Water Reactors Branch 4 80/04/04 5pp
- B004160285 Advises of fundamental misstatement in B00402 minutes of B00104 meeting w/util ro GA program unionization Requests correction to reflect that util had no influence on Local STB election
 REYNOLDS: N S Debevoise & Liberman 80/04/10 ip
- 8004210285 Responds to 800221 ltr re-schedule for completing review of qualification of safety-related electrical equipment

- --8004250074 If in-p Rept. 50-160,60-02 % 50-513/80-02 on B00211-15 No moncompliance noted Major areas inspected safety-related components, sarety related papaing installation, welder training 'weld filler matl control DODDS R T Pegion 5 for Francisco, Reactor Construction & Engineering Support Granch Haddier W J HAIST, D P Region 5, Ban Francisco Orrice of the Director 80/03/18 8pp
- 8004150220 Forwards IC Irro Notice 80-12. 'Instrument Failure Causes Opening or PORV' Block Valve the specific action or response necessary EUGELVERIAR H. Region 5. Can Francisco. Office of the Director 80/03/31. 1p
- 8004100109 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition % Onsite Supply " No written response required ENGELERIAR H Region 5, San Francisco, Office of the Director 80/04/01 1p
- 8D04110119 Forwards IE Into Notice 80-13, 'GE Type SBM Control Switches Defective CAM Followers 'No specific action or response required EMSELMEILR H Region 5, San Francisco. Office of the Director 80/04/02 in
- 8004220052 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80704702 ip
- 8004180139 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Sys "No written response required ENGELKEN, RH Region 5. San Francisco, Office of the Director 80/04/03 1p
- 8004220201 Forwards IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Written response required ENGELKEUR H Region 5. San Francisco. Office of the Director 80/04/07 1p
- 8004230370 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Pipe " Action required ENGELKER,R H Region 5. San Francisco. Office of the Director 80/04/04 ip
- 8004230239 Ack receipt of 800318 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-460/79-13 & 50-513/79-13 & SPENCER O S Region 5, San Francisco. Reactor Construction & Engineering Support Branch 82/04/08 ip
- ~~8004230248 Responds to NRC 800228 ltr re violations nated in IE Insp. Repts 50-460/79-13 & 50-513/79-13 Corrective actions identified & described nature & extent of referenced administrative & security controls RENSFROER, D.L. Washington Public Power Supply System 80/03/18 2pp
- --8004230253 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/79-13 & 50-513/79-13 Requests info re nature & extent of referenced administrative & security controls

 SPENCER, C S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/02/28 ip
 - 'I Responds to NRC 800116 itr re violations noted in IE Insp D-460/79-13 & 50-513/79-13 Corrective actions ted accessive weld weave identified as infraction i provisions to control access to Level C storage IR.D L Washington Public Power Supply System 80/02/19
 - E Insp Repts 50-460/79-13 & 50-513/79-13 on of violation & deviation n 5. San Francisco, Fuel Facility & Materials 21/16 & Zoo
- * Region 5, San Francisco, Office of the Director 80/01/15 ip
- ---8004230287 Notice of deviation from insp on 791201-31
 * Region 5. San Francisco. Office of the Director BO/01/15 ip
- --8004230290 IE insp Repts 50-460/79-13 \$ 50-513/79-13 on 791201-31
 Noncompliance noted excessive weld weave & absence of specific access controls for Level C Items
 DUDDS.R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch TOTH.A D Region 5. San Francisco, Office of the Director 80/01/15 7pp

- DOCKET 50 514 PERBLE SPRINGS NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda MD re-evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident
 THOMAS.C C Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800319 moeting w/Near-Term CP Applicants Group in Bethesda.MD re-matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS.C O Standardization Branch 80/04/03 12pp
- 8004240557 Summary of 800402 meeting u/Neal-Term CP Applicants Group in Bethesda.MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl THOMAS.C D Light Water Reactors Branch 1 80/04/0/ 4/pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8004280112 Forwards Final Suppl 1 to FES.NUREO-75/02% & related FR notice BALLARD.R L Environmental Projects Branch 1 80/04/10 2pp
- --80042B0114 Notice of availability of final Suppl 1 to /EG, NURCY-75/025 BALLARD, R L Environmental Projects Branch 1 60/04/09 App
- --8004280118 Final Suppl i to FES

 # Office of Nuclear Reactor Regulation NUREO-/5/02% 80/04/30
 80pp Available at NTIS
- 8004270500 Informs that NRC project notice was assigned file title & number "Final Suppl to Final Pebble Springs [IS," & Number 8004 4 960 Thirty-day review began 800422 # Oregon, State of 80/04/22 lp
- F Security, medical, emergency & fire protection plans
- BOO4180359 Responds to NRC 791226 request for info to evacuation time estimates around future plants Forwards summary rept, "Evacuation Time Estimates For Oilliam & Morrow Counties, OR & Kickitat County, MA"

 LINDBALD, N J Portland General Electric Co BO/04/04 ip
- --8004180364 "Evacuation limo Estimatos for Oilliam & Morrow Counties, OR & Klickitat County,WA" * Portland General Electric Co 80/03/31 21pp
- 8004180364 "Evacuation Time Estimates for Qilliam & Morrow Counties, OR & Klickitat County,WA " s Portland General Electric Co 80/03/31 21pp
- G Adjudicatory correspondence
- 8004080439 Updates 800310 ltr submitted to AB(II Final suppl to ft0 real alternative sites will be issued 15 days after 8000331 BORDENICK, B M Hearing Branch 4 80703724 1p
- 8004250375 Forwards State of OR Energy Facility Biting Council 800014 order suspending further proceedings in site certificate application until 810701 Certificate of 8vc encl SAMDVIK, R M Justice. Dept of 80/03/26 Opp
- 8004080597 Order re util 800215 announcement that facility completion will be delayed until 1990s Grants parties 10 days, from receipt of order, to respond to NRC 800310 suggestions to proceed w/site suitability matters.

 BOWERS, E. 8 Atomic Safety and Licensing Board Panel 80/03/27
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparadness, distributed as Board notification QDSSICK,L V Office of the Executive Director for Operations BD/04/02 34pp

- 8004150072 Order to OR Energy Facility Siting Council 800314 order suspending proceeding until 810701 Directs parties to inform ASLB re effects of suspension on site suitability NGWERG.E S Atomic Bafety and Licensing Board Panel 80/04/03 ip
- 8004130243 Response to ASLB 800403 order re State of DR Energy Facility Siting Council 800314 order suspending proceeding until 810701 Council action does not affect NRC position re continuance on site suitability Certificate of Svc encl BURDENICK, D M Heating Branch 4 80/04/11 4pp
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re-methods for compliance RUSS: D.F. Division of Project Hanagement 80/02/05 7pp
- BOO4216405 Summary of BOO328 meeting w/near-torm CP applicants in Bethesda, MD to evaluation of progress made to date establishing proposed requirements stemming from TMI-2 THOMASIC O Standardization Dranch 80/04/03 ASpp
- BO04300074 Summary of 600319 meeting w/Near-Term CP Applicants Group in Betheeda, MD re matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS, C [] Standardization Branch 60/04/03 12pp
- 8004240957 Bummary of BC0402 meeting w/Near-Term CP Applicants Group in Bethesda.MD re-progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments enci THOMAS.C C Light Water Reactors Branch 1 80/04/07 47pp
- D NRC Draft/final Environmental Statements, supple & correspondence
- 9004280112 Forwards Final Suppl 1 to FEG. NUREQ-75/025 & related FR notice DALLARD.R L Environmental Projects Granch 1 00/04/10 2pp
- -- 8004280114 Notice of availability of Final Buppl 1 to FEB-NUREO-75/025 BALLARD, R.L. Environmental Projects Branch 1 80/04/09 2pp
- --8004280118 Final Suppl 1 to FFS * Office of Nuclear Reactor Regulation NURLO-75/025 B0/04/30 B0pp Available at NTIS
- BOO4270500 Informs that NRC project natice was assigned file title & number "Final Suppl to Final Pebbie Springs FIB." & Number BOO4 4 760 Thirty-day review began 800422 e Oregon, State of 80704722 ip
- f' Becurity, medical, emergency & fire protection plans
- OOGA180359 Responds to NRC 791226 request for info re evacuation time estimates around future plants forwards summary rapt.
 "Evacuation Time Estimates For Gilliam & Morrow Counties, OR & Klickitat County, MA"
 LINDBALD, W.J. Portland General Electric Co. 60/04/04 ip
- B0041B0364 "Evacuation Time Estimates for Gilliam & Horrow Counties. OR & Klickitat County, MA"
 * Portland General Flectric Co. 80/03/31 Ripp
- Adjudicatory correspondence
- 800A080A37 Updates 800310 lir submitted to ASLD Final suppl to FES re alternative sites will be issued 15 days after 800331 BORDENICK.D M Hearing Branch 4 80703724 ip
- EOO4250375 Forwards State of CR Energy Facility Siting Council 800314 order suspending further proceedings in site certificate application until 810701 Certificate of Svc encl SANDVIK.R M. Justice.Dept of 80/03/26 5pg
- BOO4080597 Order re-util 800215 announcement that facility completion will be delayed until 1990s Grants parties 10 days, from receipt of order, to respond to NRC 800310 suggestions to proceed w/site suitability matters

 BOHERS, E. 8. Atomic Sefety and Licensing Board Panel BO/03/27

- 8004030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in radiological emergency planning & proparedness, distributed as Board Hotsfication GDSSICK,L V Dffice of the Executive Director for Operations GOSSICK, L V 0: 80/04/02 44pp
- 8004150092 Order to ON Energy Facility Siting Council 800314 order suspending pioceeding until 410701 Directs parties to inform ASEB re effects of suspension on site suitability BOWERS, E 6 Atomic Safety and Liconsing Board Panol 00/04/0J ip
- 8004150243 Response to ASLR 800403 order to State of UR Energy Facility Siting Council 800314 order suspending proceeding until 810701 Council action does not arrect NRC position re continuance on site sustability Certificate of Svc encl 80RDENICK, B.M. Hearing Branch 4 80/04/11 App
- DOCKEY SIN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURLG-0998, "Interim Staff Position on Environ Qualification of Sarety Rolated Electrical Equipment," providing guidance re-methods for compliance RDSS.D.F. Olvision of Project Management 80702705 7pp
- F. Security, medical, emorgency & fire protection plans
- 9004000077 Advises that submittal date for evacuation time estimates, requested by NRC 791276 ltr.ha. Duen postponed pending GAG clearance under Feieral Repts Act
 GRIMES.B K Emergency Proparedness Task Force GO/03/11 4pp
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Daard notification GCSSICKL V Office of the Executive Director for Operations 80704702 Tapp
- 8004150312 Tenth status rept por ASLAB 270607 indefinite extension for NRC to respond to Buffolk County motion to file supplemental brief lask action plan underway No written declation on coal plant issued by NY Board on Flectric Concration Biting BORDENICK.B M Hearing Branch 4 80/04/11 ./pp
- Q Inspection reports, If Bulletins & correspondence
- 8004220036 Responds to 10 Dulletin 80 03 Charcoal adsorber cells have not been purchased PLASKON,R I tong Island Laghting Co. 80/07/19 ip
- 8004150274 Forwards IE Info Notice BO 12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIFR. B H. Region 1. Philadelphia, Office of the Director 80703731 ip
- 8004090069 Forwards 16 Circular 80-09, "Emergency Diesal Generator Lubricating Oil Addition & Onsite Bupply " No written response required
 GRICE Bit Region 1, Philadelphia, Office of the Director
 80/04/01 1p
- 8004110140 Forwards II Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers" No written response required ORIER, B H Region L. Philadelphia, Office of the Director 80/04/02 ip
- 8004240313 Forwards IF Info Natice 80-14, "Safety Buggestians From Employees" No action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 8004180179 Forwards IE Circular 80-07, 'Problems W/MPCI Turbine Dil GRIER.D 11 Region 1. Philadelphia, Office of the Director 80/04/03 1p

- 8004230491 Forwards IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe " Action required GRIER, B.H. Region 1. Philadelphia. Office of the Director 80704701 Ip
- 2004180161 Forwards IF Rulletin 80-08. 'Eram of Containment Liner Penetration Welds " Written response required GRIER.B H Region 1. Fhiladelphia. Office of the Director BO/04/07 1p
- T. Hearing transcripts on non-antitrust matters
- 8004100450 Testimony before NY State Board on Electric Generation Siting & Environ re-proposed Jamesport facilities KLEIN, J V Suffolk County, NY 79/07/10 8pp
- --8004100460 Yestimony before HY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities Prof qualifications encl GEISELMAN, J N Suffolk County, NY 79/06/29 6pp
- --- G004100472 Testimony before NY State Board on Electric Generation Siting b Environ re proposed Jamesport facilities Related diagrams.ref & prof qualifications encl GIARDINA.P A Suffolk County, NY 79/06/29 25pp
- DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 9
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREQ-058B, "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment," providing guidence re-methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- BOO4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act
 GRIMES.B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK, U Office of the Executive Director for Operations
- 8004190312 Tenth status rept per AELAB 790607 indefinite extension for NRC to respond to Suffolk County motion to file supplemental brief Task action plan underway No written decision on coal plant issued by NY Board on Electric Generation Siting BORDENICK.8 M Hearing Branch 4 80/04/11 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004220036 Responds to IF Sulletin 80-03 Charcoal adsorber cells have not been purchased PLASKON R E Long Island Lighting Co 80/03/19 ip
- 8004150274 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/31 1p
- 8004090063 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply " No written response required

 GRIER, B H Region i, Philadelphia, Office of the Director

 80/04/01 lp
- 8004110140 Forwards IE Info Notice 80-13, "GE Type 8BM Control Switches Defective CAM Followers" No written response required GRISER'S H Region 1. Philadelphia, Office of the Director B0/04/02 [p
- 8004240313 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required GRIER, B H Region 1, Philadelphia, Office of the Director 80/04/02 1p

- 8004180179 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Gil Sys "No written response required GRIER.B H Region I, Philadelphia, Office of the Director BO/04/03 Ip
- 8004230471 Forwards 1E Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required CRIER, B H. Region 1, Philadelphia, Office of the Director 80/04/04 ip
- 8004180161 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required GRIER.B H Region I. Philadelphia. Office of the Director 80/04/07 ip
- T Hearing transcripts on non-antitrust matters
- 9004100450 Testimony before NY State Board on Electric Generation Siting & Environ re-proposed Jamesport facilities KLEIN, J V Suffelk County, NY 79/07/10 Bpp
- --8004100460 Testimony before NY State Board on Electric Generation Siting : Environ re proposed Jamesport facilities Prof qualifications encl GEISELMAN.J N Suffolk County, NY 77/05/29 App Suffolk County, NY 79/06/29 App
- --8004100472 Testimony before NY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities Related diagrams.ref & prof qualifications enci GIARDINA.P A Suffall County, NY 79/06/29 25pp
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0598, "Interim Staff Position on Environ Swallfication of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS.D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed punding QAU clearance under Federal Repts Act
 GRIMES B K Emergency Preparedness Task Force 80/03/11 4nn Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & FEMA re primprovement in radiological emergency planning & preparedness, distributed as Board notification GOBBICK, V Office of the Executive Director for Operations 80/04/02 34pp
- Q Inspection reports, IE Bulletine & correspondence
- 8004070352 Forwards IF Bulletin 80-03, "Loss of Charcoal from 8td Type II. Two-Inch. Tray Adsorber Celis " Action required D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/02/06
- 8004090384 Forwards IE Insp Repts 50-518/80-03,50-519/80-03, 50-820/80-03 % 50-521/80-03 on 800103-18 % 25 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/02/20
- --8004090400 IE Insp Repts 50-518/80 03, 50-519/80-03, 50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No noncompliance noted Major areas inspected 8A program review structural concrete & licenses const organization changes BMAN.W B Region 2, Atlanta, Office of the Director CANTRELL, C S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/17 Spp
- 800A090025 Confirms 8003l0 telcon arranging 8003R0 meeting between NRC & util in Atlanta. OA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by QA program O'REILLY, J.P. Region R, Atlanta. Office of the Director 00/03/12

- 8004210178 Forwards response to IE Builetin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS,L.M. Termossoe Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Hodel EA180 limit switches At facilities where applicable limit switches are identified, replacement gastets have been ordered MILLS, L. M. Tennessee Valley Authority 80/03/28 2pp
- 1004190927 Forwards IE Info Notice 80-12, "Instrument Failure Gauses Opening of PORV & Block Valve " No specific action or response necessary UREILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31
- 1004080634 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Unsite Supply " No whitten response required O'RELLY, J.P. Region 2, Atlanta, Office of the Director 80/04.
- Region 2. Atlanta, Office of the Director 80/04/01
- 3004150077 Forwards IE Info Notice 80-13, "OE Type 88M Control Switches Befective CAM Followers" No specific action or response
- O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/02
- 1004240274 Forwards IE Info Notice 80-14, "Bafety Suggestions From Employees," No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 1004180275 Forwards IE Circular BO 0/, "Problems W/HPCI Turbine 0il Bys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/03 Bys " No write O'REILLY, J P
- 004110017 Forwards IC Bulletin 80-07. 'DWR Jet Pump Assembly Failure " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 004230142 Forwards II. Bulletin 79-03A "Langitudinal Weld Defects in ABMC BA-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 004180440 Forwards IE Bulletin 80-00, "fixam of Containment Liner Penetration Wolds" Written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vascals Lapeditious approval is necessary for use of code cases in forthcoming preservice HILLS, L. M. Tennessee Valley Authority 80/04/23 3pp
- Reportable occurrences, LFRs & related correspondence
- 304160216 Forwards revised corrective actions to 800215 final deficiency rept
 MILLO,L M Tennessee Valley Authority 80/03/31 ip
- -8004160218 Revised corrective actions to 800213 final deficiency rept Buttured edges on reactor pressure vessel pedestal examined & repaired Vendor film quality sufficient to produce repair overlays * Tennessee Valley Authority 80/03/31 ip
- PO4150414 Forwards suppl to final deficiency rept re unacceptable QA documentation for Olaser steel mall MILLE, L M Tennessee Valley Authority 80/04/03 ip
- 8004130417 Suppl to final deficiency rept re unacceptable QA documentation for Qlaier steel matt All questionable matt has been tested Slightly excessive suifur content is caused by chemical differences & not QA sys defects & Tennessee Valley Authority 80/04/03 ip Tennessee Valley Authority
- 04290066 Part 21 rept to insp of generator control panels for smergency dissel generators Results determined defects could degrade emergency dissel unit to unsafe performance Corrective action includes in-depth insps & training FALTER.H. H PHR Bystem Div PA/PI 80/04/07 4pp

- 8004220724 Forwards interim deficiency rept re incorrect root face on skewed cadweld sleeves
 MILLS,L M Tennessee Valley Authority 80/04/14
- --8004230764 Interim deficiency topt re incorrect root face on skewed cadweld sleeves Root faco on skowed cadweld sleeve IB varies from 3732 to 1/2 unch Design based on assumed 1/16-inch upot face Sleeves will undergo destructive pull tests * Tennessoe Valley Authority 83/04/14 2pp
- 8004280503 forwards first interim deficiency rept re cracks in reactor prossure vessel shield wall MILLS,C M Tennessee Valley Authority 80/04/14 1p
- --8004280505 First interim deficiency rept re cracks in reactor prossure vessel shield wall Three base metal cracks were found in shield wall inner shell plates Cause to be determined pending results of Singloton analysis MILLS:L M Tennessee Valley Authority 80/04/14 ip
- BOO4300390 Forwards first interim rept of deficiency re-wiring in HPCS metal clad switchgear MILLG.L M Tennessee Valley Authority 80/04/24 1p
- --8004300397 First interim deficiency rept re wiring in HPCS metal clad switchgear QE has been notified of wiring diagram & labeling discrepancies, missing wires & billing problems Phipps Bend mgt investigating discrepancies

 * Tennessee Valley Authority 80/04/24 Ip
- DUCKET STN-50-919 HARTSVILLE NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURLO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance remethods for compliance ROS9.() F Division of Project Management 80/02/05 7pp
- f Security, modical, emergency & fire protection plans
- 00040800/7 Advises that submittel date for evacuation time estimates, requested by NRC /71226 ltr.has been postponed pending QAO clearance under Federal Repts Act QRIMIG. B.K. Umergency Proparedness Task Force BO/03/11 4pp
- Q Inspection reports, If Bulletins & carrespondence
- 8004090752 Forwards It Bulletin 80-07 "Loss of Charcoal from 8td Type II. Two-Inch. Tray Adsorber Cells " Action required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/06
- 8004070384 Forwards IE Insp Repts 90 518/80 03,50-519/80-03, 50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No ONTENDIANCE NOTED

 ORYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering

 Bupport Branch 80/02/20 2pp
- ---H004070400 (E Insp Repts 50-518/80-03,50-519/80-03,50-520/80-03 & 50-521/80-03 and B0010J 18 & 25 No nancompliance noted Major areas inspected QA program review, structural concrete & licensee const organization changes GHANA W B Region 2. Atlanta. Office of the Director CANTRELL/ G Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/17 Spp
- BOO4090025 Confirms BOO310 teleon arranging 800320 meeting between NRC & util in Atlanta. GA to discuss accuracy of written repts provided to 1F NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/12
- 8004210178 Forwards response to IE Builetin 80-03, "loss of Charcual from 8td Type II.Two-Inch.Tray Adsorber Cells " Enct lists results of inspa at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS:L M Tennessee Valley Authority 80/03/21 4pp
- 8004i80i06 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EAIBO limit suitches Atfactilities where applicable limit switches are identified, replacement gaskets have been prodered MILLS, LM Tennesser Valley Authority 80/03/28 2pp

- 800415057 Forwards IE Inro Notice 80-12, "Instrument Failure Causes Opening or PORV & Block Value " No specific action or response necessary O'REILLY, J.P. Region = Atlanta, Office of the Director 80/03/31
- GOD4080636 Forwards If Circular 80-05, "Emergency Diesel Generator Lubticating Ui) Addition / Onside Supply "No unitten response required O'RECLL: J P Region P, Atlanta, Office or the Director 60/04/01
- BOO415009/ Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 Forwards 1E Info Notice 80-14, 'Safety Suggestions From Employees " No action required O'REILLI, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp
- B004180275 Forwards IE Circular 80-07, 'Problems H/HPCI Turbine 0:1 Sys "No written response required O'REILLI, J P Region P. Atlanta, Orfice of the Director 80/04/03 20n
- BD04(10017 Forwards IE Bulletin 80-07, "BUR Jet Pump Assembly Failure "
 No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards IE Rulletin 77-03A 'Longitudinal Weld Defects in ASME BA-312, Type 304 Stainless Steel Pipe " Action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04 ip
- 8004)80445 Forwards IE Bulletin 80-08, "Exam of Containment Einer Penetration Welds "Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07 300
- 8004290377 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressury vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.
 MILLS.L M. Tennesser Valley Authority 80/04/23 3pp
- S Reportable occurrences, LERs & related correspondence
- 8004150414 Forwards suppl to final deficiency rept re unacceptable OA documentation for Claier steel matl MILLS.L M. Tennessee Valley Authority 80/04/03 1p
- --8004150417 Suppl to final deficiency rept re unacceptable QA documentation for Glazer steel matl All questionable matl has been tested Slightly excessive sulfur content is caused by chemical differences % not QA sys defects * Tennessee Valley Authority 80/04/03 ip
- 8004270066 Part 21 rept re insp of generator control panels for emergency diesel generators Results determined defects could degrade emergency diesel unit to unsafe performance Corrective action includes in-depth insps & training FALTER, H N PWR System Div PA/PI 80/04/07 App
- 8004220724 Forwards interim deficiency tept re incorrect root face on skewed cadweld sleeves MILLS.L M Tennessee Vailey Authority 80/04/14 ip
- --B004220764 Interim deficiency rept re incorrect root face on skewed cadweld sleeves Root face on stewed cadweld sleeve iB varies from 3/32 to 1/2 inch Design based on assumed i/ió-inch root face Sleeves will undergo destructive pull tests a Tennessee Valley Authority 80/04/14 2pp
- 8004300390 Farwards first interim rept of deficiency re wiring in HPCS metal clad switchgear MILLS.L M Tennessee Valley Authority 80/04/24 (p
- --8004300397 First interim deficiency rept re wiring in HPCS metal clad switchgear GE has been notified of wiring diagram & labeling discrepancies, missing wires & billing problems Phipps Bend mgt investigating discrepancies * Tennessee Valley Authority 80/04/24 1p

- DOCKET STN-50-520 MARTEVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Sarety-Related Electrical Equipment." providing guidance te methods for compliance ROSS, D.F. Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- BOD4080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K Energency Prepaiedness Task Force BO/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GDSSICK.L V Office of the Executive Director for Operations 80/04/02 34pp
- q Inspection reports, IE Bulletins & correspondence
- 8004070352 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06 200
- 8004090384 Forwards IE Insp Repts 50-518/80-03, 50-519/80-03, 50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No noncompliance noted RRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/20 3pp
- ---8004090400 IF insp Repts 50-518/80-03,50-519/80-03,50-520/80-03 & 50-521/80-03 on 800103-18 & 25 No noncompliance noted Major areas inspected GA program reviews structural concrete & licensee const organization changes 8MAN. & 1 Region 2. Atlanta. Office of the Director CANTECLL,FS Region 2. Atlanta, Reactor Censtruction & Engineering Support Branch 80/02/19 5pp
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC to this in Atlanta, GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/12
- 8004210178 Forwards response to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II. Two-Inch. Tray Adsorber Cells " Encl lists results of Insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLG.L M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model FA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS, L
- 8004150527 Forwards IF Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve" No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31, 2pp
- 8004080636 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Bupply " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80-13, "GE Type SUM Control Switches Defective CAM Followers " No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 Forwards 1E Info Notice 80-14, "Bafety Buggestions From Employees" No action required d'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp

- 8004180279 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Bys " No written response required O'REILLY.J P Region 2, Atlanta. Office of the Director 80/04/03
- 8004110017 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " No written response required O'REILLY, J. P. Region 2. Atlanta, Offsce of the Director 80/04/04
- 8004230142 Forwards IC Bulletin 79-03A "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe " Action required C'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08, "Exam of Containment Lines Penetration Welds " Written response required D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/07 38e
- 8004270377 Requests approval of ASMC Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.

 MILLE, L.M. Tennessee Valley Authority 80/04/23 3pp
- 8 Reportable occurrences. LERs & related correspondence
- B004150414 Forwards suppl to final deficiency rept re unacceptable QA documentation for Qiazer steel mati MILLS.L II Tennessee Valley Authority B0/04/03 ip
- --8004150417 Suppl to final deficiency mept me unacceptable GA documentation for Glarer steel matt All questionable matt has been tested Slightly excessive sulfur content is caused by chemical differences & not OA sys defects a Tennessee Valley Authority 80704703 ip
- 8004270066 Part 21 rept re insp of generator control panels for emergency diesel generators Results determined defects could degrade emergency diesel unit to unsafe performance Corrective action includes in-depth insps & training FALTER: H W PUR System Div PA/PI 80/04/07 4pp
- 8004220724 Forwards interim deficiency rept to incorrect root face on skewed cadweld sleeves MILLS.L M Tennessee Valley Authority 80/04/14 ip
- --8004220/64 Interim deficiency rept re incorrect root face on skewed cadweld sleeves Root face on skewed cadweld sleeves 10 varies from 3/32 to 1/2 inch, Design based on assumed 1/16-inch root face Gloeves will undergo destructive pull tests * Tennesses Valley Authority 60/04/14 2ρρ
- 8004300390 Forwards first interim rept of deficiency re wiring in HPCB metal clad switchgoar MILLS-L M Tennessee Valley Authority, 80/04/24 ip
- --8004300397 First interim deficiency rept re wiring in HPCB metal clad switchgear GE has been notified of wiring diagram & labeling discrepancies.missing wives & billing problems Phipps Bend mgt investigating discrepancies * Tennessae Valley Authority 80/04/24 ip
- DOCKET BTN-90-821 HARTSVILLE NUCLEAR PLANT, UNIT 4

 A Application/construction stage documents & correspondence
- 800404D031 Advises of issuance of NUREO-0588, "Interim Btaff Position on Environ Qualification of Bafety-Related Electrical Equipment," providing guidance re-methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791826 ltr.has been postponed pending OAO clearance under Federal Repts Act GRIMEG.B.K Emergency Preparedness Task Force 80/03/i1 App
- O Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board natification ODSBICK.L V. Office of the Executive Director for Operations 80/04/02. 34pp

- Q Inspection reports: IF Bulletins & correspondence
- 8004090384 Forwards If Insp Repts 50-518/80-03,50-519/80-03, 50-520/80-03 % 50-521/80-03 on 800103 18 % 25 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Draich 80/02/20 dpp
- --8004070400 IE losp Repts 90-518/80-03.50 519/80-03.50-520/80-03 & 50-521/80-03 on 800103-18 t 25 No noncompliance noted Major areas inspected & program review, structural concrete & licensees const organization changes BHAN, U B Region 2. Atlanta. Office of the Director 80/02/19
- 8004090025 Confirms 800310 teleon arranging 800320 meeting between NRC 5 util in Atlanta, OA to discuss accuracy of written repts provided to IE NRC will provide eventall evaluation of util handling of deficiences identified by GA program G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80703/12 200
- 8006210178 Forwards response to 1F Bulletin 80-03. "toss of Charcoal from Std Type 11.Two-inch.Tray Advantor Cells." Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS,I M. Tennessee Valley Authority 80/03/21. App
- 8004)80106 Forwards response to IC Bulletin 79 28 re possible malfunction of NAMCO Mudel EA180 limit switches At Facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLG.L (1
- 800418052/ Forwards It Info Notice 80-12, 'Instrument Failure Causes Opening of PORY & Block Valve "No specific action or response notessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/31
- 0004080636 Forwards It Circulai 60-05, "Emergency Diesel Generates Lubricating Oil Addition & Onsite Supply " No writtes response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004130097 Forwards IT Info Notice 80-13, "GC Type SIM Control Gwitches Defective CAM Followers " No specific artion or response required O'ALDITY, J.P. Region P. Atlanta. Office of the Director 80/04/02 2pp
- H00424402/4 forwards IF Info Notice H0+t4. "Safety Buggestions from Employees" No action required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/04/02
- 8004180279 Forwards IL Circulai 80-07, "Problems W/MPCI Turbine Dil Sys " No written response required D'REILLY, J.P. Region J. Atlanta, Office of the Director 80/04/03 200
- BOOA1(10017 Forwards If Bulletin 80-07, "RWR Jet Pump Assembly Failure " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04 202
- 6004230142 Forwards If Builetin /9-03A 'Longitudinal Weld Defects in ASME 9A 312. Type 304 Stainless Steel Pipe " Action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director R0/04/04 ip
- 8004180445 forwards IE Bulletin BO-OG, "Exam of Containment Liner Penetration Welds " Writton response required O'REJLLY, J.P. Region 2. Atlanta, Office of the Director B0/04/07
- 8004270779 Requests approval of ASME Code Cases N-294 & N-235 for use on reactor pressure vessels Espeditious approval is necessary for use of code cases in forthcoming preservice insp. MILLS.L M. Tennessee Valley Authority 80/04/23 3pp.
- S Reportable occurrences, LFRs & related correspondence
- 80041504i4 Forwards suppl to final deficiency rept re unacceptable QA documentation for Glorer steel mat!
 MILLS-I M Tennessee Vailey Authority 80/04/03 ip

- --8004150417 Suppl to rins) deficiency tept re unacceptable QA documentation for Glajer steel nafl All questionable mati has been tested Slightly encessive sulfur content is caused by chemical differences; not QA sys defects * Tennessee Valley Authority 80/04/03 ip
- 8004290066 Part 21 teptile insplof generator control panels for emergency diesel generators Results defermined defects could degrade emergency diesel unit to unsare performance Corrective action includes indepth insps & training program FALTER, H H PUR System Div PA/PI 80/04/07 4pp
- 8004220724 Forwards interim deficiency rept re incorrect root face on steward cadweld sleeves MILLS.L M Tennessee Valley Authority 80/04/14 tp
- --8004220764 Interim deficiency lept re incorrect root face on skewed cadweld sleeve Root face on stewed cadweld sleeve IB varies from 3/32 to 1/2 inch Design based on assumed 1/16-inch root face Sleeves will undergo destructive pull tests * Tennessee Valley Authority 83/04/14 2pp
- 8004300390 Forwards first interim rept of deficiency re-wiring in HPC8 metal clad switchgean MILLG.L H Tennessee Vailey Authority 80/04/24 lp
- --8004300397 First interim deficiency rept re wiring in HPCS metal clad switchgear QE has been notified of wiring diagram & labeling discrepancies missing wires 5 billing problems Phipps Bendingt investigating discrepancies
 * Tennessee Valley Authority 80/04/24 ip
- DOCKET STN-50-522 SAAGIT NUCLEAR POWER PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of Issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Sarety-Rolated Electrical Equipment." providing guidence re methods for compliance ROSS, D F Division of Project Management 80/02/05 7pp
- 8004070237 Discusses status of Geosciences Branch review effort Concurs in Tecommendation to withhold application until applicant performs extensive studies Branch should be informed of util meeting re-proposed site relocation STGLZ.JF Light Water Reactors Branch 1 80/03/20 1p
- 8004100:187 Responds to 800129 request for info re composition of piping in cooling sys & data concerning chemical loadings in sys Stainless steel will be used for condensor tubes in place of Admiralty metal originally specified BLACK.R L. Hearing Branch 1 80/03/31 2pp
- 9004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda, MD relevaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident
 THOMAS.C O Standardization Branch 80/04/03 63pp
- BO04300074 Summary of 800319 meeting w/Near-Term CP Applicants Group in Bethesda, MD re matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS, C D Standardilation Branch B0/04/03 12pp
- 3004240557 Summary of 800402 meetring w/Near-Term CP Applicants Group in Bethesda. MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl
 THOMAS.C O Light Water Reactors Branch 1 80/04/07 47pp
- Adjudicatory correspondence
- 3004020468 Responds to 800219 itr requesting reanalysis of A-6 aircraft accident rate in light of recent developments Potential hatara needs not be reanalyzed at present, but info is being monitored for future possibility BLACK, R. L. Hearing Branch 1 80/03/20 ip
- -8004020474 Comments recent A6 accident published in 800212 Seattle Times Accident does not (ncrease risk of crash at facility site due to military nature of Accident Analysis Branch 80/03/18 ip
- OOA080017 Order denying Stagitonians Concerned About Nuclear Power motion to compel applicants' answers to interrogatories re San Juan 1slands seismic profiles Issue does not relate to matters in controversy identified by Commission or ASLB DEALE, V B Atomic Safety and Licensing Board Panel BO/03/21 3pp

- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations 80/04/02 34m
- 8004170245 Submits progress rept in response to ASLB 800304, "Conference of 800122 Background, Purpose & Results," re resolution of US05/NRC requests for add1 info Hearing dates on geology & seismology not yet known Will submit status by 800590 SHANSON, D T Hearing Branch 1 80/04/15 2pp
- U Congressional/Executive Correspondence
- 8004140286 Responds to 791011 ltr re seismalagical review of proposed facility USGS tother experts contracted to review site Conservative assumptions are incorporated into structural & sys designs to compensate for seismalagical uncertainties DIRCKS.W.J. Orfice of the Frecutive Director for Operations 80/03/18 2pp
- DOCKET STN-50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

 A Application/constitution stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for complianco RDSS, D F Division of Project Management 80/02/09 7pp
- B004070237 Discusses status of Geosciences Branch review effort Concurs in recommendation to withhold application until applicant performs extensive studies Branch should be informed of util meeting reproposed site relocation STOLZ, J.F. Light Water Reactors Branch (80/03/20 ip
- 8004100489 Responds to 800129 request for info re composition of piping in cooling sys & data concerning chemical loadings in sys Stainless steel will be used for condensor tubes in place of Admiralty motal originally specified BLACK/R L. Hearing Branch i 60/03/31 2pp
- B004210405 Summary of B00328 meeting w/near-term CP applicants in Bathesda.MB re evaluation of progress made to date establishing proposed requirements stemming from TMI~2 accident
 THOMAS.C O Standardization Branch 80/04/03 63pp
- 8004300074 Summary of 800319 meeting w/Near-Term CP Applicants Group in Bethesda: MD re matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS, CO Standardization Branch 80/04/03 12pp
- BO04240557 Summary of B00402 meeting w/Near-Term CP Applicants Group in Bathesda.MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl
 THOMAS.C O Light Water Reactors Branch 1 B0/04/07 47pp
- O Adjudicatory correspondence
- B00402046B Responds to B00215 itr requesting reanalysis of A-6 aircraft accident rate in light of recent developments Potential hazard needs not be reanalyzed at present but info is being monitored for buture possibility
 BLACK.R L Hearing Branch t S0/03/20 ip
- ~~B004020474 Comments recent A6 accident published in B00212 Seattle Times Accident does not increase risk of crash at facility site due to military nature of A6 READ.J Accident Analysis Branch 80/03/18 Ip
- 8004080017 Order denying Skagitonians Concerned About Nuclear Power motion to compel applicants' enswers to interragatories re San Juan Islands seismic profiles Issue does not relate to matters in controversy identified by Commission or ASLB DEALE.V B Atomic Safety and Licensing Board Panel. 80/03/21 3pp.
- 8004030026 Memorandum of Understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification OCSSICK. V Office of the Executive Director for Operations
- 8004170245 Submits progress rept in response to ASLB 800306, "Conference of 800122 Background. Purpose & Results." re resolution of US95/NRC requests for addl info Hearing dates on geology & seismology not yet known Will submit status by 800536 SNANSON, D T Hearing Branch I 80/04/15 2pp

U Congressional/Executive Correspondence

8004140286 Responds to 791011 itr re seismological review of proposed facility USGS & other experts contracted to review site Conservative assumptions are incorponated into structural & sys designs to compensate for seismological uncertainties DIRCKS.N J Office of the Executive Director for Operations 80/03/18 2pp

DOCKET 50-524 BARTON, UNIT 1

@ Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OOSSICK, L V Office of the Executive Director for Operations 80/04/02 34pp

DOCKET 50-525 BARTON, UNIT 2

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification ODSSICK,L V Office of the Executive Director for Operations 80/04/02 34pp

DOCKET 50-526 BARTON, UNIT 3

Q Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification OBSICKL V Office of the Executive Director for Operations

DOCKET 50-527 BARTON, UNIT 4

Q Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSBICKL V Office of the Executive Director for Operations 80/04/02 34pp

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8004040031 Advises of issuance of NUREO-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidence re methods for compliance ROSS.D F. Division of Project Management

F Security, medical, emergency & fire protection plans

8004080077 Advises that submittal data for avacuation time estimates, raquested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES.B K. Emergency Preparedness Task Force 80/03/11 App

8004180566 Responds to NRC 771121 & 1226 requests for evacuation time estimates & revised emergency plan, respectively Delay will render AZ state plan incomplate Info will be provided in Dec 1780.

VAN BRUNT, E E Arizona Public Service Co 80/04/01 4pp

K Utility Final Safety Analysis Report (FSAR) & amends

8004010244 Forwards Amend 1 to FSAR
VAN BRUNT,E E Arisona Public Service Co 80/03/31, ip

--8004010247 Amend 1 to FSAR * Arizona Public Service Co 80/03/31 155pp

Q Inspection reports: IF Bulletins & correspondence

- 8004300117 Forwards IE Insp Repts 50-528/77-10,50-529/77-10 & 90-530/79-06 on 791101-30 No noncompliance noted SPENCER,C S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 60/01/31 2pp
- --8004300121 [E Insp Repts 50-528/79-10.50-529/79-10 & 50-530/79-06 on 791101-30 No noncompliance noted Major areas inspected const activities, including pipe hanger welds, reactor cooling postwold heat treatment & spray pond pump steel DODDS,R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch VORDERDRUEGGEN Region 5, San Francisco, Office of the Director 80/01/30 6pp
- 8004020152 Ack receipt of 800228 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-528/79-09, 50-529/79-09 & 50-530/79-05 SPENCER9-09 & 50-530/79-05 SPENCER9-0 & Region 5, San Francisco. Reactor Construction & Engineering Support Branch B0/03/17 Ip
- --8004020162 Responds to NRC 800129 ltr re violation noted in IE Insp Repts 50-528/79-09,50-529/79-09 & 50-530/79-09 Corrective actions inspected piping for cleanliness & instituted formal training for employees VAN BRUNT, E E Arizona Public Service Co 80/02/28 3pp
- --8004020168 Forwards IE insp Repts 50-528/79-09.50-527/79-09 & 50-530/79-05 on 791129-30 & notice of violation SPENCER, G S Region 5, San Francisco, Office of the Director 80/01/29 2pp
- --8004020171 Natice of violation from insp on 791129-30 * Region 5, San Francisco, Office of the Director 80/01/28 is
- --8004020180 IE Insp Repts 50-528/79-09.50-529/79-09 & 50-530/79-05 on 791129-30 Noncompliance noted failure to use temporary cleanliness pipe caps on safety-related piping DDDDS:R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch NARBUT.P P. ECKHARDT, J H Region 5. San Francisco. Office of the Director 80/01/28 7pp
- 8004150203 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELKEN,R H Region 5, Ban Francisco, Office of the Director BO/03/31 ip
- 8004100097 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/01 is
- 8004110107 Forwards IE info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers" No specific action or response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/04/02 ip
- 8004220031 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees " No action required ENGELKEN.R H Region S, San Francisco, Office of the Director 80/04/02 1p
- 8004180146 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil Øys " No written response required ENGELKEN.R H Region 3, San Francisco, Office of the Director 80/04/03 ip
- 8004230373 Forwards IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe " Action required ENGELKEN.R H Region 3, San Francisco, Office of the Director 80/04/04 ip
- 8004220170 Forwards IE Bulletin 80-0B, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN.R H Region S. San Francisco, Office of the Director 80/04/07 ip
- 8004240493 Ack receipt of 800326 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/80-01; 50-530/80-01 850-530/80-01 87ENGER,0 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/04/08 ip

- --8004240501 Responds to NRC 800227 ltm re violations noted in IE Insp. Repts 50-528/80-01.50-529/80-01 % 50-530/80-01 Corrective actions Bechtel field ronst manager issued 800201 memo enphasizing Compliance w/drawing confrol sys. VAN BRUNITE E. Arizona Public Service Co. 80/03/26 Spp.
- -8004240508 Forwards IE Insp Repts 50-528/80-01,50-529/80-01 & 50-530/80-01 on 800121-25 & notice of violation SPENCER,G S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8004240516 Notice of violation from inspion 800121-25 * Region 5. San Francisco. Office of the Director 80/02/26 20n
- --8004240522 IF Insp Repts 50-528/80-01.50-529/80-01 & 50-530/80-01 on 800121-25 Noncompliance noted failure to stamp drawings for proper identification ECKHARD, T , KIRSCH, D F Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, San Francisco, Reactor Constiuction & Engineering Support Branch 80/02/26 11pp
- S Reportable occurrences, LERs & related correspondence
- 8004070251 Ack receipt of 800305 final rept re deficient welds on safety-related pipe hanger assemblies Util rept will be reviewed & evaluated by NRC ENGELKEN.R H Region 5. San Francisco, Orfice of the Director 80/03/12 lp
- --8004070255 Forwards final rept re deficient welds on safety-related pape hanger assemblies

 VAM BRUNTLE E Arizona Public Service Co 80/03/06 ip
- ---8004070258 Final rept re deficient welds on safety-related (Quality Class Q) pipe hanger assemblies Of 47 pipe hangers installed & inspected, 17 had fillet welds that were too small Helds are being repaired per design criteria # Arizona Public Service Co 80/03/05 3pp
- BOO4010350 Forwards interim deficiency rept re Rockbestos Co 600 volt copper power cable delivered & partially installed at facility Results of qualification testing are required before final corrective action can be taken VAN BRUNT, E.E. Arizona Public Service Co. 80/03/24 2pp
- --8004010358 Interim deficiency rept re partially installed Rockbestos
 Co 600 volt copper power cables having nonsequential footage
 markings Investigation revealed factory repair of conductor,
 insulation 5 jacket unacceptable Stop work order issued
 4 Arizona Public Service Co 80/03/18 Spp
- 8004170045 Forwards interim deficiency rept re visual insp of circumfetential weld joints on ASME Section III, Class 3 piping sys between 2-4 inches in diameter VAN BRUNT,E E Arizona Public Service Go B0/04/10 pp
- --B004170051 Interim deficiency mept re visual insp of circumferential weld joints on ASME Section III.Class 3 piping sys between 2-4 inches in diameter Caused by incorrect info on Drawing 13-P225-011 Welds will be re-inspected

 ★ Arizona Public Service Co 80/04/09 2pp
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSS,D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act
 GRIMES.8 K Emergency Preparedness Task Force 80/03/11 4pp.
- 8004150546 Responds to NRC 791121 & 1226 requests for evacuation time estimates & revised emergency plan, respectively Delay will render AZ state plan incomplete Info will be provided in Dec 1980

 VAN SRUNT. E E Arizona Public Service Co 80/04/01 4pg

- V Utility Final Safety Analysis Report (FSAR) & amends
- 8004010244 Forwards Amend I to FBAR VAN BRUNT, E E Arizona Public Service Co 80/03/31 1p
- --8004010247 Amend 1 to FSAR * Arizona Public Service Co 80/03/31 155pp
- G Inspection reports, IE Bulletins / correspondence
- 8004300117 Forwards IE Insp Repts 50-528/79-10:50-529/79-10 & 50-530/79-06 on 791101-30 No noncompliance noted SPENCER.G S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/01/31 2pp
- --B004300121 IE Insp Repts 50-528/79-10.50-529/79-10 & 50-530/79-04 on 791101-30 No noncompliance noted Major areas inspected const activities including pipe hanger welds reactor cooling postweld heat treatment & spray pond pump stee) DDDDS.R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch VURDERBRUEGGEN Region 5. San Francisco. Office of the Director GO/01/30 App
- 8004020152 Ack receipt of 800228 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-528/79-09. 50-529/79-09 & 50-530/79-05 SPENCER,0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/03/17 lp
- --8004020162 Responds to NRC 800129 ltr re violation noted in IE Insp Repts 50-528/79-09, 50-529/79-09 & 50-530/79-09 Corrective actions inspected piping for clearliness & instituted formal training for employees VAN BRUNT.E E Arisona Public Service Co 80/02/20 3pp
- --800402016B Forwards IE Insp Repts 50-528/79-09,50-529/79-09 & 50-530/79-08 on 791129-30 & notice of violation SPENCER,G S Region 5, San Francisco, Office of the Director 60/01/29 2pp
- --8064020180 IE Insp Repts 50-528//9-09.50-529/79-09 & 50-530/79-08 on 791127-30 Noncompliance noted failure to use temporary cleanliness pips caps on safety-related piping DODDS,R T Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch NARBUT,P P. ECKHARDT,J H Region 5, San Francisco, Office of the Director 80/01/28 7pp
- 8004150203 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELERIA H Region B, San Francisco. Office of the Director 80/03/31 Ip
- B004100097 Forwards IE Circular B0-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required ENSELKER, R H Region 5, San Francisco, Office of the Director 80/04/01 ip
- 8004110107 Forwards IE Info Notice 80-13, "GE Type SUM Control Switches Defective CAM Followers " No specific action or response required ENOBLKEN,RH Region 5, San Francisco, Office of the Director 80/04/02 ip
- 8004220031 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/04/02 ip
- 8004180146 Forwards IE Circular 80-07, "Problems W/HPCl Turbine Oil Sys " No written response required ENGELKEN,R H. Region 5, San Francisco. Office of the Director 80/04/03 ip
- B004230373 Forwards If Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Action required. ENGELMEN, R H Region 5, San Francisco, Office of the Director 80/04/04 in
- 8004220170 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Written response required ENGELERIR H Region 5, San Francisco. Office of the Director 80/04/07 1p

- 8004240493 Ack receipt of 800326 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/80-01, 50-527/80-01 & 50-530/80-01
 8PENCER: 0 & Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/04/08 1p
- --8004240501 Responds to NRC 800227 ltr re violations noted in IE Insp Repts 50-528/80-01,50-527/80-01 & 50-530/80-01 Corrective actions Bechtel field curst manager issued 800201 memo emphasizing compliance w/drawing control sys VAN BRUNTLE E Arizona Public Service Co 80/03/26 5pp
- --B004240508 Forwards If Insp Repts 50-528/80-01.50-529/80-01 & 50-530/80-01 an 800121-25 % notice of violation SPENCER.0 8 Region %. Ban Francisco. Reactor Construction & Engineering Support Branch 80/02/2/ 2pp
- --8004240916 Notice of violation from insp on 800121-25

 * Region 5. Ban Francisco, Office of the Director 80/02/26
- 8 Reportable occurrences. LCRs & related correspondence
- 0004170045 Forwards interim deficiency rept re visual insp of circumferential weld joints on ASMC Section III.Class 3 piping sys between 2-4 inches in diameter VAN BRUNTLE C Arizona Public Service Co 80/04/10 pp
- --8004170051 Interim deficiency tept re visual insp of circumferential weld joints on ABMF Section III.Class 3 piping sys between 2-4 inches in diameter Caused by incorrect info on Drawing 13-P226-011 Welds will be re-inspected Artiona Public Service Co. 80/04/09 2pp
- DOCKET GTN-50-930 PALO VERBL NUCLEAR GTATION, UNIT 3
- 8004040031 Advises of issuance of NURFG-050B, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing puidance re methods for compliance ROSB, D.f. Division of Project Management
- F. Security, medical, emergency & fire protection plans
- BOO40BOO77 Advises that submittal date for evacuation time estimates, requested by NRC 771226 ltr. has been postponed pending GAO clearance under Federal Repts Act
 ORIMEG.B.K. Emergency Preparedness Task Force 80/09/11 App
- K Utility Final Bafaty Analysis Report (FBAR) & amends
- 8004010244 Forwards Amend 1 to FBAR VAN BRUNTIC E Aritona Public Service Co 80/03/31 ip
- Q Inspection reports, IE Bulletins & correspondence
- 8004300117 Forwards IC Insp Repts 30-520/79-10.50-529/79-10 & 50-530/79-06 on 791101-30 No noncompliance noted BPENCER.O S. Region 5. Sam Francisco. Reactor Construction & Engineering Support Branch 80/01/31 2pp
- --B004300121 IE Insp Repts 50-528/77 10:50-529/77-10 & 50-530/77-06 on 771101-30 No noncompliance noted Major areas inspected const activities, including pipe hanger welds, reactor cooling postweld heat treatment & spray pond pump steel DODDB, R T. Region 5, San Francisco, Reactor Construction & Engineering Bupport Branch VORDERBRUEGGEN Region 5, San Francisco, Office of the Director B0/01/30 App
- 8004020152 Ack receipt of 800228 itr informing NRC of steps taken to correct violation noted in IF Insp Repts 30-528/79-09, 50-529/79-09 & 50-530/79-05
 SPENCER(0 S Region 5, San Francisco, Reactor Construction & Engineering Support Drauch 60/03/17 ip

- ---8004020162 Responds to NRC 860129 Iti Te violation noted in IE Imap Repts 50-529/79 09.50 529/79-09 & 90-530/79-05 Corrective actions inspected piping for cleanliness & instituted formal training for employees VAN BRUNT.C 6 Artions Public Service Co. 80/02/28 3pp
- --8004020168 Forwards IL Insp Repts 50-578/79-09.50-529/79-09 % 50-530/79-05 on 791179 30 % notice of violation SPENCER 6 5 Region 5, ban Francisto. Office of the Director 80/01/29 200
- --8004020171 Notice of violation from insp on 791127-30 + Region 5, San Francisco. Uffice of the Director 80/01/28 10
- ---8004020180 IC Insp Repts 50-528/79-09.50-529//9-09 & 50-530/79-05 on 791129-30 Nancompliance noted failure to use temporary cleanliness pipe caps on sarety-related piping DODDS.R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch NARBUT-P P. CCKHARDT.J H Region 5. Ban Francisco. Office of the Director 80/01/28 7pp
- 8004150203 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/31 to
- E004100077 Forwards IE Circular BO-05, "Emergency Diesel Generator Lubricating Oll Addition & Onsite Supply " No written response required CNOCLKEN,R H Region 5, San Fiancisco, Office of the Director BO/04/Ol 1p
- 800411010/ Forwards IL Info Notice 80-13, "GE Type SIM Control Switches Defective CAM Followers " No specific action or response required ENGELKEN.R H Region 5, San Francisco, Office of the Director
- 8004220031 Forwards If Info Notice 80-14. "Safety Buggestions From Emplayers" No action required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/04/02 ip
- DOD4180146 Forwards IE Circular 80-0/, "Problems W/HPCI Turbine **Gil** 8ys " No written response required ENGELKEN.R H Region S. San Francisco. Office of the **Director** 80/04/03 lp
- 8004230373 Forwards IC Bulletin 77-03A, "Longitudinal Held Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" Action required ENDELKEN, R H. Region S. Ban Francisco. Office of the Director 80/04/04 in
- 8004220170 Forwards IE Builetin 80-08, "Exam of Containment Liner Penetration Welds " Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/07 ip
- BOO4240493 Ack receipt of BOO326 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/80-01. 50-529/80-01 & 50-530/80-01 BPENCER.0 9 Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch BO/04/08 1p
- --B004240501 Responds to NRC 800227 ltr re violations noted in IE Imsp Repts 50-528/80-01:50-529/80-01 & 50-530/80-01 Corrective actions Bechtel field const manager issued 800201 memo emphasting compliance w/drawing control sus VAN BRUNT.E E Arizona Public Service Co. 80/03/26 5pp
- --B004240908 Forwards IE Insp Repts 50-528/80-01:50-529/80-01 & 50-530/80-01 on 800121-25 & notice of violation SPENCER,0 B Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --80042405i6 Notice of violation from insp on 800121-25

 # Region 5. San Francisco. Office of the Director E0/02/26
- --B004240522 IE Insp Repts 50-528/80-01;50-529/80-01 & 50-530/80-01 on B00121-25 Noncompilance noted failure to stamp drawings for proper identification ECKHARD.T , KIRSCH.D F Region 3. San Francisco. Office of the Director HAYNEB.R C Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch B0/02/26 11pp

DOCKET 50-534 WOLSUNG 1

- ${\cal F}$ -Security, medical, emergency \hbar fire protection plane
- 8004150566 Responds to NRC 791121 & 1226 requests for evacuation time estimates 5 revised emergency plantrespectively Delay will render AZ state plan incomplete Info will be provided in Dec 1980 VAN SRUNTLE E Arizona Public Service Co 80/04/01 4pp
- DOCKET 50-537 CLINCH RIVER BREEDER REACTOR
- A Application/construction stage documents & correspondence
- 3004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment," providing guidance re methods for compliance RGSS.D F Division of Project Hanagement 80/02/05 7pp
- BO04290364 Forwards "Final Rept on Base Matls Tests for Cell Liner Steels " COPELAND.R L Energy, Dept of, Clinch River Breeder Reactor Plant 80/04/04 ip
- --B004290371 "Final Rept on Base Matis Tests for Cell Liner Steels "CDW01LL:M G . GDWDA.B C . THOMAS.K C Westinghouse Electric Corp WARD-D-0252 80/01/31 300pp
- 8004150473 Forwards Revision 1 to WARD-D-0218, "Structural Response of Scale Models to Simulated Hypothetical Core Disruptive Accident " COPELAND.R L Energy, Dept of, Clinch River Breeder Reactor Plant
- --8004:50480 "Structural Response of Scale Models to Simulated Hypothetical Core Disruptive Accident" Revision 1 ## Westinghouse Electric Corp | WARD-D-0218 Ri | 79/10/31 | 18pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act GRIMES B K Emergency Preparedness Task Force 80/03/11 4pp
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0598. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RQSs,D F Division of Project Management 80/02/05 7pp
- B004170193 Forwards documentation of util over capacity Current reserves are greater that 50% & predictions for 1980 show reserves of 70% No urgency to resume const HAUCK,F Affiliation Unknown 80/03/06 ip
- B004080671 Notification of B00314 meeting among Ofc of Nuclear Reactor Regulation. IE Region 3 % Ofc of IE Div of Reactor Const Inspin Bethesda. MD to discuss util submittals & answer to current order

 BHENHAMER. R F Division of Reactor Construction Inspection B0/03/07 2pp
- 8004080140 Forwards util 800305 request that NRC allow resumption of first phase of safety-related work POPE, J R Public Service Co of Indiana. Inc 80/03/11 1p
- --8004080148 Discusses NRC 790815 order confirming suspension of safety-related const at facilities Submits plan for resuming receipt lisp of safety category matls & components Requests NRC approval of resumption or safety-related activities SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/03/05 Opp
- 8004230186 Forwards request for add1 info re util QA program NRC needs info to complete review of revised QA program submitted in response to NRC 790815 order confirming suspension of const Requests consolidation of present QA program RUBENSTEIN.L.S Light Water Reactors Branch 4 B0/04/01 7pp
- 8004180370 Notification of 800411 meeting w/util in Bethesda, MD re revised QA program description WILSON J N Light Water Reactors Branch 4 80/04/02 5pp

- 8004290426 Informs of intention to use ANSI N45 2 9-1979 "Requirements for Collection. Storage % Maint of GA Records for Nuclear Power Plants" for two design parameters re wind loadings & 2-h fire rating SHIELDS.5 W Public Service Co of Indiana, Inc. 80/04/21 ip
- 8004300348 Forwards 'Consolidated Description OA Program "
 8HIELDS, S.W. Public Service Co. of Indiana, Inc. 80/04/28 1p
- --8004300350 "Consolidated Description GA Program"
 * Public Service Co. of Indiana, Inc. 80/04/28 94pp
- F. Security, medical, emergency λ tire protection plans
- BO04080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAD clearance under Federal Repts Act GRIMES; B K Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- 8004180229 Forwards util "Description of Licensee Activities Addressing Order Confirming Suspension of Const" POPE, JR Public Service Co of Indiana, Inc. 80/03/04 2pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations
- H General correspondence
- 8004020490 Awaits reply to 791210 request for hearing re-order for suspension of const-Appeal protested regulation & sys which can so easily dismiss final administrative appeal w/o reason or explanation FREY.D G Sassafras Audubon Society 80/03/02 ip
- 8004210275 Forwards except from President Carter's "Second Natl Energy Plan." transmitted to Congress on 790507, in response to ltr to DDE referred to NRC on 800122 Plan promotes expanded use of nuclear & coal power DENTON H R Defice of Nuclear Reactor Regulation 80/03/03 15pp
- --80042102BR Forwards, for NRC response, Boyles ltr urging expediting const of coal & nuclear power plants
 RATHKOPF.C L Energy, Dept of 80/01/22 3pp
- BOO4070364 Responds to 790916 request that LPDR be established in Indianapolis, IN NRC establishes LPDR in immediate vicinity of proposed & operating commercial nuclear power plants Applicable LPDR locations & hours of operation end BOUDER, J L Division of Rules and Records 80/03/13 3pp.
- --8004070373 Requests establishment of LPDR in Indianapolis, IN Believes that LPDR would be appreciated & well-used by citizens of Indianapolis BENNETT, C.L. Affiliation Unknown 79/09/16 2pp
- 9 Inspection reports. IE Bulletins & correspondence
- 8004040043 Forwards IE lnsp Repts 50-546/80-02 & 50-547/80-02 on 800117-18. No noncompliance noted FIGRELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --B004040046 IE Insp Repts S0-546/B0-02 t 50-547/B0-02 on B00117-18 No noncompliance noted Major areas inspected followps on previously identified insp findings & review of PBI rept re 790627 immediate action Itr HAYEB. D W Region 3. Chicago. Reactor Construction & Engineering Support Branch HAKKINS.F C Region 3. Chicago. Office of the Director 80/02/11 5pp
- 8004040414 Forwards IE Insp Repts 50~546/80~05 & 50~547/80~05 on B00121 No noncompliance noted KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/16
- --8004040418 IE insp Repts 50-546/80-05 & 50-547/80-05 on 800121 No noncompliance noted Major areas inspected development of licensee response to order confirming suspension of const. FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch SCHWEIBINZ, E R., MAWKINB, F C Region 3. Chicago, Office of the Director B0/02/13 2pp

- 8004100144 Forwards IE Info Notice 80-08: "States Co Bliding Link Electrical Terminal Block" No specific action or response required KEPPLER, J.G. Region 3: Chicago: Office of the Director 80/03/07
- 8004210131 Forwards util 800305 ltr to V Stello requesting that util be allowed to resume receipt insp at facility SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/03/07 ip
- B004100371 Responds to IF Builetin 80-03 Charcoal adsorber cells purchased for facility have not been delivered to site SHIELDS,5 W Public Service Co of Indiana, Inc. 30/03/17 ip
- 8004300525 Forwards 1E Insp Repts 50-546/80-03 & 50-547/80-03 en 800107-31 & natice of violation KEPPLER.J Q Region 3, Chicago, Office of the Director 80/03/21
- --8004300528 Notice of violation from insp on 800107-31 * Region 3. Chicago. Office of the Director 80/03/18 6pp
- --8004300536 IE Insp Repts 80-546/80-03 & 30-547/80-03 on 800107-31
 Noncompliance noted failure to include quality requirements in procurement documents, to prescribe quality activity in documented procedure & to implement insp program WILLIAMS, C C . HARRISON J Region 3, Chicago, Office of the Director 80/03/18 8pp
- BOG4090141 Ack receipt of BO0310 ltm informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-25 & 50-547/79-25 FIGRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch
- --8004090144 Responds to NRC 800115 ltr w/add1 info re violations noted in IE Insp Repts 80-546/79-25 & 50-547/79-25 Corrective actions custody of neutron positioning device was changed & proper purge maint was performed SHIELDB, B, W Public Sorvice Co of Indiana, Inc 80/03/10 App
- 8004110548 Ack receipt of 800306 ltr informing NRC of steps taken to correct violations noted in IC lnsp Repts 80-546/79-07 & 50-547/79-09 FIORELLI, G. Region G. Chicago, Reactor Construction & Engineering Support Branch
- --8004110856 Responds to NRC 791002 ltr re-violations noted in IE Insp. Repts 50-546/79-09 & 50-547/79-09 Corrective actions contaminant removed from reinforcing steel, joint reprepared to meet Epsec y-27022. Section 411 & featheredge aliminated SHIELDS. B W Public Service Co of Indiana. Inc. 00/03/06 10pp
- 8004100287 Ack receipt of 800306 itr informing NRC of steps taken to correct violations moted in IF Insp Repts 50-546//9-i1 & 50-547/79-i1. FIORELLI G Region 3. Chicago, Reactor Construction & Engineering Support Branch.
- --8004100291 Supplements 79:101 ltr re violations noted in IE Insp Repts 50-546/79-11 & 50-547/79-11 Corrective actions all const work stopped Util retained consultant to perform mgt analysis of site QA program revised S
- 8004150186 Forwards IF Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/31
- 8004080721 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Bupply " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/01 is
- 8004150054 Forwards IE Info Notice 80-13, "QE Type 88M Control Switches Defective CAM Followers " No specific action or response required, KEPPLER, J G. Region G. Chicago, Office of the Director 80/04/02
- 8004180059 Forwards attachments to IE Circular 80-03, "Protection From Toxic Cas Hazards," inadvertently omitted from 800306 transmittal KEPPLER, J. G. Ragion G. Chicago, Office of the Director 80/04/02 to

- 8004220150 Forwards IE Info Notice 80 14, "Safety Suggestions From Employees" No action icquired KEPPLER.J G Region 3, Chicago. Office of the Director 80/04/02 to
- 8004220398 Forwards IF Circular 80-07. "Problems W/MPCI Turbino Dil Sys " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/03
- 8004230250 Forwards IE Bulletin /9-03A. "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Action required KEPPLER, J. O. Region 3: Chicago, Ofrice of the Director 80/04/07 to
- 8004220094 Forwards IF Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Uritton response required KEPPLER, J. G. Region J. Chicago, Office of the Director 80/04/09
- S. Reportable occurrences, LERs & related correspondence
- 8004070201 Ack receipt of 800305 interim deficiency rept te noncode mat1 & certain Cotegory I components final rept will be reviewed upon receipt FIURELLIG Region 3. Chicago, Reactor Construction & Fingineering Support Branch 80703717 ip
- 8004070197 Ack receipt of 800719 interim deficiency rept re-tear in outside flange of uppermast containment liner stiffener Review will commence upon receipt of final (opt FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/18 1p
- 8004170249 Ack receipt of 800319 interim deficiency rept re-potential for reduced steam generator cooling during certain feedwater line break scenarios NRC will review final rept upon receipt FIDRELLIO Region 3. Chicago. Reactor Construction & Fingineering Support Branch 80/04/01 ip
- 8004240122 Ack receipt of final deficiency tept re interaction of nonsafety-grade sys wisteam supply equipment NRC will complete review of matter during future insp FIDRFLLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 60/04/01 ip
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, URIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of Issuance of NURLS OSED. "Interim Staff Position on Environ Qualification of Safety-Related Fiertrical Equipment." providing guidance to methods for compliance ROSS.D F Division of Project Hanagement 80/02/05 /pp
- B004170193 Forwards documentation of stil over capacity Current reserves as a greater that 50% & predictions for 1980 show reserves of 70% No urgency to resume const HAUCK: F Affiliation Unknown B0/03/06 ip
- 8004080671 Notification of 800314 meeting among Ofc of Nuclear Reactor Regulation, IE Region 3 & Ofc of IL Div of Reactor Const Insp in Bathesda, MD to discuss util submittals & answer to current order BHEMMAKER, R.E. Division of Reactor Construction Inspection 80/03/07 2pp
- 8004080160 Forwards util 800305 request that NRC allow resumption of first phase of safety-related work POPE, J.R. Public Service Co. of Indiana. Inc. B0/03/11 ip
- ~-8004080168 Discusses NRC /90815 order confirming suspension of eafetyrelated const at facilities Bubmits plan for resuming receipt insp of safety category matts & components Requests NRC approval of resumption of safety-related activities BHICLDS:8 W Public Service Co of Indiana, Inc. 80/03/05 Opp
- 8004230186 Forwards request for add1 info re util QA program NRC needs info to complete review of revised QA program submitted in response to NRC 770015 order confirming suspension of const Requests consolidation of present QA program RUBENSTEIN.L S Light Water Reactors Branch 4 BQ/04/01 9pp
- B004180370 Notification of 800411 meeting w/util in Bethesda.MD rerevised OA program description
 MILSON.J N Light Mater Reactors Branch 4 B0/04/02 5pp

- 8004290426 Interns of intential to use ANBI N45 2 9-1979 "Requirements for collection. Storage ' Maint of QA Records for Nuclear Power Plants for two regign parameters re used loadings & 2-h fire rating Public Service Co. of Indiana, Inc. 80/04/21 1p.
- 6004300348 Furwards Consolidated Description GA Program "
 SHIELES S W Public Service Co or Indiana, Inc. 80/04/28 ip
- F Security medical, energency & rice protection plans
- 8004080077 Advises that submittal date for evacuation time effequented by NPC 791226 ltm.has been postponed pending GAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force 80/03/11 Emergency Preparedness Task Force 80/03/11 4pp
- G Adjudicatory correspondence
- E03418022) Forwards util 'Description of Licensee Activities Addressing Order Confirming Suspension of Const' POPE J. R. Public Service Co. of Indiana, Inc. 80/03/04 2pp
- 8004030025 Hemorandum or understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK.L V Office of the Erecutive Director for Operations 80/04/02 34pp
- H General correspondence
- B004020490 Abaits reply to 791210 request for hearing re-order for suspension of const Appeal protested regulation & sys which can so easily dismiss final administrative appeal w/o reason or explanation Sassafras Audubon Society 80/03/02 1p
- 8004070364 Responds to 790916 request that LPDR be established in Indianapolis. IN NRC establishes LPDR in immediate vicinity of proposed 5 operating commercial nuclear power plants Applicable LPDR locations 5 hours of operation encl BOUDER. J L Division of Rules and Records 80/03/13 3pp
- --8004070373 Requests establishment of LPBR in Indianapolis, IN Believes that LPDR would be appreciated & well-used by citizens of Indianapolis BENNETT.C L Affiliation Unknown 79/09/16 2pp
- G Inspection reports, IF Bulletins & carrespondence
- 8004040043 Forwards IE Insp Repts 50-546/80-02 & 50-547/80-02 on B00117-18 No noncompliance noted FIGRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8004040046 [E Insp Repts 50-546/80-02 t 50-547/80-02 оп 800117-18 No 204040046 IE Insp Repts 50-946/80-02 t 50-947/80-02 on 800117-18 No noncompliance noted Major areas inspected followup on previously identified insp findings & review of PSI rept re 790627 immediate action ltr HAYES, D N Region 3, Chicago, Reactor Construction & Engineering Support Branch HAMKINS,F C Region 3, Chicago, Office of the ctor 80/02/11 Spp
 - Torwards IE Insp Repts 50-546/80-05 & 50-547/80-05 on noncompliance nated 7 Region 3, Chicago, Drfice of the Director 80/02/16

 - epts 50-546/80-05 % 50-547/80-05 on 800i21 No licensee response to order confirming suspension of const FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch SCHMEIBINZ E R , HAMKING, F C Region 3, Chicago, Office of the Director 80/02/13 2pp
- 8004100144 Forwards IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" No specific action or response required

 KEPPLER, J O Region 3. Chicago, Office of the Director BO/03/07
- BOO4210131 Forwards util BOO305 Itr to V Stello requesting that util be allowed to resume receipt insp at facility SHIELDS,S N Public Service Co of Indiana, Inc 80/03/07 1p

- 8004100371 Responds to 1E Bulletin 80-03 Charcoal adsorber cells purchased for facility have not been delivered to site SHIELDS.5 W Public Service Co of Indiana, Inc 80/03/19 ip
- 8004300525 Forwards IF insp Repts 50-946/80-03 & 50-947/80-03 on 800107-31 & notice of violation KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/21
- --8004300528 Notice of violation from insp on 800107-31 * Region 3, Chicago, Office of the Director 80/03 80/03/18
- --8004300536 IE Insp Repts 50-546/80-03 % 50-547/80-03 on 800107-31 Noncompliance noted failure to include quality requirements in procurement documents, to prescribe quality activity in documented procedure % to implement insp program HILLIAMS, C C , HARRISCN, J J Region 3, Chicago, Office of the Director 80/03/18 8pp
- 8004090141 Ack receipt of 800310 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-25 & 50-547/79-25 FIDRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/24 1p
- --8004090146 Responds to NRC 800115 ltr w/addl info re violations noted in IE Insp Repts 50-546/79-25 / 50-547/79-25 Corrective actions custody of neutron positioning device was changed & proper purge maint was performed SHIELDS:S W Public Service Co of Indiana, Inc 80/03/10 4pp
- 8004110548 Ack receipt of 800306 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-546/79-09 & 50-547/79-09 , Region 3, Chicago, Reactor Construction & Engineering ich 80/03/24 Ip FIRELLI.G Support Branch
- --8004110556 Responds to NRC 791002 ltr re violations noted in IE Insp Repts 50-546/79-09 & 90-547/79-09 Corrective actions contaminant removed from reinforcing steel, joint reprepared to meet Spec Y-2722, Section 411 & featheredge eliminated SHIELDS, S W Public Service Co of Indiana, Inc. 60/03/06 tOpp
- 8004100287 Ack receipt of 800306 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-546/79-il & 50-547/79-il & FIORELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/31 lp
- --8004100291 Supplements 791101 ltr re violations noted in IF Insp Repts 50-546/79-11 & 50-54//9-11 Corrective actions all const work stopped Util relatined consultant to perform mgt analysis of site GA program revised SHIELDS, S.W. Public Service Co. of Indiana, Inc. (10/03/06 7pp
- 8004150186 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary KEPPLER.J G Region 3, Chicago, Office of the Birector 100.002/21 Region 3, Chicago, Office of the Director, 80/03/31
- 8004080721 Forwards IE Circular 80~05, "Emergency Diesel Conerator Lubricating Dil Addition & Onsite Supply " No written response required Region 3, Chicago, Office of the Director 80/04/01, KEPPLER, J G
- 8004150054 Forwards IF Info Notice BD-13, "GE Type SBM Control Switches Defective CAM Followers " No specific action or response KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/02
- 8004180059 Forwards attachments to IE Circular 80-03, "Protection From Toxic Gas Hazards." inadvertently omitted from 800306 KEPPLER: J G Region 3. Chicago: Dffice of the Director 80/04/02
- 8004220150 Forwards IE Info Notice 80-14, "Safety Buggestions From Employees" No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/04/02.
- 800-1220378 Forwards IE Carcular 80-07, "Problems W/HPCI Turbine 011 NAMES OF THE PROPERTY OF THE DESCRIPTION OF THE DIRECTOR OF TH

- B004230250 Forwards 1E Bulletin 79-03A. "Longitudinal Weld Defects in ABME BA-312, Type 304 Stainless Steel Pipe " Action required KEPPLER, J G Region 3. Chicago, Dffice of the Director 80/04/07 by
- 8004220094 Forwards IE Builetin 90-08, "Exam of Containment Liner Penetration Welds " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/09 to
- 8 Reportable occurrences. LERs & related correspondence
- 8004070201 Ack receipt of 800305 interim doficiency rept re noncodo matl & certain Catogory I components Final rept will be revisused upon receipt FIURELILIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/17 ip
- 8004070197 Ack receipt of 800219 interim deficiency rept re tear in outside flange of uppermost containment liner stiffener Review will commonce upon receipt of final rept FICRELIT, G Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/03/18 ip
- 8004170249 Ack receipt of 800319 interim deficiency rept re-potential for reduced steam generator cooling during certain feedwater line break acenarios NRC will review final rept upon receipt FIURELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80704701 ip
- 8004240122 Ack receipt of final deficiency rept re interaction of nonsefety-grade sys w/steam supply equipment NRC will complete review of matter during future insp FIDRELIT, O Region 3, Chicago, Rwactor Construction & Engineering Support Branch 80/04/01 in

DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

- O Adjudicatory correspondence
- B004030026 Memorandum of understanding between NRC & FEMA re grompt improvement in radiological emergency planning & preparedises, distributed as Doard notification 008BICK.L V Office of the Executive Director for Operations 80/04/02 34pp.
- DOCKET 50-949 ORIENT COUNTY NUCLEAR POWER PLANT

 A Application/construction stage documents & correspondence
- G004040031 Advises of issuance of NUREO 0588, "Interim Staff Position on Environ Gualification of Safety-Related Flectrical Equipment," providing guidance re-methods for compliance RGS8,D F Division of Project Management 00/02/05 7pp
- Q Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 00881CK.t. V Office of the Executive Director for Operations 80/04/02 34pp
- DOCKET BIN-50-500 GEBBAR-298-NOP INTERFACE
- A Application/construction stage documents & correspondence
- 0004280422 Forwards excerpts submitted to NRC on 800331, which define low-low set relief function of nuclear boiler sys in BWR life is provided to facilitate NRC review & is unchanged from math presented at 800428 meeting w/MRC QUIRK. J F General Electric Co 80/04/21 13pp
- DOCKET STN-90-953 PRIPPS SEND NUCLEAR PLANT. UNIT 1

 A Application/construction stage documents & correspondence
- 8004040031 Advises of Issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance ROSB, D.F. Division of Project Management 80/02/05 7pp

- 8004080723 Forwards NRC 80012017 (21) line to GE re mode to BWR control rod dilzen sys % addl analysis of boil-off lates, respectively further info * guidance to be issued in NUREG-0619
 BAER.R. L. Light Water Reactors Branch ? 80/03/13 2pp
- B004020154 Forwards add1 info re shortnose sturgeon in Delaware River Concludes that continued operation of Unit 1. Future operation of Unit 2° roust completion of Hope Creek units will not joopardize existence of shortnose sturgeon REGANLY Assistant Director for Environmental Projects B0/03/14
- --8004070163 "Assessment of Impacts of Salem & Hope Creek Stations of Shortnose Sturgeon Acipenser Brevirostrum Lesuer" MASNIK.M T , WILSON, J H. Office of Nuclear Reactor Regulation 80/03/09 110pp
- 800402019.1 Forwards documentation of compliance w/Hatl Historic Preservation Act 1 maps of couridors / corridor segments Review of transmission line corridors shows no potential for adverse environ impact to structures or acheological sites MILLS.L. M. Tennessee Valley Authority 80/03/24 18pp
- -8004020197 "Transmission Line Vicinity flap " Sheet 1 of 3 * Ternessee Valley Authority 78/12/01 1p
- ~~8004020203 "Transmission line Vicinity Map " Sheet 2 of 3 * Tennessee Valley Authority -78/12/01 . Ip
- ~4004020204 "Transmission Line Vicinity Map " Sheet 3 of 3 * Tennossee Valley Authority 78/12/01 ip
- --8004020207 "Transmission Line Vicinity Map " Sheet 1A * Tennessee Valley Authority 60/01/07 1p
- 8004080553 Forwards "Fault Zone in Rock Foundation For Essential Gyc Water Pumping Station," providing detailed description of newly discovered add1 fault discussed in 800314 tolcon w/8 Wastler fault not considered capable MILLS.L M Tennesser Valley Authority 60/04/01 4pp
- BOO4300021 Discusses faulting in Unit 1 feW pumping station & Unit 2 turbine bldg area NRC considers fault Zones 15 & 16 to be associated w/deformational activity related to early geologic history of region Util 800219 & 791024 lirs enci JACKBON, R F. Geosciences Branch BO/04/08 ip
- 80041802'56 Forwards "Geologic Foundation Rept Descriptions of Faults 11-18," Revision 1 MILLS, L.M. Tennessee Valley Authority 80/04/14 1p
- -8004180264 "Geologic foundation Rept Descriptions of Faults 11-181." Revision 1 AVC., A P Tonnossee Valley Authority 80/03/31 9pp
- F. Becurity, modical, emorgoncy & fire protection plans
- GOO408007/ Advises that submittal date for evacuation time estimates. requested by NRC /91226 ltm.has been postponed pending OAD clearance under Federal Repts Act GRIMES.B K Emergency Preparedness Task Force GO/O3/11 App
- G Adjudicatory correspondence
- BOO4030026 Memorandum of understanding between NRC & FEMA re-prompt improvement in ladiological emergency planning & preparedness distributed as Board notification OOSSICK.! V Office of the Executive Director for Operations 80/04/02 34pp
- H General correspondence
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by IOCFR20 & App I to IOCFR50 Environ info available in stated LPIRS BALLARD.R L. Environmental Projects Branch 1 80/04/01 2pp
- G Inspection reports. If Bulletins & correspondence
- 8004070352 Forwards 18 Bulletin 80-03, "Loss of Charcoal From Stil Tupe 11, Two-Inch, Tray Adsorber Cells" Action required 0'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06

- BOO4[6005/ Forwards IE lnsp Repts 50-553/80-01 & 50-554/80-01 on BOO2[2-14 No noncompliance noted BRYANT.J C Region 2. whichte, Reactor Construction & Engineering Support Branch BO/02/2/ 2pp
- --8004160062 IE Insp Repts S0-553/80-01 1 50-554/80-01 on 800212-14 No noncompliance noted Major areas inspected const status, project organization, receiving insp. storage 2 preventive & licensee action on previous insp findings CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch BURDETTE.T E . NRIGHT, R W Region 2. Atlanta, Office of the Director 80/02/27 App
- 8004090025 Confirms 800310 teleon arranging 800320 meeting between NRC 5 util in Atlanta GA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/03/12 2nm
- B004210178 Forwards response to IE Bulletin B0-03, "Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS, L. M. Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit suitches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS.L # Tennessee Valley Authority 60/03/28 2pp
- 8004;50527 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/31 2nd
- 8004080636 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Gil Addition & Onsite Supply "No written response required O'REILLY, J.P. Rogion 2, Atlanta, Orfice of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80-13, "OE Type SBM Control Switches Defective CAM Followers" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 20n
- 6004240274 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02 3pp
- 8004180275 Forwards IE Circulai 80-07, 'Problems H/HPCI Turbine Gil Sys "No written response required O'REILLY, J.P. Region 2, Ablanta, Office of the Director BO/04/03 2pp
- 8004210193 Ark receipt of 800314 ltr informing NRC of steps taken to correct violations noted in 1E lnsg Repts 90-553/79-17 & 50-554/79-16 MVRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/03 tp
 - '8 Responds to NRC 800110 ltr re violations noted in IE Insp 9-17 t 50-554/79-16 Corrective actions craft quality inspectors instructed to conform to tions pending nnessee Valley Authority 80/03/14 3pp
 - s IF Bulletin 80-07. 'BWR Jet Pump Assembly Failure " nse required egion 2. Atlanta, Office of the Director -80/04/04
 - s (E Builetin 79-03A "Longitudinal Weld Defects in 304 Stainless Steel Pipe " Action required egion 2. Atlanta, Office of the Director 80/04/04
 - s IE Bulletin 80-08. "Exam of Containment Liner s " Written response required egion 2. Atlanta, Office of the Director 80/04/07

- 8004230347 Forwards supplement to 790924 response re IE Insp Rept 50-553/79-12 % noncompliance item 553/79-12-01.per NRC B00325 request Rockwell Intl notified that future work performed using insp procedures wylvopen signature affixed MILLS.L.M. Tennessee Valley Authority B0/04/15 2pp
- BOO4290379 Requests approval of ASRE Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp. MILLS, L.M. Tennessee Valley Authority BO/04/23 3pp
- R Periodic operating reports & related correspondence
- B004150392 Forwards, "Const Effects Monitoring Rept.781019-791018 " EL-ASHRY,M T Tennessee Valley Authority 80/04/11 1p
- --8004150396 "Const Effects Monatoring Annual Rept 781019-791018 " ROBERTSON,E B. (LEIN H. NEBBIO H. Tennessee Valley Authority NR-50-10-80 02 79/04/30 95pp
- S Reportable occurrences, LERs & related correspondence
- 8004160216 Forwards revised corrective actions to 800215 final deficiency rept MILLE, L. M. Tennessee Valley Authority 80/03/31 ip
- --8004160218 Revised corrective actions to 800213 final deficiency rept
 Buttered edges on reactor pressure vessel pedestal examined
 & repaired Vendor film quality sufficient to produce repair
 overlays
 * Tennessee Valley Authority 80/03/31 1p
- 8004150485 Forwards final deficiency rept re max weave width exceeded on containment shell welds
 MICLS, L M Tennessee Valley Authority 80/04/03 1p
- ~-8004150494 Final deficiency rept re max weave width exceeded on containment shell welds Weld metal deposited in excess of 5/8-inch max weave width will be removed by thermal air arc grouping All work will be completed by 800730 * Tennessee Valley Authority 80/04/03 ip
- 8004290066 Part 21 rept to insp of generator control panels for emergency diesel generators Results determined defects could degrade emergency diesel unit to untafo performance Corrective action includes indepth insps & training program FALTER, H W PNR System Div PA/PI 80/04/07 4pp
- 8004220724 Forwards interim deficiency rept re incorrect root face on skewed cadwald sleeves MILLS,L N Tennessee Valley Authority 80/04/14 ip
- ---8004220764 Interim deficiency rept re incorrect root face on skewed cadwold sleeves Root face on skewed cadwold sleeves 18 varies from 3/32 to 1/2 inch Design based on assumed 1/16-inch root face Sleeves will undergo destructive pull tests

 * Tennessee Valley Authority 80/04/14 2pp
- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for compliance RDSS.D F Division of Project Management 80/02/05 7pp
- 80040807R3 Forwards NRC 800128 & 0211 itrs to GE re mods to BMR control rod driven sys & addl analyses of boil-off rates; respectively further info & guidance to be issued in NUREG-0619
 BAER, R L Light Water Reactors Branch 2 80/03/13 2pp
- B004020194 Forwards add1 info re shortnose sturgeon in Delaware River Concludes that continued operation of Unit 1, future operation of Unit 2 & const completion of Hope Creek units will not joopardize existence of shortnose sturgeon, REGAN, N H Assistant Director for Environmental Projects 80/03/14 2pp
- 8004020193 Forwards documentation of compliance w/Natl Historic Preservation Act & maps of corridors & corridor segments Review of transmission line corridors shows no potential for adverse environ impact to structures or archeological sites MILLG.L M Tennessee Valley Authority 80/03/24 18pp

- ---8004020197 "Transmission Line Vicinity Map " Sheet 1 of 3 # Tennessee Valley Authority 78/12/01 ip
- --8004020203 "Transmission Line Vicinity Map " Sheet 2 of 3 * Tannessee Valley Authority 78/12/01 ip
- --8004020204 "Transmission Line Vicinity Map " Sheet 3 of 3 * Tennessee Valley Authority 78/12/01 1p
- --8004020207 "Transmission Line Vicinity Map " Sheet 1A * Tennessee Valley Authority 80/01/07 ip
- 8004080553 Forwards "Fault Zone in Rock Foundation For Essential Syc Water Pumping Station," providing detailed description of newly discovered addl fault discussed in 800314 telcon W/S Wastier Fault not considered capable MILLS,L M Tennessee Valley Authority 60/04/01 4pp
- 8004308021 Discusses faulting in Unit 1 ESW pumping station & Unit 2 turbine bldg area NRC considers Fault Zones 15 & 16 to be associated w/deformational activity related to early geologic history of region Util 800219 & 791024 ltrs encl JACKSON,R E Geosciences Branch 80/04/08 1p
- 8004180256 Forwards "Geologic Foundation Rept Descriptions of Faults 11-18," Revision 1 HJLLS,L M Tennessee Valley Authority 80/04/14
- --8004190264 "Geologic Foundation Rept Descriptions of Faults 11-18," Revision 1 AVEL,A P Tennessee Valley Authority 80/03/31 Spp
- F Becurity, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltr.has been postponed pending GAO clearance under Federal Repts Act Emergency Preparedness Task Force 80/03/11 4pp
- C Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification 00881CRL V Office of the Executive Director for Operations
- H General correspondence
- 8004210048 Responds to 800309 ltr requesting info re environ effects of New England nuclear power plants Radiation effluent levels determined by 10cFR20 & App 1 to 10cFR50 Environ info available in stated LPDRS BALLARD, R L Environmental Projects Branch 1 80/04/01 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004090352 Forwards IE Bulletin 80-03. "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells" Action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/06
- 8004160057 Forwards IE Insp Repts 50-553/80-01 & 50-554/80-01 on 800212-14 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactos Construction & Engineering Support Branch 80/02/27 2pp
- --8004160062 IE Insp Repts 50-553/80-01 & 50-554/80-01 on 800212-14 No noncompliance noted Major areas inspected const status, project organization, receiving inspistorage & preventive & licensee action on previous insp findings CANTRELL.F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch BURDETELT E . WRIGHT.R W Region 2, Atlanta, Uffice of the Director 80/02/27 App
- B004090025 Confirms 8003i0 telcon arranging 800320 meeting between NRC & util in Atlanta, OA to discuss accuracy of written repts provided to IE NRC will provide overall evaluation of util handling of deficiences identified by OA program G'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/12
- 8004210178 Forwards response to IE Hulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch, Tray Admorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLS.L M Tennessee Valley Authority 80/03/21 App

- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLS.L M Tennessee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening or PDRV & Block Valve " No specific action or response necessary O'REILLV.J.P. Region 2: Atlanta, Orfice of the Director 80/03/3 Region 2: Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-05, "Fmergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required G'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04
- Region 2. Atlanta: Orfice of the Director 80/04/01
- 8004150097 Forwards IE Info Notice 80-13, "GE Type SBM Control Switches Defective CAM Followers." No specific action or response O'REILLY, J.P. Region 2: Atlanta: Office of the Director 80/04/02
- B004240274 Forwards IE Info Natice 80-14, "Safety Suggestions From Employees " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004180275 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Gil Sys " No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/03
- 8004210183 Ack receipt of 800314 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-17 & 50-554/79-16 MURPHY-C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/03 ip
- --8004210168 Responds to NRC 800110 ltr re violations nated in IE Insp. Repts 50-553/79-17 % 90-554/79-16 Corrective actions craft supervisors & quality inspectors instructed to conform to specs Other actions pending MILLS.L M Tennessee Valley Authority 80/03/14 3pp
- 8004110017 Forwards IE Bulletin 80-07, 'BNR Jet Pump Assembly Failure " No written response required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004230142 Forwards IF Bulletin 79-03A "Longitudina) Weld Defects in ASME SA-312,Type 304 Stainless Steel Pipe " Action required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-09, "Exam of Containment Liner Penetration Welds" Writter response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcomino preservice insp MILLS, LM Ter

- Publication of Part 21 rept of image of generator control panels for energen y diesel generators weshits determined defects could image are energency diesel unit troussale performance corrective action includes indepth insps 5 training program FALTER HOU PROBLEMS OF App.
- EDD4220724 Forwards interim dericiency tept re incorrect root face on skewel calleld sleeves.
 MILLOI M. Tennesser Malley Authority. 80/04/14. Ip
- -BO042_G/64 Interim deficiency rept he incorrect root face on skewed caduald sleeve 18 aries arch 3/32 to 1/2 inch Design based on assumed 1/16-inch noot face Sleeve 311 undergo destructive pull tests Tannessee Valley authority 80/04/14 2pp
- ECCRET STN-50-556 BLACK Fire STATIGN. UNIT 1

 A Application/construction stage documents & correspondence
- 6004040031 Advises of issuance of NNREG-0588. "Interin Staff Position on Environ smallrication of Sarety-Related Electrical Equipment "providing juidance te methods for compliance ROSS D F Division of Project Management 80/02/05 7pp
- B004210405 Curmary of B00325 meeting w/near-term CP applicants in Bathwida. The evaluation or progress made to date establishing proposed requirements stemming from TMI-2 accident THOMAS C O Standardivation Branch 80/04/03 63pp
- 8004300074 Surnary of 800317 mmeting u/Near-Term CP Applicants Group in Bethesda.MD re-natters related to resumption of CP application review activities associated u/TMI-2 accidents THOMAS C Q Standardization Branch BD/04/03 12pp
- 8004240557 Summary of 800407 meeting u/Near-Term CP Applicants Group in Bethesda, MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl THOMAS.C O Light Water Reactors Branch 1 80/04/07 47pp
- G Adjudicatory correspondince
- 8004070149 Requests NRC permission to address meltdown issue during hearings affecting const 2 operation of facility Questions should be fully answered 2 thoroughly researched OK citizens have right to be heard MICLHITE 8 Citizens Action For Safe Energy 80/02/21 1p
- BOO4100595 Forwards intervenor response to applicant motion to strike response of DK attorney genera! to ALAB-573 & intervenor motion to strike applicant motion to dismiss Class 9 accident inquiry FARRIS. J R Feldman, Hali. Franden, Reed & Woodward 80/02/26 ip
- --B004100605 Intervenor response to applicant motion to strike response of DK attorney general to ASLAB-573 State of CK response contains important } substantive comments & should be adopted to ALAB-573 Certificate of Svc encl FARRIS, J R Citizens Action For Safe Energy FARRIS, J R Feldman, Hall, Franden, Reed } Woodward 80/02/26 3pp
- --8004100610 Intervenor motion to strike applicant motion to dismiss
 Class 9 accident inquiry 2 motion to strike response of OK
 attorney general to ALAB-573 Proceeding should be judged on
 merits 2 not technicalisties Certificate of Svc enci
 FARRIS, J.R. Citizens Action For Safe Energy FARRIS, J.R.
 Feldman, Hall, Franden, Feed & Moodward 80/02/26 App
- 8004160161 Notice of change of address for Washington ofc of Isham, Lincoln & Beale Certificate or Svc encl GALLO.J Fublic Service Co of Oklahoma GALLO,J Isham, Lincoln & Beale 83/03/14 App
- 8004040266 Suggests local self-reliant, self-sufficient communities are solution to present problems Opposes all forms of nuclear power Min amount of energy from coal t gas should be needed for mfg useful tools, bicycles & efficient tractors MEEKS.M Affiliation Unknown 80/03/15 2pp
- 8004070108 Expresses concern re NRC refusal to address meltdown issue at hearings Class 9 accident is distinct possibility & should be thoroughly examined Environ & site suitability hearings should be reopened BUTTHEAD, B J Affiliation Unknown 80/03/15 1p

- 8004100235 Response in apposition to joint intervenors' 800226 motion to strike applicants' 800211 pleadings re Class 9 accident inquiry Striking instant pleadings on grounds of untimelitres is not warranted under case law DAVIS.L D Hearing Branch 4 80/03/17 8pp
- 8004280030 Submits add1 info in support of 600206 request for extension to review ALAB-573 Class 9 accident issue Lack of NRC opposition to OA laquest & lecent proliferation of info support extension CARTHRIGHT. J.E., ROGERS. C.S. Oklahoma, State of 80/03/18 3pp
- 8004070143 Hemorandum & order to ASLAB 791207 decision.ALAB-573 Issue of Class 9 accidents variated ; remanded to ASLAB for addl action Related motions most Commission shall be informed of related cases Commissioners Gillinsky & Bradford dissented CHILK.S J. Office of the Secretary of the Commission GO/03/21
- 8004150027 Forwards licensee supplemental brief re motion for directed certification ½ for stay Pendency of Class 7 issue before Commission noted in Licensee motion for directed certification ½ for stay Discussed on Pages /-10
 WETTERHAHN,M J Conner, Moore & Corber 80/03/24 2pp
- --8004150043 Memorandum ? order vacating portion of ALAB 573 captioned "Consideration of Class 9 Accidents" & remanding to ASLAB for further consideration Certificate of Svc encl CHILK.5 J. Office of the Secretary of the Commission 80/03/21
- 8004080562 Memorandum % order re ALAB-573 concerning individual cases of Class 9 accidents Directs ASLB to address radiological health % safety proceedings in manner consistent w/ABLAB opinion. ALAB-587 % Commission momorandum CLI-880-08 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/28 488
- 8004250003 Forwards Commission order to consideration of environ consequences of Class 9 accidents at land-based reactors SHAPAR, H. Office of the Executive Legal Director 80/03/31 ip
- --8004250011 Order vacating portion of ALAB-573 re Class 9 accidents & remanding that portion to ASLAB for further consideration CHILK.5 J Office of the Secretary of the Commission 80/03/31 4pp
- 8004230082 Statements of position re-certified question of App 1 of IOCPRSO concerning litigation of health effects of routing radioactive emissions Unges dismissal of inquiry Cortificate of Svc encl
 DALTON, A T Dalton, A T 80/04/01 7pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- 8004250372 Forwards Corp Commission of State of OK 800403 order denying request for approval to sell bonds PSC of OK presently reviewing order w/view of filing appeal w/QK Supreme Court OALLOJ Isham Lincoln & Beale 80/04/04 4pp
- 8004150098 Brief on question certified by ABLAN re App I of 10CFR2 785 (d) concerning litigation of health effects Issue is litigable in context of striking overall NEPA cost-benefit balance Appeal must be denied W/Certificate of Svc encl DAVIS,L D. SCINIO.J. Hearing Branch 4 80/04/07 38pp
- BOO4220334 Memorandum stating views re question certified in ALAN-373 Consideration of health effects from emission within App I limits is central & controlling factor Certificate of Evc encl MILLER, M I , MURPHY, P M Public Service Co of Oklahoma MILLER, M I Isham, Lincoln & Deale 80/04/07 33pp
- 8004280189 Brisf amicus curian re certified question of whether litigation of health effects of normal radioactive releases is barred as matter of law Issue is precluded in absence of special circumstances W.Certificate of Syc REYNOLDS, N.S., PHILIPS, M.H. Tevas Utilities Generating Core REYNOLDS, N.S. Debevoise & Liberman 80/04/07 21pp
- H General correspondence
- BO04030337 Requests open hearings on facility re possibility of major accidents, health effects & evacuation NRC & utils have moral responsibility to insure safety People have right to know answers to problems
 FARRELL.D. FARRELLS Affiliation Unknown B0/02/14 1p

- 8004070124 Requests that NRC reopen environ $\mathcal D$ site suitability hearings Moltdown issue should be fully explored + Affiliation Unknown 80/02/15 lp
- B004040238 Requests that NRC reopen environ & site suitability hearings to consider possible moltdown & related emergencies associated w/nulcear power plants GIBBS.C F Affiliation Unknown 80/02/19 ip
- 8004070116 Requests that NRC reopen environ & site switability hearings to fully explore meltdown possibilities at facility Const should stop until problems re nuclear waste disposal & safety are resolved
 TIBETTS.L Affiliation Unknown 80/02/24 1p
- 8004040228 Suggests hearings on const of reactor did not addross meltdown issues Tulsa should not be made site for potential nuclear mistake Utils should build plants away from populated areas Requests reopening of hearings SMITH.M Affiliation Unknown 80/03/15 1p
- 8004040241 Requests that NRC hold meetings in Tulsa,CK re emergency evacuation zone around nuclear plants Plans should be more thorough to protect people if meltdown should accur HEMPLEREE,R Affiliation Unknown 80/03/15 lp
- 8004070260 Responds to 1tr to President Carter inquiring why work has stopped on facility Provides info re NRC rules & regulations involved in building & licensing nuclear plants CPs must be issued to util before work can be resumed on facility STOLZ.J F Light Water Reactors Branch 1 80/03/20 1p
- --8004070267 Forwards F friend ltr to President Carter inquiring why work has stopped on facility Requests comments RATHKOPF.C L Energy, Dept of 80/01/22 4pp
- 8004290175 Forwards D Plant 800214 ltr expressing concern re possible meltdown at facilities Requests response BYNAR.N House of Rep. 80/03/26 2pp
- 8 Reportable occurrences, LERs & related correspondence
- B004250431 Forwards first interim deficiency rept re defective concrete pour in auxiliary bldg Next rept will be submitted by B00613.
 MILLS-L M Tonnessee Valley Authority B0/04/21 ip
- --8004250432 First interim deficiency rept re defective concrete pour in auxiliary bldg Concrete samples have been sent to Bingleton Lab for testing * Tennessee Valley Authority 80/04/21 App
- DOCKET STN-50-557 BLACK FOX STATION, UNIT 2
- B004160161 Notice of change of address for Washington of of Isham, Lincoln & Beale Certificate of Svc encl OALLO, J Public Bervica Co of Oklahoma OALLO, J Isham, Lincoln & Beale B0/03/14 4pp
- A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance re methods for compliance ROSS, D f Division of Project Management 80/02/05 7pg
- 8004210405 Summary of 800328 meeting w/near-term CP applicants in Bethesda,MD re evaluation of progress made to date establishing proposed requirements stemming from TMI-2 accident THOMAS,C O Standardization Branch 80/04/03 43pp
- 8004300074 Summary of 800319 meeting w/Near-Term CP Applicants Group in Bethasds,MD re matters related to resumption of CP application review activities associated w/TMI-2 accidents THOMAS.C O Standardization Branch 80/04/03 12pp
- 8004240587 Summary of 800402 meeting w/Near-Term CP Applicants Group in Bethesda.MD re progress made establishing proposed requirements stemming from TMI-2 accident Proposed requirement category assignments encl
 THOMAS.C D Light Water Reactors Branch 1 80/04/07 47pp

- G Adjudicatory correspondence
- 8004070149 Requests NRC permission to address moltdown issue during hearings affecting constit operation of Facility Questions should be fully answered to thoroughly researched CK citizens have right to be heard WILLMITE, S. Citizens Action For Safe Energy 80/02/21 ip
- 8004100595 Forwards intervenor response to applicant motion to strike response of CK attoiney general to ALAB-5/3 * intervenor motion to strike applicant motion to dismiss Class 9 accident inquiry FARRIS. J R Feldman, Hall, Franden, Reed * Noodward 80/02/24 ip
- ~-8004100605 Intervenor response to applicant motion to strike response of GK attorney general to AbLAB-973 State of GK response contains important! substantive comments & should be adopted to ALAB-573 Certificate of Svc encl FARRIS, J R Cittiens Action For Safe Energy FARRIS, J R Feldman, Hall, Francen, Recd / Woodward 80/02/26 3pp
- --8004100610 Intervenor motion to strike applicant motion to dismiss Class 9 accident inquiry 8 motion to strike response of CK attorney general to ALAR-572 Proceeding should be judged on merits 8 not technicalities Certificate of Svc enci FARRIS, J R Citizens Action For Safe Energy FARRIS, J R Feldman, Hall, Franchen, Reed & Woodward 80/02/26 & 5pp
- BO04040266 Suggests local self-reliant, self-sufficient communities are solution to present problems Opposes all foims of nuclear power Min amount of energy from coal 3 gas should be needed for mfg useful tools, bicycles 7 efficient tractors MEEKS.M Affiliation Unknown 80/03/15 2pp
- 8004070109 Expresses concein to NRC refusal to address meltdown issue at hearings Class 9 accident is distinct possibility & should be thoroughly examined Environ & site suitablity hearings should be reopened BUTTHEAD, S J Affiliation Unknown 80/03/15 1p
- 8004)00235 Response in opposition to joint intervenors' 800226 motion to strike applicants' 800211 pleadings re Class 9 accident inquiry Striking instant pleadings on grounds of untimpliness is not warranted under case law DAVIS.L D Hearing Branch 4 80/03/17 8pp
- 8004280030 Submits add1 info in support of 800206 request for extension to review ALAB-573 Class 7 accident issue Lack of NRC opposition to OK request // recent proliferation of info support extension CARTWRIGHT.J F., ROCERS.C S. Otlahoma, State of BO/03/18 Spp
- 8004070143 Memorandum & order re ASLAB 791207 decision. ALAB-573 Issue of Class 9 accidents vacated & remanded to ASLAB for addlaction Related metions moot Commission shall be informed of related cases Commissioners Orlinsky & Bradford dissented CHILK, S.J. Office of the Secretary of the Commission 80/03/21 Abb
- B004150027 Forwards licensee supplemental brief te motion for directed certification & for stay Pendency of Class 9 issue before Commission noted in Licensee motion for directed certification & for stay Discussed on Pages 7-10 HETTERHAHN, II J Conner, Muote & Corber 80/03/24 2pp
- --8004150043 Memorandum & order vacating portion of ALAB 573 captioned "Consideration of Class 9 Accidents" > remanding to ASLAB for further consideration Certificate of Svt encl CHILKS J Office of the Secretary of the Commission 80/03/21 App
- 8004080562 Memorandum & order re ALAB-573 concerning individual cases of Class 9 accidents Directs ASLB fo address radiological health & safety proceedings in manner consistent wASLAB opinion. ALAB-587 & Commission Americandum CLI-80-08 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/28 400
- BOO4250003 Forwards Commission order to consideration of environ consequences of Class 9 accidents at land-based reactors SHAPAR, M. Office of the Executive Legal Director 80/03/31 ip
- --8004250011 Order vacating portion of ALAB-573 re Class 9 accidents & remanding that portion to ASLAB for further consideration.

 CHILK, B.J. Office or the Secretary of the Commission 80/03/31 4pp

- this design of the control of the control of the section of the se of Svc encl DALTO FA 1 Taltur m T
- ui 040°00°26 Menorandum or or renshanding between NRC & FEMA me prompt ingrollement in madiciously of energency planning & preparedness distributed as B and notify ation 603510°14 111 Other of the Exerctive Director for Operations 60704°07 Talge
- 8004251322 Furuands complements on State of OK 800403 order denying request for approval to well monts PSC of OK presently reflecting order states or rating appeal w/OK Supreme Court OALLO J. Ishan Lin To 't beale 80704/04 4pp
- +30415/6780 Brief on question centified by ASLAB re App I of 10CFR2 785
 (3) rancerning litigation of health effects Issue is
 litigable in contest of striking overall NEPA cost-benefit
 balance Appeal nust be series Wifertificate of Svc encl
 BAVIS L D SUINTO rearing Branch 4 80/04/07 38pp
- 6004220334 Memorandum stating views re question certified in ALAB-573 Consideration or health erre to recommendation within App t limits is rentral & controlling factor Certificate of Svc enri Miller II - Murphy, P. M. Public Service Co. of Oklahoma Miller, II : Isham timcoin 'Seele 80/04/07 33pp
- B304280187 Siler anicus uijav te cettified question of whether litigation of health erreits or normal radioactive releases is barred as matter of law lesue is precluded in absence of special circumstances the ethicicate or Svc REYNGLOS N S PHILIPS, II H Teras Utilities Generating Co REYNGLOS N S Debeccise? Libernan 80,04/07 21pp ,

H General correspondence

- 8004030339 Requests open Pearings on racility is possibility of major accidents health effects L evacuation NRC & utils have moral responsibility to insure safety People have right to know answers to problems

 FARRELL.D FARRELL,5 Affiliation Unknown 80/02/14 ip
- 8004070124 Requests that NHC reopen environ & site suitability hearings Heltdoun issue should be fully explored Affiliation Unknown 80/02 15 1p
- 800404023B Requests that NRC reopen environ % site suitability hearings to consider possible meltdown % related emergencies associated u/milcear price plants GIBBS.CF Affiliation Unincom 80/02/17 1p
- 8004070115 Requests that NRC reopen environ 5 site suitability hearings to fully explore meltdown possibilities at facility Const should stop until problems re nuclear waste disposal & THETTO Affiliation Uninoun 80/02/24 1
- BOO4040228 Suggests hearings on const of reactor did not address meltdown issues Tulsa should not be made site for potential nuclear mistake Utils should build plants away from populated areas Requests reopening of hearings SMITH.M Affiliation Unknown E0/03/15 ip
- 8004040241 Requests that IRC hold meetings in Tulsa.OK re emergency evacuation zone around nuclear plants Plans should be more thorough to protect people if meltdown should occur HEMPLEREE,R Aefiliation Univolum 80/03/15 1p
- 8004090260 Responds to 1t1 to President Carter inquiring why work has stopped on facility Provides info re NRC rules E regulations involved in building & licensing nuclear plants CPs must be issued to util before work can be resumed on facility STOL2. J F Light Water Reactors Branch 1 80703720 1p
- --8004090269 Forwards E Friend itr to President Carter inquiring why work has stopped on facility Requests comments RATHAUPF,C L Energy Dept or 80/01/22 4pp
- 8004290175 Forwards D Plant 800214 ltr expressing concern re possible meltdown at facilities Requests response SYHAR.M House of Rep. 80/03/26 2pp

- S Reportable occurrences. LERs / related correspondence
- 8004250431 Forwards first interim deficiency rept re defective concrete pour in auxiliary bldg Nert rept will be submitted by 800613 MILLS, L M Tennessee Valley Authority 80/04/21
- --8004250432 First interim deficiency rept ro defective concrete pour in auxiliary bldg Concrete samples have been sent to Singleton Lab for testing * Tennessor Valley Authority 80/04/21 4pp
- DOCKET 50-964 NUCLEAR FULLS RECOVERY & RECYCLE CENTER
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification QOSSICKLL V Office of the Executive Director for Operations ں 34pp 80/04/02
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance re methods for cumpliance ROSS, D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergancy & fire protection plans
- BOO40B0077 Advises that submittal date for evacuation time estimates, requested by NRC 791226 ltm.has been postponed pending GAD clearance under Federal Repts Act GRIMEG.B K Emergency Preparedness Task Force BO/03/11 4pp
- G Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICK.L. V. Office of the Executive Director for Operations 80/04/02 34pp
- Q inspection reports: IE Dulletins & correspondence
- B0041004B1 Ack receipt of 800123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-966/79-18 & S0-967/79-18 & BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/04 2μp
- --8004100495 Responds to NRC 791228 ltr re violations noted in IC Insp Repts 50-566/79-18 & 50-567/79-18 Corrective actions chemical & vol control sys charging pumps relocated from storage to area w/power supply Heaters connected HILLS.C. H. Tennessee Valley Authority (80/01/2) 2pp
- --8004100503 Forwards IE Insp Repts 50-566//9-18 & 50-567/79-18 on 791211-14 V notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/12/28 2pp
- ---8004100505 Notice of violation from insp on 791211-14 * Region 2. Atlanta, Office of the Director 7971; 77/12/27 1p
- --B004100506 IE Insp Repts S0-566/79-18 & 50-567/79-18 on 791211-14. 004100506 IE Insp Repts 30-566/79-18 t 30-367/79-18 on 791kli-14. Noncompliance noted failure to provide space heaters for safety-related pumps in storage CANTRELL,FS Region 2, Atlanta, Reactor Construction & Engineering Support Branch GOUGE,M J Region 2, Atlanta, Office of the Director 79/12/27 Spp
- 8004090352 Forwards IF Builetin 80-03, "Loss of Chercoal From 8td Type II. Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06
- 8004040203 Forwards IE Insp Repts 50-566/80-02 & 50-567/80-02 on B00123-25 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/13 2pp

- --8004040208 IE Insp Repts 50-566/80-02 & 50-567/80-02 on 800123-25 No DOUGLOCUS IE Insp Repts 30-366/80-02 & 30-366/80-02 on Budis2-25 Ni moncompliance noted Major areas inspected preservice insp of major components HERDT:A R Region 2: Atlanta: Reactor Construction & Engineering Support Branch CROKLEY, B R Region 2: Atlanta: Office of the Director 80/02/32 7pp Support Branch Director 80/
- 8004210116 Forwards IE Insp Repts 50-566/80-04 & 50-567/80-04 on 800219-22 No noncompliance noted pRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8004210121 IE Insp Repts 50-566/80-04 % 50-567/80-04 on 800219-32 No DOMATION IN IT IN THE TOTAL THE SUPPLY OF TH
- 8004090025 Confirms 800310 telcon arranging 800320 meeting between NRC & util in Atlanta.QA to discuss accuracy of written repts provided to IC NRC will provide overall evaluation of util handling of defictences identified by QA program C/REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/12
- 8004210178 Forwards response to IE Bulletin 80~03, "Loss of Charcoal from 8td Type II, Two-Inch, Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use exists MILLG.L.M Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to 11 Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities where applicable limit switches are identified, replacement gaskets have been ordered MILLB, L N Tennessee Valley Authority 80/03/28 2pp
- 8004130827 Forwards IC Info Notice 80-12, "Instrument Failure Causes Opening of PCRV & Block Valve " No specific action or response necessary O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/03/31
- 8004080636 Forwards IE Circular 80-03, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/01
- 8004150097 Forwards IF Info Notice 80-13, "OF Type 88M Control Switches Defective CAM Followers " No specific action or response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- 8004240274 Forwards IC Info Nutice 80-14, "Bafety Suggestions From Englances" No action required Employees " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
- 8004100275 Forwards IE Circular 80-07, "Problems W/HPCI Turbine Oil O'REILLY J P No written response required LLY.JP Region 2: Atlanta: Office of the Director 80/04/03
- 8004230142 Forwards IC Dulletin 79-03A "Longitudinal Hald Defects in ABME 88-312, Type 304 Stainless Steel Pipe" Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Written response required 0'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/07
- 8004300090 Ack receipt of 800324 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/80-03 & 00-567/80-03 MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch
- --8004300096 Responds to NRC 800228 itr re violations noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 Corrective actions all rediographs w/unecceptable shim placement will be reshot HILLBL M Tennesses Valley Authority, 80/03/24 2pp

- --B004300100 Forwards IF lnsp Repts 50-566/80-03 & 50-56//B0-03 on B00205-08 % natice of violation BRYANT, J.C. Region 2. Aflanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8004300103 Notice of violation from insp on 800205-08 * Region 2. Atlanta. Office of the Director 80/08 80/02/27 Lp
- --8004300100 IF Insp Repts 50-546/60-03 b 50-547/80-03 on 800205-08
 Noncompliance noted failure to establish adequate measures
 to control radiographic estam procedures for welds
 KLEINSORGE, W.P. Region 2. Atlanta, Office of the Director
 HERDIAR Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch 80/07/2/ Opp
- 8004250405 Notifies that revised response to violations noted in IE Insp Rapts 50-566/80-03 t 50-567/80-03 re failure to establish adequate measures to control radiography, will be submitted by 800468 MILLG.L.M. Tennessee Valley Authority 80/04/21 ip
- 8004290379 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice MILLS.L M Tennossee Valley Authority GO/04/23 App
- R Periodic operating reports / related correspondence
- 8004280508 Forwards YCNP-SMR 3, 'Socioeconimic Monitoring & Mitigation Rept." For Jan-June 1979 MILLS-L N Tennessee Valley Authority 80/04/15 tp
- --8004280510 "Soridecommic Manitaring & Mitigation Rept." for Jan-June
 - Tennessee Valley Authority YCNP-SMR 3 80/03/31 31pp
- S Reportable occurrences, iFRs & related correspondence
- 8004250374 Forwards first into im deficiency ropt re improper documentation & Utilization of computer program INERTIA Next rept will be submitted by 800801 MILLS.L M Tonnessee Valley Authority 80/04/21 ip
- --B0042503/9 lirst interim deficiency rept to improper documentation & utilization of computer program INERTIA Program documentation being revised to restrict use to classed sections only
 * Tennessee Valley Authority - 80/04/21
- DOCKET STN-90 967 YELLOW CREEK NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8004040031 Advises of issuance of NURCO-0588. "Interim Blaff Position on Environ Qualification of Safety-Related Electrical Equipment." providing guidance to methods for compliance RDS9.D F Division of Project Management 80/02/05 7pp
- F Security, medical, emergency & fire protection plans
- 8004080077 Advises that submittal date for evacuation time estimates, requested by NRC 771226 ltr.has been postponed pending GAO clearance under Federal Repts Act Emergency Prepareduess Task Force 80/03/11 4pp GRIMES, D K
- 9 Adjudicatory correspondence
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt temprovement in radiological emergency planning & preparedness, distributed as Board notification GOSSICK.L V Office of the Executive Director for Operations З4рр 00/04/02
- Q Inspection reports. If Bulletins & correspondence
- 8004100481 Ack receipt of 800123 ltr informing NRC of steps taken to correct vialations noted in It. Insp Repts 50-566/79-18 & 50-567/79-18 BRYANT.J.C. Region 2, Atlants, Reactor Construction & Engineering Support Branch 80/02/04 2pp

- 300×100475 mespands in 181 771273 lts se solutions noted in IE Insp. Repts to 6- 74 [8 / 4/ 55/,77-18 Corrective actions chemical in a control sys in gaing perps selected from starage to a early even supply Heaters connected MILLS L M. Tenrosse "faller, motherity 80/01/23 2pp
- - 8004100505 Notice of violation from illsp on 791211-14 * Region 2 Atlanta Office of the Director 79/12/27 ip
- --EOD410FPhb IE Inst Rept. 97 564 75-18 5 50-567/79-18 on 791211-14 Monconpliance united stallure to provide space heaters for sasety-relaised pumps in sturage CA 'TRELL' F.S. Pegion & Atlanta. Reactor Construction & Engineering Support Limanch GOUGE M.J. Pegion 2. Atlanta, Office of the Director 9-12 d7 Spp
- 2004090352 Forwards It 30(1)*tin 80-03 Loss of Chancoal From Std Type II.Two-inch Tray Advance: Cells Action required D'REILLT, J.F. Region r. Atlanta, Ortice of the Director 80/02/06 2an
- G004040203 Forwards If Insp Repts 50-556/80-02 & 50-567/80-02 on G00123-75 No moncorpliance noted BRYANT, J C Pegion 2 Atlanta, Reactor Construction & Engineering Support Branch G0/02/13 2pp
- --8004040208 IE Insp Repts 50-564/80-02 t 50-547/80-02 on 800123-25 No noncompliance noted Major areas inspected preservice insp of major components
 HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch LRGMLEY B R Region 2. Atlanta, Office of the Director 80/02/12 7pp
- 8004210116 Forwards IE Insp Repts 50-566/80-04 & 50-567/80-04 on 800219-22 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support 3 ranch 80/03/04 2pp
- --8004210121 IE Insp Repts 50-566.80-04 ? 50-567/80-04 on 800219-22 No noncompliance noted Major areas inspected licensee action on previous insp findings, insp followup items. IE builetins & circulars ? warehouse storage CANTRELL, F 9 Region 2, Aflanta, Reactor Construction & Engineering Support Bianch ITHOMAS.M. GOURGE.M J Region 2, Atlanta, Office of the Director 80/03/03 Spp
- 8004090025 Confirms BOG310 feiron arranging B00320 meeting between NRC 3 util in Atlanta, GA to discuss accuracy of written repts provided to IF NRC will provide overall evaluation of util handling of deficiences identified by GA program O'REILL: J.P. Region 2 Atlanta, Office of the Director B0/03/12 2pp
- 8004210178 Forwards response to IF Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-lnch.Tray Adsorber Cells " Encl lists results of insps at facilities to determine if potential for loss of charcoal incidental to handling or use erists MILLS.L II Tennessee Valley Authority 80/03/21 4pp
- 8004180106 Forwards response to IE Bulletin 79-28 re possible malfunction of NAMCO Model EA180 limit switches At facilities whose applicable limit switches are identified, replacement gaskets have been ordered MILLS.L M Tennassee Valley Authority 80/03/28 2pp
- 8004150527 Forwards IE Into Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Value" No specific action or response necessary O'REILLY, J.P. Region 2. Aflanta, Office of the Director 80/03/31 2pp
- 8004080o36 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required O'REILLY, J.P. Region 3, Atlanta, Office of the Director 80/04/01 2pp
- 8004150097 Forwards IE Info Notice 80-13, "GE Type 88M Control Switches Defective CAM Followers " No specific action or response required O'REILLY.J P Region 2, Atlanta, Orfice of the Director 80/04/02 2ps

- 8004240274 Forwards II Into Notice 80-14. "Safety Buggestions From Employees' No action required O'REILLY, J.P. Region 2. Aflanta, Office of the Director 80/04/02 3oo
- 8004180275 Forwards IE Circular 80-07, 'Problems W/HPCI Turbine Oil Sys "No written response required G'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/04/03
- 8004230142 Forwards IF Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312,Type 304 Stainless Steel Pipe " Action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/04/04
- 8004180445 Forwards IE Bulletin 80-08, 'Exam of Containment Liner Penetration Welds " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/07
- 8004300090 Ack receipt or 800324 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/09 Zpp
- --8004300096 Responds to NRC 800228 Ith re violations nated in IE Imap Repts 50-566/80-03 & 90-867/80-03 Corrective actions all radiographs u/unacceptable shim placement will be reshot MILLS,L M Tennessee Valley Authority 80/03/24 2pp
- --8004300100 Forwards IE Insp Repts 50-564/80-03 & 50-567/80-03 on 800205-08 totice of violation BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8004300103 Notice of violation from insp on 800205-08

 * Region 2, Atlanta, Office of the Director 80/02/27 in
- --8004300108 IE Insp Repts 50-566/80-03 & 50-567/80-03 on 800205-08
 Noncompliance noted railure to establish adoquate measures
 to control radiographic exam procedures for welds
 KLEINSORGE.W P Region 2. Atlanta. Office of the Director
 HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch 80/02/27 8pp
- 8004250405 Notifies that revised response to violations noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 re failure to establish adequate measures to control radingraphy, will be submitted by 800428 MILLS, L.M. Tennesses Valley Authority 80/04/21 ip
- 8004290377 Requests approval of ASME Code Cases N-234 & N-235 for use on reactor pressure vessels Expeditious approval is necessary for use of code cases in forthcoming preservice insp.
 MILLS.L M. Tennessee Valley Authority 80/04/23 3pp.
- R Periodic operating reports & related correspondence
- 800428050B Forwards YCNP-9MR 3. "Goctoeconimic Monitoring & Mitigation Rept," for Jan-June 1979 MILLS,L II Tennessee Valley Authority 80/04/15 ip
- --8004280510 "Socioeconomic Monitoring & Mitigation Rept." for Jan-June 1979 * Tennessee Valley Authority YCNP-6MR 3 80/03/31 3ipp
- S Reportable occurrences, LERs & related correspondence
- 8004250374 Forwards first interim deficiency rept re improper documentation & utilization of computer program INERTIA Naxt rept will be submitted by 800801 MILLS:t. M Tennessee Valley Authority 80/04/21 ip
- -8004250379 First interim deficiency rept re improper documentation & utilization of computer program INERTIA Program documentation being revised to restrict use to closed sections only * Tennessee Valley Authority 80/04/21 ip

```
DOCKET STN-50-568 NEP NUCLEAR, UNIT 1
                                                                                                                                                                 DOCKET 51N-50 580 LRIC NOLLEAR PLANT, UNIT 1
A Application/construction stage documents & correspondence
                                                                                                                                                                 A Application/construction stage documents / correspondence
7811300053 Forwards review of the Preliminary Draft Environ Statement
Finds PDEG unnecessarily wordy Believes impact sections
should only focus on real putential of probable areas
SAMWORTH. R B Environmental Specialists Branch 78/11/17 13pp
                                                                                                                                                                 8004040031 Advises of issuance of NUREG-0588. "Interim Staff Position on Environ Qualification of Sarety-Rolated Electrical Equipment," providing guidance re methods for compliance ROSE DF Division of Project Management 80/02/05 7pp
8004140012 Responds to 771217 withdrawal of CP application re recovery of review costs Ofc of Controller notified to issue invoice for balance due
                                                                                                                                                                 Q Adjudicatory correspondence
   MILLER, W.O. License Fee Management Branch 80/03/24
                                                                                                                                                                 8004030026 Memorandum of understanding between NRC & FEMA re prompt
                                                                                                                                                                     improvement in radiological emergency planning & preparedness, distributed as Board notification COSSICK.t V Office or the Executive Director for Operations 80/04/02 34pp
Q Adjudicatory correspondence
8004030026 Mamorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GDBSICK, L. V. Office of the Executive Director for Operations
                                                                                                                                                                 DOCKET BIN 50-501 ERIC NUCLEAR PLANT, UNIT 2
    60/04/02
                         34pp
                                                                                                                                                                 A Application/construction stage documents & correspondence
                                                                                                                                                                 8004040031 Advises of issuance of NUREG-0588, "Interim Btaff Position on Environ Qualification of Safety-Related Electrical Equipment," providing guidance to mothods for compliance ROSS D F Division of Project Management 60/02/05 7pp
DOCKET BIN-50-569 NEP NUCLEAR, UNIT 2
A Application/construction stage documents & correspondence
7811300053 Forwards review of the Preliminary Draft Environ Statement Finds PDEB unnecessarily wordy Believes impact soctions should only focus on real potential or probable areas SAMMORTHER B Fovironmental Specialists Branch 78/11/17 13pp
                                                                                                                                                                 O Adjudicatory correspondence
                                                                                                                                                                 8004030026 Memorandum of understanding between NRC & FEMA ie prompt
improvement in iadiological emergency planning h
preparodices, distributed as Board notification
GDSSICKL V Office of the Executive Director for Operations
BO/04/02 34ap
8004140012 Responds to 791217 withdrawal of CP application re-recovery of review costs Ofc of Controller notified to issue invoice
    for balance due
MILLER.W O License Fee Management Branch 80/03/24 ip
                                                                                                                                                                 DOCKET 50 -582 BUNDESERT, UNIT I
9 Adjudicatory correspondence
                                                                                                                                                                 G Adjudicatory correspondence
0004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification 00831CK.L. V. Office of the Executive Director for Operations
                                                                                                                                                                  8004030026 Memorandum of understanding between NRC & FEMA re prompt
                                                                                                                                                                     improvement in radiological emergency planning & preparedness, distributed as Board notification (QCSICK,L V Office of the Executive Director for Operations (QC/O4/O2 34pp
                         34pp
    80/04/02
                                                                                                                                                                                           34pp
DOCKET STN-50-574 BAGNAC NUCLEAR POULR PROJECT
                                                                                                                                                                 DOCKET 50 500 BUNDESERT, UNIT 2
A Application/construction stage documents & correspondence
                                                                                                                                                                 C Adjudicatory correspondence
8004070148 Recommends issuance of license to export reactor & associated components to Philippines Proposed export would not be inimical to VB common defense & security No further action required on SECY-79-100
SHEA-J R Diffice of International Programs SECY-80-142 80/03/14
                                                                                                                                                                 8004030076 Hemaiandum of understanding between NRC & FEMA is prompt
                                                                                                                                                                      improvement in radiological emergency planning & preparedness, distributed as Board notification GOSBICK, V. Office of the Executive Director for Operations GO/04/02 34pp
--8004070180 Discusses deaths of two energy activists & physical security of proposed reactor Continued repression creates highly unstable environ "Mother Jones" Dec 1979 article re state of civil war in Philippines enci PERLAB.N Philippine Movement for Environmental Protection 80/01/27 13pp
                                                                                                                                                                 DUCKET 50-985 TRIGA MARK II
                                                                                                                                                                 A Application/construction stage documents & correspondence
                                                                                                                                                                 9004170360 Submits application to amend export license, changing contractual \hbar delivery dates, increasing reactor power level k increasing reactor costs Also applies for SNM
Q Adjudicatory correspondence
                                                                                                                                                                      license

HOWRY: W R General Atomic Co (subs of Gulf Dil Co ) 80/03/20
8004080607 Discusses judicial review on behalf of Ctr for Development
Policy & Movement for Free Philippines Urges delay of export
license issuance for seven working days after Commission
apinion; in order to avoid hasty litigation
ABHCR.T R Asher.T R PC 80/03/21 2pp
                                                                                                                                                                  DUCKET GTH-50 592 PALO VERDE NUCLEAR STATION, UNIT 4
                                                                                                                                                                  Q Adjudicatory correspondence
0004280036 Submits Westinghouse response to TR Asher 800321 ltr on behalf of Cir for Development Policy & Movement for Free Philippines Urges Commission to promptly grant applications renuclear reactor export to Philippines COMAN.8 Z., DAUGHERTY, T.M. Eckert, Beamans, Cherin & Hellott 80/03/27 App
```

8004180101 Motion to stay effectiveness of final order pending appeal & judicial raview as nuclear reactor export to Philippines Delay in shipment will not injure interests of exporter or parties Certificate of Svc encl

80HERR.S J Natural Resources Defense Council HEISBLE R Union of Concerned Scientists DUOHERTY.J Philippine Movement for Environmental Protection 800/04/03 6pp

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board motification QBBSICK.L V Office of the Executive Director for Operations

80/04/02

34pp

EMCKET STIL MU-SYR PALL "ERRE IMPLEME STATION, UNIT 5

5.04030026 Henorality or understanding between NRC & FEMA he prompt improvement in reducionical energency planning & preparedness distributed as Brand notification GOSSICH. ** Office or the Elecutive Director for Operations GO/SICH ** 34pc

DOCKET STN-50-596 NEW HAVEN UNIT 1

A Application/construction stage documents & correspondence

8004040021 Advises of issuance of FUREC-0588. "Interim Staff Position on Environ Gualification of Sarety-Related Electrical Equipment, providing juidance is nethods for compliance ROSS.D F Division of Project Management 80/02/05 7pp

G Adjudicatory correspondence

800403u026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Soard notification GOSSICK L V Office of the Executive Director for Operations 80/04/02 34pp

DOCKET STU-50 597 NEW HAVEN, UNIT 2

A Application/construction stage documents & correspondence

BO04040031 Advises of issuance of NUREC-0588, "Interim Staff Position on Environ Qualification of Eafety-Related Electrical Equipment," providing guidance remethods for compliance ROBS.D F Division of Project Management B0/02/05 7pp

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification ODSSICK.L V Office or the Executive Director for Operations 80/04/02 34pp

DOCKET 50-599 CARROLL FACILITY I

A Application/construction stage documents & correspondence

B004020177 Requests addl 45 days to submit responses to B00206 ltr re site suitability environ & sarety repts NAUGHTON, W.F. Commonwealth Edison Co. 80/03/28 1p

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification COSSICK.L V. Office or the Executive Director for Operations 80/04/02 34pp

DOCKET 50-600 CARROLL FACILITY 11

A Application/construction stage documents & correspondence

B004020177 Requests addl 45 days to submit responses to 800206 ltr re site suitability environ A safety repts MAUOHTON,W F Commonwealth Edison Co 80/03/28 ip

G Adjudicatory correspondence

8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board notification GOSSICKL V Office of the Elecutive Director for Operations

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

8004160002 Responds to 790906 & 20 ltrs requesting approved route
Alternate route plan proposed in 790920 ltr has been
approved Enc) data is airlangements & approved route withhold
(ref 100FR2 790)
MCCORKLE, 0 & Physical Security Licensing Branch 80/02/08 2pp

8004220059 Forwards IE Info Notice 80-14. "Safety Buggestions From Employees" No action required KEPPLER, J G Region 3. Chicago, Office of the Director 80/04/04 to

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

8004100093 Forwards IE Insp Rept /0-0025/79-06 on 790821-24 No noncompliance noted BOOK.HE Region 5, San Francisco, Fuel Facility & Materials Bafety Branch 79/10/02 2pp

--8004100096 IE Insp Rept 70-0025/79-06 on 790821-24 No noncompliants noted Major areas inspected facility changes & mods, safety committee activities, operations review, radiation protection & raduaste mgt 800K.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch COQUEY.H J Region 5, San Francisco, Office of the Director 79/10/01 9pp

8004020230 Forwards IE Insp Rept 70-0025/80-03 on 800211-13 No noncompliance noted Encl withheld (ref 10CFR2 790) NCRDERHAUO, L R Region S. San Francisco. Safeguards Dranch 80/03/10 2pp

8004100174 Forwards IE Insp Rept 70-0025/80-01 on 800107-11 & notice of violation Encls withheld (ref 100FR2 770) NORDERHAUG.L R Region 5, San Francisco, Bafeguards Branch 80/03/10 200

6004040457 Ack receipt of 600307 ltr informing NRC of steps taken to correct violations noted in 600215 notice of violation NGRDERHAUG, L R Region 5, San Francisco, Safeguards Branch, 807/03/12 to

8004220007 Forwards IE Info Notice 80-14, "Safety Suggestions From Employees" No action required SNOELKEN.R H Region 5, San Francisco, Office of the Director 80/04/02 lp

8004170278 Forwards IE Insp Rept 70-0025/80-8 on 800303-07 No noncompliance noted Encl withheld (ref 10CFR2 770) NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/04/03 2pp

DOCKET 70-0027 BADCOCK & WILCOX CO

8004070153 Application for amend to SNM-42 to provide for proposed revisions to plant liquid effluent lines re use of flow meters 2 proportional automatic samplers Diagram, specs & GORDANI,R A Dabcock & Wilcor Co , Naval Nuclear Fuel Div 80/01/18 7no

8004040130 Ack receipt of 800121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/79-15 STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Bafsty Branch 80/02/06 ip

--8004040137 Responds to NRC 791226 ltr re violations noted in IE Insp Rept 70-0027/79-15 Corrective actions sampling sys was cleaned & repaired Frequent monitoring will establish needed insp schedule EMINO, J.F. Babcock & Wilcox Co. 80/01/21 20p.

--8004040144 Forwards 1E Insp Rept 70-002//79-15 on 791126-30 & notice of violation SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/12/26 2pp

--8004040148 Notice of violation from insp on 791126-30 * Region 2. Atlanta, Office of the Director 79/12/21 Ip

- --8004040156 IE Insp Rept 70-0027/79-15 on 791126-30 Noncompliance noted improper sampling of incinerator stack 01850N-A F Region 2. Atlanta. Fuel Facility & Materials Safety Branch MILLGAP.W J Region 2. Atlanta. Office of the Director 79/12/21 7pp
- 8004140476 Ack receipt of fee & 800319 itr transmitting protection plan for SNM of moderate & low strategic significance Request classified in fee Category IA, LOCFRITO 31 Addl payment should be remitted Any overcharges will be refunded WEISS, D License Fee Management Branch 80/03/28 ip
- 8004210106 Revises safeguards Amend MPP-1 to License GNM-27 by granting extension until 800404 for completion of limit of error calculation for Jan-Feb 1780 matt balance period PARTLON J O Material Control Licensing Branch
- 8004240227 Forwards II info Notice 80 14. "Bafety Suggestions From Employees" No action required 0 TRILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/02 to

DOCKET 70-0033 TEXAS INSTRUMENTS: INC

- 8004100185 Ack receipt of 800218 itr informing NRC of steps taken to correct violations noted in IC Insp Rept 70-0033/79-13 Ltr will be withheld (ref 1007R2 790)
 MARTININ 0 Region 1. Philadelphia, Safeguards Branch 80/03/17 is
- --8004100189 Forwards IE Insp Rept 70 0033/79-13 on /91217-20 & notice of violation Notice of violation withheld (ref 10CFR2 /90)
 MARTIN N 0 Region 1, Philadelphia, Safeguards Branch 80/02/08
- --B004i00191 IC Insp Rept /0-0033//9-13 on 791217-20 Noncompliance noted BNM protection Details withheld (ref 10CFR2 790) DEVLIN.J W Region I, Philadelphia, Safeguards Branch BAILEY.R J Region I, Philadelphia, Office of the Director 80/02/07 ip.
- DOCKET 70-0047 NATIONAL AERONAUTICS & SPACE ADMINISTRATION
- 8004090122 Discusses IC Insp Repts 30-4938/80-01, 30-6929/80-01 to 70-0047/80-01 on 800110 Noncompliance noted MCCLINTOCK, R Q Region i. Philadelphia. Office of the Director 80/02/04 ip

DOCKET 70-0002 NUCLLAR HETALB, INC

- 8004040207 Documents NRC actions to retire docket file in response to Nuclear Metals, Inc 790408 & 0724 requeste re License SNN-65 Readings from 791125 tabular root showed radiation level below guidelines Docket should be retired DELANEY, J. C., CROW, W. T. Uranium Fuel Licensing Branch 80/02/15 in
- ---B0040402I3 Discusses Region I action re termination of License BNM-65
 IE Insp 70-0082/74-02 on 740731 & 0801 verified that
 licensee had zero inventory of highly enriched U AEC 770930
 ltr informed licensee of conditions for release
 CROCKER.H W Region i. Philadelphia, Fuel Facility & Materials
 Bafety Branch 79/12/03 ip

DOCKET 70-0078 TOLEDO, UNIV OF

- BO04020477 Forwards notice of violation from IE insp of Licenses 34-10247-06.BUD-B15 & SNN-915 on B00219-20 DAVIB:A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch B0/03/24 2pp
- --8004020492 Notice of violation from insp on 800219-20 Noncompliance noted food consumed in room & stored in refrigerator w/ radioactive isotopes no neutron survey meter available for monitoring & no leak test records available for 1978 * Region 3. Chicago. Office of the Director 80/03/24. 1p

- DOCKET 70-0135 BABCOCK & WILCOK CO
- 8004240028 Discusses B*N /00119 ltm me temporary measures to be taken during phase-out of high enriched U operations Nithdraws mediest for changes of ten specific pages moferenced in ltm Plan will be kept cument w/mormal processing WILLIAMS.R A Babcocy / Nilco Co , Nuclear Material Div 78/03/06 lp
- --8004240038 forwards addendum to ref plan for safeguarding residual SNM during cleanout of high enriched U facilities Addendum will make plan totally acceptable Addendum withheld WILLIAMS.R A Babcork / Wilcor Co / Nuclear Material Div 78/09/08 | 2pp
- ---8004240046 Forwards revised plan for safeguarding residual SNM during cleanout of enriched U facilities Addresses all areas agreed to at 760721 meeting w//RC flow diagram of scrap recovery processes attached Plan withheld WILLIAMS,R A. Babcock & Wilcox Co., Nuclear Material Div 78/08/18 2pp
- ~~8004P40056 Submits description of upcoming change to B&W math control & accounting program (nfo withheld (ref 10CFR2 /90) WILLIAMS, R A Babcock & Wilcox Co , Nuclear Material Div 77712/22 in
- -- 4004240073 forwards projection of expected LEMUF & LEMUF limits for Mar, May 2 Jul 1978 inventories of high enriched U plant in response to NRC request Demonstrates need for exception to required LEMUF limit W/o LEMUF projection NICLIAMS, R A Babcock & Wilcox Co , Nuclear Material Div 78/04/10 1p
- --8004240084 Updates NRC /70826 memo re B&W plans to terminate highly enriched V operations at facilites Outlines key points in B&W phase-out schedule Phase-out plan is generally acceptable Parts of schedule withheld (ref 100FR2 790) SMITH Office of Nuclear Material Safety & Sareguards 77/11/29 Gpp
- --8004240099 (valuates B&W rundamontal nuclear mati control plan & proposed changes Plan should be separated into two parts, one for Pu operations & one for low enriched U operations Some plant operations are not described. Into withheld THURMAN.D G. Material Control Licensing Branch. 79/07/30. 2pp
- ---8004240104 Notifies that NBW is not able to maintain sys of control required by code requirements for high enriched U plant Code requirements criteria re scrap recovery operation are no longer applicable Info withheld THURIAN D G Material Control Licensing Branch 78/09/15 2pp
- -8004240110 Discusses 760821-23 trip to 86W sites to discuss portions of measurement control plan 3 to clarify activities retermination of high enriched U operations at Apollo site Info withheld including partion of BIM. memorandum THURMAN.D 8 Material Control Licensing Branch 78/09/11 13pp
- --8004240127 Provides followup info to J Partiow 780104 notes re-possible strike No hostility exists between mgt & labor Inventory of SNM at facilities is being reduced to absolute min All processing operations will cease MCCORKLE.0 Physical Security Licensing Branch 79/01/05 2pp
- --8004240150 Notifies Commission of status of termination of high enriched U operations finly wot & dry scrap recovery at Apolio & cleanup/dismanling activites at Leschburg have not been shutdown Info withheld (ref 10CFR2 770) EMITH.C V Office of Nuclear Material Safety & Safeguards BECY-78-3R2 78/06/16 2pp
- --8004240195 Forwards preliminary amend fee & revised plan for safeguarding residual SNM during cleanout of enriched U facility Requests that 780626 safeguards plan be withdrawn W/o encis MILLIAMS.R A Babcock & Wilcox Co . Nuclear Material Div 78/08/18 ip

- --9004_40170 (increase of doministroning plans for facilities 96M will replace progressing distance of App I windeproprietary version All prodrietary dath changed to homproprietary form Add lines re-progressing dath relations and LEMB in factors of willow to a Noclear Material Div 78/05/17 Sec.
- 8004_101/7 be_chmistining plan Arp I Cost & Other Commercial Data "

 * Patcurk * Wilson Molear Material Div 78/02/17 16pp
- --8004840163 forwards Revision 4 to decommissioning plan Plans have been revised to reflect NAT comments during 780215 presentation DZICHIBZ, J.S. Babrock * Wilcox Co., Nuclear Material Div 78,52.17 tp
- --8004_40187 (recommissioning plan Revision 4 + Rabcock / Wilcor to Nuclear Material Div 78/02/15 9pp
- 8004220019 Forwards replacement page for conditions section of application for Amend 4 to License SIM-145, omitted from 791221 ltr Sarety e albation also enc)
 CROMON T Uranium Fuel Licensing Branch 79/12/28 2pp
- --B004220026 Sarety evaluation supporting administrative amend to License SNM-145 Continued operation or processing equipment should be beneficial 'violuable mathematics of processing ending for reuse rather than distarded as waste NIXON-W A Uranium Fuel Licensing Branch 79/12/21 ip
- 8004210081 Application to amend Licenses NM-145 % SNM-364 for redefinition of waste mati AUSTIN-M A Babcock % Wiltor Co : Nuclear Material Div 80/01/16
- ~B004210093 Requests fee for amend of Licenses SNM 145 & SNM-364 NEISS.D License Fee Management Branch 80/02/11 lp
- --8004210036 Forwards fee for amend of Licenses SNM 145 & SNM-364 AUSTIN:M A Babcock & Wilco: Co . Nuclear Material Div 80/02/19
- B004020067 "Safeguards Case Study of Nuclear Matls & Equipment Corp U Processing Plant/Apollo.PA (U)." App A ALTMAN, W. HOCKERT, J. GUINN.E. Division of Bafeguards NUREC-0627 APP A 80/01/31 130pp Available at MTIS
- 8004080197 "Safeguards Case Study of Nuclear Matls & Equipment Corp U Processing Plant.Appollu.PA ' ALTMAN.R', HOCKERT.J', QUINN.F. Division of Safeguards NUREG-0A27 80/01/31 12pp
- 8004080580 Forwards IE Insp Repts 70-0135/79-23 & 70-0364/79-29 on 791105-800104 No noncompliance noted Rept details withheld fref 1007R2 790! MARTIN.U G Region 1. Philadelphia, Safeguards Branch 60/02/04 2no
- --8004080733 1E Insp Rept 70-0135/79-23 t 79-0364/79-29 on 791105-800104 fio noncompliance noted Major areas inspected material control t accounting physical security health t industrial security Details withheld (ref 10CFR2 790) KUSHMER.W t. Region 1. Philadelphia. Office of the Director KUSHMER.W t. Region 1. Philadelphia. Safeguardt Branch 80/01/30
- 8004090280 Forwards IE Insp Rept 70-0135/79-26 bh 791217-21 No honcompliance noted Details withheld (ref 100FR2 790) MARTININ G Region 1. Philadelphia. Safeguards Branch 80/02/04 2pp
- --B004070285 IE Insp Rept 70-0135/79-26 on 791217-21 No noncompliance noted Major areas inspected low enriched U betaflouride receipts, storage, internal control, measurement & statistical controls Details withheld (ref 10CFR2 790) ZIBULSKY, H., SUMMERS, R., MARTIN, W. G., Region I., Philadelphia, Safeguards Branch 80/01/30 lp
- BOD4100550 Forward: IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 790904-28 No montemptiance noted Sections withheld (ref 100FR2 790) MARTIN.U 9 Region 1. Philadelphia. Safeguards Branch 80/02/05 20p
- --8004100555 IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 790904-28
 No noncompliance noted Major areas inspected mati control & accounting physical security, health & industrial safety Sections withheld fref 10CFR2 790)
 KUSHMER.W L Region 1. Philadelphia, Office of the Director JDYMER.J H Region 1. Philadelphia, Safeguards Branch 80/01/31 700

- 8004070211 Forwards IE Insp Repts 70-0135/80-02 & 70-0364/80-02 on 800115-18 No noncompliance noted MARTIN.U G Region 1. Philadelphia, Safeguards Branch 80/02/07 20n
- --B004070217 lE insp Rept: 70-0135/80-02 % 70-0344/80-02 on B00115-18
 No noncompliance noted Major areas inspected physical
 security, health % sarety % en/21ron programs
 SMITH-G L Region 1. Philadelphia, Office of the Director
 JONNER, J H Region 1, Philadelphia, Safeguards Branch B0/02/01
 4pp
- 8004240550 Forwards Amend 7 to License SNM-145 revising Bpecs I-4,re organization 3 i-5,on Tech Specs 3 control systeplacement pages for license 5 NRC safety evaluation supporting amend PAGE,R G Uranium Fuel Licensing Branch 80703705 ip
- --8004240554 Amend 7 to License SNM-145 revising Specs I-4, re organization & I-5, on Tech Specs & control sys Replacement pages for license encl PAGE.R G Uranium Fuel Licensing Branch 80/03/05 34pp
- 8004090393 Act receipt of 800225 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-27 & 70-0364/79-31 Response to be withheld (ref 10CFR2 790) MARTIN.N G Region 1. Philadelphia. Safeguards Branch 80/03/13 lp
- --8004090405 Forwards IE Insp Repts 70-0135/79-27 & 70-0364/79-31 on 791225-800104 & notice of violation Notice of violation withheld (ref 100FR2 790) MARTIN-W G Region 1, Philadelphia, Safeguards Branch 80/02/06 200
- --B004090419 IE Insp Repts 70-0135/79-27 & 70-0364/79-31 on 791226-B00104 Noncompliance noted failure to apply temper-safing devices to insure integrity of previously made measurements Details withheld (ref 10CFR2 790) JOYNER.J H Region 1, Philadelphia, Safeguards Branch BMITH, G C Region 1, Philadelphia, Office of the Director 80/01/31 1p
- 8004100197 Ack receipt of 800228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-15 & 70-0364/79-19 Ltr will be withheld (ref iOCFR2 790) MARTIN, N G Region 1, Philadelphia, Safeguards Branch 80/03/13 ip
- --8004100201 Forwards IE Insp Repts 70-0135/79-15 & 70-0364/79-19 on 790702-0803 & notice of violation MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/02/06
- --8094100204 Notice of violation from insp on 790702-0803
 * Region 1, Philadelphia, Office of the Director 80/01/30 1p
- --8004100209 IE Insp Repts 70~0135/79~15 % 70~0364/79~19 on 790702~0803

 Noncompliance noted various sources containing small amounts
 of source math. SNM % byproduct mail located in unauthorized
 areas Betails withheld (ref 100FR2 790)

 JOYNER, J H Region 1, Philadolphia, Safeguards Branch
 KUSHKER, W L Region 1, Philadelphia, Office of the Director
 80/01/30 1p
- 8004180026 Forwards proposed PA operations security plan for safeguarding GNM of low strategic significance W/o anci AUSTIN,N A Babcock & Wilcox Co GO/03/13 ip
- 8004080334 Ack receipt of 800222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-16 & 70-0364/79-20 Ltr withhold (ref 10CFR2 790) MARTIN.N G Region 1, Philadelphia, Safeguards Branch 80/03/14 fp
- --8004080343 Forwards [E Insp Repts 70-0135/79-16 & 70-0364/79-20 on 790806-31 & notice of violation MARTIN N G Region 1, Philadelphia, Safeguards Branch 80/02/14
- --80040B0346 Notice of violation from insp on 790B04~31
 * Region 1, Philadelphia, Office of the Director B0/01/31 ip
- --8004080354 IF Insp Regis 70-0135/79-16 % 70-0364/79-20 on 790806-31 Noncompliance noted Pu fuel pins transferred from math balance area to litem control area w/delayed completion of documents Portions withheld (ref 10CFR2 790) JOYNER, J H Region 1. Philadelphia, Safeguards Branch WUSHNER, W. Region 1, Philadelphia, Office of the Director 80/01/30

- 8004210203 Ack receipt of 800221 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0135/79-25 GRIER.8 H Region 1, Philadelphia, Office of the Director 80/03/19 19
- --8004210207 Responds to NRC 800120 ltr re violations noted in IE Insp Rept 70-0135/79-25 Corrective actions CPVC pipe was replaced w/borosificate raschig rings, drums have been labeled & documents posted AUSTIN.M A Babcock & Wilcox Co 80/02/21 3pp
- --8004210214 Forwards IE Insp Rept 70-0135/79-25 on 791127-30 & notice of violation SMITH.O H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/01/29 2pp
- --8004210216 Notice of violation from this on 791127-30
 * Region 1. Philadelphia. Office of the Director 80/01/28 2pp
- --8004210222 IE Insp Rept 70-0135/79-25 on 791127-30 Noncompliance noted failure to follow procedures re storage & labeling of SNM containers & to maintain chlorine content of CPVC pipes CROCKER, H H Region i. Philadelphia. Fuel Facility & Materials Gafety Branch ROTH, J Region i. Philadelphia. Office of the Director 80/01/28 lipp
- 8004290061 Advises that use of Hodel HA-10 will be discontinued & company will not renew Certificate of Compliance 4824 AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 80/03/25 to
- 8004160027 Notifies that Source Matls License SMB-502 is terminated Activities authorized under license were incorporated into Source Matls License SMM-145
 PAGE.R 0 Uranium Fuel Licensing Branch 80/03/27 ip

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.

- 8004220081 Informs that vendor will revise 770415 Fundamental Nuclear Control Plan Section 1 O.Revision 7.to include duties & responsibilities in Attachments I, II, III & IV Attachments withheld (ref 100FR2 770)
 HCNBLEY, KD Nuclear Fuel Services, Inc (subs of Getty Gil Co) 80/01/15 1p
- 8004300085 Forwards upgrading measurement sys change to fundamental nuclear mati control plan. Section 3. Revision 9 Change withheld (ref 10CFR2 790)
 HENGLEY, R D Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.)
 80/01/17 1p
- BOO4180482 Forwards supplemental info re IE Insp Rept 70-0143/79-40, Item C Revised corrective action health & safety procedure for contamination control.NFB-OH-1.Revision 1, will be revised by BOO131 re requirement for survey of hands. MANBER,W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) BO/01/23 2pp
- BOO41BO143 Responds to 1E lnsp Rept 70-0143/79-47 on BO0107 No proprietary info MANBER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) BO/01/24 ip
- 8004220133 Requests temporary amend to License SNM-124 to permit discharges to unlined ponds until 800831 Continuance required while storage facility is being designed & installed Administrative fee encl MCCHELC J Nuclear Fuel Services. Inc (subs of Getty Gil Co) 80/02/01 ip
- 8004040037 Ack receipt of 800125 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0143/79-46 KENNA.W B Region 2. Atlanta. Safeguards Branch 80/02/08 ip
- --8004040041 Responds to NRC 800104 ltr re violations noted in IE Insp Rept 70-0143/79-46 Corrective actions withheld (ref 10CFR2 790) MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 60/01/25.
- --8004040044 Forwards IE Insp Rept 70-0143/79-46 on 791126-30 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA, W B Region 2. Atlanta. Safeguards Branch 80/01/04 App

- --8004040047 IF Insp Rept "O 0143/77-46 on 791126-30 Noncompliance noted person not employed by licensee was improperly escorted in protected area Detail: withheld (ref 10CFR2 790) PERNY, C D. CHRISTOFFER, G. Region 2 Atlanta, Office of the Director TOBIN, N J. Region 2, Atlanta, Safeguards Branch 80/01/03
- 8004100538 Requests undertaking study of facility ½ fuel making process utilized to identify maff control ½ accountability improvements which could be implemented w/o degrading quality of product as followed to NRC 800121 order AMEARNE. J F Commission 80/02/20 2pp
- BO04070422 Forwards Revision 17 to physical protection plan Fees not applicable Revision withheld (rev 10CFR2 790) MICHEL(C J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) BO/02/25 ip
- 8004300003 Forwards "Erfluent Monitoring Rept." Jul-Dec 1979 MICHEL.C J. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) 80/02/26 | 1p
- --800430024 "Ffrluent Monitoring Pept," Jul-Dec 1979

 * Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/02/26
 ip
- 8004070046 Ack receipt or 800211 ltr informing NRC of steps taken to correct violations noted in IE (msp Ropt 70-0143/79-44 LONG,F J Region 2, Atlanta, Office of the Director 80/03/03 ip
- --B004070049 Responds to NRC 800123 ltr re violations in IE Insp Rept 70-0143/79-44 Corrective actions withheld (ref 10CFR2 790) MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/02/11 ip
- --8004070054 Forwards 1E Insp Rept 70-0143/79-44 on 790918-1130 & notice of violation Notice of violation withheld (ref 10CFR2,790)
 KENNA,W B Region 2, Atlanta, Safeguards Branch 80/01/23 2pp
- --8004070059 IE Insp Rept 70-0143/79-44 on 790918-1130 Noncompliance noted failure to measure all SNA at time of physical inventory & failure to maintain identity & quality records Details withheld (ref 10CFR2 790) OILLESPIE: F P Region 2. Atlanta. Safeguards Branch 80/01/23 10
- 8004140448 Provides Subcommitter on Nuclear Regulation U/response to 791101 inquiry re sareguards adequacy NRC insp plans for NFS Erwin investigation encl AHEARINE. J F Commission 80/03/05 33pp
- ----8004140469 Forwards questions re safeguards adequacy includes matl accounting sys.physical protection sys.? specific responses to facility inventory differences
 HART. 0 Senate, Environment? Public Works 79/11/01 7pp
- BOO4180213 Forwards supplemental info re operating criteria for U hexaflouride scrubber requested during D Joy BO0225 visit Details withheld (ref 10CFR2 770) HENGLEY,K D Nuclear Fuel Services, Inc. (subs. of Oetty Dil Co.) 80/03/11 1p
- 8004220219 Forwards request for amend to License SNM-124 Encl withheld (ref 10CFR2 790) Administrative amend fee also encl HENSLEY,K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/03/i1 1p
- 8004040113 Forwards IE Insp Rept 70-0143/80-02 on 800115-0207 No noncompliance nuted KENNA, W B Region 2, Atlanta, Safeguards Branch 80/03/12 2pp
- --8004040117 IE Insp Rept 70-0143/80-02 on 800113-0207 No noncompliance noted Major areas inspected facility organization & operation, mgt of matis control, storage & internal control Details withheld (ref 10CFR2 790)
 OILLEEPIE.F P Region 2. Atlanta, Safeguards Branch MODRE, D.E., CLAY, E.L. Region 2. Atlanta, Office of the Director 80/03/10
- 8004090232 Ack receipt of 800304 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 70-0143/79-36 & 70-0143/79-37 KENNAW B Region 2. Atlanta. Safeguards Branch 80/03/13 ip
- --B004090235 Responds to NRC 791005 ltr w/addl info re violations noted in IE Insp Repts 70-0143/79-36 & 70-0143/79-37 Corrective actions withheld (ref 10CFR2 790)
 MANSER.W C Nuclear Fue) Services, Inc (subs of Getty Oil Co)
 B0/03/04 1p

- COS43 Higher Passions to the Tricus life re-violations noted in IE Insp. Repts 10 (1427 16-35) in UNIVERSITY Corrective actions withheld intel 10-682 inc.
 HMNSER/R C. Histoar High Services Inc. (subs. of Getty Dil Co.) 78 (1675) 10
- C0040 C.40 Forwards IF Irap Pepts 70-0143/79-36 & 70-0143/79-37 on 750/710-11 ' notice or i latien Notice of violation uithheld (cer 10078/70)
 FRINAL B Region 2 Arlanta Safeguards Branch 79/10/05
 2pp
- 8004090244 If Insp Repris T0-0143/79-36 & 70-0143/79-37 on 790910-14
 Noncomplian a noted reliare to establish NDA procedures
 Details withfeld (ref lo:FR2 790)
 GILLESTEE F P CLArif L Region 2, Atlanta, Safeguards Branch
 79910/02 10
- GOO4070351 Notifies that venion B00222 submittal re operating criteria for U hesarloomide scrutown is acceptable. & that NRC is revising License Conditions 2 24 1-A. 2 24 5-A. 2 22 6-A 3 3 2 Encls withheld cref 100CR2 790)
 PARTLOW, J G Material Control Licensing Branch 80/03/14 2pp
- 8C04210352 FOIA request for all documents re facility from 800117 to date COCHRAN.I B. Matural Resources Defense Council 80/03/14 ip
- 8604100259 Notice or appearance in proceeding Certificate of Svc encl WEISS.E fi Matural Resources Derense Council WEISS.E R Sheldon. Marnon I Weiss 60/03/18 Zop
- BOG4070419 Responds to RNU311 request for exception from 10CFR70 5B(e) requirements re small U herafluoride receipt Notifies of issuance of license condition, effective immediately, to amend MPP-1 to License SNM-124 PARTLOW J.G. Material Control Licensing Branch B0/03/19 1p
- E-004080565 Advises that License SNM-124.Condition 49 is amended.per 800201 application Amend 4 limits use of lined ponds to discharges from waste water treatment facilities PAGE,R G Uranium Fuel Licensing Branch 80/03/19 ip
- ---B0D40B0570 Safety evaluation supporting Amend 4 to License SNM-124, Condition 47 limiting use of unlined ponds to discharges from waste water treatment facility DELANEY, J C Urenium Fuel Licensing Branch 80/03/19 2pp
- OO04090356 Forwards IE Insp. Rept 70-0143/80-03 on 800224-28 No noncompliance noted Datails withheld (ref 10CFR2 790) KENNA.H B Region 2. Atlanta, Safeguards Branch 00/03/19 ip
- -- 8004090361 IE Insp Rept 70-0143/80-03 on 800226-28 No noncompliance noted Major areas inspected organization, physical barriers, access controls, detection aids 5 festing Details withheld (ref 105R2 790)
 KEMNAN B Region 2, Atlanta, Sareguards Branch TOBINNU J
 Region 2, Atlanta, Diffice of the Director 80/03/19 ip
- EO04240153 Approves Amend 4 to License SNM-124 re continued use of unlined ponds for discharges from waste water treatment facility PAGE.R G Uranium Fuel Licensing Branch 80/03/19 ip
- #3004210198 Responds to NRC 800229 ltr by advising that no Model 6400 packages are cured to no shipment of package has been made since 780228 MICHEL C J. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) 80/03/21 ip
- EMO04240235 Forwards IE Info Notice 80-14. "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/02 19
- E3004210350 Partial response to FOIA request for all documents re facility Forwards documents listed in App A JF Aftearne draft itr to G Hart ant FELTON.J M Division of Rules and Records 80/04/07 13pp

- -8004210357 Afradavit of AJ Whittle re restart of facility operations in accordance w/NRC 500117 decision Facility restart is essential to natl detense WHITTLE:A J Navy.Dept of 80/01/18 3pp
- --8004210359 Arradavit of W Bateman or NFS Erwin plant shutdown Costs incurred by govt are accumulating at engineous rate as facility remains idle BATEMAN,W Energy, Dept of 80/01/18 2pp

DOCKET 70-0190 CATHOLIC UNIV

- 8004070089 Ack receipt of 800226 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 30-00639/80-01, 40-6329/80-01 & 70-0190/80-01 MCCLINTOCK, R O Region 1. Philadelphia, Office of the Director
- --B0040/0099 Responds to ARC B00204 ltr re violations noted in IE Insp Rept 30-00538/80-01, 40-6329/80-01 & 70-0190/80-01 Corrective actions separate eating space provided for dept of biology & technicians reinstructed re matls rules NUESBE.C J Catholic Univ 80/02/26 2pp
- --8004070104 Forwards IE Insp Repts 30-00638/80-01,40-6329/80-01 & 70-0190/80-01 on 800116 & notice of violation MCCLINTOCK,R O Region 1. Philadelphia, Office of the Director 80/02/04 200
- --8004070107 Notice of violation from insp on B00116 Noncompliance noted failure to instruct technicians working in lab on procedures for handling radioactive maths Failure to wear protective gloves 5 having food in restricted area * Region 1, Philadelphia, Office of the Director 80/02/04 ip
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO
- 8004240028 Discusses B&W 780119 ltr re temporary measures to be taken during phase-out of high enriched U operations Withdraws request for changes of ten specific pages referenced in ltr Plan will be kept current w/normal processing WILLIAMS, R A Babcock & Wilcox Co , Nuclear Material Div 78/03/06 to
- --B004240046 Forwards revised plan for safeguarding residual ANM during cleanout of enriched U facilities Addresses all areas agreed to at 780721 meeting w/NRC Flow diagram of strap recovery processes attached Plan withheld WILLIAMS:R A Babcock / Wilcox Co , Nuclear Material Div 78/08/18 2pp
- --8004240073 Forwards projection of expected LEMUF & LEMUF limits for Mar.May & Jul 1978 inventories of high enriched U plant, in response to ARC request Demonstrates need for exception to required LEMUF limit W/o LEMUF projection WILLIAMS.R A Babcock & Wilcox Co , Nuclear Material Div 78/04/10 1p
- --B004240084 Updates NRC 770826 memo re B&W plans to terminate highly enriched U operations at facilites Outlines key points in B&W phase-out schedule Phase-out plan is generally acceptable Parts of schedule withheld (ref 100FRZ 770) SMITH Office of Nuclear Material Safety & Safeguards 77/11/29
- --8004240075 Evaluates B&W fundamental nuclear matl control plan & proposed changes Plan should be separated into two parts; one for Pu operations & one for low enriched U operations Some plant operations are not described Info withheld THURMAN.D S Material Control Licensing Branch 79/07/30 2pp
- --8004240110 Discusses 780821-23 trip to B&W sites to discuss portions of measurement control plan & to clarify activities retermination of high enriched U operations at Apollo site Info withheld including portion of BNL memorandum THURMAN, D 8 Material Control Licensing Branth, 78/09/11 13pp
- --8004240114 Forwards notes re possible strike, in response to request In event of strike, NRC would have forwarded license condition to formalize provisions for strike period, H/o enc!

 MCCORKLE, Q W Physical Security Licensing Branch 79/01/15 ip
- --8004240127 Provides followup info to J Partiow 780104 notes re-possible strike No hostility exists between mgt & labor Inventory of SNM at faculaties is being reduced to absolute min All processing operations will cease MCCORKLE, G Physical Security Licensing Branch 79/01/05 2pp.

- --8004240137 Provides add1 info re possible strike All facilities will be shut down All accesible highly enriched U at facilities will be moved to Leechburg vault PARTLOW, J Material Control Licensing Branch 79/01/04 1p
- --8004240150 Notifies Commission of status of termination of high enriched U operations Only wet % dry scrap recovery at Apoilo & cleanup/dismantling activites at Leechburg have not been shutdown Info withheld (ref 10CFR2 790) SMITH.C V Office of Nuclear Material Safety & Safeguards SECY-78-322 78/06/16 2pp
- --8004240170 Discusses decommissioning plans for facilities B&W will replace proprietary version of App I w/nonproprietary version All proprietary data changed to nonproprietary form AddI info re proprietary classification encl
 LEWIS, J R Babcock & Wilcox Co , Nuclear Material Div 78/05/17
- --8004240177 Decommissioning plan App I, "Cost & Other Commercial Data "

 * Babcock & Wilcox Co , Nuclear Material Div 78/02/17 16pg
- --8004240183 Forwards Revision 4 to decommissioning plan Plans have been revised to reflect NRC comments during 780215 presentation DZIEMISZ, J S Babcock & Wilcox Co , Nuclear Material Div 78/02/17 p
- ---8004240187 Decommissioning plan.Revision 4
 * Babcock & Wilcox Co , Nuclear Material Div 78/02/15 9pp
- BO04140006 Summary of 780620 meeting w/NRC to acquaint latest group of NRC consultants w/Pu facility specifically ventilation sys & fire protection ARTHAN.K L. Babcock & Wilcox Co , Nuclear Material Div 78/06/21
- 80042100B1 Application to amend Licenses NM-145 & SNM-364 for redefinition of waste matl AUSTIN.M A Babcock & Wilcox Co., Nuclear Material Div 80/01/16 ip
- --8004210083 Requests fee for amend of Licenses SNM 145 & SNM-364 WEISB.D License Fee Management Branch 80/02/11 1p
- --8004210086 Forwards fee for amend of Licenses SNM 145 & SNM-364 AUSTIN-M A Babcock & Wilcox Co . Nuclear Material Div 80/02/19 ip
- 80040B05B0 Forwards IE Insp Repts 70-0135/79-23 & 70-0364/79-29 on 791105-B00104 No noncompliance noted Rept details withheld (ref 10CFR2 790)
 MARTIN.W Q Region 1. Philadelphia. Safeguards Branch 80/02/04 2pp
- --8004080733 IE Insp Rept 70-0135/79-23 & 79-0364/79-29 on 791105-800104
 No noncompliance noted Major areas inspected material
 control & accounting physical security, health & industrial
 security Details withheld (ref 10CFR2 790)
 KUSHNER.H. L. Region i, Philadelphia, Office of the Director
 KUSHNER.W L. Region i, Philadelphia, Safeguards Branch 80/01/30
 ip
- 8004080593 Forwards IE Insp Rept 70-0364/79-17 on 790709-0802 No noncompliance noted Rept details withheld (ref 10CFR2 790) MARTIN-W O Region 1, Philadelphia, Safeguards Branch 80/02/05 2pp
- --8004080899 IE Insp Rept 70-0364/79-17 on 790709-0802 No noncompliance noted Major areas inspected independent assessment of Parks Township Type II process facility U-235 holdup Details withheld (ref 10CFR2 790) SHAUB, E T , BISSETT, P H , JOYNER, J. H Region i, Philadelphia, Safeguards Branch 80/01/31 ip
- 8004100550 Forwards IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 790904-28 No noncompliance noted Sections withheld (ref 10CFR2 790)
 MARTIN.W G Region 1, Philadelphia. Safeguards Branch 80/02/05
- --B004100555 IE Insp Repts 70-0135/79-17 & 70-0364/79-25 on 790904-28
 No noncompliance noted Major areas inspected matl control & accounting, physical security, health & industrial safety
 Bections withheld (ref 10CR2 790)
 KUSHNER, W.L. Region 1. Philadelphia, Office of the Director JOYNER, J.H. Region 1. Philadelphia, Safeguards Brench 80/01/31 9pp

- 8004070211 Forwards IF Insp Repts 70-0135/80-02 & 70-0364/80-02 on 800115-18 No noncompliance noted MARTIN.N G Hegion 1. Philadelphia, Safeguards Branch 80/02/07 200
- --8004070217 IE Insp Repts 70-0135/80-02 \$ 70-0364/80-02 on 800115-18
 No noncompliance noted Major areas inspected physical
 security, health & safety / environ programs
 SMITH: G C Region 1. Philadelphia. Office of the Director
 JDYNER. J H Region 1. Philadelphia. Safeguards Branch 80/02/01
 4pp
- 8004270105 Application for amend of License SNM-414 to authorize storage of SNM-contaminated waste in designated locations Proposed Revision 1 to OL encl AUSTIN.M A Babcock & Wilcor Co . Nuclear Material Div 80/02/12
- B004100080 Forwards IE Insp Rept 70-0364/80-05 on 800124-25 No noncompliance noted MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/02/13 200
- ---8004100092 IE Insp Rept 70-0364/80-05 on 800124-25 No noncompliance noted Major areas inspected sampling of mixed oxide pellets & licensee labs
 JUNNER.J H. DELLA RATTA.A. ZIBULSKY.H Region 1, Philadelphia, Office of the Director 80/02/06 2pp
- BOO4180097 Forwards fundamental nuclear math control plan for License SNM-414 W/o encl (ref 100FR9 5 % 9 12) Plan does not decrease effectiveness of math control & accountability program AUSTIN.M A Babcock & Wilcox Co BO/02/25 ip
- 8004180533 Forwards supplemental info to application by B&W re storage of waste
 AUSTIN A Babcock & Wilcox Co 80/02/26 ip
- 8004070383 Ack receipt of 800205 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/79-30 BMITH.0 H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/27 ip
- ---B0040703B8 Responds to NRC B00114 ltr re violations noted in IE Insp Rept 70-0364/79-30 Corrective actions importance of wearing proper dosimptry re-emphasized & new survey procedures for box gloves begun AUSTIN.M A Babcock & Wilcox Co B0/02/05 3pp
- --8004070392 Forwards IE insp Rept 70-0364/79-30 o violation SMITH o H Region I, Philadelphia, Fuel Facilii Safety Branch 80/01/14 2c-

~~fi0

- 8004240550 Forwards Amend 7 to License SNM-145 revising Specs I-4, re organization & I-5, on Tech Specs & control sys, replacement pages for license & NRC safety evaluation supporting amend PAGE, R G Uranium Fuel Licensing Branch 80/03/06 Ip
- BOO4070373 Ack receipt of 800225 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-27 & 70-0364/79-31 Response to be withheld (ref 10CFR2 790) MARTIN, W G Region 1, Philadelphia, Safeguards Branch BO/03/13
- --B004090406 Forwards IE Insp Repts 70-0135/79-27 & 70-0364/79-31 on 791226-B00104 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN.W G Region i. Philadelphia, Safeguards Branch 80/02/06 2pp
- ---8004090419 IE Insp Repts 70-0135/79-27 & 70-0364/79-31 on 791226-800104 Noncompliance noted failure to apply tamper-safing devices to insure integrity of previously made measurements Details withheld (ref 10CFR2 790) JOYNER,J H Region I. Philadelphia, Safeguards Branch SMITH,O C Region I. Philadelphia, Office of the Director 80/01/31 1p

- 41. 10 Flanton in _ ... ill. incorning NSC of steps taken to come * i satilis come in IE less Repts 70 0195/79-15 & ... incl. come in It for 10:582 790) as 6477 1, ... incl. come incl. compared Branch 80/03/13
- 41) If carry IF In prepts C-u135/79-15 / 70-0364/79-19 on think if the exploitable resultable re
- 6:341C., A ** tick c+ inlation from insp on 790702-0803 * Region I Philatelphia Office of the Director EU B0/01/30
- The Journal of the Jo
- C 704050934 Ark receipt of Fru202 lth informing NRC of steps taken to correct visitation, moted in IE Imap Repts 70-0135/79-14 & 70-0244/72-60 Lth uithheld (ref 100FR2 /90)
 MARTIN N S Degion 1 Forlaselptia Bakeguards Branch 80/03/14
- - 800400343 Foruards IE Insp Repts 70-0135779-16 & 70-0364779-20 on 750804-31 i notice of violation MARTIN W # Region 1 Philadelphia, Sateguards Branch 80/02/14
- -- 5004CE0345 Nutice or violation from insp on 790806-31
 Region 1 Philadelphia Office of the Director 80/01/31 ip
- ~2004020354 JE Insp Repts 70-0135/79-16 & 70-0364/79-20 on 790806-31
 Nanco-plance noted Fu fuel pins transferred from matlibalance area to item control area w/delayed completion of documents Portions Lithheid (ref 10CFR2 790)
 UJAMER J H Region I Philadelphia Safeguards Branch
 KUSHLER W L Region 1. Philadelphia Office of the Director
 B0/01/30 10pp
- 四回4180034 Provides monthly status rept for Mar 1980 re Pu ventilation Upgrading All tack ordered matls received on site Several electrical equipment pieces checked for motor rotation を Control Function

 ARTHALI N L Dab-ock & Wilcoi Co Nuclear Material Div 80/03/14
- මට 04270061 Advises that use of Model HA-10 will be discontinued & normany will not renew verticate of Compliance 4824 Avistin n A Babcock / Wilcon Co Nuclear Material Div 80/03/25
- D D C MET 70-0371 UNITED NUCLEAR CORP
- 毎年 0.4150187 Forwards IE Insp Rept 70-0371/79-24 on 791218-21 No moncompliance noted
 MARTIN N G Region 1 Philadelphia Safeguards Branch 80/02/28 MARTIN H G
- ⊖:>○4070154 Responds to NRC 791114 ltr re reporting requirements for rol 5 accounting program Forwards revised Chapter .hheld (ref 100FR2 790) ; United Nuclear Corp .Naval Products Div 80/02/29

- BOD4210104 IE Insp Rept 70-03/1/80-02 on BO0115-17 No noncompliance noted Major areas inspected shipper-receiver differences, neasurements / statisfical controls, records & repts Details withheld (rer 10CFR2 /90) MARTIFLM G Region 1, Philadelphia, Safeguards Branch MOLODY, D J COMENT Region 1, Philadelphia, Office of the Director BO/02/21 ip
- 6004220025 Forwards IC Insp Rept 70-0371/80-02 on 800211-15 No noncompliance noted MARTIN,W G Region L. Philadelphia, Safeguards Branch 80/03/06
- --8004220041 IE Insp Reg! 70-0371/80-02 on 800211-15 No honcompliance 004220031 IE Insp Rep: 70-037/180-02 on 800211-19 No honcompii noted Majori areas inspected measurement control programs, records 5 repts Details withheld (ref 100FR2 790) JUYNER, J H , ZIBULSKY, H , UULTNER, E Region 1, Philadelphia, Safeguards Branch 80/03/03 ip
- 8004210063 Forwards pages of revised emergency plan KIRK,W F United Nuclear Corp ,Naval Products Div 80/03/14 1p
- -8004210057 Pages of revised emergency plan KIRK.W F United Nuclear Corp (Naval Products Div 80/03/14
- 8004270062 Advises that revised rundamental nuclear math control plan submitted w/600125 for should not be incorporated as condition of license until deficiencies listed in enci are corrected Encl withheld (ref 100FR2 770) PARTLOW, J G Material Control Licensing Branch 80/03/27 ip
- DOCKET 70-0398 COMMERCE, DEPT OF
- 8004070115 Forwards IE Insp Rept 70-0398/80-01 on 800114-18 No noncompliance noted Details withheld (ref 10CFR2 790) MARTIN.W G Region 1. Philadelphia, Safeguards Branch 80/0
- --8004070119 IE Insp Rept 70-0398/80-01 on 800116-18 No noncompliance noted Major areas inspected facility organization & operation, storage & internal control & physical inventory petails withheld (ref 10CFR2 790)
 SUMMERS, R Region i, Philadelphia, Office of the Director SHAURE, MARTIN, W G Region 1, Philadelphia, Hafeguards Branch 80/02/04 ip
- DOCKET 70-0572 MONSANTO RESEARCH CORP
- 8004080612 Requests fee for 800312 application for amend to License WEISS, J.D. License Fee Management Branch 80/03/19
- 8004220059 Forwards IE Info Notice 80-14, "Safety Suggestions from No action required
 Region 3, Chicago, Office of the Director 80/04/04 Employees " / KEPPLER,J Q
- DOCKET 70-0687 UNION CARBIDE CORP
- 8004180042 Application to amend License SNM-639 VOTH,И H Union Carbide Corp 79/12/28 17
- 8004020101 Advises that request for amend to License SNM-639, re U recovery from waste products has been additionally classified as requiring safeguards amend Addi amend fee will be required HEISS, J D License Foe Management Branch 80/03/17 19
- DOCKET 70-0496 GENERAL SERVICES ADMINISTRATION
- 8004180511 Notifies of expired matl/byproduct license Statement required explaining method of disposal of matls, matls involved & to whom matl was shipped within 5 days MCCLINTOCK, R D Region I. Philadelphia, Office of the Director 78/10/04
- DOCKET 70-0734 GENERAL ATOMIC CO
- B004220015 Forwards IE Info Notice 80-14, "Safety Suggestions From Enployees" No action required ENGELMENT H Region 5, San Francisco, Office of the Director 80/04/02 1p

- DUCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO
- 8004100423 "Effluent Monitoring & Environ Surveillance Programs Annual Summary, 1979 "
 BROZ, R E General Electric Co NEDD-24780 80/01/31 82pp
- 8004300505 Forwards SAR for GE spent fuel shipping cask Model 700.in support of Certificate of Compliance 5942 Drawings available in Central Files only BRUGGER.R M. Missouri, Univ. of: Columbia 80/03/20 2pp
- 8004030024 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness distributed as Board notification GOBSICKL V Office of the Executive Director for Operations 80/04/02 34pp
- B004220022 Forwards IE Info Notice B0-14, "Safety Buggestions From Employees" No action required ENGELKEN.R H Region 5, San Francisco: Office of the Director B0/04/02 ip

DOCKET 70-0820 UNITED NUCLEAR CORP

- 8004180392 Forwards revision to Section 5 4 of fundamental nuclear matl control plan
 OREGO,R J United Nuclear Corp , UNC Recovery Systems Div
 80/01/17 2pp
- 8004180046 Forwards corrected page of revision to Section 5 4 of fundamental nuclear matl control plan OREGO,R J United Nuclear Corp , UNC Recovery Systems Div 80/01/21 3pp
- 8004230533 Bubmits response to 800102 ltr concerning procedure used to satisfy License Condition / 8 is waste compaction sys Procedures for waste compaction currently being revised to require specific mode of operation DDWERS: C E United Nuclear Corp , UNC Recovery Systems Div 80/01/24 2pp
- 8004170321 Summary of 800129 meeting w/United Nuclear Corp in Silver Spring.Md re proposed amend to License SNM-777 to authorize mods in procedures for processing of process wastes including wastes stored in onsite lageons STEVENSON.R L Uranium Fuel Licensing Branch 80/02/12 BO/02/12 2pg
- 8004240160 Requests that deadline for full compliance w/approved emergency plan be extended to May 1780 Fee encl BOMERS.C E United Nuclear Corp., UNC Recovery Bystems Div 80/02/18 2pp
- 8004100026 Forwards IE Insp Rept 70-0820/80-01 on 800127-31 No noncompliance moted MARTIN N Q Region 1, Philadolphia, Safeguards Branch 80/02/19
- --8004100030 IE Insp Rept 70-0820/80-01 on 800129-31 No noncompliance DUALDOOD IN INSPIRED TO TOBER 2001 IN BUDIET OF MEMORITARIES NO REPORT TO THE PROPERTY OF THE
- BOO4220177 Requests NRC guidance re processing & decontamination of lagoons to release limits by 820701 per 790115 Amend 6. Condition 26 to License BNM-777 Unable to meet deadline Possible alternatives are beyond power of facility BOWERS.C E United Nuclear Corp., UNC Recovery Systems Div 80/02/19 ip
- 8004180020 Forwards modified Sections 5 12 & 6 1 of fundamental nuclear matl control plan clarifying that "book record" includes total facility & subsidiary matl control areas OREOG, R J United Nuclear Corp , UNC Recovery Systems Div 80/03/07 4pp
- 8004150300 Informs of issuance of Amend 12 to License 6NM-777 changing effective date for instituting emergency plan to 800501 PAGE,R.Q Uranium Fuel Licensing Branch 80/03/17 ip
- --8004150305 Bafety evaluation supporting Amend 12 to SNM-777 changing effective date for instituting emergency plan to 800501. STEVENSON, R. L., CROW, W.T. Uranium Fuel Licensing Branch 8003017 20: 80/03/17.

- 8004080072 Discusses deficiencies in mati control & accounting program * submits NRC position on appropriate corrective actions
 Insufficient sample control records exist to properly
 control amount of matl going to & coming from lab
 PARTLOW-J G Material Control Licensing Branch 80/03/ 80/03/19 3pp
- 8004150178 Advises that no response received to encl 800220 fee request for change of address for License SNM-777 Requests payment within 19 days W/o encl WEISS.D License Fee Management Branch 80/03/28 [p

DOCKET 70-0824 BABCOCK & WILLOUK CO

- 8004240236 Forwards replacement pages for License SNM-778 & replacement pages for renewal application re Dec 1978 request for Amend 11 to license Co 80/02/28 21pp
- 8004070065 Disapproves primary route for transport of spent reactor fuel & approves alternate route submitted w/791205 ltr Primary route passes through heavily populated areas & does not meet requirements Encl witcheld (ref 10CFR2 790) MCCORKLE.0 & Physical Security Licensing Branch B0/03/12 2p;
- 80041501B2 Ack receipt of 800320 ltr w/fee transmitting protection plan for SNM of low strategic significance Request classified as major safeguards amend for License SNM-778, requiring addl payment WEISS,D License Fee Management Branch 80/03/28
- 8004240229 Forwards IC Info Notice 80-14, "Safety Suggestions From Employees " No action required O'REILLY. J P Region 2, Atlanta, Office of the Director B0/04/02

DOCKET 70-0827 THE DEFIANCE COLLEGE

- 8004140009 Advises no response received to enci 800211 fee request for renewal of License SNM-758 Requests payment within 15 days W/o enci License Fee Management Branch 80/03/28 ip
- DOCKET 70-0925 CIMMARON FACILITY: KERR-MCGEE CORP
- 8004230138 Forwards IE Insp Repts 70-0925/80-01 & 70-1193/80-01 on 800204-07 & notice of violation DAVIS.A.B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/04 2pp
- ---8004230146 Notice of violation from insp on 800206-07
 * Region 3. Chicago, Office of the Director 80/0 80/02/28 ip
- --8004230157 IE Insp Repts 70-0925/80-01 & 70-1193/80-01 on 800206-07 Noncompliance noted possession of SNM w/enrichment greater than authorized by license FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch DUBRY, N E Region 3, Chicago, Office of the Director 80/02/28 9pp
- 8004110563 Advises that Ofc of Controller has been notified to initiate proceedings for refunding difference between fee paid & actual manpower expenditures for 790918 request to use facility for bench-scale coal liquefaction development BHELLY, U J License Fee Management Branch 80/03/28 to
- BOO4220070 Forwards IE Info Notice BO-14, "Safety Suggestions From Employees" No action required KEPPLER, J. Q. Region 3, Chicago, Office of the Director BO/04/04

DUCKET 70-0784 PACIFIC NORTHWEST LAB

8004180502 Forwards IE Info Notice 80-14. "Bafety Suggestions From Employees" No action required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80/04/02 1p

- CONST. 1 OF SHARE ELECTRIC CO.
- r 41 / 755 enrushas scalaration for Americ THB to Centificate of Tomplia enright for the 21 EU-7 Supporting documentation which test recent is when American Confident Energy Products Division 14 August 2017
- JA1' End Apply att n r r Relation 3 to Certificate of Compliance Full revising or nispers / authorized content
 Demand Electric of No lear Energy Products Div. 80/03/14
- FUR31: 1925 Application to amend License SYM-54 to authorize transport of Fit in Models (0-14 Pit 7 as described in Mod 23 to App D full+schi A N General Electric Co 74/05/24 10pp
- 174420 CV Furtards IF Info Notice 80-14, "Sarety Suggestions From Englises to action required ENSPIRED R Region 5 Can Francisco, Office of the Director ENGPARTS.
- 1 DOKET /S 1648 FLORIDA UNIO OF
- UC14200213 Informs PRC or upgrading or physical security requirements of this Changing location of ruel storage area will result in significant improvements Inquires whether license amend DIAI.N J Florita Univ of, Gainesville 80/03/03 1p
- COCKET 70-1059 PENNSTLVANIA COMMONWEALTH DE
- E0G4130183 Discusses IE Into Rept 70-1059/80-01 on 800213 No noncompliance noted Major areas inspected hadiation safety & compliance w/Commission rules & regulations MCCLINTOCK R O Region 1. Philadelphia, Office of the Director 87/00/20- 10 83/02/26
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC.
- EC34070105 Forwards IE Insp Rept 70-1100/79-12 on 791212-14 No emin G H Region 1. Philadelphia, Fuel Facility & Materials Safety

 Branch 80/02/07 2pp
- -- ##
- 8304070203 Forwards IE Insp Rept 70-1300/79-13 on 791211-13 No noncompliance noted Details withheld (ref 100FR2 790) MARTIN N G Region I Philadelphia, Safeguards Branch 80/02/07
- BOO4020153 Bafety evaluation re C-E 791221 application for limitation of mar enrichment of U to less than 207 U-235 C-E is presently authorized to possess U-235 of any enrichment Recommends issuance of license amend METZLACH.N. CRUM.N.Y. Uransum Fuel Licensing Branch BO/02/25
- BOO4240169 Requests that sampling data be used to set higher quarterly action L reporting level of JuC: which will allow operation of fuel fabrication facility under normal conditions & Lichtenan ALARA program Withdraws hearing request LICHTENPERGER C-E Power Systems 80/02/28 ip
- BOO42:0027 Forwards Haste Packaging Insp Rept 79-07A on 79:2:2-13 No noncompliance noted BMITH 6 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch BO/03/05 1p

- --8004210034 Waste Packaging Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected shipping paper & placanding requirements, radiation levels, removable contamination & package external feature requirements
 POTTER.J P. PEER.W. W., MODDRUFF.R & Region I, Philadelphia, Fuel Faculity & Materials Safety Branch 80/01/10 74p
- 8004210126 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 70-1100/79-09 SKITH-Q Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/03/18 ip
- --B004210130 Responds to NRC 800214 ltr re violations noted in 1E Insp. Rept 70-1100/79-09 Corrective actions signs replaced & personnel reminded of importance of keeping all work stations posted w/clear & legible signs LICHTEKIBERGER.H C-E Power Bystems 80/03/03 2pp
- --8004210133 Forwards Page 3 of App A to 791113 ltr rp 1E Insp Rept 70-1100/79-09 Requests written statement in reply to 1tem E within 20 days SMITH, G R Region I, Philadelphia, Fuel Facility & Platerials Safety Branch 80/02/14 2pp
- --8004210135 Acr receipt of 771205 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1100/19-09 SMITH, 6 H Region 1, Philadelphia, Fuel Facility & Ifaterials Safety Branch 80/02/01 lp
- --G09421013B Responds to NRC 791113 itr re violations noted in 1E insp.
 Rept 70-1100/79-09 Corrective actions formal procedure
 written for knockdown operation including safety limits &
 controls necessary to assure protection
 LICHTENDERGER.H. C-E Power Bystems 79/12/05 3pp
- --8004210139 Forwards IE Insp Rept 70-1100/79-09 on 791009-12 & notice of violation SMITH G H Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 79/11/13 2pp
- ~-80042:0143 Notice of violation from insp on 791009-12 * Region 1, Philadelphia, Office of the Director 79/11/09 3pp
- ~-8004210145 IE than Pent 70-1100/79-09 on 791009-12 Noncompliance noted the dedequate or improper posting of work station; failure to keep stored rod bux covered when not attended & failure to supply procedures
 ROTH.J Region I. Philadelphia. Office of the Director
 ROTH.J Region i. Philadelphia. Fuel Facility & Materials
 Safety Branch 79/11/09 16pp
- DOCKET 70-1113 GENERAL ELECTRIC CO
- 8004150058 Forwards notice of teccipt of applications & intent to prepare environ assessments re amends of License 8NM-1077 PAGE.R G Uranium Fuel Licensing Branch 80/02/13 ip.
- ~-8004150068 Notice of receipt of applications & intent to prepare environ assessments re amends of License SNM-1097 PAGE, R.O. Uranium Fuel Licensing Branch 80/02/13, 3pp
- 8004230163 Discusses concern raised during 800121-25 inap re-presence of area manager qualification requirements in Section 4.1 of license App A Qualifications are difficult to interpret this propose changes to manager qualifications.

 **KAPLAN.A.L. General Electric Co., Nuclear Energy Products Div 80/00/25 2pp
- 8004180121 Forwards "Semiannual Effluent Rept for Jul-Dec 1979 " KAPLAN.A L General Electric Co , Nuclear Energy Products Div 80/02/29 jp
- --8004180124 "Semiannual Effluent Rept for Jul-Dec 1979 "
 KARLAN, A L General Electric Co., Nuclear Energy Products Div.
- 8004140075 Recommends approval of GE 800117 Application for muthority to obtain 5 use up to 1 g U exide containing U enriched up to 93% in U-235, in form of NBS std ref mat1
 STEVENSON R L Uranium Recovery Licensing Branch 80/03/05 2pp
- BOO4150289 Informs of issuance of Amend IR to License BNM-1079 adding Conditions 6 F.7 F k B F PAGE.R G Uranium Fuel Licensing Branch 80/03/05 1p

- 8004070149 Requests Amend S-18 of License SNM-1097 authorizing GE to retain certain scrap matis in excess of one yr period, through 800509 Attached details withheld (ref 10CFR2 790) through Call Fee encl KAPLAN, A L G CAPLON OF RPP General Electric Co , Nuclear Energy Products Div
- 8004100593 Bubmits contract costs incurred & man-h used in reviewing 800117 application for amend of License SNM-1097 BTEVENSON,R L . PAGE,R Q Uranium Fuel Licensing Branch 80/03/12
- BOO4100095 Informs vendor of fee overpayment re Amend 12 to SNM-1097 Refund will be forwarded MILLER, W.O. License Fee Management Branch 80/03/25 ip
- 8004210195 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/80-01 KENNA.H B Region 2, Atlanta. Safeguards Branch 80/03/28 ip
- ---8004210162 Responds to NRC B00203 ltr re violations noted in IE Insp.
 Rept 70-1113/80-01 Corrective actions operators & foremen
 responsible for transporting storing & using U hexafluoride
 culinders reinstricted in handling procedures
 KAPLAN,A L. General Electric Co. 80/02/29 3pp
- --8004210167 Forwards IE Insp Rept 70-1113/80-01 on 800121-25 & motice of KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/02/05 2pp
- --8004210171 Notice of violation from insp on 800121-25 * Region 2, Atlanta, Office of the Director 80/0 80/02/05 1p
- -8004210176 IE Insp Rept 70-1113/80-01 on 800121-25 Noncompliance noted ten 2 5 ton U hexafluoride cylinders discovered lying in driveway adjacent to raised dock Five cylinders were full-wino valve protectors installed KA
- 8004240233 Forwards IE Info Notice 80-14. "Gafety Buggestions From Employees" No action required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/04/02

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

- 8004220054 Forwards IE Insp Rept 70-1143/79-09 on 790518 No noncompliance noted MARTIN,W G Region i, Philadelphia, Safeguards Branck 79/11/14
- --B00422006B IE Insp Rept 70-1143//9-09 on 790518 No noncompliance noted Major areas inspected licenses plans for coping w/strikes Details withheld (ref 10CFR2 790) JUYNER, J H. KYBINER, W L. Region 1, Philadelphia, Sefeguards Branch 79/11/07, 1p
- 8004R10084 Forwards IC Insp Rept 70-1143/80-02 on 800204-05 No compliance noted TH, G H Region i. Philadelphia, Fuel Facility & Materials Safety nch 80/02/28 2pp
- -8004210089 IE Insp Rept 70-1143/80-02 on 800204-08 No noncompliance noted Major areas inspected exposure info, survey data: chronology events & regulatory requirements CRUCKER, H W Region I, Philadelphia, Fuel Facility & Materials Safety Branch CLEMON.P. Region I, Philadelphia, Office of the Director 80/02/25 5pp
- 8004220379 Forwards Waste Packaging Insp Rept 79-07A No noncompliance noted. BMITH.O H notes. BMITH,O H Region I, Philadelphia, Fuel Facility & Materials Safety Branch. 80/03/05 2pp
- --B004220402 Waste Packaging Insp Rept 79-07A on 791212-13 No noncompliance noted Major areas inspected review of shipping papers radiation survey of vehicles contamination surveys & radiation level surveys of eackages POTTER.J P. PERRY.W W. WOODRUFF.R L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch B0/01/18 7pp
- B004030006 Forwards feeder rept for Region 5 coverage of transportation insp of BBNM from Westinghouse, Cheswich, PA to Exxon Nuclear Go.Richland WA: 800217-21, W/o enci Region 5, San Francisco, Safeguards Branch NORDERHAUG, L R 80/03/11 1p.

- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP
- 8004040080 Forwards IF Insp Rept 70-1151/80-02 on 800124-25 & notice Region 2, Atlanta, Sareguards Branch 80/02/08 200
- --8004040093 Notice of violation from insp on 800124-25 * Region 2. Atlanta. Office of the Director 80/0 80/02/0B 1n
- ~-8004040097 IE insp Rept 70-1151 on 800124-25 Noncompliance noted low level radioactive mat) shipped in improperly sealed oackages packages CORYELL,G P Region 2, Atlanta, Office of the Director KAHLE,J B Region 2, Atlanta, Safeguards Branch 80/02/08
- 8004080049 Submits rept re release or radionuclides to unrestricted areas Jui-Dec 1979 Gaseous results were obtained from point source analysis of stack gas effluent Liquid values were obtained by compositing proportional sample GOODWIN, W.L. Westinghouse Electric Corp. 80/02/14 2pp
- BOO4020090 Ack receipt of BOO129 ltr re const & use of bldg & equipment for water detonization Environ impact of proposed action is covered by existing environ rept Amend to License SNM-1107 not required CROW,WT Uranium Fuel Licensing Branch B0/03/07 is
- 8004160104 Responds to 800129 itr re const 2 use of bldg & equipment for water desonization Environ impact of proposed action, which does not involve radioactive mat) is covered under aristing environ rept License amend unnecessary CROW, W T Uranium Fuel Licensing Branch 80/03/07 ip
- 8004110015 Ack receipt of IE Insp Rept 70-1151/80-03 on 800204-08 Expresses appreciation for radiation protection program COODWIN. U. L. Westinghouse Electric Corp. 80/03/12 1p
- --B004110018 Forwards IE Insp Rept 70-1151/80-03 on 800204-08 STOHR J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/02/26 2pp
- --8004110027 IE Insp 70-1151/80-03 on 800204-08 No noncompliance noted Major areas inspected radiation protection instrumentation, external & internal exposure control, posting & labeling notifications & repts & installation of new ventilation sys TROUP, O. L. Region 2, Atlanta, Office of the Director GIBSON, A F. Region 2. Atlanta, Fuel Facility & Materials Safety Granch 80/02/25 App
- 8004100456 Ack receipt of 800306 ltr informing NRC of steps taken to correct violation noted in 1E Insp Rept 70-1151/80-01 Awaiting rept on inventory difference KENNA,W B Region 2. Atlanta. Office of the Director 80/03/14
- --B004100463 Responds to NRC 800213 ltr re violation noted in IE Insp Rept 70-1151/80-01 Corrective actions withheld (ref 10CFR2 770) D'AMORE,M , GOODWIN,W L Westinghouse Electric Corp 80/03/06
- --8004100470 Forwards IE Insp Rept 70-1151/80-01 on 800114-18 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA,N B Region 2, Atlanta, Safeguards Branch 80/02/13 2pp
- --8004100482 IE Insp Rept /0-1151/80-01 on 800114-18 Noncompliance noted incorrect calculation re limit of error associated w/inventory difference Details withheld (ref 10CFR2 790) GILLESPIE, F P Region 2, Atlanta, Safeguards Branch JONES, D W Region 2, Atlanta, Office of the Director 80/02/13 tp
- 8004240237 Forwards IE Info Notics 80-14, "Safety Suggestions From Employees" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/02
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP
- 800423013B Forwards IE Insp Repts 70-0925/80-01 & 70-1193/80-01 on B00204-07 & notice of violation DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/04 2pp
- ---8004230144 Notice of violation from insp on 800206-07

 * Region 3. Chicago, Office of the Director 80/0 80/02/2B 1p

-50042 julby lit last Map+s 70-0 (25/50-01 % 70-1193/80-0) on 800204-07 UNGLINED, I and Maps 2040/25-30-01 5 June 14-3/20-01 of 200200-0 honcopyline, ender possession of SIM Wemrichment greater than authorizes by license Fighth it Region 3 hickory Fuel Facility & Materials Safety Bran h DUDR: I'f Fogion 3 Chicago, Office of the Director 83/02/20 7pp 2004220073 Forwards IE Inno Notice 80-14 - Sarety Suggestions From Engloyees - No action required AEPPLER, J.G. - Region 3, Philago - Office of the Director - 80/04/04 ECCKET 70-1201 OF & CONVERSION FACILITY, BABCOCK & WILCOX CO 8004240CF8 Discusses SFW 780115 ltm re temporary measures to be taken during phase-out or high enriched U operations Withdraus request for changes of ten Specific pages referenced in ltm Plan will be kept current w/normal processing WILLIAMS F A Babcock & Wilson Co , Nuclear Material Div 78/03/06 --8004240170 Discusses de comissioning plans for facilities BAW uill replace proprietary vortion of App I w/nonproprietary version All proprietary data changed to nonproprietary form Addl into re-proprietary classification encl LEWIS, J.R. Babcock & Wilco, Co., Nuclear Material Div. 78/05/17 - 8004240177 Decommissioning plan App I. "Cost & Other Commercial Data "
Babcock & Wilcox Co., Nuclear Material Div. 78/02/17 16pp --8004240183 Forwards Revision 4 to decommissioning plan Plans have been revised to reflect NRC comments during 780215 presentation DZ[ERISI J S | Babcock & Wilcox Co , Nuclear Materia] Div 78/02/17 | [p --8004240187 Decommissioning plan.Revision 4 • Babcock & Wilcor Co., Muclear Material Div. 78/02/15 9pp 8004010157 Amend Application 79-3 for License SNM-1168 Revision index & revised license pages encl ZEFF,D W Babcock & Wilcox Co 80/01/09 35pp 8004220169 Requests extension of due date for booking SNM physical inventory results Added load at analytical lab caused delay Preliminary results indicate difference within regulatory limity ZEFF.D W Babrock & Wilcon Co 80/02/05 1p 6004096296 Forwards IF Insp Hept 70-1201,80-01 on 800114-18 No noncompliance noted
STOHR J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 80/02/21 2pp --8004090302 IE Insp Rept 70-1201/80-01 on 800114-18 No noncompliance noted Major areas inspected radioactive airborne effluents, liquid effluents, procedures, lab instruments & effluent rects CIBSON.A F Region 2. Atlanta Fuel Facility & Materials Safety Branch MILLSAP.W.J. Region 2. Atlanta. Office of the Director BO/02/15 | IPP 8004280237 Forwards "Effluent Monitoring Results, Jul-Dec 1979" ZEFF, D W Babcock & Hilcox Co , Naval Nuclear Fuel Div 80/ 80/02/28 --B004280243 "Effluent Monstoring Results, Jul-Dec 1979 "
ZEFF, D. W. Babcock & Wilcor Co. Naval Nuclear Fuel Div 80/02/28 8004040012 Act receipt of 800307 ltr informing NRC of steps taken to correct violations nated in iE Insp Rept 70-1201/80-02 KENNA,W B Region 2. Atlanta, Safeguards Branch 80/03/13 1p

--8004040015 Responds to ARC 800225 ltr re violations noted in lE Insp Rept 70-1201/80-02 Corrective actions withheld (ref 10CFR2 790) ZEFF, D.W. Babtock & Wilcox Co. 80/03/07 1p

~-8004040018 Forwards IE Insp Rept 70-1201/80-02 on 800109-11 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA, W B Region 2, Atlanta, Safeguards Branch 80/02/25 2pp

```
~8004040021 IF Insp Rept 70-1201/B0-02 on 800109-11 Noncompliance noted fatlute to maintain procedures for tamper-safing Details withheld (ref 10CFR2 /90)
GILLESPIE,FP Region 2. Atlanta, Safeguards Branch JONES,D W , TODD,Q A Region 2. Atlanta, Office of the Director H0/02/25
    8004240231 Forwards If Info Natice 80-14, "Safety Suggestions From
Employees" No action required
O'RFILLY, J P Region 2, Atlanta, Office of the Director 80/04/02
    8004290048 Re-ponds to 800401 telecopy requesting exemption from requirement of completing Form NRC-741 for transfer of empty U oxide gooder cans Request granted * license amended Telecopy contains info of type specified in 10CFR2 790 PARTLOW, J G Material Control & Accountability Development Branch 80/04/02 1p
    DOCKET 70~1222 HISSOURI, UNIV OF
   8004300505 Forwards SAR for GE spent ruel shipping cask Model 700, in
support of Certificate of Compliance 5942 Drawings
available in Central Files only
BRUGGER,R M Missourl. Univ of, Columbia 80/03/20 Epp
    DOCKET 70~1227 ERIE MINING CO
   8004180072 Forwards revised responses to Question 8 of communts & questions, re License Amend Application 18 raised in NRC 800124 1tr ESTEY.H P Exxon Nuclear Co . Inc (subs of Exxon Corp ) 80/03/12 14pp
   DOCKET 70~1251 ALBRIGHT COLLEGE
   8004160098 Ack receipt of 800313 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 70-1251/40-01 CRCCKER.H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/24 lp
  --8004140151 Responds to NRC 800227 ltr re violations noted in 1E Insp
Rept 70-1251/80-01 Disputes noncompliance Supportive
           dacumentation enci
KREMSER. TR Albright College 80/03/13 8pp
   --8004160156 Discusses If Insp Rept 70-1251/80-01 & forwards notice of
           MCCLINIOCK, R O Region 1. Philadelphia, Office of the Director
80/02/27 2pp
  --8004160159 Notice of violation from insp on 800220 Noncompliance noted records of leak tests conducted on Pu-beryllium neutron sources were not available for insp
# Region 1. Philadelphia. Office of the Director 80/02/27 ip
  DOCKET 70-1257 MIXED OXIDE PABRICATION PLANT, EXXON NUCLEAR CO , INC
 BOO4150115 Advises of issuance of Amend 21 to License BNM-1227 re
temporary increase in Pu possession limit
CROM, W T Uranium Fuel Licensing Branch 79/12/10 ip
  --8004i50iiB Safety evaluation re 79i022 amend application for License
SNM-1227, temporarily increasing Pu possession limit
Recommends approval No EIA, negative doclaration or environ
annual hadron
          appraisal needed
eRClub I T , STEVENSON,R L Urantum Fuel Licensing Branch
79/12/10 2pp
9004090370 Forwards response to 800124 comments & questions raised by NRC on License Amend Application 18
ESTEY, H P Exxon Nuclear Co , Inc (subs of Exxon Corp )
B0/02/21 11pp
--8004070378 Proposed Amend 18 to Licenso BNM-1227 Sections I-5, 2 2 4 & II-4 & I3 re concentration control
* Exton Nuclear Co , Inc (subs of Exton Corp ) 77/12/19 App
8004140458 Forwards response to NRC 791208 ltr re questions raised about renewal of License SNM-1227 Respective pages of entl application have been amended 8 several new organization changes incorporated ESTEY.H P Exxon Nuclear Co , Inc (subs of Exxon Corp.) 80/02/22 50pp
```

- --8004140464 Revised application for amend of License SNM-1227 incorporating organization changes Replaces Apr 1979 version in entirity

 **Exxon Nuclear Co. Inc. (subs. of Exxon Corp.) 79/04/30 250pp
- 8004020238 Forwards IE Insp Rept 70-1257/80-03 on 800221-24 No noncompliance noted Encl withheld (ref 10CFR2 790) NORDERMAUD, L R Region 5, San Francisco, Safeguards Branch 80/03/10 200
- 8004030006 Forwards feeder rept for Region 5 coverage of transportation insp of SSRM from Westinghouse Cheswich.PA to Exxon Nuclear Co.,Richland WA. 800219-21 W/o encl Region 5. San Francisco, Safequards Branch NORDERHAUG, L R
- 8004100066 Forwards Endorsement 19 to MAELU Policy MF-94 for License SNM-1227 NILSON,R Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/03/11
- 8004090102 Forwards corrections to Revision 1 renewal application for License SNM-1227 Site plan Figure D-3-2 & Attachment P updated ESTEY.H P Exxon Nuclear Co , Inc (subs of Exxon Corp) B0/03/13 1c
- ---8004090108 Corrections to Revision 1 of renewal application for License 8NM-1227 Corrections include editorial changes, addition of scale to site plan Figure D-3-2 & incorporation of add1 ref info Attachment P
 - Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/03/13 6pp
- --8004090112 Submits update of descriptive info for Horn Rapids fuel fabrication plant Includes info re ofc bldg complex addition, new process chemical waste storage lagoon & maint facility Diagrams onel # Exxon Nuclear Co . Inc (subs of Exxon Corp) 79/11/12 Spp
- 8004080609 Advises that 791119 request for amend to authorize operation of three add1 facilities has been add1thonally classified as safeguards amend & requires add1 fee WEISS.J D License Fee Management Branch 80/03/19 ip
- 8004180443 Forwards IE Insp Rept 70-1257/80-02 on 800127-31 & notice of violation Notice of violation withheld (ref 10CFR2 770) NORDERHAUGL R Region 5, San Francisco, Safeguards Branch 80/03/19
- 8004100073 Forwards Endorsement 43 to NELIA Policy NF-193 for License SNM-1227 NILSON,R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 80/03/20
- 6004100105 Advises that License Condition 2 7 2 has been added to Amend MPP-2 to License SNM-1227,per 600303 request for exemption re requirements to perform receivers measurement on some fuel rods Util 1 tr to be withheld (ref 10CFR2 790) PARTLUM, J 0 Material Control Licensing Branch 80/03/24 ip
- 6004110540 Advises that Ofc of Controller has been notified to refund difference between fee paid for 791108 & 14 applications for amend to License SNN-1227 & actual review fee based on manpower expenditures

 MillER.W O License Fee Management Branch 80/03/28 1p
- 8004160019 Notifies that Div of Fuel Cycle & Matl Bafety has been authorized to complete review of new operations prior to startup Includes laundry facility, waste U recovery facility & addl conversion capacity PARTLOW, J O Material Control Licensing Branch 80/03/31 ip
- 8004220013 Forwards IE Info Notice 80-14. "Safety Suggestions From s "No action required IR.H. Region 5, San Francisco, Office of the Director Ip Employers " N ENGELKEN, R, H
- DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO
- 8004240247 Application for amend of Hatl/Byproduct License SNM-1245, authorizing deletion of references to Series A revisions of NEDD-21324 & substitution of references to Series C revisions.
 DAWBON, D.M. General Electric Co. 80/01/23 3pp
- --R004240277 Forwards fee for amend of License SNM-1268 DAWBON, D. M. General Electric Co. 80/03/12 1p

- --8004240488 Ack receipt of E.GO13 | ltr re ree for amend to License SMX-1265 Requests minor safety 2 environ amend fee Forwards NEDO-21326 Vols (2.2 "Consolidated SAR" WEISS: D. License Fee Hanagement Branch 80/03/04 | Ip
- --8004240274 "Consolidated SAR" Vols 1 t 2 * General Electric Co NEDO-21924 80/01/31 11pp
- 6004(50129 Opposes choice of Moiris. IL as dumping site for nuclear waste Suggests that waste disposal be part of nuclear plant JAA. H Affiliation Unknown 80/02/20 2pp
- B004180133 Submits info confirming 800219 telcon LI/J Kesman Describes rail attachment for cash crane & attachment for basin crane DAMSON.D M General Electric Co., Nuclear Energy Products Div 80/02/27 2pp
- 8004140078 Forwards GE 800227 ltm re info for ORNL re crane details RODNEY, M A. Mayer, Brown & Platt 80/03/03 lp
- --8004140082 Confirms info futnished to ORNL re crane details Cask crane rail is US Steel 1354 rail & is in contact winnerted 18-inch steel channel Busin crane tail is 404 rail & is clipped to top of contrete wall w/steel rail base clips

 DAVSDH, D M General Electric Co , Nuclear Energy Products Div 80/02/27 4pp
- 8004090040 Ack receipt of 791219 ltr re changes to physical security plan Changes acceptable Encl to ltr withheld tref 100FR2 790) MCCORKLE.G W Physical Security Licensing Branch 80/03/07 1p
- 8004080679 Requests addition of EJ Guigley to see list GUIGLEY, E.J. Affiliation Unknown 80/03/12 ip
- 8004140060 Forwards GL 800311 / 12 lfrs re NEDM-20682, "Sabotage Analysis for Fuel Storage at Moiris," 5 amend fee ROONEY M A Hayer, Brown & Platt 80/03/17 lp
- --8004140070 Forwards reprint of NEDM-20482. "Sabotage Analysis for Fuel Storage at Morris." in response to NRC request Reprint contains errata previously submitted as separate documents on 741217 W/o encl ROGERS.H A General Flectic Co., Nuclear Energy Products Div ROGERS, H A C. 80/03/11 2pp
- --B004140073 Forwards GC Check B66981 to be applied to amend of Matls License SNM-1245 as requested in GF 800123 ltr Ack receipt of GE Check 858932 U/o encl DANSON.D M General Flectric Co., Nuclear Fnergy Products Div 80/03/12 2pp

33

Ε

- BOO421014** Second set in ancilons unges ASLB to vacate BOD225 rulling denting tare or It motion to stay proceeding, pending pending pending rullipations regulations reliably from storage reactor in entities to use this SEKULLR, 3 in a storage per and an approximation of the second second
- BOO4090444 Furushis Numb u3ds Sept 1975 re h80 practice & procedure digest Contains referted van 31 78034 decisions interpreting jules of practice W o enc! ROMECHICO, M is antitut furusion 80703731 lp
- 8004130026 Responds to appeal re-FOIA request for all records re-sabotage analyses for spent ruel storage at Morris operation in Morris IL Info withheld (ref FOIA Evention 4) Release of info would be contrary to public interest DIRCHS.W J Office of the Elecutive Director for Operations 80/04/03 2pc
- 8004170167 Advises of contrhange for amend review fee NAC Off of Controller notified to refund difference MILLER U O Greense Fee Management Branch 80/04/03 ip
- 8004100151 Response in opposition to State of IL amended Contentions 1(r), 2, 4(c) 7(a)(b) / 10 Supports Contention 7(c) Position re admissibility of other contentions remains unchanged Urgus denial of reconsideration re notion to stay ROTHSCHILD, H U hearing Branch 1 80/04/04 14pp
- ROTHSCHILD, M. U. Hearing Branch 1 80/04/04 22pp
- 8004220063 Forwards IE Info Notice 80~14 "Safety Suggestions From Employees" No action required KEPPLER. J. G. Region 3, Chicago, Orfice of the Director 80/04/04
- BOO4280305 Response to State or IL second set of amended contentions & motion to stay proceedings (L riling is deliberate effort to delay proceeding IL sefuses to inform ASLB,NRC & GE re issues for litigation Certificate of Svc encl SZWAJKONSKI, R General Electric Co SZWAJKONSKI, R Mayer, Brown & Platt 80/04/04 33pp
- 8004170251 Advises of intention to respond to EJ Walsh 800319 petition to intervene served on NRC on 800403
 ROTHSCHILD M U Hearing Branch 1 80/04/15 ip
- 8004230206 Corrects typographical errors in NRC 800404 responses to State of IL second set of amended contentions & Romaniet al remainended contentions RDTHSCHILD: M.V. Hearing Branch 1 80/04/17 2pp
- 8004220377 Response in opposition to E Walsh 800319 untimely petition to intervene Petitioner failed to state good contention.
 demonstrate standing b establish good cause for
 untimeliness Certificate of Svc encl
 ROTHSCHILD:M U Hearing Branch | 80/04/18 20pp
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & prepatedness, distributed as Board notification GOSSICK.L. V. Office of the Executive Director for Operations 80/04/02 34pp

DOCKET 70-1319 U.S. NUCLEAR INC.

- 8004280247 Forwards IF Insp Rept 70-1319/80-01 on 800206-07 No noncompliance noted STDHR, J P Region 2: Atlanta: Fuel Facility & Materials Safety Branch 80/03/10 2pp

DOCKET 70-1426 TRANSHUCLEAR, INC

004180093 Forwards security plans re transportation of 6NM of moderate & low strategic significance 4/o enci MANQUEL, J Transnuclear, Inc. 80/03/11 1p

- 8004070380 Ack receipt or 800311 ltr transmitting security plan for transportation or SNM of moderate strategic significance Fee to be assessed per licensing review WEISS.D Office of Administration 80/03/20 lp
- DOCKET 70-1729 FUEL REC & STOR STA , ALLIED GENERAL NUCLEAR BERVICES
- BOO4030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological emergency planning & preparedness, distributed as Board nutification ODSSICK, L. V. Office of the Executive Director for Operations 80/04/02 34pp

DOCKET 70-1739 TRI STATE MOTOR TRANSIT CO

- 8004230197 Responds to 800130 ltr requesting temporary amend to SNM Security Transportation Plan II Request has been reviewed & found acceptable MCCCRRLE.6 W Physical Security Licensing Branch 80/02/13 ip
- 8004220062 Discusses 800225 Safeguards Physical Security Licensing Branch memo advising of three reviews & approvals reported under one project control number Ofic of Controller notified on 800317 to invoice licensee WEISS, D. License Fee Management Branch 80/03/28 1p
- DOCKET 70-2554 NEW ENGLAND MEDICAL CENTER BOSTON, MA
- 8004080199 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 30-01868/80-01, 30-00240/80-01, 30-15064/80-01 & 70-2254/80-01 MCCLINIOCA, R O Region 1, Philadelphia, Office of the Director
- --8004080213 Responds to NRC 800222 ltr re violations noted in IE Inap Repts 30-01868/80-01.30-00240/80-01.30-15064/80-01 & 70-2294/80-01 Corrective actions necessary monitoring reinstituted on 800207 TRULL,D New England Medical Center Boston, MA 80/03/03 ip
- --8004080230 Forwards IE Insp Repts 30-01848/80-01.30-00240/80-01. 30-15044/80-01 & 70-2254/80-01 on 800205-07 & notice of violation MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director
- --8004080248 Notice of violation from insp on 800205-07 Noncompliance noted failure to make surveys of airborne radioactivity 791214-800207 & failure to perform routine thyroid monitoring

 * Region 1, Philadelphia, Office of the Director 80/02/22, 1p

DOCKET 70-2322 EDLOW INTERNATIONAL CO

- B004160003 Approves route through Partsmouth, VA for import of irradiated reactor fuel No practical alternatives exist that are not located in heavily populated areas MCCORKLE.0 W Physical Security Liconsing Branch 80/03/12 ip
- 8004040473 Approves increase in number of routes authorized by NRC 791219 route approval as requested in 800222 ltr MCCORKLE.Q W Physical Security Licensing Branch 80/03/13 lp
- DOCKET 70-2362 BROCKTON HOSP BROCKTON, MA
- 8004210012 Discusses IE insp of Licenses 20-03333-02 & SNM-1664 on 800221 No noncompliance noted Major areas inspected selective exams of procedures & representative records, interviews w/personnel,measurements & observations MCCLINTOCK, R D Region 1, Philadelphia, Office of the Director 80/02/28 lp

DOCKET 70-2478 TRANSNUCLEAR, INC.

8004030323 Forwards IF Insp Rept 70-2478/80-01 on 800226-27 No noncompliance noted
KENNA, W B Region 2: Atlanta, Safeguards Branch 80/03/11 2pp

- --8004030362 IE Insp Rept 70-2478/80-01 on 800226-27 No noncompliance noted Major areas inspected physical protection requirements for irradiated fuel in transit Dotails withheld (ref 10CFR2 790)
 TOBIN,W J. Region 2. Atlanta, Safeguards Branch PERNY,C D. Region 2. Atlanta, Office of the Director 80/03/10 ip
- 8004240247 Approves route through Portsmouth.VA for imports of irradiated reactor fuel No practical alternatives exist that are not located in heavily populated areas MCCGRKLE,GW Physical Security Licensing Branch 80/03/12 ip
- 8004210075 Forwards Amend 3 to license for Transnuclear, Inc to import 443 058 kg U.containing 459 507 kg U-235 % 2 406 kg Pu.from STONEBURNER, W Transnuclear, Inc 80/03/14 1p
- --8004210077 Amend 3 to license for Transnuclear, Inc to import 643 058 kg U containing 459 507 kg U-235 & 2 406 kg Pu from France PETERSON, M R Office of International Programs 79/09/25 ip
- --B004210078 Amend 1 to license for Transnuclear, Inc to increase quantity of matl authorized for import SHEA, J R Office of International Programs 78/05/26 1p
- --8004210080 License for Transnuclear, Inc to import 121 708 kg U containing 96 607 kg U-235 & 666 g Pu GUHIN,M A Assistant Director for Export/Import & International Safeguards 77/07/18 2pp

BOCKET 70-2479 TRANSNUCLEAR, INC.

- 8004240247 Approves route through Portsmouth.VA for imports of irradiated reactor fuel No practical alternatives exist that are not incated in heavily populated areas MCCORKLE,O W Physical Security Licensing Branch 80/03/12 ip
- 8004110545 Forwards IE Insp Rept 70-2479/80-03 on 600305-06 No noncompliance noted KENNA,W B Region 2, Atlanta, Safeguards Branch 80/03/25 2pp
- --8004110549 IE Insp Rept /0-2479/80-03 on 800305-06 No noncompliance noted Major areas inspected physical protection of irradiated fuel in transit Details withheld TOBIN, N J Region 2, Atlanta, Safeguards Branch MODRE, D E Region 2, Atlanta, Office of the Director 80/03/25 1p
- DOCKET 70-2A23 MCGUIRE SPENT FUEL POOL, DUKE POWER CO
- BOO4220303 Protests proposed shipment of nuclear waste from facility in SC to facility in NC Nuclear plants should be required to neutralize radiosctive matl rather than transport it SPARGOLL L Affiliation Unknown 80/03/05 2pp
- ---8004220315 Discusses Gaston County, NC resolution re transportation of spent nuclear fuel through county Requests opportunity to present resolution at NRC 800428 hearing in Charlotte NC HUNSCHER, D. G. Affiliation Unknown 80/03/19 ip
- --8004220326 Favors transport of nuclear waste through Mount Holly,NC Other dangerous shipments routinely pass through city SETIER 8 R Affiliation Unknown 80/03/20 1p
- --800422033; Favors shipment of nuclear waste through Denver.NC & storage of waste at nearby nuclear plant
 KENNERLY,F M Affiliation Unknown 80/03/19 1p
- --8004220342 Opposes transport of nuclear waste through Mount Hally,NC, Route is extremely hazardous due to presence of high-speed intersection & fraquency of accidents MCINTOBH,W O Affiliation Unknown 80/03/18 ip
- --8004220353 Opposes transport of nuclear waste through Lincolnton,NC Questions necessity of transporting safe mat1 from plant ROBINGON,F 8 Affiliation Unknown 60/03/11 ip
- --8004220352 Notifies that Caston Taxpayers Association opposes transport of nuclear waste from Gaston NC facility
 SUTHERLAND, R Affiliation Unknown 80/03/07 ip
- 8004030326 Serves routing info re spent fuel transportation & storage, per Commission 800227 order denying NRC petition Forwards RD Olenn & CV Hodge testimonies evaluating route changes per EIA W/o encl HOEFLINO,R K Hearing Branch 4 80/03/07 2pp

- 8004080372 Forwards June 1919 Physical Protection of Shipments of Irradiated Reactor Fuel Interim Conduce, "NUREG-0561 KETCHEN, C.G. Hearing Branch 4 80/03/21 10
- 8004110193 Motion to deny Carolina En. Hon Study Group request to introduce add1 evidence re cask drop issue Introduction of alleged scale-model test or cask tipping incident is inconsistent wheyelations & rolling M/Certificate of Svc MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman

aqB.

- 80042300/8 Forwards 8003P8 SECY-80-166 requesting amend to irradiated reactor ruel in-transit physical protection requirements If amend approved effect on fiRC case re spent fuel transportation 9 storage will be provided HQEFLING R & Hearing Branch 4 80/04/01 1p
- 8004030026 Memorandum of understanding between NRC & FEMA re prompt improvement in radiological smergency planning & preparedness, distributed as Board mutrication GDSSICKLE V Office of the Executive Director for Operations GOSSICK, L V 80/04/02 ∨ υ 34ρρ
- 8004230012 Motion requesting ASLB consideration of proposed primary route Applicant does not deny availability of alternate routes Pertinent NRC regulation based on Sandia Labs study Study envisions highly unlikely sabotage event MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 80/04/04 7pp
- 8004180432 Forwards NRC 800403 ltm w/encl commercial newspaper Advertisement re resumption of evidentiary hearings NRC wishes to notify public officials of counties in which proposed alternate routes are located KETCHEN, E. G. Hearing Branch 4 80/04/08 lp
- --8004180441 Notifies of resumption of evidentiary hearings re amend of License SNM-1773 Proposed action is to transport up to 300 spent fuel assemblies from Oconee nuclear facility to McGuire nuclear facility Commercial newspaper notice encl ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 80/04/03
- BOO4160197 Forwards BS Spitalny, JN Donohew,CR Marotta & E Lantz prefiled testimonies re amend to License SNN-1773 for Ocohee spont feel transportation & storage at McGuire KETCHEN,E G Hearing Branch & 80/04/11 2pp
- --8004160197 Prefiled testimony re 800428 hearing Updates license amend record to spent fuel handling \$ storage alternatives status of NRC spent fuel cask review & pin compaction application BPITALNY, B \$ Advanced Fuel & Spent Fuel Licensing Branch 80/04/11 Spp
- --8004160210 Supplemental NRC rept "Spent Fue) Storage of Geomee Spent Fuel at McGuire Nuclear Station Unit 1" * Commission 80/04/11 2pp

- --8004160235 Afridavit no orrupational doses caused by Ocomee spent fuel assembly rupture at 2 0 days in age, when stoned in McGuire spent fuel pool Completes fift response to ASLB 771031 order Supporting documentation end!

 DONOHEM. J.N. Environmental Evaluation Branch 80/04/10 Bpp
- --8004160240 Afridavit re ocrupational doses caused by Doonee spent fuel assembly rupture, at 40 days in age, when stored in McGuire spent fuel pool Completes NRC response to ABLB 791031 order Supporting documentation encl DDNDHEW, J N Environmental Evaluation Branch 80/04/10 8pp
- --8004160244 Affidavit modifying JN Donohew 800111 affidavit.Table 2.Page 10 & Table 3.Page 11 DONOHEW J N Environmental Evaluation Branch 80/04/11 3pp
- 8004160265 Response requesting deferral of ASLB consideration of applicant 800405 motion proposing primary route of spent fuel shipments Urges ASLB to hold motion in abeyance pending Commission action re security issue M/Certificate of Svc HQEFLING.R K Hearing Branch 4 80/04/11 9pp
- BOO4230210 Response in support or Duke Power Co BOO401 motion to deny Carolina Environ Study Group introduction of addl evidence re cask drop issue Good cause for reopening record not demonstrated W/Certificate of Svc XETCHEN, F. G. Hearing Branch 4 80/04/21 Bpp
- 8004100558 Further supplemental testimony of RN Bostian re spent fuel storage High density relacking discussed Pp 1-3 Certificate of Svc encl BOSTIAN-R W Duke Power Co 80/03/17 Spp
- DOCKET 70-2786 GENERAL ELECTRIC CO
- 8004070136 Forwards info requesting route approval for shipment of irradiated reactor fuel Encl withheld (ref 10CFR2 790) CARRIER.N J General Flectric Co 80/01/29 ip
- 8004020147 Responds to 791205.800127 & 0213 requests for approved spent fuel route Route & law enforcement info moets NRC requirements & approval Route & law enforcement info withheld (ref100FR2 790) MCCORKLE.G W Physical Security Licensing Branch 80/02/22 ip
- DOCKET 70-2805 NISSHO-1UA1 AMERICAN CORP
- 8004240181 Forwards Frecutive Branch response on pending application for license to export highly enriched U to Japan Requests identification of issues to include in analysis
 SHEA, J.R. Office of International Programs SECY-80-120 80/03/03
- --8004240190 Application by Wissho-Twai American Corp for license to export 39 185 kg U-235 contained in 42 kg U to Japan KAWAHARA S Nissho-Twai American Corp 78/02/08 2pp
- --8004240202 Forwards Nis-ho-lwai American Corp application for license to export 39 186 kg U-235 to Japan & end use statement End use statement only encl TSUJI.N Nissho-lwai American Corp 78/02/08 6pp
- DOCKET 70-2845 TRANSMUCLEAR, INC
 - 51 forwards Executive Branch position on 800121 applications tenses to export highly enriched U to Belgium Nest; France & the Netherlands Requests comments

 R Office of International Programs SECY-80-45 80/01/24
- --8004010081 Forwards application by Transnuclear.Inc for license to export 23 058 kg U in form of U hexaflouride enriched to max 93 3% U-235.to Mest Germany MATSON.V Transnuclear. Inc 78/03/27 (p
- --8004010071 Application by Trensnuclear Inc for license to export 23 058 kg U.in form of U heraflouride enriched to max 93 3% U-235 to West Germany End use statement & checklist encl MATSON.V Transnuclear Inc 78/03/27 3pp

- DOCKET 70-2872 REUTER-STOKES
- 8004170108 Act receipt of 800317 ltr transmitting plan for protect of SNM Amend to License SNM-1826 will be upon issued upon plan approval Fee required WEISS, D. License Fee Minagement Branch 80/03/26 lp
- DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS
- 8004180090 Responds to request for name of thief executive of municipality or county mentioned in environ rept submitted in support of 791231 license application re nuclear fuel fabrication plant planned for AL CELLIER.F Westinghouse Flectric Coip 80/02/20 1p
- 8004150104 Forwards distilbution list.FR notice & news release TQ issuance of BNM license for Facility PAGE,R G Uranium Fuel Licensing Branch 80/02/27 4pp
- --8004150107 Notice of opportunity for hearing availability of on vept b intent to prepare DES re issuance of BMM license for facility
 PAGE,R G Uranium Fuel Licensing Branch 80/02/24 8pp
- 8004180098 Transcript of £1S 800327 scoping meeting in Prattville, Pp 1-66 ORAY, C M Affiliation Unknown CROW, W , SHUM, E Y Uranium Fue Cicensing Branch 80/03/27 67pp
- 8004240257 Transcript of 800327 EIS scoping meeting in Prattville. re proposed vendor fuel fabrication plant * Commission 80/03/27 67pp
- 8004170282 Confirms 800325 telcon is establishment of Prattville F²
 Library as official NRC LPDR for fabrication plant matl NRC
 representatives will visit for briefing re matl filling &
 retrieval procedures
 CARRIER.W B Division of Rules and Records 80/04/01 1p
- 8004286064 Mation for extension of time to make comments on scope proposed EIS re Westinghouse SNM application NRC statement at 800327 scoping meeting that proposed 800703 & 07 deadlines were incorrect & created confusion ARANGY.R Affiliation Unknown MCPHILLIPS.J Affiliation Unknown 80704703 3pp
- 8004300366 Response in support of RH Campbell.A Toledo.RE Ely, JA Johnson, MF Butler. CO Butler. R Aronov.LO Moore & SN Draut petitions to intervene Urges presentation of common interest by single spokeman subj. to filling of one contention TURK.S E Hearing Branch 1 80/04/28 11pp
- ---8004300371 Response in support of DL Allred 800407 petition to intervene Petitioner demonstrated interest & adequately identified relevant aspects of proceeding Urges admission of petitioner subj to filling of one admissible contention TURK.S E Hearing Branch 1 80/04/28 8pp
- --8004300378 Response in support of State of AL participation as interested state in proceeding TURK,S & Hearing Branch 1 80/04/28 1p
- ---8004300381 Requests participation in possible hearing.as interess state per (CCFR2 715/c) Notice of SE Turk appearance & Certificate of Syc encl MYERS.I L. Alabama. State of 80/03/21 4pp
- DOCKET 70-2917 TENNESSEE VALLEY AUTHORITY
- 8004240201 Forwards License SNM-1865, authorizing receipt possessical insplay storage of U-235 fuel assemblies & max of 100 fuel rods License also allows packaging & shipping for transfer Safety evaluation encl
 PAGE, R. O. Uranium Recovery Licensing Branch 80/01/30 2pp
- --BOD4240207 License GNM-1869, authorizing receipt, possession, inapt transfer of max of 2,110 kg u-295 fuel assemblies & 100 fuel rods Licensee is exempt from matts provisions of 10CFR70 24 PAGE, R O Uranium Recovery Licensing Branch BO/01/30 Spp J
- --8004240217 Safety evaluation is util application for license to receive max 2:110 kg U-235 fuel assemblies & 100 fuel rods License should be granted w/exemption from 100FR70 24 CROW, H T, DELANEY, J L. Utanium Recovery Licensing Branch 80/01/30 2pp

DOCKET 70-2920 ALABAMA POWER CD

- 8004020473 Forwards License SNM-1868 for utiliauthorizing receipt, possession & storage of U enriched in U-235 isotope & Pu License also authorizes packaging of fuel assemblies for delivery to carrier Safety evaluation encl PAGE.R G Uranium Fuel Licensing Branch 80/03/12 2pp
- --80040204B1 License SNM-1868 for util, authorizing receipt, possession, insp & storage of U enriched in U-235 isotope in fuel assemblies & fission counters. & Pu in encapsulated Puberyllium neutron sources & alpha sources PAGE, R O Uranium Fuel Licensing Branch 80/03/12 2pp
- --8004020485 Safety evaluation supporting 790918 application for license for fuel & accessories Licensee should be granted exemption from 10CFR70 24 requirements DELANEY.J C Uranium Fuel Licensing Branch 80/03/12 2pp

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0005 MAGNAFLUX CORP

8004290495 Understands GA program description will be submitted by B00417 MACBONALD, C E Transportation Branch 80/03/04 ip

DOCKET 71-0009 ISOMEDIX, INC

- 8004090220 Advises that vendor is in process of transferring mfg activity to AECL Target data for resolving transfer details is 800430 At that time, vendor will advise of last date to ship matls or submit revised GA program DIETZ, G R Isomedix, Inc (subs of Maesfield Enterprises, Inc.) 80/03/17 ip
- ---B004090225 Advises that NRC 790730 ltr requesting addl info re QA program on timely basis has not received response Provides format, previous correspondence & franked envelope for immediate response MACDONALD, C E Fransportation Branch 80/03/04 lp

DOCKET 71-0013 NAVY, DEPT OF

- 8004020373 Forwards QA program approval for radioactive matl package MACDONALD.C E $\,$ Transportation Branch $\,$ 80/03/05 $\,$ ip
- --8004020380 GA program approvel for radioactive matl package 0013, Revision 1 MACDONALD, C E Transportation Branch 80/03/05 ip

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP

- 8004090234 Requests amend to GA Program Approval 0024.Revision O, changing program implementation date from 800301 to 800322 ROHE.B B Hittman Nuclear & Development Corp (subs Hittman Corp), 80/03/03 ip
- BOO4070147 Forwards QA program approval for radioactive matl package MACDONALD.C E Transportation Branch G0/03/13 ip
- --B004070152 GA program approval for radioactive matl package 0024. Revision 1 MACDUNALD.C E Transportation Branch 80/03/13 ip

DOCKET 71-0035 ROCKWELL INTERNATIONAL

- 8004040398 Forwards QA program for packaging licensed radioactive matl for shipment in response to NRC 800123 request for revisions to program MCDERMOTT.R J Rockwell International Corp 80/03/10 1p
- --8004040403 GA program for packaging licensed radioactive math for thipment JUSEPH,R L , QLABS,D N , MCDERMOTT,R J Rockwell International Corp 80/03/07 24pp

DOCKET 71-0049 NAVY CEPT IIF

- 8004150272 Forwards GA program for receipt handling, storage t transfer of special form radical tive milt in response to NRC 800304 ltr
 - GROVES, M. L. Ha.y. Dept or, Na. al Nuclear Power Unit 80/03/13 lp
- --8004150278 Forwards GA program for receipt, handling, storage & transfer of special form radioactive mat)
 WARD, C.E. Navy, Dept. ot 79/11/12 ip
- --8004150284 QA program for receipt, handling, storage % transfer of special form indicactive mat!

 * Navy,Dept of 79/11/12 App
- BOO4100239 Forwards GA program approval for radioactive matl package MACDDNALD,C E Transportation Branch BO/03/27 1p
- ~-B004100242 QA program approval for radioactive matl package 0049, Revision O MACDDNALD,C E Transportation Branch 80/03/27 1p

DOCKET 71-0096 PAN AMERICAN WORLD AIRWAYS

- BOO4180062 Forwards revised GA plan for transportation packages for normal/special fulm radioactive matl DUNN,N M Pan American World Arrways, Inc. BO/03/19 1p
- --8004180069 Revised QA plan for transportation packages for normal/ special form radioactive matt DUNN-N M Pan American Would Arrways, Inc. 80/03/19 8pp
- 8004100231 Folwards QA program approval fol radioactive matl package MACDUNALD, C E Transpoltation Branch 80/04/01 1p
- --8004100236 GA program approval for radioactive matl package 0096. Revision O MACDOMALD.C E. Transportation Branch 80/04/01 ip

DUCKET 71-007/ NONDESTRUCTIVE TESTING SERVICE

- 8004150132 Forwards GA Piogram for industrial radiography licensess
 HAULDREN, H M Nondestructive Inspection Service 80/03/18 tp
- --8004150133 GA program for industrial radiography licensess
 * Nondestructive Inspection Service 80/03/18 3pp
- 8004100226 Forwards QA program approval for radioactive mati package MACDONALD, C.E... Transportation Branch 80/04/01 1ρ
- --8004100227 9A program approval for radioactive package 0097, Revision O MACDUNALD, C E Transportation Branch 80/04/01 ip

DOCKET 71-0102 SOURCE PROD \$ LOUIP CO . INC

80040B0098 Ack receipt of NRC 800304 ltr requesting info Project was turned over to consultant R Parker several months ago Advises that request will be forwarded DICHARRY, R F Source Production & Equipment Co., inc. 80/03/14 ip

DOCKET 71-0107 NAVY, DEPT OF

- 8004240314 Forwards revised QA program for industrial radiography, in response to NRC 790813 ltr GROVES,K L. Navy, Dept of, Naval Auclear Power Unit 80/02/28 ip
- --8004240327 Forwards revised QA program for industrial radiography GLENN, T D Navy, Dept of, Naval Nuclear Power Unit 80/02/07 1p
- --8004240331 GA program for industrial radiography GLENN,Y D. Navy, Dept of, Naval Nuclear Power Unit 80/02/07 Ann

```
4 l 4
                                                                                                                                                                                                            *; in a to hew 791228 request re
                                          т Ч
                                                                                                                                                                                                                        , , to it - - Let Unit E0/03/19 1p
                                                                                                                                               • •
                                                                                                                                                                                                                                                          in a viet through storage & transfer
                                                                                                                                                                                                                              • 41
                                                                                                                                                                                                                                                                                 ear Fuger Unit 80/03/07 1p
                                     Since the property of the state of the stat
                                                                                 * it's a man of all fin madicactive mail package
                                     Para di La gera.
Para di La gera.
                                                                                                                                                                                                                                • r viliga •: e matl package Q116,
                                                                                                                                r f n ++1 Ex# + 80/04/01 1p
                   Di met i i i i i
                   7.24 | 1.35 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.05 | 2.
                BUTHER TO CALLED A PARISHED
                THE WATER STATE IS A WATER THE TOP FOR BATTERNING TO COMPLETE PRIZEW OF QA
                            peogram

MACELIA 1 6 Transportantur Drance 80/03/14 Spp
            EDOMET 71 Clas . . ERT
            E/D4690\, Z_{\rm min} is the property of the sum of the
            mmHBBO4이루스 기계 You program att all the haddoastive mat1 package 0165.
                                       Agenter of the control of the contro
           ADD MET 71 117 TOTAL ELE THIS CA
        ECO43000f. Forwards hereigns in the program COMMIRGIAN of the end of the state of Notlean Energy Products Div GO704407 (a)
      --- GOO4300.4- WA or gram
                                                                                                                                                                                                         1/1-1 R1 +0.03/31 33pp
        DOCKET 71 618 HARTFURD STEAM DUILER OF
     E004070137 Regresta influre status or response to 790413 ltm
MACDELALF | E. Traiso its inn pranch | 80/03/14 | lp
     DOCKET 21 GIGH FRE IF.
    8004070021 F rwands GA pt 3mam Addil appendires included to cover addl
                   medulinements
STRINGFIELD H FP- In Div 03/10 lp
    DECKET 71 ORET TENNESDEE VALLEY AUTHORITY
8004290513 Forwards GA program Revision 1
MILLS.L 4 Tennessee Valley Authority 80/04/10 ip
```

```
DOCKET 71-0230 BABCOCK ? WILLON CO
     8004040374 Forwards requirt for addl info to complete review of QA
        program
MACDONALD, C.E. Transportation Branch 80/03/14 tp
     DOCKET 71-0249 NUCLEAR FUEL SERVICES, INC
    8004140024 Forwards QA Program to shipping packages for radioactive math Program includes info requested in NRC B00116 ltr MICHELIC J Nuclear Fuel Services, Inc. (subs. of Oatty Dil Co.) 80/03/17 lp
     --8004140027 OA Program Revision 2 for shipping packages for radioactive
         mati
• Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80/01/17
    DOCKET 71-0250 TRANSNUCLEAR, INC.
   8004020360 Forwards QA program approval for radioactive mat1 package MACDUNALD, C.E. Transportation Branch 80/03/05 ip
    --8004020364 GA program approval for radioactive matt package 0250.
        Revision O
HaCDONALD.C E liansportation Branch 80/03/09 ip
   DOCKET 71-0252 DAYTON X-RAY CO
   8004180400 Forwards request for addl info to complete review of OA
     program
MACDONALD, C.E. Transportation Branch 80/03/28 3pp
  DOCKET 71-0273 NAVY, DEPT OF
  8004150079 Forwards supplemental info per NAC 800€20 request re GA
    program
GROVES,K L. Navy,Dept of, Naval Nuclear Power Unit B0/03/19 lp
  ~~8004150102 Forwards QA program for radingraphic operation
ALLEN.J E Navy, Dept of Navat Nuclear Power Unit 80
                                                                         80/02/20 1p
  --8004150108 GA program for radiological operation,
ALLEN, J E Navy, Dept of, Naval Nuclear Power Unit 60/02/20
 8004100329 Forwards GA program approval for radioactive mat1 package MACDONALD, C E Transportation Branch 80704701 ip
 ~-8004100332 QA program approval for radioactive matt package 0273,
      Revision O
MACDONALD,C E Transportation Blanch 80/04/01 ip
 DOCKET 71-0367 NAVY, DEPT OF
 8004190112 Forwards supplemental info per NRC 800115 request re GA
   program
GRBVES.K L Navy. Dept of, Naval Nuclear Power Unit 80/03/19 ip
--B004150117 Forwards revised Page 3 & new Page 4 to GA program
BISEK,D G Navy,Dept of, Naval Nuclear Power Unit 80/03/13 ip
--B004150121 Revised Page 3 & new Page 4 to GA program
* Navy,Dept of, Naval Nuclear Power Unit 60/03/13 2pp
8004100346 Forwards OA program approval for radioactive matl package MACDGNALD, C & Transportation Branch 80/04/01 ip.
--8004100349 QA program approval for radioactive matt package 0367.
    MACDONALD, C.E. Transportation Branch 80/04/01 ip
```

DOCKET 71-0370 AMERSHAM CORP

8004040388 Forwards request for addl info to complete review of QA MACDONALD.C E Transportation Branch 80/03/14 12pp

DOCKET 71-0372 BDEING CO

- 8004090214 Forwards QA program approval for radioactive matl package MACDDNALD, C.E. Transportation Branch 80/03/21 ip
- --- B004090218 GA program approval for radioactive mat1 package 0372. MACDONALD,C E Transportation Branch 80/03/21 1p
- DOCKET 71-00373 NAVY, DEPT OF, NAVAL EXPLOSIVE ORDN DISPOSAL FACIL
- 8004090201 Forwards GA program approval for radioactive matl package MACDONALD, C.E. Transportation Branch 80/03/21 1p
- --8004090203 GA program approval for radioactive mat1 package 0373, MACDONALD, C E Transportation Branch 80/03/21 1p

DOCKET 71-0375 CALIFORNIA, UNIV OF

- 8004090222 Forwards GA program approval for radioactive matl package MACDONALD, C E Transportation Branch 80/03/21 ip
- --8004090226 GA program approval for radioactive mat1 package 0375. MACDONALD, C E Transportation Branch 80/03/21 1p

DOCKET 71-0377 INDIANA & MICHIGAN ELECTRIC CO

- 8004090270 Forwards QA program approval for radioactive matl package MACDDNALD, C E Transportation Branch 80/03/27 ip
- ---8004090273 GA program approval for radioactive matl package 0377. Revision 0
 MACDONALD, C E Transportation Branch 80/03/27 to

DOCKET 71-0378 WISCONSIN ELECTRIC POWER CO

8004040123 Notifies that description of QA program is App H to final description & SAR FAY, C W Wisconsin Electric Power Co 80/02/25 2pp

DOCKET 71-0379 HITTMAN CORP . HITTMAN MATL & MEDICAL COMPONENTS, INC

- 8004020274 Responds to 800226 request for approval of OA program Item 3 should be revised to require that all radioactive matl shipping packages procured since 790101 are designed & mfg under NRC-approved GA program MACD
- 8004220043 Forwards revised Operating Procedure OP-168, constituting "GA Program for Use of DOT 6M Drums in Shipping Special Form Pu-238." DISALVO Hittman Corp 80/03/25 ip
- --8004220055 Revised Operating Procedure OP-168 constituting" GA Program for use of DOT 6M Drums in Shipping Special Form Pv-238 " DISALVO Hittman Corp 80/03/28 2pp

DOCKET 71-0380 GENERAL ELECTRIC CO

- 8004070398 Advises that NEDO-11209-04A, Revision 1, "Nuclear Energy Div BWR GA Program Description," outlines GA program vendor will use for packaging activities re application for registration as user of Model 589 shipping package. CUNNINGHAM, G E General Electric Co 80/03/10 ip
- 8004090014 Forwards GA program approval for rainactive matl package MACDONALD, C. E. Transportation Branch 80/03/31 1p

- --8004090017 QA program approval for radioactive matl package 0380. Revision C MACDUNAL D. C. E. Transportation Branch B0/03/31 [p.
- DOCKET 71-0381 C L CONNELL * CO
- BOO4210066 Requests applicable tentl GA program for transportation of licensed matts.

 COPPERIUE E I Conwell & Co. 00/04/24 Ip
- --80042100/3 GA program for transportation of licensed matts
 Organizational chart for industrial radiography encl
 # E l Conwell * to 100/03/21 'pp
- DOCKET 71-0383 HODEL HET TAP LUT CASK, HE INDUSTRIES, INC.
- 8004300079 Requests registration as user of Model NLI 1/2 LWT Cask LIPPOLD:W J. Daltimore Gas * Electric Co.: 80/04/03 1p
- DOCKET 71-4824 MUDIL HA 10. BABCOCK & HILCOX CO
- B004270061 Advises that one of Model HA 10 will be discontinued & company will not renew Continicate of Compliance 4824
 AUSTIN-M A Babcock & Wilson Co., Nuclear Material Div 80/03/25
- DOCKET 71 5395 MODEL CC. WESTINGHOUSE FLECTRIC CORP
- 8004280307 Furwards Revision 9 to Costificate of Compliance 5395 for MACDONALD, C.F. Transportation Branch 80/04/02
- --B0042B0314 Centificate of tampliance 5395 Revision 5, for Model CC MACDUNALD C C limitsportation Blanch B0/04/02 3pp
- DOCKET 71 9507 HODEL GE 1-2, GENERAL ELECTRIC CO
- BOO40400B2 Notifies of expiration of Centificate of Compliance 9607 for Model OL T-d to continue using package should submit consolidated application diamings & renewal fee MACDONALD.C Transportation branch 00/07/14 tp

- BCO402012V Submits renewal to the for Centificate of Compliance 5939 re GE Hodel (550 churping integrier Packaging description & Vallectes Russian Off +10-10 ltr +0 ACC enc.) CONNINGHAM & C. Genzial a actric to BO702/21 15pp
- --8004020137 Forwards per la changed drawings on remaining containers designating jackst hindown bolts re GE models 1500 \$ 700 Mode to applications as locally modified drawings forthcoming RIKS W.H. General electric for 69.02/20 12pp
- 80040404c2 Notinication of registration as user or Model 6400 & 9E 1500 in response to request MACDUMALD. C. E. Transportation Branch 80703/14 ip
- DOCKET 71 5942 MUDEL GE 700 GENERAL ELECTRIC CO
- 8004300505 Forwards SAR +nr GE, spent fuel shipping cask Model 700, in support of Leittricate or Compliance 5942 Drawings available in Central Files only BRUGGER R M. Hissouri Mni. of Columbia 80/03/20 2pp
- DOCKET 71 5971 MODEL GF-100, GENERAL ELECTRIC CO
- 8004250084 Requests that centimicate of Compliance 5971 for GE Model 200 shipping container be renewed w/minor changes Forwards drawings indicating changes made to cask drawing list Drawings available in Centrol Files only Amend fee ontl CURNINGHAM.G E General Electric Co. 80/02/20 16pp
- DOCKET 71-5979 Hodel 5977, ALPHA-OMEGA SERVICES.INC
- BOO4040197 Notifies of expiration of Certificate of Compliance 3979 for Model 5979 To continue using package, should submit consolidated application 3 drawings MACDOMALD.C E. Transportation Branch 80/03/17 Ip
- DOCKET 71-5998 MODEL GE+400. GENERAL ELECTRIC CO
- 8004070053 Notifies of expitation of Certificate of Compliance 5998 for Model GE-400 To continue using package, should submit renewal application % fee MACDENALD.C E Transportation Branch 80/03/14 ip
- DOCKET 71-6078 MODEL 927 AT & C1: COMBUSTION ENGINEERING, INC.
- 8004100259 Forwards Revision & to Certificate of Compliance 4078 for Models 92741 % 92701 MACDUNALD,C.E. Transportation Branch 80/03/28 ip
- --8004100262 Certificate of Compliance 60/8, Revision 6 for Models 927A1 & 927C1 McCDDNALD, C & Transportation Branch 80/03/28 3pp
- DOCKET 71-6144 MODEL 6144, HUCLEAR ENGINEERING CO
- 8004110125 Ack receipt of BGD201 request re registration as package user Approved GA program required prior to registration MACDONALD.C E. Transportation Branch 80/03/04 ip
- 8004250302 Requests registration as user of Models CSN-4-101 & CBN-15-(698 CBN-15-(698 CBGNEY/M J. Philadelphia Electric Co. 80/03/28 | 1p
- DOCKET 71-6272 MODEL POLY PANTHER, TELEDYNE ENERGY SYSTEMS
- 8004100212 Forwards Revision 3 to Certificate of Compliance 6272 for Model Polly Panther MACDUNALD,C E Transportation Branch 80/03/28 2pp
- --8004100216 Certificate of Compliance 6272 Revision 3.for Model 6272 MACDDNALD.C E Transportation Branch 80/03/28 200
- DOCKET 71-6375 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC
- 8004040455 Requests registration as user of Model PB-1 SMITH R L. Vermont Yankes Nuclear Power Corp. 80/03/04 1p

- 8004040459 Notification of registration as user of Model CNS 4-45 in response to request.

 MACDIVAD.C F. Transportation Branch 80/03/17 in
- 8004210418 Forward, request for addl info re 791126 consolidated application for renewal of Certificate of Compliance 6375 for Model CN5 4-45 (PB-1) Info should be provided within
- MACDONALD.C & Transportation Granch 80/04/02 2pp
- DOCKET /1-6387 MODEL 60, BATTELLE MEMORIAL INSTITUTE
- 8004020055 Forwards Certificate of Compliance 6387 Revision 2 & safety evaluation for HEDL Model 60 ROSS.D M Energy.Dept of \$3701/21 6pp
- --8004020059 Certificate of Compliance 6387.Revision 2.for HEDL Model 60 TIERNARI M W Energy Dept of 79/05/07 7pp
- BOO4044/B Notifies of expiration of Certificate of Compliance 6387 for Model 60 To continue using package, should submit consolidated application to drawings MACDUNAL D.C E Transportation Branch BO/03/17 ip
- DOCKET 71-6400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 8004040462 Notification of registration as user of Model 6400 & GE 1500 in response to request MACDMALD. C E Transportation Branch 80/03/14 ip
- 80042R0127 Responds to NRC 800229 itr forwarding Revision 8 to Certificate o+ Compliance 6400 In response to Guestion 2. Lynchburg Research Ctr has used overpacks L-1 & Units 1 & 2 Guestions 1 & 3 do not apply GLSEN.A F Babcock & Wilcox Co 80/03/14 ip
- 8004150119 Responds to request for info re Certificate of Compliance 6400, Revision 8 Ut;1 does not own any Model 6400 package & never possessed package to perform insp Model not used since 780228

 LINDER,F Dairyland Power Cooperative 80/03/18 ip
- 8004280061 Responds to 800227 ltr re Certificate of Compliance A400. Revision & Licensee does not own DDT USA/6400/B() F packages Licensee has not used packages from other vendors since 780228 REMLEY, M & Rockwell International Corp , Energy Systems Div 80/03/18 ip
- 8004210198 Responds to NRC 800229 lite by advising that no Model 6400 packages are owned & no shipment of package has been made since 780220 MICHEL: C J Nuclear Fue) Services, Inc (subs of Getty Dil Co) 80/03/21 lp
- DOCKET 71-6574 HODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8004220274 Forwards response to NRC 791221 request for add1 info re SAR for Model HM 200 G-loads under top-corner impact conditions re-evoluated to consider peak conditions Proposed revised pages to SAR encl MALLORY Hittman Nuclear & Development Corp (subs Hittman Corp) OB/03/20 17pp
- 8004100220 Forwards Revision 5 to Certificate of Compliance 6574 for Model NH-2D0 ModDNALD, G E Transportation Branch 80/09/28 3pp
- ~-8004100224 Certificate of Compliance 6574, Revision 5, for Model HN~200 MACDONALD, C E Transportation Branch 80/03/28 3pp
- DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO
- 8004100198 Forwards Revision 3 to Certificate of Compliance 6679 for Model 1/2 Super Tiger MACDONALD, C.E. Transportation Branch 80/03/31 2pp
- --8004100200 Certificate of Compliance 6679 Revision 3.for Model 1/2 Buyer Tiger MACDONALD.C E Transportation Branch 80/03/31 4pp

- DOCKET 71-4698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC
- 8004040395 Requests authorization, under Centificate of Compliance 6698, Revision 9 for Model NFS-4, to ship reconstituted PMR U ozide fuel assemblies containing more or less than design number of fuel rods Fee encl
 JCHNSON, C R Nuclear Assurance Corp 80/03/03 ≥pp

DOCKET 71-6717 MODEL 6717 9

- 8004210037 Requests revision to Certificate of Compliance 6717 for Model 6717B deleting references to use of asbestos as thermal insulator in package design Requests that words asbestos free, appear in description paragraph RICHAROSON, H D Gamma Corp 80/02/26 7pp
- ---8004210042 Requests payment of minor amend fee re 800224 request for amend to Certificate of Compliance 6717 for Model 6717B WEISS,J D License Fee Management Branch 80/03/05 ip
- DOCKET 71-9006 MODEL 500 SU, ARGONNE NATIONAL LABORATORY
- BOO4010001 Notification of registration as user of Models 500-SU & 520 MACDONALD, C E Transportation Branch 80/03/07 ip
- BOCKET 71-9007 MODEL 520, ARGONNE NATIONAL LABORATORY
- B004010001 Notification of registration as user of Models 500-8U & 520 MACDDNALD, C E Transportation Branch 80/03/07 1p
- 8004040381 Notifies of expiration of Certificate of Compliance 9007 for Model 320 To continue using package, should submit consolidated application & drawings MACCONALD, C.C. Transportation Branch 80/03/17 ip
- DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO
- 8004070216 Requests registration as user of Model FL 10-1 package HANBEN.L E Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/02/27 ip
- 8004090046 Submits application for amend of Certificate of Compliance 9009 for FL-10-1 shipping container. DIPIAZZA,R F Westinghouse Electric Corp 80/03/11 2pp
- 8004100290 Forwards Revision 6 to Certificate of Compliance 9009 for Model FL 10-1 MAGDUNALD, C E Transportation Branch 80/03/28 2pp
- --8004100254 Certificate of Compliance 9009, Ravision 6 for Model FL 10-1 MACDUNALD.C E Transportation Branch 80/03/28 ip

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

- 8004220225 Requests that Certifificate of Compliance 9010 be revised to provide option for method of capping off neutron shield espansion tank Certificate available in Central Files only Fee encl
 WILLIAMB.C E NL Industries, NL Nuclear Div 80/02/21 2pp
- BOO4280166 Requests renewal of Certificate of Compliance 9010 for Model NLI-1/2 Forwards drawings & "BAR.MLI-1/2 Bpent Fuel Bhipping Cask " Drawings & rept available in Central Files only WILLIAMS, C.E. NL Industries, NL Nuclear Div 80/03/07 App
- 8004040321 Forwards Revision & to Certificate of Compliance 9010 for Model NLI-1/2 MACDDNALD, C. E. Transportation Branch 80/03/24 2pp
- --B004040124 Certificate of Compliance 9010.Revision 6 for Model NLI-1/2 MACDDNALD.C E Transportation Branch B0/03/26 App

- DOCKET /1-9011 MODEL (-MEH 00-00004, TRANSPORTATION, DEPT OF
- 8004100270 Ack 830127 request for Type 8(U) certification for Models 181375, 181361 % C-NEH-00 00004 shipping containers Review concludes packages authorized by certificates of Compliance 5796 % 9011 meet IAFA requirements for Type 8(U) packages MACDONALD.C E Transportation Branch 80/03/25 ip
- DOCKET 71-9015 MODEL TN-8, TRANSNUCLEAR, INC
- 8004030104 Notifies of eipiration of Certificate of Compliance 9015 for Model TR B To continue using package should submit renewal application 5 fee MACDONALD.C C. Transportation 3ranch 80/03/14 ip
- DOCKET 71-9016 MODEL TN-9 , TRANSNUCLEAR, INC
- B004030100 Notifies of expiration of Certificate of Compliance 9016 or Model TN 9 To continue using package, should submit renewal application % fee MACDDMALD.C E Transportation Branch 80/03/14 ip
- DOCKET 71-9017 MODEL BU-7, GENERAL ELECTRIC CO
- 8004090076 Requests listing as user of Model BU-6 PENNEY.J A Brookhaven National Laboratory 80/03/06 ip
- 8004020143 Forwards amond request to NRC for revision of Certificate of Compliance 9019 re authorized contents & specs for outer 55-gallon drum & inner la-gallon drum used to construct BU-7 package W/o encl KAPLAN.A L General Flectric Co , Nucleal Energy Products Div 80/03/10 ip
- 8004180515 Forwards application for Amend T-8 to Certificate of Compliance 9019 for Model RU 7 Supporting documentation attached Fee encl KAPLAN.A L. General Electric Co., Nuclear Energy Products Div 80/03/14 41pp
- --8004180522 Application for Revision 3 to Certificate of Compliance 9019, revising drum specs & authorized content # General Electric Co., Nuclear Energy Products Div 80/03/14 3pp
- --BOD4180925 Application to amend fixense GNM-54 to authorize transport of SNM in Mode)s BU-6 & BU-7 as described in Mod 23 to App D
 TSCHAECHE, A N General Electric Co 74/05/24 10pp
- B004220789 Forwards revised pages constituting Mod 1 to application for Amend T=8 for certificate of compilance for Model BU-7 KAPLANIA L General Electric Co., Nuclear Energy Products Div B0/03/17 App
- --8004220790 Revised pages constituting Mod 1 to application for Amend T-8 for certificate of compliance for Model BU-7 KAPLAN,A L General Flectric Co . Nuclear Energy Products Div 80/03/17 Spp
- BOO40B0093 Forwards Revision 4 to Centificate of Compliance 9019 for Model BU-7
 MACDONALD: C E Transportation Branch B0/03/(B 2pp
- --8004080097 Certificate of Compliance 9019 Revision 4.for Model 8U-7 MACDONALD C E Transportation Branch 80/03/18 4pp
- DOCKET 71-9020 MODEL SL-10-1, NUCLEAR CONTAINERS, INC
- 8004100036 Forwards Revision 3 to Certificate of Compliance 9020 for Model SL-10-1 MACDONALD,C E Transportation Branch 80/03/28 ip
- --800410003B Certificate of Compliance 9020, Revision 3, for Model SL-10-1 MACDONALD, C E Transportation Branch 80/03/28 4pp

DOCKET /1 9089 MODEL 675 TECHNICAL OPERATIONS, INC

800408000' Pequests regi firstion as user of Models 676 & 676E D'ROURKE E les Alanc Disentific Laboratory 80/02/29 1

DOCKET /1 7036 HODLE | C 1 | SQUARE PRODUCTION EQUIPMENT CO

800403014T Notifies or expiration or Centificate of Compliance 9036 for Model v. 1 To continue using package, should submit consolidated application reduced number of drawings showing only significant safety features if renewal fee MACDUNALDIC E. Transportation Branch. 80703717. 1p

DOCKET 71-9039 MODEL 715 TECHNICAL OPERATIONS, INC

8004280129 Forwards application for renewal of Certificate of Compliance 9039 for Model 715 MUNRO.J J Tech/Ops (Technical Operations, Inc.) 60/04/11 ip

-8004280133 Application for menewal of Certificate of Compliance 9039 for Model 715 ror Model 715 * Terh/Ops (Technical Operations, Inc.) 80/04/11 34pp

DOCKET 71-9043 MODEL NAFO: NAVY, DEPT OF

800407006B Notifies or expiration of Centificate of Compliance 9043 for Model NUPU To continue using package should submit renewal Application
MACDONALD.C E Transportation Branch 80/03/17 1p

8004300082 Responds to 800317 itr Requests discontinuation as user of Model NUPU GROVES, K.L. Navy Dept or 80/04/04 ip

DOCKET 71-9044 MODEL GE-1500, GENERAL ELECTRIC CO.

8004250303 Requests registration as user of Models CNS-1-13C & TREMBLE.D C Arkansas Power & Light Co 80/03/24 1p

DOCKET 71-9045 MODEL GE-1000, GENERAL ELECTRIC CO

8004020300 Notifies of expiration of Certificate of Compliance 9045 for Model QE-1000 Continued use requires submittal of renewal application 1 ree MACDUMALD.C E Transportation Branch 80/03/14 1p

DOCKET 71-9046 MODEL GE-1100, GENERAL ELECTRIC CO

8004030009 Notifies or expiration of Certificate of Compliance 9046 for Model GE-f100 To continue using package, should submit renewal application & fee MACDONALD. C.E. Transportation Branch 80/03/14 1p

DOCKET 71-9049 MODEL GF-500, GENERAL ELECTRIC CO

8004010061 Requests renewal of Certificate of Compliance 9049 for GE Model 500 shipping container Forwards consolidated application for certification supporting renewal request Updated drawings submitted to NRC on 800208 CUNNINGHAM.C F General Electric Co 80/02/21 jp

--8004010065 "GE Shield Container, Model 300 " * General Electric Co 80/02/21 13pp

8004020304 Notifies of expiration of Certificate of Compliance 9049 for Model 6E-500 Continued use requires submittal of renewal Application & fee MACDONALD, C.E. Transportation Branch 80/03/14 ip

DOCKET 71-9050 MODEL GE-900, GENERAL FLECTRIC CO

8004030114 Notifies of espiration of Certificate of Compliance 9050 for Model 0E-900 To continue using package, should submit consolidated application, drawings & renewal fee MACDONALD.C E Transportation Branch 80/03/14 ip

POCKET /1-906/ MODEL BCL -3

8004070389 Requests registration as user of Model BCL-3 package FIT281MMONS.T R Fnergy. Dept of 80/03/13 ip

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

8004040092 Responds to 791112 ltr re registration for Model N-55 packaging Must have approved QA program prior to registration as uses of package Vendor ref to approved GA program is not acceptable
MACDONALD, C.E. Transportation Branch 80/03/07

DOCKET 71-9072 MODEL GAHC-1. GENERAL ATOMIC CO

8004040C95 Notifies of expiration of Certificate of Compliance 9072 for Model GAHC-1 To continue using package, should submit consolidated application drawings X renewal fee MACODNALD, C.E. Fransportation Branch 80/03/14 1p

DOCKET 71-9073 MODEL OH-142, NUCLEAR PACKAGING, INC

8004100228 Forwards Revision 2 to Certificate of Compliance 9073 for Model GH-142 MACDONALD.C E Transportation Branch 80/03/28 2pp

--8004100230 Certificate of Compliance 9073, Revision 2, for Model OH-142
MACDONALD, C.E. Transportation Branch 80/03/28 4pp

DOCKET 71-9079 MGDEL HN-100 SERIES 2. HITTMAN NUCLEAR & DEVELOPMENT

8004070010 Forwards Revision 4 to Certificate of Compliance 9079 for Model HN-100.Series 2 MACDUNALD.C E Transportation Branch 80/03/17 2pp

--8004070014 Certificate of Compliance 9079, Revision 4, for Model AN-100, Series 2 MACDONALD.C E Transportation Branch 80/03/17 3pp

DOCKET 71-9080 MODEL HR-600, HITTMAN NUCLEAR & DEVELOPMENT CORP

8004040276 Requests registration as user of Model HN-600 TRIMBLE.D C Arkansas Power & Light Co 80/02/19 1

8004070018 Forwards Revision 3 to Certificate of Compliance 7080 for Model HII-600 MACDONALD, C.E. Transportation Branch B0/03/17 2pp

--80040/0020 Certificate of Compliance 9080, Revision 3, for Model HN-600 MACDONALD, C E Transportation Branch 80/03/17 3pp

DOCKET 71-9081 MODEL CNSI-1600, CHEM-NUCLEAR SYSTEMS, INC

8004250303 Requests registration as user of Models CN8-1-13C & CNS-1-130
TRIMBLE,D C Arkansas Power & Light Co 80/03/24 1p

DOCKET 71-9089 MODEL NH-100 S. HITTMAN NUCLEAR & DEVELOPMENT CORP

8004080107 Forwards Revision 2 to Certificate of Compliance 9089 for Madel HN-100S Transportation Branch 80/03/18 2pp

--8004080112 Certificate of Compliance 9089, Revision 2, for Model HN-1008 MACDONALD, C E Transportation Branch 80/03/18, 2pp

DOCKET 71-9094 MODEL CHSI-14-195-H, CHEM-NUCLEAR SYSTEMS, INC.

8004210415 Advises that facilities will be using Models CN6-80A.7-100. CNSI-21-300 & CNSI-14-145-H for shipment of radioactive DOLAN.J E Indiana & Michigan Electric Co. 80/03/17 ip

- DUCKET 71-9096 MODEL CNSI-21-300, CHEM-NUCLEAR SYSTEMS, INC
- B004Q10415 Advises that facilities will be using Models CN6-80A.7-100. CNSI-21-300 & CNSI-14-195-H for shipment of radioactive

matis DDLAN, J E Indiana & Michigaπ Electric Co 80/03/17 ip

- DOCKET 71-9105 MODEL RAD-WASTE CR I, CHEM-NUCLEAR SYSTEMS, INC
- 6004250302 Requests registration as user of Models CSN-6-101 & CSN-15-160B Philadelphia Electric Co 80/09/28 1p

DOCKET 71-9111 MODEL CN6-80A, CHEM-NUCLEAR, INC.

8004210415 Advises that facilities will be using Models CNA-80A.7-100. CNSI-21-300 & CNSI-14-195-H for shipment of radioactive

DOLAN, J E Indiana & Michigan Electric Co 80/03/17 ip

- DUCKET 71-9113 MODEL 7-100, CHEM-NUCLEAR SYSTEMS, INC
- 8004210415 Advises that facilities will be using Models CNA-80A,7-100, CNSI-21-300 & CNSI-[4-195-H for shipment of radioactive matls DDLAN, J E Indiana & Michigan Electric Co 80/03/17 1p
- DOCKET 71-9122 MODEL 18-450, CHEM-NUCLEAR SYSTEMS, INC
- 8004070254 Notifies that response to 800129 ltr re Certificate of Compliance 9122 will be transmitted by 800315 REYNOLDB.L E Chem-Nuclear Systems, Inc 80/02/27 ip
- 8004090091 Submits results of review of use of Model 19-450 in response to NRC 800129 ltr Container has not been used for shipment of radioactive matis requiring NRC approval during 1979 & cannot be used during forseable future REYNOLDB.L E Chem-Nuclear Systems, Inc 80/03/04 2pp
- DOCKET 71-9130 MODEL NP-50-XXL, NUCLEAR PACKAGING, INC
- 8004220184 Forwards Drawing X=20-200b in support of Revision 2 amends to BAR for Model NP 50 Describes application of optional const matl configurations MAELBIO:R J Nuclear Packaging, Inc 80/02/25 3pp

- --8004220189 "Transportation Shield Type A. Models 50-1 5L. 50-2 5L, 30 & 50-4-OL "Sheet 1 of 2 # Nuclear Packaging, Inc. 78/08/09 ip
- ~-8004220193 "Transportation Shield Type A.Models 50-1 5L,50-2 5L,50-% 50-4 CL " Sheet 2 of 2 # Nuclear Packaging, Inc. 78/08/09 1p
- DOCKET 71-9132 MODEL 1-3, NUCLEAR PACKAGING, INC
- 8004086205 Ack receipt of complete application for Model T-3 package Based on vendor G00125 ltr.NRC believes that all outstanding issues have been resolved NRC is preparing approval & safety evaluation for package MACDONALD, C E Transportation Branch 80/03/20 1p
- DOCKET 71-9135 NODEL CENTURY, GAMMA INDUSTRIES
- 8004020025 Forwards items for insertion into application for NRC certificate of compliance for Century model devices mfg by Gamma Industries App C detailed drawings 2 revisions for Pages 0 2,7 7 A 2 7 38 encl RICHARDSON; H D Nuclear Systems, Gamma Industries Div 80/02/27
- DOCKET 71-9142 MODEL 2526. MONSANTO RESEARCH CORP
- 8004030354 Requests approval to ship Pu~238 in quantities greater than 20 but no greater than 100 Ci in DOT Spec 20 SC-4 shipping containers Fu~238 sources will be at least double—encapsulated in metal containers & will be leak tested TAYLOR.R R Monsanto Research Corp 80/03/05 19
- 8004210019 Forwards Revision O to Certificate of Compliance 9142 for Model MRC-20MC MACDUNALD, C E Transportation Branch 80/04/03 19
- ~-8004210021 Certificate of Compliance 9142.Revision O for Model MRC-2 MACDONALD.C E Transportation Branch 80/04/03 2pp
- DOCKET 71-9853 MODEL ORNL BNL NBS UN FUEL CONTAINER, ENERGY.
- 8004070247 Forwards recommended changes to NBS unirradiated shipping containers for approval per Certificate of Compliance 9850 TRAVIS.W H Energy, Dept of 80/02/21 2pp

COMMISSION MEETING RECORDS 8004010016 Transcript of 800319 meeting in Washington, DC re NRC enforcement program Po 1-59 * Commission 80/03/19 59pp --8004010017 SECY-B0-139 MA410017 SECY-BO-139
Describes various types of enforcement actions re request for Commission approval of general statement of enforcement policy
STELLO.V Office of Inspection & Enforcement, Office of the Director 80/03/13 39pp ---8004010021 Endorses objective re development of strong explicit enforcement program Requests mod of coordination statement to include benefits costs & Commission guidance HACLER.N M Office of Management and Program Analysis BO/03/10 200 8004020022 Transcript of 800319 Affirmation Session 80-11 in Washington,DC Pp 1-5 * Commission 80/03/19 Spp 8004020024 Transcript of 800317 hydrogen control meeting in Washington, DC Pp 1-92 * Atomic Safety and Licensing Board Panel 80/03/19 92pp --8004020028 SECY-80-107 (FRN)
Establishes technical bases re interim hydrogen control requirements for small containments Technical discussions DENTON H R Office of Nuclear Reactor Regulation 80/02/22 8004020051 Transcript of 800321 meeting w/citizen group on TM! cleanup in Washington, DC Pages 1-54 + Commission 80/03/21 56pp 8004090098 Transcript of 800321 Affirmation Session 80-12 in Washington, DC Pp 1-2 * Commission 80/03/21 2pp 8004070177 Transcript of 800324 meeting in Washington, DC re briefing on policy issues in emergency planning rule Pp 1-70 * Commission 80/03/24 71pp 8004090261 Transcript of 800331 meeting in Bethesda, MD re briefing on two approaches to treatment of inventory differences in nuclear mati accounting Pp 1-52 Viewgraphs encl * Commission 80703/31 55p 8004100033 Transcript of 800313 Affirmation Session 80~10 in Washington. DC Pp 1-5 * Commission 80/03/13 5pp --8004100039 SECY-80-095 Methoday Sect-Bordya Recommends NRC approval of FR publication of enci notice of demial of petition for rulemaking 2-5 SHAPAR:H K Office of the Executive Legal Director. 80/02/14 8004100429 Transcript of 800331 meeting in Bethasda,MD re physical protection of irradiated reactor fuel in transit Pp 1-33 * Commission 80/03/31 33pp

```
--B004100431 SECY-B0-166
Recommends NRC approval of amends to 10CFR73 for immediately effective requirements re physical protection of irradiated fivel in transit for publication in final form Draft FR notice and DIRCKS, M J Office of Nuclear Material Safety & Safeguards B0/03/28 52pp

B004170345 Transcript of AIF B00402 briefing in Washington, DC Pp 1-53 * Commission 80/04/02 54pp

--8004170350 Forwards "Rept to AIF Policy Committee on Followup to TMI Accident," re draft NUREO-0460 Large number of requirements proposed by plan can & should be reduced LEE, B Atomic Industrial Forum 80/02/22 3pp

--B004170352 "Rept to AIF Policy Committee on Followup to TMI Accident, by Working Oroup on Action Plan Priorities & Resources * Atomic Industrial Forum 80/02/29 100pp

B004180137 Transcript of B00410 briefing on waste mgt technical regulations in Betheada. MD Pp 1-28 * Commission 80/04/10 29pp

B004240471 Transcript of B00414 meeting in Washington, DC to discuss BECY-B0-139 & BECY-B0-130A Pp 1-59 * Commission 80/04/14 60pp

B004240476 Transcript of Commission & ACRB B00411 joint maeting in Washington, DC Pp 1-43 * Commission # ACRB - Advisory Committee on Reactor Bafeguards 80/04/11 45pp

B004250276 Transcript of B00415 briefing in Betheada, MD on status of environ qualification review for electrical components at operating power reactors Pp 1-78 * Commission B0/04/15 79pp

B004250344 Transcript of B00410 affirmation session in Bethesda, MD re SECY-79-6-18 * Commission B0/04/10 App

B004250344 Transcript of B00410 affirmation session in Bethesda, MD re SECY-79-6-18 * Gommission B0/04/10 App

B004250344 Transcript of B00410 affirmation session in Bethesda, MD re SECY-79-6-18 * Gommission B0/04/10 App

B004250344 Transcript of B00410 affirmation session in Bethesda, MD re SECY-80-6-18 * Gommission B0/04/10 App

B004250344 Transcript of B00410 affirmation session in Bethesda, MD re SECY-80-6-18 * Gommission B0/04/10 App

B004250345 Transcript of B00410 affirmation session in Bethesda, MD re SECY-80-6-18 * Gommission B0/04
```

--8004020114 Discusses conflicts in guidance & interpretation re offeit emergency plans per review of NUREO-0376, NUREO-0388 & draft NUREO-0410

--8004020120 Forwards comments on "Basis for Emergency Action Levels for Nuclear Power Facilities." Minor events having no effect on public health & safety do not warrant consideration of public officials or agencies

JURGENSEN,R W American Electric Power Co , Inc. 79/11/30 4pp

---B004020123 Comments on NUREO--0610 recommends four classes of emergence action levels in-plant occurrence, emergency alert, site emergency & general emergency WARD, U.E. Atomic Industrial Forum. 79/11/28 14pp.

---8004020128 Comments on NUREC-0610 draft estimate too low Experience indicates that, using draft examples of initiating condition, fraquency would be six to ten times per yr rather than once or twice
VETTER, W.E. Region 4, Dallas, Office of the Director 79/11/27.

NUREG-0610 GODWIN,A V. Alabama, State of 79/11/14 25pp

- --B004080661 Forwards comments on proposed Reg Guide I 97.Revision 2 format of Table 2 % 3 should be reversed so that purpose appears first Variable types D & E should be deleted from scope TAYLUR, J H Babcock & Wilcox Co 79/11/06 6pp
- 8004100392 Summary of 234th ACRS 791004-05 meeting in Washington, DC w/table of contents & Apps 1-16

 * ACRS Advisory Committee on Reactor Safeguards 79/12/04
 14000
- 8004100554 Discusses reactor siting criteria & response capabilities for potential accidents Prompt info on accident releases & likelihood of releases is important Suggests postulating accidents at listed situes to compare potential hazards WILSON,R Plant Systems Branch 79/12/20 3pp
- 8004110147 Comments on proposed rule 10CFR50 language is ambiguous in places More clarification & numerous editorial changes suggested ORENDON. I Affiliation Unknown 79/12/29 4pp
- B004140002 Marked-up "Possible Risk Criteria for Reactor Safety " WILBON.R ACRB - Advisory Committee on Reactor Bafeguards 79/12/31 App
- 8004140030 "On History of Evolution of LWR Bafety in US " OKRENT,D ACRS - Advisory Committee on Reactor Bafeguards 80/04/10 950pp
- 8004140035 Draft notification of ACRS 800207 meeting in Washington DC to discuss annual rept to Congress on NRC safety research program & proposed NRC plans for study of addi safety features for Zion Units 1 & 2 & Indian Point Units 2 & 3 HDYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/03/12 5pp
- 8004140042 Summary of ACRB Subcommittee 791104-07 meeting repreparation of annual rept on reactor safety research Related matis & list of attendees encl 4 ACRB Advisory Committee on Reactor Safeguards 79/12/04 21pp
- 8004140033 Notification of ACRS Subcommittee on B&W Water Reactors B00304 meeting in Washington, DC to continue discussion of transients of once-through steam generators Portions of meeting may be closed to protect proprietary info MCYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/02/11 3pp
- 8004140056 Notification of ACRS Subcommittee on LERs 800123 meeting w/NRC Ofc of Analysis & Evaluation of Operational Data in Washington DC to discuss evaluation of LER info HOYLE, J.C. ACRS Advisory Committee on Reactor Safeguards 79/12/20 ip
- BOO4140063 Notification of postponement of AGRS Subcommittee on LERs 800123 meeting HOYLE.J C AGRS Advisory Committee on Reactor Bafeguards 80/01/11 1p
- 8004140089 Notice of AGRS Subcommittee on ATWS 800125 open meeting in Washington, DC to discuss proposed resolution of ATWS HOYLE, J C AGRS Advisory Committee on Reactor Safeguards 79/12/20 ip
- 8004140121 Comments re ACRB Site Evaluation Subcommittee 771220 meeting on emergency planning Research required to define magnitude of activity releases in reactor accidents & realistic distances for emergency planning rones ORTH, D A E I du Pont de Nemoura & Co., Inc. 80/01/10 App
- 8004140466 Summarizes avaluation & questions stemming from 791113 visit to OETR site Believes greatest need is for tectonic syntheses both local & regional THOMPSON. O A Affiliation Unknown 79/12/12 Zpp
- 8004i50002 Notification of ACRS Ad Hoc Subcommittee on TMJ-2 Accident Action Plan 800305 meeting in Washington DC to consider Draft 3 of NRC plans for implementing recommendations of President's Commission HDYLE, J C. ACRS - Advisory Committee on Reactor Safeguards 80/02/13 3pp
- B004150005 Notification that ACRS Ad Hoc Subcommittee on TMI-2 Bulletins & Orders B00303 meeting is recheduled until B00304 ACRS Subcommittee on B&W Water Reactors B00304 meeting has been postponed indefinitely HOYLE, J C ACRS Advisory Committee on Reactor Safeguards B0/02/19 ip

- 8004150006 Responds to recommendations of NRC Special Inquiry Group re ACRB activities Agrees w/recommendation to retain ACRB in strengthened, modified role & concurs w/same criticism Addresses specific criticisms PLESSET.M B ACRB - Advisory Committee on Reactor Safeguards 80/03/12 2pp
- B004150010 Requests that memorandum identifying safety research needs for use of Office by Nuclear Regulatory Research & other groups be automatically sent to ACRS Research requests re TMI-2 accidents should be reviewed in broad perspective PLESSET. If S ACRS Advisory Committee on Reactor Safeguards B0/01/15 ip
- 8004150016 Summarizes review of near-term OL items from Draft 3 of NUREO-0660. "NRC Action Plans Developed as Result of TMI-2 Accident " Near-term OL Items provide satsfactory basis for resumption of licensing PLESSET. M S ACRS Advisory Committee on Reactor Safeguards 80/03/11 500
- 8004150017 Notification of ACRS Subcommittee open 800107 meeting in Washington DC to discuss procedures for conduct of ACRS activities & strengthening ACRS role in regulatory process HOVLE, J C ACRS Advisory Committee on Reactor Safeguards 79/12/17 1P
- 8004i50046 Recommends verification testing of decay heat removal under upset conditions in near-term OL plant test programs PLESSET.M 8 ACRS Advisory Committee on Reactor Safeguards 80/03/11 1p
- 8004190077 Notification of ACRS Subcommittee 800109 meeting in Washington DC to continue discussion re preparation of ACRS Annual Rept to Congress on NRC Reactor Safety Research Program HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 79/12/17 2pp
- 8004150111 Notification of ACRS Bubcommittee on B&W Weber Reactors 800108 menting in Washington.DC to discuss sensitivity to transients of once-through steam generator & other features of B&W designed nuclear plants HDYLE.J C ACRS Advisory Committee on Reactor Safeguards 79/12/17 Spe
- 8004190114 Nutification of AGRS Ad Hoc Subcommittee on YMI-2 Accident Action Plan 800107 meeting in Washington, DC to discuss NRC "Draft Action Plan for Implementing Recommendations of President's Commission & Other Studies of TMI-Accident "HOYLC, J C AGRS Advisory Committee on Reactor Bafeguards 79/12/17 3pp
- B004150122 Comments on proposed rule 10CFR90 requirements for local & state approval of licensee emergency plans can result in subversion of entire open licensing process by small group of individuals
 STEINDLER.H.J. Argonne National Laboratory 80/01/02 3pp
- 8004150208 Summarises comments resulting from ACRS 209th meeting review of NRC Task Force on Bulletins & Orders recommedations of TMI-2 & generic evaluations of loss of feedwater transients & small break LUCAB PLESSET, MS ACRS Advisory Committee on Reactor Safeguards, 80/03/11. Soc
- 8004180212 Notification of AGRS 800110-12 meeting in Washington.DC to discuss proposed recommendations to Congress on NRC safety Research Program, NRC action plans to implement THI-2 accident studies & proposed changes in siting criteria. HOYLE.J C AGRS Advisory Committee on Reactor Bafeguards 79/12/20 6pp
- 8004150222 Notification of ACRS Subcommittee on Metal Components 800123-24 meeting in Washington, DC to review status of unresolved generic safety items involving pressure vessels, steem generators & other pressure boundary components HOYLE, J. C. ACRS Advisory Committee on Reactor Safeguards 79/12/20 ip
- 8004150228 Notification of ACRS Subcommittee on ECCS 800326 meeting in Washington, DC to discuss analysis of small break LOCAs on Wastinghouse upper head injection reactors Portions of meeting may be closed to protect proprietary info HDYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/03/05 3pp
- 8004190230 Discusses ACRS 791115 meeting re extreme external phenomena Subcommittee Technical quality of Seismic Bafety Margins Research Program seems high Determining strain rate should be major objective THOMPSON.O A Affiliation Unknown. 79/12/14 ip

- 8004150232 Notification of ACRS Subcommittee on Concrete & Concrete Structures 800325-26 meeting in Washington DC to review user needs in structural engineering HGYLEJ C ACRS Advisory Committee on Reactor Safeguards 80
- 8004150236 Notification of ACRS Subcommittee on ATMS 800326 meeting in Washington, DC to continue discussion on proposed resolution of ATWS Portions of meeting may be closed to protect proprietary info
 HGYLE, J C ACRE - Advisory Committee on Reactor Bafeguards 80/03/05 3pp
- 8004150240 Notification of ACRS Ad Hor Subcommittee on Natural Circulation Heat Removal 800325 meeting in Washington.DC to review info on natural circulation & bleed & feed heat removal sys & determine areas where info is inadequate HOYLE.J C ACRS Advisory Committee on Reactor Safeguards 80/03/05 3pp
- 8004150241 Notification of proposed ACRS subcommittee, working group & full committee meetings 800103-0306
 HOYLE.J C ACRS Advisory Committee on Reactor Safeguards 79/12/17 4pp
- 8004150244 Notification of proposed ACR9 subcommittee,working group & full committee meetings 800123-0412 HGYLE.J C ACRB Advisory Committee on Reactor Safeguards 80/01/17 4pp
- 8004150245 Notification of ACRS 800306-08 meeting in Washington, DC to discuss implementation of NRC "Action Plans for Recommendations of Presidents' Commission" & other studies of TMI-2 accident HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/02/19 6pp
- 8004150249 Addition to agenda for ACRS Ad Hoc Subcommittee on TMI-2 Accident Implications 800305 meeting to consider addl engineered safety features, including installation of molten core crucibles Under reactors HOYLE.J.C ACRS Advisory Committee on Reactor Safeguards 80/02/21 19
- 8004150254 Notification of ACRS Subcommittee on TMI-2 Accident Implications 800305 meeting in Washington, DC re installation of molten core crucibles at Indian Point Units 2 & 3 & Zion Units 1 & 2.
 HOYLE, J C ACRS Advisory Committee on Reactor Safeguards ACRS - Advisory Committee on Reactor Bafeguards
- 8004150272 Transcript of ACRS Subcommittee on Reactor Safety Research 800409 meeting in Washington, DC Pp 1-80. * ACRS Advisory Committee on Reactor Safeguards 80/04/09 80pp
- 8004150306 Transcript of ACRS Subcommittee on Power & Electrical Sys 800409 meeting in Washington: DC Pp 1-B5 * ACRS Advisory Committee on Reactor Safaguards 80/04/09 85pp
- 8004150321 Transcript of ACRS Subcommittee on Regulatory Activities 800409 meeting in Washington DC Pp 1-133 * ACRS Advisory Committee on Reactor Safeguards 80/04/09
- 8004160046 Evaluates 791119-16 BBMRP mesting re nuclear plants seismic safety. Repts indicate progress & accomplishment Majority of personnel presentations were of high quality. Development of sus for overall assessments doubtful WHITE, N.P. White, M. P. Consulting Engineer 79/12/24 ip
- 8004170320 Transcript of ACRS Subcommittee on B&W Water Reactors 800408 meeting in Washington.DC re sensitivity of vendor sys to feedwater transients Pp 1-194 * ACRS,- Advisory Committee on Reactor Safeguards 80/04/08
- 8004170358 Detailed schedule & outline for discussion re 239th ACRS meeting on 800306-08 in Washington.DC * ACRS Advisory Committee on Reactor Safeguards 80/02/28 3pp
- 8004170361 Apps to minutes of 236th ACRS meeting on 791206-08 in Washington, DC ACRS - Advisory Committee on Reactor Safeguards. 79/12/08

130pg

8004180003 Comments on ACRS Subcommittee on ECCS/S&O 800103-04 meeting Measured parameters other than pressure are gross indicators of increasing void fraction within pressurized sys Reduced pump speed is alternative to delayed pump to page 200108 2pp ACOSTA:A. California Institute of Technology 80/01/08 2pp

- 8004180017 Schedule & outline for discussion re 238th ACRS meeting on 800207-09 in Washington.DC * ACRE - Advisory Committee on Reactor Safeguards 80/01/28 4pp
- 8004180025 Notice of receipt of addl info for ACRS Subcommittee on TMI-1 Nuclear Power Plant 800131-0201 mosting in Middletoun. PA Designated federal employee is R Muller Also corrects first word in last paragraph HDYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/01/18 1p
- 8004180032 Notice of change in agenda for ACRS Subcommittee on ATMS 800125 meeting Meeting will include matters involving proprietary info Portion of meeting may be closed to protect proprietary info HOYLE, J C ACRS Advisory Committee on Reactor Safeguards
- B0041B0036 Notification of ACRS Subcommittee on THI-1.B00131-0201 meeting w/util & public in Middletown.PA Portions of meeting may be closed to protect proprietary info MOYLE,J C ACRS Advisory Committee on Reactor Bafeguards 80/01/11 3pp
- 8004180044 Natification of ACRS Subcommittee on Reliability & Probabilistic Assessment 800206 meeting in Washington. DC to discuss consistency of component failure experience u/WASM-1400 projection HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/01/14 1p
- 8004180049 Natification of proposed ACRS subcommittee & working group meetings
 HOVLE.J.C ACRS - Advisory Committee on Reactor Safeguards
 80/01/19 4pp
- 8004180074 Summary of 238th ACRS meeting on 800207-09 in Washington, DC Includes items tentatively scheduled for consideration at 239th ACRS meeting on 800306-08 PLESSET, M S ACRS Advisory Committee on Reactor Safeguards 80/02/22 2pp
- 8004180079 Summary of 237th ACRS meeting on 800110-12 in Washington, DC Includes items tentatively scheduled for 238th ACRS meeting on 800207-09 PLESSET, M S ACRS Advisory Committee on Reactor Safeguards 80/01/24 2pp
- 8004180085 Notification of ACRS Ad Not Subcommittee on TMI-2 Accident Action Plan 800401-02 meeting in Washington DC to discuss Draft 3 of NURCO-0660 Portions of meeting may be closed to protect proprietary info HOYLE, J C ACRS Advisory Committee on Reactor Safeguards 80/03/10 3pp
- 8004180150 Transcript of 240th ACRS 800411 general meeting in Washington,DC Pp 1-247 * ACRS Advisory Committee on Reactor Safeguards 80/04/11 254pp
- 8004180406 Notification of ACRS Subcommittee on ECCS & Reactor Fuels
- 8004180481 Comments re ACRS Site Evaluation Subcommittee 791220 meeting on proposed rule 10CFR50. "Emergency Planning " Efforts to complete plans as early as possible may result in unrealistic deadlines & unnecessary plant shutdowns FOSTER.R F Affiliation Unknown 80/01/12 3pp
- 8004180498 Notification of ACRS Subcommittee on Plant Arrangements BOO220-21 meeting w/Bandia Labs in Washington DC to discuss "Final Rept (draft) on Phass I of Generic Task A-17, Bys Interaction in Nuclear Power Plants" & items re LWRs HOYLE J C ACRS - Advisory Committee on Reactor Safeguards Interact. HOYLE, J C ACI
- 8004180506 Notification of ACRS Ad Hoc Subcommittee on TMI-2 Accident Bulletins 4 Orders 800303 meeting in Washington, DC to continue consideration of IE bulletins 4 NRC orders pertaining to TMI-2 accident HOYLE, J C ACRS Advisory Committee on Reactor Bafeguards 80/02/11, 3pp
- 8004210001 Transcript of 240th ACRS general meeting in Washington DC on 800410.Pages 1-263 * ACRS Advisory Committee on Reactor Bafeguards 80/04/10. 263pp

- 8004210311 Transcript of Ad Hoc Subcommittee 800326 meeting re natural circulation heat removal in Washington DC Pp 1-269
 * ACRS Advisory Committee on Reactor Bafeguards 80/03/26
 27000
- 8004210313 Transcript of Subcommittee on ATMS 800326 meeting in Mashington,DC Pp 1-215

 * ACRS Advisory Committee on Reactor Safeguards 80/03/26
- 8004220785 Responds to NSSB vendors presentations at ATMS 800125 meeting re Alternative 3A & 4A mods Vendor cost estimates are inflated Both alternative mods should be imposed on all plants

 8AUNDERB B C ACRS Advisory Committee on Reactor Safeguards
- 8004240476 Transcript of Commission & ACRS 800411 joint meeting in Washington, DC Pp 1-43 * Commission * ACRS - Advisory Committee on Reactor Bafeguards 80/04/11 45pp
- 8004250250 Transcript of 800422 subcommittee meeting in Washington, DC re LERs Pp 1-138

 ACRS Advisory Committee on Reactor Safeguards 80/04/22

COMMISSION NRC COMMISSIONERS

- 7908140243 Ack receipt of 790509 Itr to Hendrie re establishment of new safety position in facilities to improve emergency response Discusses review of reactor operator qualifications Invites further suggestions Forwards info re operator licensing DENTON.H R Office of Nuclear Reactor Regulation 79707/02 2pp
- --790B140247 Suggests NRC & utils jointly create new safety position in facilities Outlines qualifications & duties STAUDT.H R Bunker-Ramo Corp , Amphenol North America Div 79/05/09 4pp
- 8004020173 Responds to 800210 ltr re device for dispensing iodine in water as thuroid blocking agent NRC looks forward to FDA review of new technique DENTON.H R Office of Nuclear Reactor Regulation 80/03/06 ip
- --8004020179 Discusses nowly designed iodine device, used as alternative to potassium exide for emergency source of thyroid blocking agent in event of accident wiradicactive iodine release to atmosphere Device has unlimited storage life POLLEY, R D Omnidine Corp 80/02/15 2pp
- 8004020175 Ack receipt of yearly invitation to speak at ALT-ABA course on atomic energy licensing & regulation in Sept Requests tentative status due to prior commitments HENDRIE: J M Commission BO/03/03 ip
- --8004020199 Extends invitation to Commissioner, as luncheon speaker at ALI-ABA course on atomic energy licensing & regulations on 800925 GREEN, H.P. Fried, Frank, Harris, Shriver & Kampelman, 80/02/19
- B004030335 Discusses results of encl rept. "NRC Environ Analysis of Nuclear Accidents Is It Adequate " Typical EIS feils to analyse Class 9 accidents despite potential for greatest environ harm & public concern SPETH.0 President of US & Executive Offices 80/03/20 iipp
- --8004030340 "NRC Environ Analysis of Nuclear Accidents Is It Adequate " ENTWISLE, E., WEXLER, D. Environmental Law Institute, 80/02/04 200pc
- 8004080037 Provides Subcommittee on Energy & Environ w/updated info re NRC need for power determinations, in response to 790801 request Electricity demand forecasting techniques are being improved. Supporting documentation encl AHEARNE, J F Commission 80/03/11 App
- --8004080048 Forwards response to 780530 inquiry re NRC need for power determination procedures Need for power determinations made by NRC are part of NEPA reviews required prior to CP or OL issuance
 HENDRIE, J M Commission 78/07/19 10pp
- ~~8004080059 Forwards excerpts from decisions re need for power MANN, M M Atomic Safety and Licensing Board Panel 78/06/29

- ---B0040B0063 Requests info re NRC need for power determination procedures, per NRC 7B0522 testimony on Nuclear Siting & Licensing Act WEAVER, J. House of Rep. Interior & Insular Affairs 79/05/30 3pp
- --8004080066 Asks specific questions re NRC need for power determination, based on J Weaver 780530 inquiry
 UDALLIM K House of Rep , Interior & Insular Affairs 77/08/01
- 6004080070 Summary of 238th ACRS meeting in Washington,DC on 800207-09 PLESSIT.M S ACRS - Advisory Committee on Reactor Safeguards 80/02/22 2pp
- 8004080071 Comments on GAO rept, "NRC More Aggressive Leadership Needed" Steps are being taken to improve Commission Isadership in GAO recommended areas AHEARNE, J F Commission 80/03/14 3pp
- ---B0040B0108 Comments on GAO rept. "NRC More Agressive Leadership Needed" Steps are being taken to improve Commission leadership in GAO recommended areas Response to rept vecommendations enel AHEARNE.JF Commission B0/03/14 26pp
- 8004080223 Provides Bubcommittee on Public Works w/info re proposed changes to NRC FYBO base table Carryover funds from FY79 would be applied to priority unfunded tasks identified during post-TMI invastigations
 AHEARNE, J F Commission 80/03/07 1p
- --8004080227 Provides Subcommittee on Energy & Environ w/info re proposed changes to NRC FY80 base table Carryover funds from FY79 would be applied to priority unfunded tasks identified during post-TMI investigations AHCARNE.JF Commission 80/03/07 1p
- --B0040B0227 Provides Subcommittee on Nuclear Regulation w/info re proposed changes to NRC FYRO base table Carryover funds from FY77 would be applied to priority unfunded tasks identified during post-TMI investigations A
- ---8004080231 Provides Subcommittee on Energy & Power w/info reproposed changes to NRC FY80 base table Carryover funds from FY77 would be applied to priority unfunded tasks identified during post-TMI investigations
 AHEARNE, J F Commission 80/03/07 ip
- --8004080234 Provides Subcommittee on Energy & Water Development w/info re proposed changes to NRC FY80 base table Carryover funds From FY79 would be applied to priority unfunded tasks identified during post-TMI investigations AHEARNC, J F Commission 80/03/07 4pp
- 8004080243 Provides Subcommittee on Nuclear Regulation w/response to 800213 inquiry concerning NRC actions re federal nuclear waste mgt program
 AHEARNE J F Commission 80/03/06 7pp
- --8004080250 Requests addi info re federal waste mgt program, to clarify NRC testimony at 800123 hearing before Bubcommittee on Nuclear Regulation HART, O Senatu, Environment & Public Works 80/02/13 2pp
- 800408026B Forwards list of reactor sites to which FEMA should give priority in making independent estimates of evacuation times.per 800114 memorandum of understanding List includes addl sites not previously discussed.

 A
- 80040B0317 Responds to 800221 inquiry re basis for Commission concurrence in amended agreement between US & IAEA re matls safeguards. Amend maintains US nonproliferation policy stds to promote peaceful nuclear cooperation
 AHEARNELUE Commission 80/03/14 2pp
- --8004080323 Requests views on basis for Commission concurrance in amended agreement between US & IAEA re matls safeguards. Also requests views on Commission expectations re responsibility for supply agreements under amended US & IAEA agreement GHURCH, F Senate, Foreign Relations Committee 80/02/21 5pp.
- 8004090066 Weekly info rept for wk ending 800314 REHM.T A Office of the Executive Director for Operations. 80/03/14 27pp.

- 8004100509 Discusses priorities re safety, resumption of licensing nuclear power plants & issuing CPs in response to 791121 ltr Priority will continue to be given to operating plants as opposed to plants awaiting CPs
 AHEARNELJF Commission 80/02/12 ip
- --B004100513 Discusses balancing of priorities re licensing & implementation of post-TMI safety recommendations Equally intensive effort should be focused on plants in need of OLs & CPs MCCDLLAM, W Edison Electric Institute 79/12/21 Rpp
- 8004100592 Heekly info rept for wk ending 800321 REMM.T A Office of the Executive Director for Operations 80/03/25 24pp
- 8004:40392 Provides add1 comments re 800226 discussion on advanced reactor research program Decision re continuation of NRC advanced reactor safety research program should be separable from DDE development programs
 HENDRIE, J M Commission 80/03/18 ip
- BOO4140457 Heekly info rept for week ending 800328 REHM.T.A Office of the Executive Director for Operations BO/04/04 55pp
- BOO4150137 Notifies of reappointment to ACRS for four-yr term beginning BOO401 AHEARNE, J.F. Commission BO/03/11 Ip
- 8004150317 Notifies of re appointment to ACRS for four-yr term beginning 800402 AHEARNE, J. F. Commission 80/03/11 1p
- _ 8004160024 Ack receipt of Recommendation 79-5, re hybrid rulemaking procedures of FTC Indicates that recommendation & encl rept should prove helpful to NRC AMEARNE, JF Commission 80/03/10 2pp
- --B004160030 Forwards Recommendation 79-5, re hybrid rulemaking procedures of FTC Requests NRC support & cooperation re implementation BABCOCK, B.L. Administrative Conference of the U.B. 80/01/08
- 80041601B6 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by B00415. FR notice encl AMEARNE. J F Commission 80/03/12 ip
- --B004160190 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl
 AHEARNE.J F Commission 80/03/12 2pp
- ---8004160193 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by B00415 FR notice encl AHEARNE.JF Commission 80/03/12 2pp
- --B004160176 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by by 800415 FR notice encl AHEARNE.J.F. Commission 80/03/12 2pp
- --8004160200 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE, J. F. Commission 80/03/12 2pp
- --B004160202 Requests comments on proposed rulemaking concerning disposal of radiastes produced by nuclear facilities Comments due by B00415 FR notice encl AHEARNE, J F Commission B0/03/12 2pp.
- ---8004160203 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415.FR notice encl
 AHEARNE.J F. Commission 80/03/12 2pp
- --B004160206 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by B00415 FR notice encl.

 AHEARNE, J. F. Commission 80/03/12 2pp
- --8004i60207 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415.FR notice encl AMEARNE, J F Commission. 80/03/12 2pp

- --8004160212 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AMEARNE. J F Commission 80/03/12 2pp
- --8004160215 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by B00415 FR notice encl AHEARNE, J F Commission B0/03/12 Zpp
- --B004160220 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by B00415 FR nutice encl AHEARNE.JF Commission 80/03/12 5pp
- 8004170112 Accepts invitation to speak to New York Patent Law Association in May HENDRIE, J. M. Commission 80/02/27 ip
- --8004170117 Extends invitation to be guest speaker in May, at annual dinner meeting for New York Patent Law Association STRASSER, J A Hill & Knowlton, Inc 80/02/15 2pp
- 8004180008 Provides Subcommittee on Nuclear Regulation w/response to 791207 ltr.Question 2 d concerning H R 5809 & 5819 re low level radwaste disposal States should approach waste disposal problem on regional basis AHEARNE, J F Commission 80/03/31 6pp
- --8004180016 Requests response to questions to low level radwaste disposal, for related 800124 & 25 hearings H R 5809 & 5819 encl HART, 6 Senate, Environment & Public Works 79/12/07 1ipp
- 8004180023 Piscusses NRC actions taken in response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AHEARNE, J F Commission 80/03/31 4pp
- --B004iB0078 Forwards position paper supporting Agreement State program Paper includes comments on advantages of Agreement State vs NRC administering radiation health & safety program TEDFORD, C.F. Arizona, State of B0/01/23 Opp
- ---8004180092 Discusses NRC actions taken in response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established to verify that serious violations are corrected AMEARNE, J F Commission 80/03/31 4pp
- --B004iB00B6 Provides Bubcommittee on Nuclear Regulation w/NRC response to recommendations in QAO rept. "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AKEARNE, J F Commission B0/03/31 4pp
- --B0041B0095 Provides Subcommittee on Energy & Environ w/NRC response to recommendations in OAO rept. "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AHEARNE.JF Commission 80/03/31 App
- --B004180097 Provides Subcommittee on Energy & Power w/NRC response to recommendations in GAO rept. "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AHEARNE, J. F. Commission 80/03/31 App
- --BOO4iBO100 Provides Bubcommittee on Environ.Energy & Natural Resources w/NRC response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AMEARNE.J F Commission BO/03/31 4pp
- --B004iB0i01 Discusses NRC actions taken in response to recommendations in OAO rept. "Radistion Control Programs Provide Limited Protection " Insy followup procedures will be established to varify that serious violations are corrected AHEARNE.JF Commission 80/03/31 4pp
- ---8004180103 Discusses NRC actions taken in response to recommendations in QAO rept. "Radistion Control Programs Provide Limited Protection" Insp followup procedures will be established to verify that serious violations are corrected AHEARNE, J F Commission 80/03/31 4pp

- 8004180128 Provides Subcommittee on Energy & Water Development w/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 W/o encl AHEARNE, J F Commission 80/03/25 2pp
- ~-8004180142 Provides Subcommittee on Energy & Environ w/"Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization 8111 for FY79 W/o encl AHEARNE. J F Commission 80/03/25 2pp
- --8004180153 Provides Subcommittee on Energy & Water Development w/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 W/o encl AHEARNE.J F Commission 80/03/25 2pp
- --8004180164 Provides Subcommittee on Energy & Power of "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 AHEARNE.J F Commission 80/03/25 2pp
- ~~8004180175 Provides Subcommittee on Nuclear Regulation w/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization 3(11 for FY79 W/o encl AHEARNE, J F Commission 80/03/25 2pp
- --B004180185 Forwards "Ropt to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 W/o encl
 AHEARNE. J F Commission B0/03/25 2pp
- --8004180193 Provides Gubcommittee on Environ Energy. & Natural Resources ω/ "Rept to Congress on Resident Inspector Program," in response to Committee on Interstate & Foreign Commerce request accompanying NRC Authorization Bill for FY79 AHEARNE.J F Commission 80/03/25 2pp
- --8004180197 "Rept to Congress on Resident Inspector Program "
 GREHER: Office of Inspection & Enforcement, Office of the
 Director TKOMPSON, S. R., SLIDER, J. E. Teknekron, Inc. 80/03/31
- 8004180211 Responds to 800128 ltr re NRC emphasis on emergency planning for nuclear accidents NRC & FEMA cooperate in developing emergency planning rules & related state guidance AHEARNE, J F Commission 80/03/16 ip
- --B0041B0220 Comments on proposed rule re emergency planning more emphasis should be placed on planning for probability of catastrophic nuclear accident in context of potential danger from nuclear weapons & other possible diasters

 WYDLER.J W House of Rep B0/01/2B ip
- 8004180240 Provides Subcommittee on Energy & Environ w/response to 800311 questions for record of subcommittee hearing on FY81 budget request AHEARNE.J F Commission 80/03/28 26pp
- 8004180279 Forwards response to 791206 inquiry re NRC Agreement States program & Church Rock dam failure RI submittal satisfied Atomic Energy Act. Section 274 requirements for admission as Agreement State
 AHEARNE, J.F. Commission 80/03/17 10pp
- ---BOO4180298 Advises that Environ Improvement Board will promulgate implementation of proposed revisions to regulations re health & environ aspects of radiation BACA-T E New Mexico, State of 79/10/18 ip
- 8004180304 Responds to 791120 ltr re certain aspects of NRC proposed new 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories; Procedural Aspects " Need for in situ testing & exploration supported by USOS.NAS & earth science community AHEARNE, J F Commission 80/03/18 Spp
- ---B004180311 Responds to 791120 ltr re certain aspects of NRC proposed new 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories/Procedural Aspects " Need for in situ testing & exploration supported by UBOS.NAS & earth science community AHEARNE.J F Commission B0/03/18 Spp
- --8004180319 Comments on Proposed Rule 10CFR60 multiple geologic testing & exploration unnecessary & costly NRC should support DOE repository development program WYDLER,J W House of Rep., Science & Technology 80/01/20 2pp

- 8004230095 Responds to 800118 ltr re concern & dissatisfaction w/Region 1 workshop on proposed changes in NRC rules on emergency preparedness Memo providing summary of results of four workshops encl Apologizes for inconvenience AHEARNE, J.F. Commission 80/03/21 2pp
- ~~8004230110 Discusses four workshops re proposed emergency planning rule changes held on 800115,17,22 & 24 Rept will be prepared summarizing lessons learned from series of workshops re conduct of public meetings Agenda enci COLLER,K R Division of Siting, Health & Safeguards Standards 80/01/28 7pp
- --8004230118 Informs NRC of deep concern & dissatisfaction w/Region 1 workshop on emergency planning held 800115 Meeting accomplished next to nothing Suggests NRC undertake extensive measures to recover valuable comments & input VANDENBURGH.D E Yanker Atomic Electric Co 80/01/18 2pp
- 8004240528 Forwards point-by-point response to ACRS 800311 rept re near-term OL items from Draft 3 of NUREG-0660 Criteria used in near-term OL reviews are not suitable for all licensees DIRCKS, W J Office of Nuclear Material Safety & Bafeguards 80/04/01 11pp
- 8004250046 Weekly info rept for wk ending 800404 REHM.T A Office of the Executive Director for Operations 80/04/09 30pp
- 8004280446 Ack receipt of paper, "Practical Development of Safety Requirements " Forwards Rogovin rept 4/o encl KENNEDY, R T Commission 80/01/31 ip
- 8004280448 Ack receipt of 800110 telegram Will be unable to attend 15th Intl Nuclear Energy Symposium KENNEDY,R T Commission 80/02/04 ip
- B0042B0450 Forwards summary of MIT meeting re Seabrook licensing proceedings W/o encil
 KENNEDY,R T Commission 80/02/06 ip
- 8004280455 Ack receipt of 800123 ltr re agreement state program Proposals contained in ltr will be helpful in promoting batter relationships between NRC t states KENNEDY, R T Commission 80/02/08 ip
- ---B004280459 Discusses need to reaffirm agreement state program Details specific areas where program improvements are required. TELFORD.C F Afizona, State of, B0/01/23 6pt
- BOO4280464 Supports comments contained in ltr published in 800220 Washington Post Encourages efforts to correct editorial imbalance re nuclear industry KENNEDY,R T Commission 80/02/20 ip
- 8004280468 Ack receipt of rept of Governor's Commission on TMI Will forward Special Task Force Rept on TMI in near future KENNEDY,R T Commission 80/03/05 ip
- BO04280471 Forwards papers W/o encl KENNEDY, R T Commission 79/12/21 ip
- 8004280485 Ack receipt of comments on recent visit to US Shares conclusion that intl cooperation is of increasing importance KENNEDY, R. T. Commission 79/12/21 1p
- --8004280488 Discusses impressions from recent tour of US Necessity of intl cooperation in energy field is of Upmost importance HAKANSBON, K Sweden 79/12/11 1p
- 8004290126 Withdraws as speaker at 15th Intl Nuclear Energy Symposium, due to extensive safety reviews following YMI KENNEDY,R T Commission 79/12/28 1p
- 8004290131 Offers congratulations on reappointment as acting chairman of Japan Atomic Energy Commission KENNEDY, R T Commission 80/01/02 ip
- 8004290134 Extends thanks for copy of proceedings of symposium on "Energy What Now" KENNEDY, RT Commission 80/01/29 ip
- 8004290144 Forwards Ragovin Rept W/o encl KENNEDY, R T Commission 80/01/31 ip.

- 8004300231 Extends appreciation for rept. "Intelligence Requirements for the 1980's Elements of Intelligence" KENNEDY,R T Commission 80/01/04 ip
- 8004300233 Act receipt of T Ipponmatsu paper KENNEDY, R T Commission 79/12/28 ip
- BO04300591 Responds to invitation to attend lecture on B00205 Other commitments prevent attendance KENNEDY,R T Commission BO/01/30 1P
- BG04300597 Buggests B00414-17 as best dates for meeting in AZ KENNEDY, R T Commission 79/12/27 ip
- B004300601 Responds to B00312 ltr re NRC research involving human subjects Forwards FY80 program briefs for three projects involving human subject research
 BUDNITZ.R J Division of Reactor Safety Research FIN 8-2283
- --B004300606 Requests info re NRC research projects involving human subjects Forwards PL 95-622 establishing commission for study of ethical problems in research programs MISKKIN-B President's Comm for Study of Ethical Prob in Med & Biome & Behav Research B0/03/12 Bpp
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 8004010002 Notification of contract execution, Mod 5 to "Evaluation of Thorium Content of Human Tissues From Grand Junction, Co " Contractor NY Univ Medical Ctr HAGEY, H Research Contracts Branch FIN B-5756 NRC-04-76-358 80/02/25
- ~~8004010009 Mod 5.extending period of performance & increasing funds to "Evaluation of Thorium Content of Human Tissues From Grand Junction Co" KV Research Contracts Branch POTTE FIN 8-5756 NRC-04-76-358 80/02/25 MORTON, K V POTTER, J P
- 8004020205 Natification of contract execution Mod 6 to "Bubble Behavior in LMFBR Core Disruptive Accidents " Contractor Univ of VA JACOBS: A Research Contract: Branch FIN 8-5616 NRC-04-75-316 80/02/15 1p
- --B004020215 Mod 6, adding funds, extending term through 800930 & providing addi scope, to "Bubble Behavior in LMFBR Care Disruptive Accidents"
 - dents " ON,K V Division of Contracts MUNGER,PL Virginia, Univ FIN 8-9616 NRC-04-75-316 80/02/15 4PF
- 8004030011 Notification of contract execution.Mod 4 to "Mobile Lab " Contractor Mobile Sys MIOOINS.E Administrative Contracts Branch NRC-05-79-257 80/03/26 lp
- --B004030014 Mod 4, extending delivery schedule for Items E 2 & E 3, to "Mobile Lab" HATTIA:H J Administrative Contracts Branch KIMMEL, J J Mobile Bystems, NRC-05-79-257 B0/03/26 ip
- B004030020 Notification of contract execution Mod 3 to "Pioneer Uravan Mill Tailings Evaluation " Contractor FC Hart Associates.

 E00EMORTH.P J Technical Assistance Contracts Branch FIN B-4923-9 NRC-02-79-051 B0/03/19 ip
- --8004030023 Mod 3. extending period of performance, to "Pioneer Uravan Mill Tailings Evaluation" DUOHERTY, D J Technical Assistance Contracts Branch FIN 8-6923-9 NRC-02-79-051 80/03/19 ip
- 8004030032 Notification of contract execution Mod 2 to "Advanced Process Control " Contractor Science Applications, Inc FOSTER, J M Technical Assistance Contracts Branch FIN B-6930-7 NRC-02-79-043. 80/03/17 lp
- --8004030037 Mod 2, revising statement of work, changing project officer, adding Article 9 to schedule 8, extending performance period to "Advanced Process Control"

 DOUGHERTY, D. J. Technical Assistance Contracts Branch, TREVING, T. Brience Applications, Inc. FIN B-4930-9, NRC-02-79-043-1 80/03/17, 3pp

- 8004030040 Notification of contract execution "Lease 10 Class III FLYNN, M Administrative Contracts Branch NRC-10-80-971 80/05/05
- --8004030044 Contract "Lease 10 Class III Sedans," awarded to We Try Harder, Inc MATTIA, M J Administrative Contracts Branch NRC-10-80-371 80/05/05
- 8004040116 Notification of contract execution, Mod 1 to "Auxiliary & Emergency Feedwater Pump Reliability " Contractor Franklin Research Ctr HDYLE.A Administrative Contracts Branch FIN B-6819 NRC-03-79-161 80/02/20 1p
- --8004040120 Mod 1.extending performance period to 800630.to "Auxiliary & Emergency Feedwater Pump Reliability " PERLMAN.J Division of Contracts ASHTON, A M Franklin Institute/Franklin Research Center FIN 8-6819 NRC-03-79-161 80/02/20 1p
- BOO4040154 Notification of contract execution, Mod 2 to "Enhancement of Nuclear Matis Mgt & Safeguards Sys " Contractor Bosing Computer Sycs Co FOSTER, J M Technical Assistance Contracts Branch FIN B-6902-9 NRC 02-79-050 B0/03/17 1p
- ~-B004040162 Mod 2,adding Article 9 re utilization of small business concerns & disadvantaged ownership & control, to "Enhancement of Nuclear Matls Mgt & Safeguards Sys "
 DDUOHERTY,D J Technical Assistance Contracts Branch
 HOPKING,H R Boeing Computer Services, Inc (subs of Boeing Co
 FIN B-6902-9 NRC-02-79-050 80/03/17 2pp (subs of Boeing Co)
- 80040401B0 Notification of contract execution, Mod 1 to "Bynthesis of Physical Security & Matl Control & Accounting Assessment Results "Contractor Science Applications Inc FOSTER. J M Technical Assistance Contracts Branch FIN 8-6412-9 NRC-02-79-029 80/03/21 1p
- ~-8004040186 Mod 1,adding Article 9 re utilization of small business concerns & disadvantaged individual ownership & central, to "Bynthesis of Physical Security & Matl Control & Accounting Assessment Results"

 DOUGHERTY, D J Technical Assistance Contracts Branch TREVING, T Science Applications, Inc FIN 8-6412-9 NRC-02-79-029 80/03/21 2pp
- 8004040197 Mod 2, extending performance period, to "Licensing Assistance/ Tailings Mgt Program Technical Evaluation Exxon Highland U Mill "
 DOUGHERTY.D J Technical Assistance Contracts Branch FIN 11-6446-9
 NRC-02-79-031 80/02/29 ip
- 8004040212 Notification of contract execution.Mod 3 to "Cyprus Mines Corp.Hansen Project Mill Tailings Evaluation " Contractor FC Hart Associates EDDEWORTH.P J Technical Assistance Contracts Branch FIN B-6927-9 NRC-02-79-056 80/03/19 ip
- --8004040217 Mod 3.extending period of performance to "Cyprus Mines Corp. Hansen Project Mill Tallings Evaluation" DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-6927-9 NRC-02-79-055 B0/03/17 Ip
- 8004040435 Natification of contract execution, Mod 2 to "Util Mgt & Technical Resources "Contractor Teknekron Research, Inc MENCZER, W B Technical Assistance Contracts Branch FIN 8-6824 NRC-03-80-105 80/03/07 ip
- --8004040454 Mod 2 changing Article 1 description of work re info to be collected from licensees, to "Util Mgt & Technical Resources"
 - DDUGHERTY, D. J. Technical Assistance Contracts Branch FIN B~6824 NRC-03-80-105 B0/03/07 6pp 6рр
- --8004040464 Forwards eddl info needed to evaluate mgt & technical resources available to licensees Representative of Teknekron will contact licensees by telephone to obtain DENTON H R Diffice of Nuclear Reactor Regulation 80/02/28 9pp
- B004070003 Notification of contract execution, Mod 1, to "Evaluation of Mat1 Interactions for Advanced Reactor Sys " Contractor Aerospace Corp MENCZER, B., Technical Assistance Contracts Branch NRC-03-79-126 B0/03/07 ip

ļ

- --8004070007 Mod 1, extending period of performance to 800304-0507, to "Evaluation of Matl Interactions for Advanced Reactor Bys "DDUOHERTY, D J Administrative Contracts Branch NRC-03-79-126 80/03/07 ip
- B004070006 Notification of contract execution, Mod 6 to "Safety Analysis & Experiments for Alternative Reactor Concepts " Contractor Northwestern Univ HAGEY, H Research Contracts Branch FIN A-4064 NRC-04-75-199 80/03/14 ip
- --B004070009 Mod 6.extending period of performance to two years w/funding.to "Safety Analysis & Experiments for Alternative Reactor Concepts "
 MORTON, K V Research Contracts Branch MINTZER, D Northwestern Univ FIN A-4064 NRC-04-75-199 B0/03/14 4pp
- 8004070025 Notification of contract execution, Mod 3 to "Study of Consumer Products Containing Radioactive Matl " Contractor Science Applications: Inc EDDEMORTH, P J Technical Assistance Contracts Branch FIN 8-0280 NRC-02-78-045 80/03/20 ip
- -8004070032 Mpd 3.adding new task under Article 1.Section 2 0 re assessment of current criteria & regulatory policy for consumer products, to "Study of Consumer Products Containing Radioactive Matl " BOUGHERTY, D J Division of Contracts FIN 8-0280 NRC-02-78-043 80/03/20 2pp
- B004070096 Notification of contract execution.Mod 2 to "Sealing Rock Masses" Contractor Univ of AZ
 HAGEY.H Research Contracts Branch FIN D-6627 NRC-04-78-271
 80/02/22 1p
- --8004070100 Mod 2,adding no cost extension,to "Bealing Rock Masses MORTON,K V Research Contracts Branch CARR.8 E Arizona. Un of FIN 8-6627 NRC-04-78-271 80/02/22 2pp. Arizona, Univ
- 8004070125 Notification of contract execution "Licensing Assistance/ Socioeconomic Impacts Evaluations," awarded to Bocial Research & Applications EDDEWORTH, P J Technical Assistance Contracts Branch NRC-02-80-032-02 80/02/25 ip
- --8004070140 Contract "Licensing Assistance/Bocioeconomic Impacts Evaluations," awarded to Social Research & Applications DDUD/HERTY, D. J. Technical Assistance Contracts Branch STERLING, A. W. Social Research Applications Corp. NRC-02-80-032-02 80/02/25 12pp
- 8004080105 Notification of contract execution, Mod 1 to "Photographic Svcs " Contractor MD Color Photo HIGGINS.E Administrative Contracts Branch NRC-10-80-668 80/03/10 ip
- --8004080127 Mod 1, replacing Wage Determination 74-65, Revision 4 w/Wage Determination 80-17, to "Photographic 8vcs " MATTIA, M J Division of Contracts NRC-10-80-668 80/03/10
- GO04080237 Notification of contract execution Mod 3 to "Bys Maint Programming " Contractor Intl Business Bycs HAGAN.T F Administrative Contracts Branch NRC-10-79-372 80/03/18 2pp
- ---8004080241 Mod 3.extending period of performance to "Sys Maint Programming " MATTIA.M J Administrative Contracts Branch FLETCHER, G W International Business Services, Inc TUNBTALL, J E Small Business Administration NRC-10-79-372 80/03/18 3pp
- 8004080326 Notification of contract execution "Economic Assistance Related to Antitrust Hearings For South TX Antitrust & Commanche Park Antitrust Proceedings," awarded to Transcomm, GLAGOLA, A. F. GLAGDLA:A F Administrative Contracts Branch FIN 8-6593 NRC-03-80-129 80/01/14 Ip
- --B0040B0340 Contract "Economic Assistance Related to Antitrust Hearings for South TX Antitrust & Commanche Peak Antitrust Proceedings," awarded to Transcomm, Inc BDUOHERTY, D J Division of Contracts LERNER.N C Transcomm, Inc FIN B-6593 NRC-03-80-129 80/01/14 5pp
- 8004080603 Notification of contract execution "Shuttle Bus Syc," awarded to Beltway Limousine Svc. Inc WIGOINB.E Administrative Contracts Branch NRC-10-80-372 80/03/28 1p

- --8004080610 Contract "Shuttle Bus Svc." awarded to Beltway Limousine Svc. Inc MATTIA.M J Administrative Contracts Branch ROBERTSON, J Beltway Limousine Service, Inc. NRC-10-80-372 80/04/01
- BOO40B06iB Submits Jan 1980 rept on NRC-03-80-105. "Util Mgt & Technical Resources" Efforts concentrated on review & evaluation of licensee submittals Extended contract may be necessary unless utils respond promptly to encl NRC itr 80/02/05
- 8004090263 Notification of contract execution, Mod 1 to "Advanced Process Control " Contractor NUSAC, Inc FOSTER, J M Technical Assistance Contracts Branch FIN 8-6497-9 NRC-02-77-043-2 80/03/17 1p
- --8004090488 Nod 1, revising statement of work & extending period of performance to 800908 to "Advanced Process Control"

 DDUSHTERY, D T Technical Assistance Controls Branch NUBAG, Inc FIN 8-6437-9 NRC-02-79-043-2 80/03/17 3pp LUMB, R F
- GO04100020 Notification of contract execution "Licensing Assistance/ Tailings Mgt Program Technical Evaluation," awarded to JH Kleinfelder & Associates EDOCEMORTH.P Technical Assistance Contracts Branch NRC-02-79-031-05 80/03/07 ip
- ~-8004100023 Contract "Licensing Assistance/Tailings Mgt Program Technical Evaluation," awarded to JH Kleinfelder & Associates Notociates DOUGHERTY,D J - Technical Assistance Contracts Branch MCRAE, C. M. Kleinfelder & Associates NRC-02-79-031-05 B0/03/07
- 8004100187 Notification of contract execution.Mod 8 to "Ofc of Mgt & Program Analysis Mgt Info Bys Maint Bupport Svcs "Contractor Bmail Business Adminstration Subcontractor Logical Technical Svcs Corp HAGAN, T F Administrative Contracts Branch NRC-07-77-178 B0/03/24 1p
- --8004100194 Mod 8, revising delivery schedule for project status repts. to "Ofc of Mgt & Program Analysis Mgt Info Sys Maint Support Sys "
- 8004100339 Notification of contract execution, Mod 4 to "NRC/TMI 810 Rept 8vcs" Contractor JF Holman & Co Inc HAOAN, T.F., Administrative Contracts Branch NRC-10-79-660 B0/03/27 Ip
- --8004100342 Mod 4, revising delivery schedule & extending period of performance, to "NRC/TMI BIG Rept Bycs "
 MATTIA: H U Administrative Contracts Branch HOLMAN; J F John F Holman & Co , Inc NRC-10-79-669 80/03/27 2pp
- 8004100354 Notification of contract execution Mod 1 to "Engineering Assistance Related to Hearings for Bouth TX Antitrust & Commanche Peak Antitrust Proceedings " Contractor RW Beck

--8

- 8004100360 Notification of contract execution.Mod 10 to "Performance Testing for Personnel Dosimetry " Contractor Univ of MI. GUSTAVE.R P Research Contracts Branch FIN B-10490 NRC-01-77-180 80/03/24 ip
- -8004100369 Mod 10.extending period of performance & adding addl work & funding.to "Performance Testing for Personnel Dosimetry "MDRTON.K V Research Contracts Branch MVLDER.H J Minnesota, Univ of, Minneapolis FIN B-10490 NRC-01-77-180 80/03/24
- 8004100366 Notification of contract execution Mod 3 to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbeit " Contractor FL State OUSTAVE.R P Research Contracts Branch. FIN 8-10539 NRC-01-78-004 80/03/17 ip

- --8004100369 Mod 3, extending period of performance w/no increase in funds, to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbelt"

 MORTON, K. V. Research Contracts Branch JOHNSON, R. M. Florida Btate Univ. FIN B-10539 NRC-01-78-004 80/03/17 ip
- BOD4100523 Notification of contract execution, Mod 9 to "Flood Protection " Contractor US Army Coastal Engineering Research Ctr MENCZER, W B Technical Assistance Contracts Branch FIN B-5075 NGC-03-77-006 80/03/20 1o
- --9004100524 Mod 5, increasing funds to "Flood Protection"

 DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-5075

 NRC-03-77-006 80/03/20 1p
- BOO4100829 Notification of contract execution.Mod 1 to "Geotechnical Engineering Case Reviews " Contractor US Army Corps of Engineers MENCZER.H B Technical Assistance Contracts Branch FIN B-6826 NRC-03-79-167 B0/03/20 1p
- ---B004100531 Mod 1,increasing funds to "Osotechnical Engineering Case Raviews"

 DDUOMERTY, D J Technical Assistance Contracts Branch FIN 8-4824 NRC-03-79-167 80/03/20 ip
- 8004100572 Notification of contract execution.Mod 7 to "Design of IFMIS" Contractor Small Business Administration Bubcontractor Technassociates.Inc HAGAN.T F Administrative Contracts Branch FIN 8-5131 NRC-10-80-395 80/03/18 ip
- --8004:00576 Mod 7, revising delivery schedule of Task 2a, 2b & 3 & extending performance period through 800915, to "Design of IFMIS"

 MATTIA, M J Administrative Contracts Branch TUNGTALL, J E Bmal Business Administration YTHIER, P. Technassociates, Inc FIN B-5131 NRC-10-80-395 80/03/18 2pp
- 8004100996 Notification of contract execution, Mod 3 to "Reactor Vessel Irradiation Damage" Contractor Naval Research Lab OLAGOLA, A F Technical Assistance Contracts Branch FIN 8-6809 NRC-03-79-148 80/03/28 ip
- --8004100600 Mod 3.ertending period of performance through 800530, to "Reactor Vessel Irradiation Damage" DOUGHERTY, D J Administrative Contracts Branch FIN 8-6809 NRC-03-79-148 80/03/28 ip
- 8004150166 Notification of contract execution Mod 4 to "Kinetics of Chlorine-Ammonia in Sea Water " Contractor.Univ of NC JACOBS, A Research Contracts Branch FIN 8-6248 NRC-04-77-119 80/03/13 ip
- --B004150171 Mod 4.extending period of performance for add1 14 months at no extra cost, to "Kinetics of Chlorine-Ammonia in Bea Water " MORTON, K Research Contracts Branch HOLCOMB.O R. North Carolina, Univ of FIN 8-6248 NRC-04-77-119 B0/03/13 2pp
- 8004210117 Notification of contract execution. Hod 5 to "Programming in Bupport of Payroll Sys Development " Contractor Small Business Adminstration Subcontractor Technassociates. Inc. HAGEN. TF. Administrative Contracts Branch NRC-10-79-373 883-4-0-8(A)-79. 80/03/18 1p
- --8004210119 Mod 5.changing wording of Articles I & III & extending period of performance through 800530 to "Programming in Bupport of Payroll Bys Development" MATTIA.M J Administrative Contracts Branch TUNBTALL.JE Bmall Business Administration YTHIER.P Tachnassociates, Inc NRC-10-79-373 883-4-0-8(A)-79, 80/03/18 3pp
- 8004230523 Notification of contract execution.Mod 2 to "Subsurface Radar Profiling Study of Maxey Flats.KY, Waste Disposal Region." Contractor Geo-Centers.Inc WOLLETT.B A Research Contracts Branch FIN 8-6349 NRC-04-79-190 80/04/02 ip
- --8004230528 Mod 2.extending terms of contract, to "Subsurface Radar Profiling Study of Maxey Flats.Ky Waste Disposal Region " MORTON.K V. Research Contracts Branch BEERB.R H Geo-Centers, Inc. FIN 8-6349, NRC-04-79-190 80/04/02. Spp
- 8004240009 Notification of contract execution, Mod 4 to "Thermal Hydraulic Stability Analysis Relating to LHR." Contractor Renssalare Polytechnic Inst JACOBS, A Research Contracts Branch. FIN B-7230 NRC-03-78-128 80/04/07.

- --B004240015 Mod 4,increasing funds,to "Thermal Hydraulic Stability Analysis Relating to LWR" MORTON,K V Research Contracts Branch FIN B-7230 NRC-03-78-128 B0/04/07 ip
- 8004240033 Notification of contract execution, Mod 9 to "Consulting Svcs (AE) Related to Evaluation of Facility Concepts.Cost Estimates & Schedules for Experimental Facilities "Contractor Burns & Roe, Inc MORTON, K V Research Contracts Branch FIN 8-4220 NRC-04-77-097 80/01/09 1pp
- --B004240041 Mod 9, extending terms of contract, to "Consulting Svcs (AE)
 Related to Evaluation of Facility Concepts, Cost Estimates &
 Bichedules for Experimental Facilities "
 MORTON, K V Rosearch Contracts Branch PUCILLO, A C Burns & Roe
 Co FIN B-6220 MRC-04-77-097 80/01/09 App
- 8004240047 Notification of contract execution, Mod 4 to "Regional Tectonics & Saismicity of KS " Contractor Univ of KS JACOBS A Research Contracts Branch FIN B-6172 NRC-04-77-017 B0/04/03 |
- ---B004240051 Mod 4.extending terms of contract, to "Regional Tectonics & Seismicity of KB" MORTON, K V Research Contracts Branch HORWITZ,F D Kansas, Univ of FIN B-6172 NRC-04-77-017 B0/04/03 App
- B004240535 Notification of contract esecution, Mod 3 to "Assessing Capability of Existing Pu Facilities to Withstand Natural Phenomena "Contractor NM Newmark CLAGOLA: A F Technical Assistance Contracts Branch FIN B-6150-9 NRC-03-78-150 B0/03/31 ip
- --8004240542 Mod 3, extending period of performance w/no add1 funding to "Assessing Capability of Existing Pu Facilities to Withstand Natural Phenomena" DUOGHERTY, D J Technical Assistance Contracts Branch FIN B-6150-9 NRC-03-78-150 80/03/31 1p
- 8004240546 Notification of contract execution, Mod 5 to "Review & Evaluation of Piling Foundation Proposed for Category I Structers at Bailly Generating Station " Contractor NH Newmark GLAGOLA: A F Technical Assistance Contracts Branch NRC-03-78-150 80/04/02 ip
- --8004240553 Mod 5, extending period of performance w/no add) funding to "Review & Evaluation of Piling Foundation Proposed for Category I Structures at Bailly Generating Station " DOUGHERTY, D J Technical Assistance Contracts Branch NRC-03-78-150 80/04/02 ip
- 8004250014 Notification of contract execution, Mod 2 to "Fire Protection Research Program " Contractor Underwriters Labs WALLETT, 6 A Research Contracts Branch FIN 8-6197 NRC-04-77-122 80/04/04 1p
- --8004250022 Mod 2.providing 1-yr.no-cost extension to. "Fire Protection Research Program " MORTON,K V Research Contracts Branch BARTON,R D Underwriters Laboratory FIN B-6197 NRG-04-77-122 80/04/04 1p
- 8004250035 Notification of contract execution.Mod 1 to "Bafety Assessment of Concrete Nuclear Structures" Contractor MIT HAGEY, H Research Contracts Branch FIN B-6618 NRC-04-79-181 80/03/31 1p
- ---8004250043 Mod I.extending period of performance & including addl workscope w/addl funds, to "Bafety Assessment of Concrete Nuclear Btructures " MORTON,K V Research Contracts Branch DUMMER.Q H Institute of Technology FIN B-6618 NRC-04-79-181 80/03/31
- BO04290107 Notification of contract execution. "Orievance Review Examiner," awarded to PJ La Macchia TRAOESER,C M Administrative Contracts Branch NRC-10-80-488 80/03/20 ip
- --8004270113 Contract "Grievance Review Examiner," awarded to PJ LaMacchia PERLMAN,J Administrative Contracts Branch LAMACCHIA,P J LaMacchia, P J. NRC-10-80-688 80/03/20 6pp
- B004270507 Notification of contract execution "Environ Monitoring Program W/Btate of ME," awarded to State of ME BAIBDEN.L Research Contracte Branch FIN B-5113 NRC-05-80-274 80/01/01 ip

- --8004290514 Contract "Environ Montoring Program W/State of ME,"
 awarded to State of ME
 MORTON,K V Research Contracts Branch PETIT,M R Maine, State
 of FIN B-5113 NRC-05-80~274 B0/01/01 14pp
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 7812120219 Responds to 780316 FOIA request for SECY77-268. SECY77-268A. SECY77-268C & OPE memo Portions of documents withheld (ref IOCFR9 15 & 2 790)
 FELTON, J M Division of Rules and Records 78/12/05 3pp
- 7906010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41, info on seismic issues prepared for SEP & insp repts for Beaver Valley WEISB,E R Sheidon, Harmon & Weiss 79/03/19 2pp
- 800422023B Forwards IE Bullstin 79-09. "Failures of GE-Type Ak-2 Circuit Breaker in Bafsty-Related Sys " Bulletin should be sent on 790417 to all power reactor facilities w/OL or CP Draft itr to licensees encl Bullstin not encl MOSELEY.N C Division of Reactor Operations Inspections 79/04/16
- --8004220245 Forwards draft IE circular, "Uncontrolled Speed Increase of Reactor Recirculation MO Bet Resulting in Rapid Power Increase " Requests comments Distribution sheets for IE Bulletin 78-14 encl JORDAN,E L Division of Reactor Operations Inspections 79/03/01
- --8004220253 Forwards IE Bulletin 78-04, "Defective Cutler-Hammer, Type M Relays w/dc Colis " Bulletin should be sent to all facilities w/DL or CP Draft ltr to licensees encl THORNBURG, H D Division of Reactor Operations Inspections 78/05/24 2pp
- 7909050241 IE Builetin 78-06. "Defective Cutler-Hammer.Type M Relays w/DC Coils"

 * Office of Inspection & Enforcement. Office of the Director
- 7909290207 IE Insp Rept 30-05982/79-01 on 790614 No noncompliance noted Major areas inspected air & water samples, CAMPBELL,M , MCGINNESS, J , MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director 79/06/20 3pp
- 7911140251 Requests amend of Matl/Byproduct License 34-01055-03 authorizing addition of CK Yin as user of Go-60 source Amend fee encl STEARNS. B Riverside Methodist Hosp Columbus. OH 01610 79/10/11 Epp
- 79(1200274 Matl/Dyproduct License 34-01095 03 for Riverside Methodist Hosp is amended per 79(004 ltr. Amend 14 changes Condition 12 authorizing C Yin, J Dohorquez, BM Rahman & OC Taylor as users VACCA, P.C. Licensing Management Branch. 79/10/31 lp
- 8003310090 Responds to FOIA requests for documents re plant safety identified by accession & rept number, author, description & number of pages Forwards documents listed in App A Documents 5 & 26 partially withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/03/03 Bpp
- 8004010033 Responds to FOIA request for winning proposal in response to RFP-RB-NRR-B0-102, "Energetic Thermal Interactions, Recriticality & HTOR Accident & Transient Coolant Flow "Contractor notified to decide whether rept is proprietory FELTON, J M Division of Rules and Records 80/03/19 ip
- 8004010038 FOIA request for Purdue Research Foundation winning technical proposal submitted in response to RFP-RS-NRR-80-102, "Energetic Thermal Interactions, Recriticality & HTOR Accident & Transient Coolant Flow "RAUNER, L M Affiliation Unknown, 80/02/29 ip
- 8004010049 Responds to FOIA request for document entitled, "Director FBI Communication 10112Z Apr 1979 " Forwards requested document FBI director Apr 1979 memo to White House Bituation Room re TMI enci
 FELTON, J M Division of Rules and Records 80/03/19 3pp
- BOD4010054 FOIA request for document forwarded by RJ Brady entitled, "Director FBI Communication 1021127 Apr 1979 "POWER,D F. Affiliation Unknown BO/03/07 1p

- BOO4010056 Responds to FOIA request for documents re NRC comments on DEB written by ORNL or ANL re location, design, capacity or const of cooling water intake structures Forwards documents listed in App A Draft site study encl FELTON. J M Division of Rules and Records BO/03/19 22pp
- 8004010040 F0IA request for documents re NRC commments on DEB written by DRNL or ANL re location, design, capacity or const of cooling water intake structures HARKAMIK,D P LeBosuf, Lamb, Leiby & MacRae 80/02/27 2pp
- 8004010163 Responds to FDIA request for seven documents related to earlier request under FDIA-79-520 Forwards documents listed in App A Bafeguards manual NEDO-14502, withheld (raf FDIA Exemption 4) FELTON.J M Division of Rules and Records 80/03/18 3pp
- BO04010171 FDIA request for info missing from matls sent under FOIA-79-520 on B00130 Info includes GE 741129 ltr to NRC.Safeguards Manual NEDD-14502 & 14502-1 & NEDP-10173-9.GE 720705 ltr to NRC & NEDD-10178 GUIGG.C Pollution & Environmental Problems.Inc B0/02/20 ip
- 8004010281 Responds to FOIA request for NRC document. "Proposed Interim Hydrogen Controls Required for Small Containments." SECY-80-107 Forwards requested document W/o encl FELTON.J M Division of Rules and Records 80/03/24 1p
- 8004010282 FOIA request for NRC document, "Proposed Interim Hydrogen Controls Required for Small Containments," SECY-80-107 KONKABANY, S M Durns & Roe Co 80/03/06 ip
- B00A020192 FOIA request for Education & Human Development.Inc winning technical proposal submitted in response to RFP R8-EDD-80-502. "Study & Review of Issues Concerning Equal Employment Opportunity at NRC"
 RAUNER.L M Advanced Technology.Inc 80/02/29 1p
- BOO40202BB Responds to FDIA request for NUREO/CR-1263 Rept is free to participants in ongoing NRC hearings only Document may be purchased from NRC FELTON, J M Division of Rules and Records BO/O3/27 ip
- 8004020290 FOIA request for NUREO/CR-1263. MUFFLER.R T FOI Bervice 80/03/11 1
- 8004030302 FOIA request for info re thorium residuals in West Chicago, IL. RAPKIN, A. Illinois, State of 80/03/04 2pp
- 800403030B "Aerial Radiological Survey of West Chicago, IL." BOYNS, P.K., FRANKHAUSER, M., HENDRICKS, T.J. EG & G. Inc. EGG-1183-1730 78/08/31 20pp
- --8004030312 Forwards miscellaneous memos & minutes on Reed-Keppler Park Advisory Committee meeting including minutes, JA Pagliara trip repts & recommendations for departmental action to IL Health Dept ALLAN, J., M. Region G. Chicago, Fuel Facility & Materials Safety Branch 77/06/15 11pp
- --B004030316 Summary of Reed-Keppler Park Committee 770322 meeting at ANL PAGLIARD, J A Region 3, Chicago, Office of the Director 77/04/18 14pp
- --8004030319 Summary of Reed-Keppier Advisory Panel 770511 meeting at ANL PAQLIARD, J.A. Region 3, Chicago, Office of the Director 77705720 14pp.
- ---BOO4030321 Requests that position re NRC jurisdictional responsibility concerning licenses issued to Lindsey in late 1740's be developed due to situation visibility & interest of State of IL IE will be unable to develop further info in matter THORNBURO, H D Office of Inspection & Enforcement, Office of the Director 76/10/12. 2pp
- ----B004030324 Discusses source mat! (thorium) in Read-Keppler Park & West Chicago sewage treatment plant. NRC does not have jurisdiction over Kerr-McGee Corp to require decontamination BECKER, J M Office of the Executive Legal Director. 76/10/12. 600
- --8004030327 IE Investigation Rept 76-01 re thorium residue found in uncontrolled locations.West Chicago, IL, for 760709, 12-16, 22 & 30 JORGENSEN, B. L., JANUSKA, A. Q., PAGLIARO, J. A. Region S., Chicago, Diffice of the Director 76/08/20 16pp

- --8004030328 "Environ Assessment re Kerr-McGee Chemical Corp. West Chicago Characterization of Geohydrology & Subsurface Chemistry " * Argonne National Laboratory 78/06/30 33pp
- 8004030304 Responds to FOIA request for document, "Environ Aspects of Commercial Radwaste Mgt.US DOE Info Rept SECY-79-264.US/
 NRC " NRC has been unsuccessful in locating rept NRC rept,
 SECY-79-264 does not pertain to radwaste mgt
 FELTON.J M Division of Rules and Records 80/03/28 ip
- 8004030307 FOIA request for document, "Environ Aspects of Commerical Radwasts Mgt.US DDE Info Rept.SECY-79-264.UB/NRC " LYNXH.J X Montana, Univ of 80/01/29 ip
- 8004030310 Responds to FOIA request for NUREO-0610. "Basis for Emergency Action Level Quidelines." & NUREO-0578. "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations." Forwards requested documents W/o encl FELTON.J M Division of Rules and Records 80/03/28 1p
- 8004030314 FOIA request for NUREO-0610. "Basis for Emergency Action Level Guidelines." & NUREO-0578. "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations " ARP.D Affillation Unknown BO/03/20 ip
- 8004040422 Forwards application for source matl license involving storage only Fee encl PODHURGETS W Edicu International Co 14864 79/11/29 ip
- --8004040427 Application for source matl license, authorizing storage of 1.643,400 kgs U in form of UF-6 & 762,300 kgs U in form of U-308 EDLOW, J Edlow International Co 14864 79/12/04 25pp
- --8004040432 Responds to 791129 application for authorization to store U in East St Louis. IL Requests handling, emergency radiation safety, survey & program auditing procedures Application review will continue upon receipt of info BASSIN,N Licensing Management Branch 80/02/06 2pp
- --B004040437 Responds to B00204 request for info re application for authorization to store source matl in East Bt Louis, IL Forwards handling-radiation safety, emergency & survey procedures Lists actions to be taken if contamination found PODHURBT.B W Ediow International Co B0/02/11 26pp
- --8004040442 Forwards revised procedures re storage of source matl in response to NRC 800211 request Procedures address areas considered deficient by NRC PODHURBT, BW Edlow International Co 15459, 80/02/13 35pp
- BOO4070001 Responds to FOIA request for info re radioactive effluents, exposures, decommissioning & future plans concerning CVTR in Pharr.BC Forwards documents listed in App A. Documents 17 & 41 partially withheld (ref FOIA Exemption 6) W/o encl. FELTON.J M Division of Rules and Records BO/03/28 6pp
- 8004070002 FOIA request for info re radioactive effluents exposures, decommissioning & future plans concerning CVTR in Pharr, SC Facility is in state of limited decommissioning BURSEY, B Grass Roots Organizing Workshop 80/01/25, 1p
- 8004070004 Responds to FOIA request for info re violations of federal law concerning storage of radioactive mati on St Petersburg properties NRC has no documents concerning request State of FL should be contacted FL should be contacted
 FELTON-J M Division of Rules and Records. BO/03/28, 1p
- 8004070008 FOIA request for info re violations of federal law concerning storage of radioactive mati on St Petersburg groperties ROSERTS.G.W. Cone, Quen, Wagner, Nugent, Johnson, Hazuuri & Roth. 80/03/20.
- 8004070012 Forwards response to FOIA request for NUREQ-0550, Revision i. "Btd Distribution for Unclassified UB NRC Publications." W/o enci FELTON.J M Division of Rules and Records 80/03/28 ip
- 8004070016 FOIA request for NUREQ-0550, Revision 1, "Btd Distribution for Unclassified UB NRC Publications" COFFIN.J. Resources Publishing Co 80/03/RO 1p
- 8004080046 Responds to FOIA request for documents re extraordinary nuclear occurrence concept, including proposed rulemaking, regulations & rules adopted by AEC Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 80/03/18 5pp.

- --8004080060 Forwards draft Ofc of General Counsel paper recommending adoption of rule re waivers of defenses & extraordinary nuclear occurrences Lists changes to rule resulting from public comments & consultation w/industry H/a enci
 PRICE.E R Atomic Energy Commission 48/10/03 2pp
- -8004080076 Forwards exchange of correspondence between AEC & CK State Univ.CH State Univ & RI AEC re ability to waive defenses in indemnity agreements in view of state immunity from public liability PRICE,E R Atomic Energy Commission 69/09/16 1p
- --8004080080 Ack receipt of 690808 ltr re Amend 4 to Indemnity Agraement E-9 Provides conditions & exceptions to Amends 4 & 5 Legal opinion re state immunity from public liability encl KAMMAR B Oxlahuma State Univ 69/08/22 4pp
- ---80040800B4 Provides info to assist in resolution of 490822 questions re proposed Amend 4 to Indemnity Agreement E--9 Requests legal opinion from state legal official re DK State Univ governmental immunity & legal disability to effect waiver PRICE,E R Atomic Energy Commission 69/08/08 3pp
- --8004080095 Ack receipt of ltr re proposed Amend 2 to Indemnity Agreement E-43 Provides explanation re application of Anticle II.Paragraph 2 (b) to basic indemnity agreement Requests legal opinion PRICE, E.R. Atomic Energy Commission 69/06/17 2pp
- --8004080098 Ack receipt of ltr re proposed Amend 2 to Indemnity Agreement E-8 Provides explanation re application of Article II Paragraph 2 (b) to basic indemnity agreement Requests legal opinion Atomic Energy Commission 69/06/23 2pp
- ~~8004080110 Draft ltr responding to 680703 comments re publication of proposed amends re financial protection requirements to indemnity agreements BOT concerns have been resolved by adding language clarifying effective rule PRICE, E.R. Atomic Energy Commission 69/07/18 1p
- ---B0040B0115 Confirms 681231 telcon re waiver of defenses endorsement Maiver endorsements described in amends will be effective to all finencial protection policies on 681030 FIBHER:R J Hartford Insurance Group 68/12/31 1p
- --8004080117 Forwards sample endorsement to be used by nuclear liability pools to waive defenses in accordance w/AEC regulations Endorsement will be effective 681030 Two forwarding ltrs enc l MARRONE, J Nuclear Energy Liability Insurance Association 68/12/12 Spp
- ~-8004080120 Summary of 681021 Meeting 2350 re amend to code concerning criteria for determination of extraordinary nuclear occurrence & waivers of defenses General Counsel has been designated to take appropriate action
 MCCOOL.W B Atomic Energy Commission 48/10/23 2pp
- --8004080123 Summary of AEC/industry 780611 conference re Price-Anderson indemnity waivers of defenses List of attendees encl HOLLOHAY, C.J. Atomic Energy Commission 68/06/11 14pp
- --8004080124 Statement re amend to indemnity regulations presented at AEC/industry 680611 conference ZARIN.M S Power Authority of the State of New York 68/06/11
- --8004080130 Comments on regulations implementing 1966 Price-Anderson amends Commission should rescind approval of insurance policy forms containing 2-yr discovery provision XAHN:R D Affiliation Unknown 67/04/06. 3pp
- ---8004080i33 Forwards complaints from state educational institutions re regulations concerning indemnity agreements Submits revision of waiver portion of regulation M/o encl SLOSS.C 8 Atomic Energy Commission 69/11/20 2pp
- --B0040B0134 Comments on proposed regulations concerning financial protection requirements & indemnity agreements re criteria for determination of extraordinary nuclear occurrence Requests deletion of nuclear exclusion clause from policy LEVINSON, C.F. Affiliation Unknown 68/06/07 1p
- ---8004080136 Rept of Price-Anderson Committee, Drafting Subcommittee re criteria for extraordinary nuclear occurrence & texts of waivers of defenses
 - Atomic Industrial Forum 68/06/05 9pp

- ---B0040B0142 Forwards formal statement presented by M Zarin at AEC/industry &B0611 conference \$ Natl Lead Co &B0612 ltr commenting on proposed amend to indemnity regulations Ltr only enci PRICE, E R Atomic Energy Commission &B/06/19 1p
- --B0040B014B Discusses 680611 meeting re proposed amend of indemnity regulations AEC regulations afford reasonable protection No different claims are foreseeable in event of extraordinary nuclear occurrence
 BROWN.B H NL Industries, Inc. 68/06/12 2pp
- ---B0040B0173 Forwards draft ltr inviting participation in 680611 industry moeting to review new waiver of defensos amends & tentative list of invitoes No agenda has been developed SALTZMAN, J Atomic Energy Commission 68/05/07 7pp
- --8004080179 Summarizes ACC 680429 info meeting re proposed amend for extraordinery nuclear occurrence Commission approved publication of proposed amend MCCOOL.N B Atomic Energy Commission 68/05/01 ip
- --8004080184 Forwards 680423 memo is proposed amend to code requirements concerning extraordinary nuclear occurrences Ltrs should be circulated for Commission consideration at early info meeting MCCOOL.W B Atomic Energy Commission AEC 785/101 68/04/24
- ---8004080188 Submits three changes to proposed amend for code requirements re extraordinary nuclear occurrences Requests meeting w/Commission to approve notice of proposed rulemaking for FR publication SCHUR.3 H Atomic Energy Commission 68/04/23 3pp
- --8004080192 Responds to AEC 680412 ltr re two proposed changes in draft amend re extraordinary nuclear occurrences Proposed amends are acceptable Memo route slip encl TAYLOR, 0 H AFL-C10 68704/17 2pp
- --8004080196 Forwards two 670117 drafts of criteria for determination of extraordinary nuclear occurrence Drafts dtd 661207 & 08, 670113,16 & 19 encl NESTERN.P Atomic Energy Commission 67/01/17 61pp
- ---8004080202 Forwards draft of criteria for determination of extraordinary nuclear occurrence Draft is proliminary & intended for use at 670119 meeting Lists positions to be incorporated in preparation of proposed Draft I VALLERIO.J Atomic Energy Commission 67/01/18 12pp
- ---8004080204 Discusses insurance liability in event of extraordinary nuclear occurrence High radiation levels will result in injury to people & in loss of use of property Draft criteria for human radiation offects encl
 PATTERSON.E Atomic Energy Commission 67/01/27 5pp
- ---8004080208 Summary of 480219 meeting re proposed amend concerning extraordinary nuclear occurrence Commission requested that personnel discuss proposed amend w/labor representatives Two drafts of criteria for waiver encl
 MCCOOL.H B Atomic Energy Commission 48/02/27 App
- --B0040B0211 Forwards 670310 draft of proposed criteria for Price-Anderson waiver of defenses Basic objective is to establish & maintain good public relations Draft dtd 670321 encl
 DUNNING, O M Atomic Energy Commission 67/03/14 14pp
- --8004080216 Draft memo discussing criteria for extraordinary nuclear occurrence Forwards six draft repts re-criteria WESTERN,F Atomic Energy Commission 67/03/31 39pp
- --8004080222 Discusses drafts on waiver of defense Agrees to discuss changes in 670403 draft & need for special category for transportation DUNIING.0 M Atomic Energy Commission 67/04/25 ip
- 8004080052 FOIA request for documents re extraordinary nuclear occurrence concept including proposed rulemaking regulations & rules adopted by AEC OVERDORFF. J S Affiliation Unknown 80/02/12 1p
- 8004080707 Responds to FDIA request for Science Applications Inc rept re safety of ionization (radioactive) smoke detectors NUREO/CR-1156, "Environ Assessment of Ionization Chamber 8moke Detectors Containing Am-241," is available in PDR FELTON.J M Division of Rules and Records 80/03/31 ip

- 8004080713 FOIA request for Science Application Inc rept re safety of ionization (radioactive) smoke detectors CASEY.T E Minnesota. Univ of. Minneapolis 80/03/19 ip
- 8004070023 Partial response to FOIA request for safety/accident repts for Rockwwell Intl Energy Sys Group & safety/accident rates in radioactive matis handling at Rockwell Intl Bcieπce Ctr Forwards NRC insp rept in App A W/o encl FELTON.J M Division of Rules and Records 80/04/01 2pp
- B004090026 FDIA request for sefety/accident repts for Rockwell Intl Enorgy Bys & sefety/accident rates in radioactive matls handling at Rockwell Intl Science Ctr TRDY,M Affiliation Unknown B0/03/06 2pp
- 8004090044 Partial response to FOIA request for NRC license issued to US Radium Corp.license application & insps conducted within last three yrs Forwards documents listed in App A Insp info will be forwarded FELTON.J K Division of Rules and Records 80/03/31 2pp
- B004090050 F01A request for NRC license issued to US Radium Corp of Bloomsburg, PA. license application & insps conducted within last three urs TOMKINS.D Affiliation Unknown 80/02/27 ip
- 8004090129 FOIA request for access to entire contents of each issue of weekly highlights printed by NRC or AEC during 1974-1976, POWER, D.F. Affiliation Unknown 80/03/08 ip
- 8004090136 Responds to FDIA request for access to contents of each issue of weekly highlights printed by NRC or AEC during 1974-1976 No 1974 & 1975 repts exist All 1976 repts discharged No records are available subj to request FELTON.J M Division of Rules and Records 80/03/27 1p
- B004090144 FOIA request for written interpretations by NRC general counsel re NRC regulations,10CFR40 4(h),10CFR40 4(k) 5 10CFR40 13(b) OIROUARD,P R Affiliation Unknown 80/03/05 2pp
- 8004090150 Responds to FOIA request for written interpretations by NRC general counsel re NRC regulations, 10CFR40 4(h), 10CFR40 4(k) & 10CFR40 13(b) No written general counsel interpretations or Commission authorizations exist FELTON, J.M. Division of Rules and Records 80/03/27 ip
- B0040903B3 Responds to FOIA request & 8003B1 telcon for license application & license issued to Pharmatopes. Inc License has not been issued Request should be resubmitted in approx B0 days FELTON, J M Division of Rules and Records 80/04/01 ip.
- GOO4090362 FOIA request for radioactive matls license application & license issued to Pharmatopes.inc
 MCDDNALD.D D Nuclear Pharmacy, Inc 80/03/21 ip
- 8004070425 Forwards Rogovin Rept in response to FOIA request W/o encl Becond vol of rept will be published in Apr FELTON, J M Division of Rules and Records 80/03/27 ip.
- 8D04090486 FOIA request for Regovin Rept SHILOBOD, D.S. Affiliation Unknown 80/03/05 Ip.
- 8004100048 Responds to FOIA request for B Fishkin B00124 FOIA request & NRC response re violation of NRC policy by Equibb employee Forwards B Fishkin FOIA request (FOIA-B0-44) & NRC response W/o enc!
 FELTON.J.H Division of Rules and Records 80/04/01 tp
- 8004100052 FOIA request for B Fishkin 800126 FOIA request & NRC response re violation of NRC policy by Bquibb employee MUFFLER, R T FOI Service 80/03/26, 1p
- 8004140102 PNO-III-76-079 295 patients received radiation overdoses between Mar 1975-Jan 1976 Caused by malfunctioning of cobalt therapy unit IE plans to initiate investigation Medical consultant has been contacted for assistance.

 MHITT.K W Region 3, Chicago, Office of the Director 76/04/19
- B004140106 PNO-III-76-027 255 patients received radiation overdoses between Mar 1975-Jan 1976 Caused by malfunctioning of cobalt therapy unit IE plans to initiate investigation Medical consultant has been contacted for assistance ALLAN, J M Region 3, Chicago, Office of the Director 76/04/19 200

- 8004140110 PNO-III-76-031 new info was received re overexposure of 255 patients from improperly calibr teletherapy machine Caused by human error, rather than progressive instrument deterioration IE will complete investigation LONERQAN, G T , ALLAN, J M Region 3, Chicago, Office of the Director 76/03/07 1p
- 8004140124 Discusses FR notice for public comment re proposed rulemaking on waiver of defenses Requests responses to announcement of 480611 industry conference re amends SALTZMAN, J Atomic Energy Commission 68/05/20 1p
- --8004140131 Comments on proposed rulemaking submitted by NY City Bar Association supports AEC intention to withdraw 2-ur discovery clause Supports exclusion re claimants w/ abnormally sensitive activities AXELRAD, M Affiliation Unknown 69/01/20 5pc
- 8004150013 Responds to FOIA request for records described in 12 broad subj categories Request does not meet FOIA requirement of reasonable specificity Forwards documents listed in Apps A & B M/o enci FELTON, J M Division of Rules and Records 80/04/03 8pp
- 800415001B FOIA request for records described in 12 broad subj categories, including laws by which NRC derives authority & all safe methods for disposing of radwaste OANNIS.S Affiliation Unknown BO/01/20 ip
- 8004150026 Responds to appeal re FOIA request for all records re sabotage analyses for spent fuel storage at Morris operation in Morris. IL Info withheld (ref FOIA Exemption 4) Release of info would be contrary to public interest DIRCKS.HJ Office of the Executive Director for Operations, 80/04/03 2pp
- 8004150201 Responds to FOIA request for strip charts re transport of SNM & documents identifying safe havens & law enforcement response capabilities Request terminated due to lack of specificity
 FELTON-J M Division of Rules and Records 80/04/04 1p
- BOO4150206 FOIA request for strip charts re transport of SNM & documents identifying safe havens & Jaw enforcement response capabilities

 DOUGHERTY, J S Dougherty, J D 79/11/16 ip
- BOO41502I3 Responds to FOIA request for "Critical Items List" mentioned on Page III-8-6 of Public Buc of IN description of licensee activities in response to order confirming const suspension List not get submitted FELTON.J M Division of Rules and Records 80/04/03 ip
- 8004:50219 FOIA request for "Critical Items List" mentioned on Page III-8-6 of Public Svc of IN description of licensee activities in response to order confirming const suspension LAUDIO.8 Laudig S 80/03/24 jp
- BOO417013I FOIA responds to request for winning technical proposals submitted in response to RFP RB-08D-79-002 & RFP-08D-79-003 Forwards nonproprietary versions of proposals M/o encis FELTON: J M Division of Rules and Records BO/04/08 lp
- 8004170139 FOIA request for winning technical proposals submitted in response to RFP-RS-OSD-79-002 & RFP-RS-OBD-79-003 RIINA, J R. Personnel Assessment & Selection Service, Inc. 80/02/29 in
- 80042:0013 Responds to FOIA request for documents re Atomic Energy Commission of Canada Request should have been for documents re AECL Forwards documents listed in App A FELTON.J M Division of Rules and Records 80/04/08 2pp
 - 22 IE insp rest on 770826 Noncompliance noted no end-window counter available for insp & licenses representatives tweering hand film badges hicago. Office of the Director 77/08/26

- --80042:0033 IE Insp Rept 30-06870/79-01 on 790620 No noncompliance noted Major areas inspected assembly for installation of teletherapy unit MCCLINTOCK, R Region 3, Chicago, Office of the Director 79/06/25 3pp
- 8004210017 FOIA request for ducuments re Atamic Energy Commission of Canada MUFFLERR T FOI Service 000878 80/03/05 ip
- BOO421003B Responds to FOIA request for certain proposals under RFP-RS-NMS 80-024, "Development of Advanced Matl Accounting Bys Simulation Model " No contract has been awarded Nonproprietary proposals will be made available upon award FELTON.J M Division of Rules and Records 80/04/07 in
- 8004210041 FOIA request for sufficient proposals submitted in response to RFP-RB-NMS 80-024, "Development of Advanced Matl Accounting 8ys Simulation Model "
 EBELP E Allied General Nuclear Services 80/03/18 1p
- 8004210047 Add1 response to FOIA request for NRC license issued to U8 Radium Corp.application & insps conducted within last three yrs Forwards documents listed in App A FELTON.J M Division of Rules and Records 80/04/08 2pp
- --8004210082 IE Insp Rept 30-08982/77-01 on 770314 No noncompliance noted Major areas inspected organization & administration, equipment, facilities, contamination control, liquid waste & stack releases
 8LOBODEN:M J., MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 77/04/01 5pp
- --8004210057 Draft IE Insp Rept 30-05980/79-01 on 790626-27 No items of noncompliance noted Major areas inspected decontamination activities including tour of grounds:review of records & examination of licensee plans for decontamination QLENN, J , COBTELLO, F , MCCLINTOCK, R O Region I, Philadelphia, Office of the Director 79/08/28 3pp
- --B004210062 Discusses contamination of package & vehicle in transporting radioactive matl Carrier was responsible for decontamination Contamination levels were not high snough to require removal of truck from svc GLENN.J Region i, Philadelphia, Office of the Director 79/10/09 2pp
- --80042:0065 Discusses well water sample analysis Samples from test wells were analysed for Ra-226, Sr-90 & tritium Results confirm significant levels of Sr-90 in groundwater close to waste tanks Licensee is planning extensive monitoring & cleanup GLENN.J Region i. Philadelphia. Office of the Director 77/11/01 Spp
- 8004210075 Addi response to FOIA request for info re Pakistani const of gas centrifuge enrichment plant & negotiations concerning efforts to acquire nuclear weapons Two CIA & one Defense Intelligence Agency documents have been located FELTON, J M Division of Rules and Records 80/04/07 ip
- 8004220002 FOIA request for all documents re Riverside Methodist Hosp License 34-10195-03 GERLACH,F T Gerlach,F T 80/02/20 2pp
- 8004220020 Forwards response to FDIA request for all documents re Riverside Methodist Hosp Portions of App B & C partially withheld (ref FDIA Exemption 6 & 5), App C documents withheld (ref FDIA Exemption 5) FELTON: J M Division of Rules and Records 80/04/03 10pp
- ---B004220028 Forwards Citizen-Journal 7&0419 article re therapy unit malfunction at Riverside Hethodist Hosp CDLAUG, M HEW.Dept of. Food & Drug Administration 7&/04/19 2pp
- --8004220033 Forwards PNO-76-027 re reported medical therapy overexposures to 255 patients at Riverside Methodist Hosp ALLAN. JM Region 3, Chicago, Fuel Facility & Materials Safety Branch 76/04/21 ip
- ---8004220037 Summarizes 760421 trip to Riverside Methodist Hosp to investigate melfunctioning cobalt therapy unit Optical distance measuring sys on unit was accurate MCOUNNAOLE.H. Region 3, Chicago, Office of the Director 76/04/22 1p

- --8004220044 Discusses 760421 investigation of Co-60 teletherapy radiation overexposure incident at Riverside Methodist Hosp Provides brief description of investigation events, persons interviewed & followup pracedures

 SAENGER E L Cincinnati General Hosp Cincinnati OH 76/04/23
 2pp
- --8004220051 Confirms NRC request for info re activities authorized by License 34-01055-03 to complete preliminary evaluation of overexposure incident Lists specific info requested KEPPLER, J G Region 3, Chicago, Office of the Director 76/04/28
- --8004220056 Requests written confirmation of 760428 commitments recalibr teletherapy machine GN Callendine 760430 ltr to clients & JR Flynn 760419 statement encl KEPPLER, J G Region 3. Chicago, Office of the Director 76/04/29
- ---BOO4220075 Notifies that hose will comply w/three stipulations conveyed in NRC 760428 ltr re use of 0 66 thimble chamber model & teletherapy machine FLYNN.J R Riverside Methodist Hosp Columbus.GH 76/05/04 ip
- --B004220080 Forwards FNO-76-031 providing recent info re reported medical therapy overexposure to 255 pattents ALLAN.J M Region 3. Chicago. Fuel Facility & Materials Safety Branch 76/05/10 1p
- --8004220072 Forwards form 1tr sent to all physicians having patients involved in radiation overdose at Riverside Methodist Hosp FLYNN.J R Riverside Methodist Hosp Columbus.OH 76/05/24 2pp
- --8004220097 Discusses 760524 telcon re Riverside Methodist Hosp list of patients receiving 10% or more radiation above recorded dose Deceased list was in error due to computational or typing error

 BAENGER, E. L. Cincinnati General Hosp Cincinnati, OH 76/05/24
- --B004220101 Summarizes medical investigations re Co-60 overexposure incident at Riverside Methodist Hosp Provides description of incident events to date Requests comments re investigation proceedings NBS 760528 lir to FDA enci
 BAENDER, E.L. Cincinnati, Univ. of, Medical School 76/05/26, App.
- --8004220107 Discusses repts to public re deaths resulting from teletherapy incident at hosp Coordination between interested parties is necessary to avoid duplicative efforts & to avoid violating rights of patients & hosp FLYNN.J R Riverside Methodist Hosp Columbus.OH 76/05/28 2pp
- ---8004220120 Informs NRC of need to establish appropriate criteria re radiation injury to patients at Riverside Methodist Hosp Pathologist should aid in development of criteria SAENGER:E.L. Cincinnati, Univ of, Medical School 76/05/28 ip
- --8004220125 Responds to 760927 request for definition of NRC medical consultant role in investigation of radiation exposure incident Consultant will conduct independent investigation & render prof opinion KEPPLER, J G Region 3, Chicago, Office of the Director 76/06/02 200
- --8004220130 Forwards 760609 document, "Rept to Riverside Methodist Hosp, Columbus.OH, Concerning Overtreatment of Patients W/Co-60 Radiation " W/o encl RJ Bhalek 760609 ltrs to J Eckler & EL Baenger encl, BHALEK, R J Texas, Univ. of, Cancer Center 76/06/09 3pp
- ~~8004220132 Authorizes EL Smenger to send coroner NRC evaluation of Riverside Methodist Hosp overexposure incident VOLGENAU.E Office of Inspection & Enforcement, Office of the Director. 76/06/10 ip
- --8004220137 Forwards FR Handrickson 760406 ltr re investigation of overexposure incident at hosp Ltr can be used for relevant info but cannot become part of NRC rept on radiation problem at Riverside Methodist Hosp ECKLCR.J Brickler, Evatt. Barton & Eckler 76/06/15 ip
- ---B004220164 Discusses IE insp of License 34-01055-03 on 760512 & forwards notice of violation KEPPLER, J. O Region 3, Chicago, Office of the Director 76/06/15, 200

- --8004220167 Notice of violation from insp on 760512 Noncompliance noted 760512 hyproduct & math inventory included 40 mCi Ca-60 sealed caller source not authorized by license & medical use of hyproduct math by unawthorized person # Region 3, Chicago, Office of the Director 76/06/15 ip
- --8004220174 Discusses request for license amend to add another physician as authorized user on license No objection if NRC decides to remove present physician as authorized user EL Saenger 740617 ltr re patient overexposure encl METIGER, J. R. Office of Inspection & Enforcement, Office of the Director 74/06/16 9pp
- --8004220178 Forwards physician consultant 740406 rept & 740615 ltr to assist NRC medical consultant in investigation of overexposure incident W/a enci PHILLIP, O A Region 3, Chicago, Office of the Director 74/06/18
- ---B0042201B0 Requests on behalf of JC Kirkham, results of NRC investigation re overexposure incident at Riverside Methodist Hosp MIRMAN.J H. Topper, Alloway. Goodman. DeLeone & Duffey 76/06/22,
- --8004220186 IE Insp Rept 30-00398/76-01 on 760420-22 & 0512-13
 Nøncompliance noted licensed mati was used under supervision
 of unauthorized individual & no leak test was performed from
 730713-740803
 LÜNERGAN, G T , SCHULTZ, W H , FOSTER, J E Region 3, Chicago, Office
 of the Director 76/06/23 24pp
- --8004220176 IE Insp Rept 30-00398/76-02 on 760421-22 Noncompliance noted unspecified individual was permitted to supervise use of Co-60 teletherapy unit, no record of test results available & no leak test performed from 730713-740803 LONEROAN, O.T., PHILLIP, O.A., FOSTER, J.E. Region 3, Chicago, Office of the Director 76/06/23 37pp
- ---8004220202 Summarizes 760622 telcon re overesposure incident possible associations.
 ALLAN, J. H. Region G. Chicago, Office of the Director 76/06/24, 26p
- ---B004220207 Discusses possible svcs of C Lushbaugh as pathologist assisting NRC medical consultant in radiation overexposure incident Provides brief background of C Lushbaugh GREHER.E A Office of Inspection & Enforcement, Office of the Director 76/06/25 ip
- --8004220212 Responds to NRC 760613 ltr re violations noted in IE insp of License 34-01055-03 on 760512 Corrective actions 40 mC1 of Co-60 is therapy source, rather than calibr source Cobatt unit will be used under supervision of Fahey TAYLOR Q C Riverside Mathodist Hosp Golumbus DN 76/06/23 2pp

--6

- ---8004220216 Responds to 760622 request for NRC investigation rept on radiation overexposure at Riverside Methodist Hosp, Rept will be forwarded upon completion.

 BYRASMA, J. Region 3, Chicago, Office of the Director 76/06/30 ip
- --8004220229 Forwards revisions to IE Investigation Rept 30-0398/79-01 Revisions were result of Ofc of Executive Legal Director option that investigation rept should not contain hosp consultant rept.

 KEPPLER.J G Region 3, Chicago, Office of the Director. 76/07/02 17pp.
- --B004220231 Forwards draft rept re Riverside Methodist Hosp overexposure incident Rept has not been released to public. W/o encl KEPPLER, J Q Region 3, Chicago, Office of the Director 76/07/02
- --B004220236 Forwards PND-76-04 re radiation overexposure incident at Riverside Methodist Hosp. W/o encl. ALLAN.J M. Region G. Chicago: Fuel Facility & Materials Safety Branch 76/07/02 ip.
- --8004220242 Forwards two lists of deceased Riverside Hosp patients to be included w/original list,List 1 contains 28 names that were inadvertently omitted List 2 contains 20 names to complete deceased list of patients treated 750301-740130, FLYNN,J R Cincinnati General Hosp Cincinnati,OH. 76/07/08 ip

- ~-8004220246 Forwards Riverside Methodist Hosp consultants repts re overtreatment of patients w/co-60 radiation M/o encl EL. Saenger 760709 itr to Ofc of Franklin County Corner encl KEPPLER, J O Region 3, Chicago, Office of the Director 76/07/08
- --8004220251 Act receipt of 740625 ltr informing NRC of steps taken to correct violations noted in IE insp rept Corrective actions will be examined during future insp KEPPLER, J Q Region 3, Chicago, Office of the Director
- --8004220252 Discusses IE insp of License 34-01055-03 on 760421-22 & forwards notice of violation THOMP80N, D Defice of Inspection & Enforcement, Office of the Director, 76/07/21 2pp
- --B004220255 Notice of violation from insp on 760421-22 Noncompliance noted licenses mat1 was used under supervision of unauthorized individual & Co-60 teletherapy source leak test was not performed from 730713-740803 # Office of Inspection & Enforcement, Office of the Director 76/07/21, 2pp
- --8004220259 Discusses JE insp of License 34-01055-03 on 760420-22 & 0512-13 Rept furnished at 760802 meeting identifies insp & investigation basis Rept will be placed in PDR KEPPLER, J Q Region 3, Chicago, Office of the Director 76/08/02
- ---B004220263 Bummarizes 760802 briefing on radiation overexposure incident at Riverside Mathodist Hosp Action should be taken to identify & remedy human consequences of dosage errors BTRAUSS.P.L. Defice of the General Course 76/08/05 2pp
- ---8004220267 Forwards advance copy of Riverside Methodist Hosp overseposure incident investigation rept Rept was given to hosp for proprietary review on 760802 & is not yet in PDR W/o enci KEPPLER.J O Region G. Chicago. Office of the Director 76/08/04 is
- --B004220274 Forwards revision to AD 74-7. "Patient Exposures Above Prescribed Amounts During Cobalt Teletherapy "HIGGINBOTHAM,L Office of Inspection & Enforcement, Office of the Director 76/08/06. App
- --8004220282 Forwards draft info re overexposure incident at Riverside Methodist Hosp Requests comments by 760806 W/o encl DAVIS.J G Office of Nuclear Material Safety & Safeguards 76/08/06. 1p
- --8004220286 Bubstitutes info for Conclusion 2.Page 2 of NRC investigation rept re radiation therapy overexposure incident Requests acceptance FLYNN, J R. Riverside Methodist Hosp Columbus.CH 76/08/11 in
- --B004220294 Notifies of 760813 training session to discuss NRC investigation of teletherapy overexposure incident at Riverside Methodist Hosp & related studies NORELIUS,C E Region 3, Chicago. Office of the Director 76/08/11 1p.
- --8004220314 Recommends acceptance of Riverside Methodist Hosp 760811 request for change of Conclusion 2, Page 2 to NRC rept EL Basnger 760817 ltr to R Zipf encl.
 KEPPLER, J. G Region 3, Chicago, Office of the Director 76/08/16
- --8004220319 Forwards revised Pages 2.5.6 & 10 of NRC investigation rept re Riverside Methodist Hosp teletherapy overexposure incident & draft ltr to hosp Ltr only encl KEPPLER, J © Region 3. Chicago, Office of the Director. 76/08/17 lp.
- ---8004220323 Submits revisions to NRC investigation rept re Riverside Methodist Hosp teletherapy radiation overexposure incident Forwards revised investigation rapt Rept will be released to public on 760818 M/o encl KEPPLER.J Q Region 3. Chicago, Office of the Director, 76/08/17
- --8004220327 Forwards Riverside Methodist Hosp teletherapy overexposure incident investigation rept & NRC 760817 ltr to hosp. H/o encis PHILLIP. Q. A Commission 76/08/19 1p
- --8004220329 Forwards NRC investigation rept re teletherapy radiation overexposure incident at Riverside Methodist Hosp, W/o encl KEPPLER, J. G. Region 3. Chicago, Office of the Director 76/08/20 in

- --8004220330 Provides OH Dept of Health w/NRC investigation rept re teletherapy radiation oversposure incident at Riverside Hethodist Hosp M/o encl KEPPLER.J O Region 3. Chicago. Office of the Director 76/08/20 in
- --8004220337 Forwards NRC investigation rept re Riverside Methodist Hosp radiation therapy overexposure incident W/o encl KEPPLER, J.O. Region 3. Chicago, Office of the Director 76/08/20 1p
- --8004220341 Bubmits questions re toletherapy overesposure incident at Riversida Methodist Hosp Requests response WHITMAN,F M Affiliation Unknown 76/08/20 ip
- --8004220346 Forwards response to Items 1.2.4 & 5 required by NRC 760721 notice of violation FLYNN.J R Riverside Methodist Hosp Columbus.CH 76/08/20 5pp
- --800422035; Forwards final investigation rept re Riverside Methodist Hosp teletherapy overexposure incident W/o encl KEPPLER, J. 9 Region 3: Chicago, Office of the Director 76/08/23
- --B004220355 Requests NRC investigation rept re Riverside Methodist Hosp teletherapy overexposure incident Forwards NY Times 760811 article re cobalt radiation overdoses & testimony before Subcommittee on Health & Environ KOCH E I House of Rep 76/08/24 16pp
- --B004220361 Forwards summary of current status of NRC activities re teletherapy overexposure at Riverside Methodist Hosp Requests concurrence EL Saenger 760910 1tr to county coroner encl THOMPSON, D Diffice of Inspection & Enforcement, Office of the Director 76/09/08 7pp
- --8004220366 Forwards EL Saenger rept re EO Valentine, deceased patient of Riverside Methodist Hosp Death was caused by acute radiation pneumonitis KEPPLER, J G Region 3. Chicago, Office of the Director 77/07/29
- ~-8004220370 Bubmits distribution procedures for NRC medical consultant repts re Riverside Methodist Hosp teletherapy incident ALLAN,J M Region 3, Chicago, Fuel Facility & Materials Safety Branch 77/07/29 ip
- --B004220374 Discusses consultants' repts concerning cause of deaths at Riverside Nethodist Hosp Repts will not be routinely placed in PDR Copies will be sent to coroner & hosp upon request SMITH.O H Commission 77/08/03 ip
- --8004220380 Forwards EL Søenger 770830 ltr to PD Cameron re former patient at Riversida Methodist Hosp Hosp was requested to expedite requested info Related correspondence encl ALLAN, J M Region 3, Chicago, Office of the Director 77/09/12 7pp
- --8004220387 Forwards inquiry re former Riverside Methodist Hosp patient & request for info SAENGER, E.L. Cincinnati General Hosp Cincinnati, OH 77/10/06 3pp
- --800422039: Forwards J Fiunn response explaining patient exclusion from review group W/o encl SAENGER, E L Cincinnati General Hosp Cincinnati, OH 77/10/21
- --8004220397 Requests that govt send representative to verify computations for patients burned by radiation overdose Recalculations & after-effects do not correspond VOLKEMA, R, H Volkema, Pees & Sarap 77/10/26 1p
- --8004220403 Suggests that Commission responsibilities re Riverside Methodist Hosp overexposures be examined to define course of action for 1E regional & consultant personnel, Regulatory aspects of matter have been resolved KEPPLER, J G Region 3, Chicago, Office of the Director 77/11/11
- --8004220404 Requests that NRC redetermine vol of work to be undertaken by medical consultants in reviewing autopsy cases NRC medical consultants should not advise Franklin County, OH coroner or plaintiffs of complicated oversposure questions BARNER, E. L. Cincinnati General Hosp. Cincinnati, OH 77/11/17

- --8004220409 Forwards proposed response to EI Koch 760824 request for info re radiation overexposure at Riverside Methodist Hosp VOLGENAULE Office of Inspection & Enforcement, Office of the Director 76/09/10 App
- --8004220435 Forwards response to questions posed in 760820 ltr to WA Anders re excessive radiation exposures at Riverside Nethodist Hosp Summary section of NRC investigation rept encl BTRASMA.J Region 3. Chicago. Office of the Director 76/09/13
- --B004220439 Ack receipt of 760820 ltr informing NRC of steps taken to correct violations in IE insp rept Corrective actions will be examined during future insp
 THOMPSON.D Office of Inspection & Enforcement, Office of the Director 76/09/15 ip
- --8004220442 Responds to 740824 request for info re radiation overexposure of patients at Riverside Methodist Hosp Forwards summary describing NRC investigation EL Saenger 740910 ltr to county coroner encl ROWDEN, M Commission 74/09/20 Bpp
- ---B004220444 Responds to NRC mailgram re calibr of Picker C-9 Co-60 teletherapy unit at Riverside Methodist Hosp Provides table of exposure rates w/values decayed from original measurements for half-life of 5 26 yrs KARTHA.M K Riverside Mothodist Hosp Columbus.OH 76/09/27
- --800422044B Submits addl info to further comply w/NRC 760714 order to modify license Forwards hosp organizational chart & job descriptions for Modical Director of Radiation Therapy & Radiological Physicist DDATMRIGHT,N C Riverside Methodist Hosp Columbus,OH 76/11/09 Bon
- --B004220452 Ack receipt of 761109 ltr containing addl info requested re NRC 760714 order to modify license Response is incomplete Requests adequate description of mgt control sys within 20 days EL Saenger ltrs encl MADE. L. Radioisotopes Licensing Granch (Pre 790501) 76/11/18 Bpp
- --8004220458 Responds to NRC 761118 request for description of mgt control sys Forwards protocol for Co-60 teletherapy unit calibr BOATWRIGHT.N C Riverside Methodist Hosp Columbus.OH 76/12/06 4pp
- m-8004220461 Notifies that OH Samberg has been appointed Radiological Physicist of Riverside Methodist Hosp Position authorizes OH Samberg to handle routine radiation safety & licensing applications

 BDATHRIGHT.N C Riverside Methodist Hosp Columbus, DH 76/12/13
- --8004220463 Summarizes Riverside Methodist Hosp efforts to ensure that radiation safety program is conducted in accordance w/RRC regulations & license terms Forwards description of radiosotope committee EL Saenger 77012 1tr encl BOATWRIGHT.N.C Riverside Methodist Hosp Columbus.OH 76/12/29 60e
- ---8004220465 Responds to 770926 ltr to EL Baenger re analysis of radiation treatments received by former patient Medical consultants have only reviewed autopsied decedents Former patient will not be included in review KEPPLER.J O Region 3. Chicago, Office of the Director 77/11/18 ip
- ---8004220466 Summarizes 771111 maeting w/EL Baunger re Riverside Methodist Hosp overexposure incident EL Baunger proposed that high level Commission position be developed re further patient evaluation or review of individual cases. LONEROAN.G T Region 3. Chicago. Office of the Director 77/11/25 ip.
- --8004220467 Requests response to EL Saenger questions re need for addl review of autopsy cases & necessity of NRC advice to county officials KEPPLER, J Q Region 3, Chicago, Office of the Director 77/11/30 ip
- ---8004220468 Requests info about current NRC activities re medical use of radioisotopes, bases for IE use of medical consultants & Region 3 areas of concern DAVIS.J C. Office of Inspection & Enforcement, Office of the Director, 77/12/01 ip

- --8004220469 Requests response to EL Gaenger 771117 questions & J Ke 771105 memo DAVIS.J O Office of Inspection & Enforcement, Office of the Director 77/12/12 ip
- --8004220470 Provides brief answers to questions in 770201 memo re Riverside Methodist Hosp teletherapy radiation overexposure incident More complex issues will be addressed in Commission paper EL Saenger 760709 ltr to JR flynn encl HIOQIMBOTHAM.L. Office of Inspection & Enforcement, Office of to Director 78/01/04 5pp
- --8004220472 Discusses recommended enforcement action re Riverside Methodist Hosp overexposure incident Lists major factors contributing to overexposure Six items of noncompliance were identified during IE 760420-22 & 0512-13 insps THOMPSON.D Office of Inspection & Enforcement, Office of the Director 76/06/21 ip
- --8004220473 Matl/Byproduct License 34-01055-03 for Riverside Method: Hosp is amended in its entirety per 780309 application Amend 13 authorizes possession & use of 2,000 Ci Co-60 in teletherapy sealed sources VACCA, P. C. Licensing Management Branch 78/04/05 App
- --800422047& Amend 13 to Matl/Byproduct License 34-01055-03 for River Methodist Mosp authorizing use of licensed matl by GC Taylor or SM Rahman VACCA:P C Licensing Management Branch 77/12/27 ip
- --8004220479 Amend 11 to Matl/Byproduct License 34-01055-03 for River Methodist Hosp, adding Conditions 23 & 24 VACCA, P.C. Licensing Management Branch 77/01/13 ip
- --8004220480 Amend 12 to Matl/Byproduct License 34-01055-03 for River Methodist Hosp, authorizing use of licensed matl by LJ Fahey, GC Taylor or SR Andressen DAVI8.F C Radioisotopes Licensing Branch (Pre 790501) 76/08/1
- --8004220482 Amend 7 to Matl/Byproduct License 34-01055-03 for Rivers Mathodist Hosp, authorizing use of licensed matl by LJ Fahey or GC Taylor DAVIB, F.C. Radioisotopes Licensing Branch (Pre 790501). 76/07/0
- --8004220485 Matl/Byproduct License 34-01055-03 for Riverside Methodi Hosp is amended in its entirety per 751014 application. Amend 8 authorizes use & possession of 2000 ci Co-40 in teletherapy sealed sources DAVIS.F. C Radioisotopes Licensing Branch (Pre 790501) 75/12/1
- --B004220486 Amend 7 to Mati/Byproduct License 34-01055-03 for White Cross Hosp Association authorizing use of 2,000 Ci Co-60 in teletherapy sealed sources BABBIN.N Atomic Energy Commission 76/06/28 2pp
- --B004220489 Amend & to Mat1/Byproduct License 34-01055-03 for White Cross Association authorizing use of 10,000 Ci (two sources of not more than 5,000 Ci each) MALARO, J C Atomic Energy Commission 71/04/01 1p
- --8004220491 Amend 5 to Matl/Byproduct License 34-01085-03 for White Cross Hosp Association.changing expiration date in Itam 4 to 751130 & authorizing MB Schwartz or DR Schmidt as users of licensed matl MALARO.J C Atomic Energy Commission 70/10/14 ip
- --B004220512 Amend 4 to Matl/Byproduct 34-01055-03 for White Cross He Association, revising Subitems 7 A & B A to read teletherapy sealed sources & 7.000 Ci, respectively BUCHANAN, C R Atomic Energy Commission 69/02/07 ip
- --8004220517 Amend 3 to Matl/Byproduct License 34-01055-03 for White Cross Hosp Association; adding Condition 20 BUCHANAN, C R Atomic Energy Commission 47/11/24 1p
- --B004220521 Matl/Byproduct License 34-01055-03 for White Cross Hosp Association is amended in its entiraty per 651026 application Amend 2 authorizes Use & possession of 6,000 Ci Co-60 in teletherapy sealed sources HOWELL,D B Atomic Energy Commission 65/11/19 5pp
- --8004220528 Requests amend of Matl/Buproduct License 34-01055-03 for Riverside Methodist Hosp authorizing CK Yin as user of Co-16 Amend fee certification & NY City license amend encl REEHAL.B S Riverside Methodist Hosp Columbus, OH 79/10/04 3pp

- ---B004220532 Requests deletion of M Kartha & addition of BS Reehal as radiation safety officer for Riverside Methodist Hosp BS Reehal curriculum vitae encl H/o encl FLYNN,J R. Riverside Methodist Hosp Columbus,DH 78/03/09 ip
- --8004220539 Requests that S Rahman be included as authorized user of licensed math for Math/Byproduct Licenses 34-01055-01 & 03 B Rahman curriculum vitae encl W/o ancl KARTHA.M K Riverside Methodist Hosp Columbus.CH 77/11/21
- --8004220544 Confirms 761215 telcon re mgt control sys Hosp must file rept demonstrating that radiation safety program is conducted in accordance w/NRC regulations & license terms HADE, L. Radioisotopes Licensing Branch (Pre 790501) 76/12/15
- ---B004220548 Confirms telcon granting extension until 770104 for receipt of rept re mgt control sys Requests acknowledgement BDATHRIGHT,N C Riverside Methodist Hosp Columbus.OH 76/12/27 in
- ---B004220551 Order modifying License 34-01055-03 by adding Condition 23 to license & requiring written description of mgt control sys to ensure compliance w/NRC regulations Order is effective immediately CHAPMAN, K R Office of Nuclear Material Bafety & Safeguards 76/07/14 3pp
- ---B004220337 Ack receipt of 760921 & 1020 ltrs re appointment of M Kartha as acting radiation safety officer
 B0WYERJ E Radioisotopes Licensing Branch (Pre 790501)
 76/11/03 lp
- ---B004220562 Forwards M Kartha curriculum vitae in response to NRC 761004
 request M/o encl
 BOATMRIOHT.N C Riverside Methodist Hosp Columbus.OH 76/10/20
 in
- --8004220567 Requests amend of Mat1/Byproduct License 34-01055-03 to incorporate J Axt as radiation protection afficer & SR Andresen as user of intracevitary sources KARTHANN K Riverside Mathodist Hosp Columbus.DH 76/09/20 1p
- --8004220573 Informs NRC that M Kartha has been appointed consultant physicist for Riverside Methodist Hosp effective May 1976 Position authorizes M Kartha to take necessary action w/NRC in handling radiation safety & licensing applications FLYNN, J R Riverside Methodist Mosp Columbus. QH 74/09/21 ip
- ---8004220579 Requests complete description of M Kartha experience in rediction & radioactive meths & radiation protection training. BOMYER-J.E Radioisotopes Licensing Branch (Pre 790501) 76/10/04 10
- --B004220585 Forwards Amend 10 to Hatl/Byproduct License 34-01055-03 adding SR Angresen as individual user of Co-60 teletherapy unit at Riverside Methodist Hosp Raquests concurrence W/o enci HADE, L. Radioisotopes Licensing Branch (Pre 790501) 76/08/06
- --8004220391 Discusses Riverside Methodist Hosp request for 20-day extension to comply w/NRC 760714 order Hosp must submit request in writing SINGER, B. Radioisotopes Licensing Branch (Pre 790501) 76/07/29

Andresen not be added as authorized user on 1-01055-03 based on results of nforcement action against licensee section & Enforcement, Office of the

Methodist Hosp request for amend to Matl/ G. ification Branch, 76/06/28 ip

- --8004220602 Application for amend to Mat1/Byproduct License 34-01055-03 authorizing LJ Fahey & QC Teylor to use &/or supervise use of Co-60 Bealed sources to be housed & used in Picker 629F Go-60 teletherapy unit TAYLOR, 2 C. Riverside Methodist Hosp. Columbus, 0H 76/06/30, 4pp.
- ---9004220606 Informs that Riverside Methodist Hosp concurs w/GC Taylor request to be added to Matl/Byproduct License 34-01055-03. FLYNN, J. R. Riverside Methodist Hosp. Columbus, OH 76/06/30 ip

- --8004220609 Requests reactivity of teletherapy license TAYLOR.o C Riverside Methodist Hosp Columbus.OH 76/06/23 ip
- --8004220612 Forwards balance of metl requested for inclusion in License 34-01035-03 W/o encl ANDRESEN, S. R. Riverside Methodist Hosp Columbus, CH 76/04/29
- --8004220616 Advises that S Andresen served as resident from Jan-Jul 1972 Experience included use of Co-60 teletherapy Ca-137 brachytherapy Recommends approval of S Andresen for independent use of matls Suppl to license application encl WEIGENBERGO. I Methodist Medical Center of Illinois Peoria, IL 76/04/24 4pp
- --B004220618 Verifies that S Andresen completed residency at univ on 750801 Training included experience w/superficial voltage, arthovoltage therapy, Co-60 machines & linear accelerators Suppl to license application encl
 DEER, D A California, Univ of, San Diego 76/03/16 3pp
- --8004220622 Discusses Amend 8 to License 34-01055-03 re inclusion of 8 Andresen as individual user of toletherapy unit Requests addi info re 8 Andresen certification in radiology or therapeutic radiology & training DAVIS,F C Radioisotopes Licensing Branch (Pre 790501) 75/12/19
- --8004220625 Forwards request for renewal of License 34-01055-03 for Co-60 teletherapy sealed source & addition of B Andresen to license AXT, J C Riverside Methodist Hosp Columbus, OH NRG 75/10/09
- --8004220629 Application for renewal of Matl/Dyproduct License 34-01055-03, authorizing LJ Fahay & S Andresen to use &/or supervise use of 20,000 Ci Co-60 in form of scaled sources for teletherapy.
 TAYLOR, O C Riverside Methodist Hosp Columbus, OH 75/10/14 Sne
- --B004220633 Notifies that 721009 survey rept following installation of teletherapy unit fulfills requirements of Condition id of License 34-01055-03 Special attention should be paid to requirements of Conditions 18 & 19
 BASSIN:N Atomic Energy Commission 72/11/22 ip
- --8004220535 Forwards QW Callendine radiation survey & analysis for radiation exposure in teletherapy room at hosp subsequent to installation of Picker C-9 teletherapy device BCHWARTZ, W B Riverside Methodist Hosp Columbus, OH 72/10/09 22an
- --8004220639 Supplemental application for amend to License 34-01055-03 authorizing WB Schwartz.DR SchwidT.GC Taylor.JV Blazek & LJ Fahey to use &/or supervise use of 20,000 Ci Co-60 in sealed sources for teletherapy # White Cross Hosp Association Columbus.GH 72/04/20 2pp
- --8004220644 Forwards Forms AEC-313 & 313a in support of application for amend to License 34-01095-03 re inclusion of LJ Fahey as authorized user of licensed metl & replacement of colbalt machine w/rotational cobalt teletherapy unit CALLENDINE, O W Riverside Methodist Hosp Columbus, OH. 72/04/19
- 8004230008 Responds to FOIA request for documents detailing spent fuel shipment routes & alternate routes from Chelk River, Canada to 8C that traverse NY & PA Info withheld (ref FOIA Exemption 4)
 FELTON J M Division of Rules and Records 80/04/09 ip
- 8004230011 FOIA request for documents detailing spent fuel shipment routes & alternate routes from Chalk River, Canada to BC that treverse NY & PA KATZ, B E The Press Binghampton, NY 80/03/19 lp.
- BOO4230015 Responds to FOIA request for last insp rept of Doctor's Hospital in Columbus.OH Forwards documents listed in App A. Insp rept will be forwarded upon completion FELTON.J M Division of Rules and Records BO/04/10 2pp
- ~8004230023 Ack receipt of 761116 ltr informing of steps taken to correct item of noncompliance identified in NRC 761104 ltr Corrective actions will be examined during future insp. ALLAN.J M. Region 3. Chicago, Fuel Facility & Materiale Bafety Branch 76/12/06 ip

NONDOCKETED ITEMS

- --8004230032 DDDD
 "Leak/Mipe Test Analysis Rept " Sealed source inventory enci
 EARLY.P J Nuclear Medicine Associates. Inc Cleveland, OH 76/07/15 2pp
- --B004230040 Discusses IE insp of Licenses 34-05488-01,02 & 03 on 741021 & 22 & forwards notice of violation ALLAN, M Region 3. Chicago, Fuel Facility & Materials Safety Branch 74/11/04 2pp
- --8004230045 Notice of violation from insp on 761021 & 22 Noncompliance noted byproduct matl inventory included 12 Cs-137 sealed sources that were not leak tested between 750222 & 761021 & no quarterly inventory for sealed sources conducted * Region 3. Chicago, Fuel Facility & Materials Safety Branch 76/11/04 ip
- --B004230050 Draft IE insp rept on 761021 & 22 Noncompliance noted byproduct matl inventory included 12 Cs-137 scaled sources that were not leak tested between 750222 & 761021 & no quarterly physical inventory for scaled sources conducted SCHULTZ,W H Region 3, Chicago, Office of the Director 76/10/21
- 8004230019 FOIA request for last insp rept for Doctor's Hospital in Columbus, OH SMITH. J D Affiliation Unknown 80/01/24 ip
- 8004290087 Responds to FOIA request for NRC Translation 520
 "Radioecological Assessment of Wyhl Nuclear Power Plant "
 Forwards requested document W/o encl
 FELTON J M Bivision of Rules and Records 80/04/18 ip
- BOO4270087 FOIA request for NRC Translation 520 "Radioecological Assessment of Hybl Nuclear Power Plant" WA Post 791111 news article encl ORDSSMAN.K Island Closeup News Service BO/04/08 ip.
- 8004290094 Addl response to FOIA request for info re members of ASLB Forwards addl documents per JC Carr 79:107 ltr FELTON.J M Division of Rules and Records 80/04/14 ip
- 800.4290097 Responds to FOIA request for internal documents used to establish 19-minute notification requirement (Footnote 3 in FR notice) for NRC proposed rule 10CFR90 rs emergency planning Forwards documents listed in App A H/o encls FELTON. J M Division of Rules and Records 80/04/14 ip
- BOO4270103 FOIA request for internal documents used to establish isminute notiffication requirement (Footnote 3 in FR notice) for NRC proposed rule 10CFR50 re emergency planning KADAK: A C Yankee Atomic Electric Co BO/03/21 ip
- 8004290150 Responds to FOIA request for issues of "Weekly Highlights" from 1976 to present. All issues since 771216 have been put in PDR in Washington. DC No repts exist for 1976 or 1977, except for 760324 rept FELTON. J M. Division of Rules and Records 80/04/14 Jp
- 8004290152 FOIA request for issues of "Weekly Highlights" from 1976 to present POWER.D F Affiliation Unknown 80/03/31. 1p
- BOO4290195 Responds to FOIA request for all documents requested by public under FOIA re Union Carbide Corp NRC has not been asked for info re Union Carbide Corp Provides NRC criteria for disclosing proprietary info FELTON.J M Division of Rules and Records 80/04/14 1p
- BOO4290161 FOIA request for all documents requested by public under FDIA re Union Carbide Corp CHAIFETZ, D.H. Union Carbide Corp. BO/04/07, 2pp
- 8004270163 Responds to FOIA request for two specific documents contained in nugget file Provides detailed description of nugget file Forwards requested documents W/o encis FELTON: J M Division of Rules and Records 80/04/17 1p
- 8004290166 FOIA request for two specific documents contained in nugget file OROBSMAN.K Island Closeup News Service 80/04/14 ip

- 8004290169 Responds to FOIA request for all applications for radioactive matls licensure & radioactive matls licenses issued to Pharmatopes, Inc. excluding IL Forwards requested documents W/o encls FELTON, J M Division of Rules and Records 80/04/17 ip
- 8004270173 FOIA request for all applications for radioactive mat licensure & radioactive matts licenses issued to Pharmatopes.Inc.excluding IL MCDONALD.D D Nuclear Pharmacy, Inc 80/04/01 is
- 8004290182 Responds to FOIA request for info re Patistani & Liby shipments & design &/or const of nuclear explosive device Forwards news anticles identified in App A Other documents were originated by Btate Dept & CIA FELTON.J M Division of Rules and Records 60/04/14 App
- 8004290184 FDIA request for info re Pakistani & Libyan U shipmen design &/or const of nuclear explosive device COCHRAN,T B Natural Resources Defense Council 79/11/26 2
- GEN TEC IS GENERIC TECHNICAL ISSUES
- 7906010119 FOIA request by UCS for all documents re Task Action , A-40 & A-41 info on sessmic issues prepared for HEP & insp repts for Beaver Valley WE1881E R Bheldon, Harmon & Weiss 79/03/19 2pp
- B00402014B NUREG-0460 V4
 "ATHS for LWRs.Resolution of Unresolved Safety Issue Task
 Action Plan A-9," Vol 4.for comment
 * Office of Inspection & Enforcement, Office of the Director
 B0/03/31 202pp Available at NTIS
- 8004090004 NUREO-0460 V4
 "ATMS for LMRs.Resolution of Unresolved Safety Issue Task
 Action Plan A-9 " For comment issue
 " Office of Nuclear Reactor Regulation 80/03/31 200pp
 Available at NTIB
- 8004070269 Discusses Generic Task 8-24 (Containment Purge) schedimpacts NRC has commitment to complete task action plan by Apr 1980 Browns Forry, Ptairie Island & Turkey Point have not met schedules for submitting info LAINAS.O Plant Bystems Branch 80/03/17 ip
- 8004i4038B Forwards comments on final rept on Phase I of sysinteraction study prepared by Bandia Labs Section 5 O should note that boiling in core & condensation in steam generator is viable heat removal scheme MILLS/L M Tennessee Valley Authority 80/04/04 2pp
- 8004;50353 Forwards "Method of Applying Mark II Bingle Vent Dynam Lateral Load to Mark II Plant W/Multiple Vents," on behalf of Mark II owners group Rept withheld (ref 10CFR2 790) Affidavit enci BUCHHOLZ, R H General Electric Co RHS-027-BO 80/04/09 6p
- 8004180498 Notification of ACRS Subcommittee on Plant Arrangement 800220-21 meeting w/Bandia Labs in Washington.DC to discuss "Final Rept (draft) on Phase I of Generic Task A-17.8ys Interaction in Nuclear Power Plants" & items re LWRs HOYLE,J C ACRS Advisory Committee on Reactor Safeguards. 80/01/30 3pp
- INSPECTION AND ENFORCEMENT
- 7909050241 IE Bulletin 78-06. "Defective Cutler-Hammer,Type M Rel w/DC Coils " * Office of Inspection & Enforcement, Office of the Director 78/05/31 4pp

- 8002280644 IE Bulletin 79-03A. "Longitudinal Weld Defects In ASMS 8A-312 Type 304 Stainless Steel Pipe " # Office of Inspection & Enforcement, Office of the Director 80/04/04 3pp

- 8002280648 IE Bulletin 80-07, "BWR Jet Pump Assembly Failure "
 * Office of Inspection & Enforcement, Office of the Director 80/04/04 7pp
- B0022B0650 IE Info Notice 80-13. "GE Type 8BM Control Switches Defective CAM Followers " = Office of Inspection & Enforcement. Office of the Director B0/04/02 1p
- 8002280654 IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve"

 # Office of Inspection & Enforcement, Office of the Director Opening of Portugues 100
- 8002280657 IE Circular 80-07. "Problems W/HPCI Turbine Dil Bys "
 * Office of Inspection & Enforcement, Office of the Director 80/04/03 | 3pp
- BOOA08057B EN-80-007 on BOO314, notice of violation & notice of proposed imposition of civil penalties to be issued for License 45-0938-02 Action based on alleged items of noncompliance re mati false statements in application for license renewal BRUCKETT, T H. ODMER.0 C Office of Inspection & Enforcement, Office of the Director BO/03/11 Ip
- 8004080584 PNO-V-80-020A on 800317, lost Ir-192 seed found in restricted area of radioisotopic storage room No radiation exposures to operational personnel THOMAS, R D Region 5, San Francisco, Office of the Director 80/03/18, 1p
- , 800409017B PND-I-80-042 on 800317, notified by several sources that radioactive math package containing 13 B Ci Ir-192 source in radiographic device dropped at Philadelphia Airport was leaking Nonradioactive insulating math spilled out KINNEMAN, J Region 1, Philadelphia, Office of the Director 80/03/17 2pp
- 8004090193 PNO-III-80-048 on 800314,unknown caller informed duty officer of stolen Ra-225 implant needles bought from friend Feared contamination & agreed to place device in local Chicago phone booth Two more calls received w/no results PAPERIELLO,C J. DAVIS,A B. Region 3, Chicago, Office of the Director 80/03/14 2pp
- B004090197 PNO-I-80-044 on B00318.call received from individual in Belmont, MA re retrieval of gamma sample charger from trash compactor in Minchester, MA Unlabelled sealed yource reading ii mrem/hr found Little radiation exposure occurred KINNEMAN, J. Region I. Philadelphia, Office of the Director 80/03/19. ip
- B004100017 PNO-V-B0-020 on 800314, safety officer for License 50-17838-01 notified duty officer re 0 6 mCi Ir-192 seed missing from ribbon Radiological surveys conducted of room & patient u/o results THOMAS.R D Region 5, San Francisco, Office of the Director 80/03/17 1p.
- BOO4140102 PNO-III-74-075 255 patients received radiation overdoses between Mar 1975-Jan 1976. Caused by malfunctioning of cobalt therapy unit, IE plans to initiate investigation Medical consultant has been contacted for assistance WHITT.K W Region G. Chicago. Office of the Director 76/04/19 19.
- 8004140104 PND-111-74-027 255 patients received radiation overdoses between Mar 1975-Jan 1976 Caused by malfunctioning of cobelt therapy unit IE plans to initiate investigation Medical consultant has been contacted for assistance ALLAN, J M Region G, Chicago, Office of the Director 76/04/19 2pp
- BOC4440110 PND-III-76-031 naw info was received re overexposure of 255 pattents from improperly calibr teletherapy machine Gaused by human error, rather than progressive instrument deterioration IE will complete investigation.

 LONGROAN, O. T., ALLAN, J. M. Region 3, Chicago, Office of the Director 76/05/07 ig
- BOO4:40202 PND-III-76-110 newspaper reported that preliminary autopsy findings on two patients at Riverside Methodist Hosp indicated radiation overexposure was major cause of death Coroner has scheduled 760702 press conference MARNICK.R F. ROY.O.W. THOMPSON.D Office of Inspection & Enforcement, Office of the Director 76/07/02 ip

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 7902060387 Forwards repts of the activities of the Natl Energy Software Center for FY1978 Midyear review of NESC work scheduled for 790220
- BENNETT, G L Research Support Branch 79/01/18 2pp
- --7902050388 Natl Energy Software Center rept for FY1978 Outlines program accomplishments, breakdown of library collection by classification category, "best saller" list & number of program packages contributed to center BUTLER, M Argonne National Laboratory 78/11/07 8pp
- 7902080199 Informs NRC that nuclear liability pools are able to provide \$160 million as max combined limit under primary nuclear energy liability insurance policies Will maintain \$30 million of contingent Hability Capacity
 BARDES, CR Nuclear Energy Liability Insurance Association 79/01/09 ip
- 7902140361 Announces RER midyear review on 790220 of Natl Energy Software Center of accomplishments to date & plans for rest of FY1979 & FY1980 BENNETT,O L. Research Support Branch 79/01/31 2pp
- 7902280271 Staff position re Transnuclear application to export 779 kg enriched 4 05% U-235 to Canada License should be granted MODRE,R N Assistant Director for Export/Import & International Safeguards 78/12/04 3pp
- 7903060654 Notification of 790322 meeting w/UCLA to discuss status of steam transient research program funded by NRC Div of Reactor Safety Research UCLA pool dynamics program will be discussed
 ANDERSON,C J Containment Systems Branch (Pre 790101) 79/02/13
- 79030B0166 Notification of 790301 meeting in Bethesda, MD to discuss NRC generic questions re ATMS THADANI, A C Reactor Systems Branch 79/02/15 1p
- 7903080264 Notification of 790228 meeting w/Nuclear Associates Intl in Bethesda, MD to discuss progress made on calculations of "Steam Line Break Sensitivity Studies" 8ALAH, S Analysis Branch 79/02/26 ip
- 7903090072 Notification of date change to 790329 for meeting w/BWR Reload Licensing Users Group MORRIS B Reactor Safety Branch (Pre 791030), 79/02/27 1p
- 7903090076 Notification of 790314 meeting in Nethesda,MD w/BWR Reload Licensing Users to discuss BWR Reload Startup Tosts MDRRIS.B Reactor Safety Branch (Pre 791030) 79/02/27. 1p
- 7903200103 Responds to 790219 request for withdrawal of 790105 response to NRC new applications survey Request has been homored Original Itr is being returned No FOIA request for ltr has been made BERKGW.H N Division of Project Management 79/03/05 lp
- 7904130116 Notification of 770411 meeting w/American Inst of Steel Const in Bethesda.MB, to discuss proposed response to request for add info dated 781107 SPRAUL.J Quality Assurance Branch 79/04/04 1p
- 7904170340 Summary of anomalies between semiscale test 8-07-6 results & analytical predictions Improved downcomer insulator will be installed in semiscale in Apr 1979 No addl cold leg injection tests will be conducted MURLEY.TE Division of Reactor Safety Research 79/03/28 App
- 7704210192 Rejects documentation submitted re "Bafeguards Use of Process Control & Quality Control Data " PARTLON.J G Material Control Licensing Branch 79/04/03 1p
- 7905140144 Forwards rept re operating characteristics of numerous models of limitorque electric activators when mounted on Velan valves Constitutes coincidental acquisition CLEMENBON, F Plant Systems Branch (Pre 791020) 79/04/17 2pp
- 7905190090 Forwards monthly rept for Apr listing transfer of radioactive scaled sources used in FILTEC level detection equipment to nonagreement states CALHOUN.F L Industrial Dynamics 79/05/09. 2pp.

NONDOCKETED ITEMS

- 7906010332 Summary of 790216 GA Branch briefing for Ofc of Nuclear Regulatory Research & DDE on proposed graded approach for GA programs W/supporting documentation BENNETT.G L Research Support Branch 79/04/25 32pp
- 7906050031 Responds to 781122 telegram alleging radiation overexposure to individual during radiographic operations Forwards IE investigation rept W/o encl KEPPLER.J G Region 3, Chicago, Office of the Director 79/03/23
- 790725025B Requests clarification of NRC 790611 ltr re implementation of Category 2 & 3 Reg Guides in BEP SCHAFFSTALL,R E KMC, Inc 79/07/23 ip
- 7907308056 Summary of 790524-25 workshop in Silver Spring.MD re recommendations for condensation models in TRAC SHOTKIN,L M Analysis Development Branch 79/06/15 6pp
- 7908010063 Forwards Region i Investigation Rept 078-154 which contains results of radiation survey efforts in Norton, MA through Dec 1978 & related background info W/o encl STOHR, UP Region I, Philadelphia, Office of the Diractor 79/06/04 Ip
- 7908030084 Forwards staff position re safe shutdown capability for fires Specifies safe shutdown equipment & performance objectives for licensee consideration in demonstrating safe shutdown capability w/existing or alternate equipment LAINAS. G Plant Bystems Branch (Pre 791030) 79/06/19 9pp
- 7908060334 Suggests storage of spent fuel rods at ND antiballistic missile site.const of Thorium slow light-water-breeder reactors 3 storage of liquid wastes in NV under atomic bomb test holes MURPHY.FE Affiliation Unknown 79/07/30 1p
- 7908100158 Forwards draft 1E Bulletin proposing interim position on containment purging during normal operation LAINAS, 9 Plant Systems Branch (Pre 791030) 79/06/27 8pp
- 790B150054 Advises that suppl guidelines have been initiated to expedite completion of fire protection programs at operating plants Quidelines will be prepared by DOR reviewers FEROUSEN.R Plant Bystoms Branch (Pre 791030) 79707717 3pp
- 7908150708 Responds to 790612 ltr :e OEIS on handling & storage of spent fuel NRC will follow Commission decision in response to 790801 request DIRCKS.W J Office of Nuclear Material Safety & Bafeguards 79/07/12 1p
- 7908200112 Forwards proposed functional organization for Section A of Plant Sys Branch Requests that lead engineers be authorized to perform managerial paperwork TONDI.D Plant Systems Branch (Pre 791030) 79/07/26. 3pp
- 7908280824 Expresses regrets that Tondi was unable to attend 770726 meeting w/Rydnert at MD Natl Dank Bldg Requests that apologies be extended to Rydnert TONDI, D. Piant Systems Branch (Pre 791030). 79/07/27 1p
- 7709140279 Disagrees w/NRC plan to lift reactor licensing moratorium LEVIN.C Senate 779/09/10 2pp
- 7909190504 Responds to 790814 ltr & 7908124 telcon re licensing requirements for import of Progesterone Kits containing I-125 Forwards IOCFR110 & applicable form W/o encl MOURE, R N Office of International Programs 79/08/27 ip
- 7909190514 Responds to 790730 ltr re suggestions for storage of spent fuel rods & low level radioactive wastes & support for light water breeder reactors Provides explanations for ongoing program of concern DENTON.H R Office of Nuclear Reactor Regulation 79/08/20 ip
- 7910020720 Suggests topics for Japan/U S meeting on nuclear safety Topics include Mark II full scale condensation tests & fire protection & diesel generator reliability Summary of programs encl.

 LAINAS.O Plant Bystems Branch (Fre 791030) 79/09/05 35pp
- 7910020843 Requests summary of screening reviews of licensee responses to IE Bulletin 79-01 re environ qualification of Class IE equipment DENTON.H R Office of Nuclear Reactor Regulation 79/09/21 ip

- 7910050109 Nutification of 791001 meeting w/Ofc of IE to discuss computer sys info re NRC Form 766
 BELKE, W L Quality Assurance Branch 79/09/21 ip
- 7910050156 Advises of review completion of draft IE circular re failure of General Telephone & Electronics Sylvania relay. Type PM Bulletin 7305. Catalog Sul2-11-AC cail Issuance of proposed circular is endorsed w/no comments OAMMILL,W Assistant Director for Operating Reactor Projects (Pre 791030) 79/09713 1p
- 7710050603 Notifies of review of proposed bulletin re dewatering sys at operating plants & endorses issuance GAMMILL.H Assistant Director for Operating Reactor Projects (Pra 771030) 77/09718 ip
- 7910150161 Notifies that univ lab facilities generate no low level wastes GRANT.J J St Peter's College 79/09/29 ip
- 7910310051 Summary of 790B21 research review group meeting in Albuquerque, NM re progress of two NRC spansored studies FOULKE, J D Environmental Effects Research Branch (Pre 791030) 79/10/01 Spp
- 7911050375 Reply to Atlantic Research Corp brief No finding that licensee minimized chances of noncompliance ligh competence not basis for imposition of penalty ALAB-542 should be reversed Certificate of Bvc encl MURRY.J P , LIEBERMAN.J , BURNS.S O Rulemaking & Enforcement Division 45-02809-04 /9/10/23 App
- 8003250855 Concurs d/issuing proposed draft AO rept to Congress for Oct-Dec 1979 Forwards marked-up pages of rept DENTON, H R Office of Nuclear Reactor Regulation B0/02/26 4pp
- 8004020023 Inquires why Nuclear Safety, bimonthly technical progress review, is advertised as govt publication & who is responsible for review Similar ltrs to OAO & Dept of Laborenci EBDUE, N R Affiliation Unknown 79/12/04
- BO04020298 Discusses proposed ltr to licensees on high energy line pipe breaks inside containment No sufficient technical basis evident to advise whether method proposed by NRC for satisfying General Design Criteria 4 is legally sufficient BCINTO, J.F. Office of the Executive Legal Director BO/03/14 ip
- 8004080102 Forwards proposed FR notice of ACRB Bubcommittee on ECCB 800326 meeting Requests publication on 800311 BATES. A L ACRB Advisory Committee on Reactor Bafeguards 80703704 3no

- --8004110105 Requests answers to mine questions re nuclear power plants for school debate BPELIMAN,K Affiliation Unknown 80/01/30 3pp
- 8004140071 Notice of issuance & availability of proposed minor amends of sys of records Amends clarify & update info in NRC sys of records necessitated by adding senior executive syc training records to existing NRC training records DIRCKS, N J Office of the Executive Director for Operations 80/03/14 4pp
- 8004140092 Responds to 800216 itr re operator training Nuclear power plant simulators used in operator training programs since 1769 Under revised requirements, simulators will be programmed for multiple failures

 DENTON, HR Office of Nuclear Reactor Regulation 80/03/20 ip
- --8004140095 Expresses concern about role of plant operator error in nuclear incidents & suggests training in realistic simulated emergency situations BLANCHARD,W H Affiliation Unknown 80/02/16 2pp
- 8004140483 Responds to 800214 ltr forwarding E Griffin 800207 ltr re safety of various aspects of nuclear fuel cycle Forwards copy of proposed change to 100FR50 & other matl re concerns & discusses goal of natl waste mgt program W/o encl KAMMERER.C Office of Congressional Affairs 80/03/01 2pp
- --B004140485 Requests info responsive to encl E Oriffin B00207 ltr expressing concern re safety of various aspects of nuclear fuel cycle BOREN.D L Senete B0/02/14 2pp
- 8004170111 Comments on Nuclear Data Link Urges caution in implementation Admirable objective is not practical, safe or prudent for required level of overview LUNDVALL, A E Baltimore Qas & Electric Co 80/04/10 3pp
- 800421009B Forwards 780901-790131 replacement pages for "Intrusion Detection Handbook." SAND 76-0554 Superseded pages should be destroyed M/o enc1 VARGA.B.A Assistant Director for Light Water Reactors 79/11/15
- BOD4220035 Bubmits reply to inquiries re NRC manitoring of Inst for Nuclear Power Operations activities Inst has not developed specific procedures & criteria for manitoring operator training programs

 SKCVHOLTD U Assistant Director for Guality Assurance & Operations BO/04/01 Ip
- NUREO NUREO REPORTS AND RELATED CORRESPONDENCE
- B003250002 Comments on draft NUREO-0590, Revision 1 no discussion made of recomissioning & conversion No modes of decomissioning should be precluded at this time Classification of decomissioning modes & timing by half lives unreasonable REYNOLDS, N.S. Debevoise & Liberman 80/02/20 Spp
- 8003270223 NUREO-DO30 V3 N1 Yellow Book "Const Status Rept, Nuclear Power Plants," data as of 791231. * Office of Management and Program Analysis 80/02/29 160pp
- 8004010320 Comments on NUREG-0313, Revision 1 evaluation should be made of nonservice sensitive lines to determine potential for intergranular stress-corrosion cracking HILLS, L. M Tennessee Valley Authority 80/03/25 ip
- 8004020032 Comments on NUREG-0625, "Rept of Siting Policy Task Force "
 recommends addi measures to prevent accidents & mitigate
 affects Siting should be strengthened as factor in defense
 PLESSET, M.S. ACRS Advisory Committee on Reactor Bafeguards,
 80/02/14 7pp
- 8004020111 Certified summary of ACRS Site Evaluation Subcommittee 791220 meeting in Washington/DC re recent policy changes & implementation in area of siting & emergency planning * ACRS Advisory Committee on Reactor Safeguards 80/02/09 13pp
- --8004020116 Discusses conflicts in guidance & interpretation re offsite **mergency plans per review of NUREO-0396.NUREO-0388 & draft NUREO-0610. **GODWIN-A.V Alabama. State of 79/11/14. 25pp

- --8004020120 Forwards comments on "Basis for Emergency Action Levels for Nuclear Power Facilities" Minor events having no effect on public health & safety do not warrant consideration of public officials or agencies JURGENSEN,R W American Electric Power Co , Inc. 79/11/30 4pp
- --B004020123 Comments on NUREO-0610 recommends four classes of emergency action levels in-plant occurrence emergency alert, site emergency & general emergency HARD, J E Atomic Industrial Forum 79/11/28 14pp
- --8004020128 Comments on NUREG-0610 draft estimate too low Experience indicates that, using draft examples of initiating condition, frequency would be six to ten times per yr rather than once or tuice
 VETTER,W E Region 4. Dallas, Office of the Director 79/11/27
- --B004020131 Forwards DE Donaldson comments on NUREG-0610 8MITH,0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/11/26 ip
- --8004020138 Comments on NUREQ-0610 supports basic intent/however,does not agree w/nomenclature designation of various classes or w/sorting of example initiating conditions for various classes Marked-up draft guidelines encl DONALDBON.D Region 1. Philadelphia. Office of the Director 79/11/21 24pp
- ---B004020144 Comments on draft NUREC-0610 release potentials should be expanded for offsite agency guidance Notification should be to both state & local authorities for all classes BROMER.O W New York, State of 79/10/30 2pp
- 8004020139 NUREG/CR-1350
 "Evaluation of Factors Affecting Toxicity of Chlorine to
 Aquatic Organisms "
 CRUMLEY,8 C , STOBER, G J , DINNEL,P A Washington, Univ of FIN
 B-5479 80/03/31 85pp
- 800402014B NUREC-0460 V4
 "ATMS for LMRs.Resolution of Unresolved Safety Issue Task
 Action Plan A-9." Vol 4.for comment
 * Office of Inspection & Enforcement, Office of the Director
 B0/03/31 202pp Available at NTIB
- 8004020429 Forwards HCAP-9691, "Transient & Accident Analytis," in compliance w/ltem 2 1 9 c of NUREQ-0578 REED.C Westinghouse Operating Plants Owners Group OG-32 80/03/31 ip
- --8004020432 WCAP-9691
 "Transient & Accident Analysis "
 HITCHLER, M J. SMARP, D R , ANDERSON, T M Westinghouse Electric
 Corp 80/03/31 180pp
- B004030002 NUREO/CR-1312
 "Hethods for Evaluating Leak Tightness of Spent Fuel
 Container Closures."
 BENDA:B J , LANCLAND:R T Lawrence Livermore Laboratory FIN
 A-0117 UCRL-5273B 80/03/31 200pp Available at NTIS
- BO04030004 NUREO-0440 V4

 "ATWS for LWRs.Resolution of Unresolved Safety Issue Task
 Action Plan A-9 " For comment issue

 Office of Nuclear Reactor Regulation BO/03/31 200pp
 Available at NTIS
- B004030005 NUREO/CR-1280 "Power Plant Staffing " WEGNER, W Basic Energy Technology Associates NURC-03-80-116 BETA-103 80/03/31 54pp Available at NTIS
- 8004040272 Discusses recommendations of Task Force on Bulletins & Orders Recommends vendor methods used for small break LOCA analysis be revised documented & submitted for review PLESETIM S ACRS Advisory Committee on Reactor Safeguards 80/03/11 4pp
- --8004040274 Discusses near-term OL items from Draft 3 of NUREG-D&O & NRC action plans developed as result of TMI-2 accident PLESSET.M 8 ACR8 Advisory Committee on Reactor Bafeguards 80/03/11. 5pp.
- --8004040277 Comments on recommendations of NRC special inquiry group re ACRE activities PLESSET, M S. ACRS - Advisory Committee on Reactor Safeguards 80/03/12 2pp

8004040326 Confirms 800314 telcon re BWR owners group response to NUREC-0378 Requirement 2 1 9 FSAR Chapter 15 event review General Electric Co MFN-074-80 80/03/31 75pp 8004040379 Submits info re interpretation of App 3 of NUREG-0654 Principal objective of App 3 is to provide means of prompt notification to population NRC licensees urged to cooperate w/state & local govts to achieve objective JASKE,R T Federal Emergency Management Agency 80/03/28 2pp 8004040459 NUREQ/CR-0858 "Stress Corrosion Cracking of Incomel 600 Tubing in Deaerated High Temp Water " BULISCHECK,T S., PARK.Y S., VAN RDDYEN,D Brookhaven National Laboratory FIN A-3208 BNL-NURE9-51027 79/06/30 52pp 8004070404 Forwards NUREO-0394, "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of LMRs," in response to encl 79/1219 ltr including resolution re emergency planning for handicapped W/o enci GRIMES.B K Assistant Director for Engineering & Projects 80/03/12 4pp B004090241 Comments on proposed rules 10CFR30, 40, 50 & 70 endorses comments on NUREQ-0584, Revision 1 NUREQ-0613 is too tentative in scope & purpose In-place entonbment should be considered viable alternative for decommissioning objective PORTER. N L Duke Power Co 80/03/14 3pp B004100025 NUREQ/CR~1007 JUMINUUUZD NUNEG/CR~1007
"Evaluation of Selected Signal Processing Methods for
Characterization of Steam Geneator Eddy Current Signals "
BROWN,S D , HAYFORD,D T Battelle Memorial Institute, Columbus
Laboratories FIN A-30119 BNL-NUREG-51044 79/08/31 90pp
Available at NTIS 8004100028 NUREG/CR-1104 "Preliminary Analysis of Containment Failure Probability by Steam Explosions Following Hypothetical Core Meltdown in CORRADINI, M L. I.M L., WOODFIN,R L., VOELKER,L E. Sandia Laboratories FIN SAND79-2002 80/02/29 62pp Available at NTIS 8004100029 NUREG/CR-1203 "Quarterly Technical Progress Rept on Water Reactor Bafety Programs," Oct-Dec 1979 YBARRONDO, L J EQ \$ 0, Inc FIN A-6038 EQG-2012 80/01 42pp Available at NTIS \$3.00 FIN A-603G E0G-2012 80/01/31 8004100319 NUREG/CR-1202 "COPS - Model for Estimating Local Law Enforcement Agent Availability " BERKBIGLER, M P Gandia Laboratories FIN A-1173 BAND 78-8237 80/03/31 39pp 8004100323 NUREQ-0651 "Evaluation of Steam Generator Tube Rupture Events" MARSH.L B Office of Nuclear Reactor Regulation 80/03/31 120pp 8004100586 NUREO/CR-1320
"Measured Concentrations of Radioactive Particles in Air in Vicinity of Anaconda U Mill "MOHENIAM H , KIGIELEGKI, W E Argonne National Laboratory A-2046 ANL/E8-89 80/01/31 45pp Available at NTIS B004100591 NUREG/CR-1230 "Local Drag Laws in Dispersed Two-Phase Flow "
IBHII,M . CHAMLA,T C Argonne National Laboratory FIN A-2026
AML-79-105, 79/12/31 46pp Available at NTIS 8004110048 NUREG/CR-1265

00411004B NUREG/CR-1265
"Dynamic Analysis to Establish Normal Shock & Vibration of Radioactive Matl Shipping Packages." quarterly progress rept.Jul-Bept 1979
FIELDB. B r. MECH.B J Hanford Engineering Development Laboratory FIN B-2263 | REDL-TME 79-71 | 80/03/31 | 80pp | Available at NTIS.

8004110045 NUREG/CR-1109
"Measurement of Radon Diffusion from U Mill Tailing Piles "
BILKER, W B , WOGMAN, N A., THOMAS, C W, Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2249 PNL-3107 79/10/31

BOO4140005 Forwards comments on proposed rules 10GFR30,40,50 & 70 on behalf of CPC financial provision for decommissioning is most efficient & economical procedure REYNOLDB, N B Debevoise & Liberman BO/03/20 4pp BOO4140036 Advises that no further action is indicated on Critical Mass Energy Project 791102 petition for NRC to conduct investigation to determine if OLs of LMRs which base ECCS on faulty analytical codes should be suspended DENTON, HR Office of Nuclear Reactor Regulation BO/03/03 2pp 8004140455 NUREG/CR-1116 "Xinetics of Monochloramine Decomposition in Presence of Bromide " TROPE,T W., JOHNSON, J.D., INMAN, G.W. North Carolina, Un Brominge " TROPE:T W , JOHNSON, J D , INMAN.0 W North Carolina, Univ of FIN B-6248 80/03/31 92pp Available at NTI6 8004140470 NUREG/CR-1337 "UNN Safety Research Program," quarterly progress report, Jul-Sept 1979 MASSEY, W E , KVGER, J A Argonne National Laboratory FI ANL-79-108 79/02/28 35pp Available at NTIS Argonne National Laboratory FIN A-2014 0004140478 NUREQ/CR-1257 "Burmany of FY79 Progress on Refill Effects Program,"
quanterly progress report. Jul-Sept 1979
ROTHE,P H, CROWLEY,C J. Creare, Inc. FIN A-4070 CREARE TN-312
80/03/31 34pp Available at NTIS 8004150022 NUREG/CR-1150 "Impact of Disperison Paramaters on Calculated Reactor Accident Consequences " ALDRICH.D C Sandia Laboratories FIN A-1042 SAND79-2081 79/11/20 46pp Available at NTIS 8004190028 NUREG/CR-1029 "Program Plan for Investigation of Vent-Filtered Containment Conceptual Designs for LWRs" BENJAMIN A Sandia Laboratories FIN A-1220 SAND79-1088 79/10/31 72pp Available at NTIS 6004150033 NUREO/CR-1149 MEMORY Response Scenarios for Transportation Accidents
Involving Radioactive Matls "
ALDRICH,D C., ERICEGN,D M., FINLEY,N C. Sandia Laboratories FIN
A-1042 SAND79-2017 79/11/30 54pp Available at NTIS 8004150042 NUREO-0571 "Summary of Tube Intergrity Operating Experience w/Once-Through Steam Generators " LIAM.B D . STROSHIER.J Engineering Branch 80/03/31 41pp 8004150049 NUREO/CR-1309 "Markov & Semi-Markov Modelling of Small Engagements ENGI.D , FARRCLL.R L Sandia Laboratories FIN A-10 BAND79-2013 79/12/31 48pp 8004150074 NUREG/CR-1151 "Infiltration of Particulate Matter into Didgs "
ALDRICH,D C Sandia Laboratories COHEN,A F . C
Pittsburgh, Univ of FIN A-1042 SAND 79-2079
Available at NTIS , COHEN B L 79/11/30 26pp 8004150078 NUREG/CR-1307
"Fixed Site Neutralization Model User Manual"
ENGI.D , CHAPMAN.L Sandia Laboratories FIN FIN A-1060 SAND79-2241

BOO4170310 NUREC-0540 V2 Nt
"Title List of Documents Made Publicly Available." Jan 1980
Division of Technical Information & Document Control 80
477pp Available at NTIS

B004170329 NUREQ/CR-1351

"Fatigus of Weldments in Nuclear Pressure Vessels & Piping "
BDDKER, M K , BDDKER, B L P , MEIERAN, H B Dak Ridge National
Laboratory FIN 8-0103 ORNL/NUREG-44 B0/03/31 93pp

8004170336 NUREQ/CR-0722

"Fission Product Release From Highly Irradiated LWR Fuel "
LORENZ:R A . COLLINS:U T . MALINAUSKAS:A Dak Ridge National
Laboratory FIN 8-0127 ORNL./NUREO/TM-2 80/02/29 144pp

8004170337 NUREO-0398

"Federal-State Cooperation in Nuclear Power Plant Elicansing "
SPANGLER,M.B Division of Site Safety & Environmental Analysis
80/03/31 105pp Available at NTIS

8004170341 NUREO/CR-1193

"Transportation of Radioactive Hatl in 1L," Jun 1978-Jun 1979

1977

* Illinois, State of, Dept of Public Health NRC-06-78-358
80/03/31 53pp Available at NTIS

8004170345 Transcript of AIF B00402 briefing in Washington.DC Pp 1-53 * Commission, 80/04/02 54pp

8004180420 Notification of 800408 meeting $\omega/C=E$ in Bethesda, MD to discuss high range effluent monitors for Lessons Learned requirements & Reg Guide 1 97. BARRETT, L. Environmental Evaluation Branch 80/04/02 ip

8004210213 Forwards comments re NUREQ-0588, "Interim Staff Position on Equipment Qualification of Safety-Related Electrical Equipment "Trend studies could be conducted that point to equipment aging at unacceptable rate RENBERGER.D L Heshington Public Power Supply System ELE-068-80-074 80704/11 5pp

8004210225 Forwards comments on NUREG-0588. "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment " Believes approach to equipment qualification good as long as impact on older plants recognized HQWELL.8.H Atomic Industrial Forum 80/04/14 13pp

B004210298 NUREG/CR-1139

"Evaluation of In-Pile Pressure Data From Instrumented Fuel Assemblies IFA-432 & IFA-432 "

BRADLEY,E R , CUNNINGHAM.M E , LANNING,D D Battelle Memorial Institute Pacific Northwest Laboratory FIN 8-2043 PNL-3206 79/10/31 70pp Available at NTIS. \$5 25

8004210301 NUREG/CR-1273
"Investigation of Rn-222 Emissions From Underground U Mines" JACKSON,P D , QLISSMEYER,J A , ENDERLIN,W I Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2270-7 PNL-3262 80/02/29 100pp 60/02/29

8004220010 Comments on NRC draft study to Congress re extension of NRC regulatory authority over DDE wasts operation Serious conflict would arise if NRC regulatory activities interfere w/defenser-related activities.

MOROAN, R. L. Energy, Dept of, 79/01/26 7pp

8004230300 RIL-62

Powards NUEGO/CR-0379.Vol 5. "Repts Distributed Under NRC Reactor Safety Research Foreign Technical Exchange Program," In NUREO/CR-0450, "New Hadrid Seismotectonic Study — Activities During FY78 " LEVINE.S. Office of Nuclear Regulatory Research 79/10/18, 6pp

8004230300 RIL-62
Forwards NUREQ/CR-0379,Vol 5, "Repts Distributed Under NRC Reactor Safety Research Foreign Technical Exchange Program," & NUREQ/CR-0450, "New Hadrid Seismotectonic Study - Activities During FY78"

LEVINE

-8004230303 NUREQ/CR-0379 V5

NOMESOSOS NOMEGYCR-0379 VS
"Rapts Distributed Under NRC Reactor Safety Research Foreign
Technical Exchange Program," Vol 5 (Jan-June 1978),
GUEENER, D. 8. Dak Ridge National Laboratory, FIN B-0126
NBIC-136 78/11/30, 101pp. Available at NTIE,

~-8004230307 NUREQ/CR-0450
"Yhow Madrid Seismotectonic Study ~ Activities During FY78 "
BUSCHBACH.T C Illinois, State of NRC 04-76-204 78/10/31
135pp Available at NTIS

8004230417 Comments on NUREQ-0654 sirens are inadequate to warn farmers who live within 10-mile emergency planning rone Use of weather alert sys would be costly for state govt Emergency planning & related financing need more attention HANSEN, R H Nabrasta, State of 80/04/15 2pp

8004230436 Comments on NUREG-0654, App 3 Criteria for design of Outdoor warning siren sys should exceed design guidlines specified in FEMA Publication CPOI-17, "Outdoor Warning Sys Quide," or Bolt, Bernack & Newman, Inc Rept 4100 ANDERSON, M E Federal Signal Corp. Bignal Div 80/04/ 80/04/15 2pp

8004240022 Submits trip rept re 781213-15 visit to DDE Richland operations & Hanford plant site Forwards agenda, list of attendees summary of Hanford wastes & summary of site trip KLIGFIELD, G Uranium Fuel Licensing Branch 79/01/03 13pp

8004240454 NUREG/CR-1105

ייסידייסייסי אטאבשיכאר+1105 "Phenomenological Modeling of Small~Scale Vapor Explosion Experiments " Experiments" CORRADINI,M L Sandia Laboratories FIN A-1030 SAND79-2003 80/02/29 B9pp Available at NTIS

8004240464 NUREG/CR-0788 "Recommendations for Program Dovelopment for Safety-Related Equipment Qualification Stds & Quidss " BGNZON.L. L Sandia Laboratories SAND79-0944 79/12/31 145pp Available at NTIS

8004240528 Forwards point-by-point response to ACRS 800311 rept re near-term OL items from Draft 3 of NUREG-0660 Criteria used in near-term OL reviews are not suitable for all licensees DIRCKS, M J Office of Nuclear Material Safety & Safeguards 80/04/01 11pp

8004240559 Forwards partial response to NRC request for review of NRC 790115 draft rept. "Regulation of Federal Radioactive Waste Activities" Discussion of DDE wastes & commercial wastes nonfactual & easily misconstrued BARBER.R W Energy.Dept of 79/02/01 53pp

80042405A5 NUREQ/CR-114R

"BEACON/MIDS Computer Program for Thermal-Hydraulic Analysis of Nuclear Reactor Containments - User Manual "
BROADUB,C R : DDYLE,R J , JAMES, B W EQ & Q, Inc FIN A-6042 EQ0-2008 B0/04/30 228pp Available at NTIS

8004240966 NUREO/CR-1330 "Review of Methods & Criterion for Dynamic Combination in Piping Sys " REICHIM , WANO,P C , CURRERI,J Brookhaven National Laboratory FIN A-3123 80/03/31 560pp Available at NTIS

B004230047 NUREO/CR-122B
"Relative Hazard of Radioiodine as Function of (A) Radiation
Quality & (B) Age at Exposure "
B00K.S A California, Univ of, Davis FIN B-3028 B0/04/30
23pp. Available at NTIS

8004250052 Comments on proposed draft NUREG-04AB "Study of NRC Appellate Sys " Existing sys & immediate effectiveness rule have worked well Rulemaking unnecessary MACRAE, C F LeBoeuf, Lamb, Leiby & MacRae 80/03/17 7pp

8004230037 Bubmits supplemental data to NRC 790103 trip rept re radioactive liquid waste discharged to ground at Hanford plant Provides complete listing of all active & inactive cribs & quantities of liquid waste discharged KLIOFIELD. © Technology Assessment Branch 79/01/08 2pp

GO04250370 Comments on NUREG-0654, App 2, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparadness in Support of Nuclear Power Plants " Same discrepancy exists between App 2 & other o

```
8004280024 NUREG/CR-1352
        304280024 NURLG/LK-1352
"High Tomp Gas Cooled Reactor Safety Studies for Div of
Reactor Safety Research." quarterly progress rept.Oct-Dec
         BALL:S J. CLEVELAND, J.C., CONKLIN, J.C. Gak Ridge National
Laboratory FIN B-0122 ORNL/NUREG/TM-3 80/03/31 10pp
Available at NTIB
 8004280028 NUREO/CR-1123
"Fuel Aerosol Simulant Test Data Record Rept Argon Tests "
WRIGHT.A L . SMITH.A M . ROCHELLE, J M Dak Ridge National
Laboratory FIN 8-0121 DRNL/NUREG/TM-3 80/03/31 36pt
  8004280034 NURED/CR-0929
"BABRES II Individual Resolution Small Arms Combat
Simulation Model "
                  LAGUIL.P Sandia Laboratories FIN A-1173 SAND79-8249
/03/31 33pp Available at NTIS
   8004280035 NUREG/CR-0976
        "User's Guide to Interactive FESEM"
SABSER, D W , BARKER, B E Sandia Laboratories F
SAND79-1995 80/01/31 50pp Available at NIIS
                                                                                                                                                                                                 FIN A-1040
 B0042B004B NUREC/CR-1372

"Eddy-Current Insp for Steam Generator Tubing Program,"
quarterly progress rept for period ending 790930

DOAD.C V, DEEDS.W E , MCCLUNG, W Oak Ridge National Laboratory
FIN B-0417 URNL/NUREC/TM-3 B0/03/31 lipp
 8004280075 NUREQ/CP-0011
       DOGEOUS NORMOND TO HOME STATE OF THE STATE O
8004280263 forwards trip rept re 781219-20 visit to ORNL Purpose of
trip was to compile present & future waste inventory data
Info gathered re DOL.Union Carbide, Natl Lead & Goodyear
Atomic operations Agenda & list of attendees end
TOURIGNY,E 0 Operations & Planning Branch 79/01/11 7pp
8004280383 Submits comments on NUREO-0588, interim staff position on
environ qualifications of satety-related electrical
equipment Environmentally qualified safety-related
electrical equipment continues to be major problem
PIELAGC.H W Affiliation Unknown 80/04/18 2pp
80042B04/3 Comments on proposed rules 10CFR30,40,50 & 70 EPA stds re
ladioactivity levels currently under discussion & should not
be considered final
PORTER,W.L. Duke Power Co. 80/03/14 3pp
 8004290001 NUREQ/CR-1108
       "Numerical Study of Condensation in Concurrent Stratified Flows"

DALY.B J. HARLOW.F H Les Alamos Scientific Laboratory LA-8077
80/08/29 2/pp
 8004290007 NUREQ/CR-112A
       "Properties of Radwastos & Waste Containers," Progress Rept
12 for Jan-Mar 1979
COLOMBO, P., NEILBON, R.M. Brookhaven National Laboratory
                                      P, NEILBON,R M Brookhaven National Laboratory FIN
BNL-NURCO-51101 79/10/31 25nn
 8004290007 NUREQ/CR-1268
       2042/0007 NUREC/CR-1268
"Structural Integrity of Water Reactor Pressure Boundary
Components," querterly progress rept for Oct-Dec 1979
LOSB,F J Navy.Dept of, Naval Research Laboratory FIN
4174 80/03/20 64pp
                                                                                                                                                                                                                 FIN 0-5520 NRL
R004270012 Summary of NRC 781211-12 trip to INEL in ID Falls, ID Purpose was to get first-hand data re federal waste mgt programs at ID & Hanford operations Agenda, list of attendees & narrative
       KLIGFIELD, G Technology Assessment Branch 78/12/29 20pp
8004270017 NUREQ/CR-1323
      VOIATUOIT NOREGERIAZO
"Simulation of Thermohydrawlic Transient in Pipe Using
Commix-1A Computer Code "
CHEN.M J. DUMANUS,H M , BHA,W T Argonne National Lal
A-2045 ANL-CT-80-15 BD/02/29 73pp
```

NON-FOUZU NUMED/CR-0986
"Impact of Decontamination on LWR Radwaste Treatment Sys "
PERRIOOL D. DIVINE, J.R., HOENES, L.G. Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-2281 PNL-3277 79/04/30

8004270020 NUREQ/CR-0986

Argonne National Laboratory FIN 73pp

60/03/20

```
8004270468 Forwards "Response to NUREG-0487. Criteria for Computing
Loads on Submerged Structures." on behalf of Mark II owners
group as part of Task C 15 of Mark II containment program
BUCHHOLZ,R H General Electric Co , Nuclear Energy Products Div
MFN-081-80 80/04/21 2pp
   ---8004290474 SAI-161-79-PA
           004270474 SAI-161-79-PA
"Response to NURGE-0487.Criteria for Computing Loads on
Submerged Structures"
CHANDRA,V , HSIEH,J S Stone & Webster, Inc DOMASHDVETZ,I
Sargent & Lundy, Inc 80/03/31 73pp
  8004300192 NUREQ/CR~0981
      Available at NTIS

Available at NTIS

Available at NTIS

Available at NTIS

Available at NTIS
  8004300206 NUREQ-0592
      004300206 NUREC-0992
"Compilation of Reported Noble Gas Effluent Monitor
Capabilities at Operating Nuclear Power Plants "
FIALKOVICH.J E , BLOCK.S Office of Nuclear Reactor Regulation
NUREG-0592 80/04/30 30pp Available at NTIS
 8004300540 NUREG-0430 VI N4
Orey book "Licensed Fuel Facility Status Rept." Vol 1.data
for decisions, fuel cycle operations
* Office of Inspection & Enforcement. Office of the Director
       B0/01/01
                                70pp
  ORG
                                CORRESPONDENCE WITH OTHER ORGANIZATIONS
 8004080572 Advises that IE Circular 80-05. "Emergency Diesel Oenerator Lubricating Oil Addition & Onsite Supply" was sent to listed utils on 800401 CARROLL.D E Region 3, Chicago, Office of the Director 80/04/02
  8004090082 Informs that Naval Reactors plans to continue operation of
      DOMOTIONS INFORMS that header reactors plans to continue oper
present light water breeder reactor core at Shippingport
Atomic Power Station boyond 18,000 effective full power
hours Summary of revised reactor operating parameters encl
RICKOVER, H 0 Energy, Dept of 80/03/10 3pp
 8004070087 Informs that Naval Reactors plans to continue operation of present light water breeder reactor core at Shippingport Atomic Power Station beyond 18,000 effective full power hours Summary of revised reactor operating parameters encl RICKOVER, H G Energy, Dept of NRC 80/03/10 3pp
 8004100084 Advises that [E Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls" was sent to listed utils on 800313 CARROLL D E Region 9, Chicago, Office of the Director 80/03/17
 8004100087 Advises that IE Info Notice 80-08, "States Co Sliding Link Electrical Terminal Block" was sent to listed utils on
      800307
      CARROLL, D E Region 3, Chicago, Office of the Director 80/03/10
8004100517 Requests signing & returning encl std order for DOE work "Technical Assistance to NRC/DOR Emergency Preparedness Task Force " Work is being incrementally funded until NRC supplemental appropriation has been approved EISENHUT.D 9 Division of Operating Reactors FIN A-7114
--8004100520 8td order for DDE work "Technical Assistance to NRC/DDR
Emergency Preparedness Task Force," issued to LABL.
TRIPLETT.M P Office of Nuclear Reactor Regulation FIN A-7114
 8004140085 Forwards std order for DOE work "Technical Assistance to
NRC/Div of Operating Reactors Emergency Preparedness Task
Force "Requests indication of acceptance by signing encl
      Form 0179

EIGENHUT.D Q Division of Operating Reactors FIN A-7114
---8004140088 Std order for DDE work "Technical Assistance to NRC/Div of Operating Reactors Emergency Preparedness Task Force." issued to GRNL TRIPLETT.M P Division of Operating Reactors. FIN A-7114
```

- 8004150150 Advises that IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve," was sent to listed utils on 800331 CARROLL,D E Region 3. Chicago, Office of the Director 80/04/01
- 8004220154 Advises that IE Bulletin BO-OB. "Eram of Containment Liner Penetration Walds." was sent to listed utils on 800408 CARROLL.D E Region 3. Chicago, Office of the Director 80/04/09
- BOO4220203 Advises that IE info Notice BO-14, "Safety Suggestions From Employees" was sent to listed utils on BO0404 CARROLL.D E Region 3. Chicago, Office of the Director BO/04/09
- 8004220410 Advises that IE Circular 80-07. "Problems w/HPCI Turbine Dil Sys." was sent to listed utils on 800403 CARROLL.D E Region J. Chicago. Office of the Director 80/04/07
- 8004230308 Advises that IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312 Type 304 Stainless Steel Pipe," was sent to listed utils on 800404 for action CARROLL, D E Region 3, Chicago, Office of the Director 80/04/07
- 8004240002 Forwards std order for DOE work. "Atmospheric Release Advisory Capability Site Installations at Nuclear Power Plants," issued to LLL KERR.0 W Office of State Programs 80/04/02 Ip
- --8004240006 Btd order for DDE work, "Atmospheric Release Advisory Capability Sits Installations at Nuclear Power Plants," issued to LLL KERR, 0 W Office of State Programs FIN A-0351-0 80-80-006 80/04/02 7pp
- 8004280259 Notification of 800416 meeting w/DDE & ORNL in Silver Spring. MD for FY80 mid-yr review of NSIC FY81 program assumption & list of topics/questions encl FARMER. W S Research Support Branch 80/04/04 4pp
- B004290038 Submits branch Info Rept 7 update on epidemiologic studies of Portsmouth Navel Shipyard workers GGLBSMITH, R Assistant Director for Radiol Health & Safequards Standards B0/04/07 3pp

PR PROPOSED RULE

- 7904i10030 Ack receipt of editorial "Patient Exposure to X-Rays Whose Responsibility " Explains NRC regulations re use of radioisotopes in medicine & actions re patient safety Federal Register notice encl GOSBICKL V Office of the Executive Director for Operations 79/03/30 10pp
- --7904110034 Order modifying licenses to authorize possession & use of MO-99/Tc-99m generators
 DIRCKB.W J Office of Nuclear Material Safety & Safeguards
 79/03/12 6pp
- 7907110564 Notice of new sys of records identified as Oral History Program NRC-25 Collection of taped interviews w/NRC members will factilitate future writing of NRC history COSSICK.L V Office of the Executive Director for Operations 79706/04 4po
- 7910230124 Notice of new routine use re Privacy Act of 1974 Records from NRC sys of records may be disclosed as routine use NRC contractor on need-to-know basis within scope of pertinent NRC contract ODSSICK, L V Office of the Executive Director for Operations 79709721 3ps
- 7910280127 Notice of new sys of records re Privacy Act of 1974 Special Inquiry File, NRC-33 will provide access by individual name to records of special inquiry GOSBICK.L V Office of the Executive Director for Operations 79/09/21 App
- 7910250135 Notice of exemptions in 10CFR9 95 Portions of Special Inquiry Film are exempt from certain requirements of Privacy Act of 1974.

 QUBBICK, V Office of the Executive Director for Operations 79/09/21. 3pp.

- 8004030138 Comments on proposed rule 10CFR50 opposes change due to possible extention tactics by community or county-level officials Proposed rule should be withdrawn pending review of Rogovin Rept & NVREO/CR-1225 CRANDELL.J D Iowa, State of 80/02/07 1p
- B004030277 "Computer Bys & Data Processing Requirements for Wasto Isolation Pilot Plant Conceptual Design Rept." Addendum M YOUNG,R Sandia Laboratories AT (29-1)-789 77/06/30 10pp
- 8004030281 SAND77-0274
 "Mine Safety Code Review for Waste Isolation Pilot Plant.
 Conceptual Design Rept." Addendum L.
 8 Sandia Laboratories AT (29-1)-789 77/06/30 16pp
- 8004030284 SAND77-0274
 "Soils & Foundation investigation for Proposed Haste Isalation Pilot Plant.Conceptual Design Rept." Addendum I PETTIOREN, R R Bandia Laboratories 77/04/30 31pp
- 8004030287 BAND77-0274
 "Tailings Disposal Froposal for Waste Isolation Pilot
 Plant.Conceptual Design Rept." Addendum B
 POLI,D L Sandia Laboratories 77/04/30 7pp
- 8004030288 SAND77-0274
 "Conceptual Design Rept of Supportive Equipment in High
 Level Maste Facility.Conceptual Design Rept." Addendum B
 * Bandia Laboratories 77/04/30 94pp
- 8004030292 NP-23021
 "Considerations of Environ Protection Criteria for Radwaste," background rept
 * Environmental Protection Agency 78/02/28 66pp
- 8004030294 ANL/EIS-11
 "Oeneric Waste Mgt Concepts for Six LWR Fuel Cycles"
 LUNER:C Argonne National Laboratory 79/04/30 115pp Available
- 800403029B INI8-MF-4745 "Handling & Final Storage of Unreprocessed Spent Nuclear Fuel" * Sweden 78/12/31 liipp
- 8004030279 Y/CWI/SUB-77/42500 "US LWR Spent Fuel Inventory & Projection " WOODHALL.C B Nuclear Assurance Corp 77/06/30 203pp
- 8004030337 Comments on proposed rule 10CFR50 adequate state & local emergency plans should be made prerequisite for OLs Public can play constructive role in NRC review of local licensees OROSS, M Affiliation Unknown 80/02/23 3pp
- 8004030341 Comments on proposed rule 10CFR50 natl emergency planning/preparedness effort long overdue Implementation of proposed rulemaking re emergency planning zones presents political nightmare RENBERGER.D L Washington Public Power Supply System 80/02/19600
- 8004030343 Comments on proposed rule 10CFR50 NRC should withdraw proposed rule that would preclude issuance of OLs for safe pouser plants Rule is satheme reaction rooted in politics MCMORMACK.M House of Rep., Science & Technology 79/12/20 2pp
- BO04030345 Comments on proposed rule 10CFR50 opposes premise that low probability events should play important role in emergency planning Size of emergency planning zones should be determined on case-by-case basis ANDERSON.T M Westinghouse Electric Corp , Nuclear Energy Systems NS-TMA-220B 80/02/19 3pp
- 8004030351 Comments on proposed rule 10CFR50 NRC should review local radiological emergency planning Concurs w/idea that local populations usually have more faith in local authorities than state gov!

 MECCA, J E Puget Sound Power & Light Co 80/02/15 2pp
- 8004030361 Comments on proposed rule 10CFR50 emergency response plan should contain contingency procedures for accidents & conditions unrelated to operation BRADLEY, J P Affiliation Unknown 80/02/20 9pp

- 8004040007 Advises that on 800220,CA Energy Commissioner E Varanini sent attached 1tm to JF Abearne ELLISON,C T California, State of 80/03/03 ip
- ---B004040008 Discusses refusal of hearing officer to consider CA Energy Commission procedural suggestions to public participation & recordkeeping of rulemaking proceedings Order limits credibility of hearing process VARANINI.E C California, State of B0/02/20 Bpp
- 8004070187 Forwards joinder in NRDC motion to direct presiding officer to certify issues on NRC role in proceeding KINDER,E T New Hampshire, State of 80/02/26 ip
- --8004070202 Joinder in NRDC motion to direct presiding officer to certify issues on NRC role in proceeding on proposed rulemaking re radwaste Views of independent experts should be solicited Cortificate of Box oncl
 KINDER, E T New Hampshire. State of 00/02/26 7pp
- BOD408004; Forwards comments on proposed rule 10CFR50, submitted by San Luis Obispo Area Task Force on Nuclear Power Issue emergency plans should be fully implemented as precondition of licensing ORIFFIN.R C Affiliation Unknown 80/02/15 27pp
- 8004080046 Responds to FDIA request for documents re extraordinary nuclear accurrence concept, including proposed rulemaking, regulations 5 rules adopted by AEC Forwards documents listed in App A
 FELTON, J M Division of Rules and Records 80/03/18 Spp
- --8004080142 Forwards formal statement presented by M Zarin at AEC/industry 680611 conference & Natl Lead Co 680612 ltr commenting on proposed amend to indemnity regulations Ltr only encl PRICE, E R Atomic Energy Commission 68/06/19 1p
- 80040B0i17 Comments submitted on behalf of WA Public Power Bupply Sys. on proposed rule 10CFR90 FFMA role as lead agency must be reflected in final regulation REYNOLDB,N S Debevoise & Liberman 80/02/19 14pp
- B0040B0125 Comments on proposed rule 10CFR50 technique of imposing util between federal, state & local courts is unprecedented & w/o justification State should have primary responsibility for coordinabling emergency plans PARKER. H O Duke Power Co 60/02/19 6pp
- 8004080147 Comments on proposed rule 10CFR50 new regulatory requirements are imposed on licensees before rule promulgation & w/o due process Objects to NRC use of utils to obtain & maintain concurrence in local emergency plans WARD, J E Atomic Industrial Forum 800/02/20 16pp
- 8004080152 Comments on proposed rule 10CFR50 only those interested in actual making of plans should be present BCALPI,M New York, State of 80/02/13 lp
- 8004080228 Comments on proposed rula 10CFR50 on behalf of Bouthern CA Edison Co FEMA is best suited to assess adequacy of local emergency planning Rule fails to provide objective stds for NRC concurrence. CASEY.8 D Chickering & Oregory 80/02/15 30pp
- 8004080R45 Comments on proposed rule 10CFR50 rule is fundamentally flawed Link between NRC plan concurrence & licensing is harmful to industry & consumers NRC should consider emergency planning w/public safety & other vital goals MCCULLAM, W Edison Electric Institute 80/02/22. S5pp
- BOD40B0659 Comments on proposed rule 10CFR50 requests placement on mailing list for workshops on transporation & disposal of nuclear waste BEDROBIAN, Y Novada, State of BO/02/09 1p
- B0040B0474 Comments on proposed rule 10CFRB0 agrees that upgrading omergency propaledness is necessary to protect public health & safety COTE. A Maine, State of B0/02/11 [p
- 8004080682 Comments on proposed rule 10CFR30 NRC should only allow review by persons or organizations who are totally independent of licensee & employees Plume exposure pathway zone should not be limited to 10-mile radius CLINTON.8 Arkansas, State of 80/02/19 4pp

- 8004090116 Comments on proposed rule 10CFR50 new concept of emergency planning iones will have greatest impact in Northeastern US where political jurisdictions overlap Agrees w/requirement for NRC concurrence w/state & local plans
 HEUBNER.A T Connecticut, State of 80/02/22 ip
- 8004090145 Comments on proposed rule 10CFRS0 extrasensory perception suggests possibility that nuclear power facilities are not well constructed BISHOP.0 Affiliation Unknown 80/02/18 ip
- 8004090152 Forwards comments on proposed rule 10CFR50 nuclear emergency planning has been neglected by Commission despite repeated warnings of significant problems Studies have established importance of emergency planning & proper siting POLLOCK,R P Critical Mass Energy Project 80/02/22 16pp
- 8004090156 Comments on proposed rule 10CFR50 implementation of Alternative B in FR notice may have unnecessarily harsh economic & social consequences Requests FR notice seeking public comments re Alternative A KITTRIDGE, GR Minnesota. State of BO/O2/19 3pp
- 8004090160 Comments on proposed rule 10CFR50 requests clarification renumber of plans & extent of participation required for each govt entity State & local authorities should be able to coordinate needs

 MILLS,L M Tennessee Valley Authority 80/02/19 3pp
- 8004090165 Forwards W Connor 791207 ltr re proposed rule on emergency planning Requests comments CHILES, L. Senate 80/01/03 ip
- --8004090168 Comments on proposed rule 10CFR90 opposes authority to closs down plants located in areas w/o acceptable state & local smergency plans Forwards Tampa Tribune 791206 articls reenergency planning CONNOR.N Affiliation Unknown 79/12/07 3pp
- 8004090172 Commonts on proposed rule 10CFR50 lack of communication between Met Ed & Governor Thornberg should be corrected State of NJ legislation will provide financial assistance from tax funds for upgrading health & public safety plans WILLODSEN.A F Affiliation Unknown 80/02/16 2pp
- 8004090186 Comments on proposed rule 10CFR50 thought should be given to developing practical implementation program which will follow publication of formal rules & guidelines Comments prepared for NY workshop on proposed rule changes encl HENDERSON, O K Pennsylvania, State of 80/02/08 5pp
- 8004090188 Forwards comments on proposed rule 10CFR50, submitted on behalf of Southern CA Edison Co CASEY, 8 B Chickering & Gregory 80/02/15 1p
- ---8004070176 Comments on proposed rule 10CFR50, submitted on behalf of Bouthern CA Edison Co specific time limits in proposed rule should be replaced w/more realistic & flexible limitations Suggested util amends to proposed rule enci CASEY, S B Chickering & Gregory 80/02/15 33pp
- 8004090213 Forwards West Branch Conservation Association comments on proposed rule 100FR80 ratepayers should not have to bear financial burden of safety mods to facilities emergency sys FLEISHER, W. L. West Branch Conservation Association 80/02/18 2pp
- B00A090229 Comments on proposed rule 10CFR50 concept of NRC concurrence in adequacy of offsite response to emergancy is sound Model plans have proved to be of little assistance in past programs

 KYLE.J S Arizona, State of B0/02/28 5pp
- 8004070241 Comments on proposed rules 10CFR30, 40, 50 & 70, endorses comments on NUREO-0584, Revision 1 NUREO-0513 is too tentative in scope & purpose, in-place entombment should be considered viable alternative for decommissioning objective PORTER, W L Duke Power Co 80/03/14 3pp
- BOD4090247 Comments on proposed rules 10CFR30.40.50 & 70 overemphasizes probability of premature permanent shutdown NRC should not imply util future financial instability WILLIAMS.H P Florida Power & Light Co BO/03/13 3pp
- 8004090266 Forwards comments on proposed rule 10CFR50 no provision for public intervention in NRC concurrence process State & local emergency planners should be allowed to argue for or against concurrence before NRC DUMS, D Affiliation Unknown 80/02/27 3pp

- 8004090271 Comments on proposed rule 10CFR50 rule is vague, ambiguous & disallows public participation Intervention in concurrence is denied to currently operating plants

 MERRITT.D Citizens for a Better Environment 80/02/19 5pp
- B004090300 Forwards Luzerne County, PA 800116 ltr to NRC submitting comments on proposed rule 100FR50
 TOWNEND, F Affiliation Unknown 80/02/08 lp
- 8004090309 Comments on proposed rule 10CFR50 suggests FEMA obtain emergency plans directly from state & local govts Supports proposed Alternative A Questions benefit of 15-minute notification
 DISE, D P Niagara Mohawk Power Corp 80/03/05 2pp
- 8004090331 Comments on proposed rule 10CFR50 on behalf of three utils regulations are premised upon unsound legal assumptions Role of FEMA in emergency planning as significant & requires recognition in rule
 MCGARRY, J M Debevoise & Liberman 80/02/19 3pp
- 8004090460 Comments on proposed rule 10CFR50 recommends withdrawal of proposed rule precluding issuance of OLs w/o NRC concurrence on state & local emergency response plans WYDLER, J W House of Rep . Science & Technology 79/12/20 2pp
- 8004090463 Comments on proposed rule 10CFR30 emergency planning is as important as siting of facility All emergency related agencies should be staffed 24-h per day Public hearings should be held on emergency plan exemptions MANN, D L Susquehanna Alliance 80/02/15 3pp
- 8004100006 Comments on proposed rule 10CFR50 no exemptions to license should be given until emergency reponse plans are deemed adequate NRC should reconsider issuance of CP to facility BEIDTG, N C Affiliation Unknown 80/03/03 ip
- 8004100041 Comments on proposed rule 10CFR90 on behalf of Buffolk County.NY emergency planning must be viewed as equivalent rather than secondary to siting design in achieving public protection OlLMRTIN.D J , LIKE,I Reilly & Like 80/02/26 13pp
- --8004100046 Transcript of 790710 testimony before NY State Board on Electric Generation Siting & Environ Pp 1-6 KLEIN.J.V.N Suffolk County, NY 79/07/10 Spp
- --8004100050 Transcript of 790629 testimony before NY State Board on Electric Generation Biting & Environ Pp 1-3 GEISELMAN,J N Environmental Protection Agency 79/06/29 6pp
- --8004100055 Transcript of 790629 testimony before NY State Board on Electric Generation Giting & Environ Pp 1-20 GIARDINA, P A Environmental Protection Agency 79/06/29 25pp
- 8004100074 Forwards comments on proposed rule 10CFR50 on behalf of Haddam.CT comments will be presented at workshop in NY Communication during an emergency is concern for local govt CONTILL L. Affiliation Unknown 80/02/14 Spp
- 8004100075 Forwards Oldham County, KY 800215 resolution as comment on proposed rule 100FR50 W/o state legislation that defines & authorites local govts to implement emergency plans, any plan would be useless
 MOGRE, W. Affiliation Unknown 80/02/16 Spo

on proposed rule 10CFR50 insufficient attention y planning for research reactors NRC & FEMA which federal or state agency should key planning zones f, State of 80/02/15, 3pp

on proposed rule 10CFR50 applicant should provide or evacuation on exposure pathway zone be necessary for every type of potential lons may be more appropriate al Electric Co. 80/02/22 16pp

on proposed rule 10CFRSO NY Dept of Health will compassing suggestions of various state

rk, State of 80/02/13 ip

comments on proposed rule 10CFR50 on behalf of ion should be taken against hasty strate that NRC is making substantial TMI-Q accident.

ERR E Shaw, Pittman, Potts & Trowbridge

- BO04100294 Comments on proposed rule 10CFR61 disposal facility space should be used efficiently Storage facilities should also be addressed Some requirements should be given for incinerator use & for contaminated oil CHANDLEY, C.A. Tennessee Valley Authority BO/03/04 3pp
- 8004100388 "Determination of Extraordinary Nuclear Occurrence," iOCFR140 83 financial protection requirements & indemnity agreements Extends date until 800328 to determine whether TMI constitutes extraordinary occurrence CHILK.S J Office of the Secretary of the Commission 80/03/14 ip
- 8004100418 Comments on proposed rule iOCFR50 NRC should permanently shut down all U mines 5 mills.processing plants,generating stations.nuclear weapons const & refurbishing sites & all other nonpower reactors to protect public health & safety HYDE.D W Affiliation Unknown 80/02/15 4pp
- B004100434 Forwards comments on proposed rule 10CFR50 supports Commission policy of upgrading emergency preparedness for operators of nuclear plants Local gove emergency planning is assential component of overall emergency plan PRATT.C M Power Authority of the State of New York 80/02/19
- 8004100438 Comments on proposed rule 10CFR50 submitted by Putnam County,NY future workshops should include only those involved in making of plans SCALPI.M Affiliation Unknown B0/02/13 ip
- 8004100439 Comments on proposed rule 10CFRSO neither Alternative A or B acceptable Concurrence rule would pre-compt NRC authority to shut down plants or withhold licensing Fifteen-minute notification requirement is not justified BTAMPLEY, N L Mississippi Power & Light Co AECM-80/39 80/02/19
- 8004100450 Testimony before NY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities KLEIN.J V Suffolk County, NY 79/07/10 Bpp
- --8004100460 Testimony before NY State Board on Electric Generation Siting & Environ re proposed Jamesport facilities Prof qualifications encl GEISELMAN, J N Suffolk County, NY 79/06/29 App
- --8004100472 Testimony before NY State Board on Electric Generation Biting & Environ re proposed Jamesport facilities Related diagrams, ref & prof qualifications encl DIARDINA, PA Suffolk County, NY 79706/29 25pp
- 8004100441 Comments on proposed rule 10CFR50 local funding issue should be considered Federal & state manpower should be available to aid in problems at local level Local personnel should be consulted prior to formulation of related regulations TERRELL.D Suffolk County, NY 80/02/08 1p
- 8004100443 Ack receipt of 800201 ltrs requesting comments on proposed emergency planning rule Comments from state representatives will be consolidated into single response SMITH,E H New York, State of 80/02/13 1p
- 8004100445 Comments on proposed rule 10CFR50 15-minute early warning is impractical Recommends use of Emergency Broadcast Sys Deadline for NRC concurrence in state & local plans is not reasonable Lack of county govt in CT poses special problems MANCUSD,F. Connecticut, State of 80/02/28 2pp
- 8004100449 Comments on proposed rule 10CFR50 shortcoming lies in NRC inability to direct govt units to prepare plan & compel adequacy MYDLER, J. W. House of Rep., Science & Technology 80/02/15 ip
- 8004100494 Comments on proposed rule 10CFR50 no OL should be granted unless NRC finds that appropriate protective actions can be taken within emergency planning zone AMATO.S Rhode Island, State of 80/02/25 2pp
- 8004100501 Comments on proposed rule (OCFR50 submitted on behalf of Brooklyn SHAD If locality unable to finance adequate plan. Itcensee should finance or formulate own plan Supports Alternative B ORGBS.M Affiliation Unknown 80/02/28 3pp
- 8004100515 Comments on proposed rule 10CFR50 rule does not provide definitive guidance & criteria Objects to use of utils to obtain concurrence in state & local emergency plans FEMA should have lead responsibility
 WARD.J E Atomic Industrial Forum 80/02/20 16pp

ī

- 8004100540 Comments on proposed rule 10CFR50 insufficient time allowed to develop comprehensive emergency response plans Recommends revised draft plans be submitted to NRC/FEMA for review by BiO101 & final concurrence achieved by BiO701 KEARNS, J J California, State of 80/02/15 App
- --8004100544 Comments on proposed rule 10CFR50 NRC involvement in review & evaluation of response plans is integral part of overall responsibility for protection of public San Luis Obispo County B00115 ltr to State of CA encl
 LANGLEY, C Affiliation Unknown 80/01/08 6pp
- BOO4100589 Comments on proposed rule 10CFR50 legislation should be proposed requiring that tax revenues generated by operating plants be applied to costs of emergency planning Addresses problem on generic basis % assures continued cooperation MAURD, J. J. Ebasco Services. Inc. (subs. of Enserch Corp.) 80/02/11 4pp
- 8004100604 Forwards comments concerning proposed rule 10CFR50 NAMDJ,M New Hampshire, State of 80/02/28 1p
- -B004100609 Comments on proposed rule 10CFR50 improved prompt notification & warning of general public needed Bys should be available. & applicable to air hazards which would require prompt notification.
 FOLEY, E. New Hampshire, State of B0/02/27 ip
- -8004100612 Comments on proposed rule 10CFR50 NRC should approach proposal as significant regulatory change Flexibility in concurrence procedure is necessary & deserves commitment & attention KINDER,E T New Hampshire, State of 80/01/15 App
- 8004i10107 Forwards comments on proposed rule 10CFR50 evacuation may not be necessary for every type of potential accident Fifteen-minute notification period should begin after state or local officials decide evacuation is necessary General Electric Co , Nuclear Energy Products Div KAPLAN,A L Ge 80/02/22 16pp
- 8004110127 Comments on proposed rule 10CFR50 cooperative working relationships should be developed in areas of radiological emergency response planning to assure protection of public health & safety CLINE.W E Georgia, State of 80/03/04 3pp
- 8004110147 Comments on proposed rule 10CFR50 language is ambiguous in places More clarification & numerous editorial changes tuggested QRENDON, I Affiliation Unknown 79/12/29 4pp
- 8004110367 Comments on proposed rule 10CFR90, opposes mandatory participation in NPRDB Improvement to NPRDS can & should be achieved but not by adding regulatory actions in areas of questionable near-term safety significance KEARNEY, J J Edison Electric Institute 80/03/31 2PP
- B004110477 Comments on proposed rule 10CFR2 expresses great disappointment that proposed changes fail to solve problems of NRC licensing sys Proposed regulations only protect over-inflated gos of licensing members KEPFORD
- BOO41104BO Comments on proposed rule iOCFR2 proposed use of part-time members as special master or alternate board members would be contrary to both Atomic Energy Act & Administrative Procedure Act LEBOCUFIR J : LAMB, H R : LEIBY A C LeBoeuf, Lamb, Leiby & MacRae 80/03/24
- 8004110484 Comments on proposed rule 10CFR2 provisions for preparation of advisory repts by special assistants should be deleted VAN BRUNT, E. Artzona Public Service Co. 80/03/25 3pp
- 8004110491 Comments on proposed rule 10CFR50 opposes requirement for mandatory participation in NPRDS Implementation costs are overstated MCNEGR:C S Wisconsin Electric Power Co 80/03/20 2pp
- 8004110496 Comments on proposed rule 10CFR50 NRC should perform thorough reassessment of needs served by NPRD8 before mandating wider participation MCCUTCHAN. D A Westinghouse Electric Corp 80/03/07 3pp
- 8004110505 Comments on proposed rule IOCFR50 opposes regulations making NPRDS mandatory Submits response to 21 questions in FR notice HAUETER.R L. Consumers Power Co 80/03/11 18pp

- BOD4110523 Comments on proposed rules 10CFR2,19,20,21,30,40,51,40, & 70 rules are inadequate re-participation of Indian Tribal govts Failure to involve tribes in initial process will result in later practical & political difficulties STONE,R J Energy,Dept of 80/03/24 2pp
- BOO4110535 Comments on proposed rule IOCFR50 budget severely limits county emergency preparedness Overall emergency planning operation would be enhanced of facility & county personnel could meet HAYES, W.K. Orean County, NJ 80/02/17 3pp
- 8004110558 Comments on proposed rule 10CFR50 alternatives to negative declaration may offer comparable benefits, but cost significantly less Provisions should be made for basis to assess replacement costs associated w/plant shutdown PARKER,W D Duke Power Co 80/02/19 2pp
- GOO4140005 Forwards comments on proposed rules 10CFR30,40,50 & 70 on behalf of CPC financial provision for decommissioning is most efficient & economical procedure REYNOLDS,N S Debevoise & Liberman 60/03/20 4pp 80/03/20
- 8004140025 Comments on proposed rule 10CFR50 NRC has broadly interpreted Commission charter re requiring emergency plans to be formulated, but stops short of forcing state govts to see plans are prepared Handatory requirements are needed WYDLER, J W House of Rep., Science & Technology 80/02/15 80/02/15
- 8004140047 Forwards comments on proposed rule 10CFR50 made at NRC 800117 emergency preparedness workshop in Ban Francisco,CA OLCOTT,K Affiliation Unknown 80/01/17 ip
- --8004140052 Comments on iOCFR50 presented at NRC BO0117 emergency preparedness workshop in Ban Francisco.CA Adequate amergency planning should be requirement for nuclear facility CP & OL OLCOTT.K Affiliation Unknown BO/01/17 2pp
- 8004140094 Comments on proposed rule 10CFR50 size of emergency planning iones should be determined on individual basis re demography, topography, land characteristics, access routes & local jurisdictional boundaries ANDERBUN, T.M. Westinghouse Electric Curp. NB-TMA-220B. B0/02/19
- 8004140046 Forwards comments on proposed rule 100FR50 TOWNEND.F Luserne County.PA 80/02/08 tp
- ~-8004140100 Comments on proposed rule 10CFR50 util should be responsible for activities on nuclear facility site Ogyt should be responsible for offsite activities Use of term "plume exposure pathway emergency planning zone" is misleading TOWNEND, F. Luzerne County, PA 80/01/16 2pp
- G004140105 Comments on proposed rule 10CFR50 realistic plume exposure & ingestion pathway zones must be established regardless of difficulty of evacuation in https://doi.org/10.1016/10.1016/10.1016/10.1016/10.1016/10.1016
- BOO4140109 Comments on proposed rule 10CFR80 App E acceptable, but waste of time to have applicant provide analysis of time required to evacuate sectors in plume exposure pathway Buggests that NRC consider plant siting more critically PAGNO, C. L. New Jersey, State of 80/02/22 ip
- 8004140112 Comments on proposed rule 10CFR50 on behalf of 8CANP Ofc has yet to receive requested documents that are essential for preparation of comments due to NRC delay TOLEERT-P E Leed.R M 80/02/22 2pp
- 8004140131 Comments on proposed rulemaking submitted by NY City Har Association supports AEC intention to withdraw 2-yr discovery clause Bupports exclusion re claimants w/ abnormally sensitive activities AXELRAD. M Affiliation Unknown 69/01/20 5pp
- 8004140149 Comments on proposed rule iCCFR30 NRC role during nuclear emergency & final authority of governor must be clearly defined State should be directly notified of NRC requirements re licensee or local authority PAGANO.C L. New Jersey, State of 80/02/22 ip
- 8004140419 Comments on proposed rule 100FR50 actual emergency preparedness should be criteria for concurrence & not merely existence of state & local plans Criteria for determining insignificant deficiencies heeds to be established CARR:H League of Homen Voters of San Luis Obispo.CA 80/02/14

- 8004140426 Comments on proposed rule 10CFR50 adequate emergency planning should be required for CP Plants should be shut down in absence of concurrence Public should be notified of emergency procedures at 3-6 month intervals OLCOTT, K Affiliation Unknown 80/01/17 3pp
- BQD4;50:22 Comments on proposed rule iOCFR50 requirements for local & state approval of licensee emergency plans can result in subversion of entire open licensing process by small group of individuals

 BTEINDLER.H J Argonne National Laboratory 60/01/02 3pp
- BOO-4150224 Forwards FR notice of proposed rule 10CFR70 re issuance of general license to carriers of irradiated BNN Final version of rule will be developed after consideration at public comments
 HINGOUE/R B Office of Standards Development 80/03/25 2pp
- 80-04160055 Comments on proposed rule 10CFR50 no GL should be issued unless NRC finds that appropriate protective actions can be taken for any reasonably anticipated population within plume explosure emergency planning ione
 AMATO, S. Rhode Island, State of 80/02/25 2pp
- 8004160078 Forwards comments on proposed rule 10CFR50 each nonpower reactor operation needs emergency planning zone Unique to operation Basic plan should be appropriately designed Evacuation may not be needed for all potential incidents KAPLANAL General Electric Co., Nuclear Energy Products Div 80/02/22 16pp
- 8004160096 Comments on groposed rule 10CFR80 NRC is trying to impose detailed requirements from draft document. NUREO-0654 NRC has ignored industry & peer comments Rush to implement draft matts causes concern. Util 800219 additionments encl VANDENBURGH, D. Yankee Atomic Electric Co. WYC-80-3 80/02/29 28 nr.
- --B004160102 Comments on proposed rule 10CFR50 linkage between enforcement actions against NRC licensess & failures by state & local govts to achieve concurrence u/federal govt is illogical Negative declaration entirely fallacious VANDENBURGH, D Vankee Atomic Electric Co HYC 80-2 80/02/19 30n
- 8004160186 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800410 FR notice encl (AHEARNE, J F Commission 80/03/12 1p
- --BOO4160190 Requests comments on proposed rulemaking concerning dispusal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AMEARNE.J F Commission 80/03/12 2pp
- ---BOO4160196 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by by 800415,FR notice and AMEARNE,JF Commission 80/03/12 2pp
- ---BOO4160200 Requests comments on proposed rulemaking concerning disposal of radvastes produced by nuclear facilities Comments due by GO0415 FR notice encl AHEARNE.JF Commission 80/03/12 2pp
- --BOO4160202 Requests comments on proposed rulemaking cancerning disposal of radwastes produced by nuclear facilities Comments due by BO0415.FR notice encl AHEARNE, JF Commission 80/03/12 2pp
- --BOO4160203 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BOO415 FR notice encil AMEARNE, J F Commission 80/03/12 2pp
- ~-BOO4160206 Requests comments on proposed rulemaking concerning disposal of radwestes produced by nuclear facilities Comments due by BO0415 FR notice encl AHEARNE.J.F Commission 80/03/12, 2pp
- --8004160209 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BO0413 FR notice encl AHEARNE.J.F Commission B0/03/12 2pp

- --8004160212 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE, J F Commission 80/03/12 2pp
- ---8004160215 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice and AMEARNE, J F Commission 80/03/12 2pp
- --8004160220 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE, J F Commission 80/03/12 5pp
- BOO4170202 Forwards questions & comments resulting from 800219-20 meeting w/Radiological Assistance Committee.Radiological Emergency Planners & FEMA Region 5 state directors in Olen Ellyn.IL re revised criteria in NUREG-0654/FEMA REP-1 MCCOLLOUOH, P H Federal Emergency Management Agency 80/03/07 600
- BOO41702B4 Forwards comments on proposed rule 10CFR50 Includes Jan 1980 ltr from NH assistant attorney general to NRC NAMOJ.M New Hampshire, State of 80/02/28 Spp
- 8004170348 "Deletion of Ref to Panama Canal Zone Minor Amends," iOCFR4, 20, 30, 40, 50, 55, 70, iiO & 150 final rule Minor amends revise portions of Commission regulations to reflect revised status of Canal Zone DIRCKB W J Office of the Executive Director for Operations 80/03/14 5pp
- 8004170355 "Export of Certain Minor Quantities of Nuclear Matl," 10CFR110 final rule Amends regulations to establish ur expand general licensing provisions for gram quantities of SMM & certain kinds of source & byproduct matl CHILK.5 J Office of the Secretary of the Commission 80/03/14 13pp
- 8004180211 Responds to 800128 ltr re NRC emphasis on emergency planning for nuclear accidents NRC & FEMA cooperate in developing emergency planning rules & related state guidance AHEARNE. J F Commission 80/03/18 ip
- --8004180220 Comments on proposed rule re emergency planning more emphasis should be placed on planning for probability of catastrophic nuclear accident in context of potential danger from nuclear weapons & other possible diasters HYDLER.J W House of Rep. 80/01/28 19
- B004180304 Responds to 791120 ltr re certain aspects of NRC proposed new 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories: Procedural Aspects " Need for in situ testing & exploration supported by USOS, MSS & earth science community AHEARNE, J F Commission 80/03/18 Bpp
- --8004180311 Responds to 791120 ltr re certain aspects of NRC proposed new iOCFR60. "Disposal of High Level Radwaste in Geologic Repositories:Procedural Aspects "Need for in situ testing & exploration supported by USGG.NAS & earth science community AHEARNE.JF Commission 80/03/18 Spp
- --8004180319 Comments on Proposed Rule 10CFR40 multiple geologic testing & exploration unnecessary & costly NRC should support DOE repository development program WYDLER.J W. House of Rep ; Science & Technology 80/01/20 2pp
- 8004180477 Comments on proposed rule 10CFR50 opposes any regulations which make NPRDS mandatory Persons supplying info would become more interested in compliance wirequirements than using sys to enhance plant safety & reliability GARY,R J Texas Utilities Generating Co 80/03/10 ip
- 8004210110 Comments on proposed rule 10CFR50 illogical linkage botween enforcement actions & failures by local & state goyts to achieve concurrence wifederal agencies is flaw which could result in substantial environ impact VADENBURGH,D Yankee Atomic Electric Co WYC 80-2 80/02/19 3pp
- BO04210118 Comments on proposed rule 10CFR50 intended to write something into record before deadline Time did not permit mention of issues Advising other II residents that FR exits BONNEVILLE, R B Affiliation Unknown BO
- 8004210140 Comments on proposed rule IOCFR50 NRC role during course of nuclear emergency should be clearly defined Governor should be final authority to render decisions State needs to be made aware of NRC requirements for licenses & authorities PAGANO.C L New Jersey, State of 80/02/22 ip

- 8004210150 Comments on proposed rule 10CFR50 nuclear plants would be pawns in game in which owner-operators have little ability to affect outcome
 HUNTER:R S American Electric Power Co , Inc. 80/02/20 5pp
- 8004210154 Forwards comments on proposed rule 100FR50 from MN Dept of Public Safety FRENZEL, B House of Rep 80/03/07 1p
- --8004210160 Comments on proposed rule tOCFR50 consequences should be weighed re reactor sites inwhich adjoining states are within reactor emergency planning zone KITTRIDEE.G R Minnesota, State of 80/02/23 3pp
- 8004210353 Forwards statement of position per presiding officer 800201 re proposed rolemaking in radwaste storage & disposal DISTEFANO.J., COLEMAN.L.R., BROWN.O.F. Energy.Dept of 80/04/15
- ---8004210361 Statement of position re proposed rulemaking on radwaste storage & disposal Fuel may be disposed of offsite & may be stored safely onsite or offsite until ultimately disposed H/supporting documentation & Certificate of Svc DISTEFANO, J. DOLEMAN, C R. BROWNIO F Energy, Dept of DDE/NE-0007 80/04/15 715pp
- 8004210446 Comments on proposed rule 10CFR50 during operation all response coordinators should be operational as unit, vs existing situation County maintains four salaried personnel to achieve some degree of emergency preparedness HAYES,N K. Ocean County, NJ 80/02/17 3pp
- 8004230047 Forwards list of participants & computer bibliography index of waste storage & disposal documents placed in PDR List will be updated periodically & copies sent to participants CYR.K D Rulemaking & Enforcement Division 80/03/28 28pp
- 8004230073 Comments on proposed rule 10CFR2 NRC should not adopt provisions except for 2 713(b) Submits add1 comments reproposed changes in govt discipline adjudicatory proceedings proceedings JOHNSRUD.J H Environmental Coalition on Nuclear Power 80/03/03
- B004240230 Advises that 168 core documents on waste storage & disposal have been placed in PDR per proposed rules 100FR30 & 31 List of documents & info on placing orders encl
 CYR.K D Office of the Executive Legal Director. 80/03/28 27pp
- 8004240568 Forwards comments on proposed rule iCCFR50 smergency plans should be upgraded in response to potential hazards. Fundamental problem exists in coordinating plans of state local acencies Energy, Dept of 80/03/04 11sp PRESSESKY A J
- 8004250071 Comments on proposed rule 10CFR50 FEMA position on proposed rule, that action should be deferred for further evaluation. is appropriate
 KNUTH DF KMC. Inc 80/03/14 3pp
- 8004250306 Comments on proposed rule 10CRF50 air lock testing of air lock not used in sir-month period should not be required until after usage or within three days of first opening, if containment integrity required ERVIN,P E Affiliation Unknown 80/02/17 ip
- 8004280075 NUREG/CP-0011

 "Proceedings of Horkshops on Proposed Rulemaking on Emergency Planning for Nuclear Power Plants "PEABDY,C A. MORRONGIELLO,A Division of Biting, Health & Bafeguards Standards 80/04/30 113pp. Available at NTIB
- 8004280077 Forwards summary of NRC licensing program for high level radioactive waste disposal includes NRC 791205 FR notice & Div of Waste Mgt FY81 budget for high level waste mgt program CYR.K D Rulemaking & Enforcement Division 80/04/16 32pp
- 8004280172 Forwards comments on proposed rule 10CFR50 definition of local govt entities needed. Required NRC concurrence in state & local emergency plans gives NRC undue influence in local affairs, particularly in area of employment stability PREBSESKY, A J Energy, Dept of 80/03/04, 11pp
- 8004280218 Preliminary statement in response to Chairman Ahearne 800312 itr re proposed rulemaking on radwaste storage & disposal Solid radwaste may be disposed of w/o risk based on fundamental earth science processes a Interior, Dept of, Geological Survey 80/04/15 iApp

- B004280473 Comments on proposed rules 10CFR30,40,50 & 70 EPA stds re radioactsvity levels currently under discussion & should not be considered final PORTER.W L. Duke Power Co. 80/03/14 3pp
- 8004300279 Comments on proposed rule 10CFR2 not appropriate to specify number of sites & media to be explored in advance; endorses concepts & intent re site characterization reptiNRC requirements concerning site selection should be broad BARTLETT, J W The Analytic Sciences Corp 80/03/09 7pp
- 8004300532 Comments on proposed rule 10CFR2 opposes Subsections 2 722 (a)(2) & (3) Proposed regulation would subj special assistant to disqualification procedures Proposal to amend rule & allow ASLB special assistants should be deleted VAN BRUNT, E E Arizona Public Service Co 80/03/25 3pp
- PETITION FOR RULEMAKING
- 8004040243 Comments on petition for rulemaking requests NRC position re question of vulnerability to possible enemy action in design of nuclear power plants NK Watson 800106 ltr encl DICKS N D House of Rep. 80/02/15 ip
- 80040B0110 Draft ltr responding to 680703 comments re publication of proposed amends re financial protection requirements & indemnity agreements DT concerns have been resolved by adding language clarifying effective rule PRICE, E R Atomic Energy Commission 68/07/18 1p
- B004090224 Comments on petition for rulemaking 50-26 petition is based on several erroneous assumptions & should be denied Petition forces unreasonable requirements on new nuclear facilities OILMAN.D W San Diego Gas & Electric Co B0/03/07 2pp
- 8004100033 Transcript of 800313 Affirmation Session 80-10 in Washington.DC Pp 1-5 * Commission 80/03/13 Spp
- --8004100039 SECY-80-095 DATIONSY SECTOR 00095

 Recommends NRC approval of FR publication of encl notice of denial of petition for rulemaking 2-5

 SHAPAR, H K Office of the Executive Legal Director 80/02/14
- 8004100057 Comments on petition for rulemaking concern about explosion of nuclear weapon in vicinity of nuclear facility exemplifies NRC overreaction to potential hazards Planning for such contingencies increases energy cost to ratepayers PETERSON, R J Affiliation Unknown 80/03/05 ip
- BO04100064 Comments on petition for relemaking proposed further increase cost & delay const of needed power p for no useful purpose LOVE. E. Affiliation Unknown BO/03/03 ip

- ---8004140133 Forwards FR notice denying state of NH 781031 petition for rulemaking re efficiency in licensing Denial based on public comments & current extensive review & evaluation of NRC licensing requirements & procedures W/o encl CHILK, S J Office of the Secretary of the Commission 80/03/21
- --8004140135 Forwards FR notice denying State of NH 781031 petition for rulemaking re efficiency in kicensing Denial based on public comments & current estensive review & evaluation of NRC licensing requirements & procedures W/o encl CHILK.B J. Office of the Secretary of the Commission 80/03/21 in
- --8004140139 Forwards FR notice denying State of NH 781031 petition for rulemaking re efficiency in licensing Denial based on public comments & current extensive review & evaluation of NRC licensing requirements & procedures W/o encl CHILK.S J Office of the Secretary of the Commission 80/03/21 in
- --8004140140 Forwards FR notice denying State of NH 781031 petition for rulemaking re efficiency in licensing Denial based on public comments & current extensive review & evaluation of NRC licensing requirements & procedures CHILK, S J Office of the Secretary of the Commission 80/03/21
- ---B004140145 Notice of denial of petition for rulemaking re efficiency in licensing nuclear power facilities Denial based on public comments & corrent extensive review & evaluation of NRC licensing regultements & procedures CHILK.S J Office of the Secretary of the Commission 80/03/21
- 8004140245 Forwards draft notice of denial of Petition for Rulemaking 2-9 requesting to amend 100FR2 to limit intervenor cross-examination
 SHAPARIH K Office of the Executive Legal Director. 80/03/12 8pp
- 8004240194 Discusses, on behalf of Northern IN PSC, State of IL & Porter County Chapter of Izaak Halton League of America: Inc et al. 791220 petitions seeking amend or rescindment of 10CFR50 55(b) No good cause re const completion date shown SMEAK H . FRANTZ, S P Lowenstein, Nawman, Reis, Axelrad & Toll 80/04/07 12pp

PROJECTS - PREDOCKET LICENSING

- 8004020063 Forwards Denver & Albuquerque public meeting transcripts in response to 800212 request Name of commentator & affiliation are identified in transcript where possible W/o encl F16HER.B Uranium Recovery Licensing Branch 80/03/18 ip
- 8004030317 Bubmits info re util 800222 survey of files of intervenor-City of Roseville.CA Survey was done to verify document discovery re comprehensive performance of NCPA Omissions discovered MEISB.R L Pacific Oas & Electric Co 80/02/27 2pp
- BOO404000B Forwards belance of exhibit to second supplemental answers to fourth set of interrogatories from CA Dept of Water Resources
 MEIBB.R L Pacific Oas & Electric Co 80/03/13 ip
- --800404006B Prepared testimony re transmission functional sub categories within transmission cost category required for accounting purposes Description of transmission functions & related financial info encl.
 PATTERSON
- 8004080012 Notice of appearance in proceeding Certificate of Bvc encl COSGRIFF, JE Pacific Oes & Electric Co. COSGRIFF, JE McCotchen: Doyle: Brown & Emersen 80/03/18. 4pp.
- 80040B0132 Motion to compel CA Dept of Mater Resources compliance w/ ABLB 791109 & B00116 orders re answers to certain of PO&E fifth set of interrogatories Supplemental answers dtd B00303 do not comply w/orders, Certificate of Svc encl COBORIFF, J. E. Pacific Oas & Electric Co. * McCoutchen, Doyle, Brown & Emerson. B0/03/18 30pp
- BOO4080445 Forwards City of Santa Clara responses to PQ&E fifth set of interrogatories directed to Northern CA Power Agency & CA Dept of Water Resources & to PQ&E fourth set of interrogatories directed to cfties of Anheim & Riverside ADRAQNA.J.M Spiegel & McDiarmid. 80/03/13. 2pp

- 8004090208 Motion stating points & authorities directed to US ninth circuit court of appeals re review of ASLB 780828 subpoena duces tecum Requests order requesting 90-day stay for briefing schedule W/draft order & Certificate of Svc RIZZI,R A . BARRY,D N Southern California Edison Co RIZZI,R A Obson. Dunn & Crutcher 80/03/03 7pp
- 8004100547 Responds to 800229 ltr refusing to accept Northern CA Power Agency voluntary document production & insisting on green dotting process Deplares PGBE harrassment tactics Requests maeting to resolve problem ADRAGNA, J M Spiegel & McDiarmid 80/03/05 3pp
- B004100556 Forwards responses to PG&E fifth set of interrogatories to Northern CA Power Agency & Dept of Water Resources & fourth set of interrogatories to Cities of Anaheim & Riverside dtd 790719 W/o encl
 TRAUGER, T C Spiegel & McDiarmid 80/03/03 4pp
- 8004150173 Order granting extension until 800417 for CA Dept of Water Resources to respond to PG&E 800328 fifth set of interrogatories MILLER.M E Atomic Safety and Licensing Board Panel 80/04/08 ip
- BOD4160280 Advises of omitted transmittal slips & corresponding boses re stipulation concerning production of documents stored in warehouse Requests production of boses during final visit to records ctr OCLOBERG. A Antitrust Division BO/04/15 20p
- B0041B0279 Forwards response to 791206 inquiry re NRC Agreement States program & Church Rock dam failure RI submittal satisfied Atomic Energy Acts Section 274 requirements for admission as Agreement State AHEARNE, J F Commission B0/03/17 10pp
- 8004230275 Forwards Southern CA Edison Co & NRC agreement & joint statement re subpoema duces tecum Also forwards NRC stipulation re Edison documents production Issue resolved ODLOBERG. J R Antitrust Division 80/04/22 ip
- --8004230302 Executed agreement & joint statement re subpoena duces tecum issued to Southern CA Edison Co re production of documents by Edison to NRC EHERMODD: A L Southern California Edison Co GOLDBERG, J R Antitrust Division 80/04/08 6pp
- --B004230317 Executed stipulation re production of documents by Southern CA Edison Co to CA Dopt of Water Resources & NRC Production agreed upon will satisfy subpense for which Edison will uithdraw appeal before US 7th circuit Draft order enci SHERWOOD. A L. Southern California Edison Co STRUMWASSER, M California, State of GOLDBERG, J R Antitrust Division BO/04/10 4pp
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8004100061 Part 21 rept re defective Rosemount Model 5100U trip/calibr units & Model 1152 pressure transmitters Caused by failure of essential switch that determines trip output logic & failure of transmitter capacitor, respectively SHERWOOD, O G General Electric Co MFN-065-80 80/03/21 2pp
- 8004210345 Deficiency rept re NIBD23 fire damper spring brackets Cause unstated Tests being conducted to demonstrate effectiveness of bracket screws & to establish more stringent installation requirements

 HILL.T D Ruskin Manufacturing Co 80-193-001 80/03/17 1p
- 8004280248 Part 21 rept revising 800206 notification re ITT AH70 & NH70 series electrohydraulic actuators Attachment listing customers & projects should contain addl item Baint Lucie facility & customer Buffalo Forge Co should be added SLOAN,D E American Warming & Ventilating, Inc 80/03/19 Spp
- 8004300274 Part 21 rept re improper installation & inconsistent closure of Ruskin Hfg Co NIBD23 fire damper spring brackets during cycling tests Mfg taking corrective action HILL.T D. Ruskin Manufacturing Co 80/03/17. 2pp.
- 8004300536 Part 21 rept re Dresser Industries pilot operated relief valves & ABME code safety valves designed & tested for saturated steam as only flow medium Utils & AEs have been notified
 TACY, H Dresser Industries, Inc. 80/04/01 6pp

NONDOCKETED ITEMS

GA999 QUALITY ASSURANCE INSPECTIONS

- 8004010512 Forwards QA Program Insp Rept 99700022/79-01 on 791218-19 PDTAFOVS, U Region 4, Dallas, Vendor Inspection Branch 80/01/14 20p
- --8004010515 GA Program Insp Rept 99900022/79-01 on 791218-19 Insp revealed wendor ABME NPT certificate of authorization omitted product description Corrected certificate requested DLLER,R E, HUNNICUIT D M Region 4, Dallas, Office of the Director 80/01/14 3pp
- 8004020423 Forwards GA Program Insp Rept 9990251/80-01 on 800128-0201 No nancompliance noted POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/02/14
- ---8004020434 GA Program Insp Rept 99900251/80-01 on 800128-0201 No noncompliance noted Major areas inspected mot meeting & implementation of GA program interface w/ANI.mgt process control.control of nonconformance & corrective action WHITESELL.D E , BROWN.R L. Region 4, Dallas, Vendor Inspection Branch 80/02/13 15pp
- G004030235 Ack receipt of B00305 ltr informing NRC of steps taken to correct violation noted in GA Program Insp Rept 9990034279-02
 PDTAPGVS.U Region 4. Dalias. Office of the Director 80/03/19
- --B004030237 Responds to NRC 791210-14 audit deviation noted in QA Program Insp Rept 99900342/79-02 Corrective actions welds ultrasonically tasted to insure soundness floor inspectors instructed to survey use of template sticks ROZEK.R Lakeside Bridge & Steel Co SO/03/05 2pp
- --8004030237 Forwards GA Program Insp Rept 97900342/79-02 on 791210-14 & notice of deviation POTAPOVB.U Region 4, Dallas, Office of the Director 80/01/07 2nn
- --8004030242 Notice of deviation from insp on 791210-14
 * Region 4, Dallas, Office of the Director 80/01/04 1p
- --8004030244 OA Program Insp Rept 99900342/79-02 on 791210-14
 Noncompliance noted welding performed w/o welders equipped
 to measure interpass temps certain areas not evaluated
 by qualified welders
 ELLERSHAW.L E . HUNNICUTT.D M Region 4. Dallas. Office of the
 Director 80/01/04 9pp
- 8004040100 Forwards GA Program Insp Rept 9990004/80-01 on 800122-23 No noncompliance noted. BROWN.0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/02/24 ip
- --8004040104 GA Program Insp Rept 9990004/80-01 on 800122-23 No noncompliance noted Major areas inspected radiological evaluations conducted in Moab,UT WILBORN,L Region 4. Dallas, Office of the Director BROWN,Q D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/02/20 App
- 8004040111 Forwards GA program Insp Rept 99900048/79-02 on 791210-13 No noncompliance noted FOTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/02/06
- --9004040122 GA Program Insp Rept 99900048/79-01 on 791210-13 No noncompliance noted Major areas inspected review of corrective actions for reported deficiencies under 10CFR21 HUNTER,V H. WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch 80/01/30 9pp
- 8004040476 Ack receipt of 800228 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 97900004780-01 POTAPGV5, U Region 4, Dallas, Vendor Inspection Branch 80/03/10

- --8004040479 Responds to NRC 800122 ltr re deviation noted in GA Progra Insp Rept 99900004/80-01 Corrective actions coater operating procedure is being revised to reference correct parameter sheet FHD 1197 OALLAMAY.W C General Atomic Co (subs of Gulf Oil Co) 80/02/28 4pp
- --B004040348 Forwards QA Program Insp Rept 97900004/B0-01 on B00107-11 & notice of deviation POTAPDVB.U Region 4, Dailas, Vandor Inspection Branch B0/01/22 20p
- --8004040352 Notice of deviation from insp on 800107-11
 * Region 4, Dailas, Office of the Director 80/01/18 ip
- --8004040361 GA Program Insp Rept 99900004/80-01 on 800107-11
 Noncompliance noted review of product documents did not
 assure all requirements were clearly & accurately stated
 Approval not indicated by signature
 WHITESELL, D E. MCNEIL, W M. Region 4, Dallas, Vendor Inspection
 Branch 80/01/18 5pp
- B004070076 Ack receipt of 790912 & B00219 ltrs informing NRC of steps taken to correct violation noted in GA Program Insp Rept 99900372779-01 PDTAPDVS.U Region 4, Dallas, Vendor Inspection Branch 80/03/04
- --800407007? Forwards response to 800214 telcon w/Foster re deviation noted in GA Insp Rept 99900372/79-01 Corrective action engineering instructions reissued w/proper sign-off blocks ROBEN.A E Anaconda Co . Anaconda Industries Wire & Cable Div 80/02/19 3pp
- --8004070081 Responds to NRC 790822 ltr re deviation noted in GA Progra Insp Rept 99900372/79-01 Corrective action instruction re production tags provided to responsible GA & mfg personnel ROBEN.A.E. Anaconda Co . Anaconda Industries Wire & Cable Div 79/09/12 Spp
- --8004070083 Act receipt of 790912 ltr in response to NRC 790822 ltr Addl info requested per 790926 telcon w/AE Rosen POTAPOVS:U Region 4: Dallas: Vendor Inspection Branch 79/09/28
- --8004070087 Forwards GA Program Insp Rept 99900372/79-01 on 790807-10 notice of deviation PUTAPDVB,U Region 4. Dailas. Vendor Inspection Branch 79/08/22 200

- --8004080276 Forwards GA Program Insp Rept 99900379/79-01 on 791019-19 & notice of deviation POTAPDVS.U Region 4. Dallas, Vendor Inspection Branch 79/11/05
- 79/11/05 200
- --BOD4080287 GA Program Insp Rept 99900379/79-01 on 791015-19
 Noncompliance noted inconsistent GA practice re Criterion 5
 of App B to 10CFR50 No requirement to initiate test
 procedures re tests in machanical gneumatic test lab
 HUNNICUTT, D M , FOBTER, H E Region 4, Dallas, Vendor Inspection
 Branch 79/11/05 7pp
- BOO4080291 Ack receipt of 800229 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 97900300/80-01 POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/03/17

 - -BOO4080297 Responds to NRC 800207 itr re deviation noted in GA Program Insp Rept 9700300/80-01 Corrective actions mfg engineering std revised Mfg supervisor instructed machine operators to fill out operation sheets upon work completion MOROAN, J F Colt Industries. Inc., Fairbanks Morse Engine Div . 11pp 80/02/29
- ~~8004080301 Forwards QA Program Insp Rept 99700300/80-01 on 800121-25 & notice of deviation POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/02/07
- ---8004080306 Notice of deviation from insp on 800121-25
 * Region 4, Dallas, Office of the Director 80/02 80/02/06 2pp
- ---8004080316 GA Program Insp Rept 97900300/80-01 on 800121-25 Noncompliance noted mfg engineering stds, revisions & addenda not maintained & issued by mfg engineering dept to all holders FOSTER: M E , HUNNICUTY, D M Ragion 4: Dallas, Vandor Inspection Branch 80/02/06 12pp
- 8004080358 Ack receipt of 800227 itr informing NRC of steps taken to correct deviation & violation noted in GA Program Insp. Rept. 99900387/79-01 POTAPOVS U Region 4. Dalles, Vendor Inspection Branch 80/03/14
- --BOO4080365 Responds to NRC 800128 ltr re deviation & violation noted in QA Program Insp Rept 99900387/79-01 Corrective actions. inspectors instructed to process cleanup sheet when subassably travelers are encountered COMPAS, M J General Atomic Co (subs of Gulf Oil Corp) BO/02/27. 3pp.
- --B004080369 Forwards GA Program Insp Rept 99900387/79-01 on 791210-14 & notices of deviation & violation POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/01/24
- 80/01/24
- ---8004080382 Notice of deviation from insp on 791210-14
 * Region 4, Dallas, Office of the Director 80/01 B0/01/24
- --B0040B03B9 QA Program Insp Rept 999003B7/79-01 on 791210-14
 Noncompliance noted.implementing instructions/procedures
 made no provisions for identifying test procedures on
 subassembly
 FOSTER.W E., HUNNICUTT, D M Region 4, Dailas, Vendor Inspection
 Branch. 80/01/24, 11pp
- 8004070035 Ack receipt of 800227 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700403/ 80-01.
 - POTAPOVS.U Region 4. Dellas, Vendor Inspection Branch 80/03/10
- --B004070059 Responds to NRC 800131 ltr rs deviation noted in GA Program Insp Rept 99900403/80-01 Corrective actions responses to future NRC inquiries that involve hardware quality will be based on extensive review of applicable data BARNARD, J. General Electric Co. 80/02/27 3pp
- 8004090067 Ack receipt of 800128 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900402/ 79-03 Addl info required re prevention of Item B recurrence POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch 80/02/22

- --8004090072 Responds to NRC 791214 ltm re deviation noted in GA Program Inap Rept 99700403/79-03 Corrective actions records were validated & reviewed by GC records specialists & found acceptable Tags removed from wide range monitors BARNARD.J General Electric Co 80/01/28 10pp
- --8004090078 Forwards GA Program Insp Rept 99900403/79-03 on 791001-05 & 30 & notice of deviation SEYFRIT.K V Region 4, Dallas, Office of the Director 79/12/14
- --8004090081 Notice of deviation from insp on 791001-05 & 30 * Region 4, Dallas, Office of the Director 79/11/27
- --8004090086 GA Program Insp Rept 99900403/79-03 on 791001-05 & 30 Noncompliance noted qualifications of functioning OE GA representative not certified & no source insps or surveillance performed during fabrication of fuel grapples COSTELLO, JR, FOSTER, WE, HALE, CJ, Region 4, Dallas, Vendor Inspection Branch 79/11/27 44pp
- 8004090282 Ack receipt of 800303 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 79700268/ 80-01 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/03/14
- -8004070287 Responds to NRC 800201 ltr re deviations noted in GA Program Insp Rept 99700268/80-01 Corrective actions filed eye records for all AMD pipe examiners Revised heat treatment operating Procedure 134 re recording of charge numbers MOON,R E ARMCO International, Inc. 80/03/03 2pp
- --8004090290 Forwards GA Program Imap Rept 99900268/80-01 on 800114-18 & notice of deviation POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch
- --8004090293 Notice of deviation from insp on 800114-18 * Region 4: Dallas, Office of the Director 80/01 60/01/31
- --8004090299 GA Program Insp Rept 99700268/80-01 on 800114-18
 Noncompliance noted deficiencies reported in Mar 1979 audit
 repts not resolved as required by GA manual
 HUNNICUTT,D M, GLLER,R E Region 4. Dallas, Vendor Inspection
 Branch 80/01/31 9pp
- 8004090307 Forwards CA Program Insp Rept 99900265/80-01 on 800128-31 No noncompliance noted POTAPOVS, U Region 4. Dalias, Vendor Inspection Branch 80/02/15
- --8004090310 GA Program Insp Rept 97900266/80-01 un 800128-31 No noncompliance noted Major areas inspected implementation of App B to 100FR50 & applicable codes & stds.including design document control,mfg control & special process control HONTER:V H . WHITESELL,D E Region 4, Dallas, Vendor Inspection Branch 80/02/14 2pp
- 8004070371 Ack receipt of 791023.800116 & 0305 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 97900519/79-03 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/03/20
- --8004090377 Responds to NRC 800215 ltr re deviation noted in GA Program Insp Rept 99900519/79-03 Specific SNUPPS findings will be answered applicable to all Gaithersburg projects within 90 KOKEB. J M Bechtel Power Corp (subs of Bechtel Corp) 80/03/05
- ---8004090382 Ack receipt of 791023 & 800116 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900519/79-03 Requests confirmation that delayed response to Deviation C will apply to all licensee divs POTAPOVB, U Region 4, Dellas, Vendor Inspection Branch 80/02/15
- --8004090386 Responds to NRC 791221 ltr re deviation noted in OA Program
 Insp Rept 99900519/79-03 Corrective actions IE Bulletin
 79-14 re generic implementation program for operating
 plants.Revision 2 was approved & issued for use on 791019
 KOMES, J M Bachtel Power Corp (subs of Bechtel Corp)
 80/01/16 3pp
- 8004100001 Forwards GA Program Insp Rept 99900075/80-01 on 800204-07 No noncompliance noted PATAPOVB, U Region 4, Dallas, Vendor Inspection Branch 80/02/22

- --8004100005 GA Program Insp Rept 99900075/80-01 on 800204-07 No noncompliance noted Major areas inspected design verification.computer programs.procurement document control, mfg process control, matl identification & training NHITESELL, D. E., KELLEY, W. D. Region 4, Dallas, Vendor Inspection Branch 80/02/21 13pp
- B004100031 Forwards QA Program Insp Rept 99900107/80-01 on 800107-11 No noncompliance noted POTAPDVS.V Region 4. Dallas. Vendor Inspection Branch 80/02/22
- --8004100034 GA Program Insp Rept 99900107/80-01 on 800107-11 No noncompliance noted Major areas inspected control of nonconformances & corrective action & field reported const deficiencies in containment vessols
 WHITESELL.D E . JUHNSON.J M . BROWN.R L Region 4. Dallas, Vendor Inspection Branch 80/02/14 19pp
- 8004110031 Ack receipt of 800311 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900302/ 80-01 POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/03/25
- --B004i10037 Responds to NRC B00228 ltr re deviations noted in OA Program Insp Rept 99700302/B0-01 Corrective actions come-up file sys instituted to reinforce audit requirement & all purchase orders will be forwarded to QA for review FRIEDMAN,K A Western Piping & Engineering Co , Inc B0/03/ii 3pp
- --8004110064 Forwards QA Program Insp Rept 99700302/60-01 on 800128-0201 & notice of deviation POTAPOVB.U Region 4. Dalias, Vendor Inspection Branch 80/02/28 200
- --8004110044 Notice of deviation from insp on 800128-0201 * Region 4, Dallas, Office of the Director 80/02/27 2pp
- c-8004i10057 QA Program Insp Rept 99900302/80-01 on 800128-0201 Noncompliance noted failure to take action re audits of personnel records: QA manager not reviewing all purchase orders & purchase orders issued to nonqualified vendors WHITESELL, D E , SUTTON, J W Region 4, Dallas, Vendor Inspection Branch 80/02/27 7pp
- 8004140011 Ack receipt of 800303,0201 & 791220 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp. Rept 99900047/79-02 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/03/24
- --8004140015 Responds to NRC 800219 ltr requesting addl info re deviation noted in GA Program Insp Rept 99900047/79-02 Corrective actions appropriate instructions have been forwarded to storeroom attendants re welding electrodes & log sheets MILLER: T D Westinghouse Electric Corp TDM-80-025 80/03/09 Ann
- ---8004140018 Ack receipt of 800201 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900047/ 79-02 Addl info required PQTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/02/19
- --B004140020 Responds to NRC B00116 ltr requesting add1 info re deviation noted in QA Program Insp Rept 99900047/79-02 Corrective actions storeroom attendants were reinstructed as to procedural requirements & importance of compliance MILLER, T D Wastinghouse Electric Corp TDM-80-013 B0/02/01 200
- --8004140029 Ack receipt of 791220 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900047/79-02 Add1 info required POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/01/16 200
- --8004140034 Responds to NRC 791115 itr re deviation noted in GA Program Insp Rept 9990047/79-02 Corrective actions importance of compliance re storeroom activities was reiterated to all personnel & unit manager will review log sheets daily MILLER.T D Westinghouse Electric Corp TDM-79-089 79/12/20
- --8004140037 Forwards QA Program Insp Rept 99900047/79-02 on 791015-19 & notice of deviation POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 79/11/15

- --8004140040 Notice of deviation from insp on 791015-19 * Region 4. Dallas, Office of the Director 79/11/15 3pp
- --8004140043 GA Program Insp Rept 99900047/79-02 on 791015-19
 Noncompliance noted storage practices for electrodes not in accordance w/required procedures, absence of mechanical test data & failure to prepare MRR before weld repairs
 HUNNICUTT,D M , ROBERDS,H W , BARNES,I Region 4, Dallas, Vendor Inspection Branch 79/11/15 10pp
- 8004150145 Forwards GA Program Insp Rept 97900403/80-01 on 800107-11 No noncompliance noted PATAPDVS.U Region 4. Dallas. Vendor Inspection Branch 80/01/31 200
- --8004150149 QA Program Insp Rept 99700403/80-01 on 800107-11 No noncompliance noted Major areas inspected special insp to verify responses to deviation in Insp Rept 99700403/79-02 HALE,C J. ELLERGHANL, E Region 4. Dallas. Vendor Inspection Branch 80/01/31 10pp
- 8004280136 Forwards QA program insp rept 99700400 on 790529 & 1104-08 & notice of violation STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/10 3pp
- --8004280142 Notice of proposed imposition of civil penalties in amount of \$100,000 re NRC 770527 \$ 1104-DB insp
 * Office of Inspection & Enforcement, Office of the Director 79-HG-001 80/04/10 lp
- --8004280146 Rept of 790514-31 investigation re B&W 205 fuel assembly PMR/alleged susceptibility to small break LUCAs THOMPSON D , WARD N J Executive Officer for Operations Support 79/06/26 300pp
- --8004280149 Rept of 791025-1126 investigation re B&W NPOD/possible violation of 10CFR21
 WARD, U.J., GOMER. G. Executive Officer for Operations Support WILBURN H A Division of Reactor Operations Inspections 79-HG-003 80/01/24 10Opp
- --8004280193 Rept of 790719-0817 investigation re 8&W/NPOD possible violation of 10CFR21 MARD.W J. GOWER.O C Executive Officer for Operations Support 79-48-002 79/09/18 100pp
- 8004270016 Ack receipt of 800321 itr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 79790023/79-03 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/04/03
- --8004270023 Responds to NRC 800208 ltr re deviations noted in GA Program Insp Rept 97700025/79-03 Corrective actions deficiencies due to lack of nondestructive exam on eight subassemblies corrected prior to 771231 MDERKE,N H Bouthwest Fabricating & Welding Co (subs of IU International Corp.) 80/03/21 Bpp
- --8004270021 Forwards QA Program Insp Rept 99900025/79-03 on 791205,19 & 20 & notice of deviation PDTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/02/08 & 2pp
- --8004270027 Notice of deviation from insp on 791205.19 & 20 * Region 4, Dallas, Office of the Director 80/02/07 2pp
- --8004270031 GA Program Insp Rept 79900025/79-03 on 791205,19 & 20 Noncompliance noted failure to perform certain math nondestructive exams, inadequate insp of piping assemblies & failure to perform radiographic sxam of weld repairs BARNES, I., RUBERDS, H. HUNNICUTT, D. M. Region 4, Dallas, Vendor Inspection Branch 80/02/07 ilpp
- 800427016B Ack receipt of 800111 & 0317 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990033B/79-01
 SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/03 in
- --8004290176 Responds to NRC 800222 ltr re violation & deviation noted in GA Program Insp Rept 99900389/79-01 Corrective actions signing off of mfg order being monitored on daily basis Inspectors & GA manager cautioned on use of insp stamps FRIEDMAN, J Marvin Engineering Co , Inc 80/03/17. 10pp.

- --8004290179 Ack receipt of BOD111 itr informing NRC of steps taken to correct violations & deviations noted in QA Insp Rept 99900338/79-01 Addl info required re notice of deviation Items 3,6.7,7,16.18,23 & 24
 BEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/22
- --8004290186 Responds to NRC 791025 ltr re deviations & violations noted in QA Program Insp Rept 9990038/79-01 No proprietary info Corrective action QA manual revised to reflect organizational changes FRIEDMAN.O M Marvin Engineering Co , Inc. 80/01/11 34pp
- ~-B004290191 Forwards GA Program Insp Rept 99900338/79-01 on 790918-21 & notices of violation & deviation BEYFRIT.X. V Region 4. Dallas, Office of the Director 79/10/25
- ---8004290201 Notice of violation from insp on 790918-21 * Region 4, Dallas, Office of the Director 79/10/25 ip
- ~-8004290203 Notice of deviation from insp on 790918-21 * Region 4, Dallas, Office of the Director 79/10/25 13pp
- ~-8004290212 0A Program Insp Rept 99900339/79-01 on 790918-21
 Nomcompliance noted failure to comply w/10CFR21 re adoption
 of procedures for evaluation of deviations
 BARNESS I. ELLENSHAW, E. HUNNICUTT, D. M. Region 4, Dallas, Vendor
 Inspection Branch 79/10/25 Ropp
- B004300084 Act receipt of 800128 & 0317 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900403/77-03
 P0TAPOVE, U Region 4, Dallas, Vendor Inspection Branch 80/04/03
- --8004300072 Responds to NRC 800222 ltr re deviation noted in QA Program Insp Rept 99900403/79-03 Corrective actions will revise Quality Procedure 30 120 to strengthen welding quality requirements & checklist will be developed BARNARD.J General Electric Co 80/03/17 2pp
- ---8004300098 Ack receipt of 800128 ltr requesting add1 info re Item B Commits to review of supplier fabrication process sheets to assure proper sequencing PATAPOVS,U. Region 4: Dellas, Vendor Inspection Branch 60/02/22
- ---B004300107 Responds to NRC 791214 ltr re deviations noted in QA Insp Rept 99700403/79-03 No proprietary info Delinates GA mgt level personnel responsibilities & commits to review of work orders BARNARD, J. General Electric Co. B0/01/28 10pp
- B004300217 Forwards GA Program Insp Rept 99900705/80-01 on B00213-15 No noncompliance noted POTAPDVS, U. Region 4, Daklas, Vendor Inspection Branch 80/03/05
- --8004300222 0A Program INsp Rept 97900705/80-01 on 800213-15 No noncompliance noted Major areas inspected followup on repts re incorrect mati used for fabrication of springs for electro-hydraulic valve actuators ELLERSHAW.L E., HUNNICUTT.D M Region 4. Dallas, Vendor Inspection Branch. 80/02/29, 5pp

RECOR RECULATORY CUIDES

8004020389 Proposes changes to Reg Quide 1.133, Draft 4, re calibr method for loose part monitors which will significantly reduce radiation exposure of operators during V&LPM channel calibr. Draft of revised Paragraph 3.a (3) ancl. PEXRUL.P.J Rockwell International Corp. 80ES0-2661, 80/03/24 30e.

- --8004080628 Comments on proposed Reg Quide 1 97 guide does not have proper approach to accident info Requirements are too pervasive Quide should differentiate between info need in accident situation & normal operation BENDER.M ACRS ~ Advisory Committee on Reactor Bafeguards 79/11/03 3pp
- --8004080631 Questions Reg Guide 1 97.Revision 2 re timely heat balance feedwater sys temps & reactor coolant inventory requirement CATTON: I ACRS - Advisory Committee on Reactor Safeguards 79/11/02 1p
- --8004080439 Comments on proposed Reg Guide 1 97, Revision 2 guide is weak in defining what should be done w/measured info LIPINSKI, W.C. Argonne National Laboratory 79/10/29 2pp
- --B0040B0646 Comments on proposed Reg Guide 1 97. Revision 2 design should consider effects of nonseismic Category 1 bldg on instrumentation components
 ZUDANS. Z Franklin Institute/Franklin Research Center 79/10/30
- --B0040B0655 Comments on proposed Reg Guide 1 97,Revision 2 requirements are unjustified More graded set of requirements should be specified so quality of instruments is commensurate w/safety importance
 BUCHHOLZ,R H General Electric Co MEN-270-79 79/11/05 App
- --B0040B0&6i Forwards comments on proposed Reg Guide 1 97.Revision 2 format of Table 2 & 3 should be reversed so that purpose appears first Variable types D & E should be deleted from scope
 TAYLOR, J H. Babcock & Wilcox Co. 79/11/06 App
- BO04090254 Comments on proposed Revision 2 to Reg Quide 1 97 ref to ANS 4 5 is inappropriate until ANS 4 5.Draft 4, has been approved ANS 4 5 committee post-accident qualification period of 100 days should be endorsed BTAMPLEY.N L Mississippi Power & Light Co AECM-80/53 80/03/10 600
- 8004100071 Comments on proposed Reg Quide i 97.Revision 2 permanently installed remote monitors should have upper range of 10 R/hr Points immediately adjacent to release point should be kept at 100 R/hr KROON.J C Affiliation Unknown 80/03/07 3pp
- B004100536 Comments on draft reg guide, "Measurement of Radiation Levels on Burfaces of Packages of Radioactive Matis " Values in Table : should be changed to assure surface radiation level never exceeds 200 mrems-h MUNRO, J J Tech/Ops (Technical Operations, Inc.) 80/03/10 3pp
- BOO4100341 Comments on proposed Reg Guide 1 97.Revision 2 GA program should be invoked re instrumentation, application & design, but not imposed on manufacturer of instrumentation components for Type O or E sys
 STAMPLEY.N L. Mississippi Power & Light Co 80/03/10 App
- 8004100543 Comments on proposed Reg Guids I 97. Revision 2 environ radioactivity exposure rate in upper range of 10 rems per h should be adequate. KROOM.J C Reuter-Stokes, Inc 80/03/07 ip
- 8004100546 Forwards addl comments on proposed Reg Ouide 1 97, Revision 2 clarification is needed to use of instrumentation for routine environ mentoring purposes & type of monitors required for sample analysis LOOMIS, J S Bargent & Lundy, Inc 80/03/11, 3pp
- BO04100361 Comments on draft reg guide, "Measurement of Radiation Levels on Surfaces of Packages of Radioactive Matls " Questions if Paragraph 1, Section C means that special form matural & depleted U can be shipped in exposed state LEVIN.S Army, Dept of, Matls & Mechanics Research Center BO/03/06 ip
- 8004110127 Comments on proposed draft reg guide, "Measurement of Radiation Levels on Burfaces of Packages of Radioactive Mati "Energy response should be addressed using relative intercomparison w/energy independent instru
- 8004110359 Forwards comments on proposed Reg Guide i 97,Revision 2 variables can be grouped in generic categories & guidance should be provided for proper selection DOPCHIE.H Belgium 80/03/13 App
- B004140179 Comments on proposed Reg Quide 1 97, Revision 2 pressurizer temp & pressurizer spray flow or spray valve position should be added to Table 2, Page 11 CDX.E.L. Black & Veatch, B0/03/07 1p

- 8004180420 Notification of 800408 meeting w/C-E in Bethesda,MD to discuss high range effluent monitors for Lessons Learned requirements & Reg Guide 1 97 BARRETT,L Environmental Evaluation Branch B0/04/02 1p
- 8004180532 Comments on proposed Revision 2 to Reg Guide 1 97 instrument Types D & E could jeopardize operation of seismic qualified instrumentation if on same power source Pressurizer temp & spray flow should be added as maeasured variables COX.E L Black & Veatch, Southern Science Applications, Inc , Div 80/03/07 ip
- 8004210172 Forwards revised PWR near-term OL group generic comments for Reg Guide 1 97, proposed Revision 2 PARKER, W O Duko Power Co 80/04/01 14pp
- 8004220147 Comments on proposed Revision 2 to Reg Guide 1 97 Type A variables omitted due to plant-specific nature should be grouped in generic categories w/quidance for proper selection
 DQPCHIE.H Affiliation Unknown 2/500/D B /C D 80/03/13 App
- 8004220210 Comments on proposed Revision 2 to Reg Ouide 1 97 upper limit of environ radioactivity exposure rate measurement range should be reduced to allow for atmospheric dispersion Forwards Presidential public statement on Kemeny rept KROON, J C Reuter-Stakes, Inc 80/03/07 1p
- 8004290240 Comments on proposed Revision 2 to Reg Quide 1 97 does not state where permanently installed monitors for assessment of plant & environ conditions following accident should be placed Telemotry wiil pose maint problem PILANT, J M Nebraska Public Power District LOAG000088 80/03/03

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- BO04150152 "WRRD Monthly Rept for Jan 1980"

 YBARRONDO, L J Energy Engineering Group YBR-34-80 B0/02/29
- 8004010415 Forwards final rept, "Policy Recommendations for Treatments of ATMB Events for Standardized Nuclear Power Plants"
 OBLAY, M W Massachusetts Institute of Technology NRC-03-79-144
 B0/02/21 in
- --E004010422 8004010415

 "Policy Recommondations for Treatments of ATHS Events for Standardised Nuclear Power Plants," final rept OOLAY.M N Massachusetts Institute of Technology NRC-03-79-144 80/01/09 37pp
- 8004020142 "Data Summaries of LERs of Diesel Generators at US Commercial Nuclear Power Plants from Jan 1976-Dec 1978," data summary rept POLOSKI,J P., SULLIVAN,W H. EO & G., Inc. [IN A-6276] EEG-EA-5072 80/02/29 398pp
- 8004020158 RIL-057
 Research Info Ltr 57 submits results of emergency core coolant bypass research performed at Battelle Columbus Labs & Dartmouth College
 LEVINE, B Office of Nuclear Regulatory Research 79/08/10 App
- 8004040027 "Investigation of Post-Critical Heat Flux Heat Transfer for Mater-Cooled Reactor Application & Development of Two-Phase Flow Instrumentation," monthly progress rept for Feb 1980 CHEN.J C., GUNDARM,R K., NIJ-HAWAN,B. Lehigh Univ. FIN A-4055 NRC-04-74-180 80/03/17 App.
- 800404002B "Experimental Criticality Data for Code Validation." Informal monthly progress rept for Feb 1980 BIERRAN.S R Battella Memorial Institute, Pacific Northwest Laboratory FIN 8-2094 80/03/04 3pp
- 8004040204 "Bhipping Cask Sabotage Source Term Investigation," monthly progress rept for Feb 1980 BCHMIDT.E W Battelle Memorial Institute, Columbus Laboratories FIN 8-6012 NRC-04-76-293 80/03/05 App
- 8004040210 "Impact of Decontamination on LWR Radwaste Treatment Sys." monthly progress rept for Feb 1980 DIVINE.JR Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2303 80/03/12 19pp.
- 8004040270 "Accident Aerosol Characterization," monthly progress rept for Feb 1980 MISHIMA.J., UMZARSKI.P Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 80/03/07 3pp

- 8004040342 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels," monthly progress rept for Jan 1980 HUTTON,P H , KURTZ,R J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2088 80/02/19 16pp
- BOO4040369 "Safeguards Amalysis for Byproduct Matls & Emall Quantities of SNM," monthly progress rept for Jan 1980 CHESTER,R Q , KONAK,K K , RANDOLPH,M L Qak Ridge National Laboratory FIN B-6108 DRNL/HABRD-68 BO/02/13 Opp
- 8004070145 "Forecasting Electricity Demand by State & by Util Svc Area." progress rept for Feb 1780 CHERN.W S Oak Ridge National Laboratory FIN D-0170-8 80/03/07 5pp
- 8004070413 "Core Melt & Separate Effects Program," monthly ltr for Feb 1980 BERMAN,M Sandia Laboratories 80/09/04 4pp
- 8004080075 "Loft Monthly Progress Rept for Jan 1980 " KAUFMAN,N C EQ & G. Inc fin A-6048 LG-MR-003 80/02/29 94pp
- GOO4080082 "Calibr of Loft Modular DTT & Loft Production DTT W/Small Drag Disc:" Vol 2 SOLBRIG,C W, SHULL,0 B, ODDD,R R EQ & G, Inc FIN A-604B LO-00-80-113 80/02/29 233pp
- 8004080094 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlight ltr fre Jan 1980 BULISCHECK.T, VAN RODYEN.D Brookhaven National Laboratory FIN A-3208 80/02/15 5pp
- 8004080215 RIL-084
 Research Info Ltr 84 submits results of study of liquefaction resulting from 760204 earthquake near Lake Amatitlan Guatemala
 BUDNITZ, R J Office of Nuclear Regulatory Research 80/03/24
- 8004080242 "LUR in-Plant Measurement Program," monthly programs rept for Feb 1980 MANDLER,J.W. EO & G. Inc. FIN A-6075 80/03/18 4ep
- 8004080283 "Biocide Byproducts in Aquatic Environs," quarterly programs rept for Det-Dec 1979
 BEAN,R M Battelle Memorial Institute, Pacific Northwest Laboratory
 FIN 8-2098 79712/31 39pp
- 8004080270 "88C Code Development & Validation." monthly highlight ltr for Dec 1979 AGRAMALA,K., GUPPY.J & Drockhaven National Laboratory FIN A-3015-8 79/12/31 App
- 8004080294 "TRAC Assessment & Model Development," monthly highlight ltr for Jan 1980 JONES.O C Brookhaven National Laboratory FIN A-3215 80/01/31
- BO04080302 "LWR Thermal Hydraulic Development Program," monthly highlight ltr for Dec 1979
 JONES, O. C. Brookhaven National Laboratory FIN A-3045 79/12/31
- 8004080585 "Ramona Code Mod & Evaluation," monthly highlight 1tm for Dec 1979 LEVING.M M Brookhaven National Laboratory, FIN A-3014 79/12/31 6pp
- 8004080675 "Evaluation of LWR Residual Heat Removal Under Accident Conditions," monthly highlight ltm for Jan 1780 BURI,R A Brookhaven National Laboratory F1R A-3315, BG/O1/31, Spp
- 8004080684 "Best Estimate Prediction for LOFT Nuclear Experiment L-3-2," pretest prediction rept KEE.E J. SHINKO,M S. ORUSH,W H EO & O. Inc FIN A-6048, EOG-LOFT-8087 80/02/27 80pp
- B004090068 "Electrical, Instrumentation & Control Aspects of Proposed Tech Specs Change Re Biocking of Bafety Injection Bignals When Pressure is Balow 2000 psig," technical evaluation rept MAYB, S E EO & Q. Inc FIN A-6256 EQQ-CA-8106 B0/02/29 Bpp
- B004090158 "NTGR Bafaty Program," monthly highlights ltr for Jan 1980 BASTRE,C Brookhaven National Laboratory FIN A-3014 B0/02/04

- 8004090312 "Thermal Hydraulic LMFBR Safety Experiments," monthly highlight ltr for Dec 1979
 JONES.O C Brookhaven National Laboratory FIN A-3024 79/12/31
- 8004090324 "Thermal Hydraulic LMFBR Bafety Experiments," monthly highlight ltr for Jan 1980 JONES, C C Broothaven National Laboratory FIN A-3024 80/01/31
- 8004100258 "Advanced Reactor Safety Analysis," monthly highlight ltr for Dec 1979 BARI.R A Brookhaven National Laboratory FIN A-3000 80/01/07
- 800410032B "Estimators for Binomial Failure Rate Common Cause Model " ATHOOD.C L E0 & G. Inc FIN A-6272 EGG-EA-5112 80/03/31 B3pp
- 8004100378 "LOFT Test Support Branch Data Abstract Rept LOFT Fuel Rod Thermocouple Calibr Test-Rod RRF A-88102 " SOLBRIQ,C W , TOLMAN,E L , SELCHO,H 8 EG & 0, Inc FIN A-6048 LTR 141-100 79/04/30 53pp
- 8004100398 "Definition of Parameters for Major Accidents at Waste Solidification & Spent Fuel Storage Facilities," informal monthly progress rept for Feb 1980 FEDERICK, E. J. Oak Ridge National Laboratory FIN 8-0425 80/03/26
- 8004100411 "Div of Reactor Safety Research-DRNL Programs," Feb 1980 monthly bighlights
 MUYATT Dak Ridge National Leboratory FIN B-0413 NRC-60-19-11-01
 B0/03/10 30pp
- 8004100587 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects," monthly highlights for Jan 1980 BARIJR A Brookhaven National Laboratory FIN A-3000 80/02/01 40s.
- 8004100590 "SSC Code Development & Validation," monthly highlight ltr for Jan 1980 AGRAMELA K , GUPPY, J & Brookhaven National Laboratory FIN A-3015-8 80/01/31 4pp
- BOC4100574 "Bubtask A:RAMDNA Code Mod & Evaluation" & "Subtask B IRT & RETRAN Code Mod & Evalution." monthly highlight ltr for Jan 1980
 LEVINE, M M Brockhaven National Laboratory FIN A-3014 BO/01/31
- BOO4100599 "LWR Therms! Hydrautic Development Program," monthly highlight ltr for Jan 1980 JONES OL Brookhaven National Laboratory FIN A-3045 80/01/31 4pp
- 8004110521 Evaluation of LWR Residual Heat Removal Under Accident Conditions, "monthly highlight ltr for Dec 1979 BARIJR A Brookhaven National Laboratory FIN A-3315 80/01/07 5pp

lactrical.Instrumentation & Control Aspects of Override of Purge Valve Isolation & Other Safety Feature informal rept 0 & 0. Inc EGG-EA-5078 80/02/29 13pp

- lacht-Seaset Program." monthly prograss rept for Jan 1980 Westinghouse Electric Corp NRC-04-77-127 80/02/22
 - tle Facility Nonsecurity Personnel Response to khaven National Laboratory FIN A-3000 78/12/15 33pp
 - Facility Employees Response to Intrusion Alarm."
 otheren National Laboratory FIN A-3000,
 78/11/15 3808.
 - Facility Threat Analysis & Tactical Response mal rept khaven National Laboratory FIN A-3000 79/10/19 103pp
 - Assessments of Fuel Cycle Facilities," monthly Feb 1980 idge National Laboratory, FIN B-0279, 80/02/29 dpp

- 8004150036 "Evaluation of Dockot Files of Terminated Licenses," monthly progress rept for Feb 1980 LANTZ.P M . DICKSON.H W Oak Ridge National Laboratory FIN A-9085-7 ORNL/MARD-70 80/02/29 20pp
- BOO4150056 "Reactivity Initiated Accident Test Beries Test RIA 1-4 Experiment Predictions" FUKUDA.9 K. MARTINSON.Z R EQ & G. Inc FIN A-6041 EGG-TFBP-5023 80/02/29 74pp
- 8004150063 "BWR Blowdown/Emergency Control Ctr Program." monthly progress rept for Feb 1980 BURNETTE.O W Oeneral Electric Co FIN B-3014 NRC~94-76-215 80/02/27 5pp
- B004150066 "Physical Protection of Nuclear Matl In Transit" quarterly progress report Jan-Mar 1980 CHAPMAN.L D Sandia Laboratories FIN A-1173 B0/03/20 App
- 8004150475 "Once-Through Steam Generator Modeling for Analysis of TMT Incident," conference paper HSU.C J. BHIER.W O. LEVINE.M M Brookhaven National Laboratory BNL-MURED-27185 80/04/10 6pp
- B004160088 "Assessment of Radiation Doses Resulting From Releases of Rn-222 & Ra-226 From V Mining & Milling Activities," monthly progress rept for Feb 1980
 TRAVIS, C C , MCDDWELL-BOYER, WATGON, A P Gak Ridge National Laboratory FIN B-0281 ORNL/HASRD-72 80/03/14 3pp
- 8004160075 "Safeguards Analysis for Byproducts Matls & Small Guantities of SNM," monthly progress rept for Feb 1780 CHESTER C . KANAK.K K . RANDOLPH.M L Oak Ridge National Laboratory FIN B-6108 ORNL/HABRD-71 80/03/15 6pp
- 8004170120 "Guick Look Rept on LUFT Nuclear Experiment L3-2," experiment data presentation rept LINEBARGER, J H EG & G, Inc FIN A-6048 EGG-LOFT-5104 80/02/29 30an
- 8004170274 "Technical Evaluation Rept of Degraded Grid Protection for Class IE Power Sys at Brunswick Steam Electric Plant," technical evaluation rept CLEVELAND, J C EQ & G, Inc FIN A-6256 EGG-EA-5109 B0/02/29
- 8004170276 "Inservice Testing Evaluation of Check Valves at St Lucie Unit 1 Nuclear Station," technical evaluation rept FEHRINGER.J M EG & O. Inc FIN A-6258 EGG-EA-5097 80/02/29 1300
- 8004170287 "BWR Refill-Reflood Program." monthly ltr for Feb 1980 BURNETTE, O W General Electric Co NRC-04-79-184 80/03/13 5pp
- 8004170289 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Bafety Feature Bignals.EI Hatch Nuclear Plant," informal rept UDY.A.C. E0 & O. Inc FIN A-6255 EGO-EA-5110 80/02/27 9pp
- 8004170334 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Bafety Feature Signals.Millstone Nuclear Power Station." informal rapt UDY, A C EQ & G. Inc FIN-A-6256 EGG-EA-5111 B0/02/29 9pp
- 8004230300 RIL-62
 Forwards NUREO/CR-0379, Vol 5, "Repts Distributed Under NRC
 Reactor Safety Research Foreign Technical Exchange Program,"
 & NUREO/CR-0450, "New Madrid Seismotectonic Bludy —
 Activities During Fy78"
 LEVINE:8 Office of Nuclear Regulatory Research 79/10/18 App
- 8004240152 Forwards informal progress rept for Dec 1979 for FLECHT-SEASEY MASSIE, H W Westinghouse Electric Corp NRC-04-77-127 80/02/11
- B004240460 "Fuel Cycle Facility Threat Assessment & Response Procedures," informal rept D'BRIAN.J N. CADME(L.) J. Brookhaven National Laboratory FIN A-3000 BNL-NURE0-2487; 78/12/15, 74pp
- 8004240445 "Matl Control & Accounting Effectiveness Evaluation Development," informal monthly progress rept for Jan 1980 POGOID A Lawrence Livermore Laboratory FIN A-0115 80/04/04 7pp
- 800424046B "Semiscale Mod-3 Small Break Test S-SB-ZA " FAUBLE, T J EO & 0, Inc FIN A-603B E00-SEMI-5113 80/03/04 61pp

- 8004240475 "Experimental Evaluation of Ventilation Sys Components During Large Pressure Pulses," informal monthly progress rept for Feb 1980 OREGORY, H S Los Alamos Scientific Laboratory FIN A-7028 80/03/20 3pp
- 8004240487 "Unified Transport for Power Plant Assessment," monthly progress rept for Jan 1980

 * Oak Ridge National Laboratory FIN B-0168-9 ORNL/ED/EIS-119 80/01/31 4pp
- BOO4280032 "Analysis of Oas Circulation in Containment of High Temp Oas Cooled Reactor," informal rept OMATA: I, TAKAHABHIH Brookhaven National Laboratory FIN A-3016 BNL-NMREO-27369 BO/03/31 170pp
- BOO428003B "Critical Flashing Flows in Notzles W/Bubcooled Inlet Conditions " ABUAF,N, JONES,D C , MU,B J C Brookhaven National Laboratory FIN A-3045 BNLONURE0-27512 80/03/31 36pp
- B004280041 "High Temp Mass Transport Experimental Program," informal rept GROMCOCK, F.B., HEISER, J.H. Brookhaven National Laboratory FIN A-3016 BNL-NUREO-27502 B0/03/31 34pp
- 8004280059 "NRC Safeguards Matl Control Project," monthly progress rept for Feb 1980 POGGID.A Lawrence Livermore Laboratory FIN A-0115 MC 80-04-02-LR 80/03/07 7pp
- 8004280063 "Task 5-Natl Waste Package Program" 8CHWEITZER.D 9 Brookhaven National Laboratory FIN A-3158 8NL-NUREG-27545 80/03/31 10pp
- 8004280071 "Preliminary Pretest Analysis of FFTF Loss of Power Acceptance Tests," informal rept EPEL, L Q , GUPPY, J Q , KENNETT, R J Brookhaven National Laboratory FIN A-3041 BNL-NUREO-27116 80/04/30 63pp
- 8004300032 "General Legal Problems Affecting Nuclear Guard Tactical Responsos," informal rept CADMELLJ J Brookhaven National Laboratory FIN A-3067 BNL-NUREO-24872 78/11/19 20pp
- 8004300574 "Physical Protection of Nuclear Facilities, "progress rept for Feb 1980 CHAPMAN, D Bandia Laboratories FIN A-1060 80/03/20 7pp

REVIEW ORP NRC RESEARCH REVIEW GROUPS

- 8004100485 Forwards summary of Advanced Code Review Group 800124-25 meeting in Silver Spring.MD ZUBER.N RROW 1-14, Advanced System Code 80/03/28 ip
- --8004100490 Bummary of Advanced Code Review Group B00124-25 meeting in Bilver Bpring.MD re review of COBRA-TF & COBRA/TRAC code development program at PNL * RROW L-14. Advanced Bystem Code B0/03/28 32pp
- --8004100497 "COBRA-TF Model Description"
 * Battelle Mamorial Institute 79/12/31 100pp
- 8004220874 Forwards initial outline of acceptance & verification criteria for early warning fire detection sys BOCCIO, J Brookhaven National Laboratory BO/04/15 6pp
- 8004240141 Forwards summary of 800214 meeting w/Qualification Testing Evaluation review group re Commission-directed electrical connector tests McQuire penetration assemblies can be used for next series of tests MCRLEY.T E Division of Reactor Safety Research EIBENHUT.D Q Office of Nuclear Reactor Regulation, MATTSON.R.J Division of Systems Safety 80/04/02 4pp
- 8004280187 Forwards Sandia Labs & UL viewgraphs entitled "Fire Protection Research Program," presented to NRC on 800328 UL is planning to complete program on evaluation of IEEE-383 flame test FEIT,R Research Support Branch 80/04/04 2pp
- 8004280200 Forwards Sandia Labs 800321 ltr documenting tests to determine degree of fire retardency of Raychem splices Splices could be included in planned fire tests on electrical equipment cables in fire protection research FEIT.R Research Bupport Branch 80/04/09 2pp

- --8004280206 Forwards results of evaluation of fire resistance of Raychem heat shrinkable splice matl for comparison w/resistance of cable FR-1 test showed that splices looked as good as average cable matl
 KLAMERUS:L J Sandia Laboratories 80/03/21 Bpp
- 8004280285 Forwards NRC div directors' 800402 ltr re agreement to proceed w/next series of tosts using connectors from McQuire penetration connectors MRCLEY, T E Division of Reactor Safety Research 80/04/10 lp

SECY POSITION PAPERS DEFORE THE COMMISSION

- 7812120219 Responds to 780316 FOIA request for SECY77-268, SECY77-268A. SECY77-268C & OPE memo Portions of documents withheld (ref 10CFR9 15 & 2 790) FELTON, J M Division of Rules and Records 78/12/05 3pp
- 8004010014 Transcript of 800319 meeting in Washington.DC re NRC enforcement program Pp 1-99
 * Commission 80/03/19 59pp
- --8004010017 SECY-80-139

 Describes various types of enforcement actions re request for Commission approval of general statement of enforcement policy

 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/03/13 30pp
- --8004010021 Endorses objective re development of strong explicit enforcement program Requests mod of coordination statement to include benefits, costs & Commission guidance requirements

 HALLER N M Office of Management and Program Analysis 80/03/10
- 8004010051 SECY-80-045
 Forwards Executive Branch position on 800121 applications for licenses to export highly enriched U to Belgium. Hest Germany, France & the Natherlands Requests comments SHEA, J R Office of International Programs 80/01/24 ip
- --8004010478 Executive Brench position re five Transnuclear, Inc applications for licenses to export highly enriched U to Belgium, West Germany, France & the Netherlands Recommends issuance of licenses Ltrs of assurance encl NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/01/21 15pp
- --8004010075 Forwards two applications for licenses to export 22 050 kg U enriched to max 93 5% U-235 & 777 kg U.enriched to max 4 05% U-235 W/o latter application MATBON, V Transnuclear, Inc 78/06/22 2pp
- --8004010097 Application by Transnuclear, Inc for license to export 20 090 kg U.in form of U hexafluoride enriched to max 93 3% U-235, to the Netherlands End use statement encl MATBUN, V Transnuclear, Inc 78/06/22 2pp

--a

--8004100431 SECY-80-166

--800402002B SECY-BO-107 (FRN) Establishes technical bases re interim hydrogen control requirements for small containments Technical discussions DENTON, H R Office of Nuclear Reactor Regulation 80/02/22 8004030166 SECY-77-064 004030166 SECY-77-064
Recommends approval of encl licensee contractor & vendor insp program (as continuing part of NRC insp program) & approval of conducting 2-yr trial program to test use of third party insp sys to supplement program VQLOENAU, E Office of Inspection & Enforcement, Office of the Diractor 77/02/02 Siep 86pp --800403016B Comments on vendor 3 third party insp program Use of third party ABME inspectors should be included in Commission paper re licensee contractor & vendor insp program HUBERMAN.B Commission 76/12/23 2pp 8004040200 SECY-80-131 New York to Be 17-a-13: Recommends discontinuance of accident classification groupings & interim policy re use of probablistic risk assessment methods in NEPA reviews Proposed FR notice & related mat) snc1
DENTON, H R Office of Nuclear Reactor Regulation 80/03/11 3ipp 8004070148 SECY-B0-142
Recommends issuance of license to export reactor & associated components to Philippines Proposed export would not be inimical to US common defense & security No further action required on SECY-79-100
SHEA, J.R. Office of International Programs 80/03/14 6pp 8004090162 BECY-B0-001 004090162 BECY-BO-001
Recommends approval of JP Oleason as part-time member of ASLB Commission comment or consent should be provided to Ofc of Secretary by 800116 Resume encl W/o encl
LAZA,R M Atomic Safety and Licensing Board Panel 80/01/02 2pp 8004090297 SECY-80-054 004090297 BECY-80-054
Recommends Commission approve publication for comment of proposed amend codifying licensee compliance w/EPA "Environ Radiation Protection Stds for Nuclear Power Operations "
Proposed FR notice & proposed amend encl
MINOQUE, R B Office of Standards Development 80/01/28 22pp --B004090301 Draft value/impact assessment re proposed amend to 10CFR20 405 to codify licensee compliance w/EPA regulation 40CFR190 Requirement is necessary part of NRC enforcement responsibilities Office of Standards Development 79/11/30 5pp --8004090306 BECY-79-646 004000306 BECY-79-646
Informs Commission of plans & practices for implementation of EPA environ radiation protection stds for nuclear power operations. Primary thrust has been to make in-place NRC license mechanisms work for EPA stds implementation DENTON, H R. Office of Nuclear Reactor Regulation 79/12/07 Gpp

0040Y01221 SECY-BO-OUZ Recommends approval of LJ Carter as part-time member of ABLB Commission comment or consent should be provided to Ofc of Becretary by 800116 Resume encl H/o encl LAZA,R M Atomic Safety and Licensing Board Panel 80/01/02 2pp

004100039 SECY-80-095
Recommends NRC approval of FR publication of ancl notice of denial of patition for rulemaking 2-5
BHAPAR, H K Office of the Exacutive Legal Director 80/02/14

B004100429 Transcript of B00331 meeting in Bethesda, MD re physical protection of irradiated reactor fuel in transit Pp i-33 * Commission. B0/03/31 33pp

8004100033 Transcript of 800313 Affirmation Session 80-10 in Washington, DC Pp 1-5 * Commission 80/03/13 5pp.

8004090321 BECY-80-002

--8004100039 SECY-80-095

Recommends NRC approval of amends to 10CFR73 for immediately effective requirements re physical protection of irradiated fuel in transit for publication in final form Draft FR notice encl
DIRCKS.W J Office of Nuclear Material Safety & Safeguards
80/03/28 52pp 8004230123 Forwards corrected Page 10 to 800404 advance notice of rulemaking on technical criteria for regulating geologic disposal of high level radwastes * Office of Standards Development 80/04/08 1 --8004230126 Corrected Page 10 to 800404 advance notice of rulemaking on technical criteria for regulating geologic disposal of high vel raduastes
Orfice of Standards Development 80/04/04 1p --8004230130 SECY-80-177
Seeks NRC approval to publish in FR encl advance notice of rulemaking on technical criteria for regulating geologic disposal of high level raduastes
MINOQUE.R B Office of Standards Development 80/04/04 3pp ~-8004230136 Advance notice of rulemaking re technical criteria for regulating geologic disposal of high level radwaste # Office of Standards Development 80/04/04 80pp --8004230141 Value/impact assessment supporting solicitation of public cumment on issues & questions important to development of technical criteria for regulation of disposal of high level * Office of Standards Development 80/04/04 6pp B004240130 Notifies of Commission approval of Nissho-Iwai American Corp application for license to export 42 kg U.enriched to 93 3%, to Japan Requests detailed description of transportation method & physical security for transit CHILK.S J. Office of the Secretary of the Commission 80/04/02 8004240471 Transcript of B00414 meeting in Washington.DC to discuss SECY-80-139 & BECY-80-130A Pp 1-59 * Cammission 80/04/14 60pp 8004270072 BECY-80-026A JU42Y0U/2 BECY-BO-UZGA Updates BECY-BO-26 re amend to code requirements for reporting therapy misadministrations Licensee is not required to notify patient before consultation w/physician MINOGUE,R B Office of Standards Development B0/02/26 8004300002 SECY-80-13A Recommends approval of delegation of authority to director.
Ofc of Administration, permitting director to approve
termination of contracts & agreements Draft delegation of authority encl DONOGHUE,D J Office of Administration 80/03/11 --8004300007 Delegates authority to administer contracting activities of Commission including contracts & interagency agreements for conduct of nuclear regulatory research Draft delegation of authority and DONDGHUE, D. J. Office of Administration 75/01/20 2pp STATE PROG STATE PROGRAMS 80040200BO Responds to 800118 ltr re Subcommittee on Nuclear Energy recommendations four, five & six concerning state emergency response plan & raduaste mgt FEMA responsible for assisting state w/emergency response plans DDE should be contacted VOUNO,F W Assistant Director for Program Development 80/03/20 80040200B9 Provides Special Joint Committee on Nuclear Energy w/info on document distribution.per 800204 request Forwards list of firms authorized to receive packaged radwaste in states over which NRC has regulatory authority MCGARTHY.E Defice of State Programs 80/03/17 5pp

--B004020237 Requests placement on distribution lists to receive documents re MI nuclear facilities Also requests info re NRC licensees BCANLON.W J. CLODFELTER.M., ROSS.D. Michigan, State of B0/02/04 3pp

- --8004020102 Discusses W Scanton info request Adding W Scanton to distribution list for all documents relicensing not feasible due to vol of licensing actions & related correspondence Dept of Public Health should be contacted NUSBSAUMER, D A Assistant Director for Material Safety & Licensing 80/02/03 ip
- ---BO04020106 Forwards documents requested by W Scanlon W/o encl PAULUS,R C Office of Inspection & Enforcement. Office of the Director B0/03/06 ip
- 8004020170 Responds to 800226 ltr to 8 Schwart: Requested info re waste disposal issues encl NRC hopes to avoid schedule conflict during regional meetings w/states; on low level waste site licensing in spring W/o encls
 YUUNG.F W Office of State Programs 80/03/19 2pp
- ---8004020176 Requests info concerning state strategy underway to resolve problem of nuclear waste disposal Welcomes suggestions re course of action State of MD might pursue EASTER. J H Maryland, Stato of 80/02/26 1p
- 8004020209 Forwards documents requested re J Hendrie 791107 testimony on low level radwaste disposal W/o encl WEISSBERG.S (Office of State Programs 80/03/20 ip
- 8004040193 Expresses pleasure that Hazle has been appointed liaison officer to NRC Forwards list of key NRC personnel responsible for nuclear power plant project within US W/o encl
 RYAN, R O Office of State Programs 80/01/16 1p
- 8004040470 Confirms discussion re evaluation of SC radiation control program Program deemed adequate to protect public health & safety KERR, O W Office of State Programs 80/03/17 2pp
- 8004070069 Provides info on state transportation data base currently being developed at DRNL Contains pending legislation, state & federal laws & local ordinances re radioactive matl transport MCCARTHY, E A Office of State Programs 80/03/14 lp
- 8004070368 Confirms acceptance of control of agreement matl program & recommends independent measurements of teletherapy units radiation output be taken KERR,0 W Office of State Programs 80/03/17 ip
- 8004070417 Discusses possibility of detailing NRC radiation specialist to state for two-yrs under Intergovernmental Personnel Acts of 1970 in response to 800206 requests State would have to assume 50% of employee salary DIRCKB, M J Office of the Executive Director for Operations 80/03/11 p
- --80040/0426 Requests NRC radiation specialist be detailed to state for two-urs under Intergovernmental Personnel Acts of 1970 Appointment would provide opportunity for closer working relationship between state & federal govts ORASSO.E Connecticut. State of 80/02/06 ip
- 8004080166 Confirms 800220-21 meeting room reservations MCCARTHY, E Office of State Programs 80/02/01 1p
- 8004090206 Advises that Commission has approved BECY-BO-017 recommendation to issue revised criteria for evaluating agreement state radiation control programs as Commission policy statement Statement should be modified as noted CHILK.S J Office of the Secretary of the Commission BO/03/21 2pp
- 8004i10544 Responds to NRC comments re recent review of state regulatory program State will enforce requirements of 10GFR19 when regulations have been approved by ID Board of Health & Welfare FUNDERRURG, R. D. Idaho, State of 80/03/03 2pp
- 8004110553 Extends invitation to NRC 800115 emergency preparedness workshop in New York: NY to discuss feasibility, impact & procedures for complying w/encl proposed rule 10CFR50 Lists areas that rule would affect Agenda encl SCHMARTZ.8 A Assistant Director for Program Development 80/01/04
- 8004140047 Forwards comments on proposed rule 10CFR50 made at NRC 800117 emergency preparedness workshop in San Francisco, CA GLCOTT, K. Affiliation Unknown 80/01/17 ip

- --8004140052 Comments on 10CFR50 presented at NRC 800117 emergency preparedness workshop in San Francisco.CA Adequate emergency planning should be requirement for nuclear facility CP & GL GLCOTT.K Affiliation Unknown 80/01/17 2pp
- 8004140181 Extends appreciation for participation in regional state liaison afficers meeting in San Francisco.CA Exchange of ideas useful to all responsible for safe use & operation of nuclear matis & Pacilities

 KERR.G W Office of State Programs 80/03/13 1p
- 8004140189 Confirms discussion following evaluation of NV radiation control program Program for regulation of agreement matl is adequate & compatible w/NRC program Recommends improvement re Beatty burial site
 KERR.G W Office of State Programs 80/03/27 2pp
- 8004170341 NUREO/CR-1193 "Transportation of Radioactive Mati in IL." Jun 1978-Jun 1979 * Illinois, State of, Dept of Public Health NRC-06-78-358 80/03/31 53pp Available at NTIS
- 8004180023 Discusses NRC actions taken in response to recommendations in GAO rept. "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AHEARNE. J F Commission 80/03/31 4pp
- --8004180078 Forwards position paper supporting Agreement State program
 Paper includes comments on advantages of Agreement State vs
 NRC administering radiation health & safety program
 TEDFORD, C F Arizona, State of 80/01/23 6pp
- --8004180082 Discusses NRC actions taken in response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AMEARNE, J F Commission 80/03/31 4pp
- --8004180086 Provides Subcommittee on Nuclear Regulation w/NRC response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AHEARNE, J.F. Commission 80/03/31 App
- --8004180095 Provides Subcommittee on Energy & Environ w/NRC response to recommendations in GAO rept. "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AMEARNE, J.F. Commission 80/03/31 4pp
- --8004180097 Provides Bubcommittee on Energy & Pawer w/NRC response to recommendations in OAO rept. "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established AHEARNE, J F Commission 80/03/31 4pp
- ---B004180100 Provides Subcommittee on Environ Energy & Natural Resources w/NRC response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection" Insp followup procedures will be established AHEARNE, J.F. Commission 80/03/31 4pp
- ---B004180101 Discusses NRC actions taken in response to recommendations in GAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious volations are corrected AMEARNE, J. F. Commission 80/03/31 App
- --8004180103 Discusses NRC actions taken in response to recommendations in OAO rept, "Radiation Control Programs Provide Limited Protection " Insp followup procedures will be established to verify that serious violations are corrected AHEARNE, J.F. Commission 80/03/31 4pp
- 8004180279 Forwards response to 791206 inquiry re NRC Agreement States program & Church Rock dam failure RI submittal satisfied Atomic Energy Act. Section 274 requirements for admission as Agreement State AHEARNE, J F Commission 80/03/17 10pp
- --8004180298 Advises that Environ Improvement Board will promulgate implementation of proposed revisions to regulations rehealth & environ aspects of radiation BACA, T E New Mexico. State of 79/10/18 ip

- B004230095 Responds to B0011B ltr re concern & dissatisfaction w/Region I workshop on proposed changes in NRC rules on emergency preparedness Hemo providing summary of results of four workshops encl. Apologics for inconvenience AHEARNE.J F Commission 80/03/21 2pp
- --8004230110 Discusses four workshops to proposed emergency planning rule changes held on B00115.17.22 & 24 Rept will be prepared summartizing lessons learned from series of workshops to conduct of public meetings Agenda encl
 QULLER.K R Division of Siting, Health & Safeguards Standards
 B0/01/28 7ps
- --B004230118 Informs NRC of deep concern & dissatisfaction ω/Region 1 workshop on emergency planning held 800115 Meeting accomplished nect to nothing Suggests NRC undertake extensive measures to recover valuable comments & input VANDENBURGH.D Σ Yankee Atomic Electric Co 80/01/18 2pp
- 8004240077 Discusses 800220-21 meeting to identify problems experienced by nuclear waste generators, transporters, collectors & disposal site operators Summary of meeting will be forwarded KERR, O W Office of State Programs DISIBIO, R Nevada. State of 80/03/27 2pp
- ---8004240081 Discusses 800220-21 meeting to identify problems experienced by nuclear waste generators transporters collectors & disposal site operators Summary of meeting will be forwarded KERR. 0 M Office of State Programs DISIBIO, R Nevada, State of 80/03/27 5pp
- 8004240139 Submits comments in response to 791227 ltr, identifying spmcific new or updated procedures in radiation control program insp guides are currently being copied & will be supplied to each inspector STRONG. T R Hashington, State of 80/03/07 2pp
- 8004240451 Responds to telcon re role of Governor-appointed state limison officers Program initiated in 1977 to improve NRC-state cooperation Regional meetings held to acquaint officers w/operations & to discuss mutual interests HEIBSBERG.8 Office of State Programs 80/03/28 2pp
- 8004230060 Forwards SC first quarterly progress rept re transportation surveillance program under contract w/NRC & DOT for period 790927-1231 W/o encl UANINEK.M. Office of State Programs 80/03/27 ip
- --8004250072 Forwards first quarter progress rept under Contract
 NRC-04-78-357 for 790927-1231.w/tabulation of results
 Obtained W/o progress rept
 WILLIAMS.E F. South Carolina, State of NRC-04-78-357 80/03/10
- 8004280323 Forwards std order for DDE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Plants." issued to INEL KERR.¢ W Office of State Programs FIN 8-1604-0 80-80-008 80/04/17 1p
- --8004280327 8td order for DDE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Plants," issued to INEL KERR.O W Office of State Programs FIN 8-1604-0 80-80-008

*O123 Itr re agreement state program will be helpful in promoting n NRC b states 10/02/08 ip

) reaffirm agreement state program Details 'am improvements are required ite of 80/01/23 App

sting of NRC resource personnel assigned
Programs 80/04/04 3oo

) RELATED CORRESPONDENCE

ineral organization changes to H&R-002A c do not affect program Changes , major revision to topical rept 'p (subs of Halliburton Corp.)

- EOD401049B Forwards Figures 17-1.1/-2,17-2A.17-3 & 17-5, reflecting organizational changes, to be incorporated into CENPD-210-A, Revision 3, "GA Program Manual"

 SCHERER, A E C-E Power Systems LD-80-015 80/03/27 1p
- --8004010501 CENPD-210-A R3
 Figures 17-1:17-2.17-2A.17-3 & 17-5.reflecting organizational changes, to be incorporated into "GA Program Manual"

 * C-E Power Systems 80/03/31 5pp
- BOD4020254 Forwards NEDE-24794-P, "Dynamic Lateral Loads on Mark II Main Vent Downcomer - Correlation of Independent Ref Data " Affidavit for withholding encl Rept withheld (ref 10CFR2 790) BUCHHOLZ,R H General Electric Co MFN 070-80 80/03/31 5pp
- 8004020267 Forwards proprietary & nonproprietary versions of EDR-1-A.
 Revision 2. "Nuclear Safeby-Related Extra-Safety &
 Monitoring (X-SAM) Cranes." incorporating changes identified
 in 791023 itr Proprietary version to Central Files only
 CLARK.C W Ederer. Inc (subs of Formac International. Inc)
 80/03/28 1p
- --8004020271 EDR-1 (NP) R2

 "Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM)
 Cranes." nonproprietary version

 * Ederer, Inc (subs of Formac International, Inc.) *
 Affiliation Unknown 80/02/15 150pp
- 8004020396 Forwards updated Pages 2-2 & 2-3 of WCAP-7800, "Nuclear Fuel Div GA Program Plan" Revision 5A Pages reflect organizational changes at Columbia plant Changes will be incorporated in next rept revision ANDERBON, TM Westinghouse Electric Corp NS-TMA-2222 80/03/26 ip
- ---8004020402 WCAP-7800 R5A
 Updated Pages 2-2 & 2-3 of "Nuclear Fuel Div QA Program
 Plan." Revision 5A reflecting organizational changes at
 Columbia plant
 # Westinghouse Electric Corp 80/03/26 2pp
- B004020404 Forwards responses to NRC 790712 ltr re XN-NF-75-27. Suppl 2. "Neutronic Design Method for PWRs "OHSLEY.0 F Exxon Nuclear Co. Inc (subs of Exxon Corp) GFU 060 B0 B0/03/24 4pp
- 8004020429 Forwards WCAP-969i. "Transient & Accident Analysis." in compliance w/item 2 1 9 c of NUREO-0578 REED,C Westinghouse Operating Plants Cwners Group OG-32 80/03/31 ip
- --8004020432 WCAP-9691
 "Transient & Accident Analysis "
 HITCHLER,M J , SHARP,D R , ANDERSON,T M Westinghouse Electric
 Corp 80/03/31 180pp
- 8004020453 Notification of NRC B00401 meeting w/Westinghouse owners group in Bethesda.MD re encl guidance on analysis of accidents & transients & preparation of emergency procedure guidelines
 ROSS.D F Division of Project Management B0/03/17 7pp
- B004020464 Forwards B&W 800304 ltr & BAW-10144A to inform of availability WILSON, J N Light Water Reactors Branch 4 BAW-10144-A 80/03/18
- --8004020469 Forwards BAH-10144-A, "Evaluation of Atypical Weldment." TAYLOR.J.H Babcock & Wilcox Co 80/03/04 ip
- --8004020475 BAW-10144-A "Evaluation of Atypical Weldmant " MODRE,K E , LOWE,A L , HARRIB,C E Babcock & Wilcox Co 80/02/29
- 8004040326 Confirms 800314 telcon re BWR owners group response to NUREO-057B Requirement 2 1 9 FSAR Chapter 15 event review encl KEENAN, T P General Electric Co MFN-074-80, 80/03/31 75pp
- --8004040333 NEDO-24708 Errata consisting of Section 3 2 1 "Loss of Feedwater" * General Electric Co 80/03/31 200pp
- --8004040337 Draft (Revision 7) of "Emergency Procedure Guidelines BWR 1-5," * General Electric Co 80/03/26 25pp

- 8004070095 Notifies that NRC Ofc of Controller has been asked to bill company for review & approval of GAI-TR-106, "GA Program for Nuclear Power Plants" HILLER. N O License Fee Management Branch 80/03/19 ip
- GOO4070190 Notifies that NRC Ofc of Controller has been asked to bill company for review & approval of Amend 5 to TR-21A, "GA Program"
- Program " MILLER.W O License Fee Management Branch 80/03/19
- 8004070209 Notifies of billing for review & approval of Revision 8 to CPC-1-A, "QA Program Manual" MILLER.W O License Fee Management Branch 80/03/05 1p
- 8004070232 Summarizes 800229 discussions w/NRC re review status of WCAP-8646. "Analysis of Fuel Rod Fretting Wear" Requests MCAP-8646. "Analysis of Fuel Rod Fretting Wear " Ro review of proprietary & nonproprietary versions be discontinued Retain rept for info only Westinghouse Electric Corp NS-TMA-2223 80/03/25
- 8004070360 Forwards proposed Revision 4 to TVA-TR75-1A. "GA Program Description for Design.Const A Operation of TVA Nuclear Power Plants" Tennessee Valley Authority 80/04/01 2pp
- ---B004070363 TVA-TR75-IA R4 Proposed Revision 4 to TVA-TR75-IA, "QA Program Description for Design.Const & Operation of TVA Nuclear Power Plants " * Tennessee Vallay Authority 80/04/01 119pp
- E0040B0031 Advises that local-to-bulk at values noted in P A 2 7 of NEDE-24223 & are contained in GE 791214 ltr & can be used as nonproprietary WEIBS, J M General Electric Co B0/03/07 ip
- --8004080036 Forwards list of pages in NEDE-24222,Vols 1 & 2 & NEDE-2422 containing proprietary info for use until nonproprietary repts are available Nonproprietary versions should be available within couple of w& PFEFFEREEN.H C General Electric Co 80/03/06 2pp
- 8004080282 Notifies that NRC Ofc of Controller has been asked to bill company for review & approval of BVTR-1-0. "GA Program Description "MILLER.W O License Fee Management Branch 80/03/19 1p
- 8004090316 Forwards proprietary version of NEDE-24720-P "Mark III Confirmatory Test Program 1/7 Area Scale Multicell Condensation & Stratification Phenomena Test Beries 6003 "Rept available in Central Files only BUCHHOLZ, R H General Electric Co , Nuclear Energy Products Div 80/03/17 6pp
- 8004090461 Forwards "Mark-BZ Demonstration Assembly Licensing Rept." Revision tenonproprietary version TAYLOR.J H Babcock & Wilcox Co 80/03/26 ip
- --8004090464 BAN-1533 Ri
 "Mark-BZ Demonstration Assembly Licensing Rept." Revision 1.
 nonproprietary version
 # Dabcock & Wilcox Co BO/02/28 12pp
- BOO4100199 Forwards viewgraphs shown at B&W/NRC BOO326 meeting on TAFY beginning of life pin pressure in LOCA analyses Explanation & discussion encl TAYLOR, J H Babcock & Wilcox Co BO/04/02 App
- 8004100213 Notification of cancellation of 800403 meeting w/C-E owners group in Bethesda:MD re transient analyses & emergency procedure guidelines COX:TH Standardization Branch 80/03/27 2pp
- 8004100217 Notification of cancellation of 800401 meeting w/ Westinghouse owners group in Bethesda MD re transient analyses & emergency procedure guidelines O'REILLY, J.P. Standardization Branch 80/03/27 2pp
- 8004100237 Notification of cancellation of 800402 meeting w/OE BWR owners group in Bethesda. MD re transient analyses & emergency procedure guidelines THOMAS.C.O. Standardisation Branch. 80/03/27 2pp
- 8004100333 Forwards fire protection recommendations on proposed rule re fire protection program for nuclear power plants operating prior to 790101 HALL,R E Brookhayen National Laboratory 7590-01 80/04/01 27ор

- 8004100379 Forwards monthly fire protection rept for Mar 1980, constituting completion of short-term priority item of licensee backlog review HALL/R E Brookhaven National Laboratory 80/04/02 Spp
- 8004i10209 Forwards response to B00124 request for addl info re "Properties of Fuel & Core Component Matl," WCAP-9224 (NP) & WCAP-9179 (P). Revision 1 Application for withholding encl Response re WCAP-9179 & affidavit withhold (ref 10CFR2 790) ANDERBON, T M Westinghouse Electric Corp., PWR Systems Div NB-TMA-2218 80/03/31 2pp
- 8004110216 Forwards "Response of C-E NBSS to Transients & Accidents," CEN-128, Vols 1 & 2 Info in rept intended for use in training of reactor plant operators & revision of emergency procedures LIEBLER,G E C-E Power Systems 80/04/01 2pp
- --8004110223 CEN-128 V2
 "Response of C-E NSSS to Transients & Accidents," Vol 2
 * C-E Pawer Systems 80/04/30 850pp
- --8004110225 CEN-128 Vi "Response of C-E N988 to Transients & Accidents," Vol 1 * C-E Power Systems 80/04/30 330pp
- 9004110481 Notification of 800403 meeting w/B&W & B&W licensees in Bethesda.Md to discuss B&W reactor response & volnerability of task force rept REID.R W Operating Reactors Branch 4 80/03/31 3pp
- B004110537 Responds to B00303 ltr re changes in organization chart of QA dept NRC approves changes HASS.N P Quality Assurance Branch 80/03/21 1p
- BOO41400B3 Responds to 800307 questions re Levels 1, II & III qualified insp personnel functions Level I personnel w/specific experience.can perform direct insps Level II or III individual should review & evaluate Level I HAABB, W P Guelity Assurance Dranch 80/03/27 2pp
- 8004140113 Responds to 800228 request for re-evaluation of fee assessment for Revision 1 & exemption for NEDE-24011-P-A Re-evaluation of Revision 1 fee results in same assessment No basis for waiving topical rept fee MILLER, W O License Fee Management Branch 80/03/20 2pp
- -8004140116 Requests re-evaluation of fee assessment for review of Revision 1 & exemption from fee requirements for NEDE-24011-P-A ENCEL, R E General Electric Co MFN-049-80 80/02/28 Rpp

- 8004150324 Summary of 80010B meeting w/Westinghouse in Bethesda.HD.re-turbine disc cracks RDSB.W J Operating Reactors Branch 1. 80/04/04 5pp
- 8004190353 Forwards "Method of Applying Mark II Single Vent Dynamic Lateral Load to Mark II Plant W/Multiple Vents." on behalf of Mark II owners group Rept withheld (ref 10CFR2 770) Affidavit encl BUCHHOLZ,R H General Electric Co RHB-029-80. 80/04/09 App
- 800417002B Forwards "Failure Mode & Effects Analysis of Engineered Bafety Features Actuation Sys." Revision I, nonproprietary version Affidavit & application for withholding proprietary info encl Proprietary version withheld (ref 10CFR2 790). ANDERSON, T M Westinghouse Electric Corp., PWR Bystams Div NB-TMA-2220 80/03/20 9pp

- --BOQ4170035 "Failure Mode & Effects Analysis of Engineered Safety Features Actuation Sys." Revision 1.nonproprietary version Eighteen oversize pages encl HEBHERINGER, J. Westinghouse Electric Corp., PWR Systems Div BO/02/29 77pp
- BOO418D420 Notification of 800408 meeting w/C-E in Bethesda.MD to discuss high range affluent monitors for Lessons Learned requirements & Reg Quide 1 97
 BARRETT.L Environmental Evaluation Branch 80/04/02 1p
- 8004210244 Submits review of Draft 1 of proposed Revision 2 to SRP 4 2 Section 4 2 Choice of 1 3 safety factor on fuel assembly lateral impact load is conservative for loads created by crossflow TAYLOR, J H Babcock & Wilcox Co 80/04/14 4pp
- 8004210303 Advises of availability of NEDE-24226-P & NEDO-24226, "Evaluation of Control Blade Lifetime @/Potential Loss of B4C "_____
 - IPPOLITO, T A Operating Reactors Branch 3 80/03/24 1p
- --8004210306 Forwards NED0-24226 & NEDE-24226-P, "Evaluation of Control Blade Lifetime w/Potential Loss of B4C " Proprietary version to Central Files only (ref 10CFR2 790) CODK.K W General Electric Co MFN 037-80 80/02/12 2pp
- --B004210307 NEOD-24226 "Evaluation of Control Blade Lifetime w/Potential Loss of B4C:" nonproprietary version BRAYMAN,K W General Electric Co 79/12/31 56pp
- 800421036B Forwards summary of ECCB evaluation model improvements Hill justify continued use of TAFY w/improvements which will officet impact of increased beginning-of-life pin pressure Bix months required for pin-to-pin radiation model TAYLOR.J H Babcock & Wilcox Co 80/04/14 2app
- 8004220434 Forwards presentation matl used at 800327 meeting w/NRC re vendor design approach to post-TMI requirements for technical support & info display sys, parameter console & sys status monitoring ANDERSON.TM Westinghouse Electric Corp NS-TMA-2226 Westinghouse Electric Corp NS-TMA-2226 80/04/08
- B004220497 Forwards "Assistance for Use in Analyzing Mark II BWR Suppression Pool Temp Response to Plant Transients Involving Safety Relief Valve Discharge" BUCHDLZ,R H General Electric Co MFN-071-80 80/04/18 ip
- --8004220479 "Assumptions for Use in Analyzing Mark II BHR Suppression Pool Temp Response to Plant Transients Involving Bafety Relief Valve Discharge "

 # General Electric Operating Plant Owners Oroup 80/03/24 14pp
- BOO4230315 Confirms clarification re organizational changes Topical rept revision not required for minor changes that do not significantly impact GA program SCHERER.A E C-E Power Systems LD-80-017 80/04/18 1p
- 8004240521 SAND77-0274 C
 "Cost Worksheets for Waste Isolation Pilot Plant Conceptual Design Rept." Addendum C
 * Sandia Laboratories 77/04/30 374pp
- 8004240523 SAND77-0274 D "Alternative Energy Sources for Waste Isolation Pilot Plant," Addendum D Sandia Laboratories. 77/04/30, 70pp
- 8004240527 SAND77-0274 E
 "Electrical Load Summary for Waste Isolation Pilot Plant Conceptual Design Rept," Addendum E.
 " Bandia Laboratories 77/04/30. 25pp
- 8004240549 8AND77-0274 F
 "Heating, Ventilation & Air Conditioning Sys Energy Analysis for Waste Isolation Pilot Plant Conceptual Design Rept," Addendum F. Sandia Leboratories 77/04/30 42pp
- 8004250004 Requests pretest analyses for representative experiment re HDR bloudoun program, Analyses should be submitted by 800615 to keep within schedule for evaluation of WCAP-8707 (P) & WCAP-8709 (NP). Assistant Director for Reactor Safety 80/04/01, 2pp DENTRE, R. P.
- 8004250005 Forwards "Dow Egs for Solidification of Low Level Radwasts from Nuclear Power Plants." Amends 1 3 & NRC 780629,1019 & 1207 1trs requesting add1 info per telcon request, W/o encl BAER,R.L. Light Water Reactors Branch 2. B0/04/11. 19

- 8004250066 Requests comments on encl draft proposal re Atmospheric Release Advisory Capability site installations in NY & IL ORPHANIR C Lawrence Livermore Laboratory 80/03/20 9pp
- 8004250409 Forwards bimonthly activities rept for Feb-Mar 1980 HANN,C R Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2313 80/04/17 19pp
- BO04280103 Notification of BO0415 meeting to discuss potential generic problems w/tight radius U-bend tubes in Westinghouse steam generators. Trojan program for U-bend tube removal & establish actions to address potential generic problems LIAW, B D Engineering Branch 80/04/09 2pp
- 8004280182 Extends invitation to 800424 FY80 mid-yr review of program entitled "Experimental Support & Development of Single-Rod Fuel Codes," w/BNNL in Silver Spring, MD FY80 draft program brief, FY81 program assumptions & review agenda encl JOHNSTON, W V Fuel Behavior Branch FIN 8-2043 80/04/08 5pp
- 8004280329 Forwards Revision 1 to Bection 3 0 of WCAP-9402, "Verification Testing & Analyses of Westinghouse 17x17 Optimized Fuel Assembly "Application for withholding & affidavit encl Proprietary version withhold(ref 100FR2 790) ANDERSON, T M Westinghouse Electric Corp N8-TMA-2232 8 80/04/16
- --8004280344 WCAP-9402 NAMESBO344 MCAP-9402 Revision 1 to Section 3 O of MCAP-9402, "Verification Testing & Analyses of Mastinghouse 17x17 Optimized Fuel Assembly," nonproprietary version Westinghouse Electric Corp 80/04/16 67pp
- 8004280400 Provides commitment for thermal hydraulic analysis of Test V-31 for CEMPD-252-P, "Blowdown Analysis Method-Method for Analysis of Blowdown Induced Forces in Reactor Vessel " List of add1 data regulred encl BCMERER, A E C-E Power Systems LD-80-018 80/04/23 3pp
- 8004280504 Forwards responses to NRC 790817 questions on core spray design methodology confirmation tests.addl info requested at 791115 meeting & NEBD-24706. "Lynn SETF Bundle Flow Measurement Sys Description & Calibr "
- --8004280507 NEDD-24706 "Lynn SBTF Bundle Flow Measurement Bys Description & Calibr " DANIELSON,D W General Electric Co 79/08/31 130pp
- 8004290434 Forwards "Implementation Guidelines for Technical Support Ctr t Related Control Room Instrument Sys." Revision 2.dtd 800214 REED.C Westinghouse Operating Plants Owners Group GG-33 80/04/22 22pp
- 800429046B Forwards "Response to NUREC-04B7, Criteria for Computing Loads on Bubmerged Structures," on behalf of Mark II owners group as part of Task C 15 of Mark II containment program BUCHHOLZ,R H General Electric Co , Nuclear Energy Products Div MFN-081-80 80/04/21 2pp
- --B004290474 BAI-161-79-PA JOHAY0474 BAI-161-77-PA
 "Response to NUREC-0487.Criteria for Computing Loads on
 Submerged Structures"
 CHANDRA:V, HSIEH.JS Stone & Webster, Inc. DOMASHOVETZ, I
 Sargent & Lundy, Inc. 80/03/31 73pp

WASTE MOT NUCLEAR WASTE MANAGEMENT

- BOO4020046 Forwards requested info coordinates of receptor locations, map of restricted area boundary & yellowcake drier stack location, joint frequency tables & clarification of seepage analysis LANGE, B.L. Pioneer Nuclear, Inc. 15731 80/03/06 19pp
- 8004020057 Forwards Anaconda Co rept, "Justification for Waiver of Landownership Requirement U Mill Tailings Disposal Area " SETHNEGS.E D Camp Drøsser & McKee, Inc., Environmental Sciences, Div 15734 80/02/25 ip
- ~~8004020061 "Justification for Waiver of Landownership Requirement -U Mill Tailings Disposal Area " * Camp Dresser & McKee, Inc , Environmental Sciences, Div 15734 80/02/08 55pp

- 8004020159 Ack receipt of NRC B00125 itr requesting delay of issuance of license to Bokum Resources Corp for U mill NRC itr cantained no technical objections to project, therefore license was issued on 800129
 KING.B New Mexico, State of 15710 80/01/29 ip
- 8004020165 Requests permission to continue tailings discharge into Pand 1 until limiting conditions autlined in Acres American, Inc 800314 1tr are reached or another discharge pand authorized REKEMEYER, P.C. Union Carbide Corp. 15786 80/03/14 1p
- 8004020182 Notifies that draft rept on Church Rock scheduled for 800801 & final rept by 800901 Schedule depends on livestock data, dose assessments & Battelle scall sampling rept BUHL.T How Mexico. State of 15784 80/03/12 ip
- 8004020196 Requests structural stability evaluation of proposed evaporation pond dam at disposal site & catchment dam at mill site per Reg Guide 3 11 guidance
 MACKIN.J.L. New Merico, State of 15794 80/03/11 ip
- 8004070240 Notification of 800307 meeting w/state & federal agencies in Santa Fe.NM to discuss methods of estimating radiation doses resulting from ingestion of meat from livestock watering in Rio Puerco
 - BUHL. T New Mexico, State of 15465 80/02/28 is
- 8004070246 Notifies that San Miguel Ranch included in preoperational radiological monitoring program is occupied by three persons; including one preschool age child For dose assessment purposes, no milk or vegetable pathway included MDDNEY.FS Gulf Dil Corp. Gulf Mineral Resources Co 15651 B0/02/22 ip
- BOO4070353 Forwards NRC correspondence file re proposal from Cotter Corp to dispose of miscellaneous contaminated solid wastes in portion of new sailings impoundment at U mill Requests review & assessment.w/recommendations.of sncl matl ROTHFLEISCH, J Uranium Recovery Licensing Branch 80/03/17 ip
- --8004070355 Forwards 800226 request for assistance from A Harle, Director of Radiation & Harardous Wastes Control Div. CO Dept of Health, re trash disposal at Cotter Corp U mill KERR. OW Assistant Director for State Agreements Programs 80/03/05 ip
- --B004070359 Forwards addl info re Cotter Corp proposal to dispose of contaminated trash, machinery & const matls in secondary impoundment Requests NRC further critique or concur w/proposal HAZLE, A J Colorado, State of B0/02/24 Spp
- 8004070369 Forwards latest correspondence re tailings mgt for proposed pitch project, as promised in 800311 telcon Both applicant & state no longer consider burial at Sito B viable alternative for tailings disposal W/o encls ROTHFLEISCH. J. Uranium Recovery Licensing Branch 80/03/17 ip
- 8004080151 Responds to V Walker inquiry re radioactive matl release from Church Rock U mill 790716 tailings dam failure Contamination cleanup complete in most heavily affected areas near mill site DIRCKB.W J Office of the Executive Director for Operations 80/03/03 2pp
- 8004080226 Requests waivers of land ownership requirements for licensing U mill tailings disposal Surface tracts used for disposal are under lease & planned to be returned to lessors
 DAVIS.G R , WILLIAMS.M Anaconda Co (subs of Atlantic-Richfield Co) 15737 80/02/28 3pp
- 8004080278 Requests permission to continue discharge of tailings into Pond 1 through 800325 subject to operating conditions discussed in Acres American. Inc 800107 ltr w/exception that piezometer levels be limited to one ft above 800108 levels REKEMEYER.P C Union Carbide Corp 15660 80/02/15 1p
- 8004080665 Discusses AJ Harle 7912;9 request for NRC assessment of potential radiological impact of U mill operation on proposed residential subdivision Results of NRC evaluation are summarized in NRC 800123 ltr to Harle CNUCNGLI,9 Uranjum Recovery Licensing Branch 80/03/13 2pp
- 8004090020 "Ground Water Discharge Plan.Mt Taylor U Mill Project.NM " * Earth Sciences Associates 15849 80/01/31 42pp

- 8004090115 Forwards responses to NM Environ Improvement Div questions re U mill license application All containment basins are sized to contain drainable vol of slurry & liquid in both pipelines, plus 10 minutes of flow in pipelines ROGERS.M L. Culf Oil Corp., Gulf Mineral Resources Co. 15745 80/03/04.
- BOO4090135 Forwards discussions of work planned as part of investigation of Hale Gulch as considered site for deposition of tailings Work includes field drilling, lab testing & dam design SIMCHUCK.O Homestake Mining Co 15698 80/02/28 14pp
- --8004090140 "Evaluation of Existing Osohydrologic Data Homestake Mining Co Pitch Project-Hale Gulch (Site A) Tailings Pond Site, Saguache County,Co " Related correspondence encl ROUSE.J V Envirological Bystems, Inc. 15678 80/01/10 13pp
- 8004110118 Forwards Co Dept of Health 800221 & 19 ltrs & Union Carbide Corp 800213 & 19 ltrs re discharge of tailings into Pond 1 WEAVER.K Colorado: State of 15791 80/02/22 9pp
- 8004110144 Forwards State of CO 800226 request for assistance re trash disposal at Cotter Corp.Canon City U mill.CO KERR.G W Office of State Programs 15707 80/03/05 ip
- --B004110146 Forwards addl info re Cotter proposal to dispose of contaminated trash, machinery & const matls in secondary impoundment Requests further critique or concurrence on proposal per Public Law 95-604 HAZLE.A J Colorado. State of B0/08/26 Spp
- 8004180105 Advises of completed dam safety review for Union Carbide Uravan mill per 791104 request Results of encl safety evaluation indicate that Pond 2 & 3 do not meet safety factors recommended by NRC Reg Quide 3 11 W/o encl SCARAND, R A Uranium Recovery Licensing Branch 80/03/21 1p
- B004210416 Forwards summary of B00214 meeting between NRC, vendor & State of TX organizations Also forwards NRC comments on vendor mill tailings disposal ropt Statements made re site characteristics are consistent w/NRC visual observations, MILLER, H J Uranium Recovery Licensing Branch 80/03/25 4pp
- 8004220200 Forwards response to Question 10 in 791221 ltr re 100-yr flood boundary & final tailings discharge from wash filter Contour interval map & photos of final tailings encl LANOE.B L Pionesr Nuclear.Inc 15663 80/02/29 Bpp
- 8004230148 Discusses NM Environ Improvement Div approval of Discharge Plan DP-100 & issuance of radioactive meths license Expresses concern re question of public role in review of matl generated by vendor in response to license conditions ROBINSON.F. HECTOR.A Southwest Rossarch and Information Center 15837 80/03/10 16pp
- 8004240060 Advises that E Reed & Associates has been employed to develop techniques for return of tailings to pit, after mining, for final disposition Borings have been taken & company expects to review final Reed rept on 800416 DAVIS, G R Anaconda Co , Anaconda Copper Co Div 15914 80/03/24
- 8004240116 Responds to 800314 request for third interim authorization to discharge tailings to Pond 1 CO Dept of Health will authorize continued discharge of tailings through 800315 if requirements of dept 800180,0219 & 21 ltrs are met HAZLE, A J Colorado, State of 15834 80/03/20 2pp
- 8004280231 Submits trip rept re 791105 visit to review proposed site for mining & milling facility Review should be complete in approx four months assuming timely resolution of questions on proposal Schedule & maps encl
 KRUG,K E Uranium Recovery Licensing Branch 80/03/11 9pp.
- 8004270507 Expects review of 800227 draft agreement between NRC & State of MA will include stability review of embankment against requirements of Reg Quide 3 11 STRONG/TR Washington: State of 15970 80/04/03 ip
- 8004290520 Forwards analytical results of 791015-16 sampling trip to Canon City to investigate water, soil 5 vegetation contamination

 DREESEN, D R Los Alamos Scientific Laboratory 14054 79/12/18

- 8004300215 Forwards Ford, Baron & Davis UT, Inc "Appraisal Rept." prepared for State of DR.re area under consideration by Placer Amex in connection w/proposed tailings disposal facility Related correspondence enci HGGRATH.E J HGGrath, E J 15912 80/03/27 4pp
- --8004300219 UC-329
 "Appraisal Rept," pregared for Div of State Lands, State of Ford Bacon & Davis Utah, Inc. 15912 80/03/27 35pp
- B004300239 Safety avaluation for Tailings Ponds 2 & 3 * Geotechnical Engineers.inc NRC-02-79-055 15966 80/03/07
- 8004300254 Requests written confirmation of agreement re items discussed in NRC 791214 ltr & 800312 telcon Revised UDAD analysis & evaluation of environ impact of radon & articulates requested AZLE,A J Colorado, State of 15842 80/03/17 ip
- 8004300297 Hritten comments of Homestake Mining Co before Dept of Agriculture re appeal of Regional Foresters decision on administrative appeal of approval of U mill operation FISKE.T N , HATBON.J F Gorsuch Kirgis, Campbell, Halker & Grover FISKE.T N Homestake Mining Co 15840 80/03/25 27pp
- XPORTLIC EXPORT AND IMPORT LICENSES
- 8004010051 SECY-80-045 Forwards Executive Branch position on 800121 applications for licenses to export highly enriched U to Belgium West Germany France & the Netherlands Requests comments SHEA, R Office of International Programs 80/01/24 ip
- --B004010478 Executive Branch position re five Transnuclear, Inc applications for licenses to export highly enriched U to Belgium, Nest Germany, France & the Netherlands Recommands issuance of licenses Ltrs of assurance encl NOSENZO.L.V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs. B0/01/21 15pp
- --8004010095 Forwards two applications for licenses to export 22 050 kg U enriched to max 93 3% U-235 & 779 kg U.enriched to max 4 05% U-235 M/o latter application MAT80N,V Transnuclear Inc 78/06/22 2pp
- ---8004010097 Application by Transnuclear, Inc for license to export 20 050 kg U, in form of U hexafluoride enriched to max 93 3% U-235, to the Natherlands End use statement encl MATSON, V Transnuclear, Inc 79/06/22 2pp
- --8004010101 Forwards Transnuclear, Inc application for license to export 72 & kg U in form of U herafluoride enriched to max 93 3% U-235 to France.

 MATSON: V Transnuclear, Inc 78/08/08 1p
- --8004010105 Application by Transnuclear Inc for license to export 72 6 kg U, in form of U hexafluoride enriched to max 93 3% U-235, to France End use statement & related checklist of info encl MATBON:V Transnucteur. Inc 78/08/08 Bpp
- 8004020184 License for Exxon Nuclear Co, Inc to export nuclear fuel element hardware including Zircaloy tubes. Zircaloy end caps. Inconel plenum springs & other specially designed nuclear reactor parts to Heat Germany.

 PETERSON H R Assistant Director for Export/Import & International Safeguards 80/03/13 ip
- 8004020236 Application by Bargent Industries-Bweeney Div for license to export 125 Ci tritium contained in fulls
 SQUITIERI.R J Sargent Industries, Sweeney Div XB-5-385 80/03/12
- BOO4020240 Application by Byron Jackson Pump Div for license to export specifically designed or prepared parts & components for pumps to India * Borg Warner Corp : Bryon Jackson Pump Div INDIA. BO/03/06 ip
- 8004020246 Application by Byron Jackson Pump Div for license to export two rotating face rings, four carbon bearings, four retaining rings one coolant recirculating impeller & one bearing retainer assembly to India * Borg Harner Corp . Bryon Jackson Pump Div. 793-V-2785 80/03/06

- 8004020369 Executive Branch position re Transnuclear, Inc application for license to export 100,000 kg natural U to West Germany Ltrs of assurance encl License should be granted NDSENZOL V State. Dept of. Bureau of Oceans & Internati Environ & Scientific Affairs 80/03/06 4pp
- 8004020387 License for Aldrich Chemical Co. Inc to export 10 kg deuterium.contained in 40 kg deuterium oxide, to United Kingdom PETERSON, M R Assistant Director for Export/Import & International 180 80/03/06 2pp 6180 Safequards
- 8004020393 Amend i to Edlow Intl Co export license, extending expiration date from 800401 to 820401
 PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/12 ip
- 8004020397 Amend 1 to Edlow Intl Co export license extending expiration date from 800401 to 820401
 PETERSON N R Assistant Director for Export/Import & International Safeguards 80/03/12 ip
- 8004020401 Amend 1 to Edlaw Intl Co export license extending expiration date from 800401 to 820401
 PETERSON M R Assistant Director for Export/Import & International Safeguards 10-44-78-1 80/03/12 1p
- B004020405 Amend 1 to Ediow Intl Co export license, extending expiration date from B00401 to 820401 PETERSON M R Assistant Director for Export/Import & International Safeguards 10-44-78-2 80/03/12 ip
- 8004020467 Requests early review of applications to export two nuclear reactors & initial fuel cores in advance of util award of project Early review would be significant step to enhancing foreign confidence in US supply & licensing process WILSON, B D General Electric Co BDW-80029 80/03/07 2pp
- ---8004020471 Application by GE Tech Svc Co & GE for license to export 239,000 kg low enriched U oxido as fabricated BHR fuel bundles to Taiwan HILSON.B D General Electric Co BDN-80031 80/02/07 to
- 8004020472 Forwards application by Transnuclear, Inc for license to export 30, 476 kg U.containing 1,234 kg U-235 & 129,224 kg U.containing 919 kg U-235, to West Germany MATSON. V Transnuclear, Inc. 80/03/19 1p
- -8004020479 Application by Transnuclear, Inc for license to export 30,746 tg U.containing 1.234 tg U-235 & 129,224 kg U, containing 919 kg U-235,to Hest Germany * Transnuclear, Inc WUK-319 80-059/ 80/03/19 3pp
- 8004020404 Submits application to amend licenses extending expiration dates from 800401 to 810401 YAMAGUCHI.T Power Reactor & Nuclear Fuel Development Corp 80-0-009 80/02/26 1p
- 8004030043 Forwards application by Coordination Council for North American Affairs to export 4000 kg heavy water to Taiwan HU,K Coordination Council for North American Affairs 80/03/12
- ---B004030046 Application by Coordination Council for North American Affairs for license to export 4000 kg heavy water to Taiwan End use statement encl # Affiliation Unknown 80/03/10 2pp
- 8004030049 License for Hestinghouse Electric Co to export BF 3 counter tube, Model NL-23744 to France PETERSON,M R Assistant Director for Export/Import & International Bafguards 80/03/25 ip
- 8004030274 Forwards application for license to export component sys & parts for two OE forced circulation single cycle light water cooled & moderated BWRs w/designed power level of 984 MW. to Taluan WILSON, B D General Electric Co BDW-80029 80/03/07 2pp
- --8004030280 Submits application for license to export component sys & parts for two QE forced circulation.single cycle light water cooled & moderated BMRs w/design power level of 784 MH, to Taiwan WILSON, B. D. General Electric Co. BDW-80030 80/03/07 2pp.
- 8004030364 Requests Executive Branch position re Transnuclear.Inc application for license to export SNM to West Germany PETERSON.M R Office of International Programs 80/03/27 ip

NONDOCKETED ITEMS

- 8004040038 Waives 15-day waiting period for License X8-1090 PETERBON.M R Assistant Director for Export/Import & International Safeguards 80/03/27 4p
- --8004040042 License for Gearhart-Owen Industries, Inc to excort 5 Ci Am-241 to Poland Am-241 to Poland Perent In the sport of the sport in the sport in
- 8004040045 Waives 15-day waiting period for License XB-1089
 PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/03/27 1p
- --8004040049 License for Kay-Ray. Inc to export 400 mCi Cs-137 in two sources to Csechoslovakia PETERSON.M R Assistant Director for Export/Import & International Safeguards 2872 80/03/27 2pp
- B0040400B7 Forwards ltr from Embassy of Israel requesting cancellation of application XB-1041 H/o encl PETERSON,M R Assistant Director for Export/Import & International Safeguards B0/03/19 1p
- 8004040090 Requests cancellation of application to export byproduct matl to Southwest Africa (Namibia) JOHNSON,N R Eberline Instrument Corp EI-917682 B0/02/28 ip
- 8004040099 Requests Executive Branch position re Metal Bellows Corp application for license to export flexible metal hoses to Epain
- Spain PETERSON, M R Assist. Assistant Director for Export/Import & International
- BOO4040103 Application by Rockwell Inti,Flow Control Div for license to export Rockwell-Edward globe stop valve,metal diaphragm sealed, ASME III,1521 special class rated, body & bonnet of SA182,Grade F316 stainless steel, to India UFBANIK,W J Rockwell International Corp 2929FE 80/03/14 ip
- 8004040107 Application by Sigma Chemical Corp for license to export equivalent of 5 kg deuterium liquid over two-yr period to Canada
- 001CH,P A 80/03/07 Sigma Chemical Co (subs of Sigma-Aldrich Corp) D-39 ip
- B004040110 Forwards application by Transnuclear Inc for license to export 10.794 kg U.enriched to max 3 4% U-235 to Belgium MATBUN V Transnuclear Inc B0-037/01 TNP-3 80/03/12 ip
- --8004040114 Application by Transnuclear, Inc for license to export 10,774 kg U, enriched to max 3 4% U-235.to Delgium
 * Transnuclear, Inc 80-037/01 TNP-3 80/03/12 3pp
- 8004040135 Submits applications to amend license extending expiration date to 830501 HARMON, D W Edlow International Co 80/03/10 ip
- 8004040141 Application by Par Sys Corp for license to export Par Model 181-2, inservice insp sys. to United Kingdom PARSONS, W B Par Systems Corp 667-3 80/03/10 ip
- ~-8004040152 Ack receipt of NRC 791015 ltr Expresses surprise w/NRC apinion that sale of inservice insp sys should require NRC permit PARSONS,W B Par Systems Corp 79/11/27 2pp
- BOO4040147 Executive Branch position re Saunders-Roe Developments, Ltd application for license amend to export add1 500,000 Ci tritium, to United Kingdom License should be granted, NDZENZOL V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/14 2pp
- 8004040178 License for CERAC, Inc. to export 8 78 kg thorium, contained in 10 kg thorium oxide as powder, to Italy PETERBON.M R. Assistant Director for Export/Import & International Safeguards 80/03/25 2pp
- 8004040477 Amend 1 to Saunders Roe Developments, Inc license changing B00501 expiration date to 810715 & increasing amount of export to one million Ci tritium as tritium gas PETERSON,M R Assistant Director for Export/Import & International Bafeguards B0/03/21 2pp
- 8004040480 Requests Executive Branch position re Ediow Intl Co application for license to export source matl to Taiwan PETERSUN.H R Assistant Director for Export/Import & International Bafeguards 80/03/27 ip

- 8004070023 License for Eberline Instrument Corp to esport 0 02 microgram Pu-239 electroplated on stainless steel in DNS-10 alpha calibr std set to South Korea MODREN N Assistant Director for Esport/Import & International Safeguards 5 0 6957 80/03/07 2pp
- 8004070026 Ltr of assurance that Covt of Japan has appointed Kansai Electric Power Co. Inc as authorized party for import of 25 mg of U-235, enriched to max of 93 15/ MIYABAYASHI.M Japan 79/11/29 ip
- B004070028 License for QA Co to export 405 g U-235, contained in 579 g U.as FLIP TRIQA fuel elements, to Mexico PETERSON, M R Assistant Director for Export/Import & International Bafeguards IEL-992 80/03/06 2pp
- 8004070027 Forwards notice of applications for licenses to export nuclear facilities or matls for FR publication SHEA,J R Office of International Programs 80/03/08 ip
- ---8004070034 Notice of applications for licenses to export nuclear facilities or matis received 800211-0303
 GHEA: JR Dffice of International Programs 80/03/08 2pp
- 8004070037 Forwards application for export license for minor nuclear expart Ltr of assurance required
 PETERBUN.HR Assistant Director for Export/Import & International
 Safeguards 60/03/27 ip
- 8004070073 License for DOE to export 3 95 kg U-235.contained in 20 kg U as metal & 2 25 kg U-235.contained in 5 kg U as metal, to the Netherlands & West Germany MOGRE, R N Assistant Director for Export/Import & International Safeguards 80/03/07 2pp
- 8004070078 Amend to GA Co export license, increasing quantity of authorized matl from 1 72 g U-235, contained in 1 84 g U, to 3 52 U-235, contained in 3 84 g U MCURE, R N Assistant Director for Export/Import & International Safeguards IEL-1020 80/03/06 ip
- 8004070080 License for DDE to export 3 95 kg U-239, contained in 20 kg U as metal & 2 25 kg U-235, contained in 5 kg U as metal. to France & the Netherlands MODRE, R N Assistant Director for Export/Import & International Safeguards 80/03/07 2pp
- B004070085 Bubmits application to amend license to export, changing quantity of authorized matl to 10 1 kg U-235, contained in 51 2 kg U HATBUN, V Transnuclear, Inc 80/03/05 is
- 8004070088 License for Chase Nuclear Div of Chase Brass & Copper to export ii.000 lbs rirconium 2 5% niobium alloy extruded tubes to Italy PETERSON.M R Assistant Director for Export/Import & International Bafaguards A2-2020 80/03/07 ip
- 8004070148 SECY-80-142
 Recommends issuance of license to export reactor & associated components to Philippines Proposed export would not be inimical to US common defense & security No further action required on SECY-79-100
 SHEAJ R. Office of International Programs 80/03/14 App
- --8004070180 Discusses deaths of two energy activists & physical security of proposed reactor Continued repression creates highly unstable environ "Mother Jones" Dec 1979 article re state of civil war in Philippines encl
 PERLAS.N Philippine Movement for Environmental Protection 80/01/27
- 8004070407 Requests Executive Branch position on encl Coordination Council for North American Affairs application for license to export 4.000 kg of heavy water to Taiwan W/o encl PETERBONN M R Assistant Director for Export/Import & International Safeguards 80/03/20 ip
- BOO40BOOGY Foewards application by GA Co to export SNM contained in 20 TRIOA fuel elements & four fission chambers, to Indonesia MDWRY.W R General Atomic Co (subs of Gulf Oil Co) BO/03/14

- --8004080014 Application by GA Co for license to export 6,478 g U-sirconium hydride, contained in 20 TRIOA fuel elements & four fission chambers containing U-235, to Indonesia MORRY, WR General Atomic Co (subs of Gulf Dil Co) IEL--1159 80/03/14 ip
- 8004090020 Submits application to amend license, changing ultimate consignee address
 MATSON.V Transnuclear, Inc 80/03/21 19
- 8004080032 Application by Edlow Intl Corp for license to export 600 kg depleted U digride powder to Taiwan End use statement encl HARMON, D W Edlow International Co IM-1 80/03/17 2pp
- 8004080039 Forwards application by Transnuclear.Inc for license to export 1.638.65 kg U-235.contained on 49.656 kg U.to France MATBON.V Transnuclear. Inc 80/03/20 ip
- --8004080042 Application by Transnuclear, Inc for license to export 1,638,65 kg U-235, contained in 49 636 kg U to France End use statement encl MATBON.V Transnuclear, Inc 80-042/01 80/03/21 2pp
- 8004080050 Application by Teledyne Wah Chang Albany for license to export 108 tons Zircolay tubes to Argentina AERNI.B L Teledyne Wah Chang Albany 3155 80/03/21 ip
- BOO4080069 Advises that route for transport of AECL spent fuels from Ogdensburg, NY to Dunbarton.NC must be changed due to local ordinance in Geneva.NY Proposes alternate route BTUKENBROEKER.O NL Industries. NL Nuclear Div 15807 80/03/11
- 8004080079 Forwards application by Transnuclear, Inc for license to export 22 142 kg U.containing 10 053 kg U-235.to Japan MATSON:V Transnuclear, Inc. 80/03/25 ip
- --8004080085 Application by Transnuclear, Inc for license to export 22 142 kg U, containing 10 053 kg U-235, to Japan End use Btatement encl
 MATSON, V Transnuclear, Inc 80/03/25 18pp
- 8004080087 License for Mitsubishi Intl Corp to export 500 mci Cf-252 as encapsulated cernet wire to Japan PETERSON M R Assistant Director for Export/Import & International Safaguards 80/03/25. 2pp
- 8004080076 License for Mitsubishi Intl Corp to export 500 mci CF-252 as encapsulated cernet wire to Japan PETERSUN.H R Assistant Director for Export/Import & International Safeguards 64-7407-80 80/03/25 2pp
- BOO4080104 Forwards application by Transnuclear, Inc for license to export 40 48 kg U.containing 37 768 kg U-235 to Japan MATBON.V. Transnuclear, Inc 80/03/25 ip
- ---8004080259 Application by Transnuclear, Inc for license to export 40 48 tg U.containing 37 768 kg U-235, to Japan End use statement encl MATSON, V Transnuclear, Inc 80/03/25 35pp.
- 8004080118 Executive Branch position re CONAX Corp application for license to export adapter module assemblies & seal components for electrical penetration assemblies to Spain License should be granted NOBENZO.L.V State.Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/03/25 2pp
- 8004080126 Executive Branch position re Carpenter Technology Corpapplication for license to export Zircalog-4 fuel channels to Spain License should be granted NOBENZO-L.V. State.Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/25 2pp
- 8004080131 Executive Branch position to Reactor Experiments Inc application for license to export 0.3 mg Np-237 electroplated on mickel discs for use in dosimetry to Czechoslovakia License should be granted NOBENZO.L V. State, Dept. of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/25 2pp
- 8004080138 Executive Branch position re Westinghouse application for license amend to export low enriched U to Korea in Jan 1984 rather than 1983 License amenó should be granted NOBENZO,L V State, Dept of Bureau of Oceans & Internati Environ & Scientific Affairs, 80/03/26 2pp

- 8004080251 License for Reactor Experiments, Inc to export 0 342 mg Np-237 to Ciechoslovakia PETERBON, M R Assistant Director for Export/Import & International Safeguards C7 2806 80/03/27 2pp
- 8004080295 License for Westinghouse to export 43 mg U-235.contained in A3 mg U.to Yugoslavia PETERBON,M R Assistant Director for Export/Import & International Safeguards BX-11006 80/03/27 2pp
- 8004080299 Waives 15 day waiting period for proposed license for Aldrich Chemical Co to export deuterium oride to Brazil PETERSON, M.R. Assistant Director for Export/Import & International Safeguards 80/03/27 ip
- ---8004080303 License for Aldrich Chemical Co.Inc to export 1 kg deuterium contained in 5 kg deuterium oxide, to Brazil PETERSDN.M R Assistant Director for Export/Import & International Bafeguards 80/03/27 2pp
- 8004080311 License for Carpenter Technology Corp to export 96 pieces of 2 mm Zircaloy-4 alloy fuel channels, to Spain PETERSON, MR Assistant Director for Export/Import & International Safeguards 80/03/26 ip
- 8004080315 License for Conax Corp to export adapter module assemblies & electric penetration seal components to Spain PETERSON.M R Assistant Director for Export/Import & International Bafeguards 7-86800 80/03/27 ip
- 8004080332 Application by Kay-Ray, Inc for license to export 400 mCi Cs-137 in two sources to Crechoslovskia BAKER, R Kay-Ray, Inc 2872 80/03/21 ip
- 8004080342 Application by Westinghouse for license to export six WL23465 income detector units to Bultzerland POCHAL.W F Westinghouse Electric Corp ZE-10289 80/03/17 i
- 8004080345 Application by Teledyne Wah Chang Albany for license to export 400 lbs Zircaloy-2 tube shells to Norway WATTENBARGER.8 Teledyne Wah Chang Albany 2849 80/01/28 ip
- 8004080350 License for Ediow Intl Co to export 68,500 kg U.as natural V hexaflouride, to France PETERBON.H R Assistant Director for Export/Import & International Bafeguards KWK 80/03/26 2pp
- 8004080353 License for Transnuclear. Inc to export 100,000 kg U oxide. containing 715 kg U-235, to West Germany PETERSON, M R Assistant Director for Export/Import & International Safeguards NUK-291 79-211/ 80/03/26 2pp
- 8004080620 Requests Executive Branch position re Edlow Intl Co application for license to export U-308 to West Germany for eventual use as fuel in Emsland power reactor PETERSON M R Assistant Director for Export/Import & International Bafeguards 80/03/12 ip
- 8004080627 License for Mestinghouse to export 0 0164g U-235,contained in 0 0166 g U-to Yugoslavia PETERSON M R Assistant Director for Export/Import & International Safeguards ZEPW-11017 80/03/27 2pp
- BOO4080643 Application by Aldrich Chemical Co.Inc for license to export 1 kg deuterium.contained in 5 kg deuterium oxide to Brazil EDELBTEIN.B Aldrich Chemical Co., Inc. (subs. of Bigma-Aldrich Corp.) 80/03/27 Ip
- B004080650 Application be Gearhart-Guen Industries, Inc for license to export 5 cf Am-241 in neutron source to Poland CLAUNCHIA Gearhart-Guen Industries, Inc., 60 Nireline Services Div 40-180/80049 80/03/20 Ip
- 8004090113 Forwards Bargent Industries application for license to export tritium contained in foils to Condition 2 countries New request required because licensee inadvertently allowed old export license to expire PETERSDN.M R Assistant Director for Export/Import & International Baraguerds 80/03/20 19
- 800409019B Forwards license to export gauges to China License issued w/o 13-day waiting period due to urgent requirement of matl PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/21 ip

- --B004090202 License for Campbell Pacific Nuclear Corp to export 10 mCi Cs-137 % 50 mCi Am-241/Be contained in moisture density gauge to China PETERBON.M R Assistant Director for Export/Import & International Safeguards 80/03/21 1p
- 8004100044 Executive Branch position re Exxon Nuclear Co Inc application for license to export 1.940 kg of U-235, contained in 55.440 kg of U.to Belgium Ltr of assurance encl License should be granted NOSENZO:L V State, Dept of, Bureau of Oceans & Internat! Environ & Scientific Affairs 80/03/28 2pp
- BOO4100049 License for Sigmo Chemical Cu to export 5 kg deuterium oxide.to Camada PETERSON.M R Assistant Director for Export/Import & International Safeguards BO/04/01 2pp
- BOO410005B Executive Branch position re Exxon Nuclear Co.Inc application for license to export 2.110 kg U-235.contained in 48.000 kg of Urto West Germany Ltr of assurance encl License should be granted NGSENZO.L V State.Dept of. Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/28 2pp
- 8004100060 Executive Branch position re Nuclear Metals, Inc application for license to export 150 lbs depleted U for R&D to Oermany License should be granted NOSENZO.L V State. Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/27 2pp
- BO04100062 Requests Executive Branch position re Teledyne Isotopes application for license amend, extending expiration data from 800501 to 820501 PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/31 ip
- BC04100063 Notifies of withdrawal re 780718 application for license to export 25,000 kg enriched U
 HERBCH,M M Nestinghouse Electric Corp 80/03/03 1p
- BCO4100175 Requests Executive Branch position re OA Co application for license to export SMM to Bangladesh PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/04/02 ip
- BOO4100177 Requests Executive Branch position re Edlow Intl Coapplication for license to export Cf-282 neutron sources to United Kingdom PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/04/02 ip
- 8004100180 Requests Executive Branch position re 9A Co application for license to export SMM to Indonesia PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/04/03 ip
- GC04100181 Requests Executive Branch position re Par Bys Corpapplication for license to export inservice insp sys to Bouth Africa
 PETERSON, HR Assistant Director for Export/Import & International Safeguards 80/04/03 1p
- 8004100184 Requests Executive Branch position re Transnuclear, Inc application for license to asport SNM to Japan PETERSON. M R Assistant Director for Export/Import & International Safeguards 80/04/03 tp
- 8004100232 License for Nissho-Iwai American Corp to export 39 186 kg U-235, contained in 42 Kg U, to Japan. PETERSDN, M R Assistant Director for Export/Import & International Safeguards 80/04/02 3pp
- 8004100306 Application by Eberline Instrument Corp for license to export Pu-239 alpha calibr sources.electroplated on 47 mm metal disc to Canada
 JUHNBUN.N L Eberline Instrument Corp 50 7491 80/03/29 ip
- BD04100597 Advises of Commission acceptance of recommendation to approve Ediow Intl Co license to export 68,500 kg of U in form of UF6, to France Comments of Chairman Absarve noted CHILK.B J Office of the Secretary of the Commission B0/03/25 in
- BOO4110117 Advises of intention to cancel 791108 application re export of 1 O Ci tritium gas to Israel APPELBAUN.A Israel GF/BO/312 BO/03/13 2pp

- 8004110141 Forwards Isotope Products Labs note transmitting IAEA 800317 ltr providing add1 end use info re license application XB-1069 W/o encl PETERBONN MR Assistant Director for Export/Import & International Safeguards 80/03/28 ip
- 8004110538 Forwards QE application for license to export two BWRs to Taiwan W/g encl SHEA, J R Office of International Programs 80/03/17 ip
- 8004140010 Application by NL Nuclear Industries to amend license, increasing matl for import to 72 087 kg U, containing up to 42 541 kg U-235 as spent NRX & NRU fuel to Savannah River Plant STUKENBROEKER, O NL Industries, NL Nuclear Div 80/03/17 7pp
- 8004140064 Requests expeditious handling of 790127 application for license to export Korean Nuclear Units 7 & 8 concurrent w/Executive Branch review Undue delay could jeopardize contract as discussed in encl 791107 ltr to State Dept MERSH.N M Westinghouse Electric Corp ICS-0042 80/03/26 4pp
- 8004160082 Forwards 781129 license application w/o action per 800320 request PETERBON,M R Assistant Director for Export/Import & International Bafeguards 80/04/01 ip
- 8004170183 Forwards end use statement for completion of 791219 export license application HELM.K Isotope Products Laboratories 80/03/17 2pp
- 8004170270 Confirms that SNM identified in export license application will be subject to terms & conditions of 570528 agreement for cooperation & consignees identified on application are authorized to receive & possess matl
- 8004170291 License for Carpenter Technology Corp to export 48 Zircaloy-4 fuel channels to Japan PETERBGN.M R Assistant Director for Export/Import & International Bafeguards 80/04/04 ip
- BOO4180088 Forwards applications for licenses to export flexible metal hose to Spain
 ROGERS, W F Metal Bellows Corp 80/03/14 ip
- --8004180089 Application by Metal Bellows Corp for license to export 25 pieces flexible metal hoses to Spain ROGERS.W F Metal Bellows Corp 14812 80/03/14 ipp
- --8004180072 Application by Metal Bellows Corp for license to export four pieces hose assembly 7001-086-0707-M-A8-AS to Spain ROGERS,W F Metal Bellows Corp 14845 80/03/14 1p
- 8004180200 Forwards application to export 32 6 kg U metal, enriched to 19 79% U to France ANL 800128 memo encl BENGELSDURF.H D Energy, Dept of 80/03/28 1p
- --8004180207 Application by DOE for license to export 32 4 kg U metal, enriched to 19 79% U.to France BENGELSDORF,H Energy,Dept of 80/03/24 3pp
- 8004180229 Executive Branch position re Transnuclear, Inc application for license to export 367 kg U-235, contained in 10,794 kg U,to Belgium MARCHAL, J State, Dept of 80/03/27 ip
- 8004180242 Application by Mitsui & Co.Inc for license to export Zircaloy-2 tube shalls & Zircaloy-4 tube shalls to Japan MONDEN.T. Mitsui & Co.: Ltd 80/04/03 2pp
- 8004i80307 Requests Executive Branch position re Helix Process Sysapplication for license to export two hydrogen recombiners to South Africa PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/27 ip
- ---8004180310 Application by Helix Process Sys for license to export waste gas mgt treatment sys consisting of two hydrogen recombiners followed by ambient temp charcoal absorption equipment to South Africa Helix Technology Corp . Process Systems Div 270000 79/11/19, 1p
- --8004i80314 Forwards 791119 application for license to export waste gas mgt treatment sys to South Africa MURPHY.W J Helix Technology Corp , Process Systems DJV 80/03/17 ip

- BOO4180480 Extends appreciation for prompt issuance of license amend, changing expiration date to 810303 MOURY, W R General Atomic Co (subs of Gulf Oil Co) IEL-1160 80/03/14 ip
- BOO4180485 Submits application to amend export licence, changing expiration date to 820501 due to administrative decisions PABINDBKY, J P Teledyne Isotopes 80/03/24 ip
- 8004180507 Ltr of assurance re Teledyne Wah Chang Albany application for license to export 400 lbs Zircaloy-2 tube shell DAHL.J H Norway 80/03/18 ip
- BO04210002 Advises of NL Industries 800320 request that license be returned w/o action Application for export of 50,000 kg depleted U to Condition 2 countries was transmitted for review on 781221 PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/27 ip
- 800A210026 Forwards application to export 7 3 Kg U-235.contained in 245 kg U-to Canada W/o enci itr application to import same matl to US upon completion of experimental work ELGERT, O J Energy, Dept of 80/03/31 ip
- ---B004210149 Application by DDE for license to export 7 3 kg U-235, contained in 245 kg U to Canada HANSEN,C D Energy,Dept of BR-1593 80/03/25 ip
- 8004210090 Application by Sigma Chemical Co for license to export compounds containing deuterium to Malaysia STERN.N C Sigma Chemical Co (subs of Sigma-Aldrich Corp) D-40 B0/03/28 ip
- _800A210092 Application by Sigma Chamical Co for license to export compounds containing deuterium to New Zealand
 BTERN.H C. Bigma Chemical Co (subs of Sigma-Aldrich Corp.) D-41
 BO/OJ/31. 1p
- 8004210096 Bubmits application for license to import several mg Pu-23B, probably from France
 O'SRIEN.M J Hashington Univ 80/03/31 2pp
- BOO4210123 Application by Westinghouse for license to export 1 68 g U, contained in 1 81 g U-235 to Italy POCHAL.W F Westinghouse Electric Corp ZE-40039 B0/03/28 ip
- 8004210136 Application by Westinghouse for license to export three units ML-23944 compensated ionization chamber to France PDCHAL, M. F. Westinghouse Electric Corp. ZE-20293-4 80/04/02 ip
- BOO4210156 Application by OA for license to export 291 elements containing U-ifrconium hydride fuel w/mar isotope weight of 11 kg U-235 & TRIOA reactor neutron detectors containing max of 6 6 gm U-235 to Bangladesh MONRY, W R General Atomic Co (subs of Gulf Dil Corp.) 80/03/24
- --8004210159 Forwards application to export SNM contained in fuel elements & neutron detectors to Bangladesh HOHRY.W R General Atomic Ca (subs of Gulf Dil Corp) 80/03/24 2pp
- 8004210364 Requests Executive Branch position re Teledyne Wah Chang Albamy application for license to export Zircaloy TREX tubes to Argentina PETERBON-M R Assistant Director for Export/Import & International Bafeguards 80/03/31 ip
- 8004210369 Requests Executive Branch position re Self-Powered Lighting revised application for license to export tritium gas to Dominican Republic PETERBON.4 R Assistant Director for Export/Import & International Bafeguards. 80/04/02 ip.
- 80042i0379 Requests Executive Branch position re Transnuclear Inc application for license to export 8NH to Japan PETERSON, N R Assistant Director for Export/Import & International Safeguards 80/04/02 ip.
- 8004210426 Application by Matheson Oas Products for license to export 500 liters deuterium chemically pure (90 g) to Australia + Matheson Oas Products 101-77252 80/04/01 lp.
- 8004210451 Amend 1 to license for NL Industries, Inc. increasing quantity for import to 72 089 kg U. containing up to 42 541 kg U-235 & extending expiration date to 810701 FETERSON, HR Assistant Director for Export/Import & International Safeguards. 80/04/08 2pp

- B004220111 Forwards 800326 license for export of six WL23088 fission counters w/plugs & cables to Japan POCHAL, W F Westinghouse Electric Corp 80/03/26 1p
- --8004220116 License for Westinghouse to export six WL23088 fission counters w/plugs & cables to Japan PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/26 ip
- B004230127 Forwards application by DDE to export matl to Canada & import application to return matl following experimental work W/o export application ELGERT.O J Energy.Dept of B0/03/26 lp
- --B004230133 Application by DOE for license to import SNM upon completion of experimental work in Canada, exported under License XSNM-1671 ELOERT.O J Energy, Dept of 80/03/26 2pp
- 8004240063 Forwards application for license to expurt approx 15 lbs depleted U to West Germany for use as metallurgical samples HOLDEN:T J AAI Corp (subs of United Industrial Corp.) 80/03/24
- --8004240067 Application by AAI Corp for license to export U-238, as depleted U.to West Germany HOLDEN,T J AAI Corp (subs of United Industrial Corp) 80/03/24 to
- 8004240130 Notifies of Commission approval of Nissho-Iwal American Corpapplication for license to export 42 kg U.enriched to 93 3%, to Japan Requests detailed description of transportation method & physical security for transit CHILK.S J. Office of the Secretary of the Commission 80/04/02 to
- BOO4240224 Requests Executive Branch position re Halprin Supply Co application for license to export 250 mCi tritium, contained in two static electricity detection meters, to Egypt PETERSON, M R Assistant Director for Export/Import & International Bafeguards 80/04/07 ip
- B004250007 Ltr of assurance re Univ of Helsinki application for license to export 3 g 5td Ref Matl (SRM) 500 & 1 g each of BRM-015, BRM-020.SRM-030 & BRM-050.to Finland MAKIPENTTI.1 Finland 80/04/07 ip
- 8004250028 Notifies that NRC has not completed licensing action on application to export deplated U to France for enrichment Final NRC action delayed pending Executive Branch clarification
 SNEALUR Office of International Programs 80/04/10 ip
- 8004250039 Waives customary i5-day waiting period for issuance of license for Bandvik Special Metals Corp to export 2,350 pieces Zirconium 2 9% niobium seamless tubing to Canada PETERSONM R Assistant Director for Export/Import & International Bafeguards 80/03/24 tp
- --B004250042 License for Sandvik Special Metals Corp to export 2,350 pieces Zirconium 2,5% niobium seamless tubing to Canada PETERSON,M R Assistant Director for Export/Import & International Bafeguards B0/03/24 ip
- 8004280045 Forwards revised 790804 application for license to export tritium gas to Dominican Republic HARPER.R.G Self-Powered Lighting. Ltd 80/03/18 ip.
- --8004280053 Amended application by Self-Powered Lighting Ltd for license to export tritium gas to Dominican Republic. Amend reduces tritium to 250,000 Ci & changes shipment form to adsorption on finely divided depleted U

 HEGARTY.W Self-Powered Lighting, Ltd 80/03/18 7pp
- 8004280096 Application by Ediow Intl Co for license to export 40 mg Cf-252 as cermet wire to Great Britain HARMON, D H Ediow International Co. TRC-4 80/03/21 3pp
- BOO4300010 Discusses NRC findings re proposed license for Univ of WA to import 10 mg PU-238, greater than 10% by weight, from France Importation will not be inimical to common defense & security

 MOORE, R N Office of International Programs 80/04/10 ip
- --B004300016 License for Univ of WA to import 10 mg Pu-23B, greater than BOX by weight from France PETERBON, M R Office of International Programs B0/04/10 ip.

8004300454 Application by Sigma Chemical Co for license to export compounds containing deuterium to Belgium STERN.W C Sigma Chemical Co (subs of Sigma-Aldrich Corp.) D-42 BO/04/09 ip

8004300458 Application by Westinghouse for license to export three units ML23770 proportional counters to West Germany PDCHAL, W.F. Westinghouse Electric Corp. ZE-10214-1 80/04/08 19

BO04300459 Application by Westinghouse for license to export two units, ML6937A uncompensated ionization chamber, to The Netherlands POCHAL, W.F. Nestinghouse Electric Corp. ZE-10303 B0/04/11 1p

		1
		-
		•

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

	ACCEBBION	SUBJECT	
AUTHOR	NUMBER	CATEGORY	AUTHOR
AAMODT, M H	8004100136	50-269 G	AHEARNE, J F
A M TGOMAA	8004100142*	50~287 G	AHEARNE J F
AAMODT, N O	8004100145*	50-289 G	AHEARNE, J F
AAHODT,N O	8004100150# 8004100156#	50-289 G 50-289 G	AHEARNE, J F AHEARNE, J F
		30-207 W	THE PROPERTY
AAMODT,N O	8004010064 8004010072*	50-289 G 50-289 G	AHEARNE, J F AHEARNE, J F
AAMODT, N O	E004010085*	50-287 O	AHEARNE, J F
AAHODT, H M	8004010070*	50-289 G	AHEARNE J F
AAMODT, M. M.	8004010076*	50-289 0	AHEARNE J F
AAMODT, M M	8004010078*	50-289 G	AHEARNE, J F
AAMODT, M M	8004010082*	50-289 Q	AHEARNE, J F
AAHODT, M M	8004010089*	50-289 0	AHEARNE J F
AAMODT, H M	8004010093#	50-207 0	AHEARNE, J. F.
AAMODT, N O	8004290043	50-287 Q	AHEARNE, J F
A H T T T T T T T T T T T T T T T T T T	8004250075* 8004250081*	50-287 0 50-287 0	AHEARNE, J. F.
ABERCROMBLE: H L	8004240411	50-259 R	AHEARNE, J F AHEARNE, J F
ABUAF N	8004280038	RES	AHEARNE J F
ACKERMAN, N	8004300612	50-320 T	AHEARNE J F
ACCISTA: A	8004180003	ACRE	AHEARNE, J F
ACOSTA, A P	8004070262	40-8584	AHEARN, C D
ADAMB, J. E	7708150544*	50-358 H	AHEARN, C D
ADAMSON, R W	8004220601	50-384 P	AHEARNE, J F
ADAMS, W E	8004080434	50-255 R	AHEARNE, J F
ADKIBBION, L F	8004290458*	50-390 A	AHEARNE, J F
ADLER, T A ADLER, T. A	8004040229 8004040229	50-287 G	AHEARNE, J. F
ADLER, T A	9004030170	50-289 Q 50-289 Q	AHEARNE, J F AHEARNE, J F
ADLER, T A	B004030170	50-287 Q	AHEARN, C D
ADLER, T A	8004090399	50-207 Q	AMEARN, C D
ADLER, T. A	8004220011	50-289 Q	AHEARNE, J F
ADRAGNA, J. M	8004100547	PROJ	AHEARNE, J F
ADRAGNA, J M	8004080445	PROJ	AHEARNE, J F
AERNI, B L.,	8004080050	XPORTL1C	AHEARNE, J F
AGRAHAL, A K	8004080290	RES	AHEARNE J F
AGRAMELIA K AHEARNEJJF,	8004100590 8004100509	RES	AHEARNE, J F AHEARNE, J F
AHEARNE, J. F	8004100538	COMMISSION 70-143	AHEARNE J F
AHEARNE, J F.	B004070127	50-244 U	AHEARNE, J F.
AHEARNE, J. F	8004080268	COMMISSION	AHEARNE, J F.
AHEARNE, J F	8004140448	70-143	AHEARNE, J F.
AHEARN, C D	8004080638	50-445 M	AHEARNE, J F
AHEARN, C D	8004080638	50-445 M	AHEARNE, J F
AHEARNE, J. F	8004080243	COMMISSION	AHEARNE, J F
AHEARNE, J. F AHEARNE, J. F	8004080223	COMMISSION	AHEARNE, J. F
AHEARNE, J.F	8004080227* 8004080229*	COMMISSION COMMISSION	AHEARNE, J F AHEARNE, J F
AHEARNE, J. F	8004080231*	COMMISSION	AHEARN, C D
AHEARNE, J F,	8004080234*	COMMISSION	AHEARN, C D
AHEARN, C, D	9004100514	50-445 M	AHEARN, C. D
AHEARN, C D,	8004100525*	50-445 M	AHEARN, C D
AHEARN, C. D	B004100525*	50-445 M	AHEARNE, J F
AHEARNE, J. F AHEARNE, J. F	8004160024	COMMISSION	AHENOER, L AKER, R E
- commentated (4) I.	8004080037	COMMISSION	DOMINI E

ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATECORY	
8004150137	COMMISSION	ALDEN, W M	B004170230*	50-277	 F
8004150317	COMMISSION	ALDEN, W M	B004240391	50-277	í
8004160186	COMMISSION	ALDRICH, D C	8004150022	NUREG	
B004160190*	COMMISSION	ALDRICH, D C	8004150033	NUREG	
8004160193*	COMMISSION	ALDRICH, D C	80041500/4	NUREO	
8004160196*	COMMISSION	ALLAN, J M	8004140106	I%E	
8004160200*	COMMISSION	ALLAN, JE M	8004220033*	FOIA	
8004160202*	COMMISSION	ALLAN, J M	8004140110	1&E	
8004160203*	COMMISSION	ALLAN, J M	8004220080*	FOIA	
8004160206*	COMMISSION	ALLAN, J M	0004220202*	FOIA	
8004160209*	COMMISSION	ALLAN, J M	8004220236*	FOLA	
8004160212*	COMMISSION	ALLAN, J M	8004230040*	FOLA	
8004160215*	COMMISSION	ALLAN, J M	8004230023#	FOIA	
8004160220*	COMMISSION	ALLAN, J, M	8004030312#	FOIA	
8004080268	40-1341	ALLAN. J M	8004220370*	FOIA	
8004080300*	40-1341	ALLAN, J M	8004220380*	FUIA	
8004080305*	40-1341	ALLEN, J E	8004150102*	71-273	
8004080307*	40-1341	ALLEN, J E	8004150108*	71-273	
8004080091	COMMISSION	AL-THAN, N	8004020049	70-135	
8004080108*	۲,				

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHÜR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	TOPUBUE YRODATAS
ANDOGNIN1.6 C ANDOGNIN1.6 C ANDRESEN.8 R ANG.W P ANG.W P	8004240357 8004290424 8004220612* 8004020043* 8004230026*	50~293	BALLENTINE, M BALLENTINE, M M LANTINE, J M M LANTINE, J M BALLENTINE, J M BALLENTINE, J M	8004030245 8004030233 8004030222 8004150418 8004150402	50-327 S 50-327 S 50-327 S 50-327 S 50-327 S	BAXYER,T A BAXTER,T A BAYNARD,P Y BAYNE,J P BAYNE,J P	8004080705 8004230090 8004240467 8004080632 8004210061*	50-312 0 50-312 0 50-302 P 50-284 0 50-284 0
ANSHUTZ, T L	8004030010	50-275 H	BALLENTINE, J M	8004150408	50-327 S	P LAYVE, J P	8004220787	50~244 0
ANSON, W B	8004110303	50-275 H	BALLENTINE, J M	8004180391	50-327 R	BAYNE, J P	8004030267	50~284 0
ANSON, W B	8004240545*	50-275 G	BALLINGER, P L	8004280579±	50-298 S	P LAYVE, J P	8004110437	50~284 8
APFELBAUN, A	8004110117	XPDRTLIC	BALLINGER, P L	8004090304*	50-298 R	BAYNE, J P	8004140416	50~284 8
ARANOV, R	8004250064	70-2909	BALDUOH, R C	8004100535	50-445 M	P LAYVE	8004180448	50~286 8
ARNOLD, R C ARNOLD, R C ARNOLD, R C ARNOLD, R C ARNOLD, R C	8004220373 8004070420* 8004150478 8004170048 8004250340	50-320	BANNER,A P BARBER,R W BARDES,C R BARI,R A BARI,R A	8004290197 8004240559 7902080199 8004100258 8004110521	50-027 h Nureg Misc Res Res	Bayne, J P Bayne, J P Bebas, P G Bechhüefer, C E	8004180426 8004220741 8004080283 8004070200 8004020146	50-286 N 50-286 B RES 50-3 H 50-387 T
ARMURIUS.O	8004080169	50-367 0	BARIIR A	8004100507	RES	BECHNOEFER, C	8004080685	50-287 0
ARP, D	8004030314	F01A	BARWER: 8 E	8004280035	NUREO	BECHNOEFER, C	8004080592	50-358 0
ARTMAN, K L	8004140006	70-364	BARWER: J L	8004100432*	50-10 0	BECHNOEFER, C	8004210091	50-409 0
ARTMAN, K L	8004180034	70-364	BARWER: J L	8004030110	50-249 8	BECHNOEFER, C	8004230111	50-387 0
ASH, R F	8004220782	50-317 P	BARWER: D Q	8004010377	50-498 A	BECHOEFER, C	8004020087	50-387 T
ASHER, T R	8004080689	50-574	BARLETT, J	8004090239	50-220 q	BECKER, J M	8004030324*	FOIA
ASHTON, A M	8004040120*		BARLETT, J	8004250419	50-410 A	BECKMAN, D A	8004280079*	90-334 P
ASHELL, D L	8004010343		BARNARD, J	8004090072#	qa999	BECKMAN, D A	8004040177*	50-334 G
ASHELL, D L	8004070308		BARNARD, J	8004300107#	qa999	BECKMAN, D A	8004170309*	50-334 G
ASHELL, D L	8004150420		JARNYRAB	8004090059#	qa999	BEDROBIAN, T	8004080459	PR
ASHELL, D.L.	8004250347	50-382 8	DARNARD, J	8004300092*	0A797	BEERB,R H	8004230528*	CONTRACT
ASHELL, D.L.	8004280576	50-382 8	BARNES, I,	8004290212*	0A797	BEERB,F C	8004150370*	50~309 H
ASHELL, D.L.	8004250365	50-382 I	BARNES, I	8004140043*	0A797	BEERB,F C	8004150361*	50~271 H
ATHOOD, C.L.	8004100328	RÉS	BARNES, I	8004290031*	0A997	BEERB,F C	8004150352*	50~29 H
AUSTIN, M.A.	8004210081	70-135	BARNES, B	8004140236	50—338 F	BEILENBON,A C	8004080164*	50~142 U
Austin M A	8004070388*	70-354	BARRETT.P A BARRETT.P A BARRETT.P A BARRETT.L BARRY,D,N	8004040052*	50-341 &	BELCHER, R	7908020447	50~144 H
Austin M A	8004290105	70-364		8004080190*	50-373 Q	BELEW	8004290404*	50~327 0
Austin M A	8004210084*	,70-135		8004040048	50-341 B	BELTBLE, G A	8004210113*	50~302 0
Austin M A	8004210207*	70-135		8004180420	TOPREP	BELKE, W L	7910050109	M18C
Austin M A	8004180099	70-354		8004090208	PROJ	BENAROYA, V	8004020439	REGOD
AUSTIN H A AUSTIN H A AUSTIN H A AUTIO H A AVEL A P	8004180533 8004180026 8004290061 8004080489 8004180264*	70-364 70-135 70-135 50-29 8 50-953 A	BARTAL.L J BARTAL.L J BARTH.C A BARTH.C A BARTH.C A	8004070208 8004070276# 8004070182 8004180111 8004210445	PROJ 50-317 R 50-358 G 50-358 G 50-358 G	BENDA, B J BENDER, M. BENGELSDORF, H BENJAMIN, A S	8004030002 8004080628* 8004180207* 8004180200 8004180028	NUREQ XPORTLIC XPORTLIC NUREQ
AVER, A A	8004020276#	40-2061	BARTLETT, J	8004300279	PR	BENNETT, O L	7902040387	M180
AXELRAD, M	8004140131#	FOIA	BARTLETT, J	8004300270#	50-410 0	BENNETT, O L	7902140361	M180
AXELRAD, M	&004020225	50-344 0	BARTLETT, J	8004070269	50-220 F	BENNETT, C L	7904010332	M180
AXELRAD, M	8004020225	50-344 0	BARTLETT, J	8004210407	50-220 P	BENNETT, C L	8004070373*	50-367 H
AXT, J C	8004220625#	FOIA	BARTLETT, J	8004180345	50-220 F	BENTON, C T	8004170229*	50-327 F
AYRES, S T	8004090005	50~272 G	BARTLETT.J	8004220501*	50-220 P	Bentben, L	B004240428	50-445 #
AYRES, S T	8004090008*	50~272 G	BARTLETT.J	8004280394	30-410 H	Berkbigler, K.P	B004100319	NUREO
BABCOCK, S L	8004160030*	COMMISSION	BARTLETT.J	8004280440	50-220 H	Berkon, H. N	7903200103	MISC
BACA, T E	8004180298*	GOMMISSION	DARTLETT.J Q	8004290363	50-220 H	Bernan, M	B004070413	RES
BACON, J L	8004140391	50~329 K	BARTON.R D	8004250022*	CONTRACT	Bernstein, D. L	B004220008	50-320 0
BADER, S BADRAN, S BAER, R BAER, R BAER, R BAER, R	8004140429* 8004210288* 8004020441 8004020446 8004020451	50~237 B 50~249 B 50~352 A 50~414 A 50~354 A	Daekin, K. P Daekin, K. P Daekin, K. P Daekin, K. P Daekin, K. P	B004300071* B004220503 B004220634 B004300375 B004230494	50-387 Q 50-206 P 50-206 P 50-361 D 50-206 P	BERNSTEIN, D L GERNSTEIN, D L GERNSTEIN, D L BERNSTEIN, D L BERNSTEIN, D L	6004220008 6004220102 6004220405 6004220402 6004220403	20~320 G 20~320 G 20~320 G 20~320 G
BAER,R L BAER,R L BAER,R L BAER,R L	8004080723 8004140123 8004110028 8004300468 8004280072	50-553 A 50-369 A 50-361 A 50-395 A 50-369 A	Baskin, k p Haskin, k p Haskin, k p Haskin, k p	8004290640 8004300011 8004300363 8004240394 8004220633*	50-361 A 50-361 A 50-206 F 50-206 P FOIA	BERNBTEIN.D L BERNBTEIN.D L BESECKER.K H BEVAN.R BEVEL.K A	8004210085 8004210085 8004110566* 8004100313 8004220418	50-320 0 50-320 0 50-323 P 50-320 11
L	8004280076 8004280084 8004280038 8004250005 8004300142	50-369 A 50-416 A 50-389 A TOPREP 50-369 A	DASSIN.N BASSIN.N BASSIN.N BASSIN.N BASSIN.W H.	8004040492* 8004040446* 8004040446* 8004070332 8004100168*	F01A F01A 40-8760 50-320 R 50-354 q	BEYEA, J BHATIA, P BICKWIT, L BIDDLE, C T BIDDLE, C T	8004100127* 8004100265 8004290171 8004020232 8004020232	50-3 F 50-317 G 50-327 A 50-466 G 50-466 G
	0024*	50-272 0	Bateman, W	8004210359*	70-143	BIDDLE.C T	8004100274	50~498 Q
	0191*	70-33	Bates, A K	7907170211	30-443 H	BIDDLE.C T	8004100274	50~498 Q
	0216*	50-247 0	Bates, A	8004040271	ACRB	BIDDLE.C T	8004140415	50~466 Q
	0446*	50-344 R	Bates, A, L	8004020426	HISC	BIDDLE.C.T	8004140415	50~466 Q
	0509	CDNTRACT	Bates, A L	8004080102	MISC	BIDDLE.C T	8004080687	50~466 Q
Baker, k r Baker, r o Baker, b Baker, r Baldwin, J m	8004080594* 8004040004* 8004230024 8004080332 8004110169	50-155	BATCG.R W BAUER.E R BAUER.E R BAUER.E.R BAUER.E G	8004280530# 8004010448# 8004010383# 8004010388# 8004170252#	50-336 8 50-318 8 50-318 8 50-318 8 50-277 P	BIDDLE, C T BIDDLE, C T BIDDLE, C T BIDDLE, C T	8004080687 8004100557 8004100587 8004230022 8004230022	50-466 Q 50-466 Q 50-466 Q 50-466 Q 50-466 Q
BALLARD, R C	8004230074#	50~445 M	Bauer, R	8004270479*	50-317	Bidoleig T.	6004240538	50-466 0
BALL, A C	8004220560#	50~111 R	Bauh, e a	8004010269		Bierij.	6004070137*	50-155 H
BALL, A C	800422056#	50~111 R	Bauh, e a	8004140238		Bierbaum.g a	6004080487*	50-193 8
BALL, B U	8004280024	NUREQ	Bauh, e. a	8004250387		Bierman.e r	6004040028	RES
BALLARD, R L	8004030149	50~416 A	Bauman, r e	8004080280*		Bigiareuli.m j	6004180440*	50-245 B
BALLARD, R L	8004020205	50-382 A	Baunack, M	8004160144*	30-273 G	Bigiarelli, m J	8004270303*	50-245 B
BALLARD, R L	8004210048	50-29 H	Baunack, M	8004040411*	50-273 G	Bimal, b,	8004040067*	50-344 T
BALLARD, R L	8004130075	50-466 D	Baunack, M	8004090128*	50-213 G	Birkel, r a	8004150081	50-369 A
GALLARD, R L	8004280114*	50-514 D	Baunack, M	8004180320*	50-320 G	Bibek, d g	8004150117*	71-367
BALLARD, R L	8004280112	50-514 D	Baunack, M	8004280147*	50-272 G	Bibhop, c J	8004020231*	50-389 C

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGORY	
BISHOP.C J BISHOP.C J BISHOP.M BISHOP.C J	8004020282* 8004150168 8004070145 8004070100 8004030076	50-387	BORDENICK, B M	8004080437 8004070370 8004070376 8004230051 8004150243	50-514 0 50-320 0 50-320 0 50-322 0 50-314 0	BREY, H L BRICKLEY, R H BRIDGES, G BRIGGS, L BRIGGS, L	8004010450 8004220244* 8004210305* 8004090262* 8004090422*	50-267 50-445 50-10 50-219 50-219	P Q H Q
BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.C J	8004090450 8004080562 8004090123 8004230162* 8004080574	50-466 G 50-556 G 50-445 M 50-445 M 50-320 G	BORDENICK, B M BORDENICK, B M BOREIKO, T BOREN, D L BORES, R J	8004150312 8004250378 8004020489 8004140485* 8004070112*	50-516 0 50-322 0 50-327 0 MISC 70-1100	GRIGGS, T DRIGHT, R M GRIGHT, R M GRIGHT, R M DRIGHT, R M	8004210450* 8004040010 8004100365 8004210111 8004080374	50~302	0 0 P 0 P
BISHOP,C J BISHOP,R W BISHOP,C J BISHOP,C J	8004100253 8004080272 8004150320 8004100240 8004240541	80-272 G 50-213 I 50-245 I 50-445 M 80-275 Q	BORES, R J BORES, R J BOROMANN, E A BOROMANN, E A BOROMANN, E A	8004080352* 8004300328* 8004300604* 8004160007 8004040340	50-317	BRIGHT, R M BRIGHT, R M BRIGHT, R M BRIGHT, R M BRIGHT, R M	8004080613 8004210238 8004280351 8004180239 8004180462	50-302 50-302	P R P P
BISHOP,C J BISHOP,C J BISHETT.P H BIXEL.D A BIXEL.D A	8004210141 8004230098 8004080599* 8004100480* 8004100469*	50-445 M 50-275 G 70-364 50-155 G 50-155 O	BORGMANN.E A BORST.L BOSSER.M A BOSTIAN.R W BOUKNICHT.J A	8004280317 8004210022* 8004280337* 8004100558 8004080273	50-358 F FOIA 50-320 H 70-2423 50-445 M	BRIGHT.R M BRIGHT.R M BRIGHT.R M BRINKMAN.T J BRINKLER.J E	8004220526 8004280567 8004300331 8004010520 8004180472*	50-302 50-302 50-322	Q P Q G S
BLACK,R L BLACK,R L BLACK,R L, BLACK,R L BLAKE,E L	8004020468 8004100487 8004110142 8004140482 8004020202	50-522	А С.ТНОІИЖИОВ А С.ТНОІИЖИОВ А С.ТНОІИЖИОВ А С.ТНОІИЖИОВ	8004020113 8004020119* 8004020119* 8004170312 8004170312	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	BRINKLER.J E BRIBTOL,M BROADUB.C R BROCKETT.T W BROEHL,D J	8004210278* 8004070193 8004240565 8004080578 8004040065*	50-3B7 Nureg I&E	ន អ ក
BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L	8004020202 8004100547 8004100566 8004110561 8004110567*	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0	A C,THOINXUOB A C,THOINXUOB A AINXUOB A AINXUOB A AINXUOB	8004230154 8004230154 8004240061 8004020413 8004280051	50-445 M 50-445 M 50-445 M 50-373 F 90-373 A	BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J	8004040073# 8004010334 8004020409 8004280296 8004080504	50~344 50~344 50~344	T P P P
BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L	8004100549 8004100566 8004110567* 8004140004 8004140004	50-287 G 50-287 G 50-289 G 50-289 G 50-289 G	BOWERB, C E BOWERB, C E BOWERB, C E BOWERB, J BOWERB, J	8004230533 8004240160 8004220177 8004030322 8004100563	70-820 70-820 70-820 50-287 0 50-287 0	BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J BROOKS, E H	8004180466 8004220698 8004200380 8004200387 8004020263*	50-344 50-344 50-344	P P Q Q
BLANCHARD, W H BLOCK, B BLUMBERG, N DLUMBERG, N J BLUME, M	8004140095# 8004300204 8004160144# 8004280147# 8004020198#	M180 NUREG 90-293 Q 50-272 Q 50-445 M	BOWERS, J BOWERS, J BOWERS, E BOWERS, E BOWERS, E BOWERS, E	8004100565* 8004100567* 8004110075 8004080597 8004150092	50-287 Q ' 50-287 Q 50-287 Q 50-514 Q 50-514 Q	BRODKS, E H BROSS, I D BROUDE, M BROWER, G W BROWN, B H	8004100202* 8004040320 8004270083* 8004020144* 8004080148*	50-320	0 Н Н
BLUME, M B BLUME, M B BLUME, M B, BLUME, M B BLUME, M, B,	8004030347 8004010262 8004080420 8004100126 8004270227	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	BOWERS, E 8 BOWYER, J E BOWYER, J E BOYYER, B 6	8004210128 8004040155 8004220579* 8004220557* 8004280379*	50-250 G 50-322 H FOIA FOIA 50-10 H	BROWN, J BROWN, S BROWN, O D BROWN, G, D BROWN, R A	8004140358* 8004100025 8004300081* 8004300068* 8004160172*	NUREO 40-4492 40-4492	A G
BOATWRIGHT, N C	8004220562* 8004220448* 8004220458* 8004220461* 8004220548*	FOIA FOIA FOIA FOIA FOIA	BOYD, D C BOYD, D C BOYD, D C BOYD, D C	B004040444* B004040297* B004100290* B004070427 B004070192	50-315 0 50-315 0 50-282 0 50-315 8 50-315 8	BROWN, R A BROWN, R A BROWN, R A BROWN, R A BROWN, R A	8004210035* 8004210120* 8004280310* 8004040074* 8004040453*	50-293	G G G
BOATWRIGHT, N. C BOCCIO, J BODMER, M BODTKE, P J BOE, E	8004220463* 8004220874 8004220037* 8004080438* 8004100491*	FOIA REVIEW ORP 50-316 P 50-255 R MIBC	BOYD, D C BOYD, D C BOYER, V S BOYNS, P K	8004070030 8004040059 8004280641 8004080543 8004030308*	50-315 S 50-315 B 50-275 S 50-277 P FOIA	BROWN, R A BROWN, R A BROWN, R L BROWN, R L BROWN, R A	8004040035* 8004040399* 8004020434* 8004100034* 8004080147*	50-255 50-315 0A999 0A999 27-47	<u>a</u>
BDODEN, G BOODEN, O BOODEN, O BOODEN, O, BOHN, R. J	8004090064 8004090250 8004090255 8004080606 8004080331	40-1162 40-1162 40-1162 40-1162 50-367 R	BRADELY,R D BRADFORD,W BRADFORD,P A BRADFORD,P A BRADFORD,U H	8004090084* 8004300187* 8004180294* 8004080053* 8004280143*	50-400 0 50-302 0 50-247 E 50-309 P 50-348 0	Brown, O D Brown, O D Brown, R A Brown, R A Brown, O D	8004040104* 8004300059* 8004100528* 8004040171* 8004040100		a G
BOHN, R J BOHN, R J BOHN, R J BOHN, R J BOLT, B. A	8004150453 8004220553 8004280494 8004300431 8004170257*	50-367 R 50-367 R 30-367 R 50-367 R 50-70 P	BRADLEY,E R BRADLEY,J P BRADLEY,R D BRADLEY,E J BRADLEY,E J	8004210278 8004030361 8004070331* 8004140317 8004150246	NUREG PR 50-400 Q 50-352 I 50-277 I	BROWNEE, V L BROWN, G D BROWN, H H BROWN, G D BROWN, G, D,	6004220221* 6004250277* 8004070033 8004250273 8004300043	50~313 50~275	0 0 0
BDNNEVILLE,R B BONZON,L L. BONZON,L L BOOK,H E BOOK,H E	8004210118 8004240464 8004240505 8004100056* 8004100053	PR NUREO 50-294 P 70-25 70-25	BRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, E J	8004150267 8004150470 8004170246 8004170252* 8004100582*	50-171 I 50-277 I 50-277 P 50-277 P 50-320 H	BROWN, 8 C BROWN, 8 C BROWN, 0 F BROWN, 0 F, BROWN, M S	8004010465 8004020157 8004210353 8004210361* 8004230432*	50-404 PR PR	G R B
BODK, H, E BOOK, H, E BOOK, H E BOOK, H E BOOK, H E	8004030247* 8004210248* 8004040055* 8004210241* 8004040054	50-278 0 50-312 0 50-312 0 50-312 0 50-312 0	BRAMLETT, L, S BRAMLETT, L, S BRAMLETT, L, S BRAMLETT, L, S BRAMLETT, L, S	8004140333* 8004150641* 8004140360* 8004150547* 8004210220*	50-313 8 50-313 8 50-313 8 50-313 8 50-313 R	BROWN, B C BROWN, B C BROWN, B C BROWN, B C BROWN, B C	8004220641 8004220234 8004220399 8004220611 8004300415	50-404 50-338	P A Q & Q
800K, H. E 800K, H. E 800K, H. E. 800K, H. E. 800K, B. A	8004210020* 8004110543 8004110550* 8004210231 8004250047	50-320 Q 50-243 Q 50-243 Q 50-312 Q NUREQ	BRAMLETT, L 8 BRAMLETT, L, 8 BRAMBON, L BRAND, W, E BRANDON, R J	8004230473* 8004270385* 8004300073* 8004280004 8004070476*	50-313 8 50-313 8 50-387 9 50-395 M 50-293 P	BROZ,R E BRUGGER,R M BRUNE,J N BRUNNER,E J BRUNNER,E J	8004100423 8004300505 8004210325* 8004280070* 8004070120*	70-754 70-754 50-275 50-334 50-322	Q P Q
BOOKE, B. L. BOOKE, B. L. BOOKER, M. K. BORCHELT, M. L. BORDENICK, B. M	8004210388* 8004210388* 8004170327 8004230007* 8004070192	40-1162 40-1162 NUREQ 50-445 M 50-320 Q	BRAY,T C BRAYMAN,K W BREED,A BREED,A BRESLER,B	8004220558 8004210307* 8004150280* 8004150270 8004040070*	50-111 R TOPREP TOPREP TOPREP 50-344 T	BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8004160137* 8004070247* 8004040168* 8004040407 8004090131	50-293 50-219 50-334 50-293 50-213	0 0 0 0

	ACCESSION	SUBJECT	AUTHÔR	ACCESSION NUMBER	TOGUEUE CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR BRUNNER, E J	NUMBER 80041501894 800410007P 8004090417 8004090448 80042100454	50-277 0 50-322 0 50-322 0 50-219 0 50-213 0 50-209 0	BURCHETTE.W H BURCHETTE.W H BURCHETTE, W H GURDETTE, T E BURDETTE, T E	8004090427 8004240061 8004240071* 8004160062*	50-445 M 50-445 M 50-553 0 50-375 0	CALHOUN, J R	8004220753 8004220698 8004220659 8004220659 8004220646 8004220742	50-327 8 50-327 5 50-240 6 50-259 5 50-259 8
BRUMNER, E J BRUNNER, E J BRUMMER, E J BRUMMER, E J BRUMNER, E J	8004210059 8004210146 8004170288 8004210439 80042104145	50-244 0 50-322 d 50-272 0 50-219 0 50-293 0	BURGESS, D BURGIN, R E BURI, R A BURN, P BURNETTE, G W	8004140368 8004020274* 8004080678 6004180076 8004150063	50-320 H 40-2061 RES 50-201 P RES	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8004250396 8004280593 8004290311 8004290435 8004290515	\$0-259
BRUNKER, E J BRUNKER, E J BRUNKER, E J BRUNKER, E J BRUKKER, E J	80042801304 8004180138 8004070114 8004070238 8004180318	50-272 0 50-245 0 50-322 0 50-321 0 50-320 0	BURNETTE.G W BURNS, G G BURNS, D BURNS, G A BURNS, G G	8004170287 7911050375 8004080156 8004080062 8004080067*	RES 1190 30-387 G 50-255 G 50-255 G	CALLANIL J CALLENDINE, G W CAMM, F CAMM, F CAMPBELL, E R	8004100335* 8004220644* 8004070188* 8004030024 8004140398*	50-313
GRUMNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J DRUNNER, E J	8004070469 8004070118 8004160183 8004160125 8004280111	50~293	Burne, 5 0 Burne, 5 0 Burne, 5 0 Burne, 5 0 Bursey, 8	8004080006 8004170258 8004170258* 8004210232 8004070002	50-255 0 50-255 0 50-255 0 50-255 0 FD1A	CAMPDELL, M CANTER, H L CANTER, H L CANTRELL, F S CANTRELL, F S	7909290207* 8004300453* 800410151* 8004100506* 8004040125*	FOIA 50-312 Q 50-312 Q 50-546 Q 50-416 Q
DRYAN, S E BRYAN, S E DRYANT, J C BRYANT, J C BRYANT, J C	8004220214* 8004220593* 8004020029 8004040424* 8004040174	FOIA FOIA 50-395 Q 50-424 Q 50-259 Q	BURSTEIN, S BURSTEIN, S BURNELL, S B BUSCHBACH, T C BUTCHXG, P P	8004010223 8004270428 8004070053 8004230307* 80043300054*	50-266	CANTRELL, F S	8004070409 8004230046# 8004160062# 8004160072# 6004210121#	50~518
GRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8004100481 8004070158* 8004040084 8004040203 8004040201	50-586 0 50-438 0 50-416 0 50-586 0 50-416 0	CADWELL, J J CADMAN, T W CADMECL, J J GADWELL, J J	7902040388* 8004070108 8004020050 8004300032 8004340460	M15C 50-556 0 50-166 H RES RES	CANTRELL: C E CAPHION, D L CAPRA, R A CAPRA, R A CARFAGNO, S P	8004150615# 8004210151# 800425036B 8004180490 8004070042#	50-327 P 50-322 Q 50-269 P 50-269 P 50-271 P
BRYANT, J C	800407007t* 8004070384 8004070388 8004100045 8004020188*	50-400 0 50-518 0 50-438 0 50-416 0 50-424 0	CADMELL, J J CAHILL, W J CAHILL, W J CAHILL, W J	8004150021 8004180389 8004080256 8004300009* 8004080410	RES 50-247 P 30-247 G 50-387 G 50-247 P	CARFAGND S P CARLEGN R T CARLEGN R T CARLEGN R T CARLEGN R T	8004080494 7812110287 8004070109* 8004070223* 8004230079*	50-254 Q 50-387 Q 50-443 Q 50-245 Q 50-352 Q
BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	2004090284 2004090351 2004090346 2004230009 2004230036	50-348	CAHILL, H J CAHILL, H J CAHILL, H J CAHILL, H J CAHILL, H J	8004080417 8004210255 8004220589 8004220627 8004240410	50-247 P 50-247 R 50-247 F 50-247 P 50-247 P	CARLEDN, R T CARLEDN, R T CARLEDN, R T CARLEDN, J C CARLEDN, R T	8004100158# 8004100103# 8004070385# 8004100303# 8004070375	50-354 Q 50-387 Q 50-387 Q 50-344 Q 50-293 Q
DRYANT. J C DRYANT. J C BRYANT. J C DRYANT. J C DRYANT. J C	8004080122 8004070315* 8004110503 8004110572 8004160057	50-338	Camilly a Camilly a Camilly a Camilly a Camilly a	8904210249 8004300429 8004300307 8004300416 8004300419*	50-3 R 50-247 P 50-247 P 50-247 P 50-247 P	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8004150137 8004070435 8004100079 8004300276* 8004100533	50-352 G 50-352 G 50-410 G 50-482 G
BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8004160066 8004070039* 8004300100* 8004210116 8004210195*	50-327 G 50-400 G 50-546 G 50-566 G 50-267 G	Cahill W J Cain, C L Cain, C L Caldwell, J J Caldwell, R A	8004300411 8004300081* 8004210020* 8004150020 8004070036*	50-247 P 40-4492 50-320 0 RES 50-285 G	CARLEON, R T CARLEON, R T CARLSON, R T CARLSON, R T CARLEON, R T	8004100980 8004090432 8004180329 8004180508 8004070213	50-443 0 50-219 0 50-309 0 50-245 0
BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8004230215 8004280174 8004210242* 8004210247* 8004160118*	50~321	Caldhell.r a Calhoun.f L Calhoun.j r Calhoun.j r Calhoun.j p	8004270011* 790\$190090 8004020366 8004010375 8004010399	50~298	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, J P	8004090127 8004070102 8004090314 8004210003 8004210194*	50~482 5 50~443 6 50~355 8 50~423 6 50~243 0
BRYANT, J C BRYAN, J K BRYANT, J C BRYANT, J C BRYAN, J K	8004300484* 8004110327* 8004280079 8004240430* 8004030208	5D-393 Q 50-483 Q 50-241 Q 50-491 Q 50-483 B	CALHOUN, J R CALHOUN, J R CALHOUN, J R GALHOUN, J P CALHOUN, J R	8004010360 8004010393 8004010433 8004010451 8004010460	50~327 8 50~296 8 50~327 8 50~259 8 50~260 8	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8004079379 8004109039 8004080109 8004100152 8004100606	50-387 G 50-443 G 50-354 8 50-354 G 50-423 8
BRYAN, J. K BUCHANAN, C. R BUCHANAN, C. R BUCHANAN, J. P BUCHHOLZ, R. H	8004040362 8004220517* 8004220512* 8004180337* 8004080655*	F0)1A 50-390 R	CALHOUN, J. R. GALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R.	8004010444 8004010487 8004010502 8004070288 8004070418	50~327 8 50~259 8 50~327 8 50~260 8 50~327 8	CARLBON, R T GARLBON, R T CARLBON, R T CARLBON, R T GARLBON, J D	6004100611 6004100074 6004300602 6004230057 6004280277*	50-311 8 50-387 9 50-293 9 50-352 9 50-397 9
BUCHHOLZ, R H	8004070316 8004020254 8004150353 8004280504 8004270468	TOPREP TOPREP TOPREP TOPREP TOPREP	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8004080519 8004080616 8004090333 8004090429 8004090453	50-327 6 50-327 5 50-327 6 50-327 5 50-327 8	CARLBON,R T CARLBON,R T CARNEY,J A CARNEY,J A. CARR,H	8004280171 8004300282 8004070387 8004070387 8004140417	50-354 S 50-410 0 50-445 M 50-445 M PR
BUCHOLZ: R H BUCKLEY: B C BUCKS: N BUDNITZ: R, J	8004220497 8004240505 8004140014 8004020048 8004080215	TOPREP 50-276 P 50-275 A 40-1341 REB	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8004;50515 8004;80460 8004;40428 8004;40433 8004;50528	50-240 8 50-327 8 50-327 8 50-240 5 50-327 8	CARRIB E CARRIER, M J CARRICKI J CARRIER, W B CARROLL, D E	8004070100* 8004070136 8004010227 8004170282 8004100089	70-2786 50-294 P 70-2909 URQ
BUDNITZ,R J BUHL,T BUHL,T BUHL,T BUHL,T	8004300601 8004170221 8004070240 8004020182 8004040457		CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8004150539 8004150573 8004180399 8004180451 8004180452	50-327 8 50-259 8 50-327 8 50-260 6 50-296 8	CARROLL, D. E CARROLL, D. E CARROLL, D. E CARROLL, D. E CARROLL, D. E	8004100086 8004100088 8004150146 8004150150 8004080869	DR0 50-10 G 50-10 G DR0 90-10 G
BULISCHECK, T BULLOCK, J B BURCHETTE, W, H BURCHETTE, W H BURCHETTE, W H	8004080094 8004110466 8004080018 8004080019 8004090427		CALMOUN, J R GALMOUN, J R GALMOUN, J R CALMOUN, J R GALMOUN, J R	8004150525 8004150500 8004150523 8004150554 8004220715	\$0-259 S \$0-327 S \$0-259 S \$0-327 S \$0-327 S	CARROLL, D E. CARROLL, D E CARROLL, D E CARROLL, D E CARROLL, D E	8004080572 8004180385 8004220410 8004230304 8004230308	ORG 50-10 0 ORG 50-10 0 ORG

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
CARROLL, D E	8004220154 8004220161 8004220179 8004220203 8004270416*	ORG 50-10 Q 50-10 Q ORG 50-318 8	CHESKO,R C CHESTER,R D CHESTER,R D CHIANGI,N J CHIANGI,N J	8004220666* 8004040369 8004160095 8004170047 8004170053	50-346 S RES RES 50-400 A 50-400 S	CLAYTON, F L	8004080029* 8004110003 8004010507 8004010425 8004030212	50-348 Q 50-348 Q 50-348 S 50-348 P 50-348 R
CARSON, Ø B CARTER, R B CARTER, R B CARTER, K W CARTER, K W	8004080090* 8004090194* 8004100007* 8004100539 8004140074	50-150 I 50-164 Q 50-164 Q 50-289 G 50-289 G	CHILDS.W V CHILDS.W V CHILDS.W V CHILDS.W V	8004030278* 8004030218* 8004090440* 6004220771* 8004280559*	50-333 S 50-333 S 50-333 S 50-333 S 50-333 S	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8004080403 8004030192 8004070267 8004080492 8004080657	50-348 P 50-348 P 50-348 F 50-348 R 50-348 P
CARTER, K W CARTWRIGHT, J E	8004140077* 8004140080* 8004140084* 8004210453 8004280030	50-289	CHILK'S A CHILES'F CHILK'S A CHILK'S A	8004270511+ 8004270482+ 8004070165 8004040268 8004100388	50-333	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8004080651 8004080540 8004160242 8004100330 8004150447	50-348 P 50-348 S 50-364 S 50-364 A 50-348 P
CARTWRIGHT, W R	8004010905* 8004030221* 8004030226* 8004080336* 8004030238*	50-338 S 50-338 S 50-338 S 50-338 S 50-338 R	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8004170355 8004070143 8004080681 8004090206 8004140068	PR 50-556	CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L	8004300594 8004220729 8004150426 8004250401 8004280434	50-348 G 50-348 S 50-348 R 50-364 G 50-348 P
CARTURIGHT, W R	8004070307 8004070309* 8004220646 8004220653* 8004280549	50~338 8 50~338 9 50~338 8 50~338 8 50~338 8	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8004140072* 8004140124* 8004140128* 8004140133*	PRM PRM PRM PRM PRM	CLAYTON, F L CLAYTON, F L CLEMENSON, F CLEMONS, P CLEMONS, P E	80042902B4 8004290367 7905140144 8004280300* 8004070401*	50-348 P 50-348 S MISC 50-273 G 70-364
CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARUSO, R. CARUSO, R	8004280554* 8004280404 8004280408* 8004100161 8004100171	50-33B 9 50-33B 9 50-33B 9 50-213 P 50-245 P	CHILK, B J CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8004140139# 8004140140# 8004140145# 8004150043# 8004100597	PRM PRM PRM 50-272 G XPORTLIC	CLEMONS, P CLEVELAND, J C CLEVELAND, J C CLINE, W E	8004070358# 8004210089# 8004170274 8004280024 8004110129	50-293 Q 70-1143 RES NUREG PR
CABARO, R CASE, E Q CASE, E Q CASEY, S B CASEY, B B	8004140449* 8004070063* 8004230014* 8004080228 8004090188	50-456 A 50-281 G 50-266 G PR PR	CHILK:S J CHILK:S J CHILK:B J CHILK:B J CHILK:S J	8004070045 8004080548 8004250011* 8004070454 8004240130	50-443	CLINTON, B CLODFELTER, M COCHRAN, T B COFFIN, J	8004080682 8004020237* 8004270184 8004210352 8004070016	PR State Prog FOIA 70-143 FOIA
CABEY, B. B CAREY, T E CATALAND, G. R CATCHPDLE, G J CATCHPDLE, G J	8004090194* 8004080713 8004080092 8004030001 8004240563	PR FOIA 40-2051 40-0745 40-0745	CHILK,8 J CHILK,8 J CHILK,8 J CHILK,8 J	8004150073 8004210165 8004210168 8004210174 8004210180	50-3 G 50-486 G 50-275 G 50-407 G 50-400 G	COGGIN, C L COGGIN, C L COGGIN, C L COGGIN, C L	8004070324* 8004070283* 8004110474* 8004110483* 8004150481*	50-366 S 50-321 S 50-366 S 50-366 S 50-366 S
CATTON I. CELLIER F CERNE, A C CERNE, A C CERNE, A C	8004080631* 8004180070 8004300307* 8004070441* 8004210011*	ACRB 70-2707 50-410 G 50-443 G 50-423 G	CHILK,8 J CHILK,8 J CHILK,8 J CHILK,8 T	8004280165 8004280178 8004280222 8004240374* 8004240452*	50-443 G 50-400 G 50-320 G 50-250 R 50-250 R	COGGIN, C L COGGIN, C L COGGIN, C L COGGIN, C COHEN, A F	8004150572* 8004220671* 8004280419* 8004280447* 8004150074	50-366 S 50-366 S 50-366 S 50-366 S NUREG
CHAIFETI, D H CHANANIA, F D CHANANIA, F D CHANANIA, F CHANANIA, F	8004270161 8004020149 8004020164# 8004020198# 8004080559	FOIA 50-445 M 50-445 M 50-445 M 50-445 H	CHILSON, V. T CHILSON, V T CHILSON, V T CHILSON, V T CHILSON, V, T	8004240356* 8004240474* 8004240459* 8004240363* 8004240444*	50-250 R 50-250 R 50-250 R 50-250 R 50-250 R	COHEN, I COHEN, I COHEN, W COHEN, W COHN, D B	8004070207# B004100030* B004210104# B004240435 B004010274	70-1100 70-820 70-971 50-309 H 50-367 G
CHANANIA, F D CHANANIA, F D CHANANIA, F D, CHANANIA, F CHANANIA, F	8004030347 8004080172 8004180167* 8004240061 8004150157	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	CHILSON, V T CHILSON, V T CHILSON, V T CHILSON, V T	8004240466* 8004240440* 8004240422* 8004230332* 8004230490*	\$0-250 R 50-250 R 50-250 R 50-250 R 50-250 R	COHN, D B COLEMAN, E G COLEMAN COLEMAN, L R COLL, N A	8004010300* 8004040207 8004090008* 8004210353 8004020265*	50-367 G 50-272 G 50-272 G PR 50-367 G
CHANANIA: F D CHANANIA: F D CHANDLEY: C A CHANDLER: L CHANDRA: V	8004170347 8004270227 8004100294 8004020462 8004290474*	50-445 M 50-445 M PR 50-361 H TOPREP	CHILEON, V T CHILEON, V T CHILEON, V T CHONIN, N	8004230326* 8004180528* 8004180530* 8004180374* 8004080239	50-250 R 50-250 R 50-250 R 50-250 R 50-250 Q	COLLIN A COLLIN A COLLINS, C COLLINS, R E	8004020265* 8004020005 8004170330 8004140197* 8004040140*	50-387 9 50-387 0 50-250 0 50-10 U 50-247 9
CHANDRABEKARAN CHANDLER, L. J CHANDLER, L. J, CHAPLIN, 8 D CHAPLIN, 8 D	8004140340* 8004070465 8004150226 8004040344* 8004040347*	50-10 R 50-320 0 50-320 0 50-320 6 50-320 8	CHONIN, N CHONIN, N CHRIBTA-MARIA CHRIBTOFFER, O CHRIBBOTIMOB, N	8004080239 8004240086 8004140031* 8004040047* 8004080625*	50-250	COLLINS, J T COLLINS, J T COLLINS, J T COLLINS, J T	6004170336 6004070103 6004100579 8004080121 8004020072	NUREQ 50-320 S 50-320 P 50-320 P 50-320 S
CHAPLIN, S D CHAPLIN, S D CHAPMAN, K. R CHAPMAN, L CHAPMAN, L. D	8004140377* 8004250389* 8004220551* 8004150078 8004150044	50-320 B 50-320 B FOIA NUREQ RES	CHRISTOFFER, G CHRISTMAN, J IX CHRISSOTIMOS, N CHRISSOTIMOS, N CHRISTMAN, J N	8004080640# 8004080692 8004080573 8004030110 8004250381	50-263	COLLINS.D M COLLINS.J T COLLINS.J T COLLINS.P F COLLINS.J T	8004020067 8004020094 8004020077 8004070048 8004020097	50-287 P 50-320 S 50-320 S 50-334 V 50-320 B
CHAPMAN, L D CHAUDHARY, B CHAWLA, T, C CHECKER, J CHEN, M J	8004300574 8004090438* 8004100591 8004210310* 8004150326	RES 50-352 G NUREG 50-10 H NUREG	CHRISTENBURY, E CHRISTENBURY, E CHRISTNER, R CHUNG, J CHURGH, F	8004080246 8004280037 8004230517 8004160146* 8004080323*	50-358 A 50-202 H 50-334 J 50-293 G СОИМІВВІОН	COLLINS, P F COLLINS, J T COLLINS, J T COLLINS, J T	8004030257 8004100496 8004170344 8004100385 8004100502	50-272 V 50-320 P 50-320 R 50-320 P 50-320 P
CHEN, M J. CHEN, J C CHERN, W. S CHERRY, M. M CHERRY, M M	8004290017 8004040027 8004070145 8004020033 8004080435*	NUREG RES RES 50-454 G 50-454 G	CIESZKIEWICZ, B CLARK, K CLARK, M CLARK, D CLARK, C W	8004150387* 8004220358* 8004080165 8004020353* 8004020267	50-10 R 50-259 P 50-367 H 50-265 S Toprep	COLLING.PF COLLING.PF COLLING.ST COLLING.ST COLLING.JT	8004100420 8004150158 8004250102 8004280230 8004280244	50-287 V 50-273 V 50-320 P 50-320 R 50-320 P
CHERRY, M M CHERRY, M. M. CHERRY, M. M CHERRY, M. M CHERRY, M. M	8004070177 8004020033 8004080429 8004080435* 8004090177	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0	CLARK: 8 CLAUNCH: A CLAY: E L CLAY: E L CLAYTON: F L	8004220596* 8004080650 8004090244* 8004040117* 8004100096	XPORTLIC 70-143	COLLINS, J T COLLINOS, D M COLLINS, J T COLLINS, J, T COLLINS, P F	8004280558 8004140430 8004300273 8004240498 8004280177	50-320 H 50-267 P 50-320 P 50-320 P 50-250 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBS I DN NUMBER	SUBJECT CATEGORY
COLLINS.JT COLLOPY.T J COLOMBO.P COLOMBO.R W COLOMBO.R W	8004300303 8004090154 8004290007 8004070316* 8004160270*	50-320 P 70-371 NUREO 50-312 S 50-312 R	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8004070218* 8004040066 8004100608* 8004090466 8004140129	50-245 Q 50-213 P 50-423 S 50-336 Q 50-245 Q	CREWS, E H CREWS, E H CREWS, E H CRISCIONE, J L CRIBCIONE, J L	8004150548 8004280498 8004220455 8004010429* 8004170199*	50-395 8 50-395 8 50-395 0 50-336 8 50-336 8
COLOMBO.R W COLOMBO.R W COLOMBO.R W COLOMBO.R W	B004140405# B004210262# B004270491# B004270465# B004100051#	50-312 S 50-312 S 50-312 S 50-312 S 50-416 Q	COUNSIL.W O COUNSIL.W O COUNSIL.W O COUNSIL.W O	8004110012 8004100417 8004030261 8004030293 8004210411	50-213 Q 50-334 Q 50-213 Q 50-213 P 50-213 P	CRNICH, J CRNICH, J CRNICH, J CROCKER, H W CROCKER, H W	8004010347* 8004070310* 8004280605* 8004210145* 8004040213*	50-382 8 50-382 8 50-382 8 70-1100 70-82
COLON, J E COMPAS, W J COMPTON, R M CONICH, J CONKLIN, J C	8004240360* 8004080365* 8004080127* 8004250352* 8004280024	50-424 0 QA999 50-338 G 50-382 S NUREG	COUNSIL.W G COUNSIL.W G COUNSIL.W G	8004250132 8004290057 8004030211 8004020345 8004020331	50-213	CROCKER.H W CROCKER.H W CROCKER.H W CROCKER.H W CROCKER.H W	B004280300* 8004070401* 8004100014* 8004210222* 8004070358*	50-293 Q 70-364 50-184 Q 70-135 50-293 Q
CONLON, T E	8004040430* 8004070392* 8004110575* 8004070043* 6004220221*	50-424 0 50-438 0 50-395 0 50-400 0 50-321 0	COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	8004030215 8004040249 8004040304 8004070265 8004040331	50-245 P 50-336 P 50-245 P 50-213 P 50-213 R	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W	8004300244* 8004100234* 8004080282* 8004210089* 8004160098	50-244 Q 50-201 Q 50-333 Q 70-1143 70-1251
CONLON.T E CONNER.D E CONNER.T B CONNER.E L CONNER.T B	B004240434* B004040234* B004080409 B004070138 B004030338	50-491 Q 50-320 H · 50-395 Q 50-336 P 50-358 Q	CONVEIT'M C CONVEIT'M C CONVEIT'M C	8004040205 8004150487 8004030232 8004020408 8004080309	50-245 R 50-213 R 50-336 P 50-213 F 50-336 P	CROCKETT, J CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A	8004180411# 8004180218# 8004140049# 8004160050# 8004220244#	50-336 8 50-498 9 50-498 9 50-445 9 50-445 9
CONNER, T B CONNER, E L CONNELL, C CONNER, T B CONNER, T B	8004030338 8004170318* 8004180434* 8004220156 8004220156	50-358 G 50-317 F 50-286 R 50-358 G 50-358 G	COUNSIL.W C COUNSIL.W C COUNSIL.W C	8004070274 8004110457 8004150297 8004180346 8004140375	50-213 P 50-245 P 50-213 P 50-213 P 50-245 Q	CROSSMAN, W A CROSSMAN, W A CROUSE, R P CROUSE, R P CROUSE, R P	8004300035* 80042500B3* 8004020135 8004090424* 8004040455	50-498 O 50-445 O 50-346 O 50-346 O 50-346 O
CONNOR, W COMMOR, R J CONSTABLE, G L CONTE, R J CONTE, R J	8004070168* 8004230190* 8004040025 6004070103 8004020072	PR 50-3 H 50-298 8 50-320 5 50-320 8	COUNSIL, W C COUNSIL, W C COUNSIL, W C COUNSIL, W C	8004170012 8004180224 8004170012 8004230413 8004230279	50-213 P 50-213 P 50-213 P 50-423 A 50-213 F	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8004100091* 8004010419 8004080514 8004300617 8004180353	50-346 P 50-346 P 50-346 P 50-346 Q 50-346 F
CONTE,R J CONTE,R J CONTI,L L CONTRELL,F S CONWAY,W F	8004020094 8004020077 8004100074 8004080963 8004010256	50-320 8 50-320 8 PR 50-438 9 50-271 P	COUNSIL, W. G COUNSIL, W. G COUNSIL, W. G COUNSIL, W. G	8004220364 8004240373 8004250362 8004250442 8004270651	50-336 P 50-245 P 50-245 P 50-213 P 50-245 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8004220534 8004220457 8004250376 8004280380 8004280456	50-346 P 50-346 P 50-346 P 50-346 I 50-346 F
CONWAY, W F CONWAY, W F COOK, K W COOK, R J	8004080238 8004110190 8004110465 8004210307# 8004040475*	50-271 P 50-271 P 50-271 F TOPREP 50-329 Q	COUNSIL,W O COURCHAINE,R J COWOILL,M O COX.E L	8004280465 8004150531* 8004280036 8004290371* 8004140179	50-213 P 50-315 P 50-574 Q 50-537 A REOGD	CROW, W T CROW, W T CROW, W T CROW, W T CROW, W T	8004150115 8004150118* 8004220018 8004240217* 8004040209	70-1257 70-1257 70-135 50-438 A 70-82
COONEY, M J COONEY, M J COONEY, M J	8004210306# 8004100056# 8004250302 8004070311 8004150560	TOPREP 70-25 71-6144 50-278 S 50-277 S	COX,E L COX,T H CRANDELL,J D CRANE,P A CRANE,P A	8004180532 8004100213 8004030138 8004040131 8004010436	REGGD TOPREP PR 50-275 B 50-275 A	CROW, W T CROW, W T CROW, W T CROW, W T CROW, W T,	8004020193 8004020070 8004160104 8004150305* 8004240159*	70-1100 70-1151 70-1151 70-820 70-143
COONEY, M J COONEY, M J COONEY, M J COOPERSTEIN, R COOPERSTEIN, R	8004170228 8004220549 8004290423 8004020160 8004110168	50-277 R 50-171 P 50-277 P 40-8502 40-8502	CRANE, P, A CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8004080466 8004040281 8004080481 8004100233 8004150337	50-275 A 50-275 A 50-133 B 50-133 I 50-275 A	CROWLEY, B R CROWLEY, B R CROWLEY, C J CROWLEY, B R	8004180098 8004040208* 8004140478 8004280267 8004020139	70-2909 50-566 G NUREG 50-320 H NUREG
COOPER.S COPELAND, J G COPELAND, J G COPELAND, J G COPELAND, J G	8004150427 8004080244 8004020208 8004020208 8004240188	50-280 D 50-466 Q 50-445 M 50-445 M 50-466 Q	CRANE,PA CRANE,PA CRANE,PA CRANE,PA CRANE,PA	8004160253 8004170076 8004150343 8004220406 8004220692	50-275 A 50-275 A 50-275 A 50-275 A 50-275 A	CULP,R H CULP,R H CULP,R H CULP,R H CULVER,M W	8004020136 8004020136 8004220003 8004220003 8004210240#	50-498
COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, R L	8004240188 8004220003 8004220003 8004180167* 8004270364	50-466 0 50-466 0 50-466 0 50-445 M 50-537 A	CRANE.P A CRATER.J CREE.R E. CREW8.J L CREW8.J L	8004280373 8004070024 8004030334 8004100282* 8004070175	50-275 A 50-352 H 50-387 H 50-344 0 50-275 Q	CUNNINGHAM, M E CUNNINGHAM, A L CUNNINGHAM, O E CUNNINGHAM, A L CUNNINGHAM, O E	8004210278 8004040365* 8004250284 8004070134* 8004250084	NUREQ 50-250 Q 71-5939 50-339 Q 71-5971
COPELAND, R L COPPER, W E CORDANI, R A	8004150473 8004210066 8004070153	50-537 A 71-381 70-27 50-483 Q 50-320 R	CREWS, J L CREWS, E H CREWS, E H CREWS, J L	8004180521 8004300439* 8004020292 8004140174 8004210189	50-344 0 50-312 0 50-375 8 50-375 8 50-243 0	CUNNINGHAM, Q E CUNNINGHAM, Q E CUNNINGHAM, A L CUNNINGHAM, O E CUNNINGHAM, O E	8004010041 8004020127 8004070175* 8004080217 8004080286	71-9049 71-5939 50-338 Q 50-183 R 50-18 R
		50-320 R NUREG J	CREWS,E H CREWS,E H CREWS,J L CREWS,E H CREWS,E H	8004020321 8004220049 8004210226 8004040447 8004100359	50-395 S 50-395 S 50-312 Q 50-375 Q 50-395 Q	CUNNINGHAM, G E	8004090308 8004090348 8004070398 8004070317 8004170044	50-73 R 50-70 R 71-380 50-16 1 50-73 P
			CREWS.J L CREWS.J L CREWS.J L CREWS.E H	8004100264 8004280080 8004280272 8004280214 8004170004	50-344 0 50-344 0 50-397 0 50-312 0 50-395 8	CUNNINGHAM, Q E CURRAN, J M CURRAN, J M CURRAN, J M CURRAN, J M	8004300052 8004080539 8004180454* 8004150345 8004210257*	50-70 P 50-204 B 50-206 B 50-206 R 50-206 B
			CREWS,E H CREWS,E H CREWS,E H CREWS,J L CREWS,E H	8004300561 800402007B 8004030175 8004300425 8004150501	50-375 8 50-375 K 50-375 K 50-312 0 50-375 8	CURRAN, J M CURREN, J R CURTER, J CURTER, J CURTER, J	8004230335 8004250420* 8004240566 8004110550* 8004080516	50-206 B 50-206 B NUREO 50-243 Q 50-387 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, A P	8004080363 8004140352 8004290394 8004300374 8004150431	50-387 S 50-387 A 50-387 S 50-387 S 50-124 P	DANIELBON.D H DANIELBON.D H DANIELB DARMITZEL.R U DARMITZEL.R U	B004150496* B004280039* B004290406* B004020185 B004170254	50-341	DENONCOURT, R F DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004210366* 8004280375* 7908210247 7908140243 7909190514	50-320 P 50-10 H 50-320 H COMMISSION MISC
CURTNER, A P CURTNER, A P CURTNER, A, P CURTNER, A P CURTNER, A P	8003310411* 8003310415* 8003310417* 8003310421* 8003310427*	50-124 B 50-124 B 90-124 B 50-124 B 50-124 B	DAUGHERTY,T M DAVIDSON.D R DAVIES,L M DAVIS,F C DAVIS,F C	B004280036 B004230353 B004140354* B004220485* B004220622*	50-574 G 50-440 B 50-367 A FOIA FOIA	DENTON, H R DENTON, H R DENTON, M M DENTON, M M DENTON, M M	7910020843 8004100519* 8003310411* 8003310415* 8003310417*	MISC 50-320 0 50-124 B 50-124 B 50-124 B
CURTNER, A P CURTNER, A P CUTCHIN, J, M CUTCHIN, J M CUTCHIN, J M	8003310432* 8003310439* 8004100571 8004080347 8004090011	50-124 B 50-124 B 50-387 Q 50-289 G 50-289 O	DAVIS.F C DAVIS.J G DAVIS.F C DAVIS.J G DAVIS.J G	8004220482* 8004220282* 8004220480* 8004220468* 8004220467*	FOIA FOIA FOIA FOIA FOIA	DENTON, M M DENTON, M M DENTON, M M DENTON, M M DENTON, M R	8003310421± 8003310427± 8003310432* 8003310439* 8004090306±	50-124 B 50-124 B 50-124 B 50-124 B SECY
M L INITIONS	8004080004 8004080019 8004110016 8004150069 8004150273	50-289	DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B	8004040095 8004070172 8004040029 8004070157 8004040032	40-8135 50-373	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004240507* 8004020028* 8003250855 8004020217 8004040225	50-286 P 100FR MISC 50-320 H 50-320 H
CUTCHIN, J M CUTCHIN, J M CYPBERT, S B CYPHERT, S B CYPHERT, B B	8004170055 8004280244 8004020144* 8004020149 8004020181*	50-289 Q 50-387 Q 50-445 M 50-445 M 50-445 M	DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B	8004040392 8004040450 8004070131 8004040019* 8004100140	50-315 G 40-2061 27-47 50-10 G 50-10 Q	DENTON, H R	8004040247 8004040464* 8004070139 8004070142* 8004220417	50-320 H CONTRACT 50-295 G 50-295 G 50-409 G
CYPHERT, B B CYPHERT, B B CYPHERT, B B CYPHERT, B B CYPHERT, B B	8004020190# 8004020198# 8004020098 8004080559 8004090204	50-449 M 50-445 M 50-449 M 90-445 M 50-445 M	DAVIS.A B DAVIS.J F DAVIS.A B DAVIS.A B DAVIS.G R	8004100518 8004180389 8004040160 8004090319 8004080226	50-254 Q 50-247 P 50-331 Q 50-2 Q WASTE MOT	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004220422* 8004220430* 8004020454 8004020461 8004030019	50-409 G 50-409 G 50-320 H 50-320 H 50-320 H
CYPHERT, S B CYPHERT, S B CYPHERT, S B CYPHERT, S B CYPHERT, S D	8004110056 8004100218 8004100084 8004080028 8004080033*	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,J H	8004100372 8004100380 8004110259 8004230138 8004280255*	50-150 Q 50-162 Q 50-151 Q 70-925 70-1319	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004030022 8004030035 8004030052 8004030061 8004030087	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
CYPHERT, B B CYR, K D CYR, K D CYR, K D D'AMORE, M	8004100177 8004240230 8004230047 8004280077 8004100463*	50-445 M PR PR PR PR 70-1151	DAVIS,A B DAVIS,L D DAVIS,A B DAVIS,A B DAVIS,A B	8004090193 8004100235 8004030259 8004100067 8004100119	1&E 50-556 9 50-331 9 50-282 9 50-10 9	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004030123 8004040211 8004040214 8004040215 8004040218	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
DAHL, J H DAHLMAN, L C DAIL, L C DAIL, L C DAIL, L C	8004180507 8004180307* 8004230085 8004220105 8004240426	XPORTLIC 50-304 G 50-488 G 90-491 G 50-491 G	DAVIB,A B DAVIB,A B DAVIB,G R DAVIB,A B. DAVIS,S M	8004040014 8004300544 8004240060 8004020477 8004010351*	50-10 Q 50-10 Q WASTE MOT 40-7127 50-318 S	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004040219 8004040220 8004040223 8004140036 8004140122	50-320 H 50-320 H 50-320 H NVRE0 50-312 H
DALE, L F DALE, L F DALE, L F, DALE, L F DALE, L F	8004230070 8004170071 8004280517 8004280501 8004150568	50-416 G 50-416 B 50-416 S 50-416 S 50-416 S	DAVIS,8 M DAVIS,L D DAVIS,8 M DAVIS,L D	8004010368* 8004150078 8004150638* 8004210323 8004220371	50-318	DENTON H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004210275 8004220136 8004220159 8004030070 8004040202	50-546 H 50-320 H 50-320 H 50-320 H 50-320 H
DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8004280484 8004280541 8004100362 8004210228 8004280520	50-416 S 50-416 S 50-416 H 50-416 A 50-416 B	DAVIS,8 M DAVIS,8 M DAWSON,D M DAWSON,D M	8004270350# 8004270447# 8004270484# 8004240267 8004140082#	50-318 8 50-317 8 50-317 8 70-1308 70-1308	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004040421 8004070129 8004020173 8004020218 8004020222*	50-320 H 50-155 H COMMISBION 50-389 O 50-389 O
DALE, L F DALE, L F DALE, L F, DALE, L F, DALE, L F	8004280610 8004280481 8004170243 8004220421 8004280479	50-416 B 50-416 B 50-416 A 50-416 C 50-416 B	DAWEON, D M DAWBON, D M DAWBON, D M DAY, B D DE LAGUIL, P	8004180133 8004240277* 8004140073* 8004180472* 8004280034	70-1308 70-1308 70-1308 50-263 8 NUREO	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004040005 8004040200 8004090061 8004080078 8004080083*	50-320 P SECY 50-320 P 50-295 0 50-295 0
DALE, L F DALTON, A T DALTROFF, B. L DALTROFF, B L DALTROFF, B L	8004280606 8004230082 8004160187* 8004100211 8004140064	50-416 8 50-556 0 50-277 0 50-277 0 50-277 0	DEAKYNE, K DEALE, V B DEANE, R H DEBNAM, J DEBNAM, J	8004220772* 8004080017 8004090187 8004220560* 8004220565*	50-346 8 50-522 0 50-312 0 50-111 R 50-111 R	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004080088* 8004110079 8004020250 8004030112 8004070070	50-295 G MISC 50-275 H 50-309 H 50-483 H
DALTROFF, S L DALTROFF, S L, DALTROFF, S L DALTROFF, S, L, DALY, B J	8004100261 8004010406 8004240402 8004240372* 8004270001	50-171 Q 50-277 F 50-277 P 50-277 Q NUREO	DEEDS,W E DEEQ.F H DEER.D A DEGEN.G DELANEY.J L	8004280048 8004020219 8004220618* 8004210300* 8004240217*	NUREG 50-333 J FOIA 50-10 H 50-438 A	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004070075 8004140303* 8004090056 8004140111 8004140117*	50-327 H 50-309 U 50-320 G 50-320 G 50-320 G
DANCE, H C DANCE, H C, DANCE, H, C, DANIELSON, D W DANIELSON, D, H	8004150074* 8004150155* 8004070413* 8004280507* 8004040410*	50-321 Q 50-321 Q 50-327 Q TOPREP 50-263 Q	DELANEY, J C DELANEY, J C DELANEY, J C DELQEORGE, L D	8004040209 8004020488* 8004080570* 8004240189* 8004140213	70-82 50-364 A 70-143 70-143 50-373 I	DENTON, H R DENTON, H R. DENTON, H R DENTON, H R DENTON, H R	8004210381 8004210376 8004220112 8004220168 8004220168	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
DANIELBON, D. H DANIELBON, D. H DANIELBON, D. H, DANIELBON, D. H DANIELBON, D. H	8004070173* 8004040150* 8004030255* 8004040339* 8004080647*	50-483	DELOEDRGE, L D DELOEDRGE, L D DELLA RATTA, A DELONG, 8 D DELONG, 8 D	8004010352 8004080522 8004100072* 8004230444* 8004230447*	50-373 F 50-373 K 70-364 50-315 S 50-315 S	DENTON, H R. DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004220185 8004240270 8004240441 8004250111 8004280260	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
DANIELSON, D H DANIELSON, D H DANIELSON, L J DANIELSON, D H DANIELSON, L J	8004100130# 8004100207# 8004070181 8004280025# 8004020053	50-305 G 50-254 G 40-4492 50-265 G 40-4492	DENISE, R P DENNISON, A B DENNISON, A B DENNY, T L DENNY, T L	8004250004 8004100468 8004100468 8004180061 8004210348	TOPREP 50-358 0 50-358 0 40-2061 40-2061	DENTON, H R DENTON, H R. DENTON, H R DENTON, H R DENTON, H R	8004280279 8004280279 8004280289 8004280325 8004280327	50-320 H 50-320 H 50-320 H 50-320 H

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004280535 8004280542 8004290064 8004290076 8004140092	50-320 H 50-320 H 50-320 H 50-320 H MISC	DICEY, B B DICHARRY, R F DICKERSON, M W DICKS, N D DICKSON, H W	8004040102* 8004080058 8004080602* 8004040243 8004150036	40-8135 71-102 50-267 G PRM RES	DOLAN, J E DOLAN, J E DOLAN, J E DOLAN, G R	8004300611 8004080544 8004280398 8004230369 8004210361*	50-315 Q 50-315 F 50-315 Q 50-315 F PR
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8004080047 8004210402 8004210354 8004210363 8004280342	50-307 P 50-320 H 50-320 H 50-320 H 50-320 H	DIENEES, J K DIETCH, R DIETCH, R DIETCH, R DIETCH, R	8004150141* 8004030141* 8004030140 8004080491 8004080498*	NUREG 50-206 P 50-206 P 50-206 P 50-206 P	DOMANUS, H. M DOMANUS, H. M DOMABHOVETZ, I DONALDSON, D DONALDSON, D	8004150326 8004290017 8004290474* 8004020141* 8004020138*	NUREO NUREO TOPREP ACRS ACRB
DENTON, H R DENTON, H R DENTON, H DENTON, H R DENTON, H R	8004280357 8004280550 8004280565 8004140066 8004290054	50-320 H 50-320 H 50-320 H 50-344 F 50-3 H	DIETCH, R DIETZ, G R DIGGS, R M DIGGS, R M DIGGS, R M	8004140161 8004070220 8004070215 8004080201 8004240244	50-361 R 71-9 50-346 P 50-155 P 50-317 P	DONALDSON, D E DONOCHUE, D J DONOCHUE, D J DONOCHUE, D J	8004070112* 8004100583 8004300007* 8004300002 8004160235*	70-1100 50-311 0 SECY SECY 50-269 0
DENTON, H R	8004070056 8004150211 8004170292 8004170296* 8004180154	50-281 G 50-10 H 50-424 G 50-424 G 50-339 A	DIGGS.R M DIGGS.R M DIIANNI.D C DILLON.R L DIMEGLID.A F	8004160001 8004210036 8004210263 8004070093 8004080103*	50-269 P 50-244 P 50-289 F ACRS 50-193 I	DONDHEW, J N DONDHEW, J N DONDHEW, J N DOPCHIE, H DOPCHIE, H	8004160240* 8004160219* 8004160244* 8004220147 8004110359	50-269 Q 50-269 Q 50-269 Q REGOD REGOD
DENTON, H R	8004240145 8004250056 8004250388 8004100574 8004100581	50-424 9 50-10 9 50-10 H 50-320 H 50-320 H	DINNEL, P A DIPIAZZA, R P DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004020139 8004090046 7904110034* 7908150708 8004020169	NUREG 71-9009 PR MISC 40-1341	DOPSOVIC.D A DOPSOVIC.D A DOPSOVIC.D A DOPSOVIC.D A DORMITZEL,R W	8004020164* 8004020198* 8004100177 8004170340 8004170260*	50-445 M 50-445 M 50-445 M 50-445 M 50-70 P
DENTON: H R	8004100573 8004150317* 8004210320* 8004210336 8004150085	50-320 H 50-516 G 50-339 T 50-247 H 50-3 H	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004080151 8004080193 8004240364 8004080212 8004080137	WASTE MOT 50-3 U 50-440 H 50-387 U 50-289 U	DOROUGH, R DOUGHERTY, J B DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8004300013* 8004150206 8004080340* 8004100357* 8004070140*	50-387 Q FOIA CONTRACT CONTRACT CONTRACT
BENTON, H R DENTON, H R DENTON, H R BENTON, H R DENTON, H R	8004160173 8004170342 8004180510 8004210088 8004210173	50-3 H 50-3 H 50-302 H 50-3 H 50-3 H	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	B0040B0260 B004070417 B0040B0254 B0040B0157 B004140071	50-409 V State Prog 50-327 V 50-142 V MISC	DOUGHERTY, D J DDUGHERTY, D J DDUGHERTY, D J DDUGHERTY, D J DDUGHERTY, D J	8004040197* 8004070007* 8004040454* 8004100023* 8004030037*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, HR DENTON, HR DENTON, HR DENTON, HR DENTON, HR	8004210208 8004250013 8004250018 8004180122 8004180126*	50-3 H 50-3 H 50-247 H 50-301 0 50-301 0	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004170348 8004140286 8004140297 8004140299 8004140374	PR 50~522 U 50~339 U 50~309 U 50~266 U	DOUGHERTY, D J DOUGHERY, D J DOUGHERY, D J DDUGHERY, D J DDUGHERY, D J DDUGHERY, D J	8004040162* 8004090485* 8004030023* 8004040217* 8004070032*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R	8004180281 8004230183 8004270047 8004250036 8004280347	50-247 E 50-3 H 50-320 H 50-280 Q 50-369 H	U KARARID U RENJEID DINCKS W J DINCKS W J DINCKS W J	8004140252 8004140294 8004140183 8004140208 8004140235	50~358 U 50-264 U 50~10 U 50-10 U 50~407 U	DOUGHERTY, D J	8004100524* 8004100531* 8004040186* 8004100600* 8004240542*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON: H R	8004300078 8004230084 8004250283 8004300508 8004180431	50-336 P 50-320 0 50-320 H 50-320 0 50-320 H	DIRCKB, W J DIRCKB, W J DIRCKB, W J DIRCKB, W J	8004170301 8004180234 8004100431* 8004140459* 8004140169	50-409 H 50-3 H 10CFR 50-10 U 50-10 U	DQUOHERTY, D J DDUOHERTY, J DDUOHERTY, J DDUOHERTY, J B DOUGHERTY, J B	8004240553# 8004150101 8004150101 8004280211 8004280211	CONTRACT 50-574 Q 50-574 Q 50-338 Q 50-338 Q
DENTON: H R DENTON: H R DENTON: K R DENTON: K R DENTON: K R	8004270200 8004240480 8004250232 8004280054 8004280159	50-339 A 50-286 P 50-247 P 50-286 P 50-311 A	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8004140225 8004180114 8004240528 8004150024 8004300292	50-10 U 80-289 H COMMISSION 70-1308 50-3 U	DOUGHERTY, J B DOYLE.R J DRAODNETTE.K S DRAODNETTE.K S DRAKE, F E	8004280211 8004240565 8004070410 8004070414* 8004220110	50-338 0 Nureg 27-47 27-47 50-244 p
DENTON, H R DENTON, H R DENTON, R E DENTON, H R DENTON, H R	8004280342 8004280384 8004220719* 8004280190 8004280195*	50-10 H 50-287 H 50-317 8 50-311 0 50-311 0	DISALVO DISALVO DISE.D P DISE.D P DISE.D P	9004220043 9004220055* 8004080415 9004070307 9004010330	71-379 71-379 50-220	DREESEN, D R DREHER, F DREY, K DROMERICK, A W DROMERICK, A W	8004270520 8004220224 8004250062* 8004030177 8004100318	WASTE MOT 50-272 S 50-10 Q 50-337 A 50-339 A
DENTON-H R DENTON-H R DENTON-H R DENTON-H R DENTON-H R	8004280196* 8004300585 8004300590* 8004300598* 8004300046*	50-311 0 50-272 0 50-272 0 50-272 0 50-387 0	DISIBIO: R DISIBIO: R DISTEFANO: J DISTEFANO: J DITTO: S J	8004240077 8004240081* 8004210353 8004210361* 8004030291	State Prog State Prog PR PR ACRS	DROMERICK, A W DROMERICK, A W DROMERICK, A DROMERICK, A W DROMERICK, A W	8004140079 8004140033 8004240092 8004140016 8004250031	50-337 A 50-339 A 50-339 A 50-275 A 50-339 P
DETRICH, B F DEVINCENTIB, J DEVINE, J F DEVLIN, J W DEVLIN, J W	8004300023* 8004070106* 8004020283 8004070221* 8004210024*	50-387 0 50-443 0 50-275 A 50-201 0 50-272 0	DIVINE, J R DIVINE, J R DOAD, C V DODDS, R T DODDS, R T	8004270020 8004040210 8004280048 8004230270* 8004020180*	NUREG RES NUREG 50-440 G 50-528 G	DUBIN, K J DUBRY, N E DUBRY, N E DUBRY, N E DUBRY, N E	8004300042* 8004230189* 8004230157* 8004070192 8004040059	50-387 0 50-123 0 70-925 50-315 8 50-315 8
DEVLIN, J W DEVLIN, J W DEVLIN, J, W DEVLIN, J, W	8004100068* 8004100191* 8004210218* 8004250059* 8004210330*	50-334	DODDS, R T DODDS, R T DODDS, R T DODDS, R T DODDS, R T	8004300121* 8004040161* 8004020062* 8004300278* 8004280180*	50-528 0 50-312 0 50-341 0 50-397 0 50-312 0	DUCKWORTH, J P DUCKWORTH, J P. DUCKWORTH, J P DUGAN, D W DUGOINB, L	8004150062 8004230053 8004100219* 8004240505 8004240340	50-201 R 50-201 A 50-201 G 50-296 P 50-133 G
DEVLIN, J W DEVLIN, J DEVLIN, J DEVLIN, J DEWITT, R B,	8004230128* 8004150173* 8004280632 8004300552 8004040307	50-309 G 70-371 50-320 S 50-293 S 50-155 P	DODDS,R T DODDS,R T DOHERTY,J F DOHERTY,J F DOLAN,J E	8004280074* 8004210428* 8004110551 8004240548 8004110445	50-460 Q 50-312 Q 50-466 Q 50-466 G 50-315 R	DUMMER.O H DUMB.D DUNBAR.J.F DUNFERD.E F DUNN.C N	8004250043* 8004070266 8004270427* 8004160184* 8004070177*	CONTRACT PR 50-249 8 50-320 P 50-334 0
DEWITT.R B DEWITT.R.B DEYOUNG.R C DEYOUNG.R C DIAZ.N J	8004150398 8004150474 8004160004 8004160019* 8004220213	50-255 P 50-255 P 50-272 Q 50-272 Q 70-106B	DOLAN, J E DOLAN, J E DOLAN, J E DOLAN, J E	8004070411 8004210415 8004010325 8004010420 8004010486	50-315	DUNN, C N DUNN, C N DUNN, C N DUNN, C N	8004100358* 8004040165* 8004070009 8004150221 8004110160	50-334 Q 50-334 Q 50-334 Q 50-334 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DUNN'C N DUNN'C N DUNN'C N DUNN'N W	8004180062 8004180067* 8004010459 8004030201 8004040354	71-96 71-96 50-334 P 50-334 P 50-334 F	EISENHUT,D G EISENHUT,D G EISENHUT,D G EISENHUT,D G	8004100300 8004110910 8004110528 8004110534 8004110559	50-317 P 50-335 P 50-213 P 50-285 P 50-313 P	ENGELKEN, R H	8004180155 8004110007 8004230360 8004230364 8004230368	50-312
DUNN'C N DUNN'C N DUNN'C N DUNN'C N	B004110482 8004210283 B004220574 B004210261 B004270354	50-334 P 50-334 P 50-334 P 50-334 R 50-334 R	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8004110570 B004240141 B004100607 B004230293 B004300055	50-309 P REVIEW GRP 50-344 G 50-344 G 50-255 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8004230370 8004230373 8004230374 8004230376 8004230379	50-397 0 50-528 0 50-133 0 50-344 0 50-275 9
DUNNING, G M DUTTON D DUTTON, D DUTTON, D	8004080211#	FOIA	EISENHUT.D G	8004300589	50-206 P	ENGELKEN,R H	8004240503	50-206 P
	8004080222#	FOIA	EISENHUT.D G	8004280287	50-286 H	ENGELKEN,R H	8004250118	50-397 A
	8004070198	50-424 Q	EISENHUT.D G	8004280140	50-3 H	ENGELKEN,R H	8004220170	50-528 Q
	8004040420	50-424 Q	EL-ASHRY.M T	8004020447*	50-327 S	ENGELKEN,R H	8004220172	50-133 Q
	8004020335	50-424 B	EL-ASBRY.M T	8004020385	50-390 A	ENGELKEN,R H	8004220176	50-275 Q
DUTTON, D	8004020187	50-424 G	EL-ASHRY,M T EL-ASHRY,M T EL-ASHRY T EL-ASHRY,M T EL-ASHRY,M T	8004110425	50-390 A	ENGELKEN, RH	8004220179	50-344 Q
DUTTON, D	8004100348	50-424 G		8004150551	50-327 P	ENGELKEN, RH	8004220190	50-312 Q
DUTTON, D	8004010349	50-424 G		80041505594	50-327 P	ENGELKEN, RH	8004220195	50-206 Q
DUTTON, D	8004020390	50-424 G		8004150392	50-553 R	ENGELKEN, RH	8004220198	50-361 Q
DUTTON, D	8004240344	50-424 G		8004180331	50-390 R	ENGELKEN, RH	8004220201	50-397 Q
BUTTON, D	8004140336	50-424 A	EL-ABHRY,M T	8004220533	50-259 P	ENGI,D	8004150049	NUREG
BUTTON, D	8004150421	50-425 8	ELD,M E	8004110143	PRM	ENGI,D	8004150078	NUREG
BUTTON, D	8004150427	50-424 8	ELGERT,O J	8004230129	XPORTLIC	ENTWISLE,E	8004030340*	COMMISSION
BUTTON, D	8004280491	50-424 8	ELGERT,O J	8004230133*	XPORTLIC	EPEL,L G	8004280071	RES
BUTTON, D	8004150427	50-424 8	ELGERT,O J	8004210026	XPORTLIC	EPLER,E P	8004030295	ACRS
DYER, J A DYER, J A DZIEWISZ, J S EARLY, P J EARLY, P J	8004070163* 8004280241* 8004240183* 8004230032* 8004010257	50-302	ELIABON, L R ELIN, J O ELKUS, R J ELLENSHAW, L E	8004080400 8004020062* 8004300298* 8004170005 8004270212*	50-263 P 50-361 Q 50-397 Q 50-228 P QA799	ERB,C M ERICKSON,J R ERICKSON,L W ERICSON,D M ERNST,M L	8004100267# 8004010106# 8004040065# 8004150033 8004240253	50-329 Q 27-39 50-344 T NUREQ 50-320 H
EARLY,P J	8004010367	50-333 P	ELLERSHAW, L E	8004030244*	QA999	ERTLE,R F	8004280380	50-346 I
EARLY,P J	8004080381	50-284 P	ELLERSHAW, L E	8004150149*	QA999	ERVIN,P E	8004250306	PR
EARLY,P J	8004080473	50-333 P	ELLERSHAW, L E	8004300222*	QA999	ESCUE,N R	8004020023	MISC
EARLY,P J	8004140398	50-333 B	ELLIOTT, C P	8004300076*	50-387 G	ESKIN,L D	8003310411*	50-124 B
EARLY,P J	8004150364	50-333 P	ELLISON, C T	8004040007	PR	ESKIN,L D	8003310415*	50-124 B
EARLY,P J EARLY,P J EARLY,P J EARLY,P J EARLY,P J	8004170061 8004150508 8004300041 8004150458 8004170064	50-286 P 50-333 S 50-286 Q 50-286 Q 50-333 P	ELROD, B A ELROD, B A ELROD, B ELTAWILA, F ELTAWILA, F	8004240370* 8004280241* 8004070051 8004080660* 8004020466	50-280 G 50-335 G 50-335 B 50-387 A 50-322 A	ESKIN, LD ESKIN, LD ESKIN, LD ESKIN, LD	8003310417# 8003310421# 8003310427# 8003310432# 8003310439#	50~124 B 50~124 B 50~124 B 50~124 B 50~124 B
EARLY,P J	8004180343	50-286 P	ELTAWILA, F	8004030122	50-322 A	ESSIG, T H	6004110274*	50-151 Q
EARLY,P J	8004180350	50-286 P	ELTAWILA, F	8004040474	50-322 A	ESSIG, T H	6004300555*	50-10 Q
EAST,D J	8004210387	40-1162	ELTAWILA, F	8004300064	50-322 A	ESTEY, H P	6004070370	70-1257
EASTER,J H	8004020176*	6tate Prog	ENDERLIN, W I	8004210301	NUREO	ESTEY, H P	6004140456	70-1257
EATON,L	8004240534*	50-443 H	ENDRIZZI, D	8004080175	50-387 G	ESTEY, H P	6004160072	70-1227
EATON.J	8004010472	50-443	ENGEL,R E	8004230343*	50-217 P	ESTEY, H P	8004070102	70-1257
EBEL.P E	8004210041		ENGEL.R E	8004140116*	TOPREP	ESTRADA, P	8004280545*	50-320 H
EDNETER.S D	8004070111*		ENGELKEN,R H	8004070251	50-328 S	EVANS, C A	8004070036*	50-285 0
EDNETER.S D	8004070231*		ENGELHARDT,T W	8004070176	50-320 P	EVANS, V R	8004080391	50-317 F
EDNETER.S D	8004070396*		ENGELKEN,R H	8004100492	50-361 S	EVANS, C A	8004270011*	50-298 0
EBNETER, 8 EBNETER, 8 EBNETER, 8 D EBNETER, 8 D ECKERT, R M	8004150143* 8004070438* 8004100112* 8004180334* 8004230338	50-352	ENGELKEN, R H	8004100488 8004150203 8004150205 8004150207 8004150214	50-397 S 50-528 Q 50-123 Q 50-344 Q 50-204 Q	EWALD.S C EWING.J F FABIC.B FABRIKANT.R FAMMER.W J	8004040194* 8004040137* 8004220531* 8004040072 8004230489	50-338 Q 70-27 50-259 P 50-445 M 50-341 8
ECKHARDT, J H	8004020180*	50-528 G	ENGELKEN, RH	8004150218	50-312 9	FAHRNER.W J	8004020403	50~341 8
ECKHARD, T	8004240522*	50-528 G	ENGELKEN, RH	8004150220	50-397 0	FAIRTILE,M D	8004080644	50~307 H
ECKLER, J.	8004220137*	FOIA	ENGELKEN, RH	8004100097	50-528 0	FALCONER,J C	8004010472	50~443 0
ECONOMOS, N	8004070291*	50-348 G	ENGELKEN, RH	8004100101	50-133 0	FALK,K M	8004180130*	50~301 G
ECONOMOS, N	8004210199*	50-249 G	ENGELKEN, RH	8004100104	50-344 9	FALK,K M	8004010387	50~266 G
ECONOMOS: N	8004160122*	50-413 Q	ENGELKEN, R H	B004100107	50-204 Q	FALLON,P	8004300029*	50-387 0
EDELSTEIN, B	8004080643	XPORTLIC	ENGELKEN, R H	B004100108	50-312 Q	FALTER,H W	8004290066	50-518 8
EDGEWORTH: P J	8004070125	CONTRACT	ENGELKEN, R H	B004100109	50-397 Q	FARBER,R C	8004300009*	50-387 G
EDGEWORTH: P. J	8004040191	50-184 Q	ENGELKEN, R H	B004110107	50-528 Q	FARMER,W S	8004280259	ORG
EDGEWORTH: P	8004100020	CONTRACT	ENGELKEN, R H	B004110111	50-133 Q	FARR,R J	8004140449*	50-454 A
EDGEWORTH, P J EDGEWORTH, P J EDLOW, J EDMONSON, L D	8004030020	CONTRACT	ENGELKEN, R H	8004110113	50-344 0	FARRELL, R L	8004150049	NUREG
	8004040212	CONTRACT	ENGELKEN, R H	8004110114	50-206 0	FARRELL, D	8004030339	50-556 H
	8004070025	CONTRACT	ENGELKEN, R H	8004110115	50-312 0	FARRIS, J, R	8004100605*	50-556 G
	8004040427*	FOIA	ENGELKEN, R H	8004110119	50-397 0	FARRIS, J R	8004100610*	50-556 G
	8004020234*	50-320 H	ENGELKEN, R H	8004180502	70-984	FARRIS, J R	8004100595	50-556 O
EDSON, K,	8003190734*	50-128 P	ENGELKEN,R H	B004220009	70-25	FARRIS, J R	8004100605*	50-556
EDHARDS, D L	8004080055	40-3453	ENGELKEN,R H	B004220013	70-1257	FARRIS, J R	8004100610*	
EDWARDS, D, L	8004290449	40-3459	ENGELKEN,R H	B004220015	70-734	FASANO, A N	8004070103	
EDWARDS, D H	8004010468*	50-324 R	ENGELKEN,R H	B004220022	70-754	FASANO, A N	8004020072	
EDWARDS, D H	8004040323*	50-261 R	ENGELKEN,R H	B004220031	50-528 G	FASANO, A N	8004020094	
EICH,E	8004210258*	50-247 R	ENGELKEN,R H	8004220038	50-133	FASAND, A N	8004020077	50-320 6
EICHHORN,W H	8004020092	50-367 G	ENGELKEN,R,H	8004220046		FASAND, A N	8004020097	50-320 8
EICHHORN,W H	8004020092	50-367 G	ENGELKEN,R H	8004220048		FASCID, P	8004040224	50-387 H
EISENHUT,D Q,	7906290854	50-312 H	ENGELKEN,R H	8004220050		FAUBLE, T J	8004240448	RES
EISENHUT,D Q	8004280369*	50-10 H	ENGELKEN,R H	8004220052		FAULKENBERRY	8004300453*	50-312 0
EISENHUT, D G	8003240555	50-302 Q	ENGELKEN, R H	8004180135	50-206 @	FAULKENBERRY, B	8004210227*	50-312
EISENHUT, D G	8004070288	50-27 G	ENGELKEN, R H	8004180139	50-397 @	FAULKENBERRY, B	8004280226*	
EISENHUT, D, G	8004030102	50-320 P	ENGELKEN, R H	8004180144	50-528 @	FAY, C W	8004040123	
EISENHUT, D, G	8004100517	ORG	ENGELKEN, R H	8004180148	50-133 @	FAY, C W	8004070206	
EISENHUT, D G	8004140085	ORG	ENGELKEN, R H	8004180152	50-344 @	FAY, C W	8004030353	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8004020326 8004010319 8004240449 8004020333 8004020344*	50-266 P 50-266 P 50-266 Q 50-266 5 50-266 S	FERGUSON, R FERGUSON, J H FERGUSON, J H FERGUSON, J H FERN, B	7708150054 80042500419 8004020027 8004210372 8004210279	HISC * 50-280 Q 50-280 Q 50-338 P	FISH.R F FISH.R FISH.R FISHER,R J FISHER,J R	8004210248* 8004040030 8004040415 8004080115* 8004030033*	50-312 0 50-70 B 50-70 B FOIA 50-320 H
FAY.C W FAY.C M FAY.C W FAY.C W FAY.C W	8004020410 8004240419 8004220278 8004290307 8004290310*	50-266 F 50-266 0 50-301 P 50-266 S	FIALKOVICH, J E FIELDSETH, H FIELDER, J FIELDER, J FIELDS, S R	8004300206 80042800431 8004080281 8004080465 8004110048	NUREG 50-282 H 50-250 J 50-348 J NUREG	FISHER, W L FISHER, W L FISHER, W L FISHER, W L FISHER, W L	8004070166* 8004070174* 8004040034* 8004100383* 8004230189*	50-10 0 50-373 0 50-254 9 50-182 0 50-123 0
FAY,C W FAY,C W FAY,C W FAY,C W FAY,C W	8004290464 8004290469* 8004220475 8004290298 8004290306*	50-301	FIELDER, J FIELDER, J FIKAR, L F FILKINS, D FINFROCK, I R	8004140442 8004280449 8004230041* 8004180471* 8004220514*	50-244 5	FISHER,W L FISHER.W L FISHER.W L FISHER.B FISHER.B	8004090327* 8004100377* 8004230157* 8004070424 8004020063	50-2 Q 50-150 Q 70-925 40-1162 PROJ
FAY.C W FAY.C W FEDERICK,E J FRE,W F FEE,W F	8004290470 8004290479* 8004100398 8004070218* 8004110012	50-301 S 50-301 S RES 50-245 Q 50-213 Q	FINFROCK, I R	8004020006 8004020383 8004020319 8004220508 8004220511*	50-363 0 50-217 R 50-217 P 50-217 P 50-217 P	FISKE,T N FISKE,T N FITZGERALD,J A FITZSIMMONS,T R FLEISHER,Z S	8004300297 8004300297 8004180136 8004070389 8004290058*	WASTE MOT WASTE MOT 50-387 p 71-9067 50-3 H
FRE, W F FRE, W F FRE, W F FRE, W F FRE, W F	8004030293 8004210411 8004250132 8004150297 8004230413	50-213 P 50-213 P 50-213 G 50-213 P 50-423 A	FINKEL,A E FINLEY,N C FINLEY,A G FINLEY,A Q FINLEY,A Q	8004180334* 8004150033 8004070431* 8004030350* 8004110498*	NUREO 50-308 G	FLEIBHER,W L FLEIBHER,Z S FLEIBHER,W L FLEIBCHAKER,D FLEIBCHAKER,D S	8004090213 8004180237* 8002290456 8004020133 8004090038	PR 50~3 H 50~286 H 50~275 D 50~275 D
FEHRINGER. J M FEHRINGER. J M FEHRINGER. J M FEHRINGER. J M FETERABEND. C D	8004150025 8004150038 8004170276 8004250364 8004100270*	50-155 P 50-271 P RES 50-295 P 50-282 Q	FIGRELLI, G FIGRELLI, G FIGRELLI, G FIGRELLI, G FIGRELLI, G	8004040060 8004040418* 8004040143 8004040036 8004040043	50~483 Q 50~546 G 50~346 Q 50~373 Q 50~546 Q	FLEIBCHAKER, D FLEIBCHAKER, D FLEIBCHAKER, D FLEIBCHAKER, D FLEIBCHAKER, D	8004090132 80040901374 8004230107 8004210322 8004080554	50-275 p 50-275 p 50-275 p 50-275 p 50-275 p
FEIT, R FEIT, R FELTON, J M FELTON, J M FELTON, J M	8004280187 8004280200 7812120219 8003310090 8004010163	REVIEW GRP REVIEW GRP FOIA FOIA 50~268 P	FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, G	8004070167 8004030251 8004040050 8004040175 8004040405	50~483 Q 50~306 Q 50~341 Q 50~10 Q 50~263 Q	FLEIBCHAKER, D FLETCHER, G W FLYNN, J R FLYNN, J R #LYNN, J R	8004210322 8004080241* 8004220075* 800422092* 8004220107*	50~275 Q CONTRACY FOIA FOIA FOIA
FELTON. J M FELTON. J M FELTON. J M FELTON. J M FELTON, J M	8004080046 8004010033 8004010049 8004010056 8004070194	50-150 I FOIA FOIA FOIA 50-3 H	FIORELLI.O FIORELLI.O FIORELLI.O FIORELLI.O FIORELLI.O	8004040471 8004040316 8004080629 8004100122 8004090272	50-329 0 50-295 0 50-373 0 50-305 0 50-373 0	ELANN'O B ELANN'O B ELANN'O B ELANN'O B ELANN'O B	8004220606 8004220242* 8004220286* 8004220346* 8004220573*	FOIA FOIA FOIA FOIA FOIA
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8004030355 8004010281 8004040419 8004020288 8004030303	50-382 H FOIA 40-8740 FOIA 40-2061	FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8004110150 8004080182 8004100172 8004040145 8004110284	50-440 Q 50-373 Q 50-254 Q 50-500 Q 50-456 Q	FLYNN, J R FLYNN, P FLYNN, J, D FLYNN, M FOLEY, E,	8004220532* 8004030263 8004150301 8004030040 8004100409*	F01A 50-312 H 50-358 A CONTRACT PR
FELTON, J H FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8004070136 8004070150 8004070425 8004030304 8004030310	FOIA FOIA FOIA FOIA FOIA	FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O	8004210134 8004100245 8004070130 8004280020 8004280044	50-358	FORBER, R. C. FORD, W. H FORD, W. H FORD, W. H FORD, W. H	8004150019# 8004040221 8004020155 8004070331 8004220088	50-255 B 40-9502 40-8502 40-9502 40-8502
FELION, J M FELION, J M FELION, J M FELION, J, M FELION, J, M	8004070001 8004070004 8004070012 8004080690 8004080709	F01A F01A F01A 50-3 F F01A	FIORELLI, 0 FIORELLI, 0 FIORELLI, 0 FIORELLI, 0 FIORELLI, 0	8004280031 8004090039 8004070201 8004070204 80040901,67	50-454 Q 50-327 S 50-346 S 50-329 B 50-440 S	FORD, W H FORD, W H FORNEST, Z FORTER, J E	8004240198 8004220076 8004080821* 8004040307 8004220186*	40-8502 40-8502 90-387 9 50-320 H FDIA
FELTON, J M	8004070044 8004070171 8004070023 8004070353 8004100048	FOIA 50-320 P FOIA FOIA FOIA	FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8004070197 8004040039 8004040048 8004030173 8004030177	50-546	FOBTER, J E FOBTER, K. FOBTER, W. E FOBTER, J B FOBTER, W E	8004220176# 8004030129# 8004070091# 8004030147 8004080287#	F01A 50-320 H QA999 40-2061 QA999
FELTON, J, M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	80041 10038 80041 50013 80041 50213 80042 80020 80041 50201	50-3 P FOIA FOIA FOIA FOIA	FIORELLI.G FIORELLI.G FIORELLI.G FIORELLI.G FIORELLI.G	8004070228 8004070230 8004080672 8004020085 8004040064	50-454 B 50-483 S 50-483 S 50-329 S 50-483 Q	FOBTER.W E FOBTER.R F FOBTER, W E FOBTER.J B FOSTER.W E	8004090086* 8004180481 8004080389* 8004010106* 8004080316*	0A997 ACR8 QA999 27-39 QA999
•	8004210095 8004210350 8004170131 8004210013 8004210047	FOIA 70-143 FOIA FOIA FOIA	FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G	8004100260 8004080645 8004070141 8004110548 8004110526	50-329	FOBTER, J. M FOBTER, J M FOBTER, J M FOBTER, J M FOBTER, E, R	8004030032 8004040154 8004090263 8004040180 8004090311*	CONTRACT CONTRACT CONTRACT CONTRACT SO-SS 8
	8004210038 8004210069 8004230008 8004230015 8004270094	FDIA 50-320 C FDIA FDIA FDIA	FIORELLI, Q FIORELLI, Q FIORELLI, Q FIORELLI, Q FIORELLI, Q	8004100287 8004110318 8004170249 8004180218 8004180301	50-546 Q 50-483 Q 50-546 B 50-358 S 50-341 B	FOUKE, R L FOULKE, J D FOWLER, D K FRANCE, E R FRANCE, E R.	6004240424* 7910310031 6004290456* 6004180601* 6004180579*	50-445 0 HISC 50-390 A 50-368 F 50-368 F
	8004270097 8004270150 8004270155 8004270182 8004270195	F01A F01A F01A F01A 50-329 H	FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q	8004180486 8004240122 8004300334 8004280628 8004300592	50-483 8 50-546 8 50-306 Q 50-10 Q 50-358 Q	Frankhauser, n Franklin, w J Franklin, w J Franklin, w J Franklin, w J	8004030308* 8004080265* 8004080370 8004210397* 8004040184	FDIA 50-445 H 50-445 H 50-445 H
	8004270104 8004270163 8004270167 8004270168 8004270087	50-341 H FOIA FOIA 50-320 H FOIA	FIGRELLI.G FIGRELLI.G FIGRELLI.G FIGRELLI.G FIRESTONE,L	8004290050 8004290053 8004300048 8004300060 8004080479	50-483 8 50-341 8 50-461 8 50-483 8 50-334 I	FRANKLIN,N J FRANKLIN,N J FRANKLIN,N J FRANKLIN,N J	8004210384 8004210392* 8004210400* 8004210392*	50-445 H 50-445 H 50-445 H 50-445 H

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FRANKLIN, W J FRANKLIN, W J FRANKLIN, W J FRANKLIN, W J FRANTZ, B P	8004140003 8004140008* 8004210147 8004210147 8004040053	50-445 M 50-445 M 50-445 M 50-445 M 50-367 G	GAMMILL, W P GAMON, T H GANNIS, S GARCIA, P J GARCIA, P J	8004280044* 8004010341 8004150018 8004070249 8004110135	50-285 P TOPREP FOIA 40-8452 40-1162	GILLILAND, D L GILLILAND, D L GILLILAND, D L GILLMAN, D GILLMAN, D	8004080220* 8004080313* 8004280311 8004180208* 8004070157	50-183 R 50-73 R 50-70 P 50-358 G 50-359 H
FRANTZ,S P FRANTZ,J FRANTZ,B P FREDRICKSON,C FREEMAN,K D	8004040053 8004300133 8004240194 8004150407 8004090187	50-367	GARRITY, J H GARRITY, J H GARY, R J GARY, R J GARY, R J	8004140154 8004280562 8004010147 8004040101* 8004040083*	50-309 R 50-309 R 50-445 Q 50-445 Q 50-445 Q	GILMARTIN, D J GILMAN, D W GILMORE, D W GINTECK, P GIROUARD, P R	8004100041 8004090224 8004180439* 8004020221* 8004090144	PR PRM 50-320 H 50-320 H FOIA
FRENCH, L D FRENZEL, B FREY, D O FRIDAY, O P FRIEDLANDER, M	8004080476# 8004210154 8004020470 8004070347* 8004070078#	50-29 5 PR 50-546 H 50-320 R 50-3 P	GARY.R J GARY.R J GARY.R J GARY.R J GARY.R J	8004180477 8004010295 8004150199 8004010296 8004150001	PR 50-445 S 50-445 B 50-445 S 50-445 A	GLAGDLA, A F GLAGDLA, A F GLAGDLA, A F GLAGDLA, A F GLAGDLA, A F	8004080326 8004100354 8004100596 8004240535 8004240546	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FRIEDMAN, O N FRIEDMAN, C FRIEDMAN, K A FRIEDMAN, J FRIGO, R	8004270186* 8004040216 8004110037* 8004270176* 8004080165	QA999 50-352 H QA999 QA999 50-367 H	GARY.R J GARY.R J GARY.R GARY.R GARY.R J	8004270278 8004220426 8004220423 8004250373 8004270521	50-445 S 50-445 K 50-445 S 50-320 O 50-445 A	GLASER, M L GLASIER, G E GLASS, D N GLAZIER, K M GLAZIER, K M	8004080663 8004020151 8004040403* 8004210437 8004100177	50-445 M 40-8675 71-35 50-445 M 50-445 M
FROHNE, R FROBT, B R FROBT, B R FROBT, B R FUKUDA, B K	8004150570* 8004250350 8004280555 8004280614 8004150056	50-346 8 50-255 8 50-155 F 50-255 F RES	CARYIR J CARYIR J CARYIR J CARYIR J CARYIR J	8004270250 8004270271 8004270411 8004270430 8004270437*	50-445 S 50-445 S 50-445 S 50-445 S 50-445 S	GLENN, J GLENN, J GLENN, J GLENN, J	8004210065# 8004210025# 8004210057# 8004210062# 8004240322#	FOIA FOIA FOIA FOIA 71-107
FULLER, J K FULLER, J K FULLER, J K FUNDERBURG, R D FURR, B J	8004070286 8004030130 8004270370 8004110544 8004070134	50-267 P 50-267 G 50-267 G State Prog 50-261 G	GARY,R J GARY,R J GASKIN,C E GATEB,J GAY R R	8004290634 8004300526 8004280013* 8004220681* 8004210223*	50-445 A 50-445 A 50-344 G 50-10 B 50-3 H	GLENN, T D GLIBSMEYER, J A GNUGNOLI, G GUDDARD, R J GODDARD, R J	8004240331* 8004210301 8004080665 8004150223 8004150258	71-107 NUREG WASTE MGT 50-367 G 50-367 G
FURR, B J FURR, B J FURR, B J. OAGE, L OAGE, L	8004040461 8004100343 8004230076 8004090438* 8004150143*	\$0-324	GECKLER.R P GECKLER.R P GECKLER.R P GEIGER.G GEIGELMAN.J N	8004230076# 8004020126# 8004210431# 8004080161 8004100460#	50-367 G 50-286 D 50-367 G 50-387 G 50-516 T	CODDARD, R J CODDARD, R J CODWIN, A V COCCIN, C L COLAY, M W	8004270217 8004270237 8004020116* 8004220736* 8004010422*	50-454
QAGNER, 8 F QAGNER, 8 F QAHM, J W QAHM, J, W QAHM, J W	8004070462 8004100487 8004080427* 8004080512* 8004210271*	MISC MISC 50-267 S 50-267 S 50-267 R	GEISELMAN,J N GEKLER,R P GERLACH,F T GERTZ,8 M GERTZ,8 M	8004100050* 8004230093* 8004220002 8004140420 8004280395	PR 50-347	OGLAY,M W OGLDBERG,S C OGLDBERG,J R OGLDBERG,J R	8004010415 8004110576 8004070471 8004080656 8004230302*	RES 50-347 G 50-293 M 50-250 G PRDJ
H L WHAS H L WHAS H L WHAS H L WHAS H L WHAS	8004150334* 8004150552* 8004150611* 8004150634* 8004210276*	50-267 R 50-267 B 50-267 B 50-267 S 50-267 S	GETTY, B C. GIARDINA, P A GIARDINA, P A GIBBONB, T D GIBBB, C F.	8004170234* 8004100472* 8004100055* 8004110575* 8004040238	50-133 R 50-516 T FR 50-395 G 50-556 H	GOLDBERG.S C GOLDBERG.J R GOLDBERG.S C GOLDBERG.J R	8004210425 8004230317* 8004160280 8004210209 8004230295	50-367 G PROJ PROJ 50-367 G PROJ
QAHM, J W. QALER,R R QALLAQHER,V C QALLAQHER,E J QALLAQHER,E J	8004240328* 8004230343* 7907250327 8004210142* 8004100252*	50-267 B 50-219 P 50-443 H 50-358 Q 50-329 G	GIBBB, M C GIBERT, J D GIBBON, A F GIBBON, A F GIBBON, A F	8004100310 8004030238* 8004040154* 8004080043* 8004080038*	50-255	GOLDBERG, S C ODLDBERG, S C QOLDHOR, F GOLDSMITH, R QOLLER, K R	8004250415 8004300388 8004250030* 8004270038 8004230110*	50-367 G 50-367 G 50-3 H GRG COMMISSION
QALLAWAY, W. C QALLAGHER, J W QALLAGHER, J U QALLAGHER, J W QALLINA, C	8004040479* 8004080538 8004250045 8004080349 8004280300*	GA999 50-277 P 50-277 G 50-277 P 50-293 G	Gibson, a f Gibson, a f Gibson, a f Gibson, a f Gibson, a f	8004270141* 8004040174* 8004070302* 8004110027* 8004250271*	50-324 0 50-330 0 70-1201 70-1151 50-261 0	900b,R R 9000HOPE,A C 9000HAN,L S 9000MAN,L S 9000MIN,W L	8004080082 8004090412 8004140367* 8004300463* 8004080049	RES 50-471 0 50-409 R 50-409 S 70-1151
QALLINA,C O QALLO,R M QALLO,R M QALLO,J QALLO,J,	8004210173* 7812110291* 8004100111* 8004020278 8004080191	50-273	GIBBON.A F. GILDERT,R B GILBERT,R B GILDERTB,D E GILBERTB,D E	8004280255* 8004240282* 8004240447* 8004100070* 8004070058	70-1319 50-320 H 50-320 H 50-282 Q 50-282 Q	QODDWIN, C QOODWIN, W L QOODWIN, C QOODWIN, C	B004100273* B004100463* B004110015 B0040B0447 B004030240	50-344 Q 70-1151 70-1151 50-344 P 50-344 P
QALLO, J QALLO, J. QALLO, J QALLO, J QALLO, J	8004100570 8004100273 8004100276* 8004100278* 8004100273	50-155	GILBERTS, D E GILBERT, L D GILBERTS, D E GILBERTS, D E GILBERT, L D	8004070210 8004300035* 8004300337* 8004040456 8004250083*	50-282 0 50-498 0 80-304 0 50-282 0 50-445 0	GDODWIN, C GDODWIN, C GDODWIN, C GDODWIN, C,	9004030243* 8004080388 8004100459 8004080542 8004180361	50-344 P 50-344 P 50-344 P 50-344 Q 50-344 P
GALLO, J GALLO, J, GALLO, J GALLO, J GALLO, J	8004100276* 8004100278* 8004080180 8004080186* 8004160161	50-155	OILBERTS, D E OILBERT, J D OILINSKY, V OILINSKY, V	8004160013 8004170052* 8004030024* 8004030016 8004020112	50-282 Q 50-338 R 50-3 H 50-3 H 50-289 H	COSSICK'F A COULDON'F COULDIN'F COODMIN'C	8004180362* 8004280268* 8004290418 7904110030 7907110564	50-344 P 50-320 H 50-266 I PR PR
GALLO, J. GALLO, J GALLO, J GALLO, J GALLO, J	8004080186* 8004160161 8004100451 8004100455* 8004100455*	50-155 0 50-554 0 50-155 0 50-155 0 50-155 0	OILINGKY, V OILINGKY, V OILINGKY, V OILINGKY, V	8004040002 8004180113 8004160034 8004280250* 8004220173	50-289 H 50-289 H 50-320 P 50-320 P 50-320 H	ODSSICK, L V ODSSICK, L V ODSSICK, L V ODSSICK, L V	7910250124 7910250127 7910250135 8004070188* 8004030024	PR PR PR 50-324 P 50-320 0
QALLO, J QALLO, J. QALLO, J. QALLO, J. QALSIER, O E.	8004210420 8004210401 8004280015 8004250372 8004020487	50-155 G 50-155 G 50-155 F 50-556 G 40-8681	GILINSKY.V GILLEBPIE:FP GILLEBPIE:FP GILLEBPIE:FP. GILLEBPIE:FP	8004240472 8004070244# 8004070059* 8004100482* 8004040021*	70-149 70-1151 70-1201	ODUGE, M J ODUGE, M J ODURGE, M J ODURGE, M J ODWDA, B C	8004100506* 8004040125* 8004160072* 8004210121* 8004290371*	50-566 Q 50-416 Q 50-327 Q 50-566 Q 50-537 A
OAMBING, M CAMMILL, W CAMMILL, W, CAMMILL, W, CAMMILL, W P	8004280350* 7910050156 7910050603 8004080233 8004080005*	50-320 H Misc Misc Misc 50-275 P	GILLESPIE,F P GILLETT,W T GILLETT,W T GILLESPIE,F GILLESPIE,F P.	8004040117* 8004150365* 8004150371* 8004270177* 8004270157*	50-316 R 50-315 R 50-259 Q	GDWER.O C GDWER.O C GDWER.O C GOWER.O C GRAHAM.R L	8004220247 8004280153* 8004280147* 8004080578 8004230071	50-263 8 0A779 0A779 18 E 50-367 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RAHAMAR L ORAHAMA E ORAHAMA E ORAHAMA E ORAHAMA U ORAHAMA U	B004230101# B004010405 B0041B0344 B004240379 7910150161	50-367 0 50-261 1 50-261 J 50-261 J MISC	GRIER, B H	8004150262 8004150264 8004150266 8004150269 8004150271	50-213 G 50-334 G 50-412 G 50-217 G 50-363 G	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8004240313 8004240315 8004240318 8004240319 8004240324	50-322 Q 50-320 Q 50-309 Q 50-245 Q 50-220 Q
GRANT.W B	8004040149*	50-500 Q	GRIER, B H	8004150274	50-322	GRIER, B H	8004240330	50-410 6
GRASSO,E	8004070426*	State Prog	GRIER, B H	8004150274		GRIER, B H	8004240333	50-286 0
GRATENHUIS.H	8004140199	50-306 Q	GRIER, B H	8004150277		GRIER, B H	8004240335	50-333 0
GRAVES.R S	8004220762*	50-3 G	GRIER, B H	8004150279		GRIER, B H	8004240337	50-352 0
GRAVES.R H	8004020372	50-213 R	GRIER, B H	8004150282		GRIER, B H	8004240339	50-277 0
GRAVES, R H GRAVES, R H GRAVES, R H GRAVES, R H GRAVES, R H	8004010362 8004010369* 8004240437 8004240439* 8004290264	50-213 8 50-213 8 50-213 R 50-213 R 50-213 R	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8004150285 8004150286 8004150288 8004150291 8004150293	50-410	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8004240341 8004240342 8004240346 8004240348 8004240349	50-387
GRAVES,R H	8004210251	50-213 R	GRIER.B H	B004150295	50-387 G	GRIER, B H	8004240351	50-485 Q
GRAVES,R S	8004220754	50-3 0	GRIER.B H	B004150296	50-272 G	GRIER, B H	8004240353	50-271 Q
GRAY,P F	8004300036*	50-387 0	GRIER.B H	B004150299	50-311 G	GRIER, B H	8004240355	50-29 Q
GRAY,C M	8004160078	70-2709	GRIER.B H	B004150302	50-449 G	GRIER, B H	8004180166	50-219 Q
GRAY,R J	8004160239	50-445 K	GRIER.B H	B004150303	50-244 G	GRIER, B H	8004180169	50-334 Q
GRAY. J R OREENMAN. E O OREEN. D G GREEN. D G	8004280006 8004160194* 8004020199* 8004090439 8004020119*	50-344 G 50-277 G COMMISSION 50-445 M 50-445 M	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8004150308 8004150309 8004150310 8004280167 8004090037	50-485 Q 50-271 Q 50-29 Q 50-293 P 50-293 Q	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8004180173 8004180174 8004180179 8004180180 8004180184	50-443 0 50-307 0 50-322 0 50-410 0 50-352 0
GREEN.D G	8004080073	50-445 M	GRIER, B H	8004090042	50-317 Q	GRIER, B H	8004180186	50-311 Q
OREEN.D G	8004040198*	50-445 M	GRIER, B H	8004090045	50-3 Q	GRIER, B H	8004180189	50-387 Q
OREEN.D G	8004140111	50-445 M	GRIER, B H	8004090047	50-213 Q	GRIER, B H	8004180192	50-412 Q
GREENLEE.E A	8004100194*	CONTRACT	GRIER, B H	8004090048	50-334 Q	GRIER, B H	8004180210	50-3 Q
OREEN.D G	8004100271	50-445 M	GRIER, B H	8004090052	50-412 Q	GRIER, B H	8004180226	50-213 Q
GREEN, D G GREEN, D G GREEN, D G GREEN, D G	8004100278* 8004230064 8004250106 8004170312 8004100552	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	GRIER. B H GRIER. B H GRIER. B H GRIER. B H GRIER. B H	8004070057 8004070060 8004070063 8004070065 8004070067	50-219 Q 50-363 Q 50-322 Q 50-320 Q 50-309 Q	GRIER.B H GRIER.B H GRIER.B H GRIER.II H GRIER.B H	8004180227 8004180231 8004180234 8004180241 8004180243	50-293 G 50-245 G 50-333 G 50-284 O 50-485 G
GREEN, D O GREEN, D O GREEN, D O GREEN, D O GREEN, D O	8004100560* 8004230154 8004100552 8004100560* 8004230154	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004070074 8004070077 8004070080 8004070083 8004070092	50-245	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8004180246 8004180248 8004180251 8004180255 8004180257	50-272 G 50-244 Q 50-271 Q 50-29 G 50-917 Q
OREER, R J	8004110274*	50-151 0	GRIER, B H	8004070093	50-352 Q	GRIER.B H	8004180260	50-320 G
OREGER, L R	8004070166*	50-10 0	GRIER, B H	8004070095	50-277 Q	GRIER.B H	8004180261	50-363 G
OREGO, R J	8004180392	70-820	GRIER, B H	8004070097	50-387 Q	GRIER.B H	8004180262	50-220 G
OREGO, R J	8004180046	70-820	GRIER, B H	8004070099	50-311 Q	GRIER.B H	8004180263	50-277 G
OREGO, R J	8004180020	70-820	GRIER, B H	8004090101	50-272 Q	GRIER.B H	8004110050	50-293 G
GREGORY.W S	8004240475	RES	GRIER, B H	8004090103	50-443 G	GRIER.B W	8004110053	50-322 Q
OREMER.E A	8004220207*	FOIA	GRIER, B H	8004090105	50-485 G	GRIER.B H	8004110054	50-245 G
OREMER.E	8004180197*	COMMISSION	GRIER, B H	8004090106	50-244 G	GRIER.B H	8004110058	50-410 Q
ORENDON.I	8004110147	ACRS	GRIER, B H	8004090107	50-271 G	GRIER.B W	8004110061	50-333 Q
ORENDON.A	8004020212	ACRS	GRIER, B H	8004090110	50-27 G	GRIER.B H	8004110063	50-352 Q
GRIDLEY,R L	8004070476*	50-293 P	GRIER, B H	8004300573	MIBC	GRIER, B H	8004110066	50-277 9
GRIER, B H	8004170304	50-334 Q	ORIER, B H	8004110122	50-293 Q	GRIER, B H	8004110068	50-387 0
GRIER, B H	8004090341*	50-317 Q	ORIER, B H	8004110124	50-317 Q	GRIER, B H	8004110071	50-354 0
GRIER, B H	8004070195	50-334 Q	ORIER, B H	8004110126	50-3 Q	GRIER, B H	8004110072	50-271 9
GRIER, B H	8004220416	50-272 Q	ORIER, B H	8004110128	50-213 Q	GRIER, B H	8004230386	50-220 0
GRIER.B H	8004070385	50-293 F	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004110131	50-334 0	GRIER, B H	8004230392	50-482 Q
GRIER.B H	8004210097	50-320 0		8004110133	50-412 0	GRIER, B H	8004230394	50-317 Q
GRIER.B H	8004110070	50-334 0		8004110134	50-363 0	GRIER, B H	8004230397	50-271 Q
GRIER.B H	8004080669	50-245 P		8004110137	50-219 0	GRIER, B H	8004230399	50-352 Q
GRIER.B H	8004080430	50-309 0		8004110140	50-322 0	GRIER, B H	8004230401	50-213 Q
GRIER, BH	6004080433	50-271 0	GRIER, B H	8004110147	50-320 0	ORIER, B H	8004230403	50-3 Q
GRIER, BH	8004260277	50-253 0	GRIER, B H	8004110154	50-307 0	ORIER, B H	8004230408	50-334 Q
GRIER, BH	8004070409	50-289 0	GRIER, B H	8004110156	50-245 0	ORIER, B H	8004230433	50-245 Q
GRIER, BH	6004080324	50-317 0	GRIER, B H	8004110158	50-220 0	ORIER, B H	8004230435	50-244 Q
GRIER, BH	8004040159	50-334 0	GRIER, B H	8004110159	50-410 0	ORIER, B H	8004230439	50-333 Q
ORIER, B. H	8004250338	50-293 8	GRIER, O H	8004110163	50-286 0	ORIER, B H	8004230442	50-272 Q
ORIER, B. H	8004110005	50-334 0	GRIER, O H	8004110499	50-333 0	ORIER, B H	8004230452	50-286 Q
ORIER, B. H	8004110008	50-293 0	GRIER, B H	8004110501	50-277 0	ORIER, B H	8004230455	50-311 Q
ORIER, B. H	8004090377	50-352 0	GRIER, B. H	8004110502	50-352 0	ORIER, B H	8004230459	50-309 Q
ORIER, B. H	8004090398	50-354 0	GRIER, B H	8004110504	50-367 0	ORIER, B H	8004230463	50-293 Q
ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8004090402 8004090404 8004090407 8004090409 8004090410	50-387 Q 50-245 Q 50-220 Q 50-333 Q 50-271 Q	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004110506 8004110507 8004110511 8004110512 8004110513	50-272	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8004230468 8004230472 8004230475 8004230476 8004230481	50-289 Q 50-485 Q 50-412 Q 50-219 Q 50-387 Q
ORIER, BH GRIER, BH GRIER, BH GRIER, BH ORIER, BH	8004090414 8004090416 8004090420 8004240552 8004210203	50-922 0 50-277 0 80-219 0 50-293 0 70-135	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8004110515 8004110518 8004240290 8004240293 8004240297	50-271 0 50-29 0 50-293 0 50-317 0 50-3 0	GRIER, B. H ORIER, B. H ORIER, B. H GRIER, B. H ORIER, B. H	8004230486 8004230491 8004230505 8004230505	50-410 d 50-322 d 50-320 d 50-320 d
GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8004210016 6004210037 6004150242 8004150247 8004150253	50-272	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8004240298 8004240302 8004240303 8004240306 8004240311	50-213 Q 50-334 Q 50-412 Q 50-363 Q 50-217 Q	GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H	8004230512 8004230516 8004180115 8004180117 8004180125	50-277 6 50-29 6 50-29 6 50-217 6 50-317 6

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ORIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8004180131 8004180134 8004180144 8004180149 8004180156	50-213	HAGUE.R L HAIRSTON.W G HAIRSTON.W G HAIRSTON.W G HAIRSTON.W G	8004110245* 8004010510* 8004010513* 8004150428* 8004080547*	50-266 0 50-348 5 50-348 5 50-348 8 50-348 8	HARNAGE, H H HARNAGE, H H HARNAGE, H H HARPER, R G HARRAN, G	8004080239 8004080239 8004240086 8004280045 8004180388*	50-250 G 50-250 G 50-250 G XPORTLIC 50-245 R
GRIER, B H	8004180161	50-322 0	HAIRSTON, W G	8004080554*	50-348 5	HARRAILG	8004210249*	50-245 R
GRIER, B H	8004180171	50-287 0	HAIRSTON, W G	8004220738*	50-348 5	HARRISON.H C	8004300081*	40-4492
GRIER, B H	8004180178	50-320 0	HAIRSTON, W G	8004220746*	50-348 5	HARRISON.H C	8004040094*	50-313 Q
GRIER, B H	8004180174	50-309 0	HAIRSTON, W G	8004270369*	50-348 6	HARRIS,J R	8004070043*	50-400 Q
GRIER, B H	8004180201	50-245 0	HAIST, D P	8004040161*	50-312 9	HARRIS,C E	8004020475*	TOPREP
GRIER, B H	8004180205	50-410 Q	HAIST, D P	8004300278*	50-397 G	HARRISON.G	8004020419#	50-373 F
ORIER, B H	8004180209	50-220 Q	HAIST, D P	8004280074*	50-460 G	HARRISON.J J	8004300536#	50-546 G
ORIER, B H	8004180212	50-286 Q	HAKANSSON, K	8004280488*	COMMISSION	HARRIS.J R	8004240360#	50-424 G
ORIER, B H	8004180245	50-333 Q	HALE, C J	8004070086*	GA999	HART.G	8004140469#	70-143
ORIER, B H	8004180252	50-277 Q	HALE, C J	8004150147*	GA999	HART.G	8004180016#	COMMISSION
GRIER, B H	8004180267	50-352 Q	HALE,C J	8004220244*	50~445 Q	HART, O	8004080314*	40-1341
GRIER, B H	8004180270	50-367 Q	HALL,R E	8004080696*	50~285 Q	HART, G	8004080250*	COMMISSION
GRIER, B H	8004180276	50-311 Q	HALL,R E	8004180218*	50~498 Q	HART, J	8004010347*	50-382 8
GRIER, B H	8004180280	50-272 Q	HALL,J D	8004070238	40~4492	HARTLEY, R H	8004210394*	50-445 M
GRIER, B H	8004180284	50-443 Q	HALL,R C	8004160050*	50~445 Q	HARTNETT, R A	8004070310*	50-382 8
GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIFFIN, R E	8004180287 8004180291 8004180293 8004180302 8004080041	50-244 Q 50-485 Q 50-271 Q 50-27 Q PR	HALL,RE HALL,RE HALL,RE HALL,RE HALL,RE	8004300035* 8004250083* 8004010357 8004010446 8004010329	50-498 Q 50-445 Q 50-295 F 50-29 F 50-171 F	HARTNETT, R A HARTNETT, R A HASS, W P HATMAKER, D F HAUCK, F	8004250352* 8004280605* 8004110537 8004140354* 8004170173	50-392 8 50-392 8 TOPREP 50-369 A 50-546 A
GRIMES, B K GRIMES, B K GRIMES, B K GRIMES, B K	7910180103 8004070184 8004080077 8004070406 8004080128	50-2 P 50-324 P 50-275 F NUREQ 50-320 P	HALL,R E HALL,R E HALL,R E HALL,R E HALL,R E	8004010336 8004010410 8004070243 8004070272 8004080515	50-266 F 50-409 F 50-333 F 50-254 F 50-206 F	HAUETER,R L HAUGHNEY,C J HAUGHNEY,C J HAUGHNEY,H M	8004110505 8004030315 8004140142 8004240560 8004150132	PR 50-201 W 50-201 P 50-201 P 71-97
GRIMES, B	8004030162	50-320 F	HALL,RE	8004100333	TOPREP	HAUSEN, D B	8004180307*	50~306
GROCE, R H	8004080263	50-309 Q	HALL,RE	8004100379	TOPREP	HAVERKAMP, D R	8004020097	
GROCE, R H	8004080634	50-309 P	HALL,RE	8004080449	50-331 F	HAVEY, G K	8004290510	
GROCE, R H	8004080406	50-309 R	HALL,RE	8004140403	50-271 F	HAUKINS, F C	8004040046*	
GROCE, R H	8004140308	50-309 P	HALL,RE	800'230318	50-295 F	HAUKINS, F C	8004040418*	
GROCE, R H GROSS, M GROSS, M GROSBMAN, H GROSBMAN, H	8004180438 8004030337 8004100501 8004080591 8004080567	50-309 P PR PR 50-155 Q 50-367 Q	HALL.R E HALL.R E HALL.R E HALL.R E HALL.R E	8004230387 8004230483 8004230510 8004230320 8004230524	50-263 F 50-317 F 50-271 F 50-206 F 50-254 F	HAYES, D W HAYES, W K HAYES, W K HAYES, D W	8004040199* 8004040046* 8004110535 8004210446 8004080190*	50-10 Q 50-546 Q PR PR 50-373 Q
GROBSMAN, H	8004100008	50-367	HALL,RE	8004250382	50-286 F	HAYES, D W	8004100252*	50-329 G
GROSSMAN, K	8004270087		HALL,RE	8004250385	50-331 F	HAYES, D W	8004040079*	50-483 Q
GROSSMAN, K	8004270166		HALLER,NM	8004010021*	10CFR	HAYFORD, D T	8004100025	NUREG
GROSSMAN, H	8004230075		HALLIGAN,TJ	8004020040	50-387 Q	HAYNES, R C	8004240522*	50-528 G
GROTENHUIS, M	8004020279		HAMMER,TJ	8004110074	50-312 Q	HAYNES, R C	8004280022*	50-275 Q
OROTENHUIS, M OROTENHUIS, M GROTENHUIS, M OROTENHUIS, M OROTENHUIS, M	8004100187 8004110093 8004140120 8004070179 8004090275	50-250 Q 50-250 P 50-250 P 50-250 F 50-250 F	HAMMER.M F HANAUERR.B H HANCHETT.J G HANCOCK.J A HANCOCK.D	9004010455* 9004020125* 9004150189 9004300151* 9004100078	50-263 \$ 50-3 0 50-361 H 50-302 0 50-466 0	HAYNES, R C HAYNES, R C HAYNES, J G HAYNES, J G	8004210417* 8004210186* 8004280095* 8004020327 8004030181	50-361 0 50-361 0 50-361 0 50-206 P 50-361 A
GROTENHUIS, M GROTENHUIS, M GROVES, K GROVES, K GROVES, K GROVES, K L	8004100486 8004140099 8004240314 8004180272 8004180099	50-282 P 50-282 P 71-107 71-49 71-273	HANCOCK, D HANCOCK, D HANCOCK, D HANCOCK, D HANCOCK, J A	8004100078 8004040445* 8004100532 8004100532 8004020318	50-466	HAYNES, J G HAYNES, J G HAYNES, J G HAYNES, J G HAZELTON, W S	8004080395 8004090324 8004180449 8004220446 8004010313*	50-204 F 50-206 P 50-206 P 50-206 P 50-338 0
OROVES, K. L OROVES, K. L OROVES, K. L OROWCOCK, F. D ORUENSFELLDER, K	8004150112 8004150123 8004300082 8004280041 7908210253*	71-367 71-116 71-9043 RE8 50-320 H	HANCOCK, J A HANCOCK, J A HANCOCK, J A HANN, C R HANNON, J	8004010488 8004070313 8004270480 8004250409 8004070176	50-302 R 50-302 8 50-302 S TOPREP 50-324 F	HAZLE,A J HAZLE,A J HAZLE,A J HECK,A E	8004070359* 8004110146* 8004300254 8004240116 8004080170	TASTE MOT WASTE MOT WASTE MOT WASTE MOT HOT HOT HOT
GRUSH, W H QUHIN, M A QUICH, P A QUMBLE, F W GUMBLE, F W	8004080684	RES	N L NONNAH	8004080113	50-293 P	HECTORIA	8004230148	WASTE MGT
	8004210080*	70-2478	N L NONNAH	8004080680	50-324 F	HEGARTYIN	8004280053*	XPORTLIC
	8004040107	XPORTLIC	N L NONNAH	8004090294	50-324 P	HEIBELIR P	8004010435*	50-317 S
	8004110442*	50-284 S	N L NONNAH	8004030332	50-293 P	HEIBELIR P	8004080488*	50-318 S
	8004140422*	50-286 B	N L NONNAH	8004150053	50-324 P	HEIBELIR P	8004080507*	50-317 S
QUMBLE.F W	8004180461*	50-286 8	HANNON, J N	8004300599	50-249 P	HEIBEL.R P	8004150486*	50-319 8
QUMBLE.F W	8004220749*	50-286 8	HANRAHAN, E J	8004290171	50-327 A	HEIBEL.R P	8004220621*	50-317 8
QUMPY.J Q	8004080290	RE8	HANBELL, D	8004140130*	50-347 G	HEIBEL.R P	8004220758*	50-318 8
QUMPY.J Q	8004100590	RE8	HANBELL, D	8004080181	40-2061	HEIBEL.R P	8004290497*	50-317 8
QUMPY.J Q	8004280071	RES	HANBELL, D	8004020273*	40-2061	HEIDER.L H	8004110444*	50-29 P
QUBTAVE,R P QUSTAVE,R P HAABB,W P HAELBIQ,R J HAFERA,T.	8004100366 8004100360 8004140083 8004220184 8004020445*	CONTRACT CONTRACT TOPREP 71-9130 50-265 B	HANSEN, W H HANSEN, L E HANSEN, C D HANSEN, R A	8004040062* 8004070216 8004140123 8004210147* 8004170257*	50-483 G 71-9009 50-367 G XPORTLIC 50-70 P	HEIDER, L. H HEIDER, L. H HEIBER, J. H HEISHMAN, R. F	8004110434 8004220307 8004270415 8004280041 8004040434	50-27 P 50-271 P 50-271 P RES 50-315 G
HAFER, F D	8004090477	50-320 I	HANSELL.D.	8004150461	50-367 P	HEISHMAN, RF	8004100013	50-344
HAGAN, T F.	9004080237	CONTRACT	HANBEN.R H	8004230417	NUREO	HEISHMAN, RF	8004080588	
HAGAN, T F	8004100572	CONTRACT	HARDIN.A K	8004080361	50-261 S	HEISHMAN, RF	8004100426	
HAGAN, T F	8004100189	CONTRACT	HARDIN.A K	8004070111	50-324 S	HEISHMAN, RF	8004080617	
HAGAN, T F	8004100339	CONTRACT	HARDWICK.R J	8004110575#	50-395 Q	HEISHMAN, RF	8004300014	
HAGEN, T F	8004210117	CONTRACT	HARKAHIK, D P	8004010060	FOIA	HEISHMAN, R F	8004100269	50-282 Q
HAGEY, H	8004070094	CONTRACT	HARLON, F H	8004270001	NUREQ	HEISHMAN, R F	8004180187	50-373 Q
HAGEY, H,	8004010002	CONTRACT	HARMON, D W	8004040135	XPORTLIC	HEISHMAN, R F	8004220157	50-295 Q
HAGEY, H	8004070006	CONTRACT	HARMON, D W	8004080032	XPORTLIC	HEISHMAN, R F	8004110230	50-266 Q
HAGEY, H,	8004250035	CONTRACT	HARMON, D W	8004280076	XPORTLIC	HEISHMAN, R F	8004070427	50-315 8

FENOUNAL AUTHUR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HEISHMAN.R F HEISKMAN.R F HEISHMAN R F HEISHMAN.R F HEISHMAN.R F	8004070192 8004090030 8004040059 8004090415 8004100081	50-315 S 50-315 S 50-315 S 50-346 Q 50-346 Q	HICKLEVB J HIESTAND.O S HIGGINBOTHAN.L HIGGINBOTHAN.L MIGGINS.J C	8004150395* 8004070303 8004220276* 8004220470* 8004070123*	50-285 R 50-409 P FOIA FOIA 50-322 Q	HOLLOWAY, C J HOLLY, J T HOLMAN, J F HOLODY, D J HOLTAN, A A	8004080123* 8004180433* 8004100342* 8004210104* 8004020324	FOIA 50-305 P CONTRACT 70-371 50-320 H
HEISHMAN,R F HEISHMAN,R F HEITMULLER,H HELM,K HELMS,R E	8004180172 8004280654 8004280532* 8004170183 8004150125*	50-315 Q 50-295 S 50-320 H XPORTLIC 71-116	HIFF'L D HICOIN2'A HICOIN2'A HICOIN2'A HICOIN2'A HICOIN2'A	8004100111* 8004100077* 8004160153* 8004210365 8004300274	50-387 G 50-322 G 50-293 G PT21 PT21	HOOD, D 8 HOPKING, L J HOPKING, H R HOPPER, D M HOPPER, D M	8004110020 8004140262* 8004040162* 8004030238* 8004170052*	50-329 A 50-358 U Contract 50-338 R 50-338 R
HEMMENDINGER, R HEMPLEREE, R HENDERSON, J & HENDERSON, J & HENDERSON, D M	8004080154 8004040241 8004070186 8004100301 8004270444	50-387 C 50-554 H PR 50-410 A 40-4622	A C.GNIH A C.GNIH A C.GNIH A C.GNIH A C.GNIH	8004080640* 8004040132* 8004070431* 8004040115 8004080637	50-263	HOREY, O K HORWITZ, F D HOSEY, C M HOSELI, W HOSELER, D E	8004180338 8004240051* 8004080043* 8004220017* 8004150372	50-320 R CONTRACT 50-340 0 50-316' P 50-320 H
HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRICKE, T J HENDRIE, J M	8004020109 * 8004020105 * 8004080048 * 8004030308 * 8004170112	50-3 G 50-3 G COMMISSION FOIA COMMISSION	Y C'QNIH Y C'QNIH Y C'QNIH Y C'QNIH	8004090428 8004030350* 8004030325 8004030349 8004110498*	50-305 Q 50-278 Q 50-255 Q 50-278 Q 50-285 Q	HOSTETTER, J HOUGHTON, F C HOVEY, G K HOVEY, G K	8004100578* 8004100584 8004140127* 8004140179 8004170023	50-320 H 50-416 F 50-367 0 50-320 P 50-320 P
HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J HENSLEY, K D	8004020195 8004070011 8004140392 8004210100 8004220081	COMMISSION 50-320 P COMMISSION 50-275 G 70-143	А С. (QИІН А С. (QИІН А С. (QИІН В. (ЗЗИІН В. (ЗЗИІН	8004110489 8004240513 8004300089 8004070135* 8004080649*	50-285 0 50-2 0 50-2 0 50-341 0 50-341 0	HONEA'O K HONEA'O K HONEA'O K HONEA'O K	8004150436 8004160290 8004170039 8004250377 8004240399	50-320 P 50-320 P 50-320 P 50-320 8 50-320 P
HENSLEY, K D HENSLEY, K D HENSLEY, K D HERBEIN, J G HERBEIN, J G	8004300085 8004180213 8004220219 8004070416* 8004300586*	70-143 70-143 70-143 50-287 Q 50-287 Q	HINES,E HIRT,C W HITCHENS,D C HITCHLER,M J HODDS,T C	8004300382 8004150141* 8004220761* 8004020432* 8004230029*	50-341 Q NUREQ 50-346 B TOPREP FOIA	HOVEY.G K HOVEY.G K HOWARD.J E HOWARD.J E	8004250433 8004250354 8004180339* 8004070470 8004100386	50-320 P 50-320 P 50-320 R 50-293 P 50-293 P
HERBEIN, J C HERBEIN, J C HERBEIN, J C HERBEIN, J C HERBEIN, J C	8004090013 8004020056 8004040336 8004010412 8004030241	50-289 Q 50-289 Q 50-320 B 50-289 P 50-320 I	HOCKERT, J HOCKERT, J HODDER, M H HODDER, M H HODDER, M H	8004020069 8004080197 8004210109 8004020239* 8004020272*	70-135 70-135 50-387 @ 50-389 @ 50-389 @	HOWARD, A S HOWE, P W HOWE, P W HOWE, P W HOWE, R S	8004170040 8004070058 8004070295 8004070035 8004150290	50-320 H 50-400 G 50-400 G 50-400 G 50-309 I
HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O	8004070284 8004070290 8004070291* 8004070319 8004070323*	50-289 P 50-289 P 50-289 P 50-289 P 50-289 P	HODGDON, A P HODGDON, A P HODGDON, A P HODGDON, A P HOEFLING, R K	8004030347 8004100126 8004150157 8004290227 8004030326	50-445 M 50-445 M 50-445 M 50-445 M 70-2623	HOWELL, 8 H HOWELL, 8 H HOWELL, 8 H	8004220521* 8004100368 8004010397 8004070293 8004090248	FDIA 50-329 Q 50-329 B 50-329 R 50-329 K
HERBEIN, J G HERBEIN, J G HERBEIN, J G HERBEIN, J G	8004070335 8004080540 8004080703 8004080707* 8004100350	50-320 R 50-289 P 50-289 P 50-289 P 50-320 F	HOEFLING:R K HOEFLING:R K HOEFLING:R K HOEFLING:R K HOELLER:J	8004230078 8004210009* 8004210007 8004160265 8004150498*	50-247	HOMETT'S H HOMETT'S H HOMETT'S H HOMETT'S H	8004090251* 8004080404 8004080431 8004100384 8004100387*	50-329 K 50-329 A 50-329 A 50-329 A 50-329 A
HERBEIN, JOHERBEIN, JO	8004110395 8004140386 8004170106* 8004230406 8004150349	50-287 P 50-289 P 50-289 P 50-287 S 50-289 P	HOENES, L G HOFFMAN, D P HOFFMANN, D P HOFFMAN, D P HOFFMAN, D P	8004270020 8004070383* 8004010289 8004040327 8004040371	NUREO 50-255 Q 50-255 P 50-155 P 50-255 R	HOWELL, S H HOWELL, S H HOWELL, B H	8004100390# 8004290157# 8004190354 8004170083 8004210225	50-329 A 50-339 G 50-329 B 50-329 B NUREG
HERBEIN, J G HERBEIN, J G HERBEIN, J G HERBEIN, J G	8004150446 8004150499 8004180473 8004220223 8004220224*	50-320 P 50-320 G 50-289 D 50-289 P 50-289 P	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	9004070320 8004030217 8004070305 8004080232 8004080470	50-255 P 50-255 R 50-255 P 50-255 P 50-155 S	HOYLE, J C HOYLETT, G, H HOYLETT, B H	8004210318 8004280440 8004220413* 8004150017 8004150077	50-327 8 50-327 F 50-336 R ACRS ACRS
Herbein, J G Herbein, J G Herbein, J G Herbein, J G	8004220542 8004170104 8004220454 8004230493 8004250367	50-287 P 50-287 P 50-287 P 50-287 R 50-287 P	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004070387 8004100374 8004100403 8004100413 8004280402	50-255 P 50-255 S 50-255 S 50-255 S 50-255 Q	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8004150111 8004150114 8004150241 8004140056 8004140089	ACRB ACRB ACRB ACRB ACRB
HERBEIN, J O HERBEIN, J O HERDT, A R HERDT, A R	8004280430 8004300409 8004020043# 8004040176#	50-320 I 50-320 F 50-375 G 50-259 G 50-438 Q	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004140334 8004150012 8004140309 8004150215 8004150330	50-255 Q 50-255 8 50-155 P 50-255 P 50-255 8	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8004150212 8004150222 8004150249 8004140043 8004180034	ACRB ACRB 50-280 P ACRB ACRB
	186 18 1	50-566 0 50-416 0 50-348 0 50-302 0 50-302 0	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D, P HOFFMAN, D P	8004150544 8004150627 8004180487 8004210158 8004220575	50-255 S 50-255 P 50-255 Q 50-255 P 50-155 Q	HOYLE'' C HOATE'' C HOATE'' C HOATE'' C	8004180032 8004180044 8004150244 8004180025 8004180049	ACRS ACRS ACRS ACRS ACRS
		0 0 0 0	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8004220588 8004230383 8004240372 8004240450 8004250354	50-255 G 50-155 H 50-155 P 50-253 P 50-255 S	HOATE'' C HOATE'' C HOATE''' C HOATE''' C	8004180406 804180498 80418053 804180506 8004180502	ACRS ACRS ACRS ACRS ACRS
			HOFFMAN, D P HOPFMAN, D P HOHN, A HOHN, A HOHNE, F C	8004250426 8004280519 8004220027# 8004220034* 8004040227	50-255 P 50-255 P 50-316 P 50-316 P 40-8502	HOATE'Y C HOATE'Y C HOATE'Y C HOATE'Y C	8004150254 8004150005 8004150245 8004040116 8004150248	ACR8 ACR8 ACR8 CONTRACT ACR8
			HOLCORB, 9 R HOLDEN, T J HOLLEY, M J HOLLEY, M J HOLLENBACHER, R	8004150171* 8004240063 8004240067* 8004240070* 8004220273*	CONTRACT XPORTLIC XPORTLIC 50-344 T 50-331 F	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8004150228 8004150232 8004150236 8004150240 8004180085	ACRS ACRS ACRS ACRS ACRS

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
HBIEH' 7 C HOAFE' 7 C HOAFE' 7 C HOAFE' 7 C	8004140035 8004070047 8004080576 8004220030 8004270474*	ACRS 50-3 Q 50-331 Q 50-247 G TOPREP	IPPOLITO, T A	8004110084 8004040127 8004110519 8004110525* 8004110525*	50-271 P 50-259 P 50-259 P 50-259 P 50-259 P	JOHN, D F JOHN, D F JOHNSON, T D JOHNSON, M C JOHNS, S J	8004080174 8004100478 8004210355* 8004020035* 8004070137*	50-445 M 50-445 M 50-320 P 50-375 G 50-155 H
HSU, C J FUBBARD, R D HUBERMAN, B HUDSON, G HUETER, L J	8004150475 8004210373* 8004030168* 7704110103 8004040034*	RES 50-275 G SECY 50-2 P 50-254 G	IPPOLITO, T A	8004110531* 8004100032 8004100037 8004210303 8004100602	50-259 P 50-220 P 50-263 P TOPREP 50-333 P	7014/80V' V H 7014/80V' V H 7014/80V' V H 7014/80V' M D	8004100335* 8004100303* 8004100034* 8004100182* 8004170273*	50-313 0 50-344 0 9A999 50-335 0 50-272 0
HUETER, L J HUFF, M HUFF, K HUFFAKER, T HUGHES, J	8004100383* 8004150601* 8004150579* 8004290501* 8004040179*	50-182 Q 50-368 F 50-368 F 50-369 A 50-10 Q	IPPOLITO, T A	8004230409 8004230414* 8004230441* 8004150185 8004230221	50-277 P 50-277 P 50-277 P 50-257 P 50-259 F 50-320 F	JOHNSON, D F JOHNSON, N R JOHNSON, R W JOHNSON, R R JOHNSON, M C	8004220427* 8004040990 8004020225 8004070347* 8004020201	50-272 Q XPORTLIC 50-344 Q 50-320 R 50-375 Q
HUCHEB, J HULMAN, L G HULMAN, L G HUNNICUTT, D M HUNNICUTT, D M	8004040052* 8004270119* 8004270125* 8004070071* 8004270212*	50-341 Q 40-3453 40-3453 GA999 GA999	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8004240167 8004180253 8004180258# 8004180278# 8004210008	50-333	H C, AUSANHOL JOHNSON, C R JOHNSON, W P JOHNSON, W P JOHNSON H H	8004230073 8004040375 8004090458 8004080384 80042801434	PR 71-6698 50-309 Q 50-271 9 50-348 Q
HUNNICUTT, D M HUNNICUTT, D M * HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	8004080287* 8004140043* 8004030244* 8004010515* 8004080389*	GA797 GA797 GA797 GA797 GA797	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8004280252 8004240299 8004240307* 8004240329* 8004250007	50-277 F 50-277 P 50-277 P 50-277 P 50-277 P	70HN2ON, M P 70HN2ON, M D 70HN2ON, M D 70HN2ON, M D	6004300119* 8004280125* 8004250299* 8004080697 8004080351	50-395 Q 50-250 Q 50-313 Q 50-397 G 50-309 Q
HUNNICUTT, D M	8004090299* 8004080316* 8004290031* 8004300222* 8004220315*	GA999 GA999 GA999 GA999 70-2623	IPPOLITO, T A	8004250017 8004250021 8004250024 8004250032 8004250034	50-271 P 50-263 P 50-331 P 50-333 P 50-220 P	0 א מסבאאטרים א אמספאאטר הספאפטטי ע הספאפטטי א הפאאסטי א ה	8004080267 8004140061 8004100369* 8004040063 8004280087*	50-271 G 50-320 G CONTRACT 50-344 T 50-344 G
HUNSTAD, A A HUNSTAD, A A E-UNSTAD, A A HUNSTAD, A A HUNSTAD, A A	8004140344* 8004080484* 8004140440* 8004150603* 8004180386*	50-282 R 50-282 S 50-282 S 50-282 S 50-396 S	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8004250037 8004280027 8004290028 8004290053 8004290104	50-293 P 50-293 P 50-259 P 50-321 P 50-249 P	JOHNBON, M C JOHNBON, P H JOHNBON, M C JOHNBON, M C	8004170085 8004280277* 8004250394* 8004160110 8004100306	50-395 5 50-397 0 50-10 H 50-395 0 XPORTLIC
HUNSTAD.A A HUNT.M D FRUNT.M D HUNT.M D HUNT.M D	8004230359* 8004090084* 8004090374* 8004020194* 8004070331*	50~282 8 50~400 0 50~280 0 50~424 0 50~400 0	IPPOLITO,T A IPPOLITO,T A IRBY,8 C IRLEYN,K S IRVINO,8 M	8004300610 8004230283 8004030028# 8004270501# 8004230466	50-298	лониаои, и с лониаои, и с лониатои, и с лониаои, и с	8004140455 8004300478 8004280182 8004250404 8004250429	NUREO 50-395 Q TOPREP 50-395 9 50-395 9
HUNT, K D HUNTER, V H HUNTER, V H HUNTER, R S HUNTER, R S	8004070183 8004040122* 8004070310* 8004210180 8004180181*	50-416 8 GA999 GA999 PR 50-315 G	19HII.M 1VERBON.O N JABLON.R A JACKIW.I N JACKBON.L L	8004100591 8004150610# 8004230176 8004080664 8004290141#	NUREO 50-263 8 50-389 M 50-331 B 50-324 Q	ADMES'O C ADMES'O C ADMES'O C ADMES'O C	8004300436 8004080302 8004070312 8002040380 8004080274	50~280 J RES RES 50~320 G RES
HUNTER: R. S P-funter: R S H-unter: R S J-funter: R, S J-fuseby: D E	8004140324 8004150509 8004150507 8004150510* 8004010368*	50-315 J 50-315 P 50-315 F 50-315 F 50-316 S	JACKSON, P D JACKSON, R E JACOBSON, D A JACOBS, A	8004210301 8004300021 8004020205 8004110127 8004150166	NUREQ 50-553 A CONTRACT REGOD TOARTHOO	JONES, O C JONES, C E JONES, D W JONES, W C	8004070324 8004100599 8004040040# 8004100482* 8004230086	RES RES 50-373 G 70-1151 50-285 G
HUSEBY, D E 14USEBY, D, E 14USEBY, D, E 14USEBY, D, E, 14USEBY, D, E	8004150638* 8004220621* 8004270350* 8004270416* 8004270447*	50-318	JACOBB: A. JACOBB: A JACOBB: J C JACOBB: J C JAMEB: M	8004240047 8004240009 8004220152 8004220152 8004270280	CONTRACT CONTRACT 50-445 M 50-449 M 50-133 G	JONES, E JONES, D W JONES, C E JONES, C E	8004230128* 8004040021* 8004040147* 8004140021 8004280074*	50-309 Q 70-1201 50-500 Q 50-285 Q 50-454 Q
Huston, R W Huston, R W Huston, R W Huston, R. W Huston, R W	8004020166 8004020285 8004250313 8004250425 8004270324	50-255 P 50-155 R 50-255 Q 50-255 P 50-155 Q	JAMEB, 8 W JANACEK, R F JANACEK, R F JANECEK, R F JANECEK, R F	8004240565 8004070245 8004110458 8004010359 8004040341	NUREO 50-237 P 50-237 P 50-237 P 50-10 P	JONES, W C JONES, W C JONES, D C JONES, W C	8004220001 8004010346 8004140362 8004280038 8004150391	50-275 0 50-285 P 50-285 P RES 50-285 R
F-(UTTON, PH 1-(YDE, DW 1-(YDE, DW 1-(BBER, HW, 1-(FFLAND, RR	8004040342 8004100418 8004140105 8004010382 8004150379	RE8 PR PR 50-312 Q 50-213 J	JANECEKIR F JANECEKIR F JANECEKIR F JANECEKIR F JANECEKIR F	8004080235 8004070227 8004110399 8004150344 8004180217	50-237 P 50-10 P 50-237 F 50-10 F 50-10 P	JDNES, W C JONES, J A JONESD, J H JORDAN, E L	8004220561 8004280560 8004280561 8004080143 8004220245*	50~205 P 50~400 S 50~400 S 50~387 G FOIA
E FFLAND, R. R. E QNE, E. E QNE, E E QNE, E E NGRAH, F	8004160254 8004070241* 8004070239 8004040246 8004180109	50-245 J ACRB ACRB ACRB 50-287 H	Janecekir F. Janecekir F Janecekir F Janencekir F Janinekim	8004220332 8004220348 8004230072 8004140395 8004250068	50-10 P 50-237 P 50-10 P 50-237 P State Prog	JORDAN, W H JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	8004220350 8004160138* 8004160131 8004160138* 8004280026	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0
I MHAN, O W. I PPOLITO, T A I PPOLITO, T A I PPOLITO, T A I PPOLITO, T A	8004140455 8004080294 8004070377 8004070381 8004070384	NUREQ 50-237 P 50-263 P 50-249 P 50-289 P	JANINEK, M JANEURA, A G JAPE, F JAPE, F JARKE, R, T	8004270167 8004030327* 8004230277* 8004250357* 8004040379	State Prog FOIA 50-247 G 50-249 G NUREG	JORDAN, W S JORDAN, W H JORGENSEN, B L JORGENSEN, G D JOSEPH, R L	8004280026 8004100222 8004030327* 8004100357* 8004040403*	50-287 0 50-287 0 FDIA CONTRACT 71-35
I PPOLITO, T. A I PPOLITO, T. A I PPOLITO, T. A I PPOLITO, T. A I PPOLITO, T. A	8004070370 8004070375 8004070397 8004070400 8004070402	50-278 P 50-331 P 50-133 P 50-333 P 50-220 P	JAX,M JEANEB.J W JEPKINS.G R JENKINS.G R	8004150129 8004030038* 8004040412 8004040365* 8004040402*	70-1308 50-320 H 40-8760 50-250 Q 50-269 Q	H C'ABANAOC H C'ABANAOC H C'ABANAOC H C'ABANAOC	8004220068* 8004080354* 8004100209* 8004070207* 8004080599*	70-1143 70-135 70-135 70-135 70-1100 70-364
IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A, IPPOLITO, T A, IPPOLITO, T A,	8004070404 8004070405 8004070408 8004080187 8004080194	50-324 P 50-273 P 50-271 P 50-321 F 50-277 P	JENKINS' G K JENKINS' G K JENKINS' G K JENKINS' G K	8004070134* 8004140480* 8004070195* 8004150477* 8004150526*	50-339	H L'ABNAOC H C'ABNAOC H C'ABNAOC H C'ABNAOC H C'ABNAOC	8004070417* 8004100555* 8004070217* 8004100092* 8004100030*	70-135 70-135 70-135 70-364 70-820

	***************************************	CUBUECT		ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR JOYNER, J H JULIAN, C	NUMBER 80042200414 7 80042102064 3	EATEDBRY 70-371 90-160 0 90-259 H	AUTHOR WELLINGS, F J HELLINGS, P J RELLINGS, P J	8004280057+ 8004050111 8004080184+	CATEGORY 50-324 G 50-324 S 50-337 G	KEPPLER, J G KEPPLER, J G KEPPLER, J G VEPPLER, J G	0004100125 0004100129 0004100132 0004100134	50-440 0 50-329 0 50-155 0 50-409 0
JURERYO, R C JURGENSEN, R H KABAK, A C KAHLE, J B	800402J120# / 8004240103 F	1095 1014 70-1113	WELLY, A WEMPER, J S WEMPER, J S	80042300719 8004133424	50-320 H 50-352 G 50-352 G 50-277 P	KEPPLER, O O VEPPLER, J O VEPPLER, J G	8004100175 8004100136 8004100137 8004100143	50-331 R 50-367 G 50-263 G
VANLE. J B KAHLE. B KAHN. R D VALEER, W T	8004280255+ 3	70-1151 70-1319 FOIA 50-20a P	KEMPER, J S KEMPER, J S FEMMA N B KEMMA N B	80013003A8 8004090240* 8004040044*	50~352 5 70~143 70~143 70~143	KEPPLER J G KEPPLER, J G KEPPLER J G	8004100144 9004100146 8004100148	50~546 0 50 346 0 50~483 0
VALIVIANAKIS:N KALIVIANAKIS:N KALIVIANAKIS:N KALIVIANAKIS:N	6004020422 8001020475 8004020350	50-254 R 50-254 S 50-265 S 50-254 S 50-265 S	KEMIA, U B KEMIA, U B KEMIA, W B KEMIA, W B KEMIA, W B		70-113 70-113 70-143 70-1151 70-1151	KEPPLER, J G KEPPLER J G KEPPLER J G KEPPLER, J G	6004100149 6004100153 6004070212 6004070221	50~284 G 50~305 G 50~331 P 50~409 P
Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakas, n Kalivianakis, n	8094020430 8394150483 8094150482 8004150487 8094220613	50-245 S 50-254 S 50-245 S 50-254 S 50-25 S	FENNA, W B KENNA, W B KENNA, W B KENNA, W B	6001040535 604040113 604040113 6040404013	70-1201 70-247B 70-143 70-1201 70-143	MEPPLET, , O KEPPLET, J G KEPPLET, J G KEPPLET, J G	8004070378 6004080187 8004080224 8004090379 8004100076	50-283 P 50-305 F 50-286 P 50-255 G 50-155 P
Kal Ivianakas, n Kal Ivianakis, n Kal Ivianakis, n Kal Than, n Kamm, r	8004220333 8004270380 8004250271 8004080080# 8004140483	50-254 R 50-255 S 50-320 P FOIA MISC	Kenna, W B Kenna, W B Kenna, W B Kenna, W B Kenna, W B	8004100456 8004070354 8004070341* 8004110545 8004110562	70-1151 70-143 70-143 70-2479 50-30P 9	KEDDFEWY O KEDDFEWY O KEDDFEWY O KEDDFEWY O KEDDFEWY O	9004100102 9004100114 9004100154 9004100165 9004100170	50-10 P 50-409 P 50-255 P 50-315 P 50-331 P
KAMMERER, C KANAK, K K KANE, J D KANE, J D KANE, J F	8004140095 8004270115* 8003200211 8004110522 8004100082	RES 40-3453 50-362 A 50-470 A	KENNA, W B KENNA, W B KENNA, W B KENNA, W B KENNEDY, R T	8004210155 8004220188 8004290170 8004290151 8004280471	COWM!8210H 20-334 d 20-324 d 20-392 d 20-1113	KEPPLER, J C KEPPLER, J C KEPPLER, J C KEPPLER, J C	8004100172 8004100175 8004100183 8004100185 8004240524	50-246 P 50-346 P 50-263 P 50-305 P 50-346 F
KAPLAN A L KAPLAN A L KAPLAN A L KAPLAN A L HAPLAN A L	8004110129 8004160078 8034230163 8004210162*	PR PR 70-1113 70-1113 70-1113	KEMNEDY, R T KEMNEDY, R T KEMNEDY, R T KEMNEDY, R T KEMNEDY, R T	8004280485 8004300597 8004290126 8004300233 8004297131	COMM18810A COMM18810A COMM18810A COMM18810A COMM18810A	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G WEPPLER, J G	8004240591 8004240540 8004300012 8004200925 8004200925	50-10 F 50-155 F 50-318 F 50-349 B 50-546 B
MAPLAN, A L MAPLAN, A L MAPLAN, A L MAPLAN, A L MAPLAN, A L	8004180121 8004090149 8004090149 8004020143 8004180515 8004220789	70-1113 70-1113 71-9019 70-1007 71-9019	KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY B T KENNEDY, R T	8004390231 8004290134 8004300591 8004280444 8004290144	CONWIESIDM COUNIESIDM CONWIESIDM CONWIESIOM COMMIESIOM	MEPPLER, J G MEPPLER, J G KEPPLER, J O KEPPLER, J G	8004140484 8004150162 8004150153 0004150159 8004150163	50-315
Maplan, a l Maplan, a l Mapple, a w Mapple, a w Marman, m	6004220790 * 8004010370 * 8004110494 * 8004290217 8004220367 *	71-9019 50-272 S 50-2/2 S 50-454 G FOIA	KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T	5004280448 8004280450 8004280453 8004280464 8004280468	CONWISSION CONWISSION CONWISSION COWWISSION	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004150165 8004150167 8004150170	50-440 0 50-327 0 50-155 0 50-409 0 50-341 0
KARTHA, H X KARTHA, H X KARTHA, H X KATZ, B E KAUFHAN, N C	8004220444* 8004220539* 8004220013 8004080075 8004070038	F01A F01A F01A RES 40-8728	KENNERLY, F M KENNETT, R J KENT, B G KEPFORD, C R KEPFORD, C	8904220331* 8004280071 8004[40 <i>268</i> 8004[40 <i>06/</i> * 8004[40 <i>076</i> *	70-2623 RES 50-387 A 50-320 G 50-320 G	C L,REPLER, J C KEPPLER, J C KEPPLER, J C KEPPLER, J C KEPPLER, J C	904150174 8064190175 8064150186 8064150184 9664150186	50~J3) d 50~46) d 50~367 d 50~269 d 50~546 d
Kaufhan, R Kaufhan, D Katanar, B Hay, J Kay, J Kay, J	8004100504 8004240190* 8004230064 8004100370 8004110415	50-289 H 50-2905 50-29 P 50-29 P	KEPFORD, C KEPFORD, C KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004110477 8004240544 8004226051* 8004220156* 8004220125*	PR 50-207 G FOIA FOIA FOIA	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J G	0004150191 8004150192 8004150194 8004150196 8004080686	50-346 G 50-483 G 50-266 G 50-305 G 50-10 G
Kay, Ja Kay, Ja Kearns, J Kearney, J Kee, e J	0040854008 0540014008 74E0114008 484080608	50-27 F PR PR RES TOPREP	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220164* 8004220227* 8004220231* 8004220244* 8004220251*	FOIA FOIA FOIA FOIA FOIA	KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J G KEPPLER.J G	8004080494 8004080498 8004080702 8004080704 8004080706	50~358 G 50~440 Q 50~327 G 50~155 Q 50~407 Q
KEENAN, TP HEEPLER, JQ KENDE, D HENDE, D HENDE, DV	8004040326 8004290039 8004040411* 8004160153* 8004090473* 8004040244	50~295 F 50~293 G 50~293 G	Keppler, J G Keppler, J G Keppler, J G Keppler, J G Keppler, J G	8004220259* 8004220267* 8004220314* 8004220319* 8004220323*	FOIA FOIA FOIA FOIA	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	BDD4DBD708 BDD4QBD714 BD04QB0714 BD04QB0717 BDQ4QB0718	50-341 0 50-331 0 50-441 0 50-315 0 50-367 0
Keinig r Keinig r Keinig r Keinig r Keinig r	8004040244 80042600904 80040902628 80040904228 80040804508	50-352 H 50-334 P 50-219 G	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220329* 8004220333** 800422033** 800422036**	FOIA FOIA FOIA FOIA FOIA	KEPPLER, J O MEPPLER, J O MEPPLER, J O MEPPLER, J O MEPPLER, J O	8004080717 8004080721 8004080724 8004080725 8004080727	50-245 G 50-345 G 50-345 G 50-483 G 50-246 G
Keimig, r r Keimig, r r Keimig, r r Keimig, r r Keimig, r r	8004170293+ 8004220429+ 8004210450+ 8004180147+	50-272 G 50-272 G 50-219 G	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J G KEPPLER, J G	8004220403* 8004220465* 8004220467* 7906050031 8304170262*	F01A F01A F01A MISC 50-255 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004080778 8004180011 8004180014 8004180024 8004180034	50-315 Q 50-10 Q 50-358 Q
MELLEY, D L MELLEY, D L MELLEY, W D MELLOGO: P J MELLOGO: P J	8004090118 80040402621 8004080696 80041000091 80041004161 80040902821	* 50-285 d * 50-285 0 * 04999 * 50-395 0	KEPPLER.J O KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8004040022 8604100548 800400414 800400488 8003310412	50-341 0 40-261 50-546 0 50-315 0 40-215	KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O	8004150035 8004150035 8004150035 8004150046	50-155 D 50-407 D 50-341 Q
MELLOGO.P J MELLOGO.P J MELLOGO.P J MELLOGO.P J MELLOGO.P J	8004070413 8004240398 8004280014 8004280157 8004080361	* 50-327 0 * 50-338 0 * 50-395 0 * 50-325 0	Keppler, J o Keppler, J o Keppler, J g Keppler, J g Keppler, J g	8004230167 8004020268 8004100114 8004100118 8004100123	50-123 a 30-258 a 30-258 a	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	B00415004 B00415004 B00415005 B00415005 B00415005	9 50-367 G 2 50-263 G 4 50-546 G

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004150057 8004150059 8004150061 8004180018 8004180030	50-483	KEPPLER, J G	8004230285 8004230288 8004230291 8004230297 8004240561	50-344 Q 50-244 Q 50-305 Q 50-243 Q 50-331 F	KISTER, H B KISTER, H B KITTRIDGE, G R KITTRIDGE, G R KLAMERUS, L J	8004100077* 8004210071* 8004090156 8004210160* 8004280206*	50-322 Q 50-244 Q PR PR REVIEW QRP
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004180037 8004180038 8004180040 8004180041 8004180048	50-358 Q 50-440 Q 50-155 Q 50-329 Q 50-409 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004300479 8004290080 8004220047 8004220053 8004220057	50-266 P 50-123 0 50-263 0 50-266 0 50-346 0	KLEIN, J V II KLEIN, J V KLEIN, P W KLEINSDRGE, II P KLEIN, B	8004100046* 8004100450* 8004040129 8004300108* 8004030012	PR 50-516 T 50-322 G 50-566 Q 50-312 H
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004180050 8004180051 8004180052 8004180054 8004180055	50-341 Q 50-331 Q 50-461 Q 50-367 Q 50-263 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220060 8004220069 8004220089 8004220094 8004220098	50-305 Q 50-10 Q 50-331 Q 50-546 Q 50-483 Q	KLEIN, D KLEIN, D E KLIGFIELD, O KLIGFIELD, O	8004240416 8004240420+ 8004240012 8004240022 8004250057	50-128 R 50-128 R NUREG NUREG NUREG
MEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8004180059 8004180060 8004180063 8004180065 8004180067	50-546 Q 50-346 Q 50-483 Q 50-266 Q 50-305 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220100 8004220104 8004220108 8004220114 8004220121	50-341 0 50-409 9 50-358 0 50-367 0 50-329 0	KLINGER, G KLINGER, G KLINGER, G KLINGER, G KLINGER, G	8004210433 8004210440 8004210441 8004210224 8004180517	50-304 S 50-247 S 50-335 S 50-344 S 50-346 B
MEPPLER, J G MEPPLER, J G MEPPLER, J G MEPPLER, J G MEPPLER, J G	8004220090 8004220093 8004220113 8004220118 8004220123	50-315 G 50-10 G 50-358 G 50-440 G 50-155 G	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220129 8004220139 8004220144 8004220149 8004150489*	50-315 0 50-440 0 50-461 0 50-155 0 50-341 0	KLINDER.G KLINDER.G KNAPP.P J KNAPP.P J KNAPP.P	8004180518 8004180520 8004100173# 8004210173* 8004090027	50-257 S 50-255 S 50-220 G 50-273 G 50-213 S
KEPPLER, J. G KEPPLER, J. G KEPPLER, J. G KEPPLER, J. G	8004220126 8004220135 8004220138 8004220140 8004220142	50-329 Q 50-409 Q 50-341 Q 50-331 Q 50-461 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J O	8004300166 8004300178# 8004300184# 8004300189# 8004300174#	50-483	KNOGHTAR J KNOPAR C KNOPAR C KNOPAR C KNOPAR C	8004170270 8004040062* 8004040475* 8004040052* 8004210142*	XPCRTLIC 50-483 O 50-327 O 50-341 G 50-359 O
KEPPLER, J. O KEPPLER, J O KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220145 8004220148 8004220150 8004220151 8004220153	50-367 G 50-263 G 50-546 G 50-346 G 50-463 G	KERNE, A C KERR, G W KERR, G W KERR, G W KERR, G W	8004100040* 8004110144 8004070355* 8004140181 8004040470	50-443 Q WASTE MGT WASTE MGT State Prog State Prog	KNOP.R C KNOP.R C KNOP.R C KNOP.R C KNOTS,J B	8004100267* 8004070037 8004040037 6004040048 8004230033	50-327 G 50-327 B 50-461 B 50-341 B 50-449 M
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8004220158 8004220160 8004220324 8004220336 8004220339	50-266 G 50-305 Q 50-10 G 50-329 G 50-315 G	KERR, O W KERR, O W KERR, O W KERR, G W KERR, W	8004070368 8004140189 8004240077 8004240081* 8004040385	State Prog State Prog State Prog State Prog 50-2 P	G C'SILLONX G C'SILLONX G C'SILLONX G C'SILLONX	8004030258 8004080401 8004180151 8004240173 8004240173	50~445 M 50~445 M 50~445 M 50~445 M 50~445 M
KEPPLER, J O KEPPLER, J O KEPPLER, J G KEPPLER, J G KEPPLER, J G	8004220344 8004220347 8004220354 8004220357 8004220345	50-356 G 50-440 G 50-341 G 50-407 G 50-155 G	KERR, O W KERR, O W KERR, O W KERR, O, W KETCHEN, E O	8004240002 8004240004* 8004280323 8004280327* 8004020086	ORO ORO State Prog State Prog 50-275 O	E C'SLLONY E C'SLLONY E C'SLLONY E C'SLLONY	8004240071* 8004240562 8004220021 8004240562 8004230033	50-449 M 50-445 M 50-445 M 50-445 M 50-445 M
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J. O	8004220368 8004220373 8004220378 8004220382 8004220384	50-441	KETCHEN, E G KETCHEN, E G KETCHEN, E G KETCHEN, E O KETCHEN, E G	8004080372 8004180432 8004230081 8004160197 8004230210	70-2423 50-269	KNUDBON, D A KNUTH, D F KDCH, E I KOCIB, R KDESTER, G L	8004290467* 8004250071 8004220355* 8004110386* 8004040264	50-390 A PR FOIA 50-344 B 50-482 S
KEPPLER, J. O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J. O	8004220388 8004220392 8004220395 8004220398 8004220058	50-483 0 50-266 0 50-305 0 50-546 0 70-8	KEY,W J KEY,W J KEY,W J KEY,W J	8004020193 8004030255* 8004040339* 8004110176* 8004280025*	70-1100 50-306 G 50-275 G 50-440 G 50-265 G	KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L	8004010030 8004010034 8004170172 8004070292 8004220730	50-482 G 50-482 B 50-482 B 50-482 G 50-482 I
KEPPLER, J. O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8004220059 - 8004220063 8004220065 8004220066 8004220070	70-572 70-1308 40-7982 40-2061 70-925	KIDDS,M S KIMBLE,K KIMMEL,J J KINDER,E T KINDER,E T	8004240398* 8004280340* 8004030014* 8004100612* 8004070187	50-338 Q 50-320 H CONTRACT PR PR	KOHL, K A KOHLER, J E KOHLER, J E KOJAHN, C	8004140322* 8004140340* 8004220175* 8004280641 8004210375*	50-275 R 50-10 R 50-295 Q 50-275 B 50-275 Q
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J, Q,	8004220073 8004110023 8004110025 8004110032 8004110033	70-1193 50-373	KINDER, E T KING, W H KING, B. KINNEMAN, J KINNEMAN, J	8004070202* 8004020137* 8004020159 8004090178 8004090197	PR 71-5939 Waste Mot I&E I&E	KOLTAY,P S KOLTAY,P KOMES,J M KOMES,J M KONAK,K K	8004070231* 8004090262* 8004090386* 8004090377* 8004040349	50-245 Q 50-217 Q QA999 QA999 RES
KEPPLER, J. O KEPPLER, J. O KEPPLER, J O KEPPLER, J O KEPPLER, J. O	8004110034 8004110035 8004110036 8004110041 8004110042	50-155 G 50-409 G 50-341 G 50-331 G 50-461 G	KINSEY, W. H KINSEY, W. H KINSEY, W. H KINSEY, W. H KINSEY, W. H	8004020371* 8004010506* 8004070426* 8004080526* 8004080622*	50~327 \$ 50~327 \$ 50~327 \$ 50~327 \$ 50~327 \$	KOWALCZYK, W J KOWALCZYK, W J KOWALCZYK, W J KOWALCZYK, W J	8004110176* 8004280074* 8004080352* 8004090274* 8004010282	50-440 Q 50-454 Q 50-317 Q 50-320 H FOIA
KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8004110043 8004110047 8004230196 8004230197 8004230201	50-367 Q 50-263 Q 50-155 Q 50-409 Q 50-440 Q	KINBEY,W H KINTNER,L L KINTNER,L L KIRBY,M S KIRK,W F	8004090433# 8004090155 8004110/88 8004180337* 8004210/63	50-327 B 50-413 A 50-341 A 50-390 R 70-371	KRAUSE, L KREPS, A H KREMSER, T R KRIEMELMEYER, H KROES, R J	8004030352 6004150431 6004160151# 8004070279# 8004070328	50-382 H 50-124 P 70-1251 50-320 H 50-433 R
KEPPLER, J O. KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J. O.	8004230207 8004230211 8004230219 8004230224 8004230245	50-358	KIRK.W F KIRKEBO,J A KIRKLAND.R 8, KIRKLAND.R 8 KIRKLAND.R 8	8004210067* 8004040¢57* 8004280486 8004280477 8004280\$12	70-371 50-458 S 50-140 S 50-140 S 50-160 S	KROOM, J C KROON, J C KROON, J C KRSYKWA. E J KRUG. M E	8004100543 8004100071 8004220210 8004300061* 8004280231	REGGD REGGD REGGD 50-387 G WASTE MOT
KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8004230250 8004230264 8004230274 8004230280 8004230282	50-346 G 50-461 G 50-331 G 50-367 G 50-483 G	KIRSCH.DF KIRSCH.DF KISIELESKI.WE KISS.E KISTER.HB	8004240522* 8004280022* 8004100584 8004070476* 8004070123*	50-528 G 50-275 G NUREG 50-273 P 50-322 G	Т 6 '9ВЗВППО Т С Ч НЭГПОР Т С Ч НЭГПОР Т С С Ч НЭГПОР Т С С Ч НЭГПОР	8004180307* 8004150400 8004110308 8004040108 8004180127	50-304 Q 50-320 H 50-155 P 50-387 H 50-344 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
KURTH, W R	8004220702*	50-304 8	LEGNARD, J D	8004220445	50-333	LEWIS, S R	8004160232*	50-287 5
MURTI, R J	8004040342	RES	LEGNARD, J D	8004080419		LEWIS, R C	8004300143	50-302 G
KUBHNER, W L	8004080354*	70-135	LEGNARD, J D	8004090125		LEWIS, S R	8004220690*	50-269 5
KUSHNER, W L	8004080733*	70-135	LEGNARD, J D	8004090452		LIAW, B D	8004150042	NUREG
KUSHNER, W L	8004100209*	70-135	LEGNARD, J D	8004080266#		LIAW, B D	8004280103	TOPREP
KUSHNER, W L	6004090733*	70-135	LEONARD, J D	8004030273	50-393 8	LIBERMAN, J	8004210232	50-295 O
KUSHNER, W L	8004100555*	70-135	LEONARD, J D	8004030216	50-393 8	LIBRIZZI, F P	8004010331	50-272 P
KYGER, J A	6004140470	NUREO	LEONARD, J D	8004070296	50-393 R	LIBRIZZI, F P	8004010322	50-272 B
KYLE, J B	8004090229	PR	LERNER, N C	8004080340*	CONTRACT	LIBRIZZI, F P	8004010354	50-272 B
KYSHNER, W L	6004220068*	70-1143	LESH, L	8004220181*	50-320 H	LIBRIZZI, F P	8004040317	50-272 B
LADUN,R H	8004070221#	50-201 0	LESLIE.R B	8004210329*	50-275 G	LIGRIZZI,F P	8004080370	50-272 P
LADUN,R	8004100068*	50-334 0	LESSOR.L C	8004280574	50-298 S	LIGRIZZI,F P	8004110492	50-272 B
LADUN,R H	8004250059*	50-213 0	LESSOR.L C	8004090303	50-298 R	LIBRIZZI,F P	8004080525	50-272 B
LAGERGREN,B	8004220707*	50-327 S	LEVINSON.C F	8004080134*	FOIA	LIGRIZZI,F P	8004110497	50-272 G
LAGIEWSKI,J S	8004010448*	50-318 S	LEVIN.H A	7812060303	50-10 P	LIGRIZZI,F P	8004140320	50-272 B
LAGIEWSKI, J S	8004010388*	50-31B S	LEVINE, S	8004020158	res	LIBRIZZI,F P	8004140407	50-272 8
LAGIEWSKI, J S	8004150620*	50-317 S	LEVIN, C	7709140279	Misc	LIBRIZZI,F P	8004150553	50-272 8
LAGIEWSKI, P G	8004250417*	50-31B S	LEVINE, S	8004230300	Res	LIBRIZZI,F P	8004170062	50-272 P
LAGIEWSKI, J S	8004290377*	50-317 S	LEVINE, M M	8004080589	Res	LIBRIZZI,F P	8004250366	50-272 P
LAGIEWSKI, J S	8004290388*	50-317 S	LEVINE, M M	8004100594	Res	LICHTENBEROER,H	8004210138*	70-1100
LAGIEWSKI, J S LAGUMARSING, R J LAINAS, G LAINAS, G LAINAS, G	8004270472* 8004030013 7908030084 7908100158 7910020720	50-317 5 50-275 U MISC MISC MISC	LEVINSON, J () LEVIN, K F LEVIN, K F LEVIN, K F LEVINSON, J O	8004030025* 8004100027 8004100027 8004100027 8004030018*	50-3 H 50-454 G 50-454 G 50-454 G 50-3 H	LICHTENBERGER LICHTENBERGER, H LICITRA, E A LICITRA, E A LICITRA, E A	8004240169 8004210130* 8004040472 8004100526 8004140486	70-1100 70-1100 90-311 A 50-311 A
LAINAS, Q LAINAS, O LAINAS, Q LAMACCHIA, P J LAMB, H R	8004020178 8004030107 8004070263 8004290113* 8004110480	50-259 P 50-368 F GEN TEC IS CONTRACT PR	LEVIN, J A LEVIN, J A LEVIN, J A	8004100561 8004090257 8004010426 8004150475 8004290092	REGOD 50-10 P 50-334 G RES 50-334 T	LICITRA, E A LIEBERMAN, J LIEBLER, G E LIEBLER, G E LIEDER, C	B004140016 7911050375 B004020011* B004110216 B004100079	50-275 A hisc 50-387 O TOPREP PR
LANCASTER, K F LANCASTER, K F LANCASTER, K F LANDSMAN, R D LANGE, 5 L	8004020323* 8004070315* 8004270488* 8004040077* 8004220200	50-302 S 50-302 S ,50-302 S 50-483 Q WASTE MOT	LEWIS,N D LEWIS,R C LEWIS,R C LEWIS,R C	8004010345# 8004240170# 8004300171# 8004300158# 8004040250#	50-508 A 70-135 50-302 Q 50-302 Q 50-280 Q	LIKE, I LIKE, I LIN, Y L LINDBALD, W J LINDER, F	8004100041 8004100440 8004110300* 8004180359 8004010108	PR 50-322 T 50-272 O 50-514 F 50-409 O
LANGE,S L	8004020046	WASTE MOT	LEWIS.R C	8004020252*	50-259 Q	LINDER, F	8004150119	71-6400
LANGLEY.C	8004100544*	PR	LEWIS.R C	8004230249*	50-249 Q	LINDER, F	8004090369	50-409 P
LANGLAND,R T	8004030002	NUREG	LEWIS.R C	8004150079*	50-321 Q	LINDER, F	8004140312	50-409 P
LANNING,D D	8004210298	NUREG	LEWIS.R C	8004100409*	50-395 Q	LINDER, F	8004140365	50-409 R
LANTZ,P M	8004150036	RES	LEWIS.R C	8004040232	50-280 Q	LINDER, F	8004150204	50-409 P
LANTZ,E LANTZ,E LARINI,Q J LAROCHE,Q LATHAM,S B	8004160227* 8004160230* 8004300017* 8004300005* 8004210007*	50-269	LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8004070036# 8004300230# 8004150142# 8004040447# 8004070245	50-321 Q 50-249 Q 50-321 Q 50-302 Q 50-259 Q	LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8004150488 8004220584 8004210200 8004270341 8004300456	50-407 B 50-407 B 50-407 B 50-407 B
LAUDIO, B	8004150219	FD1A	LEWIS, R C	8004100178	50-335	LINEBARGER, J H	8004170120	RES
LAUTZENHEISER, C	8004040295*	50-317 G	LEWIS, R C	8004090405		LINEHAN, J J	8004080607	40-1162
LAUTZENHEISER, C	8004040296*	50-317 G	LEWIS, R C	8004100175		LINEHAN, J J	8004070249	40-8452
LAUTZENHEISER, C	8004040301*	50-317 G	LEWIS, R C	8004250340#		LINEHAN, J J	8004070387	40-8502
LAVERTY, E	8004160176*	50-3 H	LEWIS, R C	8004240383#		LINENBERGER, G	8004230055	50-466 9
LAWSON, J D LAWSON, L LAZA, R M LAZA, R H LAZARUS, W J	8004180120* 8004100331 8004090162 8004090321 8004210053*	50-287 H 50-387 G SECY SECY 50-309 G	LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8004070133 8004240373 8004240408 8004210105 8004280233	50-302 Q 50-338 Q 50-280 Q 50-302 Q 50-335 Q	LIPINSKI.W C LIPINSKI.W C LIPPOLD.W J LITTLE.L W	8004080639* 8004040469 8004020226 8004300079 8004220350	ACRB 50~20A D ACRB 71~303 50~269 Q
LAZO,R M	8004080626	50-133 0	LEWIS, R C	8004020242	50-259 Q	LITTLE,W S	8004220175*	50-295 Q 50-331 B 50-10 H 50-289 Q 50-289 Q
LEAR.Q	8004150151	50-335 P	LEWIS, R C	8004280115	50-250 Q	LITTLE,W S	8004080664	
LEAS,J	8004210072	50-320 C	LEWIS, R C	8004280134	50-348 Q	LITTLE,R	8004210270*	
LEBOEUF.R J	8004110480	FR	LEWIS, R C	8004280005	50-375 Q	LITTLE,L W	8004100222	
LEE.B	8004170350*	10CFR	LEWIS, R C	8004280150	50-325 Q	LITTLE,L W	8004300001	
LEE, B	8004280493	50-320 P	LENIS, 8 H	8004020454	50-312	LITVACK, B K	8004070475#	50-293 H
LEE, E W	8004070173*	50-483 Q	LEWIS, R C	8004280057*		LITVACK, B M	8004140104#	50-443 H
LEE, E W	8004280039*	50-454 Q	LEWIS, R C	8004100395		LITVACK, B M	8004110139#	50-482 H
LEE, J C	8004030300	ACRS	LEWIS, R C	8004040439		LITVACK, B M	8004030207	50-402 H
LEE, O R	8004210166*	50-267 Q	LEWIS, R C	8004070032		LOCHSTET, W A	8004110078	50-320 Q
LEECH, K	8004150448*	50-254 S	LEWIS,R C	8004280050	50-324	LOCKE,R F	8004150003	50-133 Q
LEIBY, A C	8004110480	PR	LEWIS,R C	8004020110		LOCKE,E U	8004010472	50-443 Q
LEITHAUSER, J	8004180402*	50-155 Q	LEWIS,R C	8004080183*		LOCKE,R F	8004240384	50-275 F
LEITHAUSER, J	8004030343	50-155 Q	LEWIS,R C	8004080178		LOGAN.F	8004110019*	50-387 Q
LEITHAUSER, J A	8004180394	50-155 Q	LEWIS,B H	8004080329		LONERGAN,Q T	8004140110	14E
LEITZELL,TL LEM.A LEMPGES,TE LEMPGES.TE LEMPGES.TE	8004170250 8004300033* 8004110055 6004100401 8004010373	50-272 P 50-387 0 50-220 0 50-220 0 50-220 0	LEWIS, 8 H LEWIS, 8 H LEWIS, R C LEWIS, 8 H	8004010292 8004080362 8004080414 8004230202 8004080329	50-312 0 50-312 0 50-312 0 50-249 0 50-312 0	LONERGAN, 0 T LONERGAN, 0 T LONERGAN, 0 T LONG, F J LONG, F J	8004220186* 8004220176* 8004220466* 8004300135* 8004070046	FOIA FOIA FOIA 50-375 Q 70-143
LEMPOES, TE LEMPOES, TE LEMPOES, TE LEMPOES, TE LENAHAN, JJ	8004010372 8004040404 8004080642 8004140404 8004040430*	50-220 Q 50-220 R 50-220 Q 50-220 R 50-424 Q	LEWIS, 5 R LEWIS, 5 R LEWIS, R C LEWIS, R C	8004070330* 8004080322 8004030224* 8004150065 8004150126	50-269 8 50-312 0 50-287 8 50-321 0 50-321 0	LONGSHORE, M L LOOMIS, J S LORENZ, R A LOSS, F J LOVE, E	8004040119 8004100546 8004170336 8004290009 8004100064	50-352 H REOOD NUREO NUREO PRM
LENAHAN, J J	8004020220*	50-375 G	LEWIS,R C	8004240371	50-250 Q	LOWE, A L.	8004020475*	TOPREP
LENAHAN, J J	8004070372*	50-438 G	LEWIS,R C	8004250330	50-267 Q	LOWERRE, R W.	8004140281	50-466 Q
LENAHAN, J J	8004240434*	50-491 G	LEWIS,M I	8004250053	50-269 Q	LOWRY, L M	8004300192	NUREQ
LEGN. A	8004040176	50-387 H	LEWIS,S R	8004080476*	50-269 S	LUMB, R F	8004090485*	CONTRACT
LEONARD, J	8004210360*	50-320 H	LEWIS,R C,	8004210206*	50-160 Q	LUNDVALL, A E	8004220441	50-317 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJEC CATEGO
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8004090139 8004030311 8004080335 8004080333* 8004090243	50-317	MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E	8004100212 8004100216* 8004100220 8004100224* 8004100228	71-6272 71-6272 71-6574 71-6574 71-9073	MANN, D L MANRY, M MANRY, M MANRY, M MANRY, M	8004070463 8004150454 8004020343 8004020361 8004010474	PR 50-346 50-346 50-346 50-321
LUNDVALL, A E	6004210192 8004010463 6004070275 8004040291 8004080465	50-317 R 50-317 P 50-317 R 50-317 Q 50-317 P	MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E	8004100230* 8004100250 8004100254* 8004100259 8004100262*	71-9073 71-9009 71-9009 71-6078 71-6078	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004020315 8004020325 8004020428 8004150425 8004070314	50-366 50-366 50-366 50-366 50-366
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNER, C	8004100227 8004170111 8004170238 8004280435 8004030274	50-317 P MISC 50-317 P 50-317 P PR	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8004180400 8004090014 8004090017+ 8004100198 8004100200*	71-252 71-380 71-380 71-4679 71-4679	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004020354 8004010321 8004150410 8004040427 8004040414	50~321 50~321 50~366 50~366 50~321
LUGUE, N LUGUE, N LUTKEN, D C LUTKEN, D C	8004020181 * 8004020170 * 8004170340 8004280371 * 8004280365	50~445 M 50~445 M 50~445 M 50~416 K 50~416 K	MAGDONALD, C E	8004100224 8004100229* 8004100231 8004100236* 8004100329	71-97 71-97 71-96 71-96 71-273	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004070281 8004110472 8004110479 8004150451 8004150474	90~321 50~366 50~366 50~366 50~366
LYNCH, M D LYNCH, M D LYNXH, J X LYONG, E MACDONALD, C E	6004110345 6004150084 6004030307 6004210373* 6004070225*	50-397 A 50-367 A F01A 50-320 H 71-9	MACDONALD, C E	8004100332* 8004100336 8004100341* 8004100346 8004100349*	71-273 71-116 71-116 71-116 71-367 71-367	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004150542 8004280531 8004150383 8004150388 8004150393	50-366 50-366 50-366 50-321 50-366
MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACDONALD, C E MACDONALD, C E	8004110125 8004270475 8004020360 8004020364* 8004020373	71-6144 71-5 71-250 71-250 71-13	MACDONALD, C E	8004210418 8004280307 8004280314* 8004210019 8004210021*	71-6375 71-5375 71-5375 71-5375 71-9142 71-9142	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004150399 8004220615 8004220628 8004220662 8004220713	50-321 50-366 50-366 50-366 50-321
MACDONALD, C E	8004020380* 8004010001 8004040092 8004070147 8004070152*	71-13 71-9004 71-9070 71-24 71-24	MACHAMER, G E MACKIN, J L, MACRAE, C F MADDEN, W MADDEN, W	8004300066* 8004020196 8004250052 8004250059* 8004210330*	50-387 G WASTE MOT NUREO 50-213 G 50-217 G	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8004220728 8004220464 8004220452 8004220475 8004220689	50-366 50-366 50-366 50-321 50-321
MACDONALD, C E	8004020300 8004020304 8004030007 8004030100 8004030104	71-9045 71-9049 71-9046 71-9016 71-9015	MADDEN, W MADDEN, W MADISON, W R MADISON, W R MADSEN, G L	8004150193* 8004280632 8004170211* 8004170212* 8004090151	70-371 50-320 S 50-338 R 50-338 R 50-313 Q	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	B004220705 B004220706 B004220726 B004280416 B004280441	50-366 50-366 50-366 50-366 50-366
MACDONALD, C E	8004030114 8004030124 8004040082 8004040085 8004040374	71-9050 71-5938 71-5407 71-9072 71-230	MADSEN, Q L MADSEN, Q L MADSEN, Q L MADSEN, Q L MADSEN, Q L	8004040252 8004100315 8004080691 8004040128 8004080600	50-285	MANRY, M MANRY, M MANSER, W C MANSER, W C MANSER, W C	8004280570 8004280582 8004090237* 8004180482 8004180143	50-321 50-321 70-143 70-143 70-143
MACDONALD, C E	8004040388 8004040393 8004040462 8004070053 8004070133	71-370 71-135 71-5939 71-5998 71-180	MADSEN, O L MADSEN, O L MADSEN, O L MADSEN, O L MADSEN, O L	6004080602* 6004040089 6004030246 6004210175 6004210443*	50-267 Q 50-313 Q 50-298 Q 50-445 Q 50-445 Q	MANGER, W C MANGER, W C MANGER, W C MARCHAND, R MARCHAL, J	8004040041* 8004070049* 8004070235* 8004020458* 8004180229	70-143 70-143 70-143 50-320 XPORTLIC
MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8004030142 8004040157 8004040381 8004040458 8004040478	71-9036 71-5979 71-9007 71-6375 71-4387	MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G	8004070143 8004210211 8004210432 8004070113 8004280057*	50-313 0 50-278 0 50-445 0 50-368 0 50-324 0	MARCHI,M L MARCUS.O F MARKOWSKI,R S MARKOWSKI,R S MARKWORTH,A J	8004220648* 8004140449* 8004300244* 8004210071* 8004300192	50-305 50-456 50-244 50-244 Nureg
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E HACDONALD, C E	9004070010 9004070014* 9004070018 9004070020* 9004070068	71-9079 71-9079 71-9080 71-9080 71-9043	MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, D B MADSEN, O L	8004070033 8004070036* 8004240506 8004300087 8004210163	50~285 G 50-285 G 50-313 F	MAROTTA.C R MAROTTA.C R MARRC	B004160221* B004160224*	50-269 50-269
MACDONALD, C E	8004080093 8004080097* 8004080107 8004080112* 8004020294	71-9019 71-9019 71-9089 71-9089 71-379	MADBEN, G L MADBEN, G L MAGAR, T, R MAGROW, R A MAGROW, R	8004290005 8004290011* 8004220284* 8004020337* 8004150513*				
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C. E MACDONALD, C E	8004080208 8004070201 8004070203* 8004070214 8004070218*	71-9132 71-373 71-373 71-372 71-372	MAJOR,R MAJOR,R K MAKIPENTTI,I MALARO,J C MALARO,J C	8004100375 8004100508 8004250007 8004220491* 8004220488*				
MACDUNALD, C E MACDUNALD, C E, MACDUNALD, C E, MACDUNALD, C E, MACDUNALD, C E,	8004070222 8004070226* 8004070227 8004070230* 8004100270	71-375 71-375 71-165 71-165 71-5796	MALINAUSKAS,A MALLORY, MALMROS,M H MALMROS,M,H MALONEY,O,P	8004170336 8004220274 8004180827 8004280087 8004030204				

MACDONALD, C E MACDONALD, C E. MACDONALD, C E MACDONALD, C E MACDONALD, C E

MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E 8004040121 8004040124* 8004070270 8004070273* 8004100239

8004100242* 8004100036 8004100038* 8004100205 8004100208* 71-9010 71-9010 71-377 71-377 71-49

71-49 71-9020 71-9020 71-5908 71-5908 MALONEY, 0 P MALONEY, 0 P MALONEY, 0 P MALONEY, 0 P MANCINI, A, J

MANCUSO, F MANDLER, J W MANFRED, K M MANGUSI, J MANN, M M 8004080520 8004080534 8004080367 8004080304 8004020064

8004100445 8004080242 8004210406 8004180073 8004080059

AUTHDA	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT CATEGORY
MARTIN.W G MARTIN.T J MARTIN.W G MARTIN.W G MARTIN.T J	8004210212* 8004100157* 8004100080 8004080343* 8004100613*	50-247 50-354 70-364 70-135 50-311	Q Q	MATTIA,M J MATTIMOE,J J MATTIA,M J MATTIMOE,J J MATTIA,M J	8004210119* 8004300433* 8004100194* 8004070312 8004030014*	O SIE-OE TOARTHOD TOARTHOD S SIE-OE TOARTHOD	MCCOOL, W B MCCOOL, W B MCCOOL, W B MCCOOL, W B	8004080208* 8004080184* 8004080179* 8004080120* 8004240127*	FOIA FOIA FOIA FOIA 70-135
MARTIN, W G MARTIN, R D MARTIN, R D MARTIN, T T MARTIN, W G	8004100026 80042403904 60042503574 6004210534 80042101044	70-620 50-250 50-249 50-309 70-371	Q Q Q	MATTIA,M J MATTIA,M J MATTIMOE,J J MATTIMOE,J J MATTIMOE,J J	8004100342* 8004080610* 8004140397 8004150439 8004210259	CONTRACT CONTRACT 50-312 5 50-312 P 50-312 S	MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W	8004240114* 8004140002 8004230197 8004240222 8004020147	70-135 70-8 70-1739 50-244 P 70-2786
MARTIN.W G MARTIN.T T MARTIN.R D MARTIN.T T MARTIN.W G	8004250054* 8004160153* 8004070163* 8004210102* 8004210326	50-213 50-293 50-302 50-320 50-219	9 9 9	MATTIMOE, J J MATTIMOE, J J MATTIMOE, J J MATTIMOE, J J MATTAM	8004160234 8004290485 8004210314 8004220568 8004220709	50-312 P 50-312 S 50-312 P 50-312 P 50-312 P	MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W MCCORKLE, G W	8004070040 8004070045 8004160003 8004240247 8004040473	70-1008 70-824 70-2022 70-2478 70-2322
MARTIN.W G MARTINSON.Z R MARTIN MARTIN.W G MARTIN.T T	8004150197 8004150056 8004080114* 8004230120 8004090473*	70-371 RES 50-354 50-309 50-293	s 0 0	MATTIMDE, U U MATTIMDE, U U MATTIMDE, U U MATTIMDE, U U MATTIMDE, U U	8004230498 8004290339 8004280528 8004290454 8004300421	50~312 P 50~312 P 50~312 F 50~312 S 50~312 S	MCCRACKEN, K U MCCRARY, D L MCCUTCHAN, D A MCDADE, J M MCDERMOTT, R J	8004010372 6004250390 8004110496 6004080218* 8004040403*	50-346 P 50-321 P PR 50-387 U 71-35
MARTIN, W G MARTIN, W G MARTIN, W G MARTIN, R D MARTIN, W G	8004070200* 8004210077 8004220025 8004280241* 8004070191	50-184 70-371 70-371 50-335 50-184	0 0 0	MATTIA,M J MATTSON,R MATTSON,R J MATTSON,R J MATTSON,R J	8004030044* 7908190559 8004100530* 8004020476 8004210398	CONTRACT 50-358 H 50-320 D 50-320 P 50-320 H	MCDERMOTT,R J MCDIARMID,R C MCDIARMID,R C MCDIARMID,R C MCDONALD,D D	8004040398 8004090368* 8004090368* 8004090363 8004090362	71-35 50-416 H 50-416 H 50-416 H FO(A
MARTIN,R D MARTIN,W G MARTIN,W G MARTIN,T J	8004280125* 8004090205 8004090393 8004100197 8004280174*	50-250 50-201 70-135 70-135 50-354	0 0 8	MATTSON,R J MAUGANS,E H MAUGANS,E H MAURA,F MAURO,J J	8004240141 8004150471 8004280386* 8004300022* 8004100588	REVIEW GRP 50-346 I 50-346 I 50-358 Q FR	MCDONALD.D D MCDOWELL-BOYER MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A	8004290173 8004140088 8004080451 8004220451 8004230328	FOIA RES 50-400 A 50-400 A
MARTIN, W G MARTIN, W G MARTIN, R MARTIN, T J MARTIN, W G	8004080334 8004100185 8004090051 8004250224 80042102(0	70-135 70-33 50-335 50-354 50-247	5 0 0	MAYER, L G MAYER, L G MAYER, L G MAYER, L G MAYER, L G	8004040319 8004010452 8004080225 8004090223 8004080508	50-263 P 50-263 B 50-282 F 50-263 F 50-263 F	MCFARLAND, C R MCFARLAND, C R MCGARRY, J M MCGARRY, J M MCGARRY, J M	8004020194* 8004210247* 8004070331 8004110153	50-424 0 50-410 0 PR 70-2623 70-2623
MARTIN,W MARTIN,W MARTIN,W MARX,D MASNIX,M	8004280632 8004290051 8004300552 8004180368 8004020163*	50-320 50-213 50-293 50-271 50-272	9 8 8 8	MAYER.L O MAYER.L O MAYER.L O MAYER.L O MAYER.L O	8004080368 8004080373 8004080478 8004080479 8004150543	50-263 F 50-263 P 50-282 8 50-263 F 50-263 8	MCORRAY, J M MCORRAY, J M MCOUVEY, R W MCOUVEY, R W MCOUVEY, R W	8004230012 8004230012 7812110291* 8004230114* 8004100111*	70-2623 70-2623 50-387 Q 50-352 Q 50-387 Q
MAGNIK,M T MAGGEY,W E MAGBE,R E MAGGE,R MAGGIE,H W	8004300600* 8004140470 8004040444* 8004040299* 8004240152	50-272 NURE0 50-315 50-315 RES	G G G	MAYER, L O MAYER, L O MAYER, L O MAYER, L O MAYER, L O	8004140390 8004140435 8004140339 8004140431 8004150401	50-263 8 50-282 8 50-282 R 50-263 8 50-263 R	MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W	8004100168* 8004300309* 8004090441* 8004090473* 8004100040*	50-384 0 50-410 0 50-443 0 50-293 0 50-441 0
MASSIE, H W MASTER, N MATHEWS, E R MATHEWS, E R MATHEWS, E R	8004150008 8004210403* 8004100405 8004080457 8004080337	RES 50~320 50~305 50~305 50~305	H G S P	MAYER, L O MAYER, L O MAYER, L O MAYER, L O MAYER, L O	8004150587 8004170056 8004180357 8004150339 8004180380	50-282 S 50-282 F 50-263 F 50-282 P 50-306 S	McGaughy, R W McGaughy, J McGinnebb, J McGinnagle, W McGivern, G	8004210011* 8004230322 7909290207* 8004220037* 8004080314*	50-423 0 50-416 0 FOIA FOIA 40-1341
MATHEWS, E R MATHEWS, E R MATHEWS, E R MATHEWS, E R MATHEWS, E R	8004150354 8004150524 8004150581 8004170018 8004180428	50-305 50-305 50-305 50-305 50-305	R 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	MAYER, L O	8004180468 8004180341 8004180276 8004230358 8004230480	50-263 8 50-282 P 50-304 G 50-282 S 50-282 Q	MCGRATH, E J MCGRANERY, J F MCGRIFF, J M MCGRIFF, J M MCGUIRE, D R	8004300215 8004150327 8004150533* 8004270519* 8004300135*	WASTE HOT 50-244 P 50-327 B 50-327 B 50-375 Q
MATHEWS,E R MATHEWS,E R MATHEWS,E R MATHEWS,E R MATHEWS,E R	9004190479 8004220756 8004210327 8004220642 8004220504	50-305 50-305 50-305 50-305 50-305	8 6 6 7	MAYER, L D MAYEB, J MAYE, S E MCARTHUR, T C MCCABE, E C	8004280547 8004250379# 8004090068 8004090195# 8004040177#	50-282 P 50-10 H RES 50-338 0 50-334 0	MCGUIRE,W F MCGUIRE,P J MCGUIRE,P J MCGUIRE,P J MCGUIRE,P J	8004010242 8004150574 8004140310 8004140337 8004170184	50-466 A 50-293 B 50-293 B 50-293 B 50-293 B
				MCCABE, E C MCCABE, E C MCCALLIBTER, P MCCARTHY, E MCCARTHY, E A	8004170309* 8004160194* 8004220555 8004080166 8004070069	50~334 Q 50-277 Q 50-329 A State Prog State Prog	MCGUIRE,P J MCGUIRE,P J MCGUIRE,P J MCGURREN,H J MCHENRY,T J	8004230497 8004220624 8004210289 8004170248 8004100182*	50-293 R 50-293 B 50-293 B 50-382 Q 50-333 Q
				MCCARTHY, E MCCLAIN, C M MCCLINTOCK, R D MCGLINTOCK, R O MCCLINTOCK, R O	8004020089 8004240432* 8004210052* 8004180511 7909290207*	State Prog 50⊷219 R FOIA 70⊶69∆ FOIA	MCLOUGHLIN, M G MCKEOWN, L MCKEOWN, L MCKINLEY, J C MCINTOSH, M G	8004220342* 8004070221* 8004300552 8004040261 8004150588*	70-2423 50-201 0 50-293 8 50-409 0 50-293 8
				MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R MCCLINTOCK, R D	8004210033* 8004210057* 8004070104* 8004090122 8004080230*	FOIA FOIA 40-6329 70-47 70-2254	MCLOUD, D O MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T	8004270406* 8004140342* 8004170171* 8004210272* 8004220631*	50-32/ 0 50-273 8 50-273 6 50-273 8 50-273 8
				MCCLINTOCK,R O MCCLINTOCK,R O MCCLINTOCK,R O MCCLINTOCK,R O MCCLINTOCK,R O	8004150183 8004160156* 8004210012 8004160079 8004070089	70-1089 70-1231 70-2362 40-2284 40-6329	MCMORMACK, M MCNAMARA, A E MCNEER, C MCNEER, C 8 MCNEIL, W M	8004030343 8004150384* 8004290425* 8004110491 8004040361*	PR 50-244 R 50-266 I PR 0A999
				MCCLINTOCK, R O MCCLUNG, R H MCCOLLAM, W MCCOLLAM, W MCCOLLAM, W MCCOLLAM, P H	8004080199 8004280048 8004100513* 8004080245 8004170202	70-2254 NUREO COMMISSION PR PR	MCOSCAR, J J MCOSCAR, J J MCPHILLIPS, J MCRAE, C M MECCA, J E	8004080450* 8004090441* 8004250064 8004100023* 8004030351	50-213 Q 50-443 Q 70-2909 CONTRACT PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
MECH, S J MEEKS, M MEIERAN, H B MEISS, R L MEISS, R L	8004110048 8004040266 8004170329 8004030317 8004040058	NUREG 50-556 G NUREG PROJ PROJ	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8004300094* 8004010320 8004010408 8004020395 8004280001	50-566 G NUREO 50-327 P 50-438 S 50-259 G	MILLS, L M MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8004300370 8004030160 8004070252 8004040400 8004080518	50-518 S 50-331 R 50-331 R 50-331 S 50-331 S
MELLON, K MENCZER, W B MENCZER, W B MENCZER, W B MENCZER, W B	8004220570 8004040435 8004070003 8004100523 8004100529	50-204 P CONTRACT CONTRACT CONTRACT CONTRACT	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004280056 8004010374 8004160284 8004020414 8004020431	40-1341 50-327 G 50-327 G 50-438 S 50-438 S	MINECK, D L	8004080&05 8004190340 8004090447 8004140363 8004140450	50-331 S 50-331 S 50-331 S 50-331 S
MERCURI, J MERRITT, D MERRILL, D K MERSON, B D MERSON, B D	8004030156* 8004090271 8004300057* 8004250407* 8004250406	50-320 H PR 50-387 G 50-317 R 50-317 R	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004020440 8004040377 8004020312 8004020417 8004180104	50-327 8 30-438 5 50-327 5 50-438 5 50-326 0	MINECK.D L MINECK, D L MINOGUE, R B MINOGUE, R B MINOGUE, R B	8004220385 8004230346 8004090297 8004290072 8004150224	50-331 R 50-331 R SECY PR
MESMERINGER, J MESSITT, B R MESSITT, B R METZGER, J R MEYER, K	8004170035* 6004040452* 8004240413* 8004220174* 8004040112	TOPREP 50-302 Q 50-280 Q FOIA 50-331 P	MILLS, L M MILLS, L M MILLS, L M MILLS, B D MILLS, L M	8004160216 8004160291 8004160296* 8004100334 8004070360	50-518 S 50-438 S 50-438 S 50-387 Q TOPREP	MINDOUE, R B MINTZER, D MIRMAN, J K MISHIMA, J MISHKIN, B	8004230130* 8004070009* 8004220180* 8004040270 8004300606*	SECY CONTRACT FOIA RES COMMISSION
MICHEL,C J MICHEL,C J MICHEL,C J MICHEL,C J	8004220133 8004070422 8004300003 8004140024 8004210198	70~143 70-143 70-143 71-249 70~143	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004080553 8004150413 8004150437 8004090P28 8004110186	50-553 A 50-390 S 50-390 S 50-327 P 50-327 F	MITCHELL, D G MITCHELL, D G MITTL, R L MITTL, R L MITTL, R L	8004230411* 8004230495* 8004010438 8004010443 8004010447	50-289 8 50-289 R 50-311 A 50-311 A 50-311 0
MIDURA:H J MIDURA:H J MIDURA:H J MILHISER:R J MILHISER:R J	8004280225 8004150386 8004290489 8004010347* 8004070310*	50-272 8 50-272 R 50-272 R 50-382 S 50-382 8	MILLS,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8004150414 8004150485 8004280453 8004140388 8004150423	50-518 8 50-553 8 50-328 8 GEN TEC IS 50-259 P	MITTL,R L. MITTL,R L. MITTL,R L. MITTL,R L. MITTL,R L.	8004010449 8004010453 8004070250 8004040313 8004040282	50-311 A 50-311 A 50-311 A 50-311 A 50-311 A
MILHIBER.R J MILHIBER.R J MILLER.J R MILLER.M E MILLER.T D	8004250352* 8004280605* 8004010189* 8004020122* 8004140034*	50-382 8 50-382 8 70-1308 50-445 M 0A979	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004150557 8004280170 8004280432 8004280537 8004140327	50-257 P 50-257 G 50-438 S 50-390 S 50-327 P	MITTLIR L MITTLIR L MITTLIR L MITTLIR L MITTLIR L	8004110305 8004110431 8004110468 8004110474 8004110424	50-311 A 50-311 A 50-311 A 50-311 A 50-311 A
MILLER, D E MILLER, T D MILLER, T D MILLER, T D MILLER, T D	8004070174* 8004140020* 8004070327* 8004140015* 8004080559	50-979 Q QA779 50-2 G QA779 50-445 M	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004280526 8004180377 8004180381* 8004280548 8004290513	50-390 8 50-390 8 50-390 8 50-390 8 71-227	MITTL,R L MITTL,R L MITTL,R L MITTL,R L MIYABAYASHI,M	8004170040 8004240377 8004240345 8004250393 8004070024	50-272 P 50-311 F 50-311 F 50-311 A XPORTLIC
MILLER, W O MILLER, W O MILLER, H L MILLER, H J	8004020450 8004070209 8004070220 8004080101 8004070428	50-155 P TOPREP 50-155 P 50-367 B 40-1341	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004150608 8004170026 8004170065 8004180365 8004180444	50-327 P 50-327 S 50-327 K 50-328 S 50-390 S	MODENOS, L MODENOS, L MODENOS, L MODENOS, L MODENKE, N H	8004040176* 8004070355* 8004280202* 8004280107* 8004270023*	50-257 G 50-302 G 50-259 G 50-261 G QA999
MILLER, W O MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8004070055 8004070170 8004080252 8004070062 8004140113	TOPREP TOPREP TOPREP 50-344 Q TOPREP	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004210202 8004230506 8004280388 8004170069 8004170213	50-327 P 50-259 P 50-390 S 50-327 P 50-390 A	MOGDLESKO, F J MOLHOLT, B MOLHOLT, B MOLLOY, E J	8004080524* 8004170237 8004250378 8004270289 8004020418*	50-273 R 50-320 P 50-320 P 50-320 P 50-213 F
MILLER, W O MILLER, W O MILLER, W O MILLER, H J MILLER, N E	8004140012 8004070334 8004100078 8004210416 8004070448	50-569 A 40-8728 70-1113 WASTE MOT 50-454 G	MILLS,L M MILLS,L M MILLS,L M	8004180256 8004220724 8004280503 8004280505* 8004170134	50-553 A 50-518 B 50-518 B 50-518 S 50-327 P	MOLONE,L MOMENI,M H MONDEN,T MONTOOMERY,D (¢ MONTI,W A	8004210256* 8004100584 8004180242 8004140480* 8004150599	50-10 H NUREO XPDRTLIC 50-261 G 50-3 R
MILLER, H E MILLER, H O MILLER, H O MILLER, H O MILLER, H O	80040B0424* 8004110540 800417017B 8004210112 8004170167	50-445 M 70-1257 50-314 P 50-286 P 70-1308	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004170148 8004170225 8004220340 8004220420 8004220523	50-327 P 50-327 F 50-259 P 50-438 S 50-259 P	MODDY, D E MODDY, D E MODDY, D E MODDY, D E	8004080423 8004100422 8004020016 8004100406 8004210044*	50-271 Q 50-309 Q 50-309 Q 50-309 Q 50-309 Q
MILLER, W O MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8004210005 8004210023 8004230042 8004210043 8004220788	50-344 P 50-282 P 50-348 P 50-271 P 50-313 P	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004230347 8004280508 8004220541 8004280438 8004230380	50-553 Q 50-566 R 50-438 S 50-438 S 50-438 S	MOODY, D E MOODY, D E MOODY, D E MOODY, D E	8004230005 8004080339 8004110444* 8004140172 8004150347	50-309 Q 50-309 H 50-29 P 50-29 F 50-309 R
MILLER,M I MILLER,M I MILLER,M E MILLER,W O MILLER,L X	8004220334 8004220334 8004150173 8004270077 8004150387*	50-554 0 50-556 0 PROJ 50-27 P 50-272 R	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004230503 8004230527 8004240386 8004280516 8004240405	50-438 8 50-438 8 50-438 8 50-438 8 50-370 8	MODDY, D. F. MODDY, D. E. MODN, B. T. MODN, B. T.	8004150360 8004180350 8004280534 8004040289* 8004040049*	50-271 R 50-29 R 50-29 F 50-280 Q 50-321 Q
MILLER,M E MILLSAP,W J MILLS,L M MILLS,L,M MILLS,L M	8004170351 8004040156* 8004100495* 8004040181* 8004020249*	50-445 M 70-27 50-566 G 50-259 G 50-259 G	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004250374 8004250380 8004250405 8004250413 8004250431	50-566 S 50-438 8 50-366 G 50-370 B 50-556 B	MOON, R, E MOONEY, F & MOORE, R N MOORE, R N MOORE, W	8004070287* 8004070246 7702280271 7909190504 8004100075	QA999 WASTE MOT MIBC MIBC PR
MILLEAP,W J MILLE,L M MILLE,L,M MILLE,L,M	8004070302* 8004070160 8004080207 8004280470 8004280476*	70-1201 PR 40-1341 50-327 8 50-327 8	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004280229 8004290453 8004290346 8004290379 8004290290	50-327 P 50-390 A 50-328 B 50-259 Q 50-327 P	MODRE, K E MODRE, R N MODRE, R N MODRE, R N MODRE, R N	8004020475* 8004070078 8004070023 8004070073 8004070080	TOPREP XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MILLE, L M MILLE, L M MILLE, L M MILLE, L M	8004210198* 8004300474* 8004100364 8004210178 8004020193	50-553 Q 50-370 Q 50-257 Q 50-257 Q 50-553 A	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004270276 8004270327 8004270400 9004270455 8004300341	50-390 8 50-328 8 50-327 0 50-328 8 50-327 P	MODRE, D E MODRE, D E MODRE, D E MODRE, J E MODRE, G W	8004040117# 8004010469 8004110549* 8004090001 8004090176	70-143 50-302 R 70-2479 50-155 Q 50-334 R

				ACCESSION	SUBJECT		ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR MODRE, J E	ACCESSION NUMBER 9004170302 8004300010	SUBJECT CATEGORY 50~155 G KPORTLIC	AUTHOR MURPHY: P. M MURPHY: C. E. MURPHY: C. E.	NUMBER 8004220334 8004300112 8004300462	CATEGOR' 50-554 50-395 50-390	G G G	NIX.R T NIX.R T NIX.R T	8004020317* 8004020330* 8004020347*	50-366 S 50-366 S 50-366 S 50-366 S
MODRE.R N MODRE.J E MODRE.D E MODRE.O C	8004180405 8004270157* 8004150307	50-272 T 50-339 D 50-302 P	MURPHY A J MURPHY A J MURPHY A J	6004140323* 8004140412* 8004300090	50-272 50-272 50-564 50-272	91 SS C# IS	NIX,R T HIX,R T NIX,R T NIX,R T	8004040438* 8004040426* 8004150455*	50-366 B 50-321 S 50-366 B 50-321 B
MOGRE, J E MOGRE, J E MORGAN, R L MORGAN, J F MORIARTY, J M	8004220674 8004250422 8004220010 8004080297* 8004140156	50~155 G NUREG GA979 50-483 8	WASHA'M B WASHA'M B WASHA'M C WASHA'W C	6004150559* 6004150506 6004150514* 6004160410	50-271 50-271 50-271	8	NIX.R T NIX.R T NIX.R T	8004220617>	50-366 B 50-366 B 50-366 B
MORIARTY, J M MORRIS, B MORRIS, B MORRISLL, P J	8004020455 7903090072 7903090074 8004280022*	50-395 S HISC HISC 50~275 Q	MURPHY, W P MURPHY, C E MURRHY, J P MURRHY, J P MURRHY, J P	9004190413* 9004230355* 7911050375 9004090442 9004300519*	50~271 50-314 M180 50-255 50~320	9 9	NIX,R T NIX,R T NIX,R T NIX,R T	8004220710* 8004220718* 8004220735* 8004280587*	50-321 B 50-365 S 50-366 B 50-321 B
MORRILLIF J MORRISE W HORROW D MORROW D MORROW D	8004210176* 8004030180 8004070186 8004270075 8004280075	50~243	MURRAY, F MURRAY, J J HURRAY, T D MURRAY, T D	8004300069* 8004290111 8004110485 8004110378 8004110487	50-307 50-341 50-346 50-346 50-346	0 H S S S	nixon. W A Nixon. W A NOLAN. F NOLAN. F NOLAN. F	8004220026* 8004070356 8004210433 8004220084 8004210440	70-135 40-8027 50-304 B 50-272 B 50-247 B
MORTON, K V	8004240033 8004240041 + 8004020215 + 8004070100 +	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY,T D O T.YARRUM N.YARRUM O T.YARRUM D T.YARRUM	8004140350 8004220423* 8004150543 8004210245 8004220457	50-346 50-265 50-346 50-346 50-346	R 5 5 5	NOLAN, F NOLAN, F NOLAN, F NOLAN, F NOLAN, F	8004210441 8004210224 8004180517 8004180518 8004180520	50-335 S 50-344 S 50-345 S 50-257 S 50-255 S
MORTON K V MORTON K MORTON K V MORTON K V	8004010009* 8004150171* 8004070009* 8004100369* 8004100363*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY, T D	8004220752 8004220765 8004280538 8004280572 8004100411	50~344 50~346 50~346 50~346 RES	8 8 8	Magn. J C Norderhaug. L R Marderhaug. L R Norderhaug. L R Norderhaug. L R	8004230372 8004020230 8004020236 8004100174 8004030006	90-244 B 70-25 70-1257 70-25 70-1143
MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8004250043# 8004230528# 8004240051# 8004250022# 8004240015#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MUYATT MYERBII L MYRADD, A C NALEPKAID NALEPKAID ONLEPKAID	8004300781* 8004150405* 8004230515* 8004080462* 8004080467*	70 -2905 50~263 50~305 50~305	, # 8 8	Norderhaug. L. R Morderhaug. L. R Morderhaug. L. R Norderhaug. L. R Morderhaug. L. R	8004040457 8004040460 8004110532 8004180443 8004170268	70-29 50-143
MORTON, K V MOS. L L MOSELEY, N C MOSELEY, N C MOSELEY, N C	8004250033* 8004250033* 8004220238* 8004080074* 80043004475	FOIA 50-255 G 50-272 S	MALEPKA, D 8 MALEPKA, D 8 MAGAEPRA, M MAGAEPRA, M	B004150596* 8004290336* B004110500* B004270327* B004090138*	50-305 50-305 50-272 50-305	8 9 9 8	Norderhaud, L R Norderhaug, L R Noreliug, C E Noreliug, C E Noreliug, C E	8094170278 8094300465 8094220294* 8094040926* 8094040277*	70-25 50-206
MOMBY, W R MOMBY, W R MOMBY, W R MOMBY, W R	8004080007 8004080014* 8004180480 8004170350 8004210156	XPORTLIC SO-SBS A XPORTLIC	Napuda, 0 Nabuut, p Nabuut, p Nabuut, p Nabuut, p Nabuut, p Nabuut, p	9004190320# 9004020190# 9004040161# 9004280180# 9004210428#	50-320 50-528 50-312 50-312	O O O	NOPELLUS, CE NORHOLM, LJ NORHALM, LJ NORHALM, LJ NORTON, B	B004150496* B004170293* B004090257 B004220429* B004080712	50~241
MOWRY, U R MUFFLER, R T MUFFLER, R, T MUFFLER, R T MULDER, K J	8004210017 8004210017 8004020290 8004100052 9004100363	FDIA FDIA FDIA CONTRACT	NAUGHTON, N F NAUGHTON, N F NAUGHTON, N F NAUGHTON, N F NAUGHTON, N F	9004020177 8004020189 8004080214 9004080397 8004150316	50-599 50-295 50-295 50-434 50-10	P	NORWICKI,S J NOSENZO,L V NOSENZO,L V NOSENZO,L V NOSENZO,L V	8004170253 8004010479* 8004020368 8004080118 8004080126	50-219 P SECY XPORTLIC XPORTLIC
MULLER, DR MUNGER, PL MUNRO, JJ MUNRO, JJ MURDOCK, LT	9004080275 9004020215 9004100536 9004280127 9004240499	* CONTRACT REGGD 71-9039 40-299	NAUDHON, W F NAUDHON, W F NAMOJ, M NAUDJ, M	8004100338 8004220356 8004100604 8004170284 8004140238	50-295 50-295 PR PR FR 50-405	5 F	NOBENIO, L. V NOBENIO, L. V NOBENIO, L. V NOBENIO, L. V	8004080131 8004080138 8004100040 8004100044 8004100088	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MURLEY, T E MURLEY, T E MURLEY, T E MURPHY, F E MURPHY, J A	7904170340 8004240141 8004280285 7908060334 8004100521	MISC REVIEW ORP REVIEW ORP MISC MISC	nedelman, j neiohodro, d neiohodro, d neilson, r M nelsler, j H	8004280303 8004110338 8004290007 8004090278 8004280420	* 50-326 50-28 NUREO * 50-37	9 0 3 0	Novacek, p Novarro, J p. Novarro, J p Noveliue, c e Noveliue, c e	8004220034* 8004090004 8004040314 8004220620 8004100551*	50-316 P 50-322 G 50-322 A 50-322 A 40-261
MURPHY, W J MURPHY, C E MURPHY, C E MURPHY, P M	8004080316 800408036 8004100503 800404018 800409041	5* 50-375 G 5* 50-375 G 5* 50-566 G 5* 50-259 G 1 50-454 G	NETBON' O NETBON' O NETBON' C NETBON' A NETBON' A D	B004140236 8004040353 8004040142 8004080203 8004250023	50-40 50-38 50-70 40-83	9 U 7 H P 80	NDWICKI, S J NOZENZO, L V NUEBSE, C J NUGENT, E L NUGRAY, J P	8004100320 8004040147 8004070099* 8004020291 8004020228*	40-2259
MURPHY, R J MURPHY, C E MURPHY, P M MURPHY, P M MURPHY, P M	800418031* 800407015 800410932 800410032 800408042	0 50~438 0 2 50~454 0 2 50~454 0 9 50~454 0	Neumann, m r Neuman, J r Neuman, J r Neuman, P s Neuman, J r	8004020232 8004020232 8004280044 8004240188 8004240188	50-46 50-46 40-86	6 Q 6 Q 98	Nussbaumer, D A D'Brien, J II O'Brian, J II O'Brien, J P O'Brien, M J	8004020102* 8004150015 8004240460 8004240453* 8004210076	RES RED
MURPHY, P M MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	800408042 800401048 800404016 800422011 800422013	8 50-454 0 1# 50-316 5 9 50-389 0 9* 50-491 0	newman, J r Newman, J r Newman, J r Newport, E. G Newton, B M	8004230025 8004230025 800423034 800424049 800424049	2 50-44 2 50-44 5 50-22 7 40-21	6 0 6 0 24 0	G'CONNOR, P W G'CONNOR, P W G'CONNOR, L A G'HANLON, J P G'HANLON, J P	8004030188 8004100159 8004080557 8004280487 8004280427	90-206 P 50-105 P 50-245 1 50-313 5 50-369 B
MURPHY, C E MURPHY, W P MURPHY, H P MURPHY, H P MURPHY, M J MURPHY, W P	900424035 800401048 900401049 800401034 900402035	.2* 50-424	nicholas, f c Nicholas, h h Nicholas, d Nijhaman, s Nilegon, r	B0042101% B00415043 B00404002 B00410006 B00410007	1% 50-30 0 NUREO 7 RES 6 70-12	22 0) 257	o neill, J o neill, J o neill, J o neill, J	8004140276 8004140041 8004140044 8004140048 8004140057	\$0~155 & * \$0-155 & * \$0-155 @
МИRРНY, В Р Н К.КНЯВИМ Н К.КНЯВИ	800402036 800404033 800404033 800404033 800408053 800421011	24* 50-272 8 19 50-271 8 32* 50-271 9 33* 50-272 6	KIKIR T NIXIR T	800410050 800410094 800415046 800402036 800401047	0* 50-3 2 50-3 0* 50-3 8* 50-3	61 B 12 T 66 B	D'NEILL, J H O'NEILL, J H O'NEILL, R A D'NEILL, R A O'NEILL, R A	9004010519 9004010519 9004240043 9004240045 9004240053	50-100 0 30-145 M 50-145 M

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	<u>′</u>
O'NEILL.R A O'NEILL.R A O'REILLY.J P O'REILLY.J P O'REILLY.J P	8004240043 8004240053 8004160038 8004090337 8004090339	50-445 M 50-445 M 50-34B Q 50-302 Q 50-414 Q	O'REILLY, J P	8004180321 8004180326 8004180375 8004180378 8004180382	50-250 0 50-269 0 50-488 0 50-261 0 50-437 0	ORLANDO, E ORLOSKY, P M ORPHAN, R C ORTH, D A ORTLOFF, G D	8004100471 7905190093 8004250066 8004140121 B004070154	50-352 50-57 TDPREP ACRS 40-8102	H P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004090340 8004090343 8004090344 8004090349 8004090352	50-395 Q 50-395 Q 50-250 Q 50-321 Q 50-259 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004110010 8004110011 8004110014 8004110017 8004110021	50-324 Q 50-321 Q 50-416 Q 50-518 Q 50-259 Q	ORTLOFF, G D ORTLOFF, G D OSANN, E W OSANN, E W OST, F	8004280403 8004270526 8004230071 8004230101* 8004020313*	40-8102 40-8102 50-367 50-367 50-295	G G S
O'REILLY, J P	8004090358 8004090360 8004020211* 8004020220* 8004300124*	50-280 G 50-437 Q 50-395 Q 50-395 Q 50-395 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004210204 8004230102 8004230108 8004230109 8004230113	50-140 Q 50-437 Q 50-280 Q 50-395 Q 50-348 Q	051, F 051, F 011050N, H L 011050N, H L 011050N, H L	8004220668* 8004290496* 8004070338 8004080177 8004080483*	50-275 50-275 50-204 50-204 50-204	5 5 5 5
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004090025 8004090391 8004100217 8004150313 8004150315	50-328 0 50-395 0 TOPREP 50-348 0 50-302 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004230117 8004230122 8004230132 8004230142 8004230158	50-261 0 50-488 0 50-269 0 50-259 0 50-395 0	OTTOSON, H L OTTOSON, H L OTTOSON, H L OUZTS, J E	8004210270 8004180450 8004210254 8004250418 8004280157*	50~206 50~206 50~206 50~206 50~325	5 5 0
D'REILLY, J P D'REILLY, J P D'REILLY, J P D'REILLY, J P	8004150491 8004150492 8004150495 8004150497 8004150505	50-416 Q 50-375 Q 50-375 Q 50-261 Q 50-488 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004230165 8004230169 8004230173 8004230181 8004180317	50-250 Q 50-302 Q 50-321 Q 50-416 Q 50-302 Q	OVERDORFF. J S OVERLID. T W OVERLID. T W OVERLID. T W OVERLID. T W	8004080092 8004190955* 8004150964* 8004150623* 8004140437*	FOIA 50-263 50-263 50-263 50-263	5 5 5
G'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150511 8004150517 8004150521 8004150527 8004150540	50-269 Q 50-250 Q 50-321 Q 50-259 Q 50-280 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004180323 8004180328 8004180332 8004180335 8004180340	50-34B 0 50-416 0 50-395 0 50-395 0 50-261 0	OWSLEY, O F OWSLEY, O F OWZARSKI, P PAGANO, C L PAGAND, C L	8004020404 8004020307 8004040270 8004140149 8004210140	TOPREP 50-261 RES PR PR	P
O'REILLY, J P	8004150550 8004080582 8004080583 8004080587 8004080587	50-437 Q 50-348 Q 50-395 Q 50-395 Q 50-416 Q	O'REILLY, J P	8004180351 8004180358 8004180401 8004180417 8004180436	50~488	PAGE,R O PAGE,R O PAGE,R O PAGE,R O PAGE,R O	8004240201 8004240207* 8004150058 8004150068* 8004150107*	50~438 50~438 70~1113 70~1113 70~2909	A
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004080595 8004080598 8004080604 8004080611 8004080619	50-302 Q 50-261 Q 50-488 Q 50-269 Q 50-250 Q	O'REILLY, J P O'REILLY, J P O'ROURKE, S O'TOOLE, J D	8004180445 8004180476 8004300205 8004080007 8004150433	50-259 Q 50-437 Q 50-269 Q 71-9029 50-247 P	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8004150104 8004150289 8004240554* 8004240550 8004020473	70-2909 70-1113 70-135 70-135 50-364	Α
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004080624 8004080636 8004080652 8004080658 8004180064	50-321	OBERG.C T OBERG.C R ODLAUG.M OESTMANN.M J OFBANIK.W J	8004040102# 8004140049# 8004220028# 8004300555# 8004040103	40-8135 50-458 G FOIA 50-10 G XPORTLIC	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8004020481* 8004100593 8004150300 8004080565 8004240153	50-364 70-1113 70-820 70-143 70-143	۸
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150067 8004150070 8004150075 8004150080 8004150081	50-261	OKRENT, D OKRENT, D OLCOTT, K OLCOTT, K OLCOTT, K	8004080623* 8004140030 8004140047 8004140052* 8004140426	ACRB ACRS PR PR PR	PAGE,R G PAGLIARD,J A PAGLIARD,J A PAGLIARD,J A PAGND,C L	8004160027 8004030327* 8004030316* 8004030319* 8004140108	40-1193 FDIA FDIA FDIA PR	
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150088 8004150089 8004150091 8004150093 8004150097	50-416	OLEM, H OLLER, R E OLLER, R E OLMSTEAD, W J OLMSTEAD, N J	8004150376* 8004010515* 8004070277* 8004020277* 8004150160	50-553 R QA799 QA799 50-387 G 50-389 G	PANCIERA: V PANETTA: L E PAOLINO: R J PAPAY: L T PAPAY: L T	7908210548 8004290146 8004070396# 8004020049# 8004150538	50-10 50-275 50-387 50-361 50-361	P 0 0 5
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004150105 8004150107 8004240224 8004240227 8004240229	50-280	OLSEN, A F OLSEN, A F OLSEN, A F OLSHAN, L N OLSON, R C	8004240236 8004220127 8004180355 8004100169 8004010212	70-824 71-6400 50-13 P 50-247 P 50-318 P	PAPERIELLO,C J PAPERIELLO,C PAPERIELLO,C J PARIS,O H PARIS,O H	8004040102* 8004100551* 8004070173 8004080695 8004230111	40-8135 40-241 146 50-387 50-387	G G
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004240231 8004240233 8004240235 8004240239 8004240239	70-1201 70-1113 70-143 50-437 G 70-1151	OLSON, J F OLSON, J F OLSON, R C OMATA, I ONCAVAGE, M A	8004230088 8004230100 8004090359 8004280032 8004240086	50-282	PARK, Y 8 PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004040459 8004070362 8004230236* 8004080125 8004110559	NUREG 50-269 50-269 PR PR	G G
O'REILLY, J P O'REILLY, J, P O'REILLY, J P O'REILLY, J P	8004240242 8004240245 8004240247 8004240254 8004240259	50-348	ONCAVAGE,M P ONSDORFF,K A OPEKA,J F OPEKA,J F OPEKA,J F	8004080550 8004080633 8004010407 8004010423 8004070308	50-250	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	6004300214* 6004040356 6004060253 6004250334* 6004100351	50~269 50~269 50~269 50~269 50~269	Q Q Q Q
O'REILLY, J P O'REILLY, J, P O'REILLY, J P O'REILLY, J, P O'REILLY, J P.	8004240260 8004240265 8004240268 8004240267 8004240271	50-250	OPEKA, J F. OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F	8004170224 8004170194 8004180437 8004180398 8004180408	50-334 S 50-336 S 50-245 S 50-336 S 50-336 S	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8004020019 8004180514 8004240035 8004210164 8004020348	50-413 50-369 50-269 50-413 50-369	0 0 8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P. O'REILLY, J P	8004240274 8004240284 8004180268 8004180269 8004180271	50-259 Q 50-280 Q 50-416 Q 50-395 Q 50-395 Q	OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F	8004180383 8004220411 8004210246 8004220670 8004280525	50-245 R 50-334 R 50-245 R 50-336 S 50-336 B	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8004070234 8004160272 8004010470 8004030157 8004030199	50-369 50-287 50-269 50-269 50-269	A S P F P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004180272 8004180274 8004180275 8004180279 8004180303	\$0-348	OPEKA, J F OPPENHEIM, L OPREA, O W. OPREA, O W OPREA, O W .	8004270277 8004040308 8004040240 8004040374 8004040370	50-245 8 50-320 H 50-498 A 50-498 S 50-498 S	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8004070327 8004210191 8004210234 8004030152 8004030223	50-269 50-269 50-413 50-369 50-287	9 0 F 5

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004080555 8004160116 8004210172 8004080614 8004080366	50-269 P 50-413 G REGGD 50-269 P 50-369 A	PECK, C C PECK, C C PECK, O E PEERY, W W PEERY, W W	8004100383* 8004040055* 8004180337* 8004280288* 8004210034*	50-182 Q 50-312 Q 50-390 R 50-317 Q 70-1100	PETERSON, M R	8004040045 8004040049* 8004040480 8004070037 8004080251	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8004080432 8004080455 8004080471 8004140348 8004170164	50-287	PEERY, W W PEERY, W W PEERY, W W PEERY, W W	8004210076* 8004210337* 8004210345* 8004220402* 8004080140*	50-272 Q 50-333 Q 50-245 Q 70-1143 27-47	PETERBON, M R	8004080295 8004080299 8004080303* 8004080315 8004080627	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W C PARKER, W C PARKER, W C PARKER, W C PARKER, W C	8004170203 8004150465 8004160229 8004220443 8004180273	50-269 S 50-269 P 50-287 S 50-269 F 50-369 F	PEERY, W W PEERY, W W PEERY, W W	8004040023* 8004100408* 8004020387 8004020418* 8004020424*	50-10 Q 50-10 Q REGOD 50-213 F 50-213 F	PETERSON, M R	8004180309 8004210002 8004110141 8004100062 8004210364	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W C PARKER, W C PARKER, W C PARKER, W C PARKER, W C	8004220502 8004220682 8004220640 8004220649 8004220720	50-249 P 50-269 S 50-269 P 50-270 P 50-369 A	PELLEK,R R PELTIER,I A PENCE,W B PENCE,W B PENCE,W B	8004070347* 8004250026 8004010351* 8004150486* 8004290377*	50-320 R 50-358 A 50-318 S 50-318 S 50-317 S	PETERSON, M R	8004100049 8004160082 8004100179 8004100179 8004100232	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W O PARKER, W O PARKINSON, T F PARKINSON, T F PARKINSON, T F	8004180356 8004270473 8004150431 8003310406 8004040468	50-269 P 50-369 A 50-124 P 50-124 B 50-124 F	PENCE, W B PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R PENNEY, J A	8004290438* 8004020346* 8004210280* 8004290451* 8004090076	50-317 S 50-368 S 50-368 R 50-368 R 71-9019	PETERSON, M R PETERSON, M R PETERS, R J PETERSON, M R PETERSON, M R	8004210369 8004210379 8004080443 8004100180 8004100181	XFORTLIC XPORTLIC 50-275 A XPORTLIC XPORTLIC
PARMENTER, F H PARMENTER, F PARR, O D PARR, O D PARR, O D	8004090204 8004170340 8004020247 8004020256 8004040428	50-445 M 50-445 M 50-337 A 50-311 A 50-339 A	PEOPLES, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L	8004180389 8004030027 8004100128* 8004140119 8004140441	50-247 P 50-237 P 50-10 G 50-10 G 50-456 A	PETERSON, M R PETERSON, M R PETERS, R J PETERSON, M R PETERSON, M R	9004100184 8004170271 8004150435 8004240224 8004210451	XPORTLIC XPORTLIC 50-275 A XPORTLIC XPORTLIC
PARR, O D PARR, O D PARR, O D PARR, O D PARR, O D	8004070052 8004080654 8004070097 8004070101 8004080396	50-438 F 50-387 A 50-373 A 50-311 A 50-339 A	PEOPLES, D L	B004030172 B004070273 B004220299 B004180372 B004230479	50-10 F 50-284 F 50-237 F 50-249 P 50-373 A	PETERS, B PETERSON, M R PETIT, M R PETRICK, N A PETRICK, N A	8004170240 8004300016* 8004290514* 8004040269 8004100280	50-313)/ XPORTLIC CONTRACT 50-482 8 50-482 Q
PARR, O D PARR, O D PARR, O D PARR, D D PARR, D D	8004150128 8004280308 8004040016 8004070189 8004210410	50~498 A 50~438 A 50~482 A 50~483 A 50~387 A	PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L	8004250427 8004240412 8004280509 8004230347 8004250353	50-373 A 50-265 P 50-295 P 50-10 F 50-249 P	PETRILLO, M PETRICK, N A PETRICK, N A PETRICK, N A PETRIC, L PETRICK, N A	8004110096 8004190179 8004150369 8004210264* 8004280463	50-320 H 50-482 B 50-482 B 50-10 H 50-482 A
PARR.O D PARR.O D PARR.O D PARR.O D PARSONS.W D	8004110046 8004210408 8004100484 8004240149 8004040152*	50-438 A 50-460 A 50-387 A 50-311 A XPORTL10	PEOPLES.D L PEOPLES.D L PERKINS.J L PERLAS.N PERLMAN.J	6004280410 8004270502 8004220032 8004070180* 8004040120*	50-373 A 50-295 P 50-397 G SECY CONTRACT	PETTIGREW,R R PFAFF,B J PFAFF,B J PFAFF,B J PFAFF,B J	8004030284 8004070144 8004070155* 8004070159* 8004070164*	PR 40~6657 40~6657 40~6657 40~6657
PARSONS, W B PARTLOW, J PARTLOW, J G PARTLOW, J G PARTLOW, J G	8004040141 8004240137* 7904210192 8004070351 8004070419	XPORTL1C 70-138 H1SC 70-143 70-143	PERLMAN. J PERNY.C D PERNY.C B PERRIGO, L D PERRIN. J S	8004290113* 8004040047* 8004030362* 8004290020 8004300192	CONTRACT 70-143 70-2470 Nureq Nureq	PFAFF.S J PFEFFEREEN.H C PHILBRICK.S S PHILIPS.M H PHILIPS.M H	8004070169* 8004080036* 8004040167 8004280189 8004280189	40-6659 TOPREP 50-30 0 50-356 0 50-356 0
PARTLOW, J Q PARTLOW, J G PARTLOW, J G PARTLOW, J G PARTLOW, J G	8004080072 8004100105 8004290062 8004160018 8004210106	70-820 70-1287 70-371 70-1257 70-27	PERROTTI.D J PERRY.W W PERRY.J C PERRY.J C PETERBON.M R	8004040402* 8004210082* 8004150442* 8004270478* 8004210077*	50-269 Q 50-277 Q 50-344 8 50-344 8 70-2478	PHILLIP, G A PHILLIP, G A PHILLIP, G A PHILLIPS, L B PHILLIP, O A	\$004220178* 8004220196* 8004220327* 8004220171* 8004180496*	FDIA FDIA FDIA 50-320 H 50-341 0
PARTLOW, J G PASEDAG, W F PASINDSKY, J P PASTERNAK, R J PASTERNAK, R. J	8004270048 8004180416* 8004180495 8004070318 8004070436	70-1201 50-272 T XPORTLIC 50-333 R 50-333 S	PETERBON, R J PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R	8004100057 8004020387 8004070028 8004070088 8004020393	PRM XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILLIPS, J R	8004020133 8004070038 8004070132 8004070137* 8004080556	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J. PATAPOVS, U.	8004220/67 8004280552 8004270504 8004270474 8004150145	50~333 S 50~333 S 50~333 S 50~333 S GA999	PETERBON, M R	8004020397 8004020401 8004020406 8004080620 8004020184	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILLIPS, J PHOENIX, D R PIELAGE, H W PIERGE, A C PIGGTT, D R	8004210322 8004210355* 8004280383 8004180076 8004100477	50-275 0 50-320 P NUREO 50-201 P 50-361 0
PATAPOVS.U PATAPOVS.U PATE.R J PATE.R J PATE.R J	B004100001 B004300078* B004210417* B004210166* B0042B0095*	0A999 0A999 50-361 Q 50-361 O 50-361 Q	PETERBON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8004040087 8004040099 8004070407 8004090113 8004040477	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIGDTT,D R PIGDTT,D R PIGDTT,D R PILANT,J M PILANT,J M	8004100477 8004100537 8004100537 8004230192 8004140479	50-361 0 50-361 0 50-361 0 50-298 0 50-298 0
PATON.W D PATON.W D PATON.W D PATON.W D PATTERSON.E	8004020277* 8004150160 8004090043 8004220674 8004080204*	50-369	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8004090198 8004090202* 8004250039 8004250042* 8004030049	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	M L.TNALIF H L.TNALIF H L.TNALIF H L.TNALIF H L.TNALIF	8004250077 8004250240 8004280184 8004010454 8004230371	50-298 0 RECOD 50-298 G 50-298 F
PATTERN, K PATTERBON, J P PATTERBON, K P PATTERBON, J P PAUL, R	8004020493 8004090431* 8004040068* 8004110498* 8004090327*	50~327	PETERSON, M R	8004040178 8004080087 8004080096 8004080311 8004080350	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PILANT, J, M PILANT, J M PLANJE, T J PLASKON, R E PLATO, P	8004040374 8004230457 8004270083* 8004220036 7704110103	50-29B R 50-29B P 50-123 G 50-516 G 50-2 P
PAUL,R A PAULUS,R C PAVLIND,R T PAYNE,J P PEABODY.C A	80041003774 8004020106# 8004100112# 8004080328 8004280075	50~150	PETERSON, M R, PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8004080353 8004220116* 8004030364 800404003B 8004040042*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLESSET, M 8	8004150010 8004180079 8004020032 8004080070 8004180074	ACRB NUREO COMMISSION ACRB

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PLESSET, M S	8004030333* 8004040272 8004040274* 8004150016 8004150046	50-312 G NUREG NUREG ACRS ACRS	POTTER.J P POTTER.J P POTTER.J P POTTER.J P POTTER.J P	8004210035* 8004210120* 8004280310* 8004280288* 8004210034*	40-672 50-287 0 50-293 0 50-317 0 70-1100	RATHKOPF, C L RAUNER, L IN RAUNER, L IN RAUSCH, J K RAUSCH, J K	8004220124* 8004020192 8004010038 8004040125* 8004300493*	50-320 H FOIA FOIA 50-416 Q 50-395 Q
PLESSET, N S PLESSET, N S PLESSET, M S PLUMLEE, K E PLUMLEE, K E	8004150208 80040402774 8004150006 8004100014* 8004210102*	ACRS HUREG ACRS 50-184 G 50-320 O	POTTER, J P POTTER, J P POTTER, J P POTTER, J P POTTER, J P	8004210076* 8004210082* 8004210339* 8004210345* 8004220402*	50-272 Q 50-277 Q 50-333 Q 50-245 Q 70-1143	RAUSCH, J K RAYMOND, L W RAYMOND, L W RAYMOND, L W READ, J	8004090183 8004220134* 8004220162* 8004210071* 8004020474*	50-416 9 50-491 9 50-320 H 50-244 9 50-522 9
POCHAL,W F POCHAL,W F POCHAL,W F POCHAL,W F POCHAL,W F	8004080342 8004220111 8004210123 8004210134 8004300458	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTTER.JP POTTER.JP POTTER.JP POTTER.JP POTTER.JP	8004040035* 8004040399* 8004040453* 8004080147* 8004080140*	50-255 Q 50-315 Q 40-2061 27-47 27-47	RECORD, D J RECORD, D J RECORD, D J RECORD, D J RECORD, D J	8004170227* 8004010381* 8004010403* 8004010371* 8004010475*	50-327 F 50-327 S 50-327 S 50-327 S 50-327 S
POCHALIW F PODHURSTIO U PODHURSTID W PODHURSTID W POGGIOA	8004300459 800404042* 8004040437* 8004040442* 8004280059	XPORTLIC FOIA FOIA FOIA RES	POTTER, J P POTTER, J P POTTER, J P POTTER, J P POTTER, J P	8004040023* 8004100408* 8004100528* 8004010009* 8004040171*	50-10 Q 50-10 Q 50-254 Q CONTRACT 50-331 Q	RECORD, D J RECORD, D J RECORD, D J RECORD, D J RECORD, D J	8004170229* 8004170231* 8004170234* 8004090336* 8004090457*	50-327 F 50-327 F 50-327 F 50-327 S 50-327 S
POGGIO, A POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R	8004240465 8004090434 8004030344 8004090434 8004080044	RES 50-445 M 50-445 M 50-445 M 50-445 M	POTTHOFF,F H POTTHOFF,F H POTTS,W E POWERS,J A POWER,D F	8004240555* B004100474 B004170106* B0040B061B B004010054	50-466 G 50-466 G 50-269 P CONTRACT FOIA	RECORD, D J	8004180465* 8004180407* 8004150512* 8004150565* 8004220722*	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8
POIRIER, MR POIRIER, MR POIRIER, MR POIRIER, MR POIRIER, MR	8004080044 8004040078 8004180032 8004180050# 8004180050#	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	POWER, D F POWERS, M B POWER, D F PRAGER, J C PRATT, C M	8004070127 8004300243 8004270152 8004140244 8004100434	FOIA 40-8722 FOIA 50-280 P PR	RECORD, D J REED, J W REED, R W REED, C REED, M	8004220757* 8004040153* 8004150103 8004020429 8004290407*	50-327 S 50-70 P 50-346 P TOPREP 50-265 B
POLI, D.L. POLLARD, R. D. POLLARD, R. D. POLLARD, R. O. POLLARD, R. G.	8004030287 8004020115* 8004070190 8004030320 8004110175	PR 50-3 0 50-287 0 50-287 0 50-287 0	PRESSESKY,A J PRESSESKY,A J PRICE,E R PRICE,E R PRICE,E R	8004240568 8004280172 8004080142* 8004080110* 8004080060*	PR PR FOIA FOIA FOIA	REED, C REEHAL, B B REEVES, E REEVES, E A REEVES, E	8004290434 8004220528* 8004110573 8004110559 8004300588	TOPREP FOIA 50-348 F 50-295 Q 50-295 F
POLLARD, R Q POLLARD, R Q POLLARD, R Q POLLARD, R Q POLLARD, R Q	8004230039 8004160039* 8004110157 8004110164* 8004110166*	50~287 G 50~320 P 50~287 G 50~287 G 50~287 Q	PRICE,E R PRICE,E R PRICE,E R PRICE,E R PROFIO,A E	8004080095* 8004080098* 8004080084* 8004080076* 8004070329*	FOIA FOIA FOIA FOIA 50-433 R	REGAN, W H REHM, T A REHM, T A REHM, T A REHM, T A	8004020154 8004070066 8004100572 8004140457 8004250046	50-272 P COMMISSION COMMISSION COMMISSION
POLLACK, Q L POLLEY, R D POLLITT, K POLLOCK, R P POLOBKI, J P	8004240479# 8004020179# 8004040224 8004090152 8004020142	50-320 P COMMI881ON 90-352 H PR RES	PROXMIRE, W PROXMIRE, W PUCILLO, A C PUCKETT, J M QUARANTELLI, E	8004140379* 8004080264* 8004240041* 8004250291* 8004230514	50-266 U 50-409 U CONTRACT 50-261 G 50-320 H	REICHERT, E C REICH, M REID, R W REID, R W REID, R W	8004070276* 8004240566 8004080437 8004080440* 8004030275	50-317 R NUREC 50-317 P 50-317 P 50-285 P
POPE, J R POPE, J R PORTER, W L PORTER, W L POTAPOVS, U	0004180223 8004080160 8004090241 8004280473 8004070087*	50-546 G 50-546 A PR PR QA999	GUEENER, D S GUICK, D GUICK, D R GUIGG, C GUIGG, C	8004230303* 8004300187* 8004300260* 8004150031 8004010171	NUREG 50-302 G 50-269 G 50-268 P FOIA	REID,R W REID,R W REID,R W REID,R W REID,R W	8004040091 8004040096* 8004040109* 8004070160 8004210108	50-317 P 50-317 P 50-317 P 50-313 P 50-289 H
POTAPOVB, U POTAPOVB, U POTAPOVB, U POTAPOVB, U POTAPOVS, U	8004070083* 8004080276* 8004140037* 8004030239* 8004010512	QA999 QA999 QA999 QA999 QA999	QUIQQ, C QUIQLEY, E J QUIQLEY, J R QUINN, E QUINN, E,	8004280590 8004080479 8004100194* 8004020069 8004080197	50-295 G 70-1308 CONTRACT 70-135 70-135	REID.R W REID.R W REID.R W REID.R W REID.R W	8004070266 8004080002 8004150177 8004010255 8004030230	50-336 P 50-302 P 50-312 F 50-269 P
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004140027* 8004040348* 8004080367* 8004080287*	QA797 QA997 QA979 QA979 QA999	GUIRK, J F GUISENBERRY, G F RADER, R M RAFI, A. RAGSDALE, J D	8004280422 8004020114* 8004110574 8004070276* 8004210395*	50-550 A 50-289 H 50-445 M 50-317 R 50-275 G	REID.R W REID.R W REID.R W REID.R W REID.R W	8004020449 8004170294 8004100115 8004150110* 8004150120*	50-312 P 50-289 P 50-312 P 50-346 P 50-346 P
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004040111 8004080301* 8004290021* 8004020423 8004070307	QA999 QA999 QA999 QA999 QA999	RAINEY, J L RANDOLPH, M L RANDOLPH, M L RANSOHOFF, J A RAPKIN, A	8004070151 8004040369 8004160095 8004090121* 8004030302	40-2061 RES RES 71-121 FOIA	REID, R W REID, R W REID, R W REID, R W REID, R W	8004160180 8004150082 8004210321 8004100241 8004100246*	50-335 P 50-54 P 50-269 P 50-312 P 50-312 P
POTAPOVB, U POTAPOVB, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	80040903B2* B00414001B* B004090067 B004100031 B004110064*	QA999 QA999 QA999 QA999 QA999	RABH, J L RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L	8004170020* 8004030054* 8004030071* 8004030093* 8004040233*	50-324 P 50-320 H 50-320 H	REID,R W REID,R W REID,R W	8004100255* 8004110481 8004170316	50-312 P TOPREP 50-317 F
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004070076 8004300217 8004040474 8004070058 8004080255	QA979 QA979 QA979 QA999 QA999	RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L RATHKOPF.C L	80040402 80040402 80040404 80040404 80040902				
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8004080358 8004090282 8004080291 8004030235 8004070371	QA999 QA999 QA999 QA999 QA999	RATHKUPF,C L RATHKUPF,C L RATHKUPF,C L RATHKUPF,C L RATHKUPF,C L	80042102 80042201 80042201 80040204 80040300				
	0003140011	AABBB	RATHKOPF.C I	80040402				

RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L

POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTTER, J P 8004140011 8004110031 8004270016 8004300084 8004160172* QA999 QA999 QA999 QA999 50-277

a

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT CATEGORY
REINMUTH G U	8004280968*	50-334 P	ROCKHOLD, H C	8004250364	50-295 P	ROTHE, P. H.	8004140478	NUREO
REIS H F	8004020265*	50-389 G	RODACK, M	8004076184	50-387 H	ROTHFLEISCH, J.	8004070353	NASTE HOT
REIS H F	8004220141	50-389 G	RODEN, J W	8004150385*	50-386 R	ROTHFLEISCH, J.	8004070369	WASTE HOT
REIS H F	8004020265*	50-389 G	RODEN, J W	8004150390*	50-321 R	ROTHFLEISCH, J.	8004090209	40-8721
REIS H F	8004220141	50-389 G	RODEN, J W	8004150404*	50-321 R	ROTHSCHILD, M. U.	8004080726	50-445
REIS,E J	8004086355	50-443 Q	RODGERS, L. M	8004020418*	50-213 F	ROTHSCHILD, M U	8004090015	50-445 0
REIS.H F	8004240484	50-250 G	RODGERS, L. M	8004020418*	50-213 F	ROTHSCHILD, M U	8004090446	70-1308
REIS.H F	8004246484	50-250 G	RODGERS, L. M	8004020424*	50-213 F	ROTHSCHILD, M U	8004100151	70-1308
REIS.H F	8004110529	50-250 G	RODRIGUEZ, R. J	8004160266	50-312 R	ROTHSCHILD, M U	8004100164*	70-1308
RENEMEYER.P C	8004080278	HASTE MOT	RODRIGUEZ, R. J	8004220731	50-312 S	ROTHSCHILD, M M	8004210424	50-445 0
REKEMEYER P C	8004020165	WASTE NGT	ROE.D	8004040346	50-275 H	ROTHSCHILD, M U	8004240424*	50~445
REMLEY'N E	8004280061	71-6400	ROE.J W	80040701834	50-250 F	ROTHSCHILD, M U	8004250348	
RENBERGER,D L	8004030341	PR	ROE.J W	80040702773	50-250 F	ROTHSCHILD, M U	8004170251	
RENBERGER,D L	8004230271*	50-460 Q	ROGERS.R F	80041500963	50-321 0	ROTHSCHILD, M U	8004230206	
RENBERGER,D L	8004020339	50-397 K	ROGERS.R F	8004150155*	50-321 0	ROTHSCHILD, M U	8004220377	
RENBERGER, D L	8004230248*	50-460 Q	ROGERS, W.L.	8004070115	NASTE MGT	ROTHSCHILD, M U	8004240421	5Q-445 0
RENBERGER, D L	8004010340	50-508 A	ROGERS, B.J.	8004210060*	50-29 H	ROTHSCHILD, M U	8004240433*	50-445 0
RENBERGER, D L	8004020293	50-397 S	ROGERS, H. A.	8004140070*	70-1308	ROUNDTREE, R E	8004100430*	50-445 M
RENBERGER, D L	8004020302	50-397 E	ROGERS, W.F.	8004180088	YPORTLIC	ROUSE, L C	8004010186*	70-1308
RENBERGER, D L	8004070367	50-397 A	ROGERS, W.F.	8004180089*	XPORTLIC	ROUSE, J V	8004090140*	Waste Mot
RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L.	8004170207	50-397 A	ROGERS, W F	8004180072*	XPORTLIC	ROUSE, L C	B004180441*	50-269 0
	8004140345	50-397 K	ROGERS, L W	8004210297*	50-10 H	ROWDEN, M	B004220442*	F01A
	8004150443	50-508 A	ROGERS, C S	8004280030	50-556 G	ROWE, D S	B004070234	71-24
	8004210213	NUREG	ROGERS, W H	8004020359*	50-321 S	ROY, G W	B004140202	18E
	8004210285	50-397 A	ROGERS, W H	8004220658*	50-366 S	ROY, G W	B004220226	50-272 8
RENBERGER, D. L.	8004280466	50-397 S	ROGERS, W H	8004220684*	50-321 8	RDY.G W	6004220249	50-26J B
RENDERGER, D. L.	8004280475	50-397 S	ROGERS, W H	8004220717*	50-366 5	ROY.G W	6004210429	50-231 B
RENNELS, A. E.	8004080177	40-2061	ROMAN, T W	8004140411*	50-220 R	ROZEK,R	6004030237*	6A999
RENNO, E.	8004040300	50-320 H	ROOD, H	8004270133	50-361 A	RUBENSTEIN,L B	6004140090	50-329 A
RESSLER, W. C.	8004140250	50-320 R	ROONEY, M A	8004140078	70-1308	RUBENSTEIN,L B	6004010014	50-410 A
REYES, LA REYNOLDS, NS REYNOLDS, NS REYNOLDS, LE REYNOLDS, NS	8004100022+ 8004080119 8003250002 8004070254 8004040068	50-346 O PR NUREO 71-9122 50-445 O	RONEY,W A ROONEY,V L ROOT,L D ROOT,L D ROOT,L D	8004140060 8004070040 8004160005 8004220269 8004140380	70-130B 50-271 P 50-331 G 50-331 F 50-331 P	RUBENSTEIN, L S	8004040079 8004070041 8004070072 8004070419 8004070393	50-397 A 50-440 A 50-327 Q 50-327 P 50-327 P
REYNOLDS, N S REYNOLDS, L E REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S	8004080221 8004090091 8004040088 8004080221 8004140005	50-445	ROOT,L D ROOT,L D ROOT,L D ROREM ROSA,F	8004220507 8004280461 8004280454 8004150106 7811100178	50-331 P 50-331 P 50-331 F 70-1308 50-313 B	RUBENSTEIN, L S	8004020093 8004090034 8004100297 8004110493 8004100507	50 327 P 50 410 F 50~410 A 50 327 P 50~367 A
REYNOLDS, N S RHEINHEIMER, D	6004280187 6004280187 8004160285 6004240424* 6004070171	50-556 Q 50-556 C 50-397 A 50-445 Q 50-387 H	ROSEN, A.E. ROSENTHAL, B S ROSEN, A E ROSOLIE, E ROSOH, D F	80040700B1* 8004300297* 8004070079* 8004230020 8004040295*	98797 U E-08 98999 0 44E-08 0 719-08	RUBENBTEIN, L. 8	8004140115 8004140118 8004180306 8004230186 8004250001	50-454 F 50-454 F 50-327 F 50-546 A 50-327 A
RHEINHEIMER, D RICE, O B RICHARDBON, H D RICHARDBON, H D RICHTER, S W	8004070064 8004080163* 8004210037 8004020025 8004040295*	50~3B7 H 40~2041 71~6717 71~9135 50~317 G	ROSOW.D F ROSOW.D F ROSS.D M ROSS.D ROSS.D F	8004040296* 8004040301* 8004020055 8004020237* 8004040031	50-317	RUBENBTEIN, L S RUBENBTEIN, L S RUBENBTEIN, L S RUBENBTEIN, L S	8004170263 8004180058 8004180070* 8004280617 8004300266	50-443 1 50-328 A 50-328 A 50-397 A 50-328 Q
RICHTER, S W	8004040296#	50-317 Q	ROSS.D F	8004040017	50-275 A	RUBENSTEIN, L S RUBENSTEIN, L S RUETER, D A RUETER, D, A RUFF, A B	8004300270#	50 328 Q
RICHTER, S W	8004040301#	50-317 Q	ROSS.D A	8004080421	50-217 G		8004240482	50-390 F
RICHTER, T	8004220569	50-320 H	ROSS.D A	8004090246*	50-217 G		8004010416	50-313 Q
RICKOYER, H G	8004090082	DRG	ROSS.L L	8004010789*	PT9		8004240380	50-313 P
RICKOVER, H G	8004090087	DRG	ROSS.P A	8004150430	NUREG		8004100051#	50-416 Q
RLINA, JR	8004170139	FQIA	ROSS.W J	8004020433	50-272 P	RVH-MING.L	8004280425*	40-8602
RILEY, BW	85042801574	50-325 0	ROSS.D F	8004230058	50-275 A	RVH-MING.L	8004280427*	40-8602
RISCHLING, JL	8504010500*	50-314 S	ROSS.D A	8004100424	50-217 G	RVITER.O H	8004180355*	50-305 R
RISCHLING, JL	8504080545*	50-314 S	ROSS.D F	8004020453	TDPREP	RVSSELL,W T	8004280065	50-334 P
RISCHLING, JL	8504230357*	50-316 8	ROSS.D F	8004110040	50-271 P	RVSSELL.L B	8004010439	50-318 B
RITSHER, J A RITYS, F H RIVARD, W C RIZZI, R A RIZZI, R A	8004070299 8004080559 8004150141* 8004090208 8004090208	50~443 I 50-445 M NUREO PROJ PROJ	ROSS.W J ROSS.D F ROSS.D A ROSS.D A	8004150227 8004020213 8004010480 8004010485* 8004010503	50-272 P 50-329 H 50-219 S 50-219 S 50-219 S	RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8004010342 8004010376 8004010380 8004010430 8004010364	50-310 6 50-310 8 50-310 6 90-317 8 50-310 8

c

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION REMUN	SUBJECT CATEGORY
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUZICKA, W G RUZICKA, W G	8004270459 8004270475 8004270470 8004080548 8004090375	50-317 S 50-317 S 50-317 S 50-317 S 50-54 R 50-54 R	SCHMIDT, E W SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8004040204 8004180529 8004020377 8004030282 8004030249	RES 50-250 R 50-251 S 50-335 S 50-250 S	SCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8004280151* 8004280156* 8004040179 8004040183* 8004240251	50-261 P 50-261 P 50-250 P 50-250 P 50-250 P
RYAN.R G	8004070094	50-3 P	SCHMIDT, A D	8004080601	50-250 S	SCHWENCER: A	8004240263*	50-250 P
RYAN.R O	8004040193	State Prog	SCHMIDT, A D	8004180373	50-250 R	SCHWENCER: A	8004240283*	50-250 P
RYAN.R M	8004300320*	50-225 G	SCHMIDT, A D	8004240309	50-250 S	SCHWENCER: A	8004030012	50-312 H
SABOL.A R	8004070382*	50-387 G	SCHMIDT, A D	8004240334	50-335 S	SCHWENCER: A	8004070322	50-344 G
SABOL.A R	8004100098*	50-387 G	SCHMIDT, A D	8004240369	50-335 B	SCHWENCER: A	8004220087	50-344 P
SAENGER, E. L. SAENGER, E. L. SAENGER, E. L. SAENGER, E. L. BAENGER, E. L.	8004220044* 8004220097* 8004220101* 8004220120* 8004220387*	FOIA FOIA FOIA FOIA	SCHNEIDER, F N SCHNEIDER, F N SCHNEIDER, F N SCHNEIDER, F N SCHNEIDER, F N	8004080318 8004100256 8004100247 8004300488 8004240494	50-272 Q 50-272 Q 50-272 Q 50-272 Q 90-272 Q	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004240442 8004080320 8004240462 8004300276 8004300280*	50-344 F 50-280 P 50-315 P 50-266 P 50-266 P
BAENGERIE L	8004220391*	FOIA	SCHNEIDER, F W	8004280124*	50-272 0	BCHWENCER, A	8004300287*	50-266 P
SAENGERIE L	8004220404*	FOIA	SCHNEIDER, F W	8004280207	50-272 0	BCHWENCER, A	8004210194	50-295 P
SALAHIB	7903080264	MISC	SCHNEIDER, F W	8004070225	50-272 I	BCHWENCER, A	8004240163	50-247 P
BALTZMANIJ	8004080173*	FOIA	SCHNEIDER, F W	8004160249	50-272 0	SCHWENCER, A	8004240175*	50-247 P
SALTZMANIJ	8004140124*	FOIA	SCHNEIDER, E J	8004160246	50-272 0	BCHWENCER, A	8004020096	50-261 P
SALTZMAN, J	8004140098	50-443 M	SCHOPPMAN, M A SCHOPPMANN, M A SCHOPPMANN, M A SCHOPPMANN, M A SCHOPPMANN, M A	8004020391*	50-251 8	SCHWENCER, A	8004100268	50-250 P
SALTZMAN, J	8004140279	50-443 M		8004030285*	50-335 8	SCHWENCER, A	8004100275*	50-250 P
SALTZMAN, J	8004280355	50-338 J		B004030256*	50-250 8	SCHWENCER, A	8004100284*	50-250 P
SALZMAN, L	8004300080*	50-387 9		B004080608*	50-250 8	SCHWENCER, A	8004100458	50-251 P
SALZMAN, R	8004230103*	50-275 9		B004240317*	50-250 8	SCHWENCER, A	8004100467*	50-251 P
SAMWORTH, R 1	7811300053	50-568 A	SCHOPPMANN, M A SCHOPPMANN, M A SCHUESSLER, W J SCHULTZ, W H	B004240343*	50-335 \$	SCHWENCER. A	8004100475*	50-251 P
BANDERS, W F	8004070111*	50-443 Q		B004240375*	50-335 \$	SCHWENCER. A	8004110001	50-284 P
SANDERS, D	8004150601*	50-368 F		B004010492	50-305 P	SCHWENCER. A	8004250178	50-280 P
SANDERS, D	8004150579*	50-368 F		B004210153	50-466 G	SCHWENCER. A	8004250193*	50-280 P
SANDERS, W F	8004180512*	50-309 Q		B004220186*	FOIA	SCHWENCER. A	8004250212*	50-280 P
SANDS, B P	8004080677	50-312 P	SCHULTZ, W H SCHULTZ, W B SCHULTZ, W B SCHULTZ, G R SCHULTZ, G R	8004230050*	FOIA	SCHWENCER, A	8004220004	50-286 Q
SANDVIK, R M	8004250375	50-514 0		9004010274	50-367 Q	SCHWENCER, A	8004230125	50-275 F
SARBANEB, P	8004220659	50-320 U		8004010300*	50-367 G	SCHWENCER, A	8004110547	50-338 Q
SARSOUR, B	8004140353*	50-344 R		8004230006	50-387 Q	SCHWENCER, A	8004210014	50-344 F
SASSER, D W	8004280035	NUREO		8004100377*	50-150 Q	SCHWENCER, A	8004240445	50-334 P
SABTRE.C	8004070158	RES	SCHUMACHER, K	8004080571	50-387 G	SCHWENCER, A	8004240456	50-315 P
SATTERFIELD.R	7811100178	50-313 8	SCHUR, D H	8004080188*	FOIA	SCHWENCER, A	8004140086	50-305 F
SATTERFIELD.R	8004220227*	50-287 0	SCHWARTZ, W B	8004220635*	FOIA	SCHWENCER, A	8004140039	50-272 F
GAUDER.J L	8004110571	50-289 H	SCHWARTZ, E A	8004110553	State Prog	SCHWEITZER, D	8004280063	RE9
SAUERS.M A	8004300083*	50-387 0	SCHWARZ, M D	8004020136	50-498 G	SCHWENCER, A	8004250029	50-241 P
SAUER,D W SAUNDERS,S C SAUYER,S SCALPI,M SCALPI,M	8004150532* 8004220785 8004040298* 8004100438 8004080152	50-305 B ACRS ACRS PR PR	SCHWARZ, M D SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWEIBINZ, E R	8004020134 8004180286* 8004080325* 8004080330* 8004040418*	50-498	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004160016 8004210010 8004240076 8004280273 8004280277*	50-316 P 50-280 P 50-266 P 50-266 P
ECANLON, W J	8004020237*	8tate Prog	BCHWENCER, A	8004240504*	50-286 P	BCHWENGER, A	8004280304*	50-266 P
BCARANO, R A	8004270041*	40-8402	BCHWENCER, A	8004020457	50-315 P	BCHWENGER, A	8004290077	50-250 F
SCARANO, R A	8004270044*	40-8402	BCHWENCER, A	6004020460	50-272 P	BCHWENGER, A	800430502	50-305 F
SCARANO, R A	8004280418*	40-8481	BCHWENCER, A	8004020463	50-275 P	BCHWENGER, A	8004180045	50-334 P
SCARANO, R A	8004030184	40-8502	BCHWENCER, A	8004140087	50-266 P	BCHWENGER, A	8004210032	50-272 P
BCARAND, R A SCARAND, R A SCARAND, R A SCARAND, R A SCARAND, R A	8004070259 8004070412 8004180105 8004280417 8004270036	40-1162 40-8452 WASTE MGT 40-8481 40-8602	SCHWENCER: A SCHWEIBINZ, E R SCHWENCER: A SCHWENCER: A SCHWENCER: A	8004150318 8004110300* 8004030276 8004110089 8004150138	50-334 P 50-456 Q 50-338 F 50-295 F 50-315 P	SCHWENCER.A SCHWENCER.A SCHWENCER.A SCHWENCER.A SCHWENCER.A	B004220117 B004230010 B004250002 B004300250 B004300255*	50-247 P 50-266 Q 50-334 P 50-344 P
SCARAND, R A SCARAND, R A SCARTH, E D SCHAFFSTALL, R E SCHAPER, J F	8004300104 8004270110 8004020175* 7907250258 8004040132*	40-8602 40-3453 50-445 M MISC 50-346 Q	SCHWENCER, A BCHWENCER, A BCHWENCER, A SCHWENCER, A SCHWENCER, A	8004020257 8004020262* 8004020266* 8004020270* 8004110520	50-275 P 50-295 P 50-295 P 50-295 P 50-282 P	SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A	8004300264* 8004280062 8004300162 8004300168* 8004300183*	50-344 P 50-250 P 50-334 P 50-334 P
SCHAPER, J F	8004040079*	50-483 Q	BCHWENCER, A	8004110524*	50-282 P	SCHWENCER, A	8004250020	50-348 P
SCHABER, H	8004030012	50-312 H	SCHWENCER, A	8004140481	50-280 P	SCHWENCER, A	8004250167	50-284 P
SCHAUER, F P	8004220042	50-424 A	SCHWENCER, A	8004140490	50-305 F	SCHWENCER, A	8004290158	50-247 P
SCHENDEL, K R	8004280283	40-9304	SCHWENCER, A	8004220172	50-295 P	SCHWENCER, A	8004280113	50-286 P
SCHERA, L	8004070423	50-250 H	SCHWENCER, A	8004010004	50-295 P	SCHWENCER, A	8004240458	50-247 P
SCHERER, A E	8004010478	TOPREP	SCHWENCER, A	8004020070	50-282 P	SCHWENCER, A	8004300072	50-280 F
SCHERER, S J	8004150101	50-574 G	SCHWENCER, A	8004020073*	50-282 P	SCHWENCER, A	8004280199	50-3 P
SCHERER, A E	8004230315	TOPREP	SCHWENCER, A	8004020075*	50-282 P	SCIANDRA, J	8004210093*	50-3 H
SCHERER, A E	8004280400	TOPREP	SCHWENCER, A	8004020079*	50-282 P	SCINTO, J	8004020298	MISC
SCHILLER, W	8004010521	50-322 G	SCHWENCER, A	8004140050	50-334 P	SCINTO, J	8004150098	50-556 0
SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8004240368 8004240448 8004240350 8004240470 8004240455	50-250 R 50-250 R 50-250 R 50-250 R 50-250 R	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8004140054* 8004140058* 8004150041 8004040260 8004040423		BCOTT. A BCOTT. A BCOTT. J BC INTO, J	8004270233 8004140195# 8002270321 8004230035 8004150461	50-272 G 50-339 H 50-327 G 50-466 G 50-367 P
BCHMIDT, A D	8004240359	50-250 R	SCHWENGER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8004280217	50-295 P	SCRABIAN, J	8004070027	50-213 8
SCHMIDT, A, D	8004240443	50-250 R		8004280223	50-284 P	BCRANTON, W	8004070015*	50-320 P
SCHMIDT, A D	8004240463	50-250 R		8004090271	50-250 F	BCWENCER, A	8004146014	50-286 P
SCHMIDT, A D	8004240436	50-250 R		8004090166	50-250 P	SEAL, M M	8004140026*	50-155 H
SCHMIDT, A D	8004240418	50-250 R		8004090169*	50-250 P	SEAL, M M	8004070077*	50-327 H
SCHMIDT.A D SCHMIDT.A D SCHMIDT.A D SCHMIDT.A D SCHMIEDER.J R	8004230330 8004230484 8004230321 8004180524 8004070354	50-250 R 50-250 R 50-250 R 50-250 R 50-264 G	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A. SCHWENCER, A	8004090174* 8004040190* 8004080003 8004080013* 8004280148	50-250 P 50-295 P	BEAL, M M GEAL, M M BEAL, M M SEIDLE, W C. BEIDLE, W C	8004140097* 8004140190* 8004210031* 8004290492 8004180214	50-339 H 50-339 H 50-339 H 50-445 Q 50-498 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEIDLE, W C SEIDLE W C SEIDLE W C SEIDLE, W C SEIDLE, W C	8004140046 8004160041 8004220232 8004040081 8004040098	50-458 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V	8004010476 8004010493 8004080510 8004140438 8004150363	50-316 S 50-316 S 50-316 S 50-316 S 50-319 S	SHURTS, S J SHURTS, S J SHURTS, S J SHURTS, S J SIEGEL, S	8004150571 * 8004150580 * 8004150589 * 8004150578 * 8004030313	50-263 8 50-263 8 50-263 8 50-263 9 ACRS
SEIDLE.W C SEIDLE.W C SEIDLE.W C SEIDLE.W C SEIDTS.M G	8004070057 8004300028 8004250079 8004300514 8004100006	50-498 0 50-498 0 50-445 0 50-498 0 50-352 F	SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V	8004150368 8004230430 8004230351 8004230438 8004290417	50-315 R 50-316 S 50-316 S 50-315 S 50-315 S	SILBERO, J E SILBERO, J E SILBERO, J E SILBERO, J E	8004106090 8004220008 8004220008 8004220102 8004220102	PR 50-320 0 50-320 0 50-320 0
SEIGEL.B L SEIKEN.S J SEKULA.P SEKULER,S N SELCHO,H S	8004210328 8004180352 8004100478* 8004210447 8004100328	50-269 P 50-482 A 50-289 G 70-1308 RES	Shanaman, B Shanaman, S Shanaman, S Shanaman, B Shanbaky, M	8004070478* 8004070479* 8004070480* 8004070481* 8004080352*	50-320 I 50-320 I 50-320 I 50-320 I 50-317 Q	SILBERG, J E SILBERG, J E SILKER, W B SILVER, M SILVER, R D	8004210085 8004210085 8004110065 8004070141 8004030182	50-320 0 50-320 0 NUREO 50-289 P 50-155 P
SELLS.D E SELLS.D E SELLS.D E SELLS.D E	8004020286 8004020127 8004030265 8004070268 8004070276	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	SHANK,R B SHANK,H J SHAPAR,H X SHAPAR,H X SHAPAR,H X	7908010479* 7908010475 8004100039* 8004080209 8004140245	50-320 H 50-320 H 10CFR 50-327 G FRM	SILVER.R D SIMCHUCK.Q SIMMONS.D B SIMMONS.D B SIMMONS	8004100166 8004090135 8004280425* 8004280427* 8004010379*	50-255 P NABTE MOT 40-8602 40-8602 50-327 Q
SELLS.D E SELLS.D E SELTZER.A M SELTZER.A M	8004030153 8004040230 8004220079 8004090478* 8004090479*	50-320 H 50-320 H 50-387 D 50-320 1 50-320 I	SHAPAR,H K SHAPAR,H SHAPAR,H K SHARP,D R SHAUD,E T	8004080047 8004250003 8004180283 8004020432* 8004080599*	50-307 P 50-554 G 50-416 M TOPREP 70-364	SIMMONS SIMON, P SIMPSON, A K SINGER, B SINGER, B	8004170155# 8004140180* 8004080314* 8004220598* 8004220591*	50-327 Q 50-10 U 40-1341 FOIA FOIA
SELTZER, A M SELTZER, A M SENECHAL, M E SENECHAL, M E SERABJAN, J A	8004090480# 8004090481* 8004230088 8004230100 8004210070>	50-320 1 50-320 I 50-282 0 50-282 G 50-286 Q	SHAUB,E T SHAUB,E SHCWENCER,A SHEA,J R SHEA,J R	80040702!1* 80040701!9* 8004240492* 8004210078* 8004010051	50-184 Q 70-398 50-286 P 70-2478 8ECY	SINGER, L N SINGER, L N SINGER, L N SINGER, L N SINGER, L N	9004020104 8004020107* 8004010287 8004100452 8004080045	50-209 0 50-289 0 50-289 0 50-209 0
SETHNESS, E D SETIER B R SEWELL, R B SEYFRIT, K V SEYFRIT, K V	B004020057 B004220326* B004100462* B004270171* B00407007B*	WASTE MGT 70-2623 50-155 G 9999 99999	SHEA.K H SHEA.J R SHEA.J J SHEA.K H SHEA.J R	8004020280 8004240181 8004040076 8004020092 8004020092	50-367	BINGER, L N SINGER, L N BINGER, L N BINKIN, L SIPE, L W	8004080025* 8004100587 8004170058 8004280067 8004080106	50-289 Q 50-289 Q 50-289 Q 50-498 Q 50-320 H
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004100093 8004290179* 800415023! 8004150233 8004150234	90-298 Q QA979 50-313 Q 50-298 Q 50-285 Q	SHEA, J R SHEA, J R SHEA, J R SHEA, J R SHEA, J J	8004070029 8004070034* 8004070148 8004110538 8004170322	XPORTLIC XPORTLIC SECY XPORTLIC 50-244 F	SKINNER,WF SKISLAK,S SKOLDS.JL SKOLDS.JL SKOVHOLT.DJ	8004210935 8004300037* 8004100414* 8004280014* 8004220035	50-320 P 50-387 0 50-395 0 50-395 0 MISC
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004150237 8004080666 8004080669 8004080670 8004080673	50-267 Q 50-313 Q 50-298 Q 50-285 Q 50-267 Q	SHEA, K H SHEA, K H SHEA, J R SHEDLOSKY, J T SHELDON, K P	8004230105 8004240194 8004250028 8004180147* 8004080364	50-367 G PRM XPORTLIC 50-245 G 50-443 G	SLICKER, FK SLICKER, FK SLICKER, FK SLICKER, FK SLICKER, FK	8004090164 8004090175 8004090180 8004100221 8004090164	50-448 H 50-449 H 50-449 H 50-445 H 50-445 H
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8004110097 8004110101 8004110102 8004110104 8004180493	50-313 Q 50-278 Q 50-285 Q 50-267 Q 50-313 Q	SHELDON, K P SHELDON, K P SHELLEY, N J SHELLEY, N J	8004160138* 8004280026 8004280026 8004080158 8004110563	50-287 0 50-289 0 50-289 0 40-2061 70-925	SLICKER, FK SLICKER, FK SLICKER, FK SLIDER, JE SLOAN, DE	8004090175 8004090180 8004100221 8004180197* 8004280248	50-445 H 50-445 H 50-445 H COMMISSION PT21
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004180494 8004180496 8004180499 8004220206 8004240214	50-278	SHELLY, F L SHERIDAN, C F SHERWOOD, G G SHERWOOD, A L SHERWOOD, A L	8004180247 8004210316 8004100061 8004230302* 8004230317*	50-387 Q 50-443 F PT21 PROJ PROJ	SLOBODIEN, M J SLOSS, C S SLYVIA, B R SMEDIRA, C SMEDIRA, C	8004210052* 8004080133* 8004100410 8004070117 8004070121*	FOIA FOIA 50-339 0 71-121 71-121
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004240218 8004240220 8004240225 8004180159 8004180159	50-482 Q 50-382 Q 50-445 Q 50-265 Q 50-313 Q	SHEWMAKERRE SHIELDS.S W SHIELDS.S W SHIELDS.S W	8004080671 8004080168* 8004100291* 8004110556* 8004210131	50-546 A 50-544 A 50-546 Q 50-546 Q 50-546 Q	SMITH, C W SMITH, O H SMITH SMITH, C V SMITH, O H	8004010195* 8004220374* 8004240084* 8004240150* 8004210139*	70-1308 FOIA 70-135 70-135 70-1100
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004180162 8004180165 8004220257 8004220260 8004220261	50-267 Q 50-298 Q 50-482 Q 50-498 Q 50-382 Q	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8004090144# 8004100371 8004290426 8004300348 8004150478	50-546 G 50-546 G 50-546 A 50-546 A RES	SMITH, O H SMITH, O H SMITH, O H SMITH, O H SMITH, O H	8004020131* 8004210064* 8004070392* 8004100373* 8004100009*	ACR9 50-206 Q 70-364 50-334 Q 50-184 Q
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004220268 8004220320 8004270146 8004110006 8004220770	50-458 Q 50-445 Q QA999 50-298 Q 50-458 Q	SHILLMAN, GR SHILDBOD, DS SHINEFLUG, M SHINKO, MS SHIVELY, CN	8004160184* 8004090486 8004140456 8004080684 8004020353*	50-320 P FOIA 50-10 U RES 50-313 8	SMITH, J D SMITH, Q H SMITH, Q SMITH, Q C SMITH, Q C	8004230019 8004210214* 8004070207* 8004090419* 8004070217*	FOIA 70-135 70-1100 70-135 70-135
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004220777 8004220779 8004220783 8004230324 8004230327	50-498 Q 50-445 Q 50-382 Q 50-313 Q 50-298 Q	SHOULY, S C SHOULY, S C SHOULY, S C	8004080594* 8004150618* 8004220703* 8004010036 8004010040*	50-368 6 50-368 6 50-368 6 50-289 0 50-289 0	SMITH, OH SMITH, R SMITH, OH SMITH, OH SMITH, G, H	8004210135* 8004070159* 8004070354 8004070105 8004100223*	70-1100 50-313 0 50-293 0 70-1100 50-201 0
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8004230350 8004230354 8004220208 8004220228 8004220223	50-267 G 50-285 G 50-445 G 50-382 G 50-498 G	SHOLLY, 8 C SHOLLY, 8 C SHOLLY, 8 C SHOLLY, 8 C	8004010042* 8004010044* 8004110541 8004110546* 8004020044	50-287	SMITH, O H SMITH, E H SMITH, E H SMITH, E J SMITH, O H	8004300232* 8004100083 8004100443 8004100448 8004210133*	50-244 0 PR PR 50-244 F 70-1100
SEYFRIT,K V SHA,W T SHA,W T SHALEK,R J	8004220237 8004220241 8004150326 8004290017 8004220130*	50-458 Q 50-482 Q Nureg Nureg Fola	SHOLLY,S C SHOLLY,S C SHOTKIN,L M SHULL,G B SHUM,E Y	8004070189 8004110184 7907300056 8004080082 8004180098	50-289 Q 50-320 Q MISC RES 70-2909	SMITH, T. H BMITH, O H BMITH, R SMITH, G H BMITH, I W	8004080450* 8004080271* 8004040140* 8004100142 8004220350	50-213 0 50-333 0 50-267 0 50-220 0 50-289 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	HUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SMITH. GH SMITH, GH SMITH, GH SMITH, GH SMITH. GH	8004070383 8004100347 8004210084 8004210169 8004160165	70-364 50-364 0-1143 50-293 Q 50-277 Q	SOLBRIO, C W SOLENBERGER, R SOUCY, A R SOUDER, J L SOUDER, J L	8004080062 8004280492 8004010395 8004070364 8004080064	70-287 A 50-387 A 50-29 L 50-367 H 50-289 G	STALLINGS, C II STALLINGS, C II STALLINGS, C II STAMPLEY, N L STAMPLEY, N L	6004030210 6004030236 6004070282 8004100439 8004070254	50-338 Q 50-338 R 50-338 Q PR REGOD
SMITH, R SMITH, R SMITH, J D SMITH, J H	80042101799 8004210438# 8004040465 8004110245# 8004100003	50-445 Q 50-445 Q 71-6375 50-266 Q 50-184 Q	SOUDER, J L SOWDON, T L SPANGLER, R G SPANGLER, R G SPANGLER, M B	8004110577 80040805244 8004090159# 8004210217# 8004170337	50~482 A 50~293 R 50~313 Q 50~298 Q NUREQ	STAMPLEY, N L STAMPLEY, N L STAMPLEY, N L STAMPLEY, N L STARKEY, R B	8304100541 8304070341 83041502004 8304220287 83041404684	RFGGD 50-416 A 50-416 M 50-116 C 50-261 G
SMITH, OH SMITH, OH SMITH, OH SMITH, OH	8004210027 8004210029 8004210074 8004210079 8004210115	70-1100 40-672 50-272	SPARGD, L L SPELLMAN, K SPENCER, G S SPENCER, G S SPENCER, G S	8004220303 8004110105* 8004230273* 8004020168* 8004300117	70-2623 MISC 50-460 Q 50-528 Q 50-528 Q	STARKEY,R B STARKEY,R B STARKEY,R D STARKEY,R B STARKEY,R B	8004250261* 8004030171 8004040305 8004100340 8004100345*	50-261 G 50-261 S 50-261 R 50-261 S 50-261 S
SMITH.G H SMITH.G H SMITH.G H SMITH.H SMITH.H	8004210334 8004210343 8004220379 8004280280 8004080284	50-333	SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S	8004040146* 8004020054* 8004240508* 8004230253* 8004300273	50-312 0 50-361 0 50-528 0 50-460 0 50-397 0	STARKEY.R B STARKEY.R B STARKEY.R B STARKEY.R B STARKEY.R B	8004150374 8004180418 8004180425* 8004230520 8004230525*	50-261 8 50-261 8 50-261 8 50-261 5 50-261 5
SMITH, A E SMITH, R L SMITH, G F SMITH, J SMITH, I W	8004070075 8004080261 8004300322* 8004040235 8004080022	50-320 R 50-271 Q 50-225 Q 50-320 T 50-209 G	SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S	6004280016 8004280168 8004210181 8004210412 8004020045	50-275 Q 50-312 Q 50-361 Q 50-361 O 50-361 O	STARKEY, R B STARKEY, R B STAUDT, H R STEARNS, C B STEDER, P	8004240362 8004240366* 7908140247* 7911140251 8004070421*	50-261 S 50-261 S COMMISSION Dacket 30 50-10 H
Smith.a C Smith.r D Smith.g Smith.m Smith.i W	8004100499 8004020132 8004090027 8004040228 8004100476	50-320 P 27-39 50-213 8 50-556 H 50-289 0	SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S SPENCER.G S	8004020152 8004040126 8004280683 8004280092 8004210422	50-528	STEELE, P W STEINDLER, M J STELLO, V STELLO, V STELLO, V	8004210176* 8004150122 8004020118* 8004140022 8004010017*	70~1113 ACRS 50~3 G 50~155 H 10CFR
SMITH, I W SMITH, G H SMITH, I W SMITH, I W	8004080676 8004100214 8004210126 8004080026 8004080258	50~269 0 50~201 0 70~1100 50~289 0 50~333 0	SPENCER.W C SPENCER.W C SPENCER.O S SPENCER.O S SPENCER.W C	8004010384 8004030126 8004230239 8004240493 8004140219	50-280 P 50-280 P 50-460 9 50-528 9 50-281 P	STELLO, V STELLO, V STELLO, V STELLO, V	8004070425 8004170109 8004170129* 8004240485 8004240490*	50-213
SMITH.D SMITH.A E SMITH.R L SMITH.I W SMITH.A E	8004300063# 8004010444 8004010237 8004080630 8004010490	50-387	SPERROFF, R SPERROFF, R SPESSARD, R L SPESSARD, R L SPESSARD, R L	8004080561* 8004220700* 8004100432* 8004080625* 8004180203*	50-249 S 50-249 S 50-10 Q 50-254 Q 50-373 Q	STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	8004240495* 8004240510 8004240512 8004240514* 8004240517*	50-272 G 50-247 G 50-267 G 50-267 G 50-247 G
SMITH.Q H SMITH.Q H SMITH.A E SMITH.I W SMITH.A M	8004210056 8004300223 8004070222 8004070403 8004280028	50-286 Q 50-244 Q 50-320 R 50-287 Q NUREQ	SPESSARD, R L SPESSARD, R L SPETH, Q SPIEGEL, Q SPIEGEL, Q	8004080573 8004030110 8004030335 8004070185 8004100433	50-265 S 50-249 S COMMISSION 50-445 M 50-445 M	STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	8004240532 8004240537# 8004250336 8004250339# 8004280019	50-219 0 50-219 0 50-29 0 50-29 0 50-206 0
SMITH, I W BMITH, O H SMITH, R L SMITH, I W SMITH, I W	8004100222 8004210015 8004080376 8004080579 8004080586	50-287 0 50-320 0 50-271 H 50-287 0 50-287 0	EPIEGEL, O SPIEGEL, O SPIEGEL, O SPIEGEL, O	8004100433 8004090185 8004030340 8004100428 8004100428	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	8004280021 * 8004290002 8004290006* 8004290460 8004290466*	50-204 G 50-204 G 50-204 G 50-321 G 50-321 G
SMITH, I W SMITH, I W SMITH, I W SMITH, I W SMITH, E R	8004100018 8004100021 8004100024 8004100304 8004170052#	50~287	SPIEGEL, G SPIEGEL, G SPIEGEL, G SPITALNY, B S SPRAUL, J	8004150032 8004150050* 8004150050* 8004160179* 7704130116	50-445 M 50-445 M 50-445 M 50-269 G NISC	STELLO, V STELLO, V STEPHENSON, B B STEPHENSON, B B STEPHENSON B B	8004290477# 8004280134 8004140330 8004140423	50-321 G GA999 50-10 R 50-237 B
SMITH, R L. SMITH, I W SMITH, I W SMITH, I W SMITH, I W	8004080490 8004210114 8004150176 8004240176 8004210094	50-271 P 50-287 G 50-287 G 50-287 G 50-287 G	SQUITIERI,R J STAENBURG,M R STAENBERO,M R STAHL,D M STAHL,D M	8004 8004 8004 8004 8004				
SMITH, O H SMITH, I W SMITH, A E SMITH, R L SMITH, R L	8004300317 8004230115 8004220415 8004220301 8004280506	50-225 0 50-287 0 50-320 R 50-271 R 50-271 P	STAHL, D M STAHL, D M STAHL, D STAHL, D STAHLE, C R	8004 8004 8004 8004 8004				
SMOKOWSKI,R T SNAPP,C SNIEZEK,J SNIEZEK,J SNIEZEK,J	8004180094 8004030015 8004210433 8004210440 8004210441	50-201 P 50-275 G 50-304 S 50-247 S 50-335 S	STAHL, D M STAHL, D M STALLINGS, C M STALLINGS, C M STALLINGS, C M	8004 8004 8004 8004 8004				
ENTEZEK, J ENTEZEK, J ENOW, B A ENOWE, O J	8004210224 8004180517 8004180518 8004150380 8004140304*	50-344 8 50-346 8 50-257 8 50-244 R 50-307 U	STALLINOS, C M STALLINOS, C M STALLINOS, C M STALLINOS, C M STALLINOS, C M	8004 8004 8004 8004 8004				
SNYDER, I E SNYDER, M O SODEN, R SOHINKI, S M SOHINKI, S M	8004040257* 8004090357 8004020357* 8004080319 8004080336	50-320 H 50-320 H 50-254 S 50-466 G 50-466 Q	STALLINGS.C H STALLINGS.C H STALLINGS.C H STALLINGS.C H STALLINGS.C H	8004 8004 8004 8004 8004				
SOURLO'C M SOURKI'S W SOURKI'S W SOURKI'S W	8004070021 8004080016 8004150181 8004170307 8004100378	90-437 G 50-466 G 50-466 G 50-466 G RES	STALLINGS.C M STALLINGS.C M STALLINGS.C M STALLINGS.C M STALLINGS.C M	8004 8004 8004 8004 8004				

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STEVENSON, R L STEVENSON, R L STEVENSON, R L STEVENSON, R L STEWART, W L	8004140075 8004170311 8004100593 8004150305* 7909280009	70-1113 70-371 70-1113 70-820 50-281 9	SWARTZ.L L SWARTZ.L L SWARTZ.L L SWEET.K J SWETLAND.P D	8004080055 8004280355 8004280358 8004180349* 8004210053*	50-289 G 50-289 G 50-289 G 50-289 G 50-220 F 50-309 Q	TERRY, J H THADANI, A C THIES, A C THIES, A C THOM, T	8004220559 7903080144 8004020334 8004240294 8004240415*	50-410 S MISC 50-269 I 50-269 Q 90-259 R
STEWART, W P	8004300164*	50-302 G	SYLVIA, BR	8004030234	50-280 P	THOMAS, C W	8004110065	NUREG
STEWART, W L	8004030270*	50-280 S	SYLVIA, BR	8004030183	50-339 A	THOMAS, K C	8004290371*	50-537 A
STOBER, Q J	8004020139	NUREO	SYLVIA, BR	8004070261	50-339 A	THOMAS, L H	8004100173*	50-220 G
STOHR, J P	7908010063	MISC	SYLVIA, BR	8004080312	50-339 A	THOMAS, M	8004230046*	50-370 G
STOHR, J P	8004210070*	50-286 G	SYLVIA, BR	8004080392	50-338 G	THOMAS, R D	8004040055*	50-312 G
TO SHOTE P. STONER, J. P. STONER, J. P. STONER, J. P. STORE, J. P.	8004040351* 8004080027* 8004080034* 8004040130 8004290128*	50-250 Q 50-250 Q 50-348 Q 70-27 50-324 Q	SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	8004080528 8004080621 8004170050 8004040302 8004110478	50-338 S 50-338 P 50-338 R 50-339 A 50-280 Q	THOMAS, M THOMAS, R D THOMAS, R D THOMAS, C D THOMAS, C D	8004210121* 8004100017 8004080984 8004100237 8004210405	50-566 G I&E I&E TOPREP 50-466 A
STOHR.J P	8004040383*	50-269 0	SYLVIA, B R	6004110202	50-338 Q	THOMAS, C O	8004300074	50-466 A
STOHR.J P	8004040182	50-338 0	SYLVIA, B R	8004140167	50-339 B	THOMAS, C O	8004240557	50-466 A
STOHR.J P	8004090294	70-1201	SYLVIA, B R	8004140446	50-338 Q	THOMAS, E B	8004220464	50-220 P
STOHR.J P	8004090130	50-339 0	SYLVIA, B R	8004150342	50-339 B	THOMPSON, D	8004220472*	FOIA
STOHR.J P	8004080135	27-47	SYLVIA, B R	8004170210	50-338 R	THOMPSON, D	8004140202	1%E
STOHR.JP	8004140473*	50-261 Q	SYLVIA,R B	8004170241	50-280 R	THOMPSON, D	8004220252*	FOIA
STOHR.JP	8004080145	27-47	SYLVIA,R B	8004180232	50-338 J	THOMPSON, D	8004100510	PT9
STOHR.JP	8004090173	50-338 Q	SYLVIA,D R	8004180446	50-339 B	THOMPSON, D	8004220361*	FOIA
STOHR.JP	80041100184	70-1151	SYLVIA,B R	8004280472	50-339 B	THOMPSON, D	8004220439*	FOIA
STOHR.JP	8004250275*	50-261 Q	SYLVIA,B R	8004180289	50-280 Q	THOMPSON, D	8004220226	50-272 8
9 TOHR, J P 1 TOHR, J P 1 TOHR, J P 1 TOHR, J P	8004280247 8004080021 8004040328 8004080010 8004140462	70-1319 50-348 0 50-250 0 50-250 0 50-261 0	SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B L	8004210177 8004220311 8004220318 8004220493 8004230337	50-339 A 50-280 F 50-280 P 50-338 G 50-337 P	THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, G THOMPSON, G A	8004220249 8004210429 8004280146* 8004140466 8004150230	50-243 S 50-331 S GA999 ACRB ACRB
STOHR.JP	8004250251	50-261	SYLVIA: BR	9004230231	50-339 P	THOMPSON, F	8004300070*	50-387 0
STOHR.JP	8004290116		SYLVIA: BR	9004230519	50-338 P	THOMPSON, S	8004180197*	CDMMIBBION
STOKELY.MF	7908300622		SYLVIA: BR	9004250371	50-280 S	THOMPSON, C	8004150047	50-367 A
STOLZ.JF	8004020245		SYLVIA: BR	9004290334	50-280 Q	THOMPSON, C	8004240502	50-367 A
STOLZ.JF	8004150225		SYLVIA: BR	8004300472	50-280 P	THONUS, L H	8004100391*	50-334 0
STOLI, J F	5004070237	50-522 A	SYNAR,M	8004270175	50-554 H	THONUBLE H THONUBLE H THORNBURGLE D THORNBURGLE D THORPELJ R.	8004080282*	50-333 Q
STOLI, J F	8004090260	50-556 H	SZWAJKOWSKI,R	8004280305	70-1308		8004210173*	50-293 Q
STOLI, J F	8004230193	50-341 A	SZWAJKOWSKI,R	8004280305	70-1308		8004030321*	FOIA
STOLI, J F	8004240520	50-275 A	T'NIEMI,W D	8004020412*	50-304 B		8004220253*	FOIA
STOLI, J F	8004250048	50-364 A	TABBERT,J L	8004110470*	50-346 B		8004150621	50-289 Q
STOLZ, J F	8004270165	50-341 A	TACY.W	9004300556	PT21	THURMAN, D S THURMAN, D S THURMAN, D S TIBDETTS, D L TIBBITTS, D L	8004240110*	70-135
STONEBURNER, U	8004210075	70-2478	TAKAHASHI.H	9004280032	RES		8004240104*	70-135
STONE, R	8004220019	50-289 H	TAM.P	9004030260	50-320 (1		8004240095*	70-135
STONE, R J	8004110523	PR	TAM.P	9004040283	ACRB		8004090284	50-395 A
STOTZ, J	8004110386*	50-346 B	TAMBLING.T N	9004100022*	50-346 (1		8004140069	50-352 A
STOTZ, J C	8004210267*	50-346 8	TAPIA, J I	8004160050*	50-445 @	TIBBITS, D	8004070054	50-395 A
STOUDT, T	8004070030	50-352 H	TAUBER, H	8004040278	50-341 A	TIBETTS, L	8004070116	50-354 H
STRASMA, J	8004220214*	FOIA	TAYLOR, G H	8004080192*	FOIA	TIDRICK, G A	8004010437	50-275 A
STRASMA, J	8004220435*	FOIA	TAYLOR, G C	8004220629*	FOIA	TIERNAN, M W	8004020059#	71-4387
STRASSER, J A	8004170117*	COMMIESION	TAYLOR, G C	8004220609*	FOIA	TILLMAN, A	8004290177*	50-259 0
STRASMA.R J STRATMAN.R A STRATMAN.R A STRAUSS.P L STREETER J F	8004280654 8004010417* 8004220679* 8004220263* 8004300022*	50-295 8 50-336 8 50-336 8 F01A 50-358 0	TAYLOR,G C TAYLOR,G C TAYLOR,M A TAYLOR,J H TAYLOR,B J	8004220212* 8004220402* 8004100521* 8004080661* 8004040188	F01A F01A 50-320	TIMKO, D R TIPTON, T E TOALSTON, A TOALSTON, A TOBIN, W J	8004290355* 8004160274 8004110121 8004150197 8004040047*	50-334 R 50-219 P 50-482 M 50-416 H 70-143
STRINGFIELD, H STRONG, T R STROSNIDER, J STRUMWABSER, M	8004070021 8004240139 8004290507 8004150042 8004230317*	71-185 State Prog WASTE MOT NUREG PROJ	TAYLOR,M A TAYLOR,J H TAYLOR,J H TAYLOR,J H TAYLOR,J R	8004240518* 8004010404* 8004020459 8004020469* 8004030354	50-284 P 50-327 8 50-327 8 TOPREP 71-9142	C W.NIBOT C W.NIBOT L W.NIBOT L W.NIBOT U.NIBOT	B004030342* B004070361* B004110549* B004110566* B004220204*	70-2478 70-143 70-2479 50-302 0 50-269 0
STUKENBROEKER, G	8004080069	XPORTLIC	TAYLOR.J H	8004240511*	50-313 P	TODD, O A TOLBERT, P E TOLER, L G TOLLIBON, A C TOLLIBON, A C	8004040021*	70-1201
BTUKENBROEKER, G	8004140010	XPORTLIC	TAYLOR.J H	8004150209	50-438 8		8004140112	PR
SULLIVAN, W H	8004020142	RES	TAYLOR.J H	8004300570	50-438 8		8004010104	27-39
SUMMERS, R	8004090285*	70-135	TAYLOR.J H	8004090461	TOPREP		8004270122*	50-324 G
EUMMERS, R J	8004090211*	50-184 Q	TAYLOR.J H	8004100199	TOPREP		8004020297	50-324 B
SUMMERS, R	8004070119*	70-398	TAYLOR, J H TAYLOR, J H TAYLOR, J H TEDESCO, R L TEDFORD, C F	8004210244	TOPREP	TOLLISON, A C	8004030174	50-324 8
SUN, S	8004220083	40-1162		8004210368	TOPREP	TOLLISON, A C	8004010385	50-325 8
SUNDARAM, R K	8004040027	RES		8004290517	50-313 P	TOLLISON, A C	8004010370*	50-325 8
SUTHERLAND, J T	8004040144*	70-27		8004290127	50-320 P	TOLLISON, A C	8004010374	50-324 8
SUTHERLAND, R	8004220362*	70-2623		8004180078*	COMMISSION	TOLLISON, A C	8004010400*	50-324 8
SUTTON. J W	8004110057*	0A979	TEETS, T A TELFORD, F T TELFORD, C F TELFORD, J T TELFORD, J T	8004040274	50-320 H	TOLLIBON, A C	8004010461	50-324 R
SYESLOSKY. F	8004150195*	50-361 H		8004110567	50-295 P	TOLLIBON, A C.	8004080458	50-324 S
BWAN. W B	8004090400*	50-518 G		8004280459*	CDMMIBBION	TOLLIBON, A C.	8004080464*	50-324 S
SWANBY. O T	8004220099	40-3453		8004240483*	50-286 P	TOLLIBON, A C.	8004080566	50-325 S
SWANSON, D T	8004010311	50-338 G		8004240489*	50-286 P	TOLLIBON, A C.	8004080575*	50-325 S
SWANSON, D T	8004080051*	50-287 G	TELFORD, J T	8004030309	50-286 P	TOLLISON, A C	8004080357	50-324 8
EWANSON, D T	8004100587	50-287 G	TELFORD, J T	8004080377	50-295 P		8004090332	50-324 8
SWANSON, D T	8004170245	50-522 O	TELFORD, J T	8004240486*	50-286 P		8004080453	50-325 8
SWANSON, D T	8004220271	50-287 G	TELFORD, J T	8004020259	50-247 P		8004080454*	50-325 8
SWANSON, D T	8004280247	50-287 G	TERG, N X	8004070112*	70-1100		8004070333	50-324 8
SWART, F E BWART, F E SWARTZ, L L SWARTZ, L L SWARTZ, L L	8004240469 8004210354 8004020018 8004010315 8004010514	50-267	TERC, N M TERPETRA, G L TERRELL, D TERRELL, G D TERRY, S H	8004300328* 8004010440* 8004100441 8004030008 8004010227	50-225	TOLLISON, A C. TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C	8004070337* 8004140445 8004150466 8004150504 8004150644	50-324 8 50-324 R 50-324 B 50-324 B 50-324 B

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TOLLISON A C	8004150448* 8004210293 8004220572 8004220583* 8004220599	50-324 S 50-324 Q 50-324 S 50-324 S 50-325 S	TRIPP.L E TRIPP.L E TROFE.T W TROSKOSKI.W M TROUP.G L	B004090401* B004180512* B004140455 B004210151* B004110027*	50-293 G 50-309 G NUREO 50-322 G 70-1151	UDY, A, C, UDY, A C UHRIG, R E UHRIG, R E UHRIG, R E	8004170289 8004170334 8004040003 8004040347* 8004080023*	RES RES 50-250 G 50-250 G
TOLLISON A C	8004220576 8004220732 8004220538 8004220547* 8004280576	50-325	TROMBRIDGE, G F	8004070076 8004070076 8004010517 8004080425 8004080720	50-289 G 50-289 G 50-400 G 50-289 G 50-289 G	UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE	8004040173# 8004080015# 8004020381 8004080257 8004240378#	50-389 G 50-250 G 50-335 B 50-335 R 50-250 G
TOLLISON, A C	8004280586* 8004280587 8004280599* 8004280583 8004280592*	50-325	TROWBRIDGE, G F	8004110029 8004010519 8004080425 8004080720 8004110029	50-287 0 50-400 0 50-287 0 50-287 0 50-287 0	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8004220237 8004220248 8004220313 8004210170 8004230537	50-389 A 50-389 K 50-389 C 50-389 S 50-335 G
TOLLISON, A C	8004290397 8004290401* 8004290487 8004290494* 8004100378	50~325 S 50-325 S 50-325 S 50-325 S RES	TROWBRIDGE, G F	8004100308 8004100308 8004100479 8004100479 8004110516	50-287 G 50-287 G 50-287 G 50-289 G 50-287 Q	UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE	8004240030 8004010210 8004030289 8004040425 8004110533*	50-250 G 50-250 P 50-250 P 50-335 R 50-250 9
TOMKINS.D TOMLINSON.D P TONDI.D TONGUE,T M	8004070050 8004180218* 7908200112 7908280824 8004100432*	FOIA 50-498	TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F	8004110516 8004230030 8004230030 8004140007* 8004140013*	50-289 Q 50-289 Q 50-289 Q 50-289 Q 50-289 Q	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8004240219 8004030229 8004040380 8004070279 8004090217	50-389 Q 50-389 F 50-250 R 50-335 F 50-335 R
TOOKER, D W TOOKER, D W TOOKER, D W TOOKER, D W TOOLE, R J	8004040413# 8004080531# 8004140369# 8004140452# 8004010338	50-331 S 50-331 S 50-331 S 50-331 S 50-289 S	TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F	8004140017* 8004140019* 8004140023* 8004140028* 8004140032*	50-289 Q 50-289 Q 50-289 Q 50-289 Q	UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE	8004220243* 8004080384 8004150341 8004080452 8004150404	50-387 A 50-335 P 50-335 P 50-250 P 50-250 I
TOTH, A D TOURIGNY, E O TOURTELLOTTE, J TOURTELLOTTE, J TOWNEND, F	8004230270* 8004280263 8004020104 8004020107* 8004140100*	50-440 G NUREG 50-289 G 50-289 G PR	TROWBRIDGE. G F	8004140038* B004140045* B004140051* B004140057* B004140062*	50-289 Q 50-289 Q 50-289 Q 50-289 Q	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8004300583 8004140229 8004300577 8004150519 8004230461	50-250 G 50-335 F 50-335 G 50-250 F 50-335 P
TOWNEND, F TOWNEND, F TRAGESER, C IN TRAMMELL, C TRAUGER, T C	B004070300 B004140094 B004270109 B004100307 B004100556	PR PR CONTRACT 50-344 P PROJ	TROWBRIDGE, G F	8004140065* 8004170273 8004170261* 8004140007* 8004140013*	50-287 G 50-287 G 50-287 G 50-287 G 50-287 G	UHRIG,R E ULLRICH,W T ULLRICH,W T ULLRICH,W T UPRIGHT,C M	8004280269 8004220432 8004290439 8004270443 8004040289*	50-250 P 50-278 8 50-277 8 50-277 8 50-280 0
TRAVIS.W H TRAVIS.C C TREGY.S A TREBY.S A TREVING.T	8004070247 8004160086 8004210414 8004150226 8004030037*	71-9853 RES 50-498 G 50-320 G CONTRACT	TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F TROWBRIDGE.G F	8004140017* 8004140017* 8004140023* 8004140028* 8004140032*	50-289 0 50-289 0 50-289 0 50-289 0	UPRIGHT, C M	8004020243* 8004070047* 8004040452* 8004100202* 8004100182*	50-259 Q 50-321 Q 50-302 Q 50-250 Q 50-335 Q
TREVINO, T TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C	8004040184* 8004110508 8004250044 8004040276 8004070148*	CONTRACT 50-313 P 50-313 Q 71-9080 50-313 Q	TROWDRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F	8004140038* 8004140045* 8004140051* 8004140057* 8004140062*	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0	UPRIGHT, C M UPRIGHT, C M UPRIGHT, C M UBTICK, N UBTICK, N R	8004240413# 8004210113# 8004280143* 8004080640* 8004040132*	50-280
TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8004250103 8004070116* 8004010301 8004250303 8004010216	50-349 Q 50-368 Q 50-313 P 71-9044 50-313 R	TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROY, M	8004140065* 8004170281* 8004210421 8004210421	50~287	UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E	8004010324 8004040273 8004080648 8004070313 8004080383	50-261 P 50-261 P 50-261 P 50-261 F 50-324 P
TRIMBLE, D C	8004010386 8004020342 8004020347 8004030207 8004070287	50-313 F 50-348 8 50-313 8 50-313 P 50-313 P	TRULL.D TRUSSELL.H H TRZYNA.G TSCHAECHE.A N TBUJI.N	8004080213* 8004080178 8004020374* 8004180525* 8004240202*	70-2254 40-8064 50-295 8 70-1007 70-2805	UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E	8004080472 8004140413 8004160282 8004170015 8004250410	50-324 F 50-261 P 50-324 P 50-324 P 50-324 P
TRIMBLE, D C	8004150304 8004170086 8004080577 8004070344 8004140328	50-313 P 50-313 P 50-368 S 50-313 P 50-313 S	TUNSTALL, J E TUNSTALL, J E TUNSTALL, J E TURK, S E TURK, S E.	8004080241* 8004100574* 8004210119* 8004210424 8004150464	CONTRACT CONTRACT CONTRACT 50-445 0 50-341 0	UTLEY,E E UTLEY,E E UTLEY,E E VACCA,P C	8004280497 8004300323 8004300443 8004300445 8004220479*	50-324 P 50-324 P 50-261 P 50-324 H FOIA
TRIMBLE, D C	8004150630 8004140356 8004150541 8004150567 8004150235	50-313 \$ 50-313 \$ 50-313 \$ 50-348 F 50-313 1	TURK, 5 E TURK, 8 E TURK, 9 E TURK, 9 E TURNER, L J	8004150484 8004300366 8004300371* 8004300378*	50-341	VACCA, P. C. VACCA, P. C. VACCA, P. C. VADENBURGH, D. VAHRENWALD, J.	8004220476* 8004220473* 7911200274 8004210110 8004020427*	FOIA FOIA Docket 30 PR 50-254 8
TRIMBLE, D C	8004150505 8004160185 8004210148 8004210217 8004210274	50-368 \$ 50-313 P 50-313 P 50-313 R 50-368 R	TURNER, E A TURNER, E A TURNER, E A TURNER, E, A TURNER, E A	8004070062 8004070060* 8004300523* 8004010126 8004140107	50-498 G 50-498 G 50-498 G 50-498 G 50-498 G	VAHRENWALD, J VALENTE, J V VALLERIO, J VALORE, C J VALORE, C J	8004020443* 8004140439 8004080202* 8004100466 8004100466	50-245 B 50-322 A FOIA 50-311 Q 50-311 Q
TRIMBLE, D C	B004220427 B004220427 B004220471 B004230471 B004270450	50-348 8 50-313 F 50-313 P 50-313 S 50-348 R	TURNER, E A TURNER, E A TURNER, E A TURNER, E A TURNER, E A	8004010332 8004180384 8004180423 8004180421 8004290398	50-498 8 50-498 8 50-498 8 50-498 8 50-498 8	VALORE, C J VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8004210291 8004020162* 8004070255* 8004010350 8004110484	50-272 Q 50-528 Q 50-528 8 50-528 \$ PR
TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIPLETT, M P TRIPLETT, M P	8004270374 8004270244 8004270361 8004100520* 8004140088*	50-313 8 50-313 P 50-313 R ORG ORG	TURNER.E A TUTHILL,E UDALL.M K UDY,A C UDY.A C	8004220763 8004070122 8004080066* 8004080641 8004140138	50-498 K 50-322 H COMMISBION 50-270 P RES	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E,	8004300532 8004240501* 8004010244 8004150566 8004170045	PR 50-528 Q 50-528 K 50-528 F 50-529 8

AUTHOR	ACCESSION NUMBER	SUBJECT	жонтиа	ACCESSION MUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	SUBJECT CATEGORY
VAN NESS,S C VAN RODYEN,D VAN ROOYEN D VAN SICKEL,J VAN SICKEL,J	8004070008 ± 8004040459 8004080074 8004220367 ± 8004230348 ±	50-272 0 NUREG RE5 50-331 R 50-331 R	WALKER, J R WALKER, J R WALKER, J R WALKER, F M WALKER, J R	8004170229# 8004170231* 8004170234* 8004180394* 8004150615*	50-327 F 50-327 F 50-327 F 50-327 R 50-327 P	WEISS, D WEISS, E R WEISS, E R WEISS, E R WEISS, D	8004210083* 8004100100 8004080375 8004080418 8004240288*	70-138 50-3 F 50-289 0 50-338 0 70-1308
VANDENBURGH, D E VANDENBURGH, D VANDEL, T E VANDENBURGH, D VANDEL, T E	8004230118* 8004160102* 8004210142* 8004160096 8004100267*	COMMISSION PR 50~358 Q PR 50~327 Q	WALLACE, A T WALLENSTROM, R WALLETT, S A WALTERS, E WALTON, O	8004220519 8004030003* 8004250014 8004070350 8004150143*	50-331 P 40-8745 CONTRACT 50-320 H 50-352 G	WEISS.J D WEISS.J M WEISS.E R WEISS.E R WEISS.E R	8004210042* 8004080031 8004020099* 8004020091 8004020079*	71-6717 TOPREP 50-3 Q 50-3 Q 50-3 Q
VANDENBURGH, D E VANDENBURGH, D VANDEORN, P K VANDEORN, P K VANDEORN, P K	8004110444* 8004220522 8004070177* 8004040222* 8004110514*	50-29 P 50-309 P 50-438 Q 50-416 Q 50-259 Q	WALTON G A WALTON O A WAMBACH, T V WAMBACH, T V WANDKE, N E	80040904014 8004300607# 8004080412* 8004170261 8004110087	50-293 Q 50-293 Q 50-255 P 50-244 P 50-304 Q	WEISS.E R WEISS.E R WEISS.E R WEISS.E R WEISS.J D	8004080578 8004080578 8004100562 8004100562 8004020101	50-289 0 50-289 0 50-289 0 50-289 0 70-687
VANHOGM19SEN, J VARANINI.E E VARELA, A A VARELA, A A VARELA, A A	8004010181* 8004640008* 8004070111* 8004100168* 8004100112*	50-268 P PR 50-443 Q 50-354 Q 50-352 Q	WANDKE, N WANDKE, N E WANDKE, N E WANDKE, N E WANDKE, N E	6004020311 8004020369 8004140306 8004020407 8004150472	50-275	WEISS.E R WEISS.E R WEISS.E R WEISS.J D WEISS.J D	8004100299 8004100299 8004110045 8004080609 8004080612	70-143 70-143 50-3 P 70-1257 70-572
VARELA, A A VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8004100040* 8004210078 8004020117 8004250332 8004020124	50-443 Q MISC 50-287 H 50-287 H 50-443 A	WANDKE, N E WANDKE, N E WANDKE, N E WANDKE, N E WANDKE, N E	8004150518 8004220586 8004220660 8004220694 8004270486	50-304 S 50-275 B 50-275 B 50-304 B 50-275 B	WEISS.E R WEISS.D WEISSBERG.S WEISS.D WEISS.D	8004080595 8004070380 8004020207 8004170108 8004140009	50-3 F 70-1426 State Prog 70-2872 70-827
VARGA. S. A.	8004110557 8004140093 8004140186 8004210028 8004110052	50-339 H 50-339 H 50-339 H 50-339 H 50-443 H	Wandke, n e Wang, p c Wang, a Ward, w J Ward, w J	8004290473 8004240566 8004290137 8004280146* 8004280153*	50-295 B NUREQ 50-313 P GA999 QA999	WEISS,D WEISS,D WEISS,D WEISS,D WEISSBERO,S	8004140476 8004150178 8004150182 8004220062 8004240451	70-27 70-820 70-824 70-1739 Stata Prog
VARGA, S.A.VARGA, S.A.VARGA, S.A.VARGA, S.A.VETTER, W.E.	8004110060 8004110067 8004150131 8004250266 8004020128*	50-443 H 50-443 H 50-443 H 50-29 G ACRS	WARD, C E WARD, J E WARD, D T WARD, W J WARD, J E	8004150278* 8004020123* 8004040272* 8004280147* 8004080149	71-49 ACRS ACRS QA999 PR	WEISS,D J WEISS,E R WEISS,E R WEISS,E R	8004160107 8004240108 8004150101 8004150101 8004220462	70-143 40-8768 50-374 50-574 90-247
VILLFORTH. J C VOELKËR, L E VOLGENAU, E VOLGENAU, E VOLGENAU, E	8004220677 8004100028 8004220132* 8004220409* 8004030166	50-320 P NUREG FOIA FOIA SECY	WARD, J E WARD, K D WARDEN, W G WAREMBOURG, D WAREMBOURG, D	B004100515 B004100207* B0040B0065 B0040B0399 B0040B0422	PR 50-254 G 50-387 H 50-267 F 50-267 B	WENGER, L G WENSLAWSKI, F WENSLAWSKI, F WERLING, J A WERLING, J A	8004170221* 800404030 8004040415 8004280078* 8004020002	50-317 8 50-70 8 50-70 8 50-334 P 50-334 8
VOLKEMA, R H VOLLEN, R J VOLLEN, R J VOLLEN, R J VOLLEN, R J	8004220397* 8004230091 8004230101* 8004040069 8004020214	FOIA 50-367 0 50-367 0 50-367 G 50-367 G	WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	9004080503 9004150939 9004150339 9004150432 9004150542	50-267 8 50-267 R 50-267 R 50-267 S 50-267 S	WERLING, JA WERLING, JA WERLING, JA WERLING, JA WERLING, JA	8004220597 8004030198 8004030191 8004070341 8004070346*	50-334 8 50-334 8 50-334 8 50-334 8 50-334 8
VOLLEN, R J VOLLMER, R H VOLLMER, R H VOLLMER, R H VOLLMER, R H	6004020478 8004020227 8004030272 8004030279* 8004030283*	50-347	WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	B0041505B2 B004150626 B004210294 B004210268 B004220775	50-267 S 50-267 S 50-267 S 50-267 R 50-267 I	WERLING, JA WERLING, JA WERLING, JA WERLING, JA WERLING, JA	8004070375* 8004110385 8004140329 8004140381 8004150516	50-334 8 50-334 6 50-334 8 50-334 8 50-334 8
VOLLMER,R H VOLLMER,R H VOLLMER,R H VOLLMER,R H VOLLMER,R H	8004070418 8004210252 8004210260 8004210272 8004210297	50-10 H 50-10 H 50-10 H 50-10 H 50-10 H	WAREMDOURG, D WARNICK, R F WARNICK, R F WARRINER, G H WATFORD, M L	9004240323 9004140202 9004110245* 9004040323* 9004150376*	50-267 8 1&E 50-266 0 50-261 R 50-261 R	WERLING, JA WERLING, JA WERLING, JA WERLING, JA WERLING, JA	8004150529* 8004150534* 8004150545* 8004230217 8004170223	50-334 8 50-334 8 50-334 8 50-334 8
VOLLMER,R H VOLLMER,R H VOLLMER,R H VOLLMER,P H VOLLMER,R H	8004210275 8004210279 8004210302 8004210308 8004140091	50-10 Н 50-10 Н 50-10 Н 50-10 Н 50-320 Н	WATSON, A F WATSON, J F WATSON, J F WATTENBARGER, S WATTS, T E	8004160088 8004300297 8004300297 8004080345 8004150416	RES WASTE MOT WASTE MOT XPORTLIC 50-373 A	WERLING, JA WERLING, JA WERLING, JA WERLING, JA WERLING, JA	8004230208 8004240385 8004270503 8004270508* 8004270387	50-334
	8004100047 8004180442 3004210319 2004210324 32	50-287 H 50-320 H 50-320 H 50-320 H 50-320 H	WATTSON, P WEAVER, J WEAVER, K WEBB, R E	8004150347* 8004080063* 8004110118 8004150376* 8004210379*	50-206 R COMMIBBION WABTE MOT 50-553 R 50-320 H	WERLING, JA WERNER, BJ, WESCOTT, H WEST, B WEST, WE	8004270393* 8004280546* 8004040039 8004280352* 8004140463	50-334 S 50-346 S 50-461 S 50-368 H 50-498 A
		50-320 H 50-320 H 50-320 H 50-320 P 50-320 P	WEBSTER, E H WEEKS, E D WEGNER, W WEIGAND, J O WEIGAND, J O	9004280125* 9004170233 9004030005 9004040335 9004040363	50~250 Q 50-133 R NUREO 50-458 A 50~458 A	WESTERN, P WESTERN, F WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F	8004080194* 8004080216* 8004090159* 8004040262* 8004100335*	FOIA FOIA 50-313 G 50-285 G 50-313 G
		50-320 P 50-10 H 50-528 G 70-687 50-306 Q	G t, dNAQIBW O t, dNAQIBW O t, dNAQIBW O t, dNAQIBW	9004040056 9004040106 9004040370 9004010019 9004010023	50-458 8 50-458 Q 50-458 A 50-458 Q 50-458 Q	WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F WESTERMAN, T. F WESTERMAN, T. F	8004210219* 8004080696* 8004040140* 8004080602* 8004210179*	50-298 Q 50-285 Q 50-267 Q 50-267 Q 50-445 Q
		FOIA FOIA FOIA NUREO 50~460 Q	WEIGAND, J G WEIGAND, J G WEIGAND, J G WEIGAND, J G WEIGAND, J G	9004010041 9004040378 9004180102 9004210182 9004280539	50~458 Q 50~458 A 50~458 A 50~458 I 50~458 R	WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F WESTNEOGE, T WESTON, K	8004210438* 8004250299* 8004040025 8004040166 8004300006	50-445 Q 50-313 Q 50-278 B 50-387 H 50-387 Q
		50-320 P 50-312 0 50-312 C 50-327 F 50-373 0	WEIGAND, J G WEIGENSBERG, I WEILL, C H WEILL, S M WEISS, E R	8004280543* 8004220616* 8004100551* 8004070071* 7906010118	50-458 R FOIA 40-261 50-483 H 50-334 Q	WETHY, CM WETTERBAHN, MJ WETTERHAHN, MJ WETTERHAHN, MJ WETTERHAHN, MJ WETTERHAHN, MJ	8004030167 8004030338 8004030338 8004150027 8004150030*	50-335 8 50-358 9 50-358 9 50-272 9 50-272 9

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WETTERHAHNIN J WETTERHAHNIN J WEXLER, D WHITCOMB, D WHITC, T J	8004150030> 8004150456 8004030340* 8004020379 8004220358*	50-272 G 50-311 G COMMISSION 50-320 H 50-259 P	WILLIAMS, C E WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C WILLIAMS, M	8004220225 8004090278* 8004040149* 8004110300\$ 8004080224	71-9010 50-373 Q 50-500 Q 50-456 Q MASTE MGT	WOODRUFF, R L	8004280288* 8004210034* 8004210076* 8001210082* 8004210337*	50-317 Q 70-1100 50-272 Q 50-277 Q 50-333 Q
WHITE, M P WHITENER, H L WHITESELL, D E WHITESELL, D E WHITESELL, D E	8004160046 8004020263* 8004040361* 8004040122* 8004020434*	ACRS 50-259 Q QA999 QA999 QA999	WILLIAMS, C C WILLIAMS, C E WILLIAMS, J L WILLIAMS, E F WILLIAMS, H P	8004280074+ 8004280166 8004010008 8004250072> 8004090247	50-454	WOODRUFF, R L WOODRUFF, R L WOODRUFF, R L WOODRUFF, R L WOODRUFF, R J	8004210345* 8004220402* 8004040023* 8004100408* 8004280188	50 245 Q 70-1143 50-10 Q 50-10 Q 50-412 Q
WHITESELL, D E WHITESELL, D E WHITESELL, D E WHITE, L D WHITESELL, D E	8004070310*	QA999	WILLIAMS, C C	8004300536*	50-546 Q	WOOLEVER, E J	8004070334	50-412 A
	8004100034*	QA999	WILLIS, C	8004140447*	50~324 R	WOOLEVER, E J	8004070277	50-334 R
	8004100005*	QA999	WILLODSEN, A F	8004090172	PR	WOOLEVER, E J	8004220483	50-412 Q
	8004070445	50-244 Q	WILLSEY, W B	8004070270	50-277 R	WOOLEVER, E J	8004230429	50-412 5
	8004110057*	QA999	WILSON, R D	80040802/2*	QA999	WOOLSEY, R T	8004280212	40-1162
WHITE,W W	8004040067* 8004230003 8004010355 8004110195 8004150434	50-344 T	WILSON.R	8004100554	ACRS	WRAY, J R	8004080038*	50-250 Q
WHITE,L D		50-244 Q	WILSON.B	8004140002	ACRS	WRAY, J R	8004250291*	50-261 Q
WHITE,L D		50-244 P	WILSON.B D	8004020471*	XPORTLIG	WRIGHT, K H	8004300065*	40-4492
WHITE,L D		50-244 F	WILSON.R D	8004080262*	GA999	WRIGHT, G C	8004080594*	50-155 Q
WHITE,L D		50-244 P	WILSON.R F	8004040231	50-320 P	WRIGHT, R W	8004160062*	50-553 Q
WHITE, L D	80041503314	50-244 P	WILSON, R F WILSON, R F WILSON, J H WILSON, B D WILSON, B D	8004040318	50-320 P	WRIGHT, K H	8004300053*	40-4492
WHITE, L D	8004150459	50-244 P		8004040321	50-320 P	WRIGHT, R W	8004080543	50-438 S
WHITE, L D	8004180458	50-244 S		8004020163*	50-272 P	WRIGHT, A L	8004280028	NUREQ
WHITE, L D	8004230371	50-244 P		8004020467	XPORTLIC	WU, B J C	8004280038	RES
WHITE, L D	8004230389	50-244 P		8004030274	XPORTLIC	WU, G	8004070341	40-8647
WHITE, L D	8004290378	50-244 P	WILSON, B D WILSON, R F WILSON, R F WILSON, R WILSON, R E	8004030280*	YPORTLIC	WU.G	8004070376	40-8727
WHITE, L D	8004300407	50-244 Q		8004040325	50-320 P	WU.J	8004210201*	50-3 H
WHITMAN, F M	8004220341*	F01A		8004040330	50-320 P	WU.K	8004030043	XPORTLIC
WHITMEY, O G	8004230499*	50-293 R		8004140221	50-247 P	WULLER.G E	8004010249	50-461 A
WHITSHURST, C	8004080165	50-367 H		8004020012	50-320 S	WULLER.G E	8004010328	50-461 F
WHITT,K W WHITT,K W WHITTLE,A J WICHERS,D L	8004140102 8004210429 8004220084 8004210357* 8004070235	18E 50-331 S 50-272 8 70-143 40-8502	WILSON, J N WILSON, W R WILSON, W R WILSON, W R WILSON, W R	8004020464 8004100442 8004100444* 8004100447* 8004100442	TOPREP 50-498 M 50-498 M 50-498 M 50-498 M	WULLER, G E WULLER, G E WURTZ, C B WYDLER, J W WYDLER, J W	8004140109 8004150190 8004210358* 8004090460 8004180319*	50-461 Q 50-461 Q 50-320 P PR COMMISSION
WICHERS, D.L.	8004070244	40-8502	WILSON, W R WILSON, W R WILSON, R F WILSON, R F WILSON, R F	8004100444#	50-498 M	WYDLER, J W	8004180220*	COMMISSION
WICHERS, D.L.	8004070196	40-8502		8004100447#	50-498 M	WYDLER, J W	8004100449	PR
WICHERS, D.L.	8004080219	40-8502		8004010344	50-320 P	WYDLER, J W	8004140025	PR
WICHERS, D.L.	8004090070	40-8502		8004040304	50-320 P	WYKOFF, D	8004150467*	50-254 \$
WICHERS, D.L.	8004210413	40-8502		8004070219	50-320 Q	YAMAGUCHI, T	8004020484	XPDRTLIC
WIDNER, W A	8004010112	50-321 0	WILSON, R F	8004070301	50-320 P	YANDELLIL A	8004210219*	50-298 G
WIDNER, W A	8004150072*	50-321 0	WILSON, R F	8004070318	50-320 P	YANICHKO,8 E	8004240397*	50-204 P
WIDNER, W A	8004070035*	50-321 0	WILSON, R F	8004110298	50-320 Q	YATES,5 R	8004140215*	50-10 U
WIDNER, W A	8004150136*	50-321 0	WILSON, R F	8004110362	50-320 R	YBARRONDO,L J	8004100029	NUREG
WIDNER, W A	8004110565	50-321 0	WILSON, R F	8004110471	50-320 P	YBARRONDO,L J	8004150152	RES
WIDNER, W A	8004150198 8004170298 8004030227 8004150358 8004230467	50-321	WILSON, N L WILSON, J H WILSON, J W WILSON, J L	8004070297 8004170234* 8004300600* 8004080474 8004080482*	50-334 I 50-327 F 50-272 Q 50-280 S 50-280 S	YIN, I T YIN, I T YIN, I T YIN, T YDUNG, R	8004040410# 8004080647# 8004100130# 8004040150# 8004030277	50-263 Q 50-373 Q 50-305 Q 50-346 Q PR
WIDNER, W A	8004280452	50-321 Q	WILSON, J L	8004080486*	50-280 S	YOUNG, T	8004070178*	50-275 G
WIDOFF, M P	8004080139	50-289 Q	WILSON, J N	8004180370	50-546 A	YOUNG, D W	8004280389*	50-289 H
WIDOFF, M P	8004080146*	50-289 Q	WILSON, R F	8004140372	50-320 S	YOUNG, F W	8004020170	State Prog
WIDOFF, M P	8004080150*	50-289 Q	WILSON, K R	8004170208*	50-267 S	YOUNG, F W	8004020080	State Prog
WIDOFF, M P	9004080167*	50-289 Q	WILSON, J N	8004300049	50-322 A	YOUNGDLOOD, B J	8004180194	50-352 H
WIDOFF, M P WIDOFF, M P WIDOFF, M P WIDOFF, M P WIDOFF, M P	8004080176* 8004080139 8004080146* 8004080150* 8004080167*	50-287	MINBON, J L WILSON, J L WILSON, J L WILSON, J L	8004280612 8004280616* 8004280626* 8004150617* 8004300025*	50-280 B 50-280 B 50-280 S 50-263 S 50-387 G	YTHIER, P YTHIER, P YUHAS, G P YUHAS, G P YUNDT, C P	8004100576* 9004210119* 8004300244* 8004210102* 9004080442	CONTRACT CONTRACT 50-244 Q 50-320 Q 50-344 R
MIDOFF, M P	8004080176*	90-289 0	WIZNER, D G	8004080529*	50-316 5	YUNDT,C P	6004150440	50-344 S
HIGGINS, R M	8004070185	50-387 H	WOFFORD, A W	8004070117*	50-322 G	YUNDT,C P	8004290471	50-344 S
WIGGINS, E	8004300067*	50-387 Q	WOGMAN, N A	8004110065	NUREG	YURLSIGH.B	8004290068*	50-320 H
WIGGINS, E	8004080105	CONTRACT	WOLFE, B J	8004010517	50-445 M	ZAHLER.R E	8004100090	PR
WIGGINTON, D	8004220012	50-316 P	WOLFE, B J	8004090126	50-445 M	ZAHLER,R E	8004110212	50-269 Q
Wigginton, D Wigginton, D Wiggine, E Wiggine, E Wilbern, L	8004070264 8004240087 8004030011 8004080603 8004040104*	50-334 P 50-334 P CONTRACT CONTRACT QA799	WOLFE, S J WOLFE, S J WOLFE, S J WOLFE, S J	8004090456 8004100243 8004150083 8004230055 8004230094	50-445 M 50-445 M 50-445 M 50-466 G 50-466 G	ZAHLER,R E ZAHLER,R E ZAHLER,R E ZAHLER,R E ZAHLER,R E	8004110155 80041101624 8004210235 80042102504 8004110162#	50-289 G 50-289 G 50-289 G 50-289 G 50-289 G
WILBUR, H A WILCOX, J D WILCOX, L WILKENS, P C WILKINSON, R	8004280149*	QA979	WOLFF.C C	8004070242	40-8602	ZAHLER,R E	8004210250#	50-289 0
	8004090374*	50-280 Q	WDLLETT.S A	8004230523	CUNTRACT	ZAHLER,R E	8004100435	50-289 0
	8004040001	50-312 H	WOLTNER.E	8004100030*	70-820	ZAHLER,R E	8004100436#	50-289 0
	8004100461	50-244 P	WOLTNER.E	8004220041*	70-371	ZAHLER,R F	8004100437#	50-289 0
	8004010227	50-294 P	WONG.T	8004090347	40-279	ZAHLER,R E	8004100435	50-289 0
WILLHITE,S HILLIAMS,R A HILLIAMS,R A WILLIAMS,R A HILLIAMS,R A	8004070149 8004240056* 8004240078 8004240073* 8004240046*	50-554 G 70-135 70-135 70-135 70-135	MOOD'E C MOOD'E C MOOD'T C MOOD'T C	8004070421 8004070421 8004110024 8004180487 8004210277	50-498 M 50-498 M 50-498 M 50-309 S 50-309 S	ZAHLER,R E ZAHLER,R E ZAHLER,R E ZAHLER,R L ZAHLER,R C	8004100436* 8004100437* 8004080195 8004080200* 8004090281	50-287 G 50-287 G 50-287 G 50-287 G 50-287 G
WILLIAMS,R A WILLIAMS,R A WILLIAMSON,P W WILLIAMS,C C WILLIAMS,C C	80042401534 800424003B* 7907250345 8004040040* 8004110176*	70-135 70-135 50-443 H 50-373 Q 50-440 Q	WOODFIN,R L WOODHALL,C D WOODHEAD.C P WOODHAN,D P	8004100028 8004030299 8004100564 8004300403 8004170323*	NUREG PR 50-409 G 50-446 G 50-317 F	ZAHLER, R C ZAHLER, R E ZAHLER, R C ZAHLER, R C ZAHLER, R E	8004090289 8004090295* 80041002/9 8004100285* 80040802004	50-289 G 50-289 G 50-289 G 50-289 G 50-289 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	_	AUTHOR	ACCESSION NUMBER	SUBJEC	RY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ZAHLER, R F	6004090283#	50-289 (Z 1 BULSKY, H	6004090285+	70-135		ZIEMANN D L	6004090147	50-245 P
ZAHLER, R E	60040702754	50~289 (G	ZIBULSKY, H	8004100092*	70-364		ZIEMANN, D L	8004100286	50-155 F
ZAHLER, R. E.	60041002854	50-289 (G	ZIBULSKY, H	6004220041+	70 371		ZIEMANN, D L	8004220780	50-244 P
ZAHLER, R E	6004110077	50-289 (C C	ZIEGLER	6004010379*	50 327	Q.	ZIEMANN, D L	8004080444	50-245 F
ZAHLER, R E	8004110085		G	ZIEGLER	6004170155+	50-327	ũ.	ZIEMARN, D L	6004090142	50-206 P
ZAHLER, R E	8004110100		G	ZIEMANN. D. L.	8004030365	50-213	P	ZIEMANN, D L	8004110022	50-259 F
ZAHLER, R E	8004110095	50~289 (G	ZIEMANN. D L	8004093242	50-204	P	ZIEMANN, D. L.	B004110145	50-27 F
ZAHLER,R F	8004110100	50 - 289 (G	ZIEMANN.D L	8004100302	50-10	P	ZIEMANN, D. L.	8004110146	50-206 F
ZAHLER, R E	G004100010	50-287 (G	ZIEMANN, D L	8004100309	50-213	P	ZIEMANN, D. L.	B0041B0094	50~244 P
ZAHLERIR E	8004100015*	50-289	G	ZIEMANN. Đ L	8004100311	50-245	P	ZIEMANN, D L	8004230216	50-220 F
ZAHLER, R E	8004100464		G	ZIEMANN-D L	8004100312	50-155	Ρ	ZIEMANN, D L	8004230226	50-237 P
ZAHLER R E	8004100010		G	ZIEMANN, D L	8004100314	50-409	P	ZIEMANN, D L	8004230234	50-219 P
ZAHLER, R F	6004100015*		G	ZIEMANN.D L	6004100316	50~244	₽	ZIEMANN, D Ł	8004240497	50~245 P
ZAHLER,R E	8004230001		G .	ZIEMANN, D L	B004100317	50-219	P	ZIEMANN, D Ł	8004170279	50-10 P
ZAHLER,R E	8004230097	50-267	G	ZIEMANN, D L	E004100511	50-29	þ	ZIEMANN, D L	8004210125	50~155 P
ZAHLER R F	8004230127		G	Z ZEMANN. D L	8004150135	50-255	P	ZIEMANN, D L	6004210127*	50-155 P
ZAHLER, R E	8004230131		G	ZIEMANN.D L	8004080155	50-409	₽	ZIEMANN, D L	8004210132*	50-155 P
ZAHLER, R E	8004230001		G	ZIEMANN.D L	8004080159	50-29	P	ZIEMANN, D L	8004170285	50-219 P
ZAHLER R E	G004140007*		G	ZIEHANN, B L	8004080162	50~219	P	ZIEMANN, D L	8004170290	50-409 P
ZAHLER,R E	6004140013*	50-289	e	ZIEMANN.D L	8004080699	50-204	P	ZIEMANN, D. L.	8004170297	50-206 P
ZAHLER R E	8004140017#		Q.	ZIEMANN.D L	8004090335	50-10	P	ZIEMANN, D L	8004170303	50~245 P
ZAHLER, R E	8004140023*		G	ZIEMANN D L	8004070338	50-213	P	ZIEMANN, D L	8004170308	50-27 P
ZAHLER,R E	0004140038*		G	ZIEMANN, D L	B004090344	50-155	P	ZIEMANN, D L.	8004210190	50~155 P
ZAHLER R E	8004140045*		G	ZIEMANN, D.L.	B004100559	50-244	P	ZIEMANN, D L	8004210227	50-213 P
ZAHLER,R E	6004140051+	50-287	G	ZIEMANN, D L	8004100548	50~245	P	ZIEMANN, D L	8004230178	50-10 P
ZAHLER, R. C.	B004140007+		G	Z TEMANN, D. L.	8004020001	50-155	P	ZIEMANN, D L	8004240003	50-244 P
ZAHLER R E	8004140013*		G	ZIEMANN, D L	8004020003	50~407	P	ZIEMANN, D L	8004250123	50~27 ₽
ZAHLER, R E	B004140017*		0	ZIEMANN, D L	8004020004	50-29	₽	ZIMMERMAN, R P	8004180147*	50-245 0
ZAHLER, R E	8004140023*		G.	ZIEMANNIÐ L	8004020007	50-213	P	ZIRWAS,K R	8004020310*	50~249 6
ZAHLER.R E	8004140038*	50-289	c	ZIEMANN, D L	8004020009	50-219	P	ZITTEL,H E	6004150027	REB
ZAHLER R E	8004140045*		Q	ZIEMANN, D.L.	8004020010	50-10	þ	ZUBER, N	8004100485	REVIEW CRP
ZAHLERIRE	8004140051*		G	ZIEMANN D L	6004020013	50-206	P	ZUDANS, Z	8004080646*	ACRB
ZARAKAS, P	8004030165		o	ZIEMANN, D L	8004020014	50-244	P	ZUDANS, Z	8004020241	ACRS
ZARIN, M S	8004080124+	FOIA		ZIEMANN, D L	8004020015	50~245	P	ZUFELT, E	8004090320*	50-333 R
ZECH. Q Q	8004080240	MISC		ZIEMANN, D. L.	8004080402	50-255	P	ZURAKOWSKI,P R	8004030247*	50-298 0
ZEFF.D W	8004010157	70-1201		ZIEMANHUD L	8004080405*	50~255	þ	ZWETZIO, G B	8004210227*	50-312 0
ZEFF.D W	B004220169	70-1201		ZIEMANN D L	6004040086	50-219	P	ZWETZIO, O B	8004280226*	50-312 0
ZEFF.D W	8004280237	70-1201		ZIEMANN, D L	6004080185	50-29	P	ZWETZ10, Q B	B004280214	50-312 0
ZEFF.D W	B004280243*	70-1201		ZIEMANN, D L	600403026B	50-245	F			
ZEFF.D W	8004040015*	70-1201		ZIEMANN D L	8004080426	50-255	F			

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
AAI Corp (subs of United Industrial Corp)	B004240063	XPORTLIC	:
	8004240067*	XPORTL10	:
AFL-CIO	8004080192*	FOIA	
ARMCO International, Inc Academy of Natural Sciences of Philadelp	8004090287*	0A999	
hia	8004210197*	50-317	R
Administrative Conference of the U S	B004160030*	COMMISSI	an
Advanced Energy Systems	6004030313	ACRS FOIA	
Advanced Technology, Inc Aerotost Operations	6004020192 6004170005	50-22B	Р
Akin, Gump, Hauer & Feld	B0040B0174	50-445	М
	8004080174	30-445	М
	8004080174	50-445	M
	8004080174	50-445 50-445	М
	8004100498 8004100498	50-445	M
	6004100478	30-443	11
	6004100498	50-445	М
43.4	8004100498	50-445	14
Alabama Power Co	8004010372 8004010425	50-348 50-348	P
	8004010507	50-34B	G
			٦
	8004010510*	50-346	8
	8004010513*	50-348 50-348	9
	8004030172 8004030174*	50~34B	P
	8004030212	50-348	R
	8004030214*	50-348	R
	B004070267	50-348	F
	8004080029	50-348	Q
	80040B0403	50-348	P
	8004080492	50-348	R
	8004080501*	50-348	R
	8004080540	50-348	8
	8004080547*	50-348	S
	8004080554*	50-348	8
	8004080651	50-348	P
	EQ040B0457	50-348	P
	E004100096	50-348	Q
	0004100330	50-364	À
	8004110003 8004140328	50-348 50-313	S
	0004140000	\$0-313	5
	8004140333* 8004140356	50-313	S
	B004140360*	50-313	S
	8004150426	50-348	R
	8004150428*	50-348	R
	6004150447	50-348	ρ
	6004150447	50-348	P
	E004150452*	50~349	P
	8004150452* 8004160242	50-348 50-364	P
	0004100545	JU-304	ä
	8004220729	50-348	8
	8004220738*	50-348	9
	8004220746*	50-348	8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	,
	8004250401 8004280434 8004280434 8004290284 8004290286*	50-364 50-348 50-348 50-348 50-348	0 P D D D D
'Alabama, State of	8004270367 8004270369* 8004300594 8004020116* 80043003B1*	50-348 50-348 50-348 ACRS 70-2909	5 0
Albright College Aldrich Chemical Co , Inc (subs of Sigma-Aldrich Corp)	8004160151* 8004080643	70-1251 XPORTLIC	
Allied General Nuclear Bervices Allis-Chalmers Corp	8004210041 8004220431* 8004220436*	F01A 50-313 50-313	F
	8004220440# 8004220447# 8004220450# 8004220453# 8004220454#	50-313 50-313 50-313 50-313 50-313	F F F F F F F F F F F F F F F F F F F
American Electric Power Co , Inc American Warming & Ventilating, Inc Anaconda Co (subs of Atlantic-Richfield	8004020120# 8004210150 8004280248 8004080225	ACRS PR PT21 WASTE MG1	Г
Co) Anaconda Co , Anaconda Copper Co Div	8004240060	WASTE MOT	
Anaconda Co , Anaconda Industries Wire & Cable Div	8004070079*	QA999	
Anefco, Inc Anti-Nuclear Group Representing York	80040700B1* 80042B0235* 8004030322 8004100563	QA999 50-327 50-289 50-289	P G G
Applied Biology, Inc	8004100565* 8004100567* 8004110095 8004040443* 8004040448*	50-287 50-287 50-287 50-335 50-335	G G G R R
Aquatic.Inc Argonne National Laboratory	8004180371* 7902060388* 8004020226 8004030294 8004030328*	50-271 MISC ACRS PR FOIA	R
	8004030330* 8004040469 8004080639* 8004100586 8004100591	40-2061 50-206 ACRS NUREG NUREG	o
Artiona Public Service Co	8004140470 8004150122 8004150326 8004270017 8004010244	NUREG ACRS NUREG NUREG 50-528	к
	6004010244 6004010244	50~528 50~528	K

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Υ	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGORY	Υ
	8004010247* 8004010247* 8004010247* 8004010350	50~528 50~528 90~528 50~528 50~528	8 K K	Arkansas, State of Army Dept of, Corps of Engineers Army, Dept of, Matls & Mechanics Research Center	8004290451* 80040804B2 8004220555	50-346 PR 50-329 REGOD	R A
	8004010358* 8004020162*	50-528	Q	Arthur Young & Co	8004090483*	50~320 50~574	ī e
	8004070255* 8004070258* 8004110484 8004150566	50~528 50-528 PR 50-528	S S	Asher, T.R., PC Atlantic Electric of New Jersey Atlas Minerals	8004080689 8004150255* 8004080055 8004080057* 8004220099	50-277 40-3453 40-3453 40-3453	ī
Arizona, State of	8004170045 8004170051* 8004240501* 8004300532 8004090229	50-528 50-528 50-528 PR PR	ន ទ 0	Atomic Industrial Forum	B004290449 B004290452* B004020123* B0040B0136* B0040B0149	40-3453 40-3453 ACRS FOIA PR	
Arizone, Univ of Arkanses Power & Light Co	8004180078* 8004280459* 8004070100* 8004010216 8004010217*	COMMISSI COMMISSI CONTRACT 50-313 50-313	ΦM		8004100818 8004170350* 8004170352* 8004210225 8004280493	PR 10CFR 10CFR NUREO 50-320	ę
	8004010301 8004010386 8004010416 8004020342 8004020346*	50-313 50-313 50-313 50-348 50-348	P Q S S	Austin, TX Australia Babenck & Hilcox Co	8004100535 8004170270 8004010157 8004010404* 8004010404*	50-445 XPORTL1C 70-1201 50-329 50-329	# 9 8
	8004020349 8004020353* 8004030209 8004030209 8004040276	50-313 50-313 50-313 50-313 71-7080	5 9 P		8004010404* 8004010404* 8004010404* 8004010404* 8004020459	50-327 50-327 50-327 50-327 50-327	8 8 8
	8004070118* 8004070287 8004070287 8004070344 8004070403*	50-348 50~313 50~313 50~313 50~313	0 P P P		8004020457 8004020457 8004020457 8004020457 8004020457	50-329 50-329 50-329 50-329 50-329	8 8 9 8
	8004070403* 8004080577 8004080596* 8004090148* 8004110508	50-313 50-368 50-368 50-313 50-313	P S G P		8004020467* 8004020475* 8004040015* 8004040137* 8004070388*	TOPREP TOPREP 70-1201 70-27 70-364	
	8004150235 8004150235 8004150239# 8004150239# 8004150304	50-313 50-313 50-313 50-313	Ι Ι Ι Ι		8004080661* 8004090461 8004090464* 8004100199 8004150209	ACRB TOPREP TOPREP TOPREP 50~430	ß
	8004150304 8004150541 8004150549* 8004150567 8004150579*	50-313 50-313 50-313 50-368 50-368	P 8 F F		8004150207 8004150210* 8004150210* 8004180026 8004180097	50~438 50~438 50~438 70~135 70~364	8
	8004150401* 8004150405 800415041#* 8004150630 8004150641*	50-348 50-348 50-348 50-313 50-313	r a a a a		8004180355 8004180533 8004180534* 8004210207* 8004210244	50-13 70-364 70-364 70-135 TOPREP	р
	8004160185 8004170086 8004170086 8004210148 8004210217	50-313 50-313 50-313 50-313 50-313	p p p R		8004210348 8004220127 8004220149 8004240234 8004240511*	TOPREP 71-6400 70-1201 70-824 50-313	p
	8004210220* 8004210274 8004210280* 8004220427 8004220471	50-313 50-368 50-368 50-313 50-313	R R R F	Babcock & Wilcox Co . Naval Nuclear Fuel	8004280354* 8004290517 8004300570 8004300570 8004070153	50-902 50-919 50-498 50-498 70-27	р 8 0
	B004220691 B004220703# B004230471 B004230473# B0042403B0	50-368 50-368 50-313 50-313 50-313	8 8 8 8	Div Babtock & Wilcox Co , Nuclear Material	8004280297 8004280243* 8004140006	70-1201 70-1201 70-364	
	6004250044 8004250103	50~313 50~368	Q Q	Div	8004180034 8004210081	70-364 70-135	
	8004250303 8004250347 8004250352* 8004250365	71~9044 50~382 50~382 50~382	8 8 1		8004210086* 8004240028 8004240038* 8004240046*	70-135 70-135 70-135 70-135	
	8004250369* 8004280487 8004280521	50~382 50~313 50~368	1 9 6		8004240046* 8004240056*	70~135 70~135	
	8004290244 8004290361 8004290366*	50-313 50-313 50-313	P R R		8004240073* 8004240155* 8004240170* 8004240177*	70~135 70~135 70~135 70~135	
	8004290374 8004290385# 8004290450	50-313 50-313 50-368	S S R		8004240177* 8004240177*	70-135 70-135	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEO	DRY
	8004240183* 8004240183* 8004240183* 8004240187* 8004270061	70-135 70-135 70-135 70-135 70-135			8004080335 6004080335 6004080391 8004080465 8004080465	50-317 50-317 50-317 50-317 50-317	Q Q F P
Baker & Botts	8004290105 8004020136 8004020208 8004020232 8004080073	50-445 (G M G M		8004080480 8004080488* 8004080500 8004080507* 8004090139	50-318 50-318 50-317 50-317	
	8004080244 8004080273 8004080273 8004080273 8004080285*	50-445 t 50-445 t 50-445 t	g M H M		8004090243 8004090359 8004100227 8004100265 8004150483	50-317 50-317 50-317 50-317 50-318	P P Qi
	8004090285* 8004080370 8004080370 8004080487 8004100078	50-445 1 50-445 1 50-466 (M M Q Q		8004150486* 8004150606 8004150620* 8004150624 8004150638*	50-318 50-317 50-317 50-318 50-318	\$ \$ 6
	8004100271 8004100271 8004100271 8004100274 8004100274	50~445 1 50~445 1 50~478 (M M M O O		8004170111 8004170219 8004170221* 8004170238 8004170238	MISC 50-317 50-317 50-317 50-317	ទីទី ក្
	8004100278* 8004100278* 8004100278* 8004100592 8004100552	50-445 1 50-445 1 50-466 (м м о м		8004210192 8004210197* 8004210197* 8004210323 8004210323	50-317 50-317 50-317 50-317 50-317	R R R S S
	8004100552 8004100552 8004100557 8004100560* 8004100560*	50-445 h 50-466 (50-445 h	M M G H M		8004220441 8004220614 8004220621* 8004220708 8004220719*	50-317 50-317 50-317 50-317 50-317	0 8 8 9
	8004100540* 8004110169 8004110169 8004140003 8004140003	50-445 6 50-445 6 50-445	M H H H		8004220745 8004220758* 8004220782 8004220782 8004250404	50~318 50~318 50~317 50~317 50~317	8 8 8
	8004140003 8004140008* 8004140008* 8004140008* 8004140415	50-445 h 50-445 h 50-445 h	M M M M 9		8004250407* 8004250407* 8004250411 8004250417* 8004280435	50-317 50-317 50-318 50-318 50-317	R R S P
	8004170312 8004210392* 8004210392* 8004210392* 8004210400*	50-445 h 50-445 h 50-445 h 50-445 h	H H		8004290345 8004290350# 8004290372 8004290377# 8004290382	50-318 50-318 50-317 50-317 50-317	8 8 8 8
	8004210400* 8004210400* 8004220003 8004230022 8004230074*	50-445 P 50-446 G 50-466 G 50-466 G	1 9 9		8004290388* 8004290410 8004290416* 8004290433 8004290438*	50-317 50-318 50-318 50-317	5 9 5 8
	8004230074* 8004230074* 8004230154 8004230154 8004230154	50-445 M 50-445 M 50-445 M 50-445 M 80-445 M	4 4 1		8004270440 8004270447* 8004270457 8004270472* 8004270475	50-317 50-317 50-317 50-317 50-317	8888
Raltimore Gas & Electric Co	8004240188 8004010212 8004010342 8004010351* 8004010364	50-466 Q 50-318 P 50-318 S 50-318 S 50-318 S		Barry, Davis N III	8004270484* 8004270490 8004270499* 8004300079 8004070208	50-317 50-317 50-317 71-383 PROJ	8 8 8
	8004010368* 8004010376 8004010380 8004010383*	50-318 8 50-318 9 50-318 9 50-318 8	3	Basic Energy Technology Associates Battelle Memorial Institute Battelle Mamorial Institute, Columbus Laboratories	8004030005 8004100497# 8004040204	NUREQ REVIEW RES	GRP
	8004010388*	50-318 S	3	COOL BACK TES	8004100025 8004300192	NUREO NUREO	
	8004010430 8004010435* 8004010439	50-317 8 50-318 8	i 3	Battelle Memorial Institute, Pacific Northwest Laboratory	8004040028	res	
	8004010448* 8004010463 B004030311 B004030311 B004030311 B004040271 B004040272*	50-317 P 50-317 P 50-317 Q	8 P P Q		8004040210 8004040270 8004040342 8004070093	RES RES RES ACRS	
		50-317 Q 50-317 Q ACRS 80-317 R) }		8004080283 8004110065 8004210298 8004210301 8004250409	RES NUREO NUREO NUREO TOPREP	
	8004070275 8004070276* 8004070276* 8004080333*	50-317 R 50-317 R 50-317 R 50-317 Q		Beatty, Levin, Holland, Basofin & Sarsany Bechtel Corp	8004270020 8004100027 8004010467*	NUREG 50~454 50~317	G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004010471* 8004030184* 8004040065* 8004040067* 8004220456*	50-317 50-361 50-344 50-344 50-313	A T T		8004090324 8004100258 8004100333 8004100379 8004100587	RES RES TOPREP TOPREP RES
Bechtel Power Corp (subs or Bechtel Corp)	8004280376* 8004280617* 8004280621* 8004280625* 8004040067*	50-416 50-255 50-255 50-255 50-344	F F		8004100590 8004100594 8004100599 8004110521 8004140403	RES RCS RES RES 50-271 F
Belgium Beltway Limousine Service, Inc	8004090377* 8004090386* 8004250428* 8004110359 8004080610*	GA999 GA999 50-373 REGGD CONTRAI	A		8004150015 8004150020 8004150021 8004150475 8004220574	REB REB REB REVIEW GRP
Berkeley, CA Beukers Laboratories, inc Black & Veatch Black & Veatch, Southern Science Applications inc ,Div	8004230340 8004180439* 8004140179 8004180532	50-224 50-320 REGOD REGOD	G H		8004230318 8004230320 8004230320 8004230387 8004230483	50-275 F 50-206 F 50-206 F 50-263 F 50-317 F
Black Hills Alliance Bloomsberg State College Boeing Computer Services, Inc. (subs. of Boeing Co.)		40-134: 50-387 CONTRAC	A CT		8004230510 8004230524 8004240460 8004240566 8004250382	50-271 F 50-254 F RES NUREO 50-286 F
Borg Warner Corp , Bryon Jackson Pump Di, Boston Edisan Co	8004020246 8004010013 8004070304	XPORTL1 XPORTL1 50-293 50-293	C Q P		8004250385 8004280032 8004280038 8004280041 8004280063	50-331 F RES RES RES RES
	8004080378 8004080511 8004080524* 8004090470	50-293 50-293 50-293 50-293	P የ የ የ P	Brown & Caldwell	8004280071 8004290007 8004300032 8004070345*	RE8 NURE0 RE8 50-206 R
	8004100384 8004100389* 8004100414 8004110079	50-293 50-293 50-293 50-293	P P G		8004070345* 8004070345* 8004070357* 8004070357*	50-206 R 50-206 R 50-206 R 50-206 R
	8004140310 8004140311* 8004140337 8004140342* 8004150576	50-293 50-293 50-293 50-293 50-293	P B B S	Brown & Root Corp (subs of Halliburtor Corp) Brown Boveri Corp (subs, Brown Bouveri Co ,Ltd)	& 8004220017 *	TOPREP 50-316 P
	8004150588* 8004160133* 8004170184 8004170191* 8004180363	50-293 50-293 50-293 50-293 50-293	8 0 8 8 P	Brownsvílle,™X	8004220023* 6004220027* 8004220034* 8004220039*	50-316 P 50-316 P 50-316 P 50-316 P
	8004210289 8004210292* 8004220580 8004220624 8004220631*	50-293 50-293 50-293 50-293 50-293	8 8 P 8	Bruce Norton	8004100430* 8004100433 8004150050* 8004080712	50-445 M 50-445 M 50-445 M 50-275 Q
•	8004230469 8004230477 8004230497 8004230499*	50-293 50-293 50-293 50-293	P G R R	Brush-Wellman, Inc Dunker-Ramo Corp , Amphenal North Americ Div Burns & Roe Co	8004300243 7708140247# 8004010282 8004070370# 8004070371#	40-8722 COMMISSION FOIA 50-397 A 50-397 A
.Barton & Eckler ionai Laboratory	8004240357 8004250156 8004270424 8004280004 8004220137* 8004010329	50-293 50-293 50-293 50-395 FOIA 50-171	0 9 F K	C-E Power Systems	8004070372* 8004070374* 8004240041* 8004010498 8004010501*	50-397 A 50-397 A CONTRACT TOPREP TOPREP
		50-171 50-266 50-266 50-295 50-409	F F F F		8004110216 8004110223* 8004110225* 8004210130* 8004210138*	TOPREP TOPREP TOPREP 70-1100 70-1100
		50-29 NUREO 50-333 50-254 REB	F F F	California Institute of Technology California Polytechnic State Univ	8004230315 8004240169 8004280400 8004180003 8004220601	TOPREP 70-1100 TOPREP AGRS 50-384 P
		RES RES RES 50-331 50-206	F F	California, State of	8003170734# 8004040007 8004040008# 8004090187 8004100540	50-128 P PR PR 50-312 0 PR
		50-206 RES RES 71-9019 RES	F	California, Univ of, Davis California, Univ of, San Diego	8004100542 8004220570 8004230317# 8004250047 8004210325#	50-312 T 50-204 P PROJ NUREO 50-275 0
		REB		California, Univ of, Banta Barbara	8004220418* 8004070328	FOIA 50-433 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
California, Univ of, Santa Crus Camp Dresser & McKee, Inc , Environmental Sciences, Div	8004070327* 8004210327* 8004020057	50-433 50-275 WASTE MG	R G ST		8004220676 8004220687* 8004220732 8004220740*	50-325 50-325 50-324 50-324	555
Carolina Power & Light Co	8004020061* 8004010324	90-261	β		8004230007* 8004230076	50-445 50-324	M G
	8004010385 8004010390* 6004010394 8004010400* 8004010405	50-325 50-325 50-324 50-324 50-261	5 5 5		8004230328 8004230328 8004230328 8004230328	50-400 50-400 50-400 50-400	A A A
	8004010405 8004010407* 8004010461 8004010461 8004010468*	50-261 50-261 50-324 50-324 50-324	I I R R R		8004230520 8004230525* 8004240362 8004240366* 8004240379	50-261 50-261 50-261 50-261 50-261	8 8 9 J
	8004010519 8004020297 8004030171 8004030176 8004030217	50-400 50-324 50-261 50-324 50-255	0 8 8 8		8004250261* 8004250410 8004250410 8004250412* 8004250412*	50-261 50-324 50-324 50-324 50-324	Q P P P
	8004040293 8004040297* 8004040305 8004040323* 8004040461	50-261 50-261 50-261 50-261 50-324	P P R Q		8004280497 8004280540 8004280541 8004280576 8004280583	50-324 50-400 50-400 50-325 50-324	P 9 9 8
	8004070035 8004070134 8004070275 8004070313 8004070333	50-400 50-261 50-400 50-261 50-324	Q Q Q F B		8004280586* 8004280587 8004280592* 8004280599* 8004290122*	50~325 50~324 50~324 50~324 50~324	5 5 6 0
	8004070337* 8004080357 8004080357 8004080383 8004080383	50-324 50-324 50-324 50-324 50-324	9 9 9 P		8004290397 8004290401* 8004290487 8004290494* 8004300323	50-325 50-325 50-325 50-325 50-324	5 5 5 7
	8004080451 8004080453 8004080454* 8004080458 8004080464*	50-400 50-325 50-325 50-324 50-324	A 9 8	Catholic Univ Center for Law in the Public Interest	8004300443 8004300445 8004070099* 8004020133 8004020133	50-261 50-324 40-4329 50-275 50-275	Р Н О
	8004080472 8004080472 8004080566 8004080575* 8004080648	50-324 50-324 50-325 50-325 50-261	F F S 9 P		8004080554 8004080554 8004070038 8004070038 8004070132	50-275 50-275 50-275 50-275 50-275	0 0 0
	8004070058 8004070332 8004100340 8004100343 8004100345*	50-400 50-324 50-261 50-261 50-261	& & G &		8004070132 8004070137* 8004070137* 8004210322 8004210322	50-275 50-275 50-275 50-275 50-275	0 0
	8004140413 8004140445 8004140445 8004140447*	50-261 50-324 50-324 50-324 50-324	P R R R R	Central & Southwest Corp	8004080153 8004080360 8004080559 8004080559 8004090387	50-445 50-445 50-445 50-445 50-445	M M M
	8004140468* 8004150374 8004150376* 8004150444 8004150448*	50-261 50-261 50-261 50-324 50-324	G R R S	Central & Bouthwest Bervices, Inc Central Power & Light Co Charles B Wurtz	8004090387 8004230002 8004220128 8004180167* 8004210358*	50-445 50-445 50-445 50-445 50-320	M M M P
	8004150466 8004150466 8004150504 8004150504	50-324 50-324 50-324 50-324 50-324	3	Charlevoix,MI Chem-Nuclear Systems, Inc Cherry, M. H./Cherry, Flynn & Kanter	8004030363 8004070254 8004090091 8004020033 8004020033	50-155 71-9122 71-9122 50-454 50-454	0
	8004140282 8004170015 8004170019* 8004170047	50-324 50-324 50-324 50-400	P P P A		8004080429 8004080429 8004080435# 8004080435# 8004090177	50-454 50-454 50-454 50-454 50-454	000
	8004180344 8004180344 8004180418 8004180425* 8004210273	50-400 50-261 50-261 50-261 50-324 50-400	S J S S G A	Chesapeake Energy Alliance	8004090177 8004030320 8004090190 8004110157 8004110164*	50-454 50-289 50-289 50-289 50-289	0 0 0
	8004220451 8004220451 8004220451 8004220538 8004220538	50-400 50-400 50-400 50-325	A A A S S	Chicago, City of, IL	8004110166* 8004110175 8004230039 8004080092 8004080177	50~289 50~289 50~289 40~2061 40~2061	о о
	8004220547# 8004220572 8004220593* 8004220597 8004220408*	50-325 50-324 50-325 50-325 50-325	5 BBBB	Chickering & Oregory	8004080228 8004070188 8004070196* 8004100477 8004100537	PR PR PR 50-361 50-361	9

AUTHOR AFF1LTATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Chanza, N	8004080239 8004240086	50-250 G 50-250 G		8004040341 8004070227	50-10 P 50-10 P
Christa-Maria Cincinnati Gas & Electric Co	8004140031# 8004030338 8004040340	50-159 H 50-359 0 50-359 I		8004070245 8004070273 8004070273	50-237 P 50-254 F 50-254 F
	8004040343* 8004150301 8004160009 8004220156 8004280317	50-358 I 50-358 A 50-358 0 50-358 0 50-358 F		8004070273 8004070273 8004080214 8004080214 8004080235	50-254 F 50-254 F 50-275 P 50-275 P 50-237 P
Cincinnat: General Hosp Cincinnati,OH	8004280322# 8004300604# 8004220044# 8004220097# 8004220242#	50-358 F 50-358 Q FOIA FOIA FOIA		8004080254 8004080397 8004080428 8004080428 8004080454	50-247 Q 50-454 K 50-454 Q 50-454 Q 50-249 B
Cincinnati, Univ of, Medical School	8004220387* 8004220391* 8004220404* 8004220101* 8004220120*	FOIA FOIA FOIA FOIA FOIA		8004080463* 8004080522 8004080522 8004080541 8004080549*	50-247 S 50-373 K 50-373 K 50-10 B 50-10 B
Citizens Action For Safe Energy	8004070149 8004100605* 8004100605* 8004100610* 8004100610*	50-556		8004080552 8004080561* 8004100128* 8004100322 8004100338	50-249 8 50-249 8 50-10 0 50-454 0 50-295 P
Citizens Against Nuclear Dangers Citizens Concerned About Nuclear Power, Inc	8004020040 8004280069	50-387		8004110087 8004110397 8004110458	50-304 G 50-237 F 50-237 P
Citizens Energy Forum Citizens for Fair Utility Regulation Citizens for a Better Environment	8004280211 8004240424* 8004090271	50-338		8004140119 8004140119 8004140119	50-10 0 50-10 0
Cleveland Electric Illuminating Co	8004150471 8004230353 8004280384*	50-346		8004140117 8004140117 8004140117	50-10 Q 50-10 Q 50-373 I
Coalition for Safe Power Cohn, D B	8004230020 8004010294	50-344 0 50-367 0		8004140306 8004140330	50-275 R 50-10 R 50-237 P
Colorado State Univ	8004010300* 8004280420* 8004280425* 8004280427*	50-347 G 40-8481 40-8402 40-8402		8004140395 8004140423 8004140429* 8004140441	50-237 P 50-237 B 50-237 B 50-456 A
Colorado, State of	8004070359*	WASTE MGT		8004140449*	50-456 A
Colt Industries, Inc	8004110118 8004110146* 8004240116 8004300254 8004020455	WASTE MOT WASTE MOT WASTE MOT WASTE MOT 50-395 B		8004150004 8004150314 8004150314 8004150316	50-254 R 50-10 P 50-10 P 50-10 P
Colt Industries, Inc. Fairbanks Morse	8004080297*	0A999		8004150316 8004150316	50-10 P
Engine Div Columbus & Southern Ohio Electric Co Commerce, Dept of, National Bureau of	8004140156 8004040350+ 8004070194*	50-483 6 50-358 I 50-184 Q		8004150328* 8004150344 8004150382	50-10 P 50-10 F 50-10 R
Standards	B004100007*	50-184 G		6004150382 6004150387*	50-10 R 50-10 R 50-10 R
Commerce Dept of, National Marine Fisheries Service	8004170250	50-272 P		80041503B7* 8004150416 8004130419*	50-10 R 50-373 A 50-373 A
Commonwealth Edison Co	8004010352 8004010357 8004020177 8004020187	50-373 F 50-237 P 50-597 A 50-295 P		8004150457 8004150463 8004150467* 8004150468*	50-254 B 50-254 B 50-254 B 50-254 B 50-304 B
	9004020307 B004020310* 8004020311 B004020313*	50-249 S 50-249 S 50-249 S 50-295 S		8004150477* 8004150497* 8004150498* 8004150503	50-304 8 50-304 8 50-245 8 50-265 8 50-237 8
	8004020332 8004020337* 8004020350 8004020352 8004020355*	50-249 8 50-249 5 50-254 8 50-265 8 50-265 8		8004150513* 8004150518 8004150526* 8004180217	50-237 S 50-304 S 50-304 S 50-10 P
	8004020357* 8004020363 8004020367*	50-254 S 50-249 S	1	8004180217 8004180217	50-10 P 50-10 P
	8004020367# 8004020369 8004020376#	50-249 S 50-295 S 50-295 S		8004180217 8004180217 8004180372 8004180389 8004180389	50-10 P 50-10 P 50-249 P 50-247 P 50-247 P
	8004020412# 8004020422 8004020427# 8004020430	50-304 S 50-254 S 50-254 S 50-265 S		8004180389 8004180389 8004180395* 8004180395* 8004180395*	50-247 P 50-247 P 50-247 P 50-247 P 50-247 P
	8004020443* 8004020445* 8004030027 8004030172	50-265 8 50-265 8 50-237 P 50-10 F		8004180375* 8004210286 8004210288*	50-247 P 50-249 B 50-249 B
	8004030172	50-10 F		8004220299 8004220299	50-237 F 50-237 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8004220332 8004220333 8004220333 8004220348 8004220356	50-10 50-254 50-254 50-237 50-295	P R R P F		8004110574 8004150027 8004150030* 8004150456 8004150469*	50~445 50~272 50~272 50~311 50~311	Meeee
	8004220356 8004220586 8004220596* 8004220613 8004220623*	50-275 50-275 50-275 50-245 50-265	8 8 8	Consolidated Edison Co of New York	8004220156 8004030165 8004070205* 8004070208* 8004070214*	50-358 50-3 50-3 50-3 50-3	9 H H
	8004220430 8004220460 8004220464 8004220461* 8004220693	50-10 50-295 50-295 50-10 50-249	# # # # # # # # #		8004070224* 8004070229* 8004070233* 8004080410 8004080417	50-3 50-3 50-3 50-247 50-247	H H F P
	8004220694 8004220700* 8004220702* 8004230072 8004230367	50-304 50-249 50-304 50-10 50-10	8 8 P F		8004150433 8004150599 8004150599 8004150599 8004150609#	50-247 50-3 50-3 50-3 50-3	P R R R
	8004230367 8004230367 8004230479 8004240412 8004250353	50-10 50-10 50-373 50-265 50-249	F A P P		8004150609* 8004150609* 8004180389 8004180389	50-3 50-3 50-247 50-247 50-247	R P P
	8004250427 8004280410 8004280412# 8004280414# 8004260509	50-373 50-373 50-373 50-373 50-295	A A A A P		8004180395* 8004180395* 8004180395* 8004210255 8004210258*	50~247 50~247 50~247 50~247 50~247	6 6 8 8
	8004280509 8004290380 8004290407* 8004290422 8004290429*	50-295 50-265 50-265 50-249 50-249	P 8 8 8		8004210269 8004210269 8004210269 8004210276* 8004210276*	50-3 50-3 50-3 50-3 50-3	R R R R
	8004290473 8004290483* 8004290486 8004290496* 8004290502	50-295 50-295 50-295 50-295 50-295	8 8 8 8 8		8004210276* 8004220589 8004220627 8004240410 8004300307	50-3 50-247 50-247 50-247 50-247	R F P P
	8004290502 8004290506* 8004290506* 8004300416 8004300419*	50-275 50-275 50-275 50-247 50-247	р Р Р	Consumers Pawar Co	8004300411 8004010289 8004010397 8004020166 8004020285	50-247 50-285 50-329 50-255 50-155	P 6 F R
Come, Owen, Wagner, Nugent, Johnson, Hazouri & Roth Connecticut Light & Power Co	8004300423* 8004300429 8004070008 8004080564* 8004150322*	50-247 50-247 FOIA 50-245	P P		8004020289* 8004030220* 8004040309 8004040311* 8004040327	50-155 50-255 50-155 50-155 50-155	R R P P
Connecticut Yankes Atomic Power Co	8004010362 8004010367* 8004020372 8004020374* 8004030211	50-245 50-213 50-213 50-213 50-213 50-213	1 8 8 8 8 8		8004040371 8004040376* 8004070293 8004070293 8004070294*	50-255 50-255 50-327 50-327 50-327	R R R
	8004040066 8004040331 8004040338* 8004070274	50-213 50-213 50-213 50-213 50-213	6 6 8 6		8004070294* 8004070305 8004070320 8004070322* 8004080184*	50-329 50-255 50-255 50-255 50-155	Р Р О
	80040B0292 8004110012 8004150297 8004150487 8004170012	50-213 50-213 50-213 50-213 50-213	I Q P R		8004080232 8004080404 8004080404 8004080431 8004080431	50-255 50-327 50-327 50-327 50-327	Р А А А
	8004170012 8004180224 8004180346 8004210251 8004210253*	50-213 50-213 50-213 50-213 50-213	F F R R		800408043& 8004080438* 8004080470 8004080475* 8004090248	50-255 50-255 50-155 50-155 50-329	R R B K
	8004210411 8004230297 8004240437 8004240439* 8004250132	50-213 50-213 50-213 50-213 50-213	₽ F R R		8004070248 8004070251* 8004070251* 8004070258* 8004070258*	50-329 50-329 50-329 50-329 50-329	K K K
Commecticut, State of	8004250143* 8004280465 8004270264 8004270442 8004070426*	50-213 50-213 50-213 50-213 8tate P	G P R P		8004070383* 8004070387 8004100273 8004100276* 8004100278*	50-255 50-255 50-155 50-155 50-155	0 0 0
Conner, Mpore & Corber	8004070114 8004100445 8004030338 8004080409	PR PR 50-358 50-375	Q Q		8004100368 8004100384 8004100384 8004100387* 8004100387*	50-329 50-329 50-329 50-329 50-329	Q A A A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004100390* 8004100390* 8004100396 8004100397* 8004100403	50-329 A 50-327 A 50-255 S 50-255 S 50-255 S	Debevoise & Liberman	8003250002 8004040088 8004080119 8004080221 8004080247	NUREO 50-445 Q PR 50-445 Q 50-445 M
	8004100404* 8004100413 8004100455* 8004100455*	50-255 S 50-255 S 50-255 S 50-155 G 50-155 G		8004080247 8004080247 8004080401 8004080401 8004080401	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M
	8004100469* 8004100480* 8004110308 8004110308 8004110505	50-195 G 50-195 G 50-195 P 50-195 P PR		8004080638 8004090331 8004100514 8004100514 8004100514	50-445 M PR 50-445 M 50-445 M
	8004140309 8004140334 8004140391 8004150012 8004150019*	50-155 P 50-255 Q 50-327 K 50-255 S 50-255 S		8004100525* 8004100525* 8004110153 8004140005 8004140285	50-445 M 50-445 H 70-2623 PR 50-397 A
	8004150215 8004150354 8004150354 8004150398 8004150474	50-255 P 50-227 8 50-227 8 50-255 P 50-255 P		8004140285 8004160285 8004180151 8004230012 8004230033	50-397 A 50-397 A 50-445 M 70-2623 50-445 M
	8004150479* 8004150530 8004150537* 8004150544 8004150556*	50-255 P 50-255 S 50-255 S 50-255 S 50-255 S		8004230033 8004240173 8004240562 8004250049 8004280189	50-445 M 50-445 M 50-445 M 50-445 M 50-556 Q
	8004150427 8004170083 8004170083 8004180487 8004210158	50-255 P 50-329 S 50-329 S 50-255 G 50-255 P	Delmarva Power & Light Co Detroit Edison Co	8004150260* 8004020403 8004040278 8004070135* 8004080647*	50-277 I 50-341 B 50-341 A 50-341 Q 50-341 Q
	8004210318 8004220575 8004220581* 8004220588 8004230383	50-329 8 50-155 0 50-155 0 50-255 9 50-155 H	Doctors Hosp Columbus,OH Doherty,JF Dougherty,JB	8004230489 8004300382 8004230029* 8004240548 8004150101	50-341 S 50-341 G FOIA 50-466 G 50-574 G
	8004230383 8004240372 8004240450 8004250313 8004250350	50-155 H 50-155 P 50-255 P 50-255 Q 50-255 8	Oresser Industries, Inc Duke Pawer Co	8004150204 8004280211 8004300555 8004010470 8004010470	FOIA 50-338
	8004250354 8004250359* 8004250359* 8004250425 8004250426	50-255 \$ 50-255 \$ 50-255 \$ 50-255 P 50-255 P		8004010470 8004020019 8004020334 8004020338* 8004020348	50-269 P 50-413 Q 50-269 I 50-269 I 50-369 B
	8004280402 8004280460 8004280519 8004280555 8004280597*	50-255 Q 50-327 F 50-255 P 50-155 F 50-155 F		8004020348 8004020358* 8004020358* 8004030152 8004030152	50-369 8 50-369 8 50-369 8 50-369 F 50-369 F
Control Data Corp Coordination Council for North American Affairs	8004280514 8004290324 8004290501# 8004150590# 8004030043	50-255 F 50-155 G 50-369 A 50-366 F XPORTLIC		8004030157 8004030157 8004030157 8004030199 8004030199	50-269 F 50-269 F 50-269 F 50-269 P 50-269 P
Creare. Inc Critical Mass Energy Project Dairyland Power Cooperative	8004140478 8004090152 8004010108 8004090369 8004140312	NUREO PR 50-409 Q 50-409 P 50-409 P		8004030199 8004030202* 8004030223 8004030224* 8004040358	50-249 P 50-249 P 50-287 9 50-287 8 50-269 9
	8004140314* 8004140365 8004140367* 8004150119 8004150204	50~409 P 50~409 R 50~409 R 71~6400 50~409 P		8004070234 8004070234 8004070236* 8004070236* 8004070327	50-369 A 50-369 A 50-369 A 50-369 A 50-269 B
	9004190488 8004219200 8004220584 8004290341 8004300455	50-407 S 50-407 S 50-407 S 50-407 B 50-409 S		8004070330* 8004070362 8004080101 8004080125 8004080253	50-269 8 50-269 9 50-369 8 PR 50-269 9
	8004300463* 8004230082 8004010250* 8004040387* 8004210409	50-409 8 50-556 6 50-466 A 50-250 R 50-409 P		8004080366 8004080366 8004080432 8004080455 8004080455*	50-349 A 50-349 A 50-287 Q 50-349 A 50-349 A
spons ible	8004240499 8004040355* 8004100027	40-297 50-358 I 50-454 Q		8004080461* 8004080461* 8004080471 8004080476* 8004080555	50-369 A 50-369 A 50-269 B 50-269 B 50-269 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8004080614 8004090241 8004100351 8004100558 8004110153	50-269 PR 50-269 70-2623 70-2623	P G	***************************************	8004150534* 8004150545* 8004170223 8004210261 8004210266*	50-334 50-334 50-334 50-334 50-334	9 9 9 8
	800411055B 800414034B 8004140430 8004140430 8004140430	PR 50-369 50-269 50-269 50-269	A P P		8004210283 8004220483 8004220594 8004220597 8004230208	50-334 50-412 50-334 50-334 50-334	P G P S S
	8004140430 8004150465 8004150465 8004150465 8004160116	50-269 50-269 50-269 50-269 50-413	P P G		8004230217 8004230429 8004230517 8004240089* 8004240385	50-334 50-412 50-334 50-334 50-334	8 9 9 9
	8004160227 8004160232* 8004160272 8004170164 8004170203	50-287 50-287 50-287 50-269 50-269	8 9 9 9 9		8004280078* 8004280188 8004290354 8004290355* 8004290389	50-334 50-412 50-334 50-334 50-334	P G R R
	8004170208* 8004170327 8004180273 8004180356 8004180516	50-269 50-269 50-369 50-269 50-369	5 F P Q	E L Conwell & Co	8004270393* 8004270503 8004270508* 8004210066 8004210073*	50-334 50-334 50-334 71-381 71-381	5 5
	8004210164 8004210172 8004210171 8004210171 8004210171	50-413 Regod 50-269 50-269 50-269	0 0 0	E 1 du Pont de Nemours & Co , Inc EDS Nuclear, Inc EG & G, Inc	8004140121 8004220273* 8004020142 8004030308* 8004080075	ACRS 50-331 RES FOIA RES	F
	8004210234 8004220105 8004220105 8004220105 8004220443	50-413 50-491 50-491 50-491 50-269	Q Q Q F		8004080082 8004080242 8004080641 8004080684 8004080684	RES RES 50-270 50-270 RES	P P
	8004220443 8004220443 8004220502 8004220502 8004220640	50-269 50-269 50-269 50-269 50-269	F F P P		8004070048 8004100027 8004100328 8004100378 8004140138	RES NUREO RES RES	
	8004220640 8004220649 8004220682 8004220690* 8004220720	50-269 50-270 50-269 50-269 50-369	P P B S A		8004150025 8004150038 8004150056 8004170120 8004170274	50-155 50-271 RES RES RES	þ
	8004230012 8004230085 8004230236* 8004240035 8004240276	70-2623 50-488 50-269 50-269 50-269	0 0 0		8004170276 8004170289 8004170334 8004210340* 8004210344*	RES RES RES 50-320 50-320	P P
	8004240424 8004240424 8004240426 8004250334* 8004280473	50-491 50-491 50-491 50-269 PR	0 0 0 0		8004210347* 8004210349* 8004240468 8004240565 8004250364	50-320 50-320 RES NUREG 50-275	P P
Duquesne Light Co	8004270493 8004270501* 8004300214* 8004010459	50-369 50-369 50-269 50-334	A G P	ETA Engineering,Inc Earth Scionces Associates Ebasco Services, Inc (subs of Enserch Corp)	8004150520* 8004090020 8004100588	50-315 WASTE M	
	8004020002 8004030191	50-334 50-334	8	Eberline Instrument Carp	8004140224* 8004040090	SO-201 XPORTLI	
	8004030196 8004030197* 8004030198 8004030201	80-334 50-334 50-334 50-334	R R S P	Eckert. Seamans, Cherin & Møllott	8004100306 8004140322* 8004140340* 8004150007* 8004280036	XPORTL1 50-295 50-10 50-254 50~574	.C R R R
	8004040165* 8004040354	50-334 50-334 50-334	Q F F	Ederer, Inc. (subs of Formac Internatio	8004020267	TOPREP	
	8004040359* 8004070199* 8004070277 8004070280*	50-334 50-334 50-334	G R R	nal. Inc) Edison Electric Institute	8004020271* 8004080245 8004100513* 8004110367	TOPREP PR COMMISS PR	310N
	8004070334 8004070341 8004070346* 8004070375*	50-412 50-334 50-334 50-334	A S S S	Ediow International Co	8004040135 8004040422* 8004040427* 8004040437*	XPORTLI FOIA FOIA FOIA	IC
	9004090009 8004100398* 8004110160 8004110389 8004110482	50-334 50-334 50-334 50-334 50-334	0 0 9 5 P	Eichharn, Eichhorn & Liny Elbert P Epler	8004040442* 8004080032 8004280096 8004020092 8004030295	FOIA XPORTLI XPORTLI 50-367 ACRS	1 C
	8004140327 8004140381 8004150221 8004150514 8004150527*	50-334 50-334 50-334 50-334 50-334	8 0 8 S	Ellis Fischel St. Cancer Hosp. Columbia, MO Energy Engineering Group Energy Fuels Nuclear, Inc	8004010789* 8004150152 8004020487	PT9 RES 40-8681	1

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Energy, Dept of *	8004020055 8004020057* 8004020455* 8004030054* 8004030065*	71-6387 71-6387 50-320 H 50-320 H 50-320 H		8004070108* 8004070112* 8004070370 8004070378* 8004100066	70-1257 70-1257 70-1257 70-1257 70-1257
	8004030071* 8004030093* 8004040233* 8004040237* 8004040245*	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	FBF, inc	8004100073 8004140458 8004140464* 8004180072 8004070021	70-1257 70-1257 70-1257 70-1227 71-185
	B004040248* B004040253* B004040258* B004040263* B004040265*	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	FOI Service Federal American Partners	8004070022* 8004020290 8004100052 8004210017 8004300053*	71-185 FOIA FOIA FOIA 40-4492
	8004040431* 8004070247 8004070389 8004070082 8004090087	50-320 H 71-9853 71-9067 GRG DRG	Federal Emergency Management Agency Federal Signal Corp , Signal Div	8004300069* 8004030026 8004040379 8004170202 8004230436	40-4492 50-320 9 NUREQ PR NUREQ
	8004090269* 8004100575* 8004110523 8004180200 8004180207*	90-996 H 90-320 H PR XPORTLIC XPORTLIC	Feldman, Hall, Franden, Reed & Woodward	8004100595 8004100595 8004100605* 8004100605*	50-556
	8004210026 8004210149* 8004210282* 8004210353 8004210359*	XPORTLIC XPORTLIC 50-546 H PR 70-143	Finland Fire Equipment, Inc	8004100610* 8004250009 8004230309* 8004230313* 8004230316*	50-556 0 XPDRTLIC 50-213 F 50-213 F 50-213 F
	8004210361* 8004220010 8004220124* 8004220143* 8004220191*	PR NUREG 50-320 H 50-320 H 50-320 H	Fleischaker, D S	8004020133 8004020133 8004080556 8004080556 8004090038	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
	8004230129 8004230133+ 8004240559 8004240568 8004280172	XPORTLIC XPORTLIC NUREG PR PR		800409003B 8004090132 8004090132 8004090137* 8004090137*	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
Energy,Dept of, Clinch River Breeder Reactor Plant Envirological Systems, Inc Environmental Coalition on Nuclear Power	8004150473 8004290364 8004090140* 8004080143 8004080143	50-537 A 50-537 A WASTE MOT 50-387 Q 50-387 Q	Florida Citíos	8004210322 8004210322 8004230107 8004230107 8004220152	50-275 0 50-275 0 50-275 0 50-275 0 50-275 H
	8004080597 8004080597 8004110477 8004140051 8004140057*	50-387 0 50-387 0 PR 50-320 0 50-320 0	Florida Power & Light Co	8004230174 8004010210 8004010210 8004010214* 8004010214*	50-387 H 50-250 P 50-250 P 50-250 P 50-250 P
En√ıronmental Defense Fund Environmental Law Institute	8004140076* 8004230073 8004240544 8004040346 8004030340*	50-320 G PR 50-287 G 50-275 H COMMISSION		8004010497* 8004020011* 8004020265* 8004020377 8004020381	50-302 R 50-387 0 50-387 0 50-251 9 50-335 8
Environmental Policy Center Environmental Protection Agency	8004070350 8004010345* 8004010444 8004010470 8004030272	50-320 H 50-508 A 50-320 R 50-320 R FR		8004020384* 8004020391* 8004030167 8004030229 8004030249	50-335 8 50-251 8 50-335 8 50-387 F 50-250 9
	8004040188 8004070222 8004070332 8004090075 8004100050*	40-2041 50-320 R 50-320 R 50-320 R PR		8004030256* 8004030282 8004030285* 8004030287 8004030287	50-250 8 50-335 8 50-335 8 50-250 P 50-250 P
	8004100050# 6004100055# 8004100055# 8004100497 8004140246	FR FR FR 50-320 P 50-280 P		8004040003 8004040003 8004040173* 8004040347* 8004040347*	50-250 G 50-250 G 50-367 G 50-250 G 50-250 G
, √i ≒chen	B004R20415 B004R30375 B004R30375 B004R30370 S004R20152	50-320 R 50-320 R 50-320 R NUREO 50-445 M		8004040380 8004040380 8004040397* 8004040425 8004040434*	50-250 R 50-250 R 50-250 R 50-235 R 50-335 R
ubs of Exxan	8004070154 8004080178 8004280403 8004290526 8004020307	40-8102 40-8064 40-8102 40-8102 50-261 P		8004070279 8004080015* 8004080023* 8004080257 8004080265*	50-335 F 50-250 G 50-250 G 50-335 R 50-335 R
	9004020404 9004070214 9004090102	TOPREP 71-9009 70-1257		8004080386 8004080452 8004080601 8004080608* 8004090217	50-335 P 50-250 P 50-250 8 50-250 8 50-335 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	YF	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8004070217* 8004070247 8004110533* 8004110536*	50-335 PR 50-250 50-250 50-250	R G G		8004240334 8004240343* 8004240350 8004240350 8004240350	50~335 50~335 50~250 50~250 50~250	9 9 8 8 8
	8004110536* 8004140227 8004150156* 8004150341 8004150406	50-250 50-335 50-335 50-335 50-250	G F P I		8004240356* 8004240356* 8004240356* 8004240359 8004240359	50-250 50-250 50-250 50-250 50-250	R R R R
	8004150406 8004150406 8004150411* 8004150519 8004180373	50-250 50-250 50-250 50-250 50-250	F F R		8004240359 8004240363* 8004240363* 8004240363* 8004240368	50-250 50-250 50-250 50-250 50-250	R R R R
	8004180373 8004180373 8004180374* 8004180374* 8004180374*	50-250 50-250 50-250 50-250 50-250	R R R R		8004240369 8004240375* 8004240375* 8004240318* 8004240418	50-335 50-250 50-335 50-250 50-250	S R S G R
	8004180524 8004180524 8004180524 8004180528* 8004180528*	50-250 50-250 50-250 50-250 50-250	R R R R		8004240418 8004240418 8004240422* 8004240422* 8004240422*	50-250 50-250 50-250 50-250 50-250	R R R R
	8004180528* 8004180527 8004180527 8004180527 8004180530*	50-250 50-250 50-250 50-250 50-250	R R R R		8004240436 8004240436 8004240446 8004240440* 8004240440*	50-250 50-250 50-250 50-250 50-250	R R R R
	8004180530* 8004180530* 8004210170 8004210184* 8004220141	50-250 50-250 50-387 50-387 50-387	R R S S G		8004240440* 8004240443 8004240443 8004240443 8004240444	50-250 50-250 50-250 50-250 50-250	R R R R
	8004220239 8004220243* 8004220248 8004220250* 8004220256	50-387 50-389 50-389 50-389 50-389	А К К		8004240444* 8004240444* 8004240448 8004240448 8004240448	50-250 50-250 50-250 50-250 50-250	R R R R
	6004220258 8004220261 8004220264 8004220266 8004220271	50-389 50-389 50-389 50-389 50-389	К К К К		8004240452* 8004240452* 8004240452* 8004240455 8004240455	50~250 50~250 50~250 50~250 50~250	R R R R
	8004220275 8004220279 8004220283 8004220287 8004220276	50-389 50-389 50-389 50-389 50-389	K K K K		8004240455 8004240459* 8004240459* 8004240459* 8004240463	50-250 50-250 50-250 50-250 50-250	R R R R
	8004220298 8004220300 8004220305 8004220306 8004220308	50-389 50-389 50-389 50-389 50-389	K K K K		8004240463 8004240463 800420466# 8004240464#	50-250 50-250 50-250 50-250	R R R
	8004220309 8004220313 8004220317* 8004220321* 8004230321	50-389 50-389 50-389 50-389 50-250	K C C C R				
	8004230321 8004230321 8004230326* 8004230326* 8004230326*	50-250 50-250 50-250 50-250 50-250	R R R R				
	8004230330 8004230330 8004230330 8004230332* 8004230332*	50-250 50-250 50-250 50-250 50-250	R R R R	Florida Pow			
	8004230332* 8004230461 8004230464* 8004230484 8004230484	50-250 50-335 50-335 50-250 50-250	R P R R				
	8004230484 8004230490* 8004230490* 8004230490* 8004230537	50-250 50-250 50-250 50-250 50-335	R R R R				
	8004240030 8004240030 8004240219 8004240309 8004240317*	50-250 50-250 50-389 50-250 50-250	0 0 5 5				

AUTHOR ACCESSION SUBJECT AUTHOR ACCESSION SUBJECT
AFFILTATION NUMBER CATEGORY AFFILTATION NUMBER CATEGORY

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	_	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8004180237 8004180462 8004180464* 8004210111 8004210238	50-302 P 50-302 I 50-302 G 50-302 G	1 []]		800417020* 8004170020* 8004170044 8004170046* 8004170049*	TOPREP 50-324 50-73 50-73 50-73	Р Р Р
	8004210240* 8004220526 8004240467 8004280351 8004280567	50-302 P 50-302 P 50-302 P 50-302 P))		8004170254 8004170257* 8004170260* 8004170287 8004180525*	50-70 50-70 50-70 REB 70-1007	P P P
	8004280548* 8004280571* 8004290480 8004290488* 8004300151*	50-302 F 50-302 F 50-302 S 50-302 S	s 5 6		8004210162# 8004210306# 8004210307# 8004220497 8004230343#	70-1113 TOPREP TOPREP TOPREP 50-219	P
Florida State Univ Florida, Univ of, Gainesville Ford Bacon & Davis Utah, Inc	8004300164* 8004300321 8004100369* 8004220213 8004300219*	50-302 0 50-302 0 CONTRACT 70-1068 WASTE MOT			8004240267 8004240277* 8004240294* 8004250084 8004250284	70-1308 70-1308 70-1308 71-5971 71-5939	
Franklin Institute/Franklin Research Center	8004020241 8004040120* 8004070042* 8004080474 8004080646*	ACRS CONTRACT 50-271 F 50-254 C ACRS			8004280305 8004280311 8004280422 8004280504 8004280507*	70-1308 50-70 50-550 TOPREP TOPREP	P A
Fried, Frank, Harris, Shriver & Kampelman Friends United for Safe Energy Friends of the Earth OTE Sylvania, Inc (subs of General Telephone & Electronics Corp)	8004110500+ 8004020199+ 8004280553+ 800430080+ 8004170323+	90-272 0 COMMISSION 50-320 H 50-387 0 50-317 F	N H G	General Electric Co . Nuclear Energy Products Div	B004300056* B004300056* B004300092* B004300107* B004020143	50-70 50-70 9A999 9A999 71-9019	P P
Oags-Babcock Associates, Inc Gamma Corp Gearhart-Duen Industries, Inc., GQ Wireline Services Div	8004140236 8004210037 8004080650	50-338 F 71-6717 XPORTLIC	±		8004090149 8004090314 8004110109 8004140070* 8004140073*	70-1113 TOPREP PR 70-1308 70-1308	
General Atomic Co (subs of Gulf Dil Co)	8004040479*	QA999			8004140082*	70-1308	
	8004080007 8004080014* 8004170360 8004180480	XPORTLIC XPORTLIC 50-585 / XPORTLIC	A		8004150270 8004150280* 8004140078 8004180121	TOPREP TOPREP PR 70-1113	
General Atomic Co (subs of Gulf Oil Corp)	8004080365#	0A999			8004180124* 8004180133	70-1113 70-1308	
	8004210156 8004210159*	XPORTLIC XPORTLIC			8004180515 8004180515	70-1007 70-1007	
General Electric Co	8004010061 8004010064* 8004010181* 8004010175*	71-9049 71-9049 50-248 70-1308	p		8004180522* 8004180522* 8004220787 8004220790* 8004230163	70-1007 70-1007 71-9019 71-9019 70-1113 TOPREP	
	8004020137# 8004020185 8004020254 8004020467	71-5939 50-70 F TOPREP XPORTLIC	p	General Electric Operating Plant Owners Group	8004270468 8004300052 8004220497*	50-70 TOPREP	Р
	B004020471#	XPORTLIC		General Public Utilities - GPU Service Corp	8004090477	50-320	1
	8004030274 8004030280* 8004040112 8004040326	XPORTLIC XPORTLIC 50-331 F TOPREP	p		6004070482* 8004100354* 8004140250	50-320 50-217 50-320	I I R
	8004040333* 8004040337* 8004070136 8004070317	TOPREP TOPREP 70-2785 50-18		Geo-Centers, Inc Georgia institute of Technology	8004150621 8004280638* 8004230528* 8004230477	50-289 50-320 CGNTRACT 50-160	Q I
	8004070321* 8004070378 8004080031 8004080036* 8004080217	50-18 1 71-380 TOPREP TOPREP 50-183 6	7	Georgia Power Co	8004280486 8004280512 8004010112 8004010321 8004010321	50-160 50-160 50-321 50-321 50-321	8 6 8 8 8
	8004080220# 8004080285# 8004080289# 8004080308 8004080313#	50-183 F 50-18 F 50-18 F 50-73 F 50-73 F	₹ } ₹		8004010326* 8004010326* 8004010349 8004010349 8004010474	50-321 50-321 50-424 50-424 50-321	A R 8 8
	8004080348 8004080359* 8004080635* 8004090059* 8004090072*	50-70 F 50-70 F ACRS GA999 GA999	4		8004010477* 8004020187 8004020315 8004020317* 8004020325	50-321 50-424 50-366 50-366 50-366	8 8 8
	8004090476* 8004090476* 8004100061 8004100082 8004100423	97777 50-293 F PT21 PR 70-754	3		8004020330* 8004020335 8004020335 8004020340* 8004020340*	50-366 50-424 50-424 50-424 50-424	88888
	8004140116* 8004150043	TOPREP RES			8004020345 8004020345 8004020347*	50-344 50-344	8

AUTHOR AFFILIATION	AUCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004020354 8004020359* 8004020361 8004020365* 8004020390	50-321 50-321 50-366 50-366 50-424	ត ថ ភ ភ ភ ភ		6004280447* 8004280452 6004280452 9004280491 6004280491	50-366 S 50-321 Q 50-321 Q 50-424 S 50-424 S
	8004020390 8004020428 8004020437* 8004030227 8004040416	50-424 50-366 50-366 50-321 50-321	ឆេឆេខ		8004280531 8004280566* 8004280570 8004280582 8004280589*	50-364 S 50-321 S 50-321 S 50-321 S
	8004040420 8004040426* 8004040429 8004040438* 8004070198	50-424 50-321 50-366 50-366 50-424	9 5 5 9	Georgia, State of Geotechnical Engineers, Inc Gerlach,F T Getty Oil Co , Petrotomics Co Div	8004110129 8004200239 8004220002 8004070144 8004070155*	PR WASTE MOT FDIA 40-6659 40-6659
	8004070281 8004070283* 8004070314 8004070324* 8004070035*	50-321 50-321 50-366 50-366 50-321	s s s q	Gibson, Dunn & Crutcher Gibert/Commonwealth Cos	8004070159* 8004070164* 8004070169* 8004090208 8004070343*	40~6659 40~6659 40~6659 PROJ 50~320 R
	8004100348 8004110472	50-424 50-366	g S	Gorsuch, Kirgis, Campbell, Walker &	8004090484* 8004300297	50-320 1 WASTE MOT
	8004110476* 8004110477 8004110483*	50-366 50-366	8 8	Graver Government Services, Inc Graham, R L	8004240526* 8004230091 8004230101*	50-344 F 50-347 G 50-347 G
	8004110565 8004110565 8004140336 8004150072*	50-321 50-321 50-424 50-321	9 0 A 9	Grass Roots Organizing Workshop Gulf Dil Corp , Gulf Mineral Resources Co	8004070002 8604070246	FOIA WASTE MGT
	8004150136* 8004150198 8004150198	50-321 50-321 50-321	0 0 0	Ouif States Utilities Co	B004090115 B004010018 B00401001B	WASTE MGT 50-458 G 50-458 G
	8004150358 8004150383 8004150385* 8004150388	50-321 50-366 50-366 50-321	P R R		B004010023 B004010023 B004010041 B004010041 B004040056	50-458 Q 50-458 Q 50-458 Q 50-458 Q 50-458 S
	B004150390# 8004150393 8004150399 B004150404#	50-321 50-366 50-321 50-321	R R R		8004040104 8004040335 8004040363 8004040370	50-458 G 50-458 A 50-458 A 50-458 A
	8004150410 8004150421 8004150425 8004150427	50-366 50-425 50-366 50-424	9 9 9		8004040378 8004180102 8004210182	50-458 A 50-458 A 50-458 I
	8004150427 8004150451 8004150454	50-424 50-366 50-366	8 8 8		8004210182 8004210185* 8004210185*	50-450 I 50-450 I 50-450 I
	8004150455* 8004150460* 8004150476	50-366 50-366 50-366	8 8		8004280539 8004280543*	50-450 R 50-450 R
	8004150481* 8004150562	50~344 50~366	6 9	HEW.Dept of, Food & Drug Administration Hanford Engineering Development Laboratory	8004220028* 8004220677 8004110048	FOIA 50-320 P NUREG
	8004150572# 8004170298 8004170298	50-344 50-321 50-321	6 0 0	Hanse, Holley & Briggs, Inc Harnage,H H	8004040070* 8004080239 8004080239	50-344 T 50-250 G 50-250 G
	8004220615 8004220617# 8004220628	50-346 50-346 50-346	\$ 8 8		8004240086 8004240086	50-250 G 50-250 G
	8004220636* 8004220652 8004220658*	50-366 50-366 50-366	9 9 8	Hartford Electric Light Co Hartford Insurance Group Helix Technology Corp , Process Systems	B004080581* 8004150325* 8004080115* 8004180310*	50-245 I 50-245 I FOIA XPORTLIC
	8004220662 8004220664 8004220667*	50-366 50-366 50-366	8 6	Div	8004180314*	XPORTLIC
	8004220671* 8004220675	50-344 50-321	\$ \$	Hill & Knawlton, Inc Hill Christopher & Phillips Hittman Corp	8004170117* 8004090033 8004220043	COMM188ION 50-275 G 71-379
	8004220484* 8004220689 8004220705 8004220706	50-321 50-321 50-364 50-366	9 9 6 5	Hittman Nuclear & Development Corp (subs Hittman Corp)	B004220055* B004090234	71-979 71-24
	8004220710* 8004220713	50-321 50-321	8 8	Hodder, M H	8004220274 8004020239* 8004020272*	71-6574 50-389 0 50-389 0
	8004220717* 8004220718* 8004220721*	50-366 50-366 50-321	8 8 8	Homestake Mining Co	6004090135 6004300297	WASTE MOT
	8004220726 8004220728 8004220735* 8004220736*	50-366 50-366 50-366 50-366	8 5 8 8	Housetonic Safe Energy Alliance	8004220754 8004220762* 8004030013 8004040243 8004080164*	50-3 G 50-3 G 50-275 U FRM 50-142 U
	8004230467 8004230467 8004240344 8004280416 8004280419* 8004280441	50-321 50-321 50-424 50-366 50-366 50-366	0 0 8 8 8		8004080218* 8004140262* 8004140304* 8004180220* 8004210154	50-387 U 50-358 U 50-309 U COMMISSION PR

AUTHOR AFF)L (ATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
House of Rep , Appropriations House of Rep , Education & Labor	B004220355* B004290146 B004290175 B004140215* B0041401B0*	FOIA 50-275 U 50-556 H 50-10 U 50-10 U		8004140415 8004170312 8004180167* 8004180167* 8004180384	50-445 M 50-445 M 50-445 M 50-445 M 50-478 B
House of Rep , Foreign Affairs House of Rep , Interior & Insular Affairs House of Rep , Merchant Marine & Fisheries	8004140197# 8004300297# 8004080063* 8004080280*	50-10 V 50-3 V COMMISSION COMMISSION 50-320 U		8004180421 8004180423 8004210147 8004210392* 8004210392*	90-498 6 50-498 6 50-445 H 50-445 H
House of Rep , Science & Technology	8004030343 8004090440 8004100449 8004140025 8004180319#	PR PR PR PR COMMISSION		8004210392* 8004210392* 8004210400* 8004210400* 8004210400*	50-445 M 50-445 M 50-445 M 50-445 M 50-448 M
Houston Lighting & Power Co	8004010126 8004010242 8004010332 8004010332 8004010377	50-498		8004210400* 8004220003 8004220763 8004220763 8004220769*	50-445 M 50-466 G 50-498 X 50-498 K 50-498 K
	8004020119* 8004020119* 8004020119* 8004020119* 8004020136	50-445 M 50-445 M 50-445 M 50-445 M 50-478 O		8004220769* 8004230022 8004230074* 8004230074* 8004230074*	50-478 K 50-466 0 50-445 M 50-445 M 50-445 M
	8004020208 8004020232 8004040184 8004040184	50-445 M 50-466 G 90-445 M 50-445 M 50-445 M		8004230074* 8004230154 8004230154 8004230154 8004230154	50-445 M 50-445 M 50-445 M 50-445 M
	8004040240 8004040240 8004040390 8004040390 8004040394	50-498 A 50-498 A 50-498 S 50-498 S 50-498 S		8004240061 8004240061 8004240061 8004240188 8004240538	50-445 H 50-445 H 50-445 M 50-466 0 50-466 0
	8004040394 8004040409* 8004040409* 8004070060* 8004070062	50-498 8 50-498 8 50-498 6 50-498 0 50-498 0	Hunton & Williams ITT General Cantrols, Division of Intl Tel & Tel Corp	8004270378 8004300523* 8004080672 8004250381 8004080521*	50-49B B 50-49B Q 50-33B Q 50-33B Q 50-387 B
	8004080073 8004080073 8004080073 8004080073 8004080273	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	Idaho, State of Idaho, Univ of Illinois Power Co	8004110544 8004110143 8004010249 8004010249 8004010328	State Prop PRM 50-461 A 50-461 A 50-461 F
	8004080273 8004080273 8004080273 8004080285* 8004080285*	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004010328 8004140107 8004140107 8004150170 8004150170	50-461 F 50-461 Q 50-461 Q 50-461 Q
	8004080285* 8004080370 8004080687 8004100078 8004100271	50-445 M 50-445 M 50-466 C 50-466 C 50-445 M	Illinois Safe Energy Alliance Illinois, State of	8004140456 8004020273* 8004030302 8004080181 8004140125	50-10 U 40-2061 FOIA 40-2061 50-367 O
	8004100271 8004100271 8004100271 8004100274 8004100274	50-445 M 50-445 M 50-445 M 50-498 G 50-498 G	Illinois, State of, Dept of Public Health	8004140130* 8004150461 8004230307* 8004250394* 8004170341	50-367 0 50-367 P NUREQ 50-10 H NUREG
	8004100278* 8004100278* 8004100278* 8004100278* 8004100532	50-445 M 50-445 M 50-445 M 50-445 M 50-466 Q	Indiana & Michigan Electric Co.	8004010325 8004010325 8004010420 8004010420 8004010476	50-315 P 50-315 P 50-315 P 50-315 P 50-314 B
	8004100552 8004100552 8004100552 8004100552 8004100557	50-445 M 50-445 M 50-445 M 50-445 M 50-466 G		8004010481* 8004010486 8004010486 8004010493 8004010500*	50-316 B 50-315 F 50-315 F 50-316 B 50-316 B
	8004100560* 8004100560* 8004100560* 8004100560* 8004140003	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004030204 8004070411 8004080304 8004080304 8004080347	50-315 P 50-315 Q 50-315 R 50-315 R 50-316 P
	8004140003 8004140003 8004140003 8004140008* 8004140008*	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004080510 8004080520 8004080529* 8004080534 8004080534	50-316 B 50-316 P 50-316 S 50-315 P 50-315 P
	8004140008* 8004140008* 8004140107	50-445 M 50-445 M 50-498 Q 50-498 Q		8004080544 8004080544 8004080545*	50-315 F 50-315 F 50-314 B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	₹Y		AUTHOR AFFILIATION	NOI88300A RABMUN	CATEGOR SUBJEC	T RY
	8004110445 8004110445 8004110449* 8004110449* 8004140324	50-315 50-315 50-315 50-315 50-315	R R R J			8004100278* 8004100310 8004100322 8004100451 8004100455*	50-155 80-255 50-454 50-155 50-155	0000
	8004140324 8004140438 8004140444* 8004150363 8004150365*	50-315 50-315 50-315 50-314 50-314	5 8 8 8			8004100570 8004110030 8004160161 8004210401 8004210420	50-155 50-445 50-556 50-155 50-155	6 H G G
	8004150368 8004150371* 8004150507 8004150507 8004150509	50-315 50-315 50-315 50-315 50-315	R R F P			8004220128 8004220334 8004230002 8004250372 8004280018	50-445 50-556 50-445 50-556 50-155	M Q M Q F
	8004150509 8004150510* 8004150510* 8004180181* 8004210415	50-315 50-315 50-315 50-315 50-315	P F G P	Island Closeup News Service Isomedix, Inc. (subs. of Maesfield Enterprises, Inc.) Isotope Products Laboratories Israel J H. Kleinfelder & Associates Jack R. Benjamin & Associates, Inc. Japan Jersey Central Power & Light Co	8004270087 8004270164 8004070220 8004170183	FOIA FOIA 71-9		
	8004230351 8004230355* 8004230357* 8004230430 8004230432*	50-314 50-316 50-316 50-316 50-316	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8004110117 8004110023* 8004040153* 8004070026 8004010480 8004010485*	XPORTLIC XPORTLIC CONTRACT 90-70 XPORTLIC 50-219	; T P ;	
	8004230438 8004230444* 8004230447* 8004280398 8004280398	50-315 50-315 50-315 50-315 50-315	8 9 9 0 0			8004010503 8004010509* 8004020006 8004020319 8004020320*	50-219 50-219 50-219 50-363 50-219 50-219	8 8 9 P
Indiana & Michigan Power Co Industrial Dynamics	8004290417 8004300611 8004300611 8004230369 7905190090	50-315 50-315 50-315 50-315 MISC	S Q Q F			8004020383 8004020386* 8004040284 8004040288* 8004080421	50-219 50-219 50-219 50-219 50-219	R R R B
Interior,Dept of Interior,Dept of, Burgau of Land Management Interior,Dept of, Fish & Wildlife Service Interior,Dept of, Geological Survey	8004010104 800407023B 8004290070 8004030003* 8004010106*	27-39 40-4492 40-1341 40-8745 27-39				8004090246* 8004090329 8004090330* 8004090482* 8004100352	50-217 50-217 50-217 50-220 50-217	9 P 1
International Business Services, Inc International Verbatim Reporters, Inc Iowa Electric Light & Power Co	8004020283 8004280218 8004080241* 8004040235 8004030160	50-275 PR CONTRACT 50-320 50-331	A T R			8004100355# 8004100424 8004110422 8004160276 8004220508	50-219 50-219 50-219 50-219 50-219	1 Q Q P P
	8004030161* 8004040400 8004040413* 8004070252 8004070256*	50-331 50-331 50-331 50-331 50-331	R G S R R			8004220511* 8004220514* 8004230341 8004240425 8004240432*	50-219 50-219 50-219 50-219 50-219	P P R R
	8004080531# 8004080531# 8004080605 8004090447 8004140363	50-331 50-331 50-331 50-331	8 8 8	(subs John F	Blume & Associates, Engineers URB Corp) Holman & Co , Inc Controls, Inc	8004280513 8004090394* 8004100342* 8004080262*	50-219 50-255 CONTRACT GA999	P
	8004140367* 8004140382* 8004140382* 8004140450 8004140452*	50-331 50-331 50-331 50-331 50-331	8 P P 8 9	Jones, i Justica				
	8004150340 8004160005 8004220268 8004220385 8004220387*	50-331 50-331 50-331 50-331	8 G F R R					
	8004220507 8004230346 8004230348* 8004280454 8004280461	50-331 50-331 50-331 50-331 50-331	P R R F P					
lowar State of Isham. Lincoln & Beale	800403013B 8004220519 800402027B 8004080153 8004080180	PR 50-331 50-155 50-445 50-155	Р О Н О					
	8004080186# 8004080191 8004080340 8004080428 8004090387	50-155 50-155 50-445 50-454 50-445	о н с н					
	8004070387 8004070411 8004100273 8004100276*	50-445 50-454 50-155 50-155	M G G					

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'	
	8004080033* 8004080033* 8004080033* 8004080559	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M		8004010347* 8004070308 8004070310* 8004150420 8004150424*	50-382 50-382 50-382 50-382 50-382	9 9 8 A A
	8004080559 8004080559 8004090204 8004090204 8004090204	50-445 M 50-449 M 50-445 M 50-445 M 50-445 M	Lowenstein Newman, Reis, Axelrad & Toll	8004280594 8004280405* 8004020092 8004020113 8004020113	50-382 50-382 50-367 50-445 50-445	8 0 M M
	8004070204 8004090475* 8004100084 8004100177 8004100218	50-445 M 50-293 M 50-445 M 50-445 M 50-445 M		8004020113 8004020113 8004020119* 8004020119* 8004020119*	50-445 50-445 50-445 50-445 50-445	H H H
	8004110056 8004110056 8004110056 8004110056 8004110137*	50-445 M 50-445 M 50-445 M 50-445 M 50-482 M		8004020136 8004020225 8004020232 8004020265* 8004020280	50-498 50-344 50-466 50-389 50-367	0 0 0
Justice.Begt of, Attorney General's	8004170340 8004210437 8004210447 8004250375 8004030207	50-445 M 50-445 M 70-1308 50-514 G 50-482 M		8004040198 8004040198 8004040198 8004040198 8004040198	50-367 50-445 50-445 50-445 50-445	0 Н Н
Office K F Industries, Inc. KMC, Inc.	8004140104* 7908210253* 7907250258 8004250071	50-443 M 50-320 H MISC PR		8004080073 8004080073 8004080073 8004080273 8004080273	50-445 50-445 50-445 50-445 50-445	M M M
Kansas Oas & Electric Co	8004010030 8004010034 8004040264 8004070292 8004170172	50-482 G 50-482 S 50-482 S 50-482 S 50-482 S		8004080273 8004080285* 8004080285* 8004080285* 8004080370	50-445 50-445 50-445 50-445 50-445	н н н н
Kansas, Univ of Kay-Ray, Inc	8004220747* 8004220757* 8004240051* 8004080332 8004070151	50-482 I 50-482 I 50-482 I CONTRACT XPORTLIC 40-2041		8004070439 8004070439 8004070439 8004070439 8004100271	50-445 50-445 50-445 50-445 50-445	H H H
Kerr-McGee Corp Kerr-McGee Nuclear Corp Kriemlmager,H	8004080163* 8004180061 8004210348 8004080158 8004090279*	40-2061 40-2061 40-2061 40-2061 50-320 H		8004100271 8004100271 8004100278* 8004100278* 8004100278*	50~445 50~445 50~445 50~445 50~445	Н Н Н
LaMacchia, P J Lake Michigan Federation Lakeside Bridge & Steel Co Laudig, B Laurence Livermore Laboratory	8004290113* 8004230028 8004030237* 8004150219 8004030002	CONTRACT 50-347 G GA999 FOIA NUREG		8004110529 8004140003 8004140003 8004140003 8004140008*	50-250 50-445 50-445 50-445 50-445	о н н н
LeBoeuf, Lamb, Leiby & MacRao	8004240445 8004250046 8004280059 8004010060 8004110480	RES TOPREP RES FOIA PR		8004140008* 8004140008* 8004160111 8004160111	50-445 50-445 50-445 50-445 50-445	Н Н Н
League of Women Voters of Rockford, IL	8004150329 8004220464 8004250052 8004020033	50-244 P 50-220 P NUREG 50-454 0		8004210147 8004210386 8004210386 8004210386 8004210386	50-445 50-445 50-445 50-445 50-445	н н н
	8004020033 8004080435* 8004080435* 8004090177	50-454		8004210372* 8004210372* 8004210372* 8004210377* 8004210400*	50-445 50-445 50-445 50-445 50-445	н н н
League of Women Voters of San Luis Obispo.CA Leed.R M Leesburg.FL	8004140419 8004140112 8004180491*	PR PR 50-302 I		8004210400* 8004210400* 800422003 8004220141	50-445 50-445 50-466 50-387	K H 0
Lehigh Üniv Lockheed Center for Marine Research Logical Technical Service Corp	8004040027 8004070352* 8004100194*	RES 50-206 R CONTRACT		8004230022 8004230066 8004230066	50-445 50-445 50-445	9 8
Long Island Lighting Co	8004040314 8004070117* 8004070004 8004140439	50-322 A 50-322 Q 50-322 Q 50-322 A		8004230066 8004230066 8004230074*	50-445 50-445 50-445	H H
Los Alamos Scientific Laboratory	8004220036 8004220620 8004080007 8004150140 8004150141*	50-516 Q 50-322 A 71-9029 NUREO NUREO		8004230074* 8004230074* 8004230105 800424018B 8004240194	50-445 50-445 50-367 50-466 PRM	9
Louisiana Power & Light Co	8004240475 8004240475 8004240001 8004290520 8004010343	NUREG NUREG WASTE MOT 50-382 8	Lower Alloways Greek, NJ Luzerne County,PA	8004240484 8004250104 8004100466 8004100583 8004140096	50~250 50~445 50~311 50~311 PR	0 H O

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
MHB Technical Associates Haine Voice of Energy Haine Yantee Atomic Power Co	8004140100* 8004210393* 8004080653* 8004020016 8004020345	50-275 G 50-309 H 50-309 Q 50-213 P		6004040335 6004040335 6004040344* 6004040344*	50-320 S 50-320 S 50-320 S 50-320 S 50-320 S
	8004080263 8004080339 8004080351 8004080406 8004080411*	50-309 0 50-309 H 50-309 Q 50-309 R 50-309 R		8004040349* 8004070219 8004070219 8004070284 8004070285*	50-320 S 50-320 0 50-320 0 50-289 P 50-289 P
	B004080634 B004090458 B004100406 B004100422 B004140154	50-309 P 50-309 Q 50-309 Q 50-309 Q 50-309 R		8004070290 8004070291* 8004070301 8004070306* 8004070318	50-289 P 50-289 P 50-320 P 50-289 P 50-320 P
	6004140157* 8004140308 8004150290 8004150347 8004150370#	50-309 R 50-309 P 50-309 I 50-309 R 50-309 R		8004070318 8004070319 8004070323* 8004070325* 8004070335	50-320 P 50-289 P 50-289 P 50-289 P 50-320 R
	6004180438 6004180489 6004180492* 8004210044* 8004210277	50-309 P 50-309 S 50-309 S 50-309 G 50-309 G		8004070335 8004070339* 8004070416* 8004070420* 8004080200*	50-320 R 50-320 R 50-287 0 50-287 G
	8004210278* 8004220522 8004220530* 8004230005 8004280562	50-309 S 50-309 P 50-309 P 50-309 Q 50-309 R		8004080425 8004080560 8004080703 8004080707* 8004080716*	50-289 P 50-289 P 50-289 P 50-289 P 50-289 P
Maine, State of Marchand Construction, Inc Marina Biological Consultants, Inc ,	8004080674 8004280564# 8004290514# 8004020458# 8004070348#	PR 50-309 R CONTRACT 50-320 H 50-206 R		8004080720 8004070013 8004070096 8004070283* 8004070275*	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0
Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div	8004010323 8004080281 8004080485 8004140346 8004140442	50-18 J 50-250 J 50-348 J 50-344 J 50-327 J		8004070482# 8004070482# 8004070482# 8004100010 8004100015#	50-320 I 50-320 I 50-320 I 50-289 G 50-289 G
Marvin Engineering Co , Inc	8004280447 8004270176* 8004270186* 8004020176* 8004040375	50-250 J 9A797 9A797 8tate Prog 50-320 P		8004100285* 8004100308 8004100350 8004100350 8004100435	50-289 G 50-289 G 50-320 F 50-320 F 50-289 G
Maryland, Univ of Massachusetts Institute of Technology	8004100079 7708020467 8004020050 8004010415 8004010422#	PR 50-146 H 50-146 H REB RCB		B004100436# B004100437# B004100479 B004100549 B004100566	50-289 G 50-289 G 50-289 G 50-289 G 50-289 G
Hatheson Gas Products Hatthews, Nowlin, Macfarlane & Barrett	8004250043# 8004210426 8004070421 8004100442 8004100442	CONTRACT XPORTLIC 50-498 M 50-498 M 50-498 M		8004110029 8004110081* 800 800	50-289 G 50-289 G
Mayer, Brown & Platt	8004100444* 8004100444* 8004100447* 8004100447* 8004140060	50-498 M 50-498 M 50-498 M 50-499 M 70-1308		ſ	
McCutchen, Doyle, Brown & Emerson McGrath, E. J	0004140078 9004280305 8004080012 8004080132 8004300215	70-1308 70-1308 PROJ PROJ WASTE MOT			
Metal Bellows Corp Methodist Medical Center of Illinois Peoria, IL	8004180088 8004180089* 8004180092* 8004220616*	XPORTLIC XPORTLIC XPORTLIC FOIA			
Metropolitan Edison Co	8004010338	50-289 S			
	8004010344 8004010412 8004020012 8004020056 8004020202	50-320 P 50-289 P 50-320 B 50-287 Q 50-289 Q			
	1450E0400B 1450E0400B 1E5040400B 40E040400B B1E040400B	50-320 I 50-320 I 50-320 P 50-320 P 50-320 P			
	8004040321 8004040325 8004040330	50-320 P 50-320 P 50-320 P			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEQURY
	8004150436 8004150446 8004150446 8004150478 8004150479	50~320 P 50~320 P 50~320 P 50~320 H 50~320 G	Mississippi Power & Light Co	8004090254 8004090341 8004090341 8004090345* 8004090345*	REGGD 50-416 A 50-416 A 50-416 A 50-416 A
	8004150499 8004160179 8004160184* 8004160290 8004160298*	50~320 G 50~320 P 50~320 P 50~320 P 50~320 P		8004100362 8004100437 8004100541 8004150200* 8004150200*	50-416 H PR REGOD 50-416 M 50-416 M
	8004170023 8004170039 8004170048 8004170104 8004170106*	50-320 P 50-320 P 50-320 P 50-287 P 50-289 P		8004190568 8004190568 8004170071 8004170071 8004170074*	50-414 8 50-414 8 50-414 8 50-416 8 50-416 8
	8004170281* 8004180338 8004180339* 8004180473 8004210085	50-287 0 50-320 R 50-320 R 50-287 0 50-320 G		8004170074* 8004170243 8004170243 8004210228 8004220289	50-416 8 50-416 A 50-416 A 50-416 C
	8004210250* 8004210421 8004220008 8004220102 8004220223	50-289 0 50-289 0 50-320 0 50-320 0 50-289 P		8004220287 8004220293* 8004220293* 8004220421 8004220421	50-416 C 50-416 C 50-416 C 50-416 C
	8004220224* 8004220393 8004220405 8004220542 8004220545*	50-287 P 50-320 Q 50-320 Q 50-287 P 50-289 P		8004230070 8004230322 8004230322 8004280365 8004280365	50-416 0 50-416 0 50-416 K 50-416 K
	8004220552* 8004220654 8004230001 8004230030 8004230406	50-289 P 50-289 P 50-289 G 50-289 G 50-289 S		8004280371# 8004280381# 8004280381# 8004280481	50-416 K 50-416 K 50-416 K 50-416 S
	8004230411* 8004230493 8004230495* 8004240379 8004250356	50~287 \$ 50~287 R 50~320 P \$0~320 P		8004280484 8004280484 8004280499 8004280499 8004280501	50-416 8 50-416 8 50-416 8 50-416 8
	8004250360 8004250367 8004250377 8004250369* 8004250433	50-320 Q 50-287 P 50-320 S 50-320 S 50-320 P		8004280501 8004280517 8004280517 8004280520 8004280520	50~416 8 50~416 8 50~416 8 50~416 8
	8004280633% 8004280633% 8004280633% 8004290510 8004300409	50-320 I 50-320 I 50-320 I 50-320 S 50-320 F		8004280522* 8004280522* 8004280541 8004280541 8004280606	50-414 8 50-414 8 50-414 8 50-414 8
Miami Valley Power Project Miami, FL, Univ of Michigan State Univ	8004300586* 8004090157 8004020239* 8004020272* 8004010227	50-289 Q 50-358 H 50-389 Q 50-389 Q 50-294 P		8004280606 8004280610 8004280610 8004280618* 8004280618*	50-416 8 50-416 8 50-416 8 50-416 8
Michigan, State of	8004010229* 8004160039* 8004240479* 8004020237* 8004090368*	50-294 P 50-320 P 50-320 P State Prog 50-416 M	Missouri, Univ of, Columbia Missouri, Univ of, Rolla Mitsui & Co , Ltd Mobile Systems Mansanto Research Corp	8004300805 8004270085* 8004180242 8004030014* 8004030354	70-754 50-123 Q XPORTL1C CQNTRACT 71-9142
Hichigan, Univ of	8004150531* 7704110103 B004030300 B004040385 8004040389*	50-315 P 50-2 P ACRS 50-2 P 50-2 P	Montana, Univ of Morgan, Lewis & Bockius Kurphy & Parish NL Industries, Inc	8004030359* 8004030307 8004070303 8004100471 8004080148*	71-9142 FOIA 50-409 P 50-352 H FOIA
Middle Bouth Utilities.Inc Mike Auer Construction Co Miller.Balis & O'Neil	8004220835 8004020275* 8004240043 8004240043 8004240043	50-313 1 40-2061 90-445 M 50-445 M 50-445 M	NL Industries, NL Nuclear Div NUS Corp	8004080069 8004140010 8004220225 8004280166 8004070347*	XPORTLIC XPORTLIC 71-9010 71-9010 50-320 R
	8004240045 8004240045 8004240045 8004240045 8004240053	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	NUBAC, Inc National Wildlife Federation Natural Resources Defense Council	8004100465* 8004090485* 8004020053 8004070181 8004100299	50-155 Q CUNTRACT 40-4492 40-4492 70-143
Minnesota, State of	8004240053 8004240053 8004070156 8004210160# 8004230088	90-445 M 90-445 M PR PR 50-282 Q	Navy.Dept of	8004150101 8004210352 8004270184 8004150278* 8004150284*	50-574 0 70-143 FOIA 71-49 71-49
Minnesota, Univ of, Minneapolis	8004230088 8004230100 8004230100 8004080713 8004100343*	50-282 0 50-282 0 50-282 G FOIA CONTRACT	Navy Dept of Naval Nuclear Power Unit	8004210357* 8004300082 8004150099 8004150102* 8004150108*	70-143 71-9043 71-273 71-273 71-273

AUTHOR AFFILTATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004150112 8004150117* 8004150121* 8004150123 8004150125*	71-367 71-367 71-367 71-116 71-116	Nissho-Iwai American Corp Nondestructive Inspection Service	8004300270* 8004240170* 8004240202* 8004150132 8004150133*	50-410 0 70-2805 70-2805 71-97 71-97
	9004150127* 9004150272 9004240314 9004240322* 9004240331*	71-116 71-49 71-107 71-107 71-107	North Carolina State Univ	8004220558 8004220560* 8004220565* 8004140455 8004150171*	50-111 R 50-111 R 50-111 R NUREO CONTRACT
Navy,Dept of: Naval Research Laboratory Nabraska Public Power District	8004270007 8004010454 8004010457* 8004040396	NUREG 50-298 R 50-298 R 50-298 R	Northcutt Ely Northeast Nuclear Energy Co (subs of Northeast Utilities)	8004080018 8004090427 8004020331	50-445 M 50-445 M 50-245 P
	E004090303 E004090304*	50-298 R 50-298 R		B004030232 B004030270*	50-336 P 50-336 P
	8004140479 8004230192 8004230457 8004250077	50-278		8004100408* 8004110457 8004110443* 8004140375 8004150409*	50-423 S 50-245 P 50-245 P 50-245 Q 50-245 I
	8004250240 8004250391 8004280184 8004280186* 8004280574	REGGD 50-278 F 50-278 G 50-278 G 50-278 B		8004160254 8004160254 8004160254 8004170012 8004170012	50-245 J 50-245 J 50-245 J 50-213 P 50-213 P
Nebraska, State of Neutron Products, Inc	8004280579* 8004110127 8004230417 8004090119 8004090121*	50-298 S REGOD NUREG 71-121 71-121		8004180383 8004180388* 8004180398 8004180404*	50-245 R 50-245 R 50-336 S 50-336 S
Nevada, State of	B0040B0459 B004240077	PR State Prog		8004220364	50-336 P 50-336 R
New England Medical Center Boston,MA New Hampshire, State of	8004240081* 8004080213* 8004070187	State Prog 70-2254 PR		8004220413* 8004220670 8004220679* 8004230413	50-334 R 50-336 S 50-336 S 50-423 A
	8004070202* 8004100604 8004100607* 8004100612* 8004170284	PR PR PR PR PR		8004240373 8004250362 8004280525 8004290057 8004290651	50-245 P 50-245 P 50-336 S 50-245 Q 80-245 P
New Jersey, State of	8004080433 8004070005 8004070008* 8004140108 8004140147	50-272 0 50-272 0 50-272 G PR PR	Northoast Utilities	8004010407 8004010417* 8004010423 8004010429* 8004020408	50-336 S 50-336 S 50-336 S 50-336 S 50-213 F
New Mexico, State of	8004210140 8004020159 8004020182 8004020196 8004070240	PR WASTE MOT WASTE MOT WASTE MOT WASTE MOT		8004020408 8004020408 8004030215 8004030261	50-213 F 50-213 F 50-245 P 50-213 Q
New York Univ New York, State Univ of, Buffalo New York, State of	8004180298* 8004010007* 7905170094 8004020144* 8004080152	COMMISSION CONTRACT 50-57 P ACRS PR		8004030293 8004040205 8004040206* 8004040206*	50-245 R 50-245 R 50-245 R 50-245 R
New York, NY	8004100083 8004100443 8004100448 8004230190* 8004070098*	PR PR 50-244 F 50-3 H 50-3 P		8004040254* 8004040304 800404070218* 8004070265	50-336 P 50-245 P 50-245 Q 50-213 P
Niagara Mohawk Power Corp	8004210073# 8004010330 8004010373 8004010372 8004040404	50-3 H 50-220 P 50-220 G 50-220 G 50-220 R		8004070265 8004080309 8004080557 8004090311* 800409046	50-213 P 50-334 P 50-245 I 50-334 S 50-334 S
	8004070269 8004080415 8004080642 8004090239 8004090309	50-220 F 50-220 Q 50-220 Q 50-220 Q PR		9004100417 9004140127 9004150320 9004150320 9004150379	50-336 0 50-245 0 50-245 1 50-245 1 50-213 J
	9004100401 9004110055 9004140406 9004140411* 9004190345	50-220 Q 50-220 Q 50-220 R 50-220 R 50-220 F		8004170194 8004170199* 8004170224 8004170226* 8004180408	50-334 8 50-334 8 50-334 8 50-334 8 50-334 8
	8004180349* 8004210407 8004220301* 8004220306* 8004220559	50-220 F 50-220 P 50-220 P 50-220 P 50-410 S		8004180411* 8004180497 8004180440* 8004210246 8004210249*	50-334 8 50-245 8 50-245 8 50-245 R 50-245 R
	8004220977* 8004250419 8004280396 8004280440 8004270363	50-410 8 50-410 A 50-410 H 50-220 H 50-220 H	Northeast Utilities Service Co	8004280530* 8004290299 8004290303* 8004020418*	50-336 8 50-245 S 50-245 S 50-213 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE(CATEQ(
	8004020418* 8004020418* 8004150327 8004150327 8004150493*	50-213 50-213 50-245 50-245 50-213	F	Nuclear Energy Service, Inc Nuclear Fuel Services, Inc (subs of Getty Oil Co)	80040801179 80040903769 80040400419	50-409 70-143	р
Northern Illinois Univ Northern Indiana Public Service Co	8004280346* 8004020092 8004040053 8004080331 8004150453	50-10 50-367 50-367 50-367 50-367	H O G R R		8004070422 8004070235* 8004070237* 8004100219* 8004140024	70-143 70-143 70-143 50-201 71-249	q
Northern States Power Co	8004220553 8004280494 8004300431 8004010151 8004010452	50-367 50-367 50-367 50-306 50-263	R R R Q S		8004150062 8004150071* 8004180096 8004180149	50-201 50-201 50-201 70-143	R R P
	8004010455• 8004040319 8004040456 8004070058 8004070058	50-263 50-263 50-282 50-282 50-282	\$ Q Q		8004180213 8004180482 8004210178 8004220081 8004220133 8004220217	70-143 70-143 70-143 70-143 70-143	
	8004070210 8004070210 8004080225 8004080368 8004080373	50-282 50-282 50-282 50-243 50-263	Q F F P		B004220217 B004230053 B004230060* B004300024* B0043000B5	70-143 50-201 50-201 70-143 70-143	R R
	8004080400 8004080478 8004080479 8004080484*	50-243 50-282 50-263 50-282	P 8 F 8	Nuclear Medicine Associates,Inc Cleveland,DH Nuclear Packaging, Inc	8004230032*	70-143 F01A 71-9130	
	8004080508 8004090223 8004100070* 8004140339	50-263 50-263 50-282 50-282	F Q	Nuclear Pharmacy, Inc	8004220187* 8004220193* 8004070362	71-9130 71-9130 71-9130 FOIA	
	8004140337 8004140344* 8004140390 8004140431	50-262 50-263 50-263	R R S S	Nuclear Services Corp Nuclear Systems, Gamma Industries Div Oak Ridge National Laboratory	8004290173 8004280624* 8004280627* 8004020025 8004030291	FDIA 50-255 50-255 71-9135 ACRB	F F
	8004140435 8004140437* 8004140440* 8004150339	50-282 50-282 50-282	8 8 8		8004040369 8004070145 8004100398 8004100411	REB REB REB	
	8004150401 6004150405* 8004150843 8004150555*	50-263 50-263 50-263 50-263	R 8 8		8004110466 8004150029 8004150036 8004160088	TOPREP RES RES RES	
	8004150554* 8004150571* 8004150580* 8004150587 8004150589*	50-263 50-263 50-263 50-282 50-263	80 80 80 80 80 80 80 80 80		8004160095 8004170329 8004170336 8004230303* 8004240487	RES NUREO NUREO NUREO	
	8004150598* 8004150603* 8004150610* 8004150617*	50-263 50-282 50-263 50-263	***************************************	Ocean County, NJ	8004280024 8004280028 8004280048	REB NUREO NUREO	
	8004150623# 8004160013 8004170056 8004170056		9 r F	Ogle Petroleum, Inc	8004110535 8004210446 8004030001 8004240563	PR PR 40-8745 40-8745	
	8004170059* 8004170059* 8004180296 8004180307*	50-282 50-282 50-306	F 0	Ohio Edison Co Ohio State Univ Oklahoma State Univ	8004080497 8004080502# 8004080070# 8004230514 8004080080#	50-334 50-334 50-150 50-320 FOIA	1 1 1 H
	8004180341 8004180342* 8004180342* 8004180357	50-282 50-282 50-282	6 6 6	Oklahoma, State of Omaha Public Power District	8004280030 8004010346 8004140021 8004140362	50-556 50-265 50-265 50-265	0 P 0 P
	8004180360* 8004180380 8004180386*	50-263 50-306 60-03 60-03	F 9 8 8	Omnidine Carp	8004150391 8004150395* 8004220561 8004250086	50-285 50-285 50-285	R R P G
		50-282 50-282 50-282	8 8 9 9	Oncavage, Mark	8004020179# 8004080239 8004080239 8004080550	50-250 50-250 50-250	0 0 0
		50-282 (50-282 (Q Q P	Oragon, State of Orlando,FL	8004240084 8004240086 8004270500	50-250 50-250 50-514	O D
	,	CONTRACT XPORTLIC PR	a	Gsann, E W PRC Systems Services Co	8004180474* 8004180478* 8004230091 8004230101* 8004240389*	50-302 50-302 50-347 50-367 50-275	1 0 0 F
		71-6698 MISC		PSE & Q Research Corp PWR System Div PA/PI Pacific Gas & Electric Co	8004080394* 8004290066 8004010436	50-272 50-518 50-275	p B A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004010437 8004010441# 8004010441# 8004030317 8004040058	50-275 A 50-275 A 50-275 A PROJ PROJ		8004070186 8004070478* 8004070479* 8004070480* 8004070481*	PR 50-320 1 50-320 1 50-320 1 50-320 1
	8004040065* 8004040068* 8004040131 8004040281 8004040281	50-344 T PROJ 50-275 S 50-275 A 50-275 A		8004100539 8004140074 8004140077* 8004140080* 8004140084*	50-289 Q 50-289 Q 50-289 Q 50-289 Q
	8004080012 8004080132 8004080443 8004080443 8004080447	PROJ PROJ 50~275 A 50-275 A 50-344 P		8004140268 8004210453 8004270092 8004270095* 8004270101*	50-387 A 50-289 Q 50-334 T 50-334 T
	8004080464 8004080481 8004080487* 8004100233 8004100233	50-275 A 50-133 S 50-133 S 50-133 I 50-133 I	People Against Nuclear Energy Personnel Assessment & Selection Service Inc	8004160138* 8004280026 8004170139	50-289 Q 50-289 Q FOIA
	8004100233 8004100244# 8004150003	50-133 I 50-133 I 50-133 9	Paterson, Ross & Schloerb & Seidel Philadelphia Electric Co	8004070176 8004010406 8004070270 8004070270	50-320 P 50-277 P 50-277 R 50-277 R
	8004150337 8004150337 8004150343	50-275 A 50-275 A 50-275 A		8004070271* 8004070271* 8004070311	50-277 R 50-277 R 50-278 S
	6004150343 8004150435 8004150441* 8004160253	50-275 A 50-275 A 50-275 A 50-275 A		8004080347 8004080347 8004080538 8004080538 8004080543	50-277 P 50-277 P 50-277 P 50-277 P 50-277 P
	8004140253 8004140254* 8004140259* 8004140240* 8004140244*	50-275 A 50-275 A 50-275 A 50-275 A 50-275 A		8004080543 8004080543 8004100211 8004100261 8004100421	50-277 P 50-277 P 50-277 Q 50-171 Q 50-352 Q
	8004160267* 8004160271* 8004170076 8004170233 8004170236*			8004140044 8004140273 8004140317 8004140317* 8004150246	50-277 0 50-277 P 50-352 I 50-352 I 50-277 I
	8004220406 8004220692 8004220697* 8004220697* 8004220704*	50-275 A 50-275 A 50-275 A 50-275 A 50-275 A	•	B004150250* 8004150267 8004150470 8004150470 B004150560	50-277 I 50-171 I 50-277 I 50-277 I 50-277 B
	B004220704* B004220716* B004220716* B004220727* B004220727*	50-275 A 50-275 A 50-275 A 50-275 A 50-275 A		8004140187* 8004170228 8004170228 8004170230* 8004170230*	50-277 Q 50-277 R 50-277 R 50-277 R 50-277 R
	8004220737* 8004220737* 8004220744* 8004220744* 8004220751*	50-275 A 50-275 A 50-275 A 50-275 A 50-275 A		8004170246 8004170246 8004170252* 8004170252*	50-277 P 50-277 P 50-277 P 50-277 P
	8004220751 * 8004220755* 8004220755* 8004240384 8004240384	50-275 A 50-275 A 50-275 A 50-275 F 50-275 F			
Pan American Horld Airways, Inc Par Systems Corp	8004280373 8004180062 8004180067* 8004040141 8004040152*	50-275 A 71-96 71-96 XPORTLIC XPORTLIC			
Pathfinder Mines Corp Pennsylvania Power & Light Co	8004020291 8004270444 8004070382* 8004080363 8004080514	40-2259 40-6622 50-387 0 50-387 8 50-387 8			
	8004100098* 8004140352 8004210335 8004290394 8004290394	50-387 Q 50-387 A 50-320 P 50-387 S 50-387 S			
	8004270377* 8004270377* 8004300374 8004300374 8004300383*	50-387 8 50-387 8 50-387 8 50-387 6 50-387 8			
Pennsylvania Power Co Pennsylvania, State of	8004300383* 8004070297 8004070298* 8004070426 8004070015*	50-387 B 50-334 I 50-334 I 50-334 Q 50-320 P			

AUTHÚR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Pittsjurgh. Univ of Plateau Resources, Ltd Pollution b Environmental Problems. Inc Pollution Environmental Problems	B004040386* B004150074 B004280064 B004010171 B004150031	50-458 NUREQ 40-8698 FOIA 50-268	A		8004180434* 8004180448 8004180461* 8004210061* 8004220445	50-284 R 50-286 S 50-286 S 50-286 Q 50-333 Q
Porter-Gert: Consultants, Inc	8004280590 8004140420 8004250395 8004010008 8004010334	50-295 50-320 50-320 50-344 50-344	G R R G P		8004220741 8004220749* 8004220767 8004220771* 8004220787	50-286 S 50-286 S 50-333 S 50-333 S 50-286 Q
	8004020225 8004020409 8004030240 8004030243* 8004040063	50-344 50-344 50-344 50-344 50-344	G P P F		8004280552 8004280559# 8004290476 8004290482* 8004290504	50-333 S 50-333 S 50-333 S 50-333 S
	8004040073* 8004080388 8004080442 8004080446* B004080506	50-344 50-344 50-344 50-344 50-344	T P R R		8004290511* 8004300041 8004300044* 8004020484	50-333 B 50-286 Q 50-286 Q XPORTLIC
	8004080509* 8004080542 8004100273* 8004100457 8004150440	50-344 50-344 50-344 50-344 50-344	P G G P 8		8004030335 8004070077* 8004140026* 8004140097* 8004140190* 8004210031*	50-327 H 50-155 H 50-337 H 50-339 H 50-337 H
	8004150442* 8004180359 8004180361 8004180362*	50~344 50~514 50~344 50~344	9 F P	President's Comm for Study of Ethical Prob in Med & Biome & Behav Resvarch	8004300406* 8004100127*	COMMISSION 50-3 F
	8004180364*	50-514	F	Public Interest Law Center of Philadelph ia	8004170239	50-320 P
	8004180366# 8004180466 8004180467#	50-344 50-344 50-344	P P P		8004250378 8004290289	50-320 P 50-320 P
	8004180470* 8004220695 8004280296 8004290471	50-344 50-344 50-344 50-344	P P B	Public Service Co of Colorado	8004230466 8004010450 8004030130 8004030131*	50-458 M 50-247 P 50-247 Q 50-247 Q
Potomac Alliance	8004270478* 8004200380 8004300387 8004280211	50-344 50-344 50-344 50-338	S P Q	•	8004030132* 8004030133* 8004030134* 8004030136* 8004070286	50-247 Q 50-247 Q 50-247 Q 50-247 Q 50-247 P
Pawer Authority of the State of New York	8004010259 8004010367 8004020219 8004030216	50-333 50-333 50-333 50-333	P P J		8004080379 8004080422 8004080427* 8004080503	50-267 F 50-267 8 50-267 8 50-267 8
	8004030218* 8004030247 8004030273 8004030278* 8004070296	50-333 50-286 50-333 50-333 50-333	9 9 8 8		8004080512* 8004150333 8004150336*	50-267 B 50-267 R 50-267 R
	8004070300* 8004080124* 8004080266*	50-333 FOIA 50-333	R R G		8004150338 8004150432 8004150438* 8004150542	50-247 S 50-247 S 50-247 S
	8004080328 8004080381 8004080419 8004080473	50-286 50-286 50-333 50-333	G G P		8004150552* 8004150582 8004150611* 8004150626 8004150634*	50-247 8 50-247 8 50-247 8 50-247 8 50-267 6
	8004090632 8004090125 8004090318	50-286 50-333 50-333	Q Q R		8004210166* 8004210268 8004210271* 8004210294	50-267 Q 50-267 R 50-267 R 50-267 B
	8004070354 8004070436 8004070440# 8004070452	50-286 50-333 50-333 50-333	0 8 0		8004210276* 8004210354 8004220775 8004220778* 8004240323	50-267 8 50-267 0 50-267 I 50-267 I 50-267 B
	8004110437 8004110442* 8004140398 8004140414	50-286 50-286 50-333 50-286	8 8		800424032B* 8004240469 8004290390 8004080160	50-267 B 50-267 Q 50-267 Q 50-546 A
	8004140422* 8004150364 8004150458 8004150508 8004170061	50-286 50-333 50-286 50-333 50-286	S P G S		8004080168* 8004090146* 8004100291* 8004100291*	50-546 A 50-546 Q 50-546 G 50-546 Q
	B004170064 B004180343 B004180350	50-333 50-286 50-286	P P		8004100371 8004110556# 8004110556#	50-546 Q 50-546 Q 50-546 Q
	8004180389 8004180389 8004180389 8004180395#	50-247 50-247 50-247 50-247	P P P		8004180223 8004210131 8004290424 8004300348 8004300348	50-546 Q 50-546 A 50-546 A 50-546 A
	B0041B0395* B0041B0395* B0041B0426	50-247 50-247 50-286	Р Р Я		8004300350* 8004300350*	50-546 A 50-546 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGORY
Public Service Co of New Hampshire Public Service Co of Oklahoma Public Service Electric & Gas Co of New Jersey	8004070106# 8004070302* 8004160161 8004220334	50-443 Q 50-443 I 50-556 Q 50-556 G 50-272 S		8004220972* 8004220107* 8004220212* 8004220286* 8004220346*	FOIA FOIA FOIA FOIA FOIA
	8004010331 8004010337* 8004010348* 8004010354 8004010370*	50-272 R 50-272 R 50-272 S 50-272 S 50-272 S		8004220444* 8004220448* 8004220458* 8004220461* 8004220463*	FOIA FOIA FOIA FOIA
	8004010438 8004010443 8004010447 8004010449 8004010453	50-311 A 50-311 A 50-311 G 50-311 A 50-311 A		8004220528* 8004220532* 8004220539* 8004220548* 8004220562*	POIA POIA POIA POIA PDIA
	8004040282 8004040313 8004040317 8004040324* 8004070225	50-311 A 50-311 A 50-272 S 50-272 S 50-272 I		8004220567# 8004220573* 8004220602* 8004220606* 8004220609*	FOIA FOIA FOIA FOIA
	8004070250 8004080114* 8004080318 8004080370 8004080525	50-311 A 50-354 S 50-272 Q 50-272 P 50-272 B		800 422061 2* 800 4220625* 800 4220627* 800 4220635* 800 4220644	FOIA FOIA FOIA FOIA
	8004080533* 8004090317* 8004100157* 8004100247 8004100256	50-272 S 50-355 S 50-354 Q 50-272 Q 50-272 Q	Rochester Gas & Electric Corp	8004010355 8004090445 8004100461 8004110195 8004150331*	50-244 P 50-244 P 50-244 P 50-244 F 50-244 P
	8004100413* 8004110305 8004110426 8004110431 8004110468	50-311 8 50-311 A 50-311 A 50-311 A 50-311 A		8004150332* 8004150334* 8004150335* 8004150380 8004150384*	50-244 P 50-244 P 50-244 R 50-244 R
	8004110474 8004110475* 8004110492 8004110494* 8004110497	50-311 A 50-311 A 50-272 S 50-272 B 50-272 G		8004150434 8004150459 8004150502 8004120458 8004180471*	50-244 P 50-244 P 50-244 I 50-244 S 50-244 S
	8004110500* 8004140320 8004140323* 8004140407 8004140412*	50-272		8004220110 8004230003 8004230371 8004230372 8004230389	50-244 P 50-244 Q 50-244 P 50-244 S 50-244 P
	8004150030* 8004150252* 8004150384 8004150387* 8004150467*	50-272	Rockland Mobilization for Survival	8004290378 8004290381* 8004300227* 8004300407 8004080206*	50-244 P 50-244 P 50-244 Q 50-244 Q
	8004150553 8004150558# 8004160246 8004160249 8004170060	50-272 8 50-272 8 50-272 0 50-272 0 50-272 P	Rockwell International Corp Rockwell Inte Bystems Div	8004020389 8004040303	REGGD XFDRTLIC
	8004170062 8004230338 8004240365 8004240377 8004240494	50-272 P 50-311 P 50-311 F 50-311 F 50-272 0	Rocky Mountair		
	8004240494 8004250224 8004250366 8004250366 8004250393	50-272			
	8004280124* 8004280174* 8004280207 8004280225 8004290489	50-272 0 50-354 8 50-272 0 50-272 8 50-272 R			
Puget Sound Power & Light Co R F Denoncourt R W Beck & Associates	8004270497* 8004300488 8004030351 8004210366* 8004100357*	50-272 R 50-272 Q PR 50-320 P CONTRACT			
Reilly & Like Rensselaer Polytechnic Inst Resources Publishing Co Reuter-Stokes, Inc	8004100041 8004300320* 8004070016 8004100543 8004220210	PR 50-225 O FOIA REGOD REGOD			
Rhode Island, State of Riverside Methodist Hosp Columbus, CH	8004100494 8004160055 7911140251 8004220075#	PR PR Dacket 30 FOIA			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	NUMBER NUMBER	SUBJECT CATEGORY
	8004210259 8004210262* 8004210314 8004220568 8004220709	50-312 S 50-312 S 50-312 P 50-312 P	Senate, Foreign Relations Committee Shaw, Pittman, Potts & Trowbridge	8004180014* 8004080323* 8004010519 8004020202 8004080195	COMMISSION COMMISSION 50-400 Q 50-289 Q 50-269 Q
	800422073 8004230498 8004280528 8004290338 8004290454	50-312 S 50-312 P 50-312 F 50-312 P 50-312 S		8004080200* 8004080425 8004080705 8004080720 8004090096	50-269 Q 50-269 Q 50-312 Q 50-269 Q 50-269 Q
	8004290465* 8004290485 8004290491* 8004290524* 8004300421	50-312 S 50-312 S 50-312 S 50-312 P 50-312 S		8004070281 8004070287 8004070275* 8004100010 8004100015*	50-289 Q 50-289 Q 50-289 Q 50-289 G 50-289 G
San Antonio, T.	8004300433* 8004090421 8004090421 8004100442 8004100442	50-312		B004100090 B004100277 B004100285* B004100308 B004100435	PR 50-287 G 50-287 G 50-287 G 50-287 G
	8004100444* 8004100444* 8004100447* 8004100447* 8004110024	50-498 M 50-498 M 50-498 M 50-498 M 50-498 M		8004100436* 8004100437* 8004100464 8004100479 8004100547	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0
San Diego Gas & Electric Co San Luis Obispo Mothers for Peace San Luis Obispo.CA Sandia Laboratories	8004110024 8004070224 8004210322 8004280545* 8004030277	50-498 M PRM 50-275 G 50-320 H PR		8004100566 8004110027 8004110077 8004110085 8004110100	50-287 0 50-287 0 50-287 0 50-287 0
	8004030281 8004030284 8004030287 8004030288 8004070413	PR PR PR PR RES		8004110155 8004110162* 8004110516 8004110561 8004110567*	50-287 G 50-287 G 50-287 G 50-287 G
	8004100028 8004100319 8004110051* 8004150022 8004150028	NUREG NUREG 50-3 P NUREG NUREG		8004140004 8004140007* 8004140013* 8004140017* 8004140017*	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0
	8004150033 8004150047 8004150046 8004150074 8004150078	NUREQ NUREG RES NUREQ NUREQ		B004140023* B00414002B* B004140032* B00414003B* B004140045*	50-287 0 50-287 0 50-287 0 50-289 0 50-287 0
	8004240454 8004240464 8004240505 8004240521 8004240523	NUREQ NUREG 50-294 P TOPREP TOPREP		B004140051* B004140057* B004140062* B004140065* B004170273	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0
	8004240527 8004240549 8004280034 8004280035 8004280206#	TOPREP TOPREP NUREG Nureg Review Grp		8004170281* 8004210085 8004210235 8004210230* 8004210421	50-287
Sargent & Lundy, Inc Sargent Industries,Sweeney Div Sassafras Audubon Society	8004300574 8004100546 8004290474* 8004020236 8004020490	RES REGOD TOPREP XPORTLIC 50-546 H		8004220008 8004220102 8004220405 8004230001 8004230030	50-320 0 50-320 0 50-320 0 50-287 0 50-287 0
· W B	8004010294 8004010300* 8004030037* 8004040186* 8004300069*	50-247 9 50-347 9 CONTRACT CONTRACT 50-387 9	Sheldon, Harmon & Weiss	8004230090 8004230097 8004230127 8004230131 7906010118	50-312 0 50-287 0 50-287 0 50-287 0 50-334 9
d tive, Inc	8004180500* 8004280045 8004280053* 8004180469* 7909140279	50-302 I XPDRT(.IC XPDRTLIC S0-302 I MIBC		8004020091 8004020091 8004020091 8004020099* 8004020099*	50-3 0 50-3 0 50-3 0 50-3 0
	[# # #	50-289 U 30-409 U 40-1341 PR 50-10 U		8004020099* 8004080364 8004080375 8004080418 8004080678	50-3 0 50-443 0 50-269 0 50-338 0 50-269 0
		50-409 U 50-266 U 1180 50-289 H 50-320 U		8004080495 8004100100 8004100299 8004100542 8004110045	50-3 F 50-3 F 70-143 50-289 G 50-3 P
		50-44\$ H 50-309 H COMMISSION 10-1341 70-143		8004150101 8004160131 8004160138* 8004220462 8004280026	50-574 Q 50-289 Q 50-289 Q 50-247 E 50-289 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	PRY
Shoreham Opponents Coalition Sigma Chemical Co (subs of Sigma-Aldri ch Corp)	8004210090 8004210092	50-322 XPORTLIC XPORTLIC XPORTLIC	G		8004230317* 8004230335 8004230494 8004240394 8004240395*	PROJ 50-206 50-206 50-206 50-206	8 P P
Sinnissippi Alliance for the Environment	8004300454 8004100027	XPERTL [C 50-454	G.		800425041B 800425042J*	50-206 50-206	5 S
(SAPE) Small Business Administration	8004080241# 8004100194# 8004100576# 8004210119#	CONTRACT CONTRACT CONTRACT CONTRACT			8004270640 800427064 <i>0</i> 8004300011	50-361 50-361 50-361	A A
Social Research Applications Corp Source Production & Equipment Co , Inc South Carolina Electric & Qas Co	8004070140# 8004080058 8004020035# 8004020078 8004020201	CONTRACT 71-102 50-395 50-395 50-395		Southern Co Services.Inc Southwest Fabricating & Welding Co	8004300011 8004300363 8004300375 8004150427 8004250390	50-361 50-206 50-361 50-424 50-321	A F D S F
	6004020292 8004020321 8004020322* 8004030175 6004030178*	50-375 50-375 50-375 50-375 50-375	8 8 8	(subs of IV International Corp) Southwest Research Institute	8004290023* 8004040280* 8004040295* 8004040296* 8004040301*	9A999 50-341 50-317 50-317 50-317	A Q Q
	8004040467 B004100357 B004100402* 8004140161 B004140174	50-375 50-375 50-375 50-361 50-395	0 0 0 8	Southwest Research and Information Center Southwest Teras Electric Cooperative	8004230148 800424043 800424043 800424043	WASTE MG 50-445 50-445 50-445 50-445	3.0 H H H
	8004150501 8004150548 8004160110 8004170004 8004170085	50~395 50~395 50~395 50~395 50~395	6 8 0 5 5	Spiegel & McDiarmid	8004240053 8004240053 8004240053 8004240053 8004240053	50-445 50-445 50-445 50-445 50-445	м м м
	8004220049 8004220455 8004220459# 8004250404 8004250429	50-395 50-395 50-395 50-395 50-395	8 0 8 8		8004080445 8004090185 8004090185 8004090185 8004090363	PRDJ 50-445 50-445 50-445 50-416	м м м
South Carolina, State of	8004280498 8004300119# 8004300478 8004300561 8004250072#	50-395 50-395 50-395 50-395 State Pro	S 0 0 8		8004090368* 8004090434 8004090434 8004090434 8004100428	50-414 50-445 50-445 50-445 50-445	M M M
South Mississippi Electric Power Association	*05E070350*	50-416	A		8004100433 8004100433 8004100433	50-445 50-445 50-445	M
Southern California Edison Co	8004020049# 8004020327 8004030140 8004030141#	50~361 50~206 50~206 50~206	9 P P		8004100547 8004100556 8004150032	PROJ PROJ 50-445	M
	8004030145* 8004030181 8004030181 8004070338 8004070338	50-204 50-341 50-341 50-204 50-204	P A A R R		B004150032 B004150032 B004150032 B004150050#	50-445 50-445 50-445 50-445	M M M
	8004070342* 8004080395 8004080395 8004080395 8004080477	50-206 50-206 50-206 50-206 50-206	R F F B	Str Si			
	8004080483* 8004080491 8004080498* 8004080504* 8004080539		5 P P				
	8004070208 8004070326 8004100477 8004100500* 8004100537	PRGJ 50-206 50-361 50-361 50-361	P 0 9	State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs	800401047E* 8004020369 8004040147	SECY XPORTLIC XPORTLIC	
	8004150345 8004150347* 8004150449 8004150538 8004150538	50-206	R R F S S		800408011B 8004080126 8004080131 8004080139 8004100044	XPORTLEO XPORTLEO XPORTLEO XPORTLEO XPORTLEO	: :
	8004150546* 8004150546* 8004180450 8004180454* 8004210254	50-361 50-361 50-206 50-206 50-206	0 0 C 0 C	Steel, Hector & Dayis	B00410005B B004100040 B004020005 B004020265* B004170330	XPORTL 10 XPORTL 10 50-389 50-389 50-250	
	8004210257* 8004210270 8004210273* 8004220446 8004220503	50-204 50-204	8 8 P P	Stane & Webster Engineering Carp Stone & Webster, Inc Storch Engineers	8004030128* 8004040057* 8004270474* 8004020418* 8004020424*	50-280 50-450 TOPREP 50-213 50-213	P 8 F
	8004220434 8004230302*	50-206 PROJ	P	Suffolk County, NY	8004100046* 8004100046*	PR PR	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATIO	אכ	ACCESBION NUMBER	SUBJEC CATEGO	
	8004100440 8004100441 8004100450* 8004100450* 8004100460*	50-322 PR 50-514 50-516 50-516	T T T			8004020440 8004020447* 8004030222 8004030233 8004030245	50-327 50-327 50-327 50-327 50-327	88888
Susquehanna Alliance Susquehanna Environmental Advocates	8004100460* 8004100472* 8004100472* 8004090463 8004230006	50-516 50-516 50-516 PR 50-387	T T T			8004040181* 8004040377 8004040377 8004040391* 8004040391*	50-259 50-438 50-438 50-438 50-438	9 8 8 8
Sweden Tallahasse,FL Tech/Ops (Technical Operations, Inc)	8004030298 8004280468* 8004180503* 8004100536 8004280129	PR COMMISS 50-302 REGGD 71-9039	1			8004070288 8004070289* 8004070340 8004070363* 8004080207	50-260 50-260 TOPREP TOPREP 40-1341	9 \$
Technassociates, Inc Technology for Energy Corp Teknekron Research,Inc	8004280133* 8004100576* 8004210117* 8004300612 8004080618	71-9039 CONTRAC CONTRAC 50-320 CONTRAC	T T T			8004080210* 8004080519 8004080526* 8004080553 8004080616	40-1341 50-327 50-327 50-553 50-327	8 8 8
Teknekron, Inc Teledyne Isotopes Teledyne Wah Chang Albany	8004180197* 8004040406* 8004180495 8004080050 8004080345	COMMISS 50-298 XPORTLI XPORTLI XPORTLI	R C			9004080622* 9004090160 9004090228 8004090228 8004090333	50-327 PR 50-327 50-327 50-327	8 P P
Tennessee Valley Authority	8004010320 8004010360 8004010371* 8004010374 8004010375	NURE9 50-327 50-327 50-327 50-327	S 9 0 S			8004090336* 8004090418 8004090426* 8004090429 8004090433*	50-327 50-327 50-327 50-327 50-327	8888
	8004010379* 8004010381* 8004010393 8004010399 8004010402*	50-327 50-327 50-296 50-327 50-296	0 8 8 8			8004090453 8004090457* 8004100294 8004100364 8004100364	50-327 50-327 PR 50-259 50-259	S S Q
	8004010403* 800401040B 8004010433 8004010440* 8004010451	50-327 50-327 50-327 50-327 50-259	8 p s s s s			8004100364 8004100495* 8004110186 8004110425 8004110425	50-259 50-544 50-327 50-390 50-390	0 F A
	8004010459* 8004010460 8004010464 8004010466* 8004010475*	50-259 50-240 50-327 50-260 50-327	8 8 9 8 8			8004140327 8004140332* 8004140388 8004140428 8004140432*	50-327 50-327 GEN TEC 50-327 50-327	P 18 6 8
	8004010487 8004010491* 8004010502 8004010506* 8004020193	50-257 50-257 50-327 50-327 50-553	8 8 8 8 A			8004140433 8004140436* 8004150392 8004150396* 8004150402	50-260 50-260 50-553 50-553 50-327	8 8 8 8
	8004020197* 8004020197* 8004020203* 8004020203* 8004020204*	50-553 50-553 50-553 50-553 50-553	A A A A			800415040B 8004150413 8004150413 8004150414 8004150414	50-327 50-390 50-390 50-518 50-518	8888
	8004020204# 8004020207# 8004020249#	50-553 50-553 50-259 50-327	A Q S S			8004150414 8004150414 8004150417* 8004150417* 8004150417*	50-518 50-518 50-518 50-518 50-518	88888
			ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ			8004150417* 8004150418 8004150423 8004150423 8004150423	50-518 50-327 50-259 50-259 50-259	4448
			5 5 6 4			8004150437 8004150437 8004150450* 8004150450* 8004150485	50~390 50~390 50~390 50~390 50~553	8 8 8 8
						8004150494* 8004150494* 8004150500 8004150512*	50-553 50-553 50-553 50-327 50-327	8 8 8 8 8
						8004150522* 8004150522* 8004150523 8004150525 8004150528	50-240 50-240 50-257 50-257 50-327	8888
						8004150533* 8004150535* 8004150536* 8004150539 8004150547*	50-327 50-259 50-259 50-327 50-327	00 00 00 00

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGOR	₹¥
	8004150551 8004150551 8004150554 8004150557 8004150957	50-327 50-327 50-327 50-259 50-259	6 2 2 5		8004220420 8004220523 8004220523 8004220523 8004220533	50-438 50-259 50-259 50-259 50-259	20 p p p p
	8004150557 8004150559* 8004150565* 8004150565* 8004150573	50-259 50-327 50-327 50-327 50-259	ម ម ម		8004220541 8004220541 8004220546* 8004220546* 8004220669	50-438 50-438 50-438 50-438 50-260	89996
	80041505854 8004150608 8004150608 8004150615* 8004150615*	50-259 50-327 50-327 50-327 50-327	ងងង		8004220680* 8004220686 8004220698 8004220699* 8004220707*	50-260 50-259 50-327 50-259 50-327	9 8 8 6
	8004160216 8004160216 8004160218* 8004160218* 8004160284	50-518 50-518 50-518 50-518 50-327	ខាធាធាធ		8004220715 8004220722* 8004220724 8004220724 8004220724	50-327 50-327 50-518 50-518 50-518	9999
	8004140291 8004140296* 8004170026 8004170031* 8004170065	50-438 50-438 50-327 50-327 50-327	8888		8004220724 8004220724 8004220724 8004220742 8004220750*	50-518 50-518 50-518 50-259 50-259	55555
	8004170065 8004170067* 8004170067* 8004170069 8004170073*	50-327 50-327 50-327 50-327 50-327	K K P P		8004220753 8004220757* 8004220764* 8004220764* 8004220764*	50-327 50-327 50-518 50-518 50-518	S S S S S
	8004170134 8004170140* 8004170148 8004170155* 8004170213	50-327 50-327 50-327 50-327 50-390	P P G A		8004220764# 8004220764# 8004220764# 8004230347 8004230380	50-518 50-518 50-518 50-553 50-438	5000
	8004170225 8004170227# 8004170229# 8004170229# 8004170231#	50-327 50-327 50-327 50-327 50-327	1 1 1 1 1		8004230380 8004230382* 8004230382* 8004230503 8004230503	50-438 50-438 50-438 50-438 50-438	មា មា មា មា
	8004170231* 8004170234* 8004170234* 8004180106 8004180106	50-327 50-327 50-327 50-328 50-328	F F Q		8004230504 8004230507* 8004230507* 8004230527 8004230527	50-257 50-438 50-438 50-438 50-438	P 55 55 55
	8004180106 8004180106 8004180106 8004180256 8004180256	50-328 50-328 50-328 50-553 50-553	0 0 A A		8004230529* 8004230529* 8004240386 8004240386 8004240388*	50-438 50-438 50-438 50-438 50-438	50000
	8004180264* 8004180331 8004180337* 8004180365 9004180367*	50-553 50-390 50-390 50-328 50-328	A R R S S		B004240405 B004240411 B004240415* B004250374	50-438 50-390 50-259 50-259 50-566	53 FR FR FS
	8004180377 8004180377 8004180381* 8004180381* 8004180391	50-390 50-390 50-390 50-390 50-327	8 8 8 8		8004250374 8004250379* 8004250379* 8004250380 8004250380	50-546 50-546 50-566 50-438 50-438	5555
	8004180394* 8004180399 8004180407* 8004180444 8004180444	50-327 50-327 50-327 50-390 50-390	R \$ \$ \$ \$		8004250384* 8004250384* 8004250394 8004250405 8004250405	50-438 50-438 50-259 50-564 50-566	S S Q
	8004180451 8004180452 8004180456* 8004180457* 8004180460	50-240 50-296 50-296 50-260 50-327	8 8 8 8		8004250408# 8004250413 8004250413 8004250424# 8004250424#	50-257 50-370 50-370 50-370 50-370	8 8
	2004180465* 9004210178 9004210178 9004210178 9004210188*	50~327 50~259 50~259 50~259 50~553	6 0 0		8004250431 8004250431 8004250432* 8004250432* 8004280001	50-956 50-556 50-556 50-556 50-259	5 5 8 9 9
	8004210202 8004210202 8004210205* 8004220340 8004220340	50-327 50-327 50-327 50-259 50-259	ь ь ь		B004280056 B004280060* B004280170 B004280170	40-1341 40-1341 50-259 50-259 50-259	Q Q
	8004220340 8004220349* 8004220349* 8004220349* 8004220358*	50-259 50-259 50-259 50-259 50-259	P P P		8004280227 8004280388 8004280388 8004280432 8004280432	50-327 50-390 50-390 50-438 50-438	P 9 8 8

AUTHOR AFF]LIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y
	8004280436* 8004280436* 8004280438 8004280438 8004280442*	50-438 50-438 50-438 50-438 50-438	8 5 5 5 5		8004070175 8004070180 8004070180 8004070180 8004070180	50-445 50-445 50-445 50-445 50-445	M M M M
	8004280442* 8004280453 8004280458* 8004280470 8004280476*	50~438 50~328 50~328 50~327 50~327	5 6 9 8	Texas Utilities Generating Co	8004100221 8004100221 8004100221 8004100221 8004010147	50-445 50-445 50-445 50-445 50-445	M M M
	8004280503 8004280505* 8004280508 8004280510* 8004280514	50-518 50-518 50-564 50-566 50-438	8 S R R		8004010298 8004010295 8004010296 8004010296 8004010299*	50-445 50-445 50-445 50-448 50-445	99999
	9004280516 9004280524* 9004280524* 8004280536 8004280537	50-438 50-438 50-438 50-370 50-370	8 8 8 8		8004010299* 8004030258 8004040083* 8004040088 6004040101*	80-445 50-445 50-445 50-445 50-445	8 M G G
	8004280544* 8004280548 8004280548 8004280593 8004280598*	50-390 50-390 50-390 50-259 50-259	8 8 8 8 8		8004070278 8004080221 8004080638 8004100525* 8004150001	50-445 50-445 50-445 50-445 50-445	8 0 M A
	8004270270 8004270270 8004270274 8004270311 8004270316*	50-327 50-327 50-370 50-327 50-327	P P S S 8		8004150001 8004150197 8004150197 8004150202* 8004150202*	30-445 50-445 50-445 50-445 50-445	A 8 5 8 6
	8004290329 8004290335* 8004290346 8004290346 8004290346	50-328 50-328 50-328 50-328 50-328	8 5 5 8		8004160239 8004160239 8004160243* 8004160243* 8004180477	50-445 50-445 50-445 50-445 PR	K K K
	8004290353* 8004290353* 8004290353* 8004290379 8004290379	50-328 50-328 50-328 50-259 50-259	8 8 0 0		8004220021 8004220021 8004220021 8004220021 8004220423	50-445 50-445 50-445 50-445 50-445	M M M M
	8004270377 8004270377 8004270400 8004270400 8004270406#	50-259 50-259 50-327 50-327 50-327	a a e a a		8004220426 8004230041* 8004230041* 8004230041*	50-445 50-445 50-445 50-445 50-445	K M M M
	8004270435 8004270446* 8004270453 8004270453 8004270455	50-327 50-327 50-390 50-390 50-328	5 6 A A B		8004240071* 8004240173 8004240424* 8004240424* 8004240562	50-445 50-445 50-445 50-445 50-445	M 0 0 M
	8004270458* 8004270458* 8004270461* 8004270462* 8004270462*	50-390 50-390 50-328 50-390 50-390	A A B A		8004240562 8004240562 8004240562 8004250049 8004250049	50-445 50-445 50-445 50-445 50-445	М М М
	8004270467* 8004270467* 8004270513 8004270515 8004270516*	50-370 50-370 71-227 50-327 71-227	A A 6		8004280189 8004280189 8004270250 8004270250 8004270254*	50-556 50-556 50-445 50-445 50-445	9 8 8
	8004270517* 8004300076* 8004300341 8004300340	50-327 50-566 50-327 50-327 50-518	5 9 9 5		8004270254* 8004270271 8004270271 8004270411 8004270411	50-445 50-445 50-445 50-445 50-445	8 8 8
	8004300390 8004300390 8004300397* 8004300397*	50-518 50-518 50-518 50-518 50-518	5 5 9 9		8004270430 8004270430 8004270437* 8004270437* 8004270521	50-445 50-445 50-445 50-445 50-445	8 8 8 A
Texas Electric Service Co	8004300397* 8004300397* 8004300474* 8004100534 8004100545	50-518 50-518 50-390 50-445 50-445	8 0 M M	Texas, State of	8004270634 8004270634 8004300526 8004300526 8004030344	50-445 50-445 50-445 50-445 80-448	A A A A M
Texas Instruments, Inc Texas Public Interest Research Graup Texas Utilities Co	8004040408* 8004230035 8004080247 8004090164 8004090164	50-220 50-466 50-445 30-445 50-445	я о м м м		8004030344 8004030344 8004030344 8004030360 8004040078	50-445 50-445 50-445 50-445 80-445	M M M M
	8004070164 8004070164 8004070175 8004070175 8004070175	50-445 50-445 50-445 50-445 50-445	м м м м		8004080044 8004090185 8004090185 8004090185 8004090185	50-445 50-445 50-445 50-445 50-445	# # #

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004090434 8004090434 8004090434 8004090434 8004140281	50-445 M 50-445 M 50-445 M 50-445 M 50-446 G	Transportation, Dept of U S Court of Appeals 9th Circuit Underwriters Laboratory	8004180093 8004210075 8004150429 8004090187 8004250022*	70-1426 70-2478 50-280 0 50-312 G
Tesas, Univ of Tesas,Univ of, Cancer Center Tesas-Louisiana Electric Cooperative,Inc	8004140463 8004240416 8004240420* 8004220130* 8004080018	50-498 A 50-128 R 50-128 R FOIA 50-445 M	Union 76 Minerals Exploration Co Union Carbide Corp	8004070262 8004020165 8004080278 8004080548 8004080551#	40-8584 WASTE MOT WASTE MOT 90-54 R 50-54 R
	8004080559 8004090427 8004240061 8004240061 8004240061	50~445 M 50~445 M 50~445 M 50~445 M 50~445 M		6004090347 8004090375 8004090380# 8004180042 8004290161	40-299 50-54 R 50-54 R 70-687 FOIA
The Analytic Sciences Corp The Press Binghampton,NY	8004240071* 8004240071* 8004240071* 8004300279 8004230011	50-445 M 50-445 M 50-445 M PR FOIA	Union Electric Co Union of Concerned Scientists	8004030208 8004040362 8004040368* 8004110329* 8004020099*	50-483 S 50-483 S 50-483 G 50-483 G
Three Mile Island Alort	8004030170 8004040227 8004080137 8004080146* 8004080150*	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0	United Nuclear Corp	8004080678 8004100562 8004150101 8004210072 8004070242	50-289 G 50-289 G 50-574 G 50-320 C 40-8602
Toledo Edison Ca	8004080167* 8004080176* 8004220011 8004010419 8004010427*	50-289 G 50-289 G 50-287 G 50-344 F 50-344 F	United Nuclear Corp , UNC Recovery Systems Div	8004180046 8004180046 8004180392 8004220177	70-820 70-820 70-820 70-820
	8004020135 8004040455 8004080514 8004090424* 8004100091*	50-346 Q 50-346 Q 50-346 P 50-346 Q 50-346 Q	United Nuclear Corp ,Navel Products Div	B004230533 B004240140 B004090154 B004210063 8004210067* B004300133	70-820 70-820 70-371 70-371 70-371 50-367 9
	8004110378 8004110386* 8004110485 8004110487 8004110489*	50-346 S 50-346 S 50-346 S 50-346 S 50-346 S	Utah, State of Valore, C Vermont Yankee Nuclear Power Corp	8004300087 8004100466 8004210291 8004010237 8004010243#	40-8681 50-311 0 50-272 0 50-271 P 50-271 P
	8004110490* 8004140350 8004140353* 8004150563 8004150570*	50-346 B 50-346 R 50-346 R 50-346 B 50-346 S		8004010254 8004010487 8004010499* 8004020356 8004020362*	50-271 P 50-271 S 50-271 S 50-271 S 50-271 S
	8004180353 8004210265 8004210267* 8004220457 8004220534	50-346 F 50-346 S 50-346 B 50-346 P 50-346 P		8004040329 8004040332* 800404045 8004080238 8004080261	50-271 E 50-271 E 71-6375 50-271 P 50-271 0
	6004220457 8004220466* 8004220752 8004220761* 8004220765	50-346 9 50-346 9 50-346 8 50-346 8		8004080269 8004080376 8004080384 8004080423 8004080490	
	8004220772* 8004250376 8004280380 8004280382* 8004280456	50-346 B 50-346 P 50-346 I 50-346 I 50-346 F			
	8004280538 8004280546* 8004280572 8004280575* 8004300617	50-346 8 50-346 8 50-346 9 50-346 9 50-346 9			
Topper, Alloway, Goodman, Deleone & Duffey Transcomm, Inc Transnuclear, Inc	8004010091* 8004010081* 8004010091* 8004010095*	FOIA CONTRACT 70-2845 70-2845 SECY			
	8004010097* 8004010101* 8004010105* 8004020472 8004020479*	SECY SECY SECY XPORTLIC XPORTLIC			
	8004040110 80040401114* 80040700B5 8004080020 8004080039	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
	8004080042* 8004080079 8004080085* 8004080104 8004080259*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			

AUTHOR AFFILZATION	ACCESSION NUMBER	SUBJECT	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8004010401 8004010465 8004010504 8004010505* 6004020027	50-280 50-404 50-338 50-280	9 9 8 9		B004210372 B004210376* B004220234 B004220234 B004220311	50-338 50-338 50-404 50-404 50-280	P P A A
	8004020157 8004020161* 8004020328 8004020336 8004020400	50-404 50-404 50-339 50-339 50-280	R R S S H		8004220311 8004220318 8004220318 8004220399 8004220379	50-280 50-280 50-280 50-338 50-338	F P O G
	8004020400 8004020400 8004020400 8004030126 8004030183	50-280 50-280 50-280 50-280 50-339	H H F A		B004220493 B004220493 B004220611 B004220611 B004220641	50-338 50-338 50-404 50-404 50-339	0 0 5 9 P
	8004030185* 8004030190* 8004030193* 8004030195* 8004030200*	50-339 50-339 50-339 50-339 50-339	A A A		8004220444 8004220453* 8004230231 8004230238* 8004230246*	50-338 50-339 50-339 50-339 50-339	9 9 9 9
	8004030205* 8004030206* 8004030210 8004030210 8004030219	50-339 50-339 50-338 50-338 50-338	A Q Q S		8004230255* 8004230240* 8004230337 8004230519 8004240509	50-337 50-337 50-339 50-338 50-280	Р Р О
	8004030221* 8004030225 800403022 <i>6</i> * 8004030234 8004030234	50-338 50-338 50-338 50-280 50-280	8 8 9 P		8004240507 8004250041* 8004250371 8004250387 8004250387	50-280 50-280 50-280 50-338 50-338	0 9 3 J
	8004030234 8004030236 8004030238* 8004030238* 8004030242	50-338 50-338 50-338 50-338 50-338	R R R R		8004280472 8004280547 8004280554* 8004280604 8004280608*	50-339 50-338 50-338 50-338 50-338	9 8 8 8 9
	8004030266 8004030270* 8004040242* 8004040302 8004070019	50-280 50-280 50-280 50-339 50-339	\$ G A S		8004280612 8004280616* 8004280626* 8004270334 8004300415	50-280 50-280 50-280 50-280 50-404	8 8 9 0
	8004070261 8004070282 8004070282 8004070307 8004070307*	50-339 50-338 50-338 50-338 50-338	A Q G S	Virginia Tech	8004300435 8004300435 8004300472 8003310406 8003310408*	50-280 50-280 50-280 50-124 50-124	J P B F
	8004080270 8004080312 8004080354 8004080372 8004080372	50~280 50~339 50~280 50~338 50~338	9 9 9		8003310411* 8003310415* 8003310417* 8003310421* 8003310427*	50-124 50-124 50-124 50-124 50-124	9 8 8 8
	8004080474 8004080474 8004080482* 8004080482* 8004080488	50-280 50-280 50-280 50-280 50-280		Virginia, Univ of	8003310432* 8003310439* 8004040468 8004150431 8004020215*	50-124 50-124 50-124 50-124 CONTRACT	B B F P
	8004080528 8004080536* 8004080621 8004080621 8004100410	50-338 50-338 50-338 50-338 50-339	9 P P	Volkema, Pees & Sarap Volken. R J	8004220397* 8004020214 8004020478 8004040069 8004230091	FOIA 50-367 50-367 50-367 50-367	0 0 0
	8004110202 8004110202 8004110478 8004140167 8004140217	50-338 50-338 50-280 50-339 50-281	g g s	Washington Public Power Supply System	8004230101* 8004010340 8004020273 8004020296* 8004020302	50-347 50-508 50-397 50-397 50-397	0 A B B
	8004140258 8004140258 8004140258 8004140446 8004140446	50-280 50-280 50-280 50-338	F		8004020305* 8004020337 8004020341* 8004030341 8004070367	50-397 50-397 50-397 PR 50-397	K K B
	8004150164 6004150342 8004170050 6004170052* 6004170079	50-280 50-339 50-338 50-338 50-280	S R		8004140345 8004150443 8004150443 8004170207 8004210213	50-397 50-508 50-508 50-397 NUREG	K A A
	8004170210 8004170211* 8004170212* 8004170241 8004170244*	50-339 50-338 50-338 50-280 50-280	R		8004210285 8004210285 8004210285 8004230248* 8004230271*	50-397 50-397 50-397 50-460 50-460	A A G
	8004170244* 8004180232 8004180287 8004180446 8004210177	50-280 50-338 50-280 50-339 50-339	. G	Washington Univ	8004280466 8004280469* 8004280475 8004280476* 8004210096	50-397 50-397 50-397 50-397 XPORTLIG	8 8 8

	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
	Washington, State of Washington, Univ of West Branch Conservation Association	8004240139 8004290507 8004020139 8004090213 8004090213	State Pri WASTE MG NUREG PR PR	og		8004020410 8004020410 8004030353 8004040123 8004070206	50-266 50-266 50-266 50-266 50-266	FOPO
	West Chicago, IL	8004070213 8004180237* 8004180237* 8004180237* 8004030147	PR 50-3 50-3 50-3 40-2061	н н		8004110491 8004220278 8004220475 8004220475 8004240419	PR 50-301 50-266 50-266 50-266	P P Q
	Western Geophysical Hestern Massachusetts Electric Co Hestern Nuclear, Inc (subs of Phelps Dodge Corp)	8004180348* 8004080590* 8004150412 8004080606	50-213 50-245 50-245 40-1162	I I		8004240417 8004240447 8004240447 8004270278 8004270206*	50-266 50-266 50-266 50-266 50-266	0 0 0 5 8
	Western Piping & Engineering Co , Inc Western Washington State College Westinghouse Electric Corp	8004090250 8004090255 8004110037* 8004030156* 8004020396	40-1162 40-1162 QA969 50-320 TOPREP	н		8004290307 8004290310* 8004290418 8004290425* 8004290428	50-266 50-266 50-266 50-266 50-266	S S I I F
		8004020402* 8004020432* 8004070232 8004080049 6004080342	TOPREP TOPREP TOPREP 70-1151 XPORTLIC		Wisconsin Public Service Cosp	8604270464 8604270469* 8004270470 8004270479* 8004010472	50-301 50-301 50-301 50-301 50-305	99999
		B004070044 B004070064 B004100063 B004100463* B004110015 B004110476	71-9009 40-1162 XPORTLIC 70-1151 70-1151 PR			8004010495* 8004080337 8004080457 8004080462* 8004080467*	50-305 50-305 50-305 50-305 50-305	P P B 6 6
		8004140015* 8004140020* 8004140034* 8004140094 8004140210*	GA797 GA797 GA797 PR 50~304	G-		8004100405 8004150354 8004150355* 8004150524 8004150532*	50-305 50-305 50-305 50-305 50-305	Q R R B B
		8004150008 8004150480* 8004160064 8004160070 8004180464	RES 50-537 XPORTLIC 70-2909	A		8004150581 8004150596* 8004170018 8004180428 8004180433*	50-305 50-305 50-305 50-305 50-305	88666
		8004210123 8004210136 8004220111 8004220284* 8004220434	XPORTLIC XPORTLIC XPORTLIC 50-301 TOPREP	P		8004180479 8004180483* 8004210327 8004210331* 8004220442	50-305 50-305 50-305 50-305 50-305	P P P B
		8004240152 8004280329 8004280344# 8004290371* 8004300458	RES TOPREP TOPREP 50-537 XPORTLIC	A		6004220648* 6004220756 6004230504 6004230515* 6004230521	50-305 50-305 50-305 50-305 50-305	9000
	Westinghouse Electric Corp , Nuclear Energy Systems	8004300459 8004030345 8004180475*	XPORTLIC PR 50-202	P	Wisconsin's Environmental Decade Wiss, Janney, Elstner & Association, Inc	8004290327* 8004290336* 8004010389 8004180130* 8004040070*	50-305 50-305 50-266 50-301 50-344	8 8 0 T
	Westinghouse Electric Carp , PWR Systems Div	8004240397# 8004110209 8004170028 8004170035#	50-204 TOPREP TOPREP TOPREP	P	Worsham, Forsythe & Sampels	8004070164 8004070164 8004070164 8004070175 8004070175	50-445 50-445 50-445 50-445 50-445	M M M M
	Westinghouse Electric Corp , Wyoming Mineral Corp	B004270404 B004040221 B004040227 B004080217	50-327 40-8502 40-8502 40-8502	P		8004090175 8004090180 8004090180 8004090180 8004100221	50-445 50-445 50-445 50-445 50-445	M M M
	Westinghouse Operating Plants Owners Group	8004090070 8004020429	40-8502 TOPREP			8004100221 8004100221	50-445 50-445	M
	White Cross Hosp Association Columbus, OH	8004290434 8004220639*	TOPREP FOIA ACRE		Wyle Laboratories	8004140354* 8004140354* 8004140358*	50~369 50~369 50~369	AAA
	White, M P Consulting Engineer Widoff, Reager, Selkowitz & Adler	8004030170 8004040227 8004080137 8004080146*	50-287 50-289 50-289 50-289	0 0 0	Wyoming Mineral Corp	8004140358* 8004020155 8004070196 8004070235 8004070244	50-369 40-8502 40-8502 40-8502 40-8502	A
	Wisconsin Electric Power Co	8004080150* 8004080167* 8004080176* 8004090397 8004010223	50-289 50-289 50-289 50-289 50-266	G G G G		8004090231 B004210413 B004220076 800422008B B00424019B	40~8502 40~8502 40~8502 40~8502 40~8502	
		8004010317 8004010317 8004020324 8004020333 8004020344*	50-266 50-266 50-266 50-266 50-266	P P S S	Wysming Outdoor Council Wysming, State of	8004240209* 8004280283 8004210387 8004210388* 8004020064	40-8502 40-8304 40-1162 40-1162 40-8745	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	
Yankee Atomic Electric Co	8004070186 8004270075 8004010395 8004010398* 8004040298*	40-8380 40-8502 50-29 50-29 ACRS	 I		8004160102* 8004160102* 8004210110 8004230064 8004230118*	PR PR PR 50-29 COMMISS	P ION
	B004080489 B004080496> 8004100370 8004100374* 80041104419 8004110444* 8004110444* 8004140172 8004150352*	50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29 50-29	99886 65488	York Research Corp York, PA	8004280534 8004280600 8004270103 8004190462* 8004080106	50-29 80-29 FOIA 50-244 50-320	F P H

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

ែ≱ម អាក្ ColomEM	ACEE8910N NIM 1FH	SUBJECT CATEGORY	OTHER PEPOKT NUMBER	HERORT MIMBER	ACEESSION NUMBER	SUBJECT Category	OTHER REPORT NUMBER
			~~~~~~~~~			****	
13904 45 46	#00414J <b>35</b> 0*	50 = 36 9 A		A004160UBH	#0041600AB	p g g	URAL/HASRD=72
13904-1 41 64	8001140350*	50-369 1		40041h0U95	8004169095	HES	ORML/HASKO#71
1498+657=12	8004010250*	50-466 4		MANA170120	8904170120	₩ES	EGG=LOFT=5104
79-15-15	4004010106*	27-19		8004170274	8004170274	RES	EGG-EA-5109
77-1373	h204010415	al S		8004170276	0004170276	PtS	EGG-EA-5097
24114014413	9304010413	ara		4004114510	01134111616		F13/1-EW-3047
4004010415	#0040f0455*	41.2		#104170287	8004170287	HES	
4004025162	M064020142	HES	EEG*tA-501≥	9004170287	B004170289	HF3	EGG-EA-5110
4004646027	6004040927	44	NAC= }u=/4=150	8004170331	A004170334	RES	EGG=EA=5111
4004040624	4004040028	RES		8004240152	8004240152	HES	
8000010201	2004040504	FES	NHC-01-16-293	8004244460	8004240460	RES	ANL+hUREG+24871
	311 0 4 3 4 7 E 13 4		that a district the tri	2,40-1,40-110	000-210-00		THE TOTAL OF THE TENT
		1.0.		4004240465	8004240465	KES	
4004049519	4004040510	+F5					
80040402 <i>1</i> 0	4004040510	HF3		400454A#P&	9900549499	es E &	EGG-8EMI-5113
4044040315	8004040 442	₩FS		4004240475	8004240475	kES	
500 JO JU 369	8464040364	hŁ 5	044L / 04 9HD = 68	8004240481	A004240487	RES	ORNL/E0/E19-119
800 10701 15	60040/0145	HES		F004250 <i>56</i> 4	8010250364	50-295 P	EGG=EA=5117
	24101113						
A004070415	4004010415	nt S		8004240042	6004284032	HLS	9NL = NUREG = 27369
49040F007'5	AUD4080075	HE 5	LOWHR-OOS	8094280038	8004280038	HES	BNL-NUREG-27512
наоченция	SA00804006	*LS	LU-00-80-113	H004280041	1400854008	RES	UNL-NUREL-27502
		FES	£4-60-04-142	×004280059	8904280059	иŁЯ	MC 80-04-02-LR
400000000	<b>8004080094</b>				0004200034		
<b>80000095 15</b>	4004080545	HES		9004280065	F9004580063	RES	#NL+NUREG-27545
8004084294	8001090290	RES		M0042H0G/1	8004280071	HES	HAL-MUREG-27116
4044064544	8004080290	HES		4004300042	8004303452	RES	UNL-NUREG-24872
							UNIT-HOWER-SHOLE
3004040302	8004040705	HES		8004500574	P004300574	HES	
<b>どのりゅうおいちょう</b>	X1041)X15A5	#FS		ALP-10P-14	A∩04U71413*	50-313 P	
R0040R0P11	4004080841	50=270 P	FGG=&A=5060	ANL/EIS-11	8620508048	PH .	
ANDIOROD75	8004080675	4E5		HAM-10144-6	8004020475*	THEREP	
		FES	EGG-LAFT-5084	94*+1533 H1	8004090464#	TOPSEP	
NAA040P000B	8004080684						
<del>የ</del> ያር4በ4በባሉዶ	80v4090Db8	HES	£6G= <b>£</b> A=8100	BA#=1607	#604580324#	50-302 P	
8004040154	8904098158	hE S		Ct =1=A +13	855241008	50-10 P	
80040A0315	8004091312	FE S		LEN-128 VI	#8004110225#	TOPREP	
8004090424	8004040324	HES		CEN-12A VS	6000L10223*	TOPREP	
4004100256	500410075B	HFS		CFNPU-210-4 HS	8004010501+	TUPREP	
4550010068	Ac04100328	HES	EG6-FA-5112	CH+1 030 043 E	8004220039*	50=316 P	
			LTR 141=100	CHAI DOD 053 E			
9304100574	8004100378	h I S	Cist lataling		H004220027*		
4004[00]A44	4004104594	⊬f S		CH-T 0HO 072 E	#00#220023*	50-316 P	
3004100111	4004100411	HES.	58C-60-19-11-01	C#*1 060030 E	471005540UA	50-316 P	
800410057	8004190587	RES		Ed=1 0+0040 E	8004220034*	50-316 P	
3004[0959]	8004100590	HES		anen	8004230032*	FOLA	
8004100594	M004100594	H1 8		EDK=[ (NP) H2	80040202714	TOPREP	
				EE+21=000a			D DAGE
8004100544	8104140599	14E 5			#004030132#		P-80044
5U34110521	8004110521	HF5		11-52-11	8004030134*		P = 80064
######################################	8004140L38	RF S	FGG+EA+409A	1 118=41-4765	8650101030548	PR	
800415anns	8004150008	HER		14 April 2015 112-04	#0041502A0#	TUPREP	7811F0116R
8004159615	5004150015	FES	NUREG-MAL -25546	1.FDU-21326	8004240294*	70-1308	15326
	8004150020	FE 9	HNL-NUREG 20855	4100-24195	8004230343*		79460288
80041St 050							
3004150321	8004150721	KF et	UNL-YUREG-24950	*t no=5 155a=1	8B04B90476*		80450262
9004 56925	4009150025		F1.G=£4=5099	ぺFDO→5☆22ム	4004210307*	100000	
9004156020	4004150029	4E8	UR 167807F10+155	*FAU=24235 R1	#404170020*	50-324 P	AONEO253R
406415603e	4004150036	nFS	Nº 4L/HASRD-7D	NF00=2470m	8004280507+	TUPREP	
	8904150038		F66=FA=\$100	hF00-21708	8004049333*	TUPREP	
A00415003A	4404124434	10-rii F				OPREP	
300415 JuSa	8004150056	MES	ECG-T+HP-5023	4FDG=247H0	5004100423	70-754	15781
811415 (06)	4004150065	115	NRC-91-76-215	10-23021	362650505	Pfi	-
900415006-	H004[54066	FFS		*UREG=0020 Va NOV	0004150430	YUREG	
	P004150152	HES	Y#9+54-80	NUPEG-ORSO VS NOE			
4004159157				MUNEU-0021 A2 MAI	1003270223	NUMEG	
A004151475	Aç04150475	r C S	47F = 418F C= \$ 1182	Westernian 1 918	90041H0160±	50=334 A	

k∤#1⊬1 01 ₹aF∀	WINH H	SUMJECT CATEGORY	OTHER REPORT	146454 146454	^CCE5510N 6494€₽	SUBJECT CATEBORY	OTHER REPORT RIGHMAN
		*******		***			*
4616EG=6547	FU0 1570 557	POREL		ANKE C \ L % = 1.315	8004030002	MUREG	UCRL=52738
41-15-14-14 V\$ 44	A004 \$1:0540	108EG		10RFG/[x=1429	8044180586	NUREG	ANL/ES-89
մ <b>եի հ</b> եսանը Մ. Ք Գ	A110504004	odk EG		7111-FG/E4-1452	8004299017	PUPES	ANL-CT+80-15
III FGmi at VI	#0040 FAUUA	DIREG		* UHt 6/CA+(550	8004240566	* UREG	
9616-1517-54	1004/101624	50-311 4	1	411HEG/CH=(337	8004140470	VOREG	ANL-79-108
				. =	,, .		H-12-17-100
onefGentur v2 %1	6000170310	t tikt ti		1JRE6/LR-1350	8004020139	NURFG	
1 AREG=05/1	900 115 1002	NUMEG		HIRE G/CH-1351	8004170329	SUREG	NOW 20/1050-4-9
* 44 E* 1305	4JU47UU206	huit u		1998EG/CH-1352	4004280024		ORNL/NUREG=64
	AUU4UHU141			VINEE / CP = 1372		HURES	ORAL/MUREG/TM=3
#UREG=2027 ##REG=4527 APP A	400405JUPA	70-135		94P+( +)	8004280048	UNAFE	ORNL/NUREG/TM+3
MUNICIPALITY APP 4	4004050004	10-135		221.41.43	8004300056*	50-70 F	, 19055
1 0215-0-51	MUD 1100751	utid£6		#1L =057	H004020158	PES	
auch Grunge	800650068	50-320 F	1	41L=0n2			
		50=320 F		414-084	R004230300	kF5	
MINEG-0662 AND 1	HU04211351+			H+ 2	8004080215	RES	
19466-75/035	MO042B0114*				8004290458*	50-390 A	
VURFG=757007 3.7.2	8004280075	50-354 )	•	SA1-161-74-PA	8004290474*	LUBRED	
				0.000.70 0.71			
MURE 670 P = 301	Agnu264075	PH	NE 15 45.	34NU77-0274	8004030201	99	
-UHEG/C1 =11379 vs	H004234305*	t HREG	NS1C=156	\$44077=0274	8004030284	PR	
9114F G/CH = 0 450	HU04210507+	· 17HEF		SAND77-0274	8004050287	Pk	
, 11HE GVC++ 1155	0104174336	+ <del>የ</del> የተ	04v/\U04F2\1,4+5	SAND 7 7 = 0 2 / 4	8004030288	PH	
%iffEg/Ex=0m58	9001049424	ATIME C	8116-41186-21051	SAND17-0214 C	8004240521	TOPKLP	
111667CH=11858	2004580024	NUMEG	74KD74-8244	544D77-02/4 D	8004240523	TOPREP	
4ilint 67(k=4951	8000150140	.UHEG		5AND77=0774 F	8004240527	TUPREP	
4,11KF PAL K#U & 2.5	4004150141*	1117 B\$ ()	LA=7927	844D77-0274 F	8004240549	TOPPEP	
ソルコトもノしは=137ゃ	8004280035	DUREG	8ANN79-1595	SEEY-77-064	8004030166	SECY	
*##£G/CP#@4K1	M101101115	<b>ብሀ</b> ሴቶ (s	0505•IMB	SECY=78-322	8004240150*	70-135	
##8F6/CH##986	4004540050	fail) h E ta	PNL-3297	3f C Y + 7 9 - 646	*4020901008	9 E. C. Y	
~URFG/C+=n9A8	4004549464	4UHEG	344579-0944	\$1CY-80-001	8004090162	SECY	
プロガチを入しれる1001	8004100025	LIBEC	ANT-NAKEC-21044	25CY+80-002	8004090321	SECY	
1166676841156	8004150028	HUPEG	944079-1088	S+ CY = おり−∪ 2カA	8004290072	SECY	
ARREPACH-TTOR	85000100058	1 UKEG	544079-2002	SFCY=#0=045	8004010051	SECY	
*UHEG/LH#1105	A+004540454	NUREG	99/11/2012	SECY-AN-054	8004093297	SECY	
178F E\CH=1 F49	4004550001	HUREG	LA-8077	StCY=HO=OH1A	3004290171	50-327 A	
NUHFG/CK+1109	M104111065	さいれたら	P*L~3187	5LCY-An=095	8104100039*	LUCFR	
10 KFU/1 H=1116	8004140455	NUREG		SFCY-Hu=LO/	800402002A*	LOCER	
, NwF@\CH-1152	8004580058	MINEG	URVL/DUREG/1M=3	SFCY=#0-120	8004240181	70-2805	
7UNE6/(R=112a	8004290007	<b>∿€19€</b> 6	1 IL = 1URFG=51101	5ECY#8v=131	#804040200	SFCY	
144EG/64=1134	90 14214278	HHEG	har=350P	SECY-#0-132	8004090061	50=320 P	
194EG/CR=1144	8101240565	INFE(	E66-2304	S+CY~&∪=\3o	8094300002	SECY	
" _ RF 6 / C H = 1 1 4 9	8004150033	1 DHEG	SA4079-2017	SFCY=80=139	9004010017*	LOCER	
14EG/1 K=1350	*#04150922	1,0626	944079-2081	SFCY-80-142	8004070148	SFCY	
એ₹EG/L K=1151	H004[500]4	* UREG	SA (D 14-2079	SFCY=80-100	8004100431*	10CF#	
∗ι•ƙ&G/(R=1191	4004244505	50-296	11ES-PTUVAS	SECY-80-177	R004230130*	SECY	
HIREG/CHELLOS	A004170341	NUMEG		SECY=BU=45	8004010051	70=2845	
WINERAL HE I SUS	8004100319	NUPEG	SAND 78+8237	Inletterk=6	8004180339*	50-320 R	
#146 E/CH+1203	6004100029	NUREG	EGG=2012	TOP 31-6	8004180096	50-201 P	
	_	•	<del></del>	-, -		'	
418FG/ER=1 c 28	8004250047	A 11H} G		TVA-TN75-1A MA	8004070363*	TOPREP	
				IVA/AUU-179/13	8004290467*	50-390 A	
				UC=329	8004300219*	hASTE MG1	15912
				1H 8150-0-040	8004150480*	50-537 A	
/ JRFC/CH=1510	HO04100591	NURES	4"L-/9-105	4ARD+0-0252	8004290371*	50-537 A	
+JREG/CK-1257	8004140478	441HE'L	CREARE IN-512	··· ·· · · · · · · · · · · · · · · · ·			
#UREG/Ch+1245	8004110048	KIIPEG	HEDL-THE 79-71	ACAP-7800 HSA	9004020402*	TOPREP	
SUREGICE-1264	H104290009	HINE (	4Rt 4174	4CAP=7402	F004280344*	TOPREP	
		17		*CAP=9520	8004240397*	50-204 P	
****EG/(**1273	H004210301	FUREG	PML-1595	*CAP#9645		30-E00 /	1021-3
SUPER/LH=1280	HO 04030005	KUSEG	98.14=103	*CAP=9691	******		1461-5
"UPEG/[ -1245	8004150326	AUNEG AUNEG		4041	80040204324	TOPREP	
1/19t G/C==130/	3004130326		4 VL=(1=80=10	40-E4 40-60 63	0000120701		
17PFG/CA-1409	8001150000	*UREG	544D79=2241	#R=50=10=80.02	8004150396*	50=553 X	
1 G/G-1 - 4 10 T	DA 11 JANA	ting []	544079-2013	Y/On1/508-77/42500	8004030299		
				YCNP+SMK \$	8004280510*	50=566 A	
				Y 0 11 A P = 1 - A	8004110444*	50-29 P	

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the doc! number and the symbol for the category of informat! within that docket; for example, 50-320 P. The docket su ject categories are defined in Appendix A.

Subject categories for nondocketed items are also enter in this column by symbol; for example, ACRS. These cat gories are defined in Appendix B and listed in the Content

ACCESSION NUMBER

	PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATEGORY	1
7812110289	7812110207	78/10/17	50~387	a
7812110291	7812110287	78/10/17	50-387	ŏ
7902040388	7902040387	79/01/18	MISC	u
7904110034	7904110030	79/03/30	PR	
7905190137	7905190134	79/05/15	50~312	ρ
7908010479	7908010475	80/07/20	50-320	Н
7900140247	7908140243	79/07/02	COMMISSIO	
7900150564	7908150559	79/07/11	50-358	Н
7908210253 7909290207	7908210247 7909290201	79/06/25 79/07/03	90-320 FDIA	н
7707270207	7707270201	77707703	LDIM	
8003190734	B003190717	80/01/28	50-128	P
80401EE00B	6004040468	60/03/19	50~124	F
8003310411	8003310406	80/03/19	50-124	Ħ
8003310415	B003310406	80/03/19	50-124	B
8003310416	8003310412	B0/03/03	40-215	
8003310417	8003310406	80/03/19	50~124	В
8003310421	2003310406	80/03/19	50-124	B
8003310427	8003310406	60/03/19	50-124	Ö
8003310432	E003310406	80/03/19	50-124	B
8003310439	8003310406	80/03/19	50-124	B
8004010006	B004010004	80/02/29	50-295	P
8004010009	8004010002	80/02/25	CONTRACT	
8004010017	B004010014	80/03/19	LOCFR	
8004010021	B004010016	B0/03/19	LOCFR	_
B004010040	B004010036	80/02/25	90-584	G
B004010042	8004010036	80/02/25	50-289	G
8004010044	8004010036	80/02/25	50-287	G.
8004010066	8004010061	80/02/21	71-9049	
8004010070	8004010064	80/02/23	50~209	G
8004010072	8004010064	80/02/23	50-207	G
8004010076	8004010064	80/02/23	50-289	G
8004010078	B004010064	80/02/23	50-289	Ğ
8004010081	B004010051	80/01/24	70-2845	_
8004010082	8004010064	80/02/23	50~209	G .
8004010085	8004010064	80/02/23	50-289	Q
	•			
8004010089	8004010064	80/05/53	50-269	G
8004010071	8004010051	80/01/24	70-2045	_
8004010093	8004010064	80/05/53	50-289	G
8004010095	8004010051	80/01/24	SECY	
8004010097	8004010051	80/01/24	SECA	
E004010101	8004010051	80/01/24	SECY	
8004010105	B004010051	80/01/24	SECY	
8004010106	8004010104	80/03/07	27-39	
8004010181	8004010163	80/03/18	50-268	Ρ
8004010186	8004010163	80/03/18	70~1308	
8004010189	8004010163	80/03/18	70-1308	
8004010195	8004010163	80/03/18	70-1308	
B004010214	8004010210	80/03/28	50-250	Р
8004010217	8004010216	60/03/25	50-313	R
8004010229	B004010227	80/03/11	50-274	P

HELESSIO	N HOUSEK			
ENCLOSURE	PRINCIPAL DECUMENT	DATE (SSUED	SUBJEC CATEGO	RΥ
8004010236	8004010231	B0/03/31	50-280	۳
8004010243	8004010237	80/03/24	50~271	P
B004010247	8004010244	1E\E0\08	50-52B	¥
8004010250	8004010242	60/03/56	50-466	Α
8004010275	8004010269	80/03/27	50-280	1
8004010299	8004010295	80/03/21	50-445	8
B004010300	B004010294	80/02/26	50-347	ō
8004010313	8004010311	80/03/24	50-338	Ğ
8004010326	8004010321	80/03/56	50-321	ñ
8004010337	E004010331	80/03/16	50-272	R
00010100007	0004010031	20703710	JU-212	n
B004010345	0004010340	80/03/21	50~508	Α
B004010347	B004010343	80/03/20	50~362	s
8004010348	8004010322	80/03/27	50-272	s
8004010351	B004010342	80/03/25	50-318	š
8004010358	B004010350	80/03/24	50-528	8
	200,010100	407 037 24	00-3EE	-
8004010366	6004010363	80/03/31	50-338	P
B00401036B	8004010364	80/03/28	50-318	5
8004010369	B004010362	80/03/20	50-213	5
8004010370	8004010356	80/03/27	50-272	š
8004010371	8004010360	80/03/27	50-327	8
	000-010000	00/03/2/	00-Je7	43
8004010379	8004010374	80/03/26	50-327	Q)
8004010381	B004010375	80/03/24	50~327	S
8004010383	B004010376	80/03/25	50-310	8
8004010387	8004010384	80/03/28	50-280	P
8004010388	8004010380	80/03/25	50-318	9
5554545555				
8004010370	8004010385	80/03/25	50-325	ទ
8004010398	0004010395	00/03/31	50~29	t
8004010400	8004010394	00/03/27	50~324	8
8004010402	B004010393	80/03/28	50~296	S
8004010403	8004010399	80/03/24	50-327	5
8004010404	8004010377	80/03/27	50~329	ŝ
8004010409	B004010405	80/03/27	50-261	i
B004010417	8004010407	80/03/27	50~336	Ś
8004010422	8004010415			3
B004010427	8004010419	80/02/21	RES	_
4004010427	2004010414	80/03/27	50~346	F
8004010429	8004010423	80/03/27	50~336	s
8004010435	B004010430	80/03/25	50-317	s
8004010440	8004010433	80/03/28	50~327	š
8004010441	B004010437	80/03/21	50-275	Ä
6004010448	8004010437	80/03/24	50-318	8
224.0131.10	2004010407	40703744	30-316	٥
8004010455	8004010452	80/03/27	50-263	S
8004010457	8004010454	80/03/21	50-298	R
800401045B	B004010451	80/03/28	50-257	8
8004010466	B004010460	80/03/28	50~260	ş
8004010467	8004010463	80/03/28	50-317	P
8004010468	8004010461	80/03/28	50-324	R
B004010471	8004010463	80/03/58		
8004010473	8004010469		50-317	P
8004010475		80/03/25	50-302	R
	E004010464	80/03/28	50-327	8
8004010477	8004010474	80/03/25	50~321	6

### TO PRINCIPAL DOCUMENTS

PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	SUBJECT	
EUCEOSOUS DOGGLICAL LEGGED	CATEGÜRY	PRINCIPAL DATE SUBJECT ENCLOSURE DOCUMENT IBSUED CATEGORY
8004010478 8004010051 80/01/24 8004010479 8004010447 80/03/25 8004010481 8004010467 80/03/21 8004010483 8004010469 80/03/24 8004010485 8004010460 80/03/24	SECY 50~302 R 50~316 S 50~302 R 50~219 S	8004020222 800402021B 80/03/06 50-389 9 8004020228 800402021B 80/03/06 50-389 9 8004020231 800402021B 80/03/06 50-389 9 8004020231 800402021B 80/03/06 50-389 9 8004020234 8004020237 8004020237 8004020379 \$8004020377 \$\$\$tats Prog
8004010491         9004010487         80/03/28           8004010494         8004010488         80/03/31           8004010495         8004010492         80/03/27           8004010497         8004010488         80/03/27           8004010499         80/03/26         80/03/26	50-259 9 50-302 R 50-305 P 50-302 R 50-271 S	8004020237     8004020218     80/03/04     50-387     0       8004020247     8004020242     80/03/11     50-257     0       8004020252     8004020242     80/03/11     50-257     0       8004020258     8004020242     80/03/11     50-257     0       8004020258     8004020247     80/02/28     50-275     P
8004010500 8004010473 80/03/25 8004010501 8004010478 80/03/27 8004010505 8004010504 80/03/28 8004010506 8004010502 80/03/28 8004010507 8004010503 80/03/24	50-316 S TOPREP 50-338 S 50-327 S 50-219 S	8004020263 8004020242 80/03/11 50-259 Q 8004020265 8004020218 80/03/06 50-387 Q 8004020266 8004020257 80/02/28 50-295 P 8004020270 8004020257 80/02/28 50-295 P 8004020271 8004020267 80/03/28 TOPREP
8004010510 8004010507 80/03/21 8004010513 8004010507 80/03/21 8004010515 8004010512 80/01/14 8004010769 8004010787 80/03/13 8004020011 8004020005 80/03/14	50-348 S 50-348 S 0A979 PT9 50-389 Q	8004020272 8004020218 80/03/04 50-387 0 8004020273 8004020288 80/03/04 40-2061 8004020274 8004020268 80/03/04 40-2061 8004020274 8004020268 80/03/04 40-2061 8004020277 8004020218 80/03/04 50-387 0
8004020028         8004020024         80/03/19           8004020035         8004020027         80/01/16           8004020036         8004020027         80/01/16           8004020037         8004020027         80/01/16           8004020043         8004020027         80/01/16	10CFR 50~395	8004020282     8004020218     80/03/04     50-387     0       8004020287     8004020285     80/03/28     50-155     R       8004020294     8004020273     80/03/21     50-397     8       8004020305     80/03/21     50-397     8       8004020310     80/03/21     50-397     8       8004020310     80/03/25     50-247     8
8004020047 8004020045 80/03/17 8004020054 8004020045 80/03/17 8004020058 8004020045 80/03/17 8004020057 8004020055 80/01/21 8004020051 8004020057 80/02/25	50-361 0 50-361 0 50-361 0 71-6387 WARTE MOT	B004020313     B004020311     B0/03/17     50-295     B       B004020316     B004020312     B0/03/28     50-327     B       B004020317     B004020315     B0/03/25     50-366     B       B004020320     B004020319     B0/03/31     50-219     P       B004020322     B004020321     B0/03/10     50-395     B
8004020042 8004020045 80/03/17 8004020073 8004020070 80/02/27 8004020077 8004020070 80/02/27 8004020077 8004020070 80/02/27 8004020079 8004020071 80/02/27	50-361	8004020323     8004020318     80/03/11     50-302     9       8004020330     8004020325     80/03/25     50-364     9       8004020337     8004020332     80/03/26     50-249     9       8004020338     80/03/28     50-249     1       8004020339     80/03/28     50-247     1       8004020340     8004020335     80/03/03     50-424     6
8004020102 8004020089 80/03/17 8004020105 8004020081 80/03/10 8004020106 8004020089 80/03/17 8004020107 8004020104 80/03/21 8004020107 8004020091 80/03/10	State Prog 50-3 O State Prog 50-289 O 50-3 G	8004020341 8004020339 80/03/10 50-397 K 8004020344 8004020333 80/03/25 50-264 9 8004020346 8004020342 80/03/28 50-368 9 8004020347 8004020343 80/03/24 50-364 9 8004020353 8004020349 80/03/28 50-313 8
8004020114 8004020112 80/03/19 8004020115 8004020091 80/03/10 8004020116 8004020111 80/02/09 8004020118 8004020091 80/03/10 8004020119 8004020113 80/03/13	50-287 H 50-3 O ACRS 50-3 O 50-445 M	8004020355 8004020352 80/03/22 50-265 8 8004020357 8004020350 80/03/20 50-254 9 8004020358 8004020348 80/03/27 50-365 9 8004020359 8004020348 80/03/27 50-321 9 8004020362 8004020356 80/03/28 50-271 8
8004020120         8004020111         80/02/09           8004020122         8004020113         80/03/13           8004020123         8004020111         80/02/09           8004020125         8004020071         80/03/10           8004020126         8004020110         80/03/19	ACRS 50-445 M ACRS 50-3 G 50-286 D	8004020364 8004020360 80/03/05 71-280 8004020365 8004020361 80/03/24 50-366 8 8004020367 8004020363 80/03/25 50-249 9 8004020371 8004020366 80/03/17 50-327 8 8004020374 8004020372 80/03/14 50-213 R
8004020128 8004020111 80/02/09 8004020131 8004020111 50/02/09 8004020137 8004020129 80/02/21 8004020138 8004020111 80/02/09 8004020141 8004020111 80/02/09	ACRS ACRS 71-5739 ACRS ACRS	8004020376 8004020369 80/03/17 50-295 8 8004020380 8004020373 80/03/05 71-13 8004020384 8004020381 80/03/12 50-335 8 8004020386 8004020383 80/03/28 50-219 R 8004020388 8004020385 80/03/24 50-390 A
B004020144         8004020111         80/02/09           8004020161         8004020157         80/03/31           8004020162         8004020152         80/03/14           8004020163         8004020154         80/03/14           8004020164         8004020149         80/02/28	ACRS 30-404 R 50-528 Q 50-272 P 50-445 M	B004020391
8004020168 B004020152 B0/03/17 8004020171 B004020152 B0/03/17 8004020175 B004020149 B0/02/28 8004020176 B004020170 B0/03/10 8004020177 B004020173 B0/03/10	50-528 Q 50-520 G 50-445 M State Prog COMMISSION	8004020418 8004020408 80/03/31 50-213 F 8004020419 8004020413 80/03/10 50-373 F 8004020421 8004020417 80/03/28 50-439 9 8004020424 8004020409 80/03/31 50-213 F 8004020427 8004020422 80/03/14 50-254 8
8004020180 8004020152 80/03/17 8004020181 8004020147 80/02/28 8004020188 8004020187 80/03/11 8004020190 8004020187 80/03/18 8004020194 8004020187 80/03/11	50-528	8004020432 8004020427 80/03/31 TOPREP 8004020434 8004020423 80/02/14 QA797 8004020436 8004020431 80/03/27 50-438 8 8004020437 8004020428 80/03/25 50-366 8 8004020434 8004020435 80/03/17 50-265 8
8004020197         8004020193         80/03/24           8004020198         8004020149         80/03/28           8004020199         8004020195         80/03/03           8004020203         8004020193         80/03/24           8004020204         8004020193         80/03/24	50-553 A 50-445 M COMM1881ON 50-583 A 50-553 A	8004020449     8004020430     80/03/24     50-265     8       8004020447     8004020440     80/03/27     50-327     8       8004020458     8004020454     80/03/03     50-320     4       8004020459     8004020461     80/03/03     50-320     H       8004020469     8004020464     80/03/18     TUPREP
8004020201 8004020193 80/03/24 8004020211 8004020201 80/02/27 8004020215 8004020205 80/02/15 8004020220 8004020201 80/02/27 8004020221 8004020201 80/02/28	150-553 A 50-395 Q CONTRACT 50-395 Q 50-320 H	8004020471 8004020467 8D/03/07 XPDRTLIC 8004020474 8004020468 8D/03/20 50-522 0 8004020475 8004020464 8D/03/18 TOPREP 8004020477 8004020472 8D/03/17 XPDRTLIC 8004020481 8004020473 8D/03/12 50-964 A

SUBJECT CATEGGRY

70-2478 50-213 P 50-289 H PR 70-1201

70~1201 50-10 G 70-1201 50-10 G 50-341 G

50-254 0 50-255 0 50-373 0 70-143 XPORTLIC

70-143 50-546 Q 70-143 XPORTLIC 50-341 Q

50-312 Q 50-458 8 50-483 Q 50-483 Q 50-344 T

50-344 T PROJ 50-344 T 50-483 Q 50-344 T

50-483 G 50-445 G 70-1151 50-313 G 50-317 P

70-1151 50-445 Q 40-8135 QA999 50-317 P

50-317 P XPORTLIC 70-143 CONTRACT GA999

71-9010 50-416 G 50-346 G 50-267 G 50-267 G

70-27 50-312 Q 50-267 Q 70-27

## CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION	4 NUMBER				ACC	ESSION	NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR'	,	ENCLOS		PRINCIPAL DOCUMENT	DATE ISSUED
8004020482 8004020485	8004020477 8004020473	80/03/24 80/03/12	40-7127 50-364	Α	800403 800403	30362 30366	8004030323 8004030365	B0/03/11 B0/02/26
8004030003 8004030014 8004030018	8004030001 8004030011 8004030016	80/03/04 80/03/26 80/03/11	40-8745 CONTRACT 50-3	н	800404 800404 800404	40008	8004040002 8004040007 8004040012	80/03/19 80/03/03 80/03/13
8004030023 8004030024 8004030025	8004030020 8004030016 8004030016	80/03/19 80/03/11 80/03/11	CONTRACT 50-3 50-3	H	B00404 B00404	40019	B004040012 B004040014 B004040012	80/03/13 80/03/13
8004030029 8004030033	8004030019 8004030019	80/03/03	50-320 50-320	H	800404 800404 800404	40023	8004040012 8004040014 8004040022	80/03/13 80/03/13
8004030037 8004030038 8004030044	8004030032 8004030035 8004030040	80/03/17 80/03/03 80/05/05	CONTRACT 50-320 CONTRACT	н	800404 800404	40035	8004040029 8004040032	80/02/12 80/02/13
8004030044 8004030054	8004030043 8004030052	80/03/12 80/03/03	XPORTLIC 50-320	н	800404 800404 800404	40041	8004040036 8004040037 8004040038	80/02/15 80/02/08 80/03/27
8004030065 8004030071	8004030061 8004030070	80/03/03 80/03/05	50-320 50-320	H	B00404 B00404	40046	8004040037 8004040043	80/02/08 80/02/15
8004030093 8004030118 8004030128	8004030087 8004030102 8004030124	80/03/12 80/03/12	50~320 50~320 50~280	H P	800404 800404 800404	40049	8004040037 8004040045 8004040050	80/02/08 80/03/27 80/02/16
8004030129 8004030131	8004030123 8004030130	80/03/03 80/03/31	50-320 50-247	H G	800404 800404	40057	8004040054 8004040056	80/02/22 80/02/01
8004030132 8004030133 8004030134	8004030130 8004030130 8004030130	80/03/31 80/03/31	50-267 50-267 50-267	а О О	800404 800404 800404	40062	8004040060 8004040060 8004040063	80/02/12 80/02/12 80/03/17
8004030136 8004030141	8004030130 8004030140	80/03/31 80/03/31	50-267 50-204	Q P	900404 900404	40068	8004040063 8004040058	80/03/17 80/03/13
8004030145 8004030154 8004030161	8004030140 8004030153 8004030160	80/03/31 80/03/12 80/02/21	50-206 50-320 50-331	P H R	800404 800404 800404	40071	8004040063 8004040064 8004040063	80/03/17 80/03/20 80/03/17
8004030168 8004030178	8004030166 8004030175	77/02/02 80/04/01	8ECY 50-395	ĸ	B00404 800404	40083	8004040064 8004040081	80/03/20 80/03/11
8004030185 8004030186 8004030190	8004030183 8004030181 8004030183	80/04/02 80/04/01 80/04/02	50-339 50-361 50-339	A A	900404 900404 900404	40094	8004040089 8004040091	80/02/08 80/02/26 80/03/10
8004030193 8004030194	8004030183 8004030172	80/04/02 80/03/28	\$0~339 50~348	A P	800404 800404	40101	B0040400B0 B00404009B	80/02/08 80/03/11
8004030195 8004030197 8004030200	8004030183 8004030194 8004030183	80/04/02 80/03/31 80/04/02	50-339 50-334 50-339	A R A	800404 800404 800404	40104	8004040095 8004040100 8004040091	80/02/07 80/02/28 80/03/10
8004030202 8004030205	8004030199 8004030193	80/03/28 80/04/02	50-249 50-339	P	800404 800404	40114	8004040091 8004040110	80/03/10 80/03/12
8004030206 8004030214 8004030218	8004030183 8004030212 8004030216	80/03/26 80/03/26 80/03/28	50-337 50-348 50-333	A R B	800404 800404 800404	40120	8004040113 8004040116 8004040111	80/03/12 80/02/20 80/02/06
8004030220 8004030221	8004030217 8004030219	80/03/31 1E/E0/08	50-255 50-338	R	800404 800404	40125	8004040121 8004040084 8004040115	80/03/26 80/02/12 80/03/18
8004030224 8004030226 8004030237	8004030223 8004030225 8004030235	80/03/31 80/03/28 80/03/19	50-287 50-338 GA777	8	80040 80040 80040	40133	8004040128 8004040128	BO/02/19 BO/02/19
8004030238 8004030239	8004030236 8004030235	80/04/01 80/03/19	8EE-08 999AD 999AD	ĸ	80040 80040 80040	140139	8004040130 8004040126 8004040128	80/02/04 80/03/17 80/02/19
8004030242 8004030243 8004030244	8004030235 8004030240 8004030235	80/03/19 80/04/01 80/03/19	50-344 GA999	p	80040- 80040-	40144	B004040130	80\05\09
8004030247 8004030252 8004030255	8004030244 8004030251 8004030251	80/02/28 80/02/14 80/02/16	50-278 50-306 50-306	0 0	80040 90040 90041			
8004030256 8004030264	8004030249 8004030260	80/03/26 79/11/13	50-250 50-320	0	800%			
8004030270 8004030278 8004030279	8004030266 8004030273 8004030272	80/03/28 80/03/27 80/03/12	50-280 50-333 50-320	6 8 P				
8004030280 8004030283	8004030274 8004030272	80/03/07 80/03/12	XPORTL10 50-320					
8004030285 8004030270 8004030308	8004030282 8004030232 8004030303	80/03/25 80/03/31 80/03/27	50-335 50-336 F01A	8 P				
8004030312 8004030316	8004030303 8004030303	80/03/27 80/03/27	FOIA FOIA					
8004030319 8004030321 8004030324	8004030303 8004030303 8004030303	80/03/27 80/03/27 80/03/27	FOIA FOIA FOIA					
8004030324 8004030327 8004030328	8004030303 8004030303	80/03/27 80/03/27	FOIA FOIA					
8004030330 8004030333 8004030340	8004030303 8004030329 8004030335	80/03/27 80/03/20 80/03/20	40-2061 50-312 COMMISSI	Q ON				
8004030350 8004030359	8004030335 8004030354	80/03/24 80/03/05	50-298 71-9142	Q				

## CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESSION (				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 155UED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	٧
8004040197 8004040198 8004040199 8004040206 8004040208	8004040191 8004040184 8004040195 8004040205 8004040203	80/02/27 80/03/21 80/02/16 80/03/30 80/02/13	CONTRACT 50-445 50-10 50-245 50-566		8004040409 8004040410 8004040411 800400403	8004040394 8004040405 8004040407 8004040400 8004040414	80/03/24 80/02/16 80/02/08 80/03/31 80/02/16	50-498 50-263 50-293 50-331 50-546	6 G G S
8004040213 8004040217 8004040222 8004040233 8004040234	8004040207 8004040212 8004040201 8004040202 8004040225	80/02/15 80/03/19 80/02/15 80/03/05 80/02/28	70-82 CONTRACT 50-414 50-320 50-320	Н Н	8004040424 8004040426 8004040427	8004040419 8004040420 8004040416 8004040419 8004040420	80/03/24 80/02/06 80/04/01 80/03/24 80/02/06	FOIA 50-424 50-321 FOIA 50-424	0 5 0
8004040237 8004040242 8004040245 8004040248 8004040250	8004040211 8004040232 8004040214 8004040215 8004040232	80/03/03 80/02/05 80/03/03 80/03/03 80/02/05	50-320 50-280 50-320 50-320 50-280	О Н Н	8004040432 8004040434 8004040437	8004040421 8004040417 8004040425 8004040417 8004040427	80/03/05 80/03/24 80/03/28 80/03/24 80/03/31	50-320 FOIA 50-335 FOIA 50-366	н я 8
8004040253 8004040254 8004040256 8004040257 8004040258	8004040219 8004040249 8004040246 8004040247 8004040220	B0/03/03 B0/03/26 B0/01/29 B0/02/28 B0/03/03	50~320 50-336 ACR8 50-320 50-320	Н Р Н	B0040402 90404043 904040444	8004040436 8004040419 8004040425 8004040436 8004040439	80/02/16 80/03/24 80/03/28 80/02/16 80/03/18	50-315 FOIA 50-339 50-315 50-302	Q R Q Q
8004040259 8004040262 8004040263 8004040265 8004040267	8004040232 8004040252 8004040223 8004040218 8004040261	80/02/05 80/02/05 80/03/03 80/03/03 80/02/06	50-280 50-285 50-320 50-320 50-409	0 H H	8004040447 8004040448 8004040449	8004040419 8004040439 8004040425 8004040439 8004040439	80/03/24 80/03/18 80/03/28 80/03/16 80/03/18	40-8760 50-302 50-335 50-302 50-302	0 R Q
8004040274 8004040275 8004040277 8004040280 8004040287	8004040272 8004040271 8004040272 8004040278 8004040283	80/03/11 80/01/17 80/03/11 80/03/28 80/01/17	NUREG ACRS NUREG 50-341 ACRS	A	6004040454 6004040464 6004040475	8004040450 8004040435 8004040435 8004040471 8004040476	80/03/07 80/03/07 80/03/07 80/02/16 80/03/10	40-2061 CONTRACT CONTRACT 50-329 GA999	<b>Q</b>
6004040288 6004040289 6004040292 6004040295 6004040296	8004040284 8004040232 8004040283 8004040271 8004040271	80/03/27 80/02/05 80/01/17 80/03/29 80/03/29	50-219 50-200 ACRS 50-317 50-317	\$ 0 0	8004070009 8004070014 8004070015	8004070003 8004070006 8004070010 8004070011 8004070018	80/03/07 80/03/14 80/03/17 80/03/07 80/03/17	CONTRACT CONTRACT 71-7079 50-320 71-7080	P
8004040297 8004040298 8004040299 8004040301 8004040311	8004040293 8004040283 8004040285 8004040291 8004040309	80/03/31 80/01/17 80/02/20 80/03/29 80/04/02	50-261 ACRS 50-315 50-317 50-155	P Q Q P	8004070032 8004070034 8004070036	8004070021 8004070025 8004070029 8004070033 8004070035	80/03/10 80/03/20 60/03/08 80/03/19 80/03/07	71-185 CONTRACT XPORTLIC 50-285 50-400	Q Q
8004040323 8004040324 8004040332 8004040333 8004040337	8004040305 8004040317 8004040329 8004040326 8004040326	80/03/31 80/03/31 80/03/31 80/03/31	50-261 50-272 50-271 TOPREP TOPREP	R S S	8004070043 8004070049 8004070054	8004070040 8004070035 8004070046 8004070046 8004070046	80/03/21 80/03/07 80/03/03 80/03/03 80/03/03	50-271 50-400 70-143 70-143 70-143	P Q
8004040338 800404033 <del>7</del> 8004040343 8004040344 8004040345	8004040331 8004040316 8004040340 8004040336 8004040335	80/03/30 80/02/20 80/04/01 80/03/27 80/01/22	50-213 50-275 50-359 50-320 50-458	R Q I S A	8004070063 8004070066 8004070071	8004070057 8004070056 8004070056 8004070070 8004070075	80/03/11 80/03/26 80/03/26 80/03/17 80/03/17	50-498 50-281 50-281 50-483 50-327	0 0 H H
8004040347 8004040348 8004040349 8004040350 8004040351	8004040328 8004040476 8004040336 8004040340 8004040328	80/03/13 80/03/10 80/03/27 80/04/01 80/03/13	50-250 0A979 50-320 50-358 50-250	G S I Q	800407009) 8004070083 8004070087	8004070076 8004070076 8004070076 8004070076 8004070076	80/03/04 80/03/04 80/03/04 80/03/04 80/03/04	0A999 0A999 0A999 0A999	
8004040352 8004040355 8004040356 8004040359 8004040360	8004040476 8004040340 8004040335 8004040354 8004040328	80/03/10 80/04/01 80/01/22 80/03/31 80/03/13	QA999 50-358 50-458 50-334 50~250	I A F Q	8004070098 8004070099 8004070100	8004070076 8004070094 8004070089 8004070096 8004070089	80/03/04 79/12/31 80/03/04 80/02/22 80/03/04	0A999 50-3 40-6329 CONTRACT 40-6329	P
8004040361 8004040364 8004040365 8004040367 8004040368	8004040476 8004040363 8004040328 8004040363 8004040362	80/03/10 80/01/30 80/03/13 80/01/30 80/03/27	0A799 50-458 50-250 50-458 50-483	A Q A S	8004070107 8004070109 8004070110	8004070102 8004070089 8004070102 8004070102 8004070102	80/03/05 80/03/04 80/03/05 80/03/05 80/03/05	50-443 40-6329 50-443 50-443 50-443	Q Q Q Q
8004040372 8004040373 8004040376 8004040383 8004040384	8004040370 8004040370 8004040371 8004040358 8004040378	80/02/22 80/03/31 80/03/10 80/03/10	50-458 50-458 50-255 50-269 50-458	A R Q A	8004070117 8004070118 8004070119	8004070105 8004070114 8004070113 8004070115 8004070114	80/02/07 80/03/04 80/03/11 80/02/07 80/03/04	70-1100 50-322 50-348 70-398 50-322	G G
8004040386 8004040387 8004040387 8004040371 8004040397	8004040378 8004040380 8004040385 8004040377 8004040380	80/02/28 80/03/31 80/04/02 80/03/27 80/03/31	50-458 50-250 50-2 50-438 50-250	A R P S R	8004070123 8004070132 8004070135	8004070114 8004070114 8004070129 8004070130 8004070129	80/03/04 80/03/04 80/03/05 80/03/06 80/03/05	50-322 50-322 50-155 50-341 50-155	Q Q H G H
8004040399 8004040402 8004040403 8004040406 8004040408	8004040392 8004040358 8004040378 8004040394 8004040404	80/02/13 01/03/10 01/03/08 02/03/28 80/03/28	50-315 50-264 71-35 50-298 50-220	Q Q R R	8004070142 8004070152 8004070155	8004070125 8004070139 8004070147 8004070144 8004070150	80/02/25 80/02/29 80/03/13 80/02/20 80/03/17	CONTRACT 50-295 71-24 40-6659 50-438	Ç G

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGORY
8004070159 8004070162 8004070164 8004070165 8004070166	8004070144 8004070157 8004070144 8004070140 8004070157	80/02/12 80/02/12 80/02/10 80/02/10	40-6659 50-10 G 40-6659 50-313 P 50-10 G	600407038 600407038 600407038 600407039 600407039	2 8004070379 5 8004070379 8 8004070383 1 8004070379	80/03/07 80/03/07 80/03/07 80/03/07 80/03/27	50-387 0 50-387 0 70-364 50-387 0 70-364
8004070148 8004070149 8004070170 8004070171 8004070173	8004070150 8004070144 8004070160 8004070167 8004070167	80/03/17 80/02/20 80/03/10 80/02/15 80/02/15	50-438 Q 40~6659 50-313 P 50-483 Q 50-483 Q	800407037 800407039 800407040 800407040 800407041	6 B004070379 1 B004070383 3 B004070287	80/02/27 80/03/07 80/02/27 80/03/31 80/03/13	70-364 50-387 0 70-364 50-313 P 27-47
8004070174 8004070177 8004070178 8004070180 8004070183	8004070172 8004070150 8004070175 8004070148 8004070179	80/02/07 80/03/17 80/02/20 80/03/14 80/03/19	50-373 Q 50-438 Q 50-275 Q 8ECY 50-250 F	B00407041 B00407042 B00407042 B00407042 B00408000	0 8004070409 1 8004070418 5 8004070417	80/03/07 80/03/07 80/03/13 80/03/11 80/03/13	50-289 0 50-289 0 50-10 H State Prog 50-295 P
8004070188 8004070189 8004070202 8004070205 8004070207	8004070184 8004070195 8004070187 8004070194 8004070203	80/03/04 80/02/26 80/02/26 80/03/19 80/02/07	50 324 P 50-334 Q PR 50-3 H 70-1100	B0040B000 B0040B001 B0040B001 80040B001 B0040B001	1 8004080003 3 8004080003 4 8004080009	80/03/13 80/03/13 80/03/13 80/03/14 80/03/17	50-295 P 50-295 P 50-295 P XPDRTLIC 50-250 G
8004070208 8004070214 8004070217 8004070218 8004070223	8004070194 8004070194 8004070211 8004070213 8004070213	80/03/19 80/03/19 80/02/07 80/02/28 80/02/28	50-3 H 50-9 H 70-195 50-245 Q 50-245 Q	800408002 800408002 800408002 800408003	5 8004080019 7 8004080010 9 8004080021	80/03/19 80/04/01 80/03/19 80/03/11 80/03/19	50-250 Q 50-259 0 50-250 G 50-348 Q 50-250 Q
8004070224 8004070224 8004070229 8004070231 8004070233	8004070174 8004070213 8004070174 8004070213 8004070174	80/03/19 60/02/28 60/03/19 80/02/28 80/03/19	50-3 H 50-245 Q 50-3 H 50-245 Q 50-3 H	800408003 800408003 800408003 800408003 800408004	4 8004080021 6 8004080031 8 8004080010	80/03/13 80/03/11 80/03/07 80/03/19 80/03/11	50-445 M 50-348 Q TOPREP 50-250 Q 50-348 Q
8004070236 8004070241 8004070255 8004070256 8004070258	8004070234 8004070237 8004070251 8004070252 8004070251	80/03/27 80/01/10 80/03/12 80/03/25 80/03/12	50~349 A ACR8 50~528 8 50~331 R 50~528 S	800408004 800408004 800408004 800408005 800408005	8004080021 8 8004080037 1 8004080045	80/03/20 80/03/11 80/03/11 80/03/31 80/03/21	XPORTL1C 50-340 Q COMMISSION 50-289 Q 50-309 P
8004070268 8004070271 8004070276 8004070280 8004070283	8004070266 8004070270 8004070275 8004070277 8004070281	80/03/13 80/03/26 80/03/28 80/03/31 80/04/01	50-336 P 50-277 R 50-317 R 50-334 R 50-321 S	800408005 800408005 800408005 800408006 800408006	9 B0040B0037 0 B0040B0046 3 B0040B0037	80/02/28 80/03/11 80/03/19 80/03/11 80/03/11	40-3453 COMMISSION FOIA COMMISSION COMMISSION
8004070285 8004070289 8004070291 8004070294 8004070298	8004070284 8004070288 8004070290 8004070293 8004070297	80/03/31 80/03/31 80/03/31 80/03/31	50-289 P 50-260 S 50-289 P 50-329 R 50-334 I	800408005 800408007 800408007 800408005 800408005	4 8004080042 6 8004080046 0 8004080046	80/03/31 80/03/31 80/03/18 80/03/18 80/03/13	50-255 Q 50-255 Q FOIA FOIA 50-275 Q
8004070300 8004070302 8004070305 8004070309 8004070310	8004070296 8004070299 8004070290 8004070307 8004070308	80/03/28 80/03/31 80/03/31 80/04/02 80/03/31	50-333 R 50-443 I 50-289 P 50-338 5 50-382 S	800408008 800408006 800408006 800408009 600408009	8 8004080079 8 8004080078 0 8004080046	80/03/18 80/03/25 80/03/13 80/03/18 80/03/18	FOIA XPORTLIC 50-295 0 50-150 I FOIA
8004070315 8004070316 8004070321 8004070322 8004070323	8004070295 8004070312 8004070317 8004070320 8004070319	80/03/06 80/03/25 80/03/28 80/03/31	50-400 Q 50-312 S 50-18 I 50-255 P 50-287 P	800408009 800408009 800408010 800408010 800408011	8 8004080046 9 8004080046 8 8004080071	80/03/18 80/03/18 80/03/18 80/03/14 80/03/18	71-9019 FOIA 50-193 I COMMISSION FOIA
8004070324 8004070325 8004070329 8004070330 8004070331	8004070314 8004070317 8004070328 8004070327 8004070295	80/03/28 80/03/31 80/03/31 80/03/26	50-344 8 50-289 P 50-433 R 50-249 S 50-400 Q	B0040B011 B0040B011 B0040B011 B0040B011 B0040B012	4 8004080109 5 8004080046 7 8004080046	80/03/18 80/03/18 80/03/18 80/03/18 80/03/18	71-9089 50-354 8 FOIA FOIA FOIA
8004070337 8004070339 8004070342 8004070343 8004070345	8004070333 8004070335 8004070338 8004070335 8004070338	80/04/04 80/03/31 80/03/31 80/03/31 80/03/31	50-324 S 50-320 R 50-206 R 50-320 R 50-206 R	800408012 800408013 800408013 800408013 800408013	94 8004080046 97 8004080105 97 8004080122	80/03/18 80/03/18 80/03/10 80/02/25 80/03/18	FOIA FOIA CONTRACT 50-338 G FOIA
8004070346 8004070347 8004070348 8004070352 8004070355	8004070341 9004070335 8004070338 8004070338 8004070353	80/03/31 80/03/31 80/03/31 80/03/31 80/03/17	50~334 8 50~320 R 50~206 R 50~206 R WASTE MOT	800408013 800408013 800408014 800408014	64 B0040B0046 B0040B0046 B0040B0135	80/03/18 80/03/18 80/03/18 80/02/25 80/03/07	FOIA FOIA FOIA 27-47 50-209 U
8004070357 8004070358 8004070359 8004070363 8004070370	8004070338 8004070354 8004070353 8004070360 8004070367	80/03/31 80/02/05 80/03/17 80/04/01 80/03/25	50-206 R 50-273 Q WASTE MOT TOPREP 50-397 A	80040801 80040801 80040801 80040801 80040801	6 8004080139 8 8004080143 8 8004080046	80/02/22 80/03/18 80/03/18 80/03/18	FOIA 50-289 Q 27-47 FOIA 50-289 Q
8004070371 8004070372 8004070373 8004070374 8004070375	8004070367 8004070367 8004070364 8004070367 8004070341	80/03/25 80/03/25 80/03/13 80/03/25 80/03/31	50-397 A 50-397 A 50-367 H 50-397 A 50-334 8	80040801 80040801 80040801 80040801	54 8004080157 57 8004080139 58 8004080160	79/08/17 80/03/13 80/02/22 80/03/11 80/03/18	40-2061 50-142 U 50-289 Q 50-546 A FOIA

ACCESSION	NUMBER					CESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 19SUED	SUBJECT CATEGOR		ENCLO:	SURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8004040197 8004040198 8004040199 8004040206 8004040208	8004040191 8004040184 8004040195 8004040205 8004040203	80/02/27 80/03/21 80/02/16 80/03/30 80/02/13	CONTRACT 50-445 50-10 50-245 50-566		80040- 80040- 80040- 80040- 80040-	40409 40410 40411 40413	8004040394 8004040405 8004040407 8004040400 8004040414	80/03/24 80/02/16 80/02/08 80/03/31 80/02/16	50-263 50-293 50-331	8008
8004040213 8004040217 8004040222 8004040233 8004040234	8004040209 8004040212 8004040201 8004040202 8004040225	80/02/15 80/03/19 80/02/15 80/03/05 80/02/28	70-82 CONTRACT 50-416 50-320 50-320	О Н	80040 80040 80040 80040 80040	40424 40426 40427	8004040419 8004040420 8004040416 8004040419 8004040420	80/03/24 80/02/06 80/03/24 80/02/06	50-321 FDIA	0 8 0
8004040237 8004040242 8004040245 8004040248 8004040250	8004040211 8004040232 8004040214 8004040215 8004040232	80/03/03 80/02/05 80/03/03 80/03/03 80/02/05	50-320 50-280 50-320 50-320 50-280	Н Э Н	80040 80040 80040 80040 80040	40432 40434	8004040421 8004040419 8004040425 8004040419 8004040429	80/03/05 80/03/24 80/03/28 80/03/24 80/03/31	FOIA 50-335 FOIA	H R S
8004040253 8004040254 8004040256 8004040257 8004040258	8004040219 8004040249 8004040246 8004040247 8004040220	80/03/03 80/03/26 80/01/29 80/02/28 80/03/03	50-320 50-336 ACRS 50-320 50-320	H P H H	80040 80040 80040 80040 80040	40442 940443 940444	804040436 804040419 804040425 804040436 804040439	80/02/16 80/03/24 80/03/28 80/02/16 80/03/18	FOIA 50-335 50-315	Q Q Q
8004040259 8004040262 8004040263 8004040265 8004040267	8004040232 8004040252 8004040223 8004040218 8004040261	80/02/05 80/02/05 80/03/03 80/03/03 80/02/06	50-280 50-285 50-320 50-320 50-409	9 4 4 0	80040 80040 80040	140446 140447 140448 140449 140452	8004040419 8004040439 8004040425 8004040439 8004040439	80/03/24 80/03/18 80/03/28 80/03/18 80/03/18	50-335 50-302	Q R G
8004040274 8004040275 8004040277 8004040280 8004040287	8004040272 8004040271 8004040272 8004040278 8004040283	80/03/11 80/01/17 80/03/11 80/03/28 80/01/17	NUREG ACRB NUREG 50-341 ACRB	A	80040 80040 80040	040453 040454 040464 040475 040479	8004040450 8004040435 8004040435 8004040471 8004040476	80/02/13 80/03/07 80/03/07 80/02/16 80/03/10	40-2061 CONTRACT CONTRACT 50-329 GAPPP	9
8004040288 8004040289 8004040292 8004040295 8004040296	8004040284 8004040232 8004040283 8004040291 8004040291	80/03/27 80/02/05 80/01/17 80/03/29 80/03/29	50-219 50-280 ACRS 50-317 50-317	0 0	80040 80040 80040	070007 070009 070014 070015	8004070003 8004070006 8004070010 8004070011 8004070018	80/03/07 80/03/14 80/03/17 80/03/07 80/03/17	CONTRACT CONTRACT 71-9079 50-320 71-9080	þ
8004040297 8004040298 8004040299 8004040301 8004040311	8004040293 8004040283 8004040285 8004040291 8004040309	80/03/31 80/01/17 80/02/20 80/03/29 80/04/02	50-261 ACRS 50-315 50-317 50-155	P Q Q P	80040 80040 80040	070022 070032 070034 070034 070039	8004070021 8004070025 8004070029 8004070033 8004070035	80/03/10 80/03/20 80/03/08 80/03/19 80/03/07		G G
8004040323 8004040324 8004040332 8004040333 8004040337	8004040305 8004040317 8004040329 8004040326 8004040326	80/03/31 80/03/31 80/03/31 80/03/31	50-261 50-272 50-271 TOPREP TOPREP	R S S	80040 80040 80040	)70042 )70043 )70049 )70054 )70059	8004070040 8004070035 8004070046 8004070046 8004070046	80/03/21 80/03/07 80/03/03 80/03/03 80/03/03		P G
8004040339 8004040339 8004040343 8004040344 8004040345	8004040331 8004040316 8004040340 8004040336 8004040335	80/03/30 80/02/20 80/04/01 80/03/27 80/01/22	50-213 50-275 50-358 50-320 50-458	R Q I S A	80040 80040 80040	070060 070063 070066 070071	8004070057 8004070056 8004070056 8004070070 8004070075	80/03/11 80/03/24 80/03/26 80/03/17 80/03/17	50-281 50-281 50-483	0 0 H H
8004040347 8004040348 8004040349 8004040350 8004040351	8004040328 8004040476 8004040336 8004040340 8004040328	80/03/13 80/03/10 80/03/27 80/04/01 80/03/13	50-250 0A979 50-320 50-358 50-250	Q S I Q	80040 80040 80040	070079 070081 070083 070087 070090	8004070076 8004070076 8004070076 8004070076 8004070076	80/03/04 80/03/04 80/03/04 80/03/04 80/03/04	QA999 QA999 QA999 QA999 QA999	
8004040352 8004040355 8004040356 8004040359 8004040360	8004040474 8004040340 8004040335 8004040354 8004040328	80/03/10 80/04/01 80/01/22 80/03/31 80/03/13	GA999 50-358 50-458 50-334 50-250	I A F Q	80040 80040 80040	070091 070098 070099 070100 070104	8004070076 8004070094 8004070089 8004070096 8004070089	80/03/04 79/12/31 80/03/04 80/02/22 80/03/04	QA777 50-3 40-6327 CONTRACT 40-6327	p
8004040361 8004040364 8004040365 8004040367 8004040368	8004040476 8004040363 8004040328 8004040363 8004040362	80/03/10 80/01/30 80/03/13 80/01/30 80/03/27	0A999 50-458 50-250 50-458 50-483	A Q A B	80040 80040 80040	070106 070107 07010 <del>9</del> 070110 070111	8004070102 8004070089 8004070102 8004070102 8004070102	80/03/05 80/03/04 80/03/05 80/03/05 80/03/05	50-443 40-6329 50-443 50-443	9 9
8004040372 8004040373 8004040374 8004040383 8004040384	8004040370 8004040370 8004040371 8004040358 8004040378	80/02/22 80/03/31 80/03/10 80/03/10	50-458 50-458 50-255 50-269 50-458	A A R G A	80040 80040 80040	070112 070117 070118 070119 070120	8004070105 8004070114 8004070113 8004070115 8004070114	80/02/07 80/03/04 80/03/11 80/02/07 80/03/04	70-1100 50-322 50-348 70-398 50-322	0 0
8004040386 8004040387 8004040389 8004040391 8004040397	800404037B 8004040380 8004040385 8004040377 8004040380	80/02/28 80/03/31 80/04/02 80/03/27 80/03/31	50-458 50-250 50-2 50-438 50-250	A R P B R	80040 80040 80040	070121 070123 070132 070135 070137	8004070114 8004070114 8004070129 8004070130 8004070129	80/03/04 80/03/04 80/03/05 80/03/06 80/03/05	50-322 50-322 50-155 50-341 50-155	0 0 H 0 H
8004040399 8004040402 8004040403 8004040406 8004040408	8004040372 8004040358 8004040378 8004040376 8004040404	80/02/13 80/03/10 80/03/10 80/03/28 80/03/28	50-315 50-269 71-35 50-298 50-220	Q Q R R	80040 80040 80040	070140 070142 070152 070155 070158	8004070125 8004070137 8004070147 8004070144 8004070150	80/02/25 80/02/29 80/03/13 60/02/20 80/03/17	CONTRACT 50-295 71-24 40-6659 50-438	G G

SUBJECT CATEGORY

> G G

> a

q

00000

М О О

50-387

50-347 50-347 70-364 50-387 70-364

70-364 50-387 70-364 50-313 27-47

50-269 Q 50-269 Q 50-10 H State Prog 50-295 P

50-295 50-295 50-295 XPORTLIC 50-250

50-250 50-269 50-250 50-348 50-250

50-445 50-348 TOPREP 50-250 50-348

XPORTLIC 50-348 Q COMMISSION 50-287 Q 50-309 P

40-3453 COMMIBBION FOIA COMMISSION COMMISSION

50-255 50-255 FOIA FOIA 50-295

FO1A XPORTLIC 50-295 0 50-150 1 FOIA

## CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESSIO	ON NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 15SUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE (SSUED
8004070159 8004070162 8004070164 8004070165	B004070144 B004070157 B004070144 B004070160	80/02/20 80/02/12 80/02/20 80/03/10	40-6659 50-10 40-6659 50-313	<u>-</u> -	8004070382 8004070385 8004070388 8004070381	8004070379 8004070379 8004070383 8004070379	80/03/07 80/03/07 80/03/07 80/03/07
8004070166 8004070168 8004070169 8004070170	8004070157 8004070150 8004070144 8004070160	80/02/12 80/03/17 80/02/20 80/03/10	50-10 50-439 40~6659 50-313	0 0 P	8004070392 8004070394 8004070396 8004070401	8004070383 8004070383 8004070379 8004070383	80/02/27 80/02/27 80/03/07 80/02/27
8004070171 8004070173	8004070167 8004070167 8004070172	80/02/15 80/02/15 80/02/07	50~483 50~483 50~373	9	B004070403 B004070414 B004070416	8004070287 8004070410 8004070409	80/03/31 80/03/13 80/03/07
8004070177 8004070178 8004070180 8004070183	8004070150 8004070179 8004070148 8004070179	80/03/17 80/02/20 80/03/14 80/03/17	50-438 50-275 8ECY 50-250	Q Q F	8004070420 8004070421 8004070426 8004080005	8004070409 8004070418 8004070417 8004080003	80/03/07 80/03/13 80/03/11 80/03/13
8004070188 8004070199 8004070202 8004070205 8004070207	6004070184 6004070195 6004070187 6004070194 6004070203	80/03/04 80/02/26 80/02/26 80/03/19 80/02/07	50 -324 50 -334 PR 50-3 70-1100	Q H	B0040B00B B0040B0011 B0040B0013 B0040B0014 B0040B0015	8004080003 8004080003 8004080009 8004080009	86/03/13 80/03/13 80/03/13 80/03/14 80/03/19
8004070208 8004070214 8004070217 8004070218 8004070223	8004070194 8004070194 8004070211 8004070213 8004070213	80/03/19 80/02/28 80/02/28	50-3 50-3 70-135 50-245 50-245	H H G	B004080023 8004080025 8004080027 8004080029 8004080030	8004080010 8004080019 8004080010 8004080021 8004080010	80/03/19 90/04/01 80/03/19 80/03/11 80/03/19
8004070224 8004070226 8004070227 8004070231 8004070233	8004070194 8004070213 8004070194 8004070213 8004070194	80/03/19 80/02/28 80/03/19 80/02/28 60/03/19	50-3 50-245 50-3 50-245 50-3	HOH	8004080033 8004080034 8004080038 8004080038 8004080040	8004080028 8004080021 8004080031 8004080010 8004080021	80/03/13 80/03/11 80/03/07 80/03/19 80/03/11
8004070234 8004070241 8004070255 8004070254 8004070258	8004070234 8004070239 8004070251 8004070252 8004070251	80/03/27 80/03/12 80/03/25 80/03/12	50~369 ACR9 50~528 50~331 50~528	A S R S	8004080042 8004080043 8004080048 9004080051 8004080053	8004080039 8004080021 8004080037 8004080045 8004080047	80/03/21 80/03/11 80/03/31 80/03/21
8004070268 8004070271 8004070276 8004070280 8004070283	8004070266 8004070270 8004070275 8004070277 8004070281	80/03/13 80/03/26 80/03/28 80/03/31 80/04/01	50-334 50-277 50-317 50-334 50-321	P R R R S	8004080057 8004080059 8004080060 9004080063 8004080066	8004080055 8004080037 8004080046 8004080037 8004080037	80/02/28 80/03/11 80/03/18 80/03/11
8004070285 8004070287 8004070271 8004070274 8004070278	8004070284 8004070288 8004070290 8004070293 8004070297	80/03/31 80/03/31 80/03/31 80/03/31 80/03/31	50-289 50-240 50-289 50-329 50-334	P 8 P R 1	8004080047 8004080074 8004080080 8004080080 8004080083	8004080062 8004080062 8004080046 8004080046 8004080078	80/03/31 80/03/31 80/03/18 80/03/18 80/03/13
8004070300 8004070302 8004070306 8004070309 8004070310	8004070296 8004070299 8004070290 8004070307 8004070308	80/03/28 80/03/31 80/03/31 80/03/31 80/03/31	50-333 50-443 50-287 50-338 50-382	# P 5 8	#00408084 #00408085 #004080085 #004080090 #004080095	8004080046 8004080079 8004080078 8004080044 8004080046	80/03/18 80/03/13 80/03/18 80/03/18
8004070315 8004070316 8004070321 8004070322 8004070323	8004070295 8004070312 8004070317 8004070320 8004070319	80/03/04 80/03/25 80/03/28 80/03/31 80/03/31	50-400 50-312 50-18 50-255 50-289	0 8 P P	8004080077 8004080078 8004080108 8004080108 8004080110	f	
8004070324 8004070325 8004070329 8004070330 8004070331	8004070314 8004070317 8004070328 8004070327 8004070295	80/03/26 80/03/31 80/03/28 80/03/06	50-346 50-287 50-433 50-269 50-400	80 P R SI CI	8004080112 8004080114 8004080115 8004080117		
8004070337 8004070339 8004070342 8004070343 8004070345	8004070333 8004070335 8004070338 8004070335 8004070338	80/04/04 80/09/31 80/03/31 80/03/31 80/03/31	50-324 50-320 50-206 50-320 50-206	S R R R			
8004070346 8004070347 8004070348 8004070352 8004070355	8004070341 8004070335 8004070338 8004070338 8004070353	80/03/31 80/03/31 80/03/31 80/03/31 80/03/17	50-334 50-320 50-206 50-206 Waste Mg	B R R R			
8004070357 8004070358 8004070359 8004070363 8004070370	8004070338 8004070354 8004070353 8004070360 8004070367	80/03/31 80/02/05 80/03/17 80/04/01 80/03/25	50-206 50-293 Waste Mg Toprep 50-397	R Q T			
8004070371 8004070372 8004070373 8004070374 8004070375	8004070367 8004070367 8004070364 8004070367 8004070341	80/03/25 80/03/25 80/03/25 80/03/25	50-397 50-397 50-367 50-397 50-334	AAHAS			

ACCESS I OF					ACCESS101				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,
8004080176 8004080179 8004080183 8004080184 8004080184	8004080137 8004080046 8004080178 8004080046 8004080180	80/02/22 80/03/18 80/03/19 80/03/18 80/03/14	50-289 G FOIA 50-339 G FOIA 50-155 G	•	8004080424 8004080427 8004080435 8004080438 8004080440	8004080420 8004080422 8004080427 8004080436 8004080437	80/03/27 80/04/02 80/03/12 80/04/01 80/02/28	50-267 50-454 50-255	MBGRP
8004080169 8004080190 8004080192 8004080196 800408000	8004080046 8004080182 8004080046 8004080046 8004080175	90/03/18 80/02/27 80/03/18 80/03/18 80/03/17	FOIA 50-373 6 FOIA FOIA 50-289 6		8004080446 8004080450 8004080454 8004080459 8004080461	8004080442 8004080448 8004080453 8004080455 8004080455	80/04/01 80/02/19 80/04/03 80/04/04 80/04/04	50-344 50-213 50-325 50-369 50-369	R G B A A
8004080202 8004080204 8004080204 8004080208 8004080210	8004080046 8004080046 8004080193 8004080046 8004080207	80/03/18 80/03/18 80/03/05 80/03/18 80/02/24	FOIA FOIA 50-3 U FOIA 40-1341	;	80 04080462 80 04080463 80 04080464 80 04080467 80 04080475	8004080457 8004080456 8004080458 8004080457 8004080470	80/04/01 80/03/26 80/03/28 80/04/01 80/04/02	50-249	8888
8004080211 8004080213 8004080216 8004080218 8004080220	8004080046 8004080199 8004080046 8004080212 8004080217	80/03/18 80/03/11 80/03/18 80/03/06 80/02/29	FDIA 70-2254 FDIA 50-387 U 50-183 F		80 04080476 80 04080482 80 04080483 80 04080484 80 04080486	8004080471 8004080474 8004080477 8004080478 8004080474	80/04/04 80/04/02 80/04/02 80/04/03 80/04/02	50-280	8 8 8 8
8004080222 8004080227 8004080229 8004080230 8004080231	8004080046 8004080223 8004080223 8004080179 8004080223	80/03/18 80/03/07 80/03/07 80/03/11 80/03/07	FOIA COMMISSION COMMISSION 70-2254 COMMISSION	4	8004080487 8004080488 8004080476 8004080478 8004080501	8004080481 8004080480 8004080487 8004080491 8004080492	80/04/01 80/04/02 80/04/04 80/04/04 80/03/31	50-133 50-318 50-29 50-206 50-348	8 8 8 P R
8004080234 8004080241 8004080248 8004080250 8004080259	8004080223 8004080237 8004080199 8004080243 8004080104	80/03/07 80/03/18 80/03/11 80/03/06 80/03/25	COMMISSION CONTRACT 70-2254 COMMISSION XPORTLIC		8004080502 8004080504 8004080507 8004080509 8004080512	8004080497 8004080491 8004080500 8004080504 8004080503	80/04/02 80/04/04 80/04/03 80/04/01 80/04/02	50-334 50-206 50-317 50-344 50-267	8 8 1
8004080262 8004080264 8004080265 8004080266 8004080267	8004080255 8004080260 8004080257 8004080258 8004080255	80/03/14 80/03/10 80/03/20 80/03/17 80/03/14	50~335 F		8004080521 8004080524 8004080526 8004080527 8004080531	8004080511 8004080511 8004080519 8004080510 8004080518	80/03/28 80/04/01 80/04/02 80/04/02 80/03/31	50-387 50-293 50-327 50-316 50-331	8 8 8 8
8004080271 8004080272 8004080274 8004080276 8004080279	8004080258 8004080255 8004080258 8004080255 8004080255	80/03/19 80/03/14 80/03/19 80/03/14 80/03/14	QA999	3 3	8004080533 8004080536 8004080545 8004080547 8004080549	8004080525 8004080528 8004080510 8004080540 8004080541	80/04/01 80/04/03 80/04/02 80/04/02 80/03/25	50-272 50-338 50-316 50-348 50-10	9 8 8 8
8004080280 8004080282 8004080285 8004080287 8004080289	8004080275 8004080258 8004080273 8004080255 8004080286	80/03/19 80/03/19 80/03/06 80/03/14 80/02/29	50-333 (	3 4 1	8004080551 8004080554 8004080561 8004080564 8004080570	8004080548 8004080540 8004080552 8004080557 8004080565	80/03/31 80/04/02 80/03/28 80/04/01 80/03/19	50-54 50-348 50-249 50-245 70-143	R 8 8
8004080297 8004080300 8004080301 8004080303 80040803Q5	8004080291 8004080289 8004080271 8004080299 8004080288	80/03/17 80/03/13 80/03/17 80/03/27 80/03/13	QA999 40-1341 QA999 XPORTLIC 40-1341		8004080575 8004080581 8004080590 8004080594 8004080896	8004080557 8004080557 8004080557 8004080588 8004080577	80/03/31 80/04/01 80/04/01 80/02/26 80/04/01	50-325 50-245 50-245 50-155 50-368	9 1 1 0 8
8004080306 8004080307 8004080310 8004080313 8004080314	8004080271 8004080288 8004080274 8004080308 8004080288	80/03/17 80/03/13 80/02/20 80/02/27 80/03/13		P R	8004080599 8004080602 8004080608 8004080610 8004080622	8004080593 8004080400 8004080401 8004080403 8004080416	80/02/05 80/02/25 80/03/31 80/03/28 80/04/02	70-364 50-267 50-250 CONTRACT 50-327	0 9
8004080316 8004080323 8004080325 8004080327 8004080330	8004080291 8004080317 8004080320 8004080320 8004080320	80/03/17 80/03/14 80/03/17 80/03/17 80/03/17	50-280 I	N P P P	8004080623 8004080625 8004080628 8004080631 8004080635	8004080615 8004080617 8004080615 8004080615 8004080627	80/01/07 80/02/27 80/01/07 80/01/09 80/02/20	ACR8 50-254 ACR8 ACR9 50-373	G G
8004080333 8004080340 8004080341 8004080343 8004080344	8004080324 8004080324 8004080324 8004080334 8004080324	80/03/08 80/01/14 80/03/08 80/03/14 80/03/08	CONTRACT 50-317 ( 70-135	a a	8004080639 8004080640 8004080646 8004080647 8004080649	8004080615 8004080637 8004080615 8004080629 8004080645	80/01/09 80/03/18 80/01/09 80/02/20 80/03/24	ACR8 50-263 ACR8 50-373 50-341	Q Q
8004080394 8004080392 8004080354 8004080359 8004080365	8004080334 8004080324 8004080334 8004080348 8004080358	80/03/14 80/03/08 80/03/14 80/03/05 80/03/14	70-135	g R	8004080653 8004080655 8004080660 8004080661 8004080696	8004080644 8004080618 8004080654 8004080618 8004080691	80/03/11 80/01/07 80/03/14 80/01/09 80/02/14	50-309 ACRE 50-387 ACRE 50-285	H A Q
8004080369 8004080379 8004080380 8004080382 8004080389	8004080358 8004080358 8004080374 8004080358 8004080358	80/03/14 80/03/14 80/04/03 80/03/14 80/03/14	QA799 QA999 50-302 ( QA999 QA999	P	8004080707 8004080716 8004080733 8004070008 8004070017	8004080703 8004080703 8004080580 8004090005 8004090014	80/03/31 80/03/31 80/02/04 80/03/19 80/03/31	50-287 50-289 70-195 50-272 71-380	P P
8004080394 8004080405 8004080408 8004080411 8004080412	8004080370 8004080402 8004080402 8004080406 8004080402	80/03/91 80/03/04 80/03/91 80/03/06	50-255   50-255   50-309	7 P P R R	8004070035 8004070036 8004070041 8004070047 8004070057	8004070032 8004070032 8004070032 8004070032 8004070055	80/03/18 80/03/18 80/03/18 80/03/19	50-321 50-321 50-321 50-321 0A999	0 0 0

ACCESS	ION NUMBER				****	IGN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	UNIE	SUB.		N. C. 23	PRINCIPAL	DATE	SUBJE	ст
800409007	I 60040000				ENCLOSURE	DOCUMENT	IBSUED	CATEG	
800409007 800409007	800409006 B00409006	7 60/02/2	2 GA999	,	800409037	6 8004090369	80/03/28	50~409 0A999	₽
800409008 800409008	BOOMEGES.	7 80/02/2	2 04999		500407037 500407037	8004090370	80/03/50	70-1257	
B0040900B6		_		0 0	80040903B: 80040903B:		80/03/31	50~94 QA999	R
B004090108 B004090112	800409010	2 90.00.0			800407038		80/03/20	50~255	a
8004090121	800409011	5 80/03/1	3 70-12	57	900407038; 900407039;		80/03/20 80/02/20	0A999 50~438	a
8004090134	800409013	0 80\05\5	3 71-12 2 50-33		800407037 8004090400	8004090389	80/04/02 80/02/20	50~255 50~518	P
8004090137 8004090138	900409013			5 G				50~293	
8004090140 8004090146	HOGANDA LA	5 80/02/2	WASTE	3 <i>q</i> Mgt	8004090401 8004090404	8004090393	80/02/12	70-135	a
B004090146	800407014				8004090413 8004090415	8004090393	80/02/20 80/03/13	50~327 70~135	a
8004090153 8004090159	,0,013	80/02/01			5004090422	8004090417	80/02/14	50-219	G
8004090143	800409012	80/02/0	50-31	3 G	8004070424 8004070424		80/03/24 80/04/01	50~346 50~327	G B
8004090168 8004090169	8004000144	80/01/03	PR		5004090431 8004090433	6004090428	80/03/18	50-305	Q.
8004090170	,0,0100			) P	8004070438		80/04/03 60/02/13	50~327 50~352	8
8004090174 8004090194	8004070164	80/02/12			E004090440	6004090436	80/04/03	50-333	8
8004090195	8004090191 8004090173	80/02/24	50-184	a	8004090441 8004090457	8004090432 8004090453	80/02/26 80/04/03	50-443 50-327	6
8004090196	8004090188	80/02/15		, ,	8004090464 8004090472	8004070461 8004070470	80/03/26 80/04/03	TOPREP 50-293	P
8004090200 8004090202	8004090191 8004090198	00,00,10			8004090473	8004070467	80/03/06		
8004090203 8004090210	8004090201	80/03/21	71-373		B004090475	8004090471	80/03/31	50-293 50-293	Q. M
8004090211	8004090205 8004090191	80/03/13 80/03/10			8004090476 8004090478	8004090470 8004090477	80/04/03 80/04/03	50-293 50-320	P Î
6004090215	8004090205	80/03/13	50-201	a	8004090479	8004090477	80/04/03	50-320	1
8004070218 8004070219	8004090214 8004090217	80/03/21	71-372 50-335		80040904 <b>60</b> 80040904 <b>91</b>	8004690477 8004690477	80/04/03 80/04/03	50-320 50-320	I I
8004090221 8004090225	B004090205 B004090220	80/03/13 80/03/17	50-201	R Q	8004090482 8004090483	8004090477 8004090477	B0/04/03 B0/04/03	50-320 50-320	I
8004090224	8004090222		71-9		B0040704B4	8004090477	B0/04/03	50-320	I
8004090230 8004090235	8004070227	80/03/21	71-375 71-165		8004090485 8004100005	8004090263	80/03/17	CONTRACT	
6004090237	8004070232 8004070232	80/03/13 80/03/13	70-143 70-143		8004100007	8004100001 8004100003	80/02/22 80/02/22	9A999 50-184	G
8004090240	E004090232	80/03/13	70~143		8004100D07 8004100011	6004100003 6004100003	80/03/05 80/03/05	50-184 50-184	9
6004070244 6004070244	8004090232 8004090238	80/03/13 80/03/04	70-143 50-219	Q.	8064100514	B004100003	80/03/05	50-164	G.
8004090249 8004090251	800409023B 800409024B	80/03/04 80/03/31	50-219	0	8004100015 8004100016	B004100010 B004100013	80/03/24 80/02/21	50-289 50-346	G
B004090252	8004090245	80/02/19	50-329 50-259	ā	6004100022 8004100023	B004100013 B004100020	80/02/21	50~346	G G
8004070256 8004070258	8004090238	80/03/04	50-219	q	8004100030	B004100026	80/03/07	CONTRACT	
8004090262	8004070248 8004070238	80/03/31 80/03/04	50~329 50~219	K Q	8004100034	B004100031	80/02/22	70-820 GA999	
8004090269 8004090273	8004090260 8004090270	80/03/20 80/03/27	50-586 71-377	Н	8004100038 8004100039	8004100036 8004100033	80/03/13 80/03/28	71-9020 100FR	
8004090274	8004090268	80/03/10	50-320	н	8004100040	8004100035	80/03/11	5D-443	æ
8004090277 8004090278	8004090275 8004090272	80/03/19 80/02/25	50-250 50-373	F	8004100045 8004100050	8004100041 8004100041	80/02/26 80/02/26	PR PR	
8004090279 8004090283	8004090276	80/03/10	50-320	H	8004100051 8004100055	8004100045 8004100041	80/02/20	50-416	Q.
	8004090281	80/03/17	50-269	C	8004100056	0004100041	80/02/24	PR	
8004090285 8004090287	8004070280 8004070282	BQ/02/04 B0/03/14	70-135 0A999		8004100068 8004100070				
8004090290 8004090291	6004070282 6004070284	80/03/14 80/02/21	0A999 50-348	a	8004100077				
8004090293	8004070282	80/03/14	QA999	_	9004100091 9004100092				
8004090295 8004090299	8004070289 8004090282	80/03/17 80/03/14	50-289 GA999	e	8004100098				
10004090301	8004090297	80/01/28	SECY		8004100103 8004100104				
8004090302 8004090304	8004090294 8004090303	80/02/21 80/04/03	70-1201 50-298	R	8004100111 8004100112				
8004090306	8004090297	80/01/28	SECY		8004100127				
8004090310 8004090311	8004070307 8004070308	80/02/15 80/04/02	0A979 50~334	s	8004100126				
8004090315 8004090317	8004070313 8004070314	80/04/03 80/03/06	50-302 50-355	S	8004100130 8004100142				
8004090320	8004090318	80/04/02	50-333	R	8004100145				
8004090327	8004090319	80/02/25 80/03/26	50-2 50-219	Q	8004100150 8004100154				
8004090330 8004090336	8004090329 8004090333	80/04/03	50-327	Р Б	8004100157 8004100158				
8004090345	8004090341	80/04/03	50-416	Α .	8004100160				
8004090350 8004090355	8004090341 8004090351	80/04/03 80/02/21	50-416 50-302	A Q	8004100164 8004100168				
8004090361 8004090368	8004090354 8004090363	80/03/19 80/04/04	70-143 50-416	M	8004100173				
B004090374	8004090366	80/02/21	50-280	g	8004100182 8004100188				

ACCESSION						IN NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8004100191 8004100194 8004100200 8004100201 8004100202	8004100185 8004100189 8004100198 8004100197 8004100195	80/03/17 80/03/24 80/03/31 80/03/13 80/02/20	70-33 CDNTRACT 71-6679 70-135 50-250	a	8004100430 8004100431 8004100431 8004100432 8004100436	8004100428 8004100429 8004100426 8004100435 8004100435	80/03/31 80/03/31 80/02/26 80/03/13 80/03/13	50-445 M 10CFR 50-10 G 50-287 G 50-287 G
8004100204 8004100207 8004100208 8004100209 8004100216	8004100197 8004100192 8004100205 8004100197 8004100212	80/03/13 80/02/28 80/03/28 80/03/13 80/03/28	70-135 50-254 71-5708 70-135 71-6272	a	B004100444 8004100447 800410450 8004100450 8004100460	8004100442 8004100442 8004100440 8004100451 8004100440	80/02/26 80/03/19 80/03/19 80/03/19	\$0-498 M \$0-498 M \$0-516 T \$0-155 G \$0-516 T
8004100219 8004100223 8004100224 8004100225 8004100229	8004100214 8004100214 8004100220 8004100214 8004100226	80/03/18 80/03/18 80/03/28 80/03/18 80/04/01	50-201 50-201 71-6574 50-201 71-97	0 0	8004100462 8004100465 8004100465 8004100467 8004100467	8004100451 8004100454 8004100451 8004100459 8004100451	80/03/19 80/03/14 80/03/19 80/03/21 80/03/19	50-159 G 70-1151 50-155 G 50-251 P 50-155 G
8004100230 8004100234 8004100236 8004100242 8004100244	8004100228 8004100214 8004100231 8004100239 8004100233	80/03/28 80/03/18 80/04/01 80/03/27 80/04/03	71-9073 50-201 71-96 71-49 50-133	g I	8004100470 8004100473 8004100473 8004100475 8004100478	8004100456 8004100440 8004100458 8004100458 8004100476	80/03/14 80/02/26 80/03/21 80/03/21 80/03/17	70-1151 50-516 T 50-251 P 50-251 P 50-267 G
8004100244 8004100251 8004100252 8004100254 8004100255	8004100241 8004100241 8004100245 8004100250 8004100241	80/03/31 80/03/31 80/03/03 80/03/28 80/03/31	50-312 50-312 50-329 71-9009 50-312	P Q P	80041 00480 80041 00482 80041 00490 80041 00491 80041 00493	8004100451 8004100456 8004100485 8004100487 8004100481	80/03/19 80/03/14 80/03/28 80/03/25 80/02/04	50-155 G 70-1151 REVIEW GRP MISC 50-566 G
8004100257 8004100262 8004100263 8004100266 8004100267	8004100249 8004100259 8004100249 8004100249 8004100260	80/03/26 80/03/26 80/02/24 80/02/24	40-8452 71-4078 40-8452 40-8452 50-329	o.	8004100497 8004100503 8004100503 8004100305 8004100306	8004100485 8004100492 8004100481 8004100481 9004100481	80/03/28 80/03/15 80/02/04 80/02/04 80/02/04	REVIEW ORP 50-361 S 50-566 G 50-566 G
8004100272 8004100273 8004100275 8004100276 8004100278	8004100249 8004100264 8004100268 8004100249 8004100271	80/03/26 80/03/21 80/03/21 80/02/26	40-8452 50-344 50-250 40-8452 50-445	g P M	8004100512 8004100513 8004100519 8004100520 8004100521	8004100508 8004100509 8004100508 8004100517 8004100508	80/03/04 80/02/12 80/03/04 80/03/20 80/03/04	50-320 D COMMISSION 50-320 D ORO 50-320 D
8004100281 8004100282 8004100283 8004100284 8004100283	8004100268 8004100264 8004100269 8004100268 8004100277	80/03/21 80/03/13 80/03/03 80/03/21 80/03/17	50-250 50-344 50-282 50-250 50-269	P G P C	8004100522 8004100524 8004100528 8004100528 8004100530	8004100518 8004100523 8004100514 8004100518 8004100508	80/02/22 80/03/20 80/03/10 80/02/22 80/03/04	90-254 G CONTRACT 90-445 M 50-284 G 50-320 U
8004100268 8004100287 8004100270 8004100271 8004100275	8004100264 8004100286 8004100267 8004100287 8004100264	80/03/13 80/03/11 80/03/03 80/03/31 80/03/13	50-344 50-155 50-282 50-546 50-344	0 F Q Q	8004100531 8004100531 8004100551 8004100555 8004100560	8004100529 8004100549 8004100549 8004100550 8004100552	80/03/20 80/02/15 80/02/13 80/02/05 80/04/07	CONTRACT PR 40-261 70-135 50-445 M
8004100296 8004100298 8004100303 8004100324 8004100332	8004100293 8004100293 8004100264 8004100315 8004100329	80/03/13 80/03/13 80/03/13 80/02/08 80/04/01	50-155 50-155 50-344 50-313 71-273	0 0	8004100565 8004100567 8004100575 8004100576 8004100578	8004100563 8004100563 8004100573 8004100572 8004100574	80/03/14 80/03/14 80/03/28 80/03/18 80/03/27	50-289 & 50-289 & 50-320 H CONTRACT 50-320 H
8004100335 8004100341 8004100342 8004100345 8004100347	8004100315 8004100336 8004100339 8004100340 8004100346	80/02/08 80/04/01 80/03/27 80/04/04 80/04/01	50-313 71-116 CONTRACT 50-261 71-367	G	8004100382 8004100600 8004100608 8004100608 8004100609	8004100581 8004100596 8004100595 8004100606 8004100604	80/03/27 80/03/28 80/02/26 80/03/12 80/02/28	50-320 H CONTRACT 50-556 Q 50-423 B PR
8004100355 8004100356 8004100357 8004100358 8004100363	8004100352 8004100352 8004100354 8004100347 8004100360	80/04/01 80/04/01 80/02/15 80/02/27 80/03/24	50-217 50-219 CONTRACT 50-334 CONTRACT	Q	8004100410 8004100612 800410018 8004110018 8004110019	8004100595 8004100604 8004100611 8004110015 8004110016	80/02/26 80/02/28 80/03/12 80/03/12 80/04/03	50-556 Q PR 50-311 8 70-1151 50-387 Q
8004100367 8004100367 8004100373 8004100374 8004100377	8004100365 8004100366 8004100347 8004100370 8004100372	80/03/24 80/03/17 80/02/27 80/03/31 80/02/29	50-02 CONTRACT 50-28 50-29 50-150	P Q R Q	8004110026 8004110027 8004110037 8004110044 8004110051	8004110022 8004110015 8004110031 8004110031 8004110038	80/03/19 80/03/12 80/03/25 80/03/25 80/04/02	50-255 F 70-1151 GA999 GA999 50-3 P
8004100381 8004100382 8004100387 8004100387	8004100375 8004100347 8004100380 9004100384 8004100386	60/03/20 60/02/27 80/02/29 80/04/01 60/04/07	50~320 50~334 50~182 50~329 50~293	0 0 0 A P	8004110057 8004110064 8004110016 8004110105 8004110139	8004110031 8004110031 8004110077 8004110099 8004110121	80/03/25 80/03/25 80/03/20 80/03/14 80/04/02	QA999 QA999 50-289
8004100390 8004100391 8004100399 8004100402 8004100404	8004100384 8004100347 8004100376 8004100375 8004100403	80/04/01 90/02/27 80/04/03 80/03/17 80/04/03	50~329 50~334 50~255 50~395 50~255	A Q B Q S	8004110146 8004110151 8004110152 8004110164 8004110164	8004110144 8004110142 8004110150 8004110155 8004110157	80/03/05 80/04/02 80/02/26 80/03/10 80/03/26	WASTE MQT 50-312 9 50-440 9 50-287 9 50-287 9
8004100408 8004100409 8004100412 8004100415 8004100416	8004100140 8004100395 8004100395 8004100413 8004100395	80/02/22 80/03/17 80/03/17 80/04/03 80/03/17	50-10 50-395 50-395 50-255 50-395	9 9 9 9	8004110166 8004110176 8004110223 8004110223 8004110245	8004110157 8004110150 8004110216 8004110216 8004110230	80/03/26 80/02/26 80/04/01 80/03/05	50-287 G 50-440 G TOPREP TOPREP 50-266 G

ACCESSIO					ACCEBS	ION NUMB	ER
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRIN DDC	
8004110274 8004110271 8004110300 8004110327 8004110386	8004110259 8004110284 8004110284 8004110318 8004110378	80/03/03 80/02/29 80/02/29 80/04/01 80/04/03	50-151 50-456 50-456 50-483 50-346	9 9	800414011 800414012 800414012 800414012 800414012	4 8004 5 8004 7 8004	140 140 140
8004110442 8004110444 8004110449 8004110463 8004110475	8004110437 8004110434 8004110445 8004110457 8004110474	80/04/03 80/04/04 80/03/04 80/04/02 80/04/03	50-286 50-27 50-315 50-245 50-311	8 P R P	800414013 800414013 800414013 800414013 800414013	B004 B004 B004 B004	140 140 140 140
8004110476 8004110483 8004110488 8004110490 8004110494	8004110472 8004110479 8004110485 8004110487 8004110492	80/04/02 80/04/03 80/04/02 80/04/03 80/03/31	90-366 50-366 50-346 50-346 50-272	8 8 8 8	800414014 800414014 800414015 800414016 800414016	8004 8004 8004 8004	140 140 140 140
8004110498 8004110500 8004110514 8004110524 8004110525	8004110489 8004110497 8004110503 8004110520 8004110519	80/03/27 80/04/03 80/02/27 80/02/28 80/03/17	50-285 50-272 50-259 50-282 50-259	0 0 P P	800414019; 800414019; 800414021; 800414021;	9004 9004 9004	140: 140: 140:
8004110325 8004110327 8004110331 8004110533 8004110536	8004110519 8004110519 8004110519 8004110529 8004110529	80/03/17 80/03/17 80/03/17 80/04/01 80/04/01	50-259 50-259 50-259 50-250 50-250	P P O O	800414023 800414023 800414023 800414030 800414030	8004 8004 8004	140; 140; 140;
8004110346 8004110349 8004110350 8004110356 8004110366	8004110541 8004110545 8004110543 8004110548 8004110562	80/03/03 80/03/25 80/03/04 80/03/24 80/03/25	50-289 70-2479 50-243 50-546 50-302	0 0 0	800414031 800414031 800414031 800414032 800414032	8004 8004 8004	1400 1400 1400
6004110567 6004110575 6004140007 6004140008 6004140013	8004110561 8004110572 8004140004 8004140003 8004140004	80/03/17 80/02/27 80/03/31 80/04/03 80/03/31	50-289 50-395 50-289 50-445 50-289	0 0 0 0	8004140333 8004140333 8004140343 8004140344 800414034	8004 8004	1400 1400 1400
8004140015 8004140017 8004140018 8004140017 8004140020	8004140011 8004140004 8004140011 8004140004 8004140011	80/03/24 80/03/31 80/03/24 80/03/31 80/03/24	0A779 50-287 0A779 50-287 0A779	0 0	8004140352 8004140354 8004140355 8004140366 8004140367	80041 80041	1403 1403 1403
8004140023 8004140026 8004140027 8004140028 8004140029	8004140004 8004140022 8004140024 8004140004 8004140011	80/03/31 80/01/17 80/03/17 80/03/31 80/03/24	50-289 50-155 71-249 50-289 GA999	о н о	8004140365 8004140377 8004140379 8004140382 8004140405	80041 80041	1403 1403 1403
8004140031 8004140032 8004140034 8004140037 8004140038	8004140022 8004140004 8004140011 8004140011 8004140004	80/01/17 80/03/31 80/03/24 80/03/24 80/03/31	50-155 50-289 0A979 0A979 50-289	H O	8004140411 8004140412 8004140422 8004140422 8004140429	80041 80041 80041	1404 1404 1404
8004140040 8004140043 8004140044 8004140045	8004140011 8004140011 8004140041 8004140004 8004140041	80/03/24 80/03/24 80/03/10 80/03/31 80/03/10	GA999 GA999 50-155 50-289 50-155	000	8004140436 8004140437 8004140440 8004140444		
8004140049 8004140051 8004140052 8004140054 8004140055	B004140044 B004140004 B004140047 B004140050 B004140050	B0/02/28 B0/03/31 B0/01/17 B0/02/29 B0/02/29	50-458 50-269 PR 50-334 50-334	Q Q P P			
8004140057 8004140058 8004140059 8004140062 8004140065	8004140004 8004140050 8004140041 8004140004 8004140004	80/03/31 80/02/29 80/03/10 80/03/31 80/03/31	50-289 50-334 50-155 50-289 50-289	GP 9 9 9			
8004140047 8004140070 8004140072 8004140073 8004140076	8004140061 8004140060 8004140069 8004140060 8004140061	80/03/15 80/03/17 80/03/21 80/03/17 80/03/15	50-320 70-1308 PRM 70-1308 50-320	0			
8004140077 8004140080 8004140082 8004140084 8004140088	8004140074 8004140074 8004140078 8004140074 8004140085	80/03/17 80/03/17 80/03/03 80/03/17 80/03/20	50-289 50-289 70-1908 50-289 GRO	0			
8004140075 8004140097 8004140100 8004140104 8004140116	8004140072 8004140073 8004140076 8004140078 8004140113	80/03/20 80/03/24 80/02/08 80/03/21 80/03/20	M18C 50-339 PR 50-443 TOPREP	H			

	PRINCIPAL.	DATE	SUBJEC	T
ENCLOSURE	DOCUMENT	ISSUED	CATEOD	RY
8004140117	8004140111	80/03/18	50-320	
8004140124	6004140114	80/03/31	FOIA	
8004140126	800414006B	80/03/21	PRM	
8004140127	8004140125	80/03/19	50-367	Q
8004140128	800414006B	12\60/08	PRM	
6004140130	8004140125	80/03/19	50-347	Q
8004140131	8004140114	80/03/31	FOIA	
8004140133	8004140068	80/03/21	PRM	
E004140135	8004140059 8004140059	80/03/21 80/03/21	PRM PRM	
		,	FRIT	
E004140140	8004140069	12/00/08	PRM	
B004140145 B004140157	8004140068 8004140154	80/03/21 80/04/04	PRM 50-309	_
E004140180	8004140154	80/03/31	50-307	R
8004140190	8004140186	80/03/26	50-339	Й
8004140195	8004140186	80/03/26	50-339	н
8004140197	8004140183	80/03/28	50-10	ü
B004140210	8004140199	80/03/20	40E-06	a
B004140215	8004140208	80/03/28	50-10	U
8004140224	8004140219	80/04/11	50-281	P
8004140230	8004140225	80/03/31	50-10	U
8004140238	8004140235	80/03/28	50-409	U
8004140262 8004140303	8004140252 8004140299	80/03/25 80/03/21	50-358 50-309	Ü
8004140304	8004140279	80/03/21	50-309	ŭ
8004140311	8004140310	80/04/07	50-293	р
B004140314	8004140312	80/04/01	50-409	Þ
8004140319	8004140317	80/04/08	50~352	I
8004140322	8004140306	90/03/18	50-295	R
8004140323	8004140320	80/04/09	50~272	용
6004140332	6004140327	80/04/09	50-327	P
B004140333	6004140328	80/04/07	50-313	셤
B004140340 B004140342	8004140330 8004140337	80/03/19 80/04/09	50-10 50-293	R
8004140344	8004140337	80/04/10	50-282	R
E004140353	8004140350	90 (04 (07	60 047	_
8004140354	8004140348	80/04/07 80/04/08	50-346 50-369	R
B00414035B	6004140346	80/04/08	50-369	Ä
8004140360	8004140356	80/04/08	50-313	8
8004140367	8004140365	80/04/07	50-409	R
8004140369	6004140363	80/04/10	50-331	8
8004140377	8004140372	80/04/03	50-320	8
8004140379	8004140374	80/03/21	50-266	U
8004140382 8004140405	8004140380 8004140397	80/04/09 80/04/03	50-331	P
8004140405	8004140397	80/04/03	50-312	8
8004140411	B004140406	E0/4/03	50-220	R
8004140412 8004140422	8004140409 8004140416	80/04/09	50-272	8
8004140422	E004140418	80/04/10 80/03/21	50-286 50-237	5 6
8004140432	Bungingang	00/03/61	80-207	G
8004140436				

ACCESSIBII						IN NUMBER			
ENCLOSURE	PRINCIPAL DECUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC1 CATEGOR	
8004150110 8004150116 8004150117 8004150118 8004150120	8004150103 8004150103 8004150112 8004150115 8004150103	80/03/27 80/03/27 80/03/19 79/12/10 80/03/27	50-346 50-346 71-367 70-125/ 50-346	P P	8004150477 8004150479 8004150480 8004150481 8004150486	8004150472 8004150474 8004150473 8004150476 8004150483	80/03/28 80/04/11 80/04/11 80/04/07 80/04/10	50-304 50-255 50-537 50-366 50-318	S P A 8
8004150121 8004150125 8004150127 8004150133 8004150136	8004150112 8004150123 8004150123 8004150132 8004150126	80/03/19 80/03/19 80/03/19 80/03/18 80/04/01	71-367 71-116 71-116 71-97 90-321	Q	9004150489 9004150490 9004150493 9004150494 8004150494	8004150484 8004150484 8004150487 8004150485 8004150484	80/04/14 80/04/14 80/03/31 80/04/03 80/04/14	50-341 50-341 50-213 50-553 50-341	0 8 9
8004150141 8004150142 8004150143 8004150147 8004150147	8004150140 8004150126 8004150139 8004150126 8004150145	80/03/26 80/04/01 80/02/12 80/04/01 80/01/31	HUREG 50-321 50-352 50-321 9A999	a a a	8004150499 8004150510 8004150512 8004150513 8004150514	8004150462 8004150507 8004150500 8004150503 8004150504	80/03/26 80/04/09 80/04/11 80/04/03 80/04/11	50-265 50-315 50-327 50-237 50-271	9 F 6 6
8004150154 8004150155 8004150156 8004150171 8004150193	800415015) 8004150126 8004150151 8004150166 8004150167	80/04/01 80/04/01 80/04/01 80/03/13 80/02/28	50-335 50-321 50-335 CONTRACT 70-371	P Q P	8004150520 8004150526 8004150526 8004150529 9004150531	8004150507 8004190515 8004150518 8004150516 8004150509	80/04/03 80/04/07 80/04/02 80/04/08 80/04/03	50-315 50-240 50-304 50-334 50-315	9 9 9
8004150195 8004150200 8004150202 8004150210 8004150216	8004150188 8004150197 8004150199 8004150209 8004150211	80/03/11 80/04/14 80/03/21 80/03/24 80/03/26	50-361 50-416 50-445 50-438 50-10	H S S H	8004150532 8004150533 8004150534 8004150535 8004150536	8004150524 8004150928 8004150516 8004150523 8004150525	80/04/09 60/04/08 80/04/08 80/04/11 80/04/10	50-305 50-327 50-334 50-259 50-259	8 8 8 6
8004150239 8004150250 8004150252 8004150255 8004150260	8004150235 8004150246 8004150246 8004150246 8004150246	80/04/10 80/04/68 80/04/08 80/04/08 80/04/08	50-313 50-277 50-277 50-277 50-277	I I I	800 4150537 800 4150545 800 4150546 800 4150547 800 4150549	8004150530 8004150516 800415053B 8004150539 8004150541	80/04/10 80/04/08 80/04/07 80/04/08 80/04/08	50-255 50-334 50-361 50-327 50-313	8 8
8004150278 8004150280 8004150284 8004150287 8004150305	8004150272 8004150270 8004150272 8004150281 8004150300	80/03/13 80/04/08 80/03/13 80/04/14 80/03/17	71-49 TOPREP 71-49 50-289 70-820	Р	8004150552 8004150555 8004150556 8004150558 8004150559	8004150542 8004150543 8004150544 8004150553 8004150551	80/04/09 80/04/08 80/04/10 80/04/11 80/04/09	50-267 50-263 50-255 50-272 50-327	8 8 8 P
8004150319 8004150322 8004150325 8004150328 8004150331	8004150312 8004150320 8004150320 8004150316 8004150327	80/04/11 80/04/02 80/04/02 80/04/02 80/04/11	50-516 50-245 50-245 50-10 50-244	9 1 1 P	8004150565 8004150565 8004150570 8004150571 8004150572	8004150543 8004150554 8004150563 8004150543 8004150562	80/04/08 80/04/11 80/04/10 80/04/08 80/04/07	50-263 50-327 50-346 50-263 50-366	8 8 8
8004150332 8004150334 8004150335 8004150334 8004150347	8004150329 8004150329 8004150329 8004150333 8004150345	80/04/11 80/04/11 80/04/11 80/04/07 80/04/09	50-244 50-244 50-244 50-267 50-206	የ የ የ	8004150577 8004150580 8004150586 8004150586 8004150589	8004150567 8004150543 8004150573 8004150576 8004150543	80/04/09 80/04/08 80/04/08 80/04/02 80/04/08	50-368 50-263 50-259 50-293 50-263	F 8 8 8 8
8004150351 8004150352 8004150355 8004150361 8004150365	8004150349 8004150350 8004150354 8004150360 8004150363	80/04/11 80/04/11 80/04/09 80/04/11 80/04/08	50-289 50-29 50-305 50-271 50-316	P R R R	8004150570 8004150576 8004150598 8004150601 8004150603	8004150567 8004150581 8004150543 8004150567 8004150587	80/04/09 80/04/09 80/04/09 80/04/09 80/04/10	50~368 50~305 50~263 50~368 50~282	F 8 F 8
8004150370 8004150371 8004150376 8004150384 8004150385	8004150367 8004150368 8004150374 8004150380 8004150383	80/04/11 80/04/08 80/04/09 80/04/09 80/04/10	50-309 50-315 50-261 50-244 50-366	R R R R	8004130407 8004130410 8004130411 8004130615 8004150617	8004150599 8004150543 8004150582 8004150608 8004150543	80/04/10 80/04/08 80/04/09 80/04/11 80/04/08	50-3 50-263 50-267 50-327 50-263	R 8 8 P 8
8004150387 8004150389 8004150390 8004150395 8004150396	8004150382 8004150386 8004150388 8004150371 8004150372	80/04/10 80/04/10 80/04/10 80/04/02 80/04/11	50-10 50-272 50-321 50-285 50-553	R R R R	9004150618 8004150620 8004150623 8004150634 8004150638	8004150605 8004150606 8004150543 8004150626 8004150624	80/04/11 80/04/10 80/04/09 80/04/09 80/04/10	50-368 50-317 50-263 50-267 50-318	8 8 8
'4 5 7	8004150399 8004150401 8004150320 8004150406 3004150414	80/04/10 80/04/10 80/04/02 80/04/08 80/04/03	50-321 50-243 50-245 50-250 50-518	R R I I	8004130641 8004160007 8004160017 8004160030 8004160030	8004150630 8004160004 8004160004 8004160024 8004160034	80/04/07 80/03/20 80/03/20 80/03/10 80/03/26	50-313 50-272 50-272 COMMISS 50-320	8 0 0 10N
	3004150416 3004150420 3004150426 3004150432 3004150435	80/04/03 80/04/11 80/04/11 80/04/09 80/04/07	50-373 50-382 50-348 50-267 50-275	A R S A	8004160050 8004160062 8004160072 8004160102 8004160118	8004160044 8004160057 8004160066 8004160096 8004160116	80/02/27 80/02/27 80/02/27 80/02/29 80/04/01	50-445 50-553 50-327 PR 50-413	0 0 0
	3004150440 3004150444 3004150447 3004150447 3004150451	80/04/07 80/04/08 80/04/01 80/04/07 80/04/03	50-344 50-324 50-390 50-348 50-366	8 8 8	8004160122 8004160133 8004160137 8004160138 8004140138	8004160116 8004160125 8004160125 8004160131 8004160125	80/04/01 80/03/24 80/03/24 80/03/28 80/03/24	50-413 50-293 50-293 50-289 50-293	0 0 0
	3004150454 3004150459 3004150463 3004150457 3004150456	80/03/13 80/04/11 80/03/25 80/03/27 80/04/11	50-366 50-244 50-254 50-254 50-311	8 P 8 8	8004160146 8004160151 8004160153 8004160155 8004160159	8004160125 8004160078 8004160145 8004160078 8004160078	80/03/24 80/03/24 80/02/28 80/03/24 80/03/24	50-293 70-1251 50-293 70-1251 70-1251	G

ACCESS10	1 NUMBER				ACCESSIO	IN NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT		. ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEOORY
8004160172	8004160165	80/02/29	50-277	0	8004170293	8004170288	80/02/26	50-272 0
8004160176 8004160184	8004160173 8004160179	80/04/01 80/04/07	50-3 50-320	H P	8004170296 8004170300	8004170292 8004170294	80/03/26 80/03/26	50-424 0 50-289 P
8004160187 8004160187	8004160183 8004160183	80/03/21 80/03/21	50-277 50-277	G G	8004170309 E004170318	8004170304 8004170316	80/02/07 80/03/31	50-334 0 50-317 F
8004160190 8004160191	8004160186 8004160183	80/03/12 80/03/21	COMMISS: 50-277	DN ù	8004170323 8004170350	8004170316 8004170345	80/03/31 80/04/02	50-317 F 100FR
8004160193 8004160194	8004160186 8004160183	80/03/12 80/03/21	CDMMISS: 50-277		8004170352 8004180016	8004170345 8004180008	80/04/02 80/03/31	IOCFR COMMISSION
8004160196	8004160186	80/03/15	COMMISSI	ΩN	8004180044	8004180058	BO/04/04	50-328 A
8004160199 8004160200	8004160197 8004160186	B0/04/11 B0/03/12	50-269 COMMISSI		8004180069 8004180070	8004180062 8004180058	80/03/19 80/04/04	71-96 50-328 A
8004160202 8004160203	8004160186 8004160186	80/03/12 80/03/12	COMMISSI	ūΝ	800418007B 8004180082	8004180023 8004180023	80/03/31 80/03/31	COMMISSION
8004140206 8004160209	8004160186	80/03/12	COMMISSI		B004180084	8004180023 8004180088	B0/03/31	COMMISSION
8004160210 8004160212	8004160197 8004160196	80/04/11 80/03/12	50-269 COMMISSI	G	8004180089 8004180092 8004180095	8004180088 8004180023	80/03/14 80/03/14 80/03/31	XPORTLIC XPORTLIC COMMISSION
8004160215 8004160218	8004160186 8004160216	80/03/12 80/03/31	COMMISSI 50-518		8004180097 8004180100	8004180023 8004180023	80/03/31 10/03/31	COMMISSION
8004160219	8004160197	80/04/11	50-269	0	8004180101	8004190023	80/03/31	COMMISSION
8004160220 8004160221	8004160186 8004160197	80/03/12 80/04/11	COMMISS!	C C	9004180103 9004180120	8004180023 8004180113	80/03/31 80/03/19	CDMMI8810N 50-289 H
B004160224 B004160227	8004160197 8004160197	BO/04/11 BO/04/11	50-269 50-269	G G	8004180124 8004180124	8004180121 8004180122	80/02/29 80/04/02	70-1113 50-301 9
8004140230 8004160232	8004160197 8004160229	80/04/11 80/04/11	50-269 50-287	G S	8004180130 8004180142	8004180122 8004180128	80/04/02 80/03/25	50-301 0 COMMISSION
8004160235 8004160240	8004160197 8004160197	80/04/11 80/04/11	50-269 50-269	G	8004180147 8004180153	8004180138 8004180128	80/03/03 80/03/25	50-245 G COMMISSION
8004160243	8004160239	80/03/31	50-445	Ř	9004180150	8004180154	90/03/59	50-337 A
B004160244 B004160256	8004160197 8004160253	BO/04/11 BO/04/0B	50-269 50-275	Q A	8004180164 8004180167	9004180129 9004180151	80/03/25 80/04/02	COMMISSION 50-445 M
8004160259 8004160260	8004140253 8004140253	80/04/08 80/04/08	50-275 50∽275	A	8004180175 8004180191	6004160126 6004160172	80/03/25 80/03/27	COMM 1881 DN 50-315 0
B004160264	8004160253	80/04/08	50-275	Α .	B004180185	8004180128	80/03/25	COMMISSION
8004160267 8004160270	8004160253 8004160266 8004160253	80/04/08 80/40/03 80/04/08	50-275 50-312 50-275	R	8004180193 8004180197 8004180199	8004190129 8004190129 8004190187	80/03/25 80/03/25 80/03/04	COMMISSION COMMISSION 50-373 Q
8004160271 8004160296 8004160298	8004160291 8004160290	80/03/31 80/04/10	50-438 50-320	A B P	8004180203 8004180207	8004180187 8004180200	80/03/04 80/03/2B	50-373 0 XPORTLIC
B004170019	8004170015	80/04/11	50-324	Р	B00418020B	6004180111	80/04/10	50-358 G
8004170020 8004170031	8004170015 8004170026	80/04/11 80/04/11	90-324 50-327	P S	8004180218 8004180220	8004180214 8004180211	80/02/21 80/03/18	50-498 0 COMMISSION
8004170035 8004170046	B004170028 B004170044	80/03/20 80/04/03	TOPREP 50-73	P	80 <b>0418023</b> 7 80 <b>0418023</b> 8	9004180234 8004180233	80/03/28 80/03/20	50-3 H 50-387 T
8004170049	8004170044	80/04/03	5073	P	E004180258	8004180253 8004180256	80/03/28 80/04/14	50-220 P A E&E-0&
8004170051 8004170052 8004170059	8004170045 8004170050 8004170056	80/04/10 80/04/03 80/04/10	50~528 50~338 50~282	9 R F	8004180264 8004180277 8004180278	8004180253 8004180253	80/03/58	50-553 A 50-220 P 50-220 P
8004170067	8004170065	80/04/11	50-327	K	8004180286	8004180281	EO/400	50-247 €
8004170073 8004170074	B004170069 B004170071	80/04/14 80/03/21	50-327 50-416	P B	8004180294 8004180298	8004180281 8004180279	B0/04/03 B0/03/17	50-247 E COMMISSION
8004170106 8004170115	8004170104 8004170107	80/04/14 80/04/01	50-289 50-312	P	9004180307 9004180310	8004180296 8004180309	80/04/14 80/03/27	50-306 G XPORTLIC
8004170117	8004170112	80/02/27	COMMISSI		8004180311	8004180304	80/03/18	COMMISSION
8004170121 8004170129	8004170109 8004170109	80/04/01 80/04/01	50-312 50-312	Q Q P	8004180314 8004180319 8004180320	8004180309 8004180304 8004180318	80/03/27 80/03/18 80/03/05	XPORTLIC COMMISSION 50-320 G
8004170140 8004170155 8004170191	8004170134 8004170148 8004170184	80/04/15 80/04/15 80/04/09	50-327 50-327 50-273	G B	8004180334 8004180337	8004180329 8004180331	80/02/26 80/04/15	50-320 G 50-219 G 50-370 R
8004170177	8004170194	80/04/10	50-336	s	8004180339	8004180338	80/04/19	50-320 R
8004170208 8004170211	8004170203 8004170210	80/04/10 80/04/14	50-269 50-338	S R	8004190342 8004180348	8004180341 8004180346	80/04/15 80/04/07	50-282 P 50-213 P
8004170212 8004170221	8004170210 8004170219	80/04/14 80/04/14	50-338 50-317	R 8	8004180347 8004180360	8004180345 8004180357	80/04/14 80/04/10	50~220 f 50~243 f
8004170226	8004170224	80/04/09	50-336	8	8004180362	8004180361	80/04/14	50-344 P
8004170227 8004170227	8004170225 8004170225	80/04/15 80/04/15	50-327 50-327 50-277	F	, B004180364 B004180364 B004180367	8004180359 8004180361 8004180365	80/04/04 80/04/14 80/04/11	50-314 F 50-344 P 50-328 S
8004170230 8004170231	8004170228 8004170225	80/04/10 80/04/15	50-327	R F	8004180371	B0041B0369	80/04/11	50-271 R
8004170234 8004170236	B004170225 B004170233	80/04/15 80/04/09	50-327 50-133	F R	8004180374 8004180381	8004180373 8004180377	80/04/05 80/04/10	50~250 R 50~390 S
8004170244 8004170252	8004170241 8004170246	80/04/14 80/04/15	50~280 50-277	₽ P	8004180384 8004180388	8004180380 8004180383	80/04/11 80/04/14	50-304 £ 50-245 R
8004170256	E004170246	80/04/15	50-277	P	8004180394	8004180391	80/04/11	50-327 R
8004170257 8004170258	8004170254 8004170255	80/04/14 80/04/14	50-70 50-255 50-70	P G P	8004180395 8004180402 8004180404	8004180387 8004180396 8004180398	80/02/25 80/03/12 80/04/11	50-247 P 50-155 0 50-336 B
8004170260 8004170262 8004170281	8004170254 8004170255 8004170273	80/04/14 80/03/14 80/03/31	50-255 50-289	0	8004180404 8004180407 8004180411	8004180399 8004180408	80/04/11 80/04/08 80/04/11	50-327 B 50-336 B
MONTAFORDI	2004110613	20,00,01	40,	-	WASHINGTH		44, 44, 11	W

ACCESSION	NUMBER				ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1850ED	SUBJECT CATEGORY	ť	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8004180413 8004180416 8004180425 8004180433 8004180434	8004180410 8004180405 8004180418 8004180428 8004180426	80/04/14 80/04/10 80/04/14 80/04/14 80/04/15	50-271 50-272 50-261 50-305 50-286	5 T 5 P 8	8004210127 8004210129 8004210130 8004210132 8004210132	8004210125 8004210125 8004210126 8004210125 8004210125	80/03/27 80/03/27 80/03/18 80/03/27 80/03/19	50-155 50-155 70-1100 50-155 70-1100	P P
8004180439 8004180440 8004180441 8004180454 8004180456	8004180431 8004180437 8004180432 8004180450 8004180452	80/04/08 80/04/10 80/04/08 80/04/09 80/04/08	50-320 50-245 50-269 50-206 50-296	H 50 5 5 5	8004210135 8004210137 8004210138 8004210139 8004210142	8004210126 8004210134 8004210126 8004210126 8004210134	80/03/18 80/02/29 80/03/18 80/03/18 80/02/29	70-1100 50-359 70-1100 70-1100 50-358	G Q
8004180457 8004180461 8004180465 8004180467 8004180469	8004180451 8004180448 8004180460 8004180466 8004180462	80/04/08 80/04/14 80/04/07 80/04/14 80/04/15	50-260 50-286 50-327 50-344 50-302	S S S P 1	8004210143 8004210145 8004210149 8004210151 8004210159	8004210126 8004210126 8004210026 8004210146 8004210156	80/03/18 80/03/18 80/03/31 80/02/25 80/03/24	70-1100 70-1100 XPORTLIC 50-322 XPORTLIC	Q
8004180470 8004180471 8004180472 8004180474 8004180475	8004180466 8004180458 8004180468 8004180462 8004180464	80/04/14 80/04/14 80/04/11 80/04/15 80/04/11	50~344 50-244 50~263 50-302 50~282	P 5 7 P	8004210160 8004210162 8004210166 8004210167 8004210171	8004210154 8004210155 8004210163 8004210155 8004210155	80/03/07 80/03/28 80/04/07 80/03/28 80/03/28	PR 70-1113 50-267 70-1113 70-1113	Q
8004180478 8004180483 8004180484 8004180491 8004180492	8004180462 8004180479 8004180462 8004180462 8004180489	80/04/19 80/04/14 80/04/19 80/04/19 80/04/10	50-302 50-305 50-302 50-309 50-309	1 1 5	9004210173 9004210174 9004210179 9004210184 9004210185	8004210169 8004210155 8004210175 8004210170 8004210182	80/02/28 80/03/28 80/02/29 80/03/25 80/04/14	50-293 70-1113 50-445 50-389 50-458	Q Q S I
8004180500 8004180503 8004180512 8004180522 8004180523	8004180462 8004180508 8004180515 8004180521	80/04/15 80/04/15 80/02/26 80/03/14 80/02/21	50-302 50-302 50-309 70-1007 50-344	G 1 1	8004210186 8004210188 8004210195 8004210196 8004210197	8004210181 8004210183 8004210191 8004210187 8004210192	80/03/11 80/04/03 80/03/29 80/03/07 80/03/14	50-341 50-553 50-249 50-243 50-317	0 0 0 R
8004180525 8004180527 8004180528 8004180530 8004180534	8004180515 8004180521 8004180524 8004180529 8004180533	80/03/14 80/02/21 80/02/09 80/03/08 80/02/26	70-1007 50-344 50-250 50-250 70-364	g R R	8004210199 8004210201 8004210205 8004210204 8004210207	8004210191 8004210193 8004210202 8004210204 8004210203	80/03/28 80/04/01 80/04/11 80/04/04 80/03/17	50-269 50-3 50-327 50-160 70-135	0 Н Р
8004210009 8004210011 8004210018 8004210020 8004210021	8004210007 8004210003 8004210014 8004210015 8004210019	80/04/09 80/03/06 80/03/25 80/03/31 80/04/03	50-322 50-423 50-344 50-320 71-9142	G Q F Q	8004210212 8004210214 8004210215 8004210216 8004210218	8004210210 8004210203 8004210211 8004210203 8004210210	80/03/21 80/03/19 80/03/10 80/03/19 80/03/21	50-247 70-135 50-298 70-135 50-247	G G G
B004210022 B004210024 B004210025 B004210030 B004210031	8004210013 8004210014 8004210013 8004210013 8004210028	80/04/08 80/03/26 80/04/08 80/04/08 80/03/26	FOIA 50-272 FOIA FOIA 50-339	о Н	8004210217 8004210220 8004210222 8004210223 8004210229	8004210211 8004210217 8004210203 8004210208 8004210226	80/03/10 80/04/11 80/03/17 80/04/01 80/03/10	50-298 50-313 70-135 50-3 50-312	G R H G
8004210033 8004210034 8004210035 8004210042 8004210044	8004210013 8004210027 8004210029 8004210037 8004210039	80/04/08 80/03/05 80/03/05 80/02/26 80/03/26	FOIA 70-1100 40-672 71-6717 50-309	a	8004210237 8004210240 8004210241 8004210242	8004210231 8004210238 8004210231 8004210234 8004210231	80/03/25 80/04/11 80/03/25 80/03/26 80/03/25	50-312 50-302 50-312 50-413 50-312	Q Q Q
8004210045 8004210049 8004210052 8004210053 8004210057	8004210039 8004210047 8004210039 8004210039 8004210047	80/03/26 80/03/24 80/04/08 80/03/26 80/04/08	50-309 50-09 FOIA 50-309 FOIA	о о	8004210247 8004210248 8004210249 8004210250 8004210253	8004210234 8004210231 8004210246 8004210235 8004210251	80/03/28 80/03/25 80/04/14 80/03/10 80/04/10	50-413 50-312 50-245 50-287 50-213	Q G R Q R
6004210060 6004210061 6004210062 6004210064 6004210065	8004210048 8004210054 8004210047 8004210054 8004210047	80/04/01 80/03/26 80/04/08 80/03/26 80/04/08	50-27 50-286 FDIA 50-286 FOIA	H 0	8004210254 8004210257 8004210258 8004210262 8004210264	8004210252 8004210254 8004210255 8004210259 8004210260	80/03/15 80/04/09 80/04/14 80/04/10 80/03/15	50-10 50-206 50-247 50-312 50-10	H 23 45 H
8004210067 8004210068 8004210070 8004210071 073	8004210063 8004210036 8004210036 8004210059 8004210066	80/03/14 80/03/26 80/03/26 80/02/25 80/03/24	70-371 50-284 50-264 50-244 71-381	G G	6004210266 6004210267 6004210271 6004210273 6004210276	8004210261 8004210265 8004210268 8004210270 8004210269	80/04/15 80/04/15 80/04/14 80/04/08 80/04/15	50-334 50-346 50-267 50-206 50-3	R S R S R
	8004210074 8004210075 8004210075 8004210075 8004210079	80/03/05 80/03/14 80/03/14 80/03/14 80/03/05	50-272 70-2478 70-2478 70-2478 50-277	Q Q	8004210278 8004210279 8004210280 8004210282 8004210288	8004210277 8004210272 8004210274 8004210275 8004210286	80/04/14 80/03/15 80/04/11 80/03/03 80/04/09	50-309 50-10 50-368 50-546 50-249	8 H R H B
	8004210081 8004210081 8004210084 8004210088	80/01/16 80/01/16 80/02/28 80/04/01 80/02/28	70-135 70-135 70-1143 50-3 50-320	H G	8004210290 8004210292 8004210296 8004210297 8004210300	8004210287 8004210289 8004210294 8004210295 8004210299	80/03/15 80/04/12 80/04/09 80/03/15 80/03/15	50-10 50-273 50-267 50-10 50-10	H 8 8 H
		30/03/04 30/03/04 30/03/18 30/03/05 80/03/04	70-371 50-302 CONTRACT 50-269 50-566	a a	8004210305 8004210306 8004210307 8004210310 8004210320	8004210302 8004210303 8004210303 8004210308 8004210315	80/03/15 80/03/24 80/03/24 80/03/15 80/04/01	50-10 TOPREP TOPREP 50-10 50-339	H H

C

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION	NUMBER				ACCESSIO	IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8004210325	8004210322	80/03/28	50-275	 G	6004220167	B004220184	80/02/25	71-9130	
8004210329 8004210330	8004210322 8004210326	80/03/28 80/02/27	50-275 50-219	Ç G	6004220191 8004220193	8004220185 8004220184	80/03/19 80/02/25	50-320 71-9130	ŀ
8004210331	8004210327	80/04/16	50-305	P	8004220176	8004220020	80/04/03	FOIA	
6004210339	8004210334	80/03/05	50-333	G	8004220202	8004220020	80/04/03	FOIA	
B004210340 B004210344	8004210335 8004210335	80/04/15 80/04/15	50-320 50-320	P	8004220204 8004220207	8004220188 8004220020	80/03/31 80/04/03	50-249 FOIA	(
8004210345 8004210346	8004210343 8004210342	80/03/05 80/03/26	50-245 50-320	Q P	8004220212 8004220214	8004220020 8004220020	80/04/03	FOIA FOIA	
8004210347	8004210342	B0/04/15	50-320	P	8004220214	8004220020	80/04/03	FOIA	
8004210349	8004210335	80/04/15	50-320	ρ	B00422 <b>0</b> 221	8004220215	80/03/04	50-321	(
8004210351 8004210355	8004210342 8004210335	80/03/26 80/04/15	50-320 50-320	P P	8004220224 6004220227	8004220223 7907100034	80/04/11 79/06/21	50~269 50~267	Ŧ
8004210357	8004210350	80/04/07	70-143	P	8004220229 8004220231	8004220020	B0/04/03	FOIA	
8004210358	8004210335	80/04/15	50-320	г		8004220020	80/04/03	FOIA	
8004210359 8004210360	8004210350 8004210356	80/04/07 80/03/24	70-143 50-320	Н	8004220236 8004220238	9004220020 7907100034	80/04/03 79/06/21	FOIA FOIA	
8004210361 8004210366	B004210353 8004210335	80/04/15 80/04/15	FR 50-320	P	8004220242 8004220243	8004220020 8004220239	80/04/03 80/03/24	FOIA 50-389	i
8004210373	8004210363	00/03/24	50-320	н	8004220244	8004220232	80/02/29	50-445	Ċ
8004210376	8004210372	80/04/16	50-338	þ	8004220245	7907100034	79/06/21	FOIA	
8004210388 8004210391	8004210387 8004210381	80/03/21 81/E0/08	40~11&2 50-320	H	6004220246 6004220250	8004220020 8004220248	80/04/03 80/03/24	FQ1A 50~389	K
8004210392 8004210393	8004210386 8004210322	80/03/27 80/03/28	50-445 50-275	M	8004220251 8004220252	8004220020 8004220020	80/04/03 80/04/03	FDIA FOIA	
8004210394 8004210395	8004210386 8004210322	80/03/27 80/03/28	50-445 50-275	e O	8004220253 8004220255	7907100034 8004220020	79/06/21 80/04/03	FOIA FOIA	
8004210397 8004210399	9004210386 8004210398	00/03/27 00/03/24	50-445 50-320	M	8004220257 8004220243	8004220020 8004220020	80/04/03 80/04/03	FOIA FOIA	
8004210400	800421 038A	80/03/27	50-445	M	B004220267	B004220020	B0/04/03	FOIA	
8004210403	8004210402	80/03/22	50-320	н	8004220273	800422026B	80/04/01	50-331	F
8004210417 8004210428	8004210412 8004210422	80/03/11 80/03/21	50-361 50-312	G G	6004220274 6004220262	8004220020 8004220020	80/04/03 80/04/03	FOIA FOIA	
E004210431	8004210425	80/04/10	50-367 50-445	Q Q	80042202B4 80042202B6	8004220278 8004220020	80/04/14 80/04/03	50~301 FOIA	F
8004210438	8004210432	00/03/10							
8004210443 8004210450	8004210432 8004210439	80/03/10 80/02/27	50-445 50-219	a a	8004220293 8004220294	8004220289 8004220020	80/04/18 80/04/03	50-416 FOIA	
8004220007 8004220017	8004220004 8004220012	80/03/24 80/03/17	50-286 50-316	GI P	8004220304 8004220314	8004220301 8004220020	BO/04/17 BO/04/03	50-271 FOIA	F
8004220023	8004220012	80/03/17	50-316	P	8004220315	8004220303	80/03/05	70-2623	
8004220026	8004220018	79/12/28	70-135		6004220317	6004220313	80/03/24	50~389	¢
8004220027 8004220028	8004220012 8004220020	80/03/17 80/04/03	50-316 FOIA	þ	8004220319 8004220321	8004220020 8004220313	80/04/03 80/03/24	F01A 50-389	¢
8004220033 8004220034	8004220020 8004220012	80/04/03 80/03/17	FDIA 50-314	Р	8004220323 8004220326	8004220020 8004220303	80/04/03 80/03/05	FO1A 70-2623	
				•			80/04/03	FOIA	
8004220037 8004220039	8004220020 8004220012	80/04/03 80/03/17	FOIA 50-314	P	8004220327 8004220329	8004220020 8004220020	E0/4/03	FOIA	
8004220041 8004220044	8004220025 8004220020	80/03/06 80/04/03	70-371 FOIA		8004220330 8004220331	8004220020 8004220303	80/04/03 80/03/05	FOIA FO-2623	
8004220051	8004220020	E0/04/03	FOIA		8004220337	8004220020	80/04/03	FOIA	
8004220055	8004220043	80/03/25	71~379		8004220341	8004220020	80/04/03	FOIA	
8004220056 8004220068	8004220020 8004220054	60/04/03 79/11/14	FOIA 70-1143		8004220342 8004220346	6004220303 8004220020	80/03/05 80/04/03	70-2623 FOIA	
8004220075 8004220080	8004220020 8004220020	80/04/03 80/04/03	FOIA FOIA		8004220349 8004220351	8004220340 8004220020	80/04/15 80/04/03	50-259 FOIA	
8004220092	8004220020	80/04/03	FOIA		8004220353	8004220303	80/03/05	70-2623	
8004220097	8004220020	80/04/63	FOIA		8004220355	8004220020	80/04/03	FOIA	
8004220101 8004220107	8004220020 8004220020	80/04/03 80/04/03	FOIA FOIA		8004220358 8004220361	6004220340	80/04/15	50-257	
8004220116	8004220111	80/03/24	XPORTLIC		and Take				
8004220119	8004220105	80/03/28	50-491	a					
8004220120 8004220124	8004220020 8004220112	80/04/03 80/03/19	F01A 50-320	н					
8004220125 8004220130	8004220020 8004220020	80/04/03 80/04/03	FOIA FOIA						
8004220132	8004220020	80/04/03	FOIA						
B004220134	B004220105	80/03/28	50-491	Q					
8004220137 8004220143	8004220020 8004220136	80/04/03 80/03/13	FOIA 50-320	н					
8004220162	6004220159	80/03/03	50-320	Н					
8004220164	8004220020	80/04/03 80/03/04	FOIA 50-275	G					
8004220165 8004220167	8004220157 8004220020	80/04/03	FOIA						
8004220171 8004220174	8004220168 8004220020	80/03/19 80/04/03	50-320 F01A	н					
B004220175	8004220157	80/03/04	50-295	Q					
8004220178	8004220020	80/04/03	FOIA FOIA	•					
8004220180 8004220181	8004220020 8004220173	80/04/03 80/04/02	50-320	н					
8004220186	8004220020	80/04/03	FOIA						

ACCESSION NUMBER

## TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ACCESSION	NUMBER				ACCESSION	1 MONREK			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1690ED	SUBJECT CATEGOR'		ENCLOSURE	PRINCIPAL DOCUMENT	DATE (SSUED	SUBJECT CATEGOR	
8004220440 8004220442 8004220444 8004220447 8004220448	8004220427 8004220020 8004220020 8004220427 8004220020	80/04/16 80/04/03 80/04/03 80/04/16 80/04/03	50-313 FGIA FGIA 50-313 FGIA	F	8004220636 8004220636 8004220639 8004220644 8004220648	800422020 8004220428 800422020 800422020 800422042	80/04/03 80/04/15 80/04/03 80/04/03 80/04/16	FOIA 50-366 FOIA FOIA 50-305	S S
8004220450 8004220452 8004220453 8004220454 8004220456	8004220427 8004220020 8004220427 8004220427 8004220427	80/04/16 80/04/03 80/04/16 80/04/16 80/04/16	50-313 FOIA 50-313 50-313 50-313	F F F	8004220653 8004220658 8004220666 8004220667 8004220668	8004220646 8004220652 8004220657 8004220662 8004220660	80/04/15 80/04/17 80/04/16 80/04/15 80/04/14	50-338 50-346 50-346 50-366 50-298	55555
8004220458 8004220459 8004220461 8004220463 8004220465	8004220020 8004220455 8004220020 8004220020 8004220020	80/04/03 80/04/15 80/04/03 80/04/03 80/04/03	FOIA 50-375 FOIA FOIA FOIA	Q	8004220671 8004220679 8004220680 8004220681 8004220684	8004220664 8004220670 8004220669 8004220630 8004220675	80/04/15 80/04/18 80/04/18 80/04/17 80/04/17	50-366 50-336 50-260 50-10 50-321	9 9 9 9 9
8004220466 8004220467 8004220468 8004220469 8004220470	8004220020 8004220020 8004220020 8004220020 8004220020	80/04/03 80/04/03 80/04/03 80/04/03 B0/04/03	FOIA FOIA FOIA FOIA		8004220687 8004220690 8004220697 8004220699 8004220700	8004220676 8004220692 8004220692 8004220686 8004220693	80/04/15 80/04/14 80/04/18 80/04/18 80/04/10	50-325 50-269 50-275 50-259 50-249	S A S S
8004220472 8004220473 8004220476 8004220479 8004220480	8004220020 8004220020 8004220020 8004220020 8004220020	80/04/03 80/04/03 80/04/03 80/04/03 80/04/03	FOIA FOIA FOIA FOIA FOIA		8004220702 8004220703 8004220704 8004220707 8004220710	8004220694 8004220691 8004220692 8004220698 8004220689	80/04/14 80/04/15 80/04/18 80/04/17 80/04/17	50-304 50-368 50-275 50-327 50-321	8 A 8
8004220482 8004220485 8004220486 8004220488 8004220491	8004220020 8004220020 8004220020 8004220020 8004220020	80/04/03 80/04/03 80/04/03 80/04/03 80/04/03	FOIA FOIA FOIA FOIA FOIA		8004220716 8004220717 8004220718 8004220719 8004220721	8004220692 8004220705 8004220706 8004220708 8004220713	80/04/18 80/04/17 80/04/17 80/04/16 80/04/15	50-275 50-366 50-366 50-317 50-321	A 9 8 8
8004220499 8004220501 8004220506 8004220511 8004220512	8004220497 8004220464 8004220464 8004220508 8004220020	80/04/18 80/04/21 80/04/21 80/04/17 80/04/03	TOPREP 50-220 50-220 50-219 FOIA	P P P	8004220722 8004220727 8004220735 8004220735 8004220737	8004220715 8004220692 8004220726 8004220728 8004220692	80/04/16 80/04/18 80/04/17 80/04/15 80/04/18	50-327 50-275 50-346 50-366 50-275	5 8 8
8004220514 8004220517 8004220521 8004220528 8004220530	800422050B 8004220020 8004220020 8004220020 8004220522	80/04/17 80/04/03 80/04/03 80/04/03 80/04/17	50-219 FDIA FDIA FDIA 50-309	P P	8004220738 8004220740 8004220744 8004220746 8004220747	8004220729 8004220732 8004220692 8004220729 8004220730	80/04/09 80/04/15 80/04/18 80/04/09 80/04/15	50-348 50-324 50-275 50-348 50-482	5 8 8 8 1
8004220531 8004220532 8004220539 8004220544 8004220545	8004220523 8004220020 8004220020 8004220020 8004220542	80/04/15 80/04/03 80/04/03 80/04/03 80/04/11	50~259 FOIA FOIA FOIA 50~289	P P	8004220749 8004220750 8004220751 8004220755 8004220757	8004220741 8004220742 8004220672 8004220692 8004220753	80/04/17 80/04/18 80/04/18 80/04/18 80/04/16	50-266 50-259 50-275 50-275 50-327	8 8 A 8
8004220546 8004220547 8004220548 8004220551 8004220552	8004220541 8004220538 8004220020 8004220020 8004220542	80/04/16 80/04/16 80/04/03 80/04/03 80/04/11	50-43B 50-325 FOIA FOIA 50-289	5 S	8004220758 8004220759 8004220761 8004220762 8004220764	8004220749 8004220730 8004220752 8004220754 8004220724	80/04/18 80/04/15 80/04/16 80/04/13 80/04/14	50-318 50-482 50-344 50-3 50-518	8 9 0 8
8004220557 8004220560 8004220562 8004220565 8004220567	8004220020 8004220558 8004220020 8004220558 8004220020	80/04/03 80/03/13 80/04/03 80/03/13 80/04/03	FOIA 50-111 FOIA 50-111 FOIA	R	8004220769 8004220771 8004220772 8004220778 8004220790	8004220763 8004220767 8004220765 8004220775 8004220789	80/04/21 80/04/17 80/04/16 80/04/14 80/03/17	50-498 50-333 50-346 50-267 71-9019	K 8 1
8004220573 8004220577 8004220579 8004220581 8004220583	8004220020 8004220559 8004220020 8004220575 8004220572	80/04/03 80/04/15 80/04/03 80/04/17 80/04/15	FOIA 50-410 FOIA 50-155 50-324	ន ៤ ទ	8004230007 8004230014 8004230017 8004230023 8004230026	8004230002 8004230010 8004230010 8004230015 8004230009	80/04/11 80/04/04 80/04/04 80/04/10 80/02/22	50-445 50-266 50-266 FDIA 50-250	M Q Q
8004220585 8004220591 8004220593 8004220596 8004220598	8004220020 8004220020 8004220020 8004220586 8004220020	80/04/03 80/04/03 80/04/03 80/04/11 80/04/03	FOIA FOIA FOIA 50-295 FOIA	g	8004230029 8004230032 8004230040 8004230041 8004230045	8004230015 8004230015 8004230015 8004230033 8004230015	80/04/10 80/04/10 80/04/10 80/04/10 80/04/10	FOIA FOIA FOIA 50-445 FOIA	М
8004220602 8004220608 8004220609 8004220607	8004220020 8004220020 8004220579 8004220020 8004220020	80/04/03 80/04/03 80/04/15 80/04/03 80/04/03	FOIA FOIA 50-325 FOIA FOIA	s	8004230044 8004230050 8004230040 8004230071 8004230074	8004230036 8004230015 8004230053 8004230059 8004230066	80/02/22 80/04/10 80/02/29 80/03/20 80/04/03	50-390 FOIA 50-201 50-352 50-445	G R G M
8004220616 8004220617 8004220618 8004220621 8004220622	8004220020 8004220615 8004220020 8004220614 8004220020	80/04/03 80/04/15 80/04/03 80/04/17 80/04/03	FOIA 50-366 FOIA 50-317 FOIA	8 8	8004230077 8004230089 8004230093 8004230096 8004230101	8004230059 8004230059 8004230091 8004230091 8004230091	80/03/20 80/03/20 76/11/24 76/11/24 76/11/24	50-352 50-352 50-367 50-367 50-367	9 9 9
8004220623 8004220625 904220627 1606224008	8004220613 8004220020 8004220020 8004220624 8004220020	80/04/09 80/04/03 80/04/03 80/04/11 80/04/03	50-265 FOIA FOIA 50-293 FOIA	s	8004230103 8004230110 8004230114 8004230118 8004230126	8004230078 8004230075 8004230059 8004230075 8004230123	80/04/11 80/03/21 80/03/20 80/03/21 80/04/08	50-275 CDMM1881 50-352 COMM1881 SECY	G

ACCESSION	NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL BOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8004230128 8004230130 8004230133 8004230136 8004230141	8004230120 8004230123 8004230123 8004230123 8004230123	E0\E0\03 B0\40\08 B0\40\08 B0\40\08 B0\40\08	50-309 SECY XPORTLIC SECY SECY	Q.	8004240155 8004240159 8004240170 8004240170 8004240175	8004240028 8004240153 8004240028 8004240163 8004240028	78/03/06 80/03/19 78/03/06 80/03/20 78/03/06	70-135 70-143 70-135 50-247 70-135	Р
8004230144 8004230157 8004230162 8004230175 8004230179	8004230138 8004230138 8004230154 8004230167 8004230167	B0/03/04 B0/03/04 B0/04/07 B0/03/03 B0/03/03	70-925 70-925 50-445 50-123 50-123	11 0 0	8004240183 8004240187 8004240190 8004240802 8004240202	8004240028 8004240028 8004240181 8004240181 8004240201	/8/03/06 78/03/03 80/03/03 80/03/03	70-135 70-135 70-2805 70-2805 50-438	A
8004230189 8004230190 8004230236 8004230238 8004230246	8004230167 8004230185 8004230202 8004230231 8004230231	80/03/03 80/04/03 80/03/26 80/04/21 80/04/21	50-123 50-3 50-269 50-339 50-339	G H G P P	8004240207 8004240217 8004240213 8004240276 8004240277	8004240178 8004240201 8004240251 8004240251 8004240267	80/03/10 80/01/30 80/03/14 80/03/14 80/01/23	40-8502 50-438 50-250 50-250 70-1308	A P P
8004230248 8004230249 8004230253 8004230255 8004230260	8004230237 8004230202 8004230237 8004230231 8004230231	80/04/08 80/03/26 80/04/08 80/04/21 80/04/21	50-460 50-267 50-460 50-339 50-339	0 0 P P	B004240282 B004240283 B004240288 B004240294 B004240307	B004240270 B004240251 B004240267 B004240267 B004240299	80/03/19 80/03/14 80/01/23 80/01/23 80/04/03	50-320 50-250 70-1308 70-1308 50-277	H P
8004230267 8004230271 8004230273 8004230276 8004230277	8004230202 8004230237 8004230239 8004230237 8004230202	80/03/26 80/04/08 80/04/08 80/04/08 80/03/26	50-269 50-460 50-460 50-460 50-269	0 0 0 0	8004240317 8004240320 8004240322 8004240328 8004240329	8004240307 8004240299 8004240314 8004240323 8004240379	80/04/15 80/04/03 80/02/28 80/04/18 80/04/03	50-250 50-277 71-107 50-267 50-277	2 5 5
8004230287 8004230270 8004230302 8004230303 8004230307	8004230239 8004230239 8004230295 8004230300 8004230300	80/04/08 80/04/08 80/04/22 79/10/18 79/10/18	50-460 50-460 PROJ NUREG NUREG	G G	8004240331 8004240343 8004240352 8004240354 8004240360	8004240314 8004240334 8004240344 8004240350 8004240344	80/02/28 80/04/15 80/04/02 78/06/03 80/04/02	71-107 50-335 50-424 50-250 50-424	S Q R
8004230309 8004230313 8004230316 8004230317 8004230326	8004230299 8004230299 8004230299 8004230295 8004230321	80/04/14 80/04/14 80/04/14 80/04/22 79/08/04	50-213 50-213 50-213 PROJ 50-250	F F R	8004240363 8004240366 8004240375 8004240375 8004240378	8004240357 8004240362 8004240368 8004240367 8004240371	78/09/04 80/04/21 78/04/07 80/04/16 80/04/02	50-250 50-261 50-250 50-335 50-250	R S R S O
8004230332 8004230348 8004230355 8004230357	8004230330 8004230341 8004230346 8004230351 8004230351	79/06/09 80/04/21 80/04/14 80/04/18 80/04/18	50-250 50-219 50-331 50-316 50-316	R P R S	8004240383 8004240387 8004240388 8004240389 8004240390	8004240371 8004240371 8004240386 8004240384 8004240371	80/04/02 80/04/02 80/04/17 80/04/11 80/04/02	50-250 50-250 50-438 50-275 50-250	0 9 8 6
8004230357 8004230362 8004230411 8004230414 8004230417	8004230358 8004230380 8004230406 8004230407 8004230407	80/04/17 80/04/17 80/04/09 80/03/26 80/03/26	50-282 50-438 50-289 50-277 50-277	8 8 8 P P	8004240372 8004240395 8004240396 8004240397 8004240378	8004240391 8004240394 8004240393 8004240394 8004240393	80/04/16 80/04/24 80/03/03 80/04/24 80/03/03	50-277 50-206 50-238 50-206 50-338	Q P Q P
8004230432 8004230441 8004230444 8004230447 8004230464	8004230430 8004230407 8004230438 8004230438 8004230461	80/04/15 80/03/26 80/04/18 80/04/18 80/04/18	50-316 50-277 50-315 50-315 50-335	\$ P 8 9 P	8004240413 8004240415 8004240420 8004240422 8004240422	8004240408 8804240411 8004240416 8004240418 8004240421	80/03/03 80/04/10 80/03/31 79/01/05 80/04/22	50-280 50-259 50-128 50-250 50-445	Q R R R
8004230473 8004230487 8004230490 8004230495 8004230497	B004230471 B004230480 B004230484 B004230473 B004230477	80/04/16 80/04/17 79/07/07 80/04/15 80/04/09	50-313 50-282 50-250 50-289 50-293	S Q R R R	B004240430 B004240432 B004240433 B004240434 B004240434	8004240425 8004240425 8004240421 8004240426 8004240437	80/03/28 80/04/16 80/04/22 80/03/28 80/04/01	50-491 50-219 50-445 50-491 50-213	Q R Q Q R
8004230507 8004230515 8004230525 8004230528 8004230527	8004230503 8004230504 8004230520 8004230523 8004230527	80/04/17 80/04/18 80/04/19 80/04/02 80/04/17	50-438 50-305 50-261 CONTRACT 50-438	8 8 8	8004240440 8004240444 8004240447 8004240452 8004240459	8004240434 8004240443 8004240441 8004240448 8004240455	78/12/06 78/10/07 80/03/19 78/05/06 78/08/10	50-250 50-250 50-320 50-250 50-250	R R H R
8004240006 8004240015 8004240038 8004240041 8004240046	8004240002 8004240007 8004240028 8004240033 8004240028	80/04/02 80/04/07 78/03/04 80/01/09 78/03/06	ORG CONTRACT 70-135 CONTRACT 70-135		8004240466 8004240474 8004240479 8004240483 8004240483	8004240463 8004240470 8004240472 8004240480 8004240480	78/11/04 78/07/01 80/04/03 80/04/09 80/04/09	50-250 50-250 50-320 50-286 50-286	R P P
8004240051 8004240056 8004240067 6004240071 8004240073	8004240047 8004240028 8004240063 8004240061 8004240028	80/04/03 78/03/06 80/03/24 80/04/07 78/03/06	CONTRACT 70-135 XPORTLIC 50-445 70-135	м	8004240487 8004240470 8004240472 8004240475 8004240801	8004240480 8004240485 8004240480 8004240485 8004240493	80/04/09 80/04/04 80/04/09 80/04/04 80/04/08	50-284 50-272 50-284 50-272 50-528	Р С С С
8004240081 8004240084 8004240089 8004240075 8004240104	8004240077 8004240028 8004240087 8004240028 8004240028	80/03/27 78/03/04 80/03/25 78/03/04 78/03/06	State Pr 70-135 50-334 70-135 70-135	P	8004240504 8004240507 8004240508 8004240511 8004240514	8004240480 8004240480 8004240493 8004240506 8004240512	80/04/09 80/04/09 80/04/08 80/04/01 80/04/04	50-286 50-286 50-528 50-313 50-267	P G P G
8004240110 8004240114 8004240127 8004240137 8004240150	8004240028 8004240028 8004240028 8004240028 8004240028	78/03/06 78/03/06 78/03/04 78/03/06 78/03/06	70-135 70-135 70-135 70-135 70-135		8004240916 8004240517 8004240918 8004240922 8004240926	8004240493 8004240510 8004240480 8004240493 8004240524	80/04/08 80/04/04 80/04/07 80/04/08 80/03/20	50-528 50-247 50-286 50-528 50-346	9 9 9 9

## TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ESSION NUMBER		
FR INCIPAL	DATE ISSVED	SUBJECT CATEGORY	ENCLOS		DATE 188VED	SUBJECT CATEGORY
8004240534 8004240529 8004240537 8004240532 8004240542 8004240535 8004240544 8004240541 8004240545 8004240544	80/04/09 80/04/04 80/03/31 80/04/09 80/04/02	50-443 H 50-219 G CONTRACT 50-275 G CONTRACT		80114 8004280112 80118 8004280112 80120 8004280113 80124 8004280111	80/04/10 80/04/10 80/04/09 80/03/24 80/03/12	50-514 D 50-514 D 50-284 P 50-272 Q 50-250 Q
8004240554 8004240550 8004240555 8004220548 8004250008 8004250004 8004250011 8004250003 8004250012 8004250003	80/03/04 80/03/21 80/04/03 80/03/31 80/04/03	70~135 50-466 ( 50-302 F 50-556 ( 50-302 F	800428 800428 800428 800428 800428	30133 8004280129 30135 8004280111 30139 8004280136	B0/03/26 B0/04/11 B0/03/26 B0/04/10 B0/04/10	50-272 G 71-9039 50-272 G GA999 GA999
8004250015 8004250006 8004250022 8004250014 8004250030 8004250018 8004250041 8004250018 8004250041 8004250036	80/04/03 80/04/04 80/04/01 80/04/01 80/04/04	50-302 F CONTRACT 50-3 F 50-247 F 50-280 F	800426	30144 B004280134 30147 B004280111 30149 B004280136	80/03/12 80/04/10 80/03/26 80/04/10 80/03/13	50-348 Q QA999 50-272 Q QA999 50-261 P
8004250042 8004250039 8004250043 8004250035 8004250054 8004250051 8004250054 8004250051 8004250056 8004250056	80/03/24 80/03/31 80/03/28 80/03/28 80/03/26	XPORTLIC CONTRACT 50-213 50-213 50-10		90156 8004280148 90157 8004280150 90162 8004280159	B0/04/10 B0/03/13 B0/03/13 B0/04/09 B0/03/31	0A999 50-261 P 50-325 Q 50-311 A 50-354 B
8004250072 8004250068 8004250075 8004250063 8004250081 8004250063 8004250083 8004250079 8004250143 8004250132	80/03/29 80/03/20 80/03/20 80/03/20 80/03/24		800426	80186 8004280184 80195 8004280190 80196 8004280190 80202 8004280194	80/03/04 80/03/19 80/04/16 80/04/16 80/03/07	50-312 Q 50-298 Q 50-311 Q 50-311 Q 50-259 Q
8004250193 8004250178 8004250204 8004250178 8004250212 8004250178 8004250261 8004250251 8004250251 8004250251	80/03/21 80/03/21 80/03/21 80/04/09 80/04/09	50-261		30204 8004280200 30224 8004280214 30234 8004280230	80/04/14 80/04/09 80/03/26 80/03/31 80/04/22	50-3 P REVIEW ORP 50-312 G 50-320 R 50-327 P
8004250282 8004250251 8004250271 8004250251 8004250279 8004250273 8004250334 8004250330 8004250337 8004250336	80/04/09 80/04/09 80/03/17 80/04/02 80/04/04	50-261 50-313 50-269	800426 800426 800426 800426	30243 8004280237 30250 8004280244 30255 8004280247	80/03/10 80/02/28 80/04/01 80/03/10 80/03/19	50-335 Q 70-1201 50-320 P 70-1317 50-320 H
8004250340 8004250330 8004250346 8004250330 8004250352 8004250347 8004250357 8004250330 8004250358 8004250350	80/04/02 80/04/02 80/04/21 80/04/03 80/04/21	50-269 50-382 50-269	80042E 80047E 80042E 80042E 80042E	30288 8004280280 30299 8004280293 30300 8004280297	80/03/24 80/03/05 80/04/03 80/03/04 80/04/03	50-397 0 50-317 0 50-266 P 50-293 0 50-266 P
8004250357 8004250354 8004250369 8004250365 8004250377 8004250374 8004250384 8004250360 8004250389 8004250377	80/04/21 80/04/22 80/04/21 80/04/21 80/04/12	50-255 50-382 50-544 50-438 50-320	8 B00426 B00426 B00426 B00426 B00426	90304 8004280293 90310 8004280297 90314 8004280307	80/03/19 80/04/03 80/03/04 80/04/02 80/04/25	50-320 H 50-266 P 50-293 Q 71-5395 50-358 F
B004250394 8004250388 B004250399 8004250308 B004250407 8004250406 B004250408 8004250396 B004250412 8004250410	80/03/26 80/03/26 80/04/15 80/04/18 80/04/22	50-10 50-10 50-317 50-259 50-324	6 B00426 6 B00426 6 B00426 6 B00426	8004280325 8004280327 8004280342 8004280342	80/04/17 80/03/19 80/04/16 80/03/24 80/04/04	State Prog 50-320 H TOPREP 50-320 H 50-368 H
B004250417 8004250411 B004250420 8004250418 B004250424 8004250413 B004250428 8004250427 B004250428 8004250427	80/04/18 80/04/21 80/04/21 80/04/15 80/04/21	50-318 50-206 50-390 50-373 50-556	6 800426 6 800426 6 800426 6 800426	90366 8004280362 80369 8004280362 90371 8004280365	80/04/14 80/04/14 80/04/14 80/04/25 80/04/14	50-302 P 50-10 II 50-10 H 50-416 K 50-10 H
8004280007 8004280005 8004280013 8004280005 8004280014 8004280005 8004280021 8004280017 8004280022 8004280016	80/03/13 80/04/11 80/03/13 80/04/04 80/03/04	50-395 50-344 50-395 50-206 50-275	9 800426 9 800426 9 800426 9 800426	30379 8004280362 30381 8004280365 30382 8004280380	80/04/25 80/04/14 80/04/25 80/04/18 80/04/18	50-416 K 50-10 H 50-416 K 50-346 I 50-346 I
8004280025         8004280020           8004280037         8004280037           8004280043         8004280037           8004280044         8004280040           8004280040         8004280040	80/03/06 80/03/12 80/04/08 80/04/11 80/04/11	50-265 50-454 50-282 50-285 50-285	9 800426 0 800426 4 800426 6 800426 6 800426	30412 8004280410 30414 8004280410 30418 8004280417	80/04/14 80/04/21 80/04/21 80/03/31 80/04/21	50-289 H 50-373 A 50-373 A 40-8681 50-366 8
8004280047 8004280040 8004280053 8004280050 8004280057 8004280050 8004280060 8004280056 8004280070 8004280065	80/04/11 80/03/18 80/03/18 80/03/25 80/02/05	50-285 XPORTLIC 50-324 40-1341 50-334	800426 800426 3 800426 800426 9 800426	80425 8004280423 80427 8004280423 80426 8004280432	80/03/31 79/08/15 79/08/15 80/04/07 80/04/16	40-8681 40-8602 40-8602 50-438 8 50-438 8
8004280074 8004280045 8004280079 8004280065 8004280079 8004280065 8004280085 8004280065 8004280087 8004280080	80/03/06 80/02/05 80/02/05 80/02/05 80/03/24	50-454 50-334 50-334 50-334 50-344	9 800426 800426 9 800426 9 800426 9 800426	30458 B004280453 30459 B004280455 30469 B004280466	80/04/22 80/04/03 80/02/08 80/04/21 80/04/21	50-366 S 50-328 8 COMMISSION 50-397 B 50-397 6
B004280090 B004280065 B004280091 B004280082 B004280095 B004280092 B004280098 B004280065 B004280109 B004280099	80/02/05 80/03/19 80/03/20 80/02/05 80/03/14	50-334 50-460 50-361 50-334 50-261	80042E 80042E 1 80042E 80042E 0 80042E	30496 8004280490 30505 8004280503 30507 8004280504	79/12/21 80/03/03 80/04/14 80/04/21 80/04/15	COMMISSION 50-327 8 50-318 8 TOPREP 50-566 R

SUBJECT

8 S R R S

88808

8 8 8

50-319 50-329 50-334 50-313 50-348

50~537 50-317 50-244 50-313 50-317

50-334 50-387 50-325 50-327 50-265

50-318 50-266 50-249 50-445 50-317

50-327 50-317 50-34B 40-3453 50-390

50-328 50-390 50-312 50-321 50-390

50-301 50-317 TOPREP 50-321 50-344

50-301 50-333 50-295 50-317 50-302

50-312 50-325 50-275 50-272 50-445

50-317 50-369 50-275 50-334 50-333

CONTRACT 71-227 50-327 50-312 50-289

SECY 50-387 0 50-387 0 50-387 0

98888

9 9 9 R Q

## CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION						ACCE8810N	NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGOR		ENC	LOSURE	PRINCIPAL DOCUMENT	DATE 165UED
8004280522 8004280524 8004280530 8004280532 8004280540	8004280517 8004280514 8004280529 8004280527 8004280535	80/03/31 80/04/17 80/04/18 80/03/19 80/03/19	50-416 50-438 50-336 50-320 50-320	8 8 H	800 800 800	04290350 04290353 04290355 04290366 04290369	B004290345 B004290346 B004290354 B004290361 B004290367	80/04/25 80/04/23 80/04/25 80/04/25 80/04/22
8004280543 8004280544 8004280545 8004280546 8004280853	8004280537 8004280537 8004280542 8004280538 8004280550	80/04/21 80/04/07 80/03/19 80/04/24 80/03/24	50-458 50-390 50-320 50-346 50-320	R S H S H	909 909 909	04290371 04290377 04290381 04290385 04290388	8004270364 8004270372 8004270378 8004270374 8004270382	B0/04/04 B0/04/25 B0/04/25 B0/04/22 B0/04/25
8004280854 8004280587 8004280589 8004280564 8004280566	8004280549 8004280555 8004280552 8004280562 8004280570	80/04/25 80/04/24 80/04/23 80/04/23 80/04/22	50-338 50-155 50-333 50-309 50-321	8 8 8 8	800 800 800	04270373 04270377 04270401 04270406 04270407	80042903B9 8004290394 8004290397 E004290400 8004290380	80/04/23 80/04/18 80/04/24 80/04/24 80/04/21
8004280548 8004280571 8004280575 8004280579 8004280586	8004280567 8004280567 8004280572 8004280574 8004280576	80/04/23 80/04/23 80/04/24 80/03/25 80/04/21	50-302 50-302 50-346 50-298 50-325	P P S S S	800 800 800	04290416 04290425 04290429 04290437 04290438	8004290410 8004290418 8004290422 8004290430 8004290433	80/04/25 80/04/22 80/04/22 80/04/21 80/04/25
8004280589 8004280592 8004280598 8004280599 8004280605	8004280582 8004280583 8004280593 8004280587 8004280594	80/04/22 80/04/22 80/04/18 80/04/21 80/04/21	50-321 50-324 50-259 50-324 50-382	88888	800 800	)4290446 )4290447 )4290451 )4290452 )4290458	8004290435 8004290440 8004290450 8004290449 8004290453	80/04/25 80/04/25 80/04/17 80/03/24 80/04/22
8004280608 8004280616 8004280617 8004280618 8004280621	8004280604 8004280612 8004280614 8004280610 8004280614	80/04/25 80/04/24 80/04/24 80/04/11 80/04/24	50-338 50-280 50-255 50-416 50-255	4848	800 800 800	)4290461 )4290462 )4290465 )4290466 )4290467	8004270455 8004270453 8004270454 8004270460 8004270453	80/04/24 80/04/22 80/04/21 80/04/04 80/04/22
8004280624 8004280625 8004280626 8004280627 8004280633	8004280614 8004280614 8004280612 8004280614 8004280630	80/04/24 80/04/24 80/04/24 80/04/24 80/04/22	50-255 50-255 50-280 50-255 50-320	F B F I	800 800 800	04290469 04290472 04290474 04290477	8004270464 8004270457 8004270468 8004270460 8004270471	80/04/16 80/04/25 80/04/21 80/04/04 80/04/22
8004280634 8004280638 8004290006 8004290011 8004290021	8004280628 8004280630 8004270002 8004270005 8004270016	80/04/09 80/04/22 80/04/04 80/04/07 80/04/03	50-10 50-320 50-284 50-298 6A979	0 0 0	800 800 800	)4290479 )4290482 )4290483 )4290484 )4290488	B004290470 B004290476 B004290473 B004290475 B004290480	80/04/17 80/04/25 80/04/22 80/04/25 80/04/16
8004270023 8004270027 8004270031 8004270041 8004270044	8004270016 8004270016 8004270016 8004270036 8004270036	80/04/03 80/04/03 80/04/03 80/04/02 80/04/02	0A777 0A777 0A777 40-8602 40-8602		800 800 800	94290491 94290494 94290496 94290497 94290498	8004270485 8004270487 8004270486 8004270489 8004270472	80/04/11 80/04/24 80/04/18 80/04/21 80/01/23
B00427005B B00427006B B0042700B1 B0042700B3 B0042700B5	8004270054 8004270064 8004270077 8004270076 8004270080	80/03/25 80/03/19 80/04/03 80/03/19 80/04/08	50-3 50-320 50-250 50-320 50-123	H H F H Q	800- 800- 800-	94290499 94290501 94290504 94290508	8004270470 8004270473 8004270502 8004270503 8004270504	80/04/25 80/04/24 80/04/22 80/04/22 80/04/24
8004270075 8004270101 8004270113 8004270115 8004270117	8004270072 8004270072 8004270107 8004270110 8004270110	80/04/24 80/04/24 80/03/20 80/04/16 80/04/16	50-334 50-334 CONTRACT 40-3453 40-3453	T T	800- 800- 800-	4270514 4270516 4270517 4270524 4300005	8004270507 8004270513 8004270515 8004270338 8004300001	80/01/01 80/04/10 80/04/25 80/04/17 80/04/02
8004270121 8004270122 8004270125 8004270128 8004270135	8004270110 8004270116 8004270110 8004270116 8004270116	80/04/16 80/04/10 80/04/16 80/04/10 80/04/10	40-3453 50-324 40-3453 50-324 50-324	a a a	800 800 800	4300007 4300008 4300009 4300013	8004300002 8004300006 8004300006 8004300006	80/03/11 80/03/10 80/03/10 80/03/10
8004270138 8004270141 8004270157 8004270176 8004270177	8004270137 8004270116 8004270151 8004270168 8004270170	80/04/11 80/04/10 80/04/10 80/04/03 80/04/09	50-313 50-324 50-339 0A999 50-259	Р О О				
8004270177 8004270186 8004270171 8004270201 8004270203	8004270168 8004270168 8004270168 8004270168 8004270168	80/04/03 80/04/03 80/04/03 80/04/03 80/04/03	0A979 0A999 0A999 0A999 0A999					
8004270212 8004270254 8004270286 8004270303 8004270306	8004270168 8004270250 8004270284 8004270299 8004270278	80/04/03 80/04/21 80/04/21 80/04/21 80/04/17	GA999 50-445 50-348 50-245 50-266	8 P 8				
8004270310 8004270316 8004270327 8004270335 8004270336	8004270307 8004270311 8004270321 8004270327 8004270321	80/04/14 80/04/24 80/04/23 80/04/24 80/04/23	50-266 50-327 50-305 50-328 50-305	6 8 8 8				

ACCESSIO	I NUMBER				VCCERRIT	N NUMBER			
	PRINCIPAL	DATE	SUBJECT			PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATEGOR		ENCLOSURE	DOCUMENT	ISSUED	CATEGORY	
		20.400.401	40-4492		B0Q4300259	8004300250	80/04/04	50-344	Р
8004300045	8004300043	80/03/21	50-397	G	B004300260	8004300205	80/04/07	50-269	à
8004300066	8004300006	80/03/10		Ğ	8004300264	8004300250	80/04/04	50-344	į.
9004300047	8004300006	80/03/10	50-397 40-4492	G	6004300270	8004300263	80/04/04	50-328	o
800430006B	8004300043	80/03/21		G	8004300280	B004300276	80/03/19	50-266	P
8004300069	8004300006	80/03/10	50-387	G	8504300280	6004300276	00/03/1/	30-200	t.
BD04300070	8004300006	80/03/10	50-397	G	8004300285	8004300276	80/03/19	50-266	Р
6004300071	8004300006	80/03/10	50~397	G	8004300287	8004300276	80/03/19	50-246	Р
6004300073	8004300006	80/03/10	50-38/	G	8004300290	8004300282	80/03/31	50-410	Q
8004300075	8004300043	80/03/21	40-4492		8004300296	8004300282	80/03/31	50-410	G.
8004300076	8004300006	80/03/10	50~387	٥	8004300298	8004300273	80/02/29	50-397	Q.
8004300080	8004300006	80/03/10	50~387	٥	8004300299	8004300292	80/04/11	50-3	U
8004300080	8004300043	80/03/21	40-4492	-	8004300301	8004300282	80/03/31	50-410	Ğ
8004300083	8004300043	80/03/10	50-367	Ğ	8004300309	8004300282	B0/03/31	50-410	Ğ
	8004300006	80/03/10	50~387	Ğ	8004300320	8004300317	80/04/09	50-225	Ğ
8004300089	8004300084	80/04/03	QA999	•	B004300322	8004300317	80/04/09	50-225	ĕ
9004300092	8004300084	60704703	un.,,		DUOTOODRE	000400017	80704707	30 220	•
8004300096	8004300090	80/04/09	50-566	a	8004300324	8004300317	80/04/09	50-225	Œ
8004300098	8004300084	80/04/03	04999		8004300328	8004300317	80/04/09	50-225	Q
8004300100	8004300090	80/04/09	50-546	O .	8004300337	8004300334	80/04/08	50-306	0
8004300103	8004300090	80/04/09	90~566	Q	8004300350	8004300348	80/04/28	50~546	Α
8004300107	8004300084	80/04/03	0A979		8004300371	B004300366	80/04/28	70-2909	
0004000400	8004300090	80/04/09	50-566	a	B004300376	B00430036B	80/04/24	50-352	6
8004300108 8004300119	8004300112	80/04/07	50-395	ă	8004300378	8004300366	80/04/28	70-2909	
8004300114	8004300112	80/01/31	50-528	Ğ	B0043003B1	8004300346	80/04/28	70-2909	
8004300124	8004300112	80/04/07	50-375	õ	80043003B1		80/04/18	50-387	5
8004300128	8004300112	80/04/07	50-375	ă	8004300397		B0/04/18	50-518	6
8004300158	8004200115	80704707	20-310	ď	8004300377	8004300370	00/04/24	30-316	•
8004300135	B004300112	80/04/07	50-395	a	8004300419	8004300416	B0/04/25	50-247	P
8004300151	8004300143	80/04/11	50~302	Q:	8004300423		B0/04/25	50-247	P
8004300159	8004300143	80/04/11	50-302	ũ.	8004300433		80/04/04	50-312	a
8004300164	8004300143	80/04/11	50-302	0	8004300439		B0/04/04	50-312	G
800430016B	8004300162	B0/04/07	50-334	P	8004300445		80/04/04	50-312	G
	8004300143	80/04/11	50-302	G	8004300453	8004300425	B0/04/04	50-312	G
8004300171		80/04/11	50-334	P	B004300433	8004300425	80/04/21	50-409	š
8004300174	8004300162		50-302	á	8004300474	8004300458	80/04/07	50-390	ā
8004300177	E4100E400B	60/04/11	50-302 50-483	ū	8004300474 8004300484	B004300479	80/04/08	50-395	ö
8004300178	8004300166	80/04/14	50-483 50-334	P	8004300493	B004300478	80/04/08	50-375	ŏ
8004300183	8004300142	50/04/07	30-334	г	0004300473	000430047W	40,04,00	00 0,0	*
8004300184	8004300166	BO/04/14	50-4B3	Q	8004300519	8004300508	80/04/07	50-320	0
8004300187	8004300143	80/04/11	50-302	a	8004300523	8004300514	80/03/21	50-498	a
8004300189	8004300166	80/04/14	50~483	a	8004300528		15\E0\03	50-546	a
8004300194	8004300166	80/04/14	50-483	G	E004300536		80/03/21	50-546	G
8004300214	8004300205	BO/04/07	50-267	O	8004300548	8004300544	80/03/21	50-10	Q
8004300219	8004300215	80/03/27	WASTE MO	38	8004300555	8004300544	80/03/21	50-10	G
8004300217	8004300217	80/03/05	0A999	- *	8004300586		B0/04/10	50-289	ä
8004300227	8004300223	80/03/24	50-244	Q	8004300590		80/04/18	50-272	G
8004300230	8004300205	80/04/07	50-249	ā	8004300598	8004300585	B0/04/18	50-272	Q
8004300232	B004300223	80/03/26	50-244	ũ	8004300600	8004300585	80/04/18	50-272	G
20042555	0004500555	0040040	EO -044	G	8004300604	8004300592	80/04/11	50-358	æ
8004300235	8004300223	80/03/26	50-244 50-269	Q.	8004300604	8004300572	80/04/15	COMMISSI	
8004300237	8004300205	80/04/07	50-244	Q.	8004300607	8004300602	80/03/17	50-293	G
8004300244	8004300223 8004300205	80/03/26 80/04/07	50~269	ä	8004300807	JOSOGOR			•
8004300245	8004300205	80/04/04	50~269	P					
6004300255	9004300530	80704704	20~344	r					

#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic another facility which may affect the subject
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical repo

#### B. UTILITY PRELIMINARY SAFETY ANALYS

This category is strictly limited to the items listed Category A.

- 1. Preliminary Safety Analysis Report (PSAR) si Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

#### C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

### D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

#### E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

#### H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

#### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

#### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

#### L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

#### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

#### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

### O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR)
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7 Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP)
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

### Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

#### R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

#### S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

#### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

#### U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

#### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan,
  Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

ł

#### APPENDIX B

#### DEFINITIONS OF NONDOCKETED CATEGORIES

#### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

#### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

#### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

#### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

#### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

#### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- Draft reports of action plans to accomplish generic tasks in the regulatory program.
  - with industry and internal correspondence regarding the methodologies, ogrammatic and technical aspects of issues.

ions and minutes.

and status reports on generic tasks addressing related aspects of generic

#### I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

#### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

#### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria.
  - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

#### ORG - Correspondence with Other Organizations

This category contains correspondence with professiona other than Regulatory Guides that pertain to the activiment; and emergency petitions not assigned Petition fo the Commission to take immediate action on some issu

 Meeting summaries and technical correspondence and international bodies, such as the Atomic Indu Energy Agency.

- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are.

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.
- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

#### I. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

#### A. Application/Construction Stage

- 1. Application submitted by the utility
- 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
- 3. Applicant's Quality Assurance Manual.
- 4. Early site review information.
- 5. Backup technical documents submitted in support of the application.
- 6. Early site visits.

#### B. Utility PSAR and Amendments

- 1. PSARs submitted by the utility.
- 2. Amendments and changes to the PSAR.
- Transmuttal letters.
- 4. Letters acknowledging receipt of the PSAR.

#### G. Adjudicatory Correspondence

1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.

#### M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

#### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

#### PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

#### REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

#### RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

Thus category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE. For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
  - Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
  - State Legislative Reports.
  - . Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

#### XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.

- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET	NUREG-0540 Vol 2, No 4				
TITLE AND SUBTITLE (Add Volume No., if appropriate)	2 (Leave blank)				
Title List of Documents Made Publicly Available April 1-30, 1980	3 RECIPIENT'S ACCESSION NO				
7 AUTHOR(S)	5 DATE REPORT COMPLETED  MONTH May 1980				
PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)	DATE REPORT ISSUED				
Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission	July YEAR 1980				
Washington, D.C. 20555	6 (Leave blank)				
	8 (Leave blank)				
2 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Division of Technical Information and Document Control	10 PROJECT/TASK/WORK UNIT NO				
U.S. Nuclear Regulatory Commission Washington, D.C. 20555	11 CONTRACT NO				
3 TYPE OF REPORT PERIOD COV	EREO (Inclusive datus)				
Monthly					
5 SUPPLEMENTARY NOTES	14 (Leave plank)				
6 ABSTRACT (200 words or less)	- 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10				
This document is a monthly publication containing of information received and generated by the US NRC. includes (1) docketed material associated with civiplants and other uses of radioactive materials and material received and generated by NRC pertinent to regulatory agency. The docketed information included merly issued through the U.S. Department of Energy Center under the title Power Reactor Docket Information document replaces PRDI, which will no longer be precontains the following indexes: Personal Author Index, and Report Number Index.	This information ilian nuclear power (2) nondocketed o its role as a des information for- s Technical Information attion (PRDI). This epared. This document				
7 KEY WORDS AND DOCUMENT ANALYSIS 17d DESCRIPTO	DRS				

18 AVAILABILITY STATEMENT

Unclassified

20 SECURITY CLASS (This deport) Unclassified

20 SECURITY CLASS (This page) 22 PRICE S

17b IDENTIFIERS/OPEN-ENDED TERMS